

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

11-JUN-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

723831

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2HKRL1860XH544847	HONDA TRUCK	ODYSSEY	1999	

Purchase Date 01-SEP-1999	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☒ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 13450000	Part Name(s) STRUCTURE:DOOR ASSEMBLY:LATCHES AND LOCKS	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1000	Date(s) of Failure(s) 30-DEC-1999 Mileage at Failure(s) 3332 Vehicle Speed at Failure(s) 0	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE LEFT AND RIGHT SLIDING DOORS OF MY 1999 HONDA ODYSSEY EX DO NOT REBOUND WHEN CONSISTANT PRESSURE IS APPLIED. IT TAKES VARIOUS LEVELS OF PRESSURE TO GET THE DOORS TO REBOUND WHILE CLOSING. AT TIMES, I FEEL THE PRESSURE TO REBOUND THESE DOORS ARE TOO MUCH FOR SMALL CHILDREN AND ELDERLY PEOPLE. I HAVE COMPLAINED TO BOTH HONDA WINDWARD AND AMERICAN HONDA AND HAVE DOCUMENTS THAT CLAIM THAT NOTHING CAN BE DONE TO REMEDY MY COMPLAINT. BOTH HONDA WINDWARD AND AMERICAN HONDA DO NOT CONSIDER MY DOORS A PROBLEM AND SAY THE EXCESSIVE PRESSURE IS NORMAL OPERATION OF THE ODYSSEY. I FEEL THIS IS A SAFETY ISSUE THAT SHOULD BE LOOKED INTO BY YOUR OFFICE. *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.