

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

21-JUN-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

724312

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1GKGK26N4SJ708129	GMC	SUBURBAN	1995	

Purchase Date 01-NOV-1994	Dealer's Name _____	Engine Size (CID/CC/L) 454	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☒ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08100000 03250000 15902000	Part Name(s) ELECTRICAL SYSTEM: BATTERY BRAKES: HYDRAULIC: ANTI-SKID SYSTEM EQUIPMENT: OTHER PIECES: TRAILER HITCHES AND ATTACHMEN	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) 06-MAR-1998 Mileage at Failure(s) 35000 Vehicle Speed at Failure(s) 60	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE ELECTRIC CONNECTOR FOR THE LOW PRESSURE/ LOSS OF FLUID WAS NOT CONNECTED AT THE FACTORY TO THE ABS VALVE. THE ORIGINAL BATTERY LEAKED AT THE + POST. THE OEM REPLACEMENT BATTERY DID THE SAME. AFTER THAT I SWITCHED TO AN AFTER MARKET GEL BATTERY, OPTIMA BRAND AND NEVER HAD A PROBLEM WITH IT. THE FACTORY INSTALLED TRAILER HITCH PLATFORM STARTED TO FAIL WHEN I WAS TOWING A 9000LBS TRAILER, SHOWING A 3 TO 4 INCH CRACK IN THE RIGHT SIDE BOLTED TO THE FRAME. ALL THOSE FAILED PARTS WERE REPLACED AT NO CHARGE BY THE DEALER UNDER EITHER GMC WARRENTY OR "GOOD WILL" POLICY. *AK

CONTINUED ON BACK (SEE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.