

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

22-JUL-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

725833

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) _____ (located at front of windshield on drivers side)	Vehicle Make SUBARU TRUCK	Vehicle Model FORESTER	Vehicle Year 1998	Current Odometer Reading
---	-------------------------------------	----------------------------------	-----------------------------	--------------------------

Purchase Date 01-SEP-1998	Dealer's Name _____	Engine Size (CID/CC/L) 4 CYL	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06310000	Part Name(s) ELECTRICAL SYSTEM:WIRING:HARNESS:FRONT:UNDERHOOD	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) 21-JUL-2000 Mileage at Failure(s) 35000 Vehicle Speed at Failure(s) 2	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☒ Yes ☐ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☒ Yes ☐ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

CAR BEGAN SMOKING UNDER THE HOOD-NO INDICATION FROM DASHBOARD THAT PERHAPS THE CAR WAS OVERHEATING. WHEN THE CAR WAS ULTIMATELY TURNED OFF AT THE HOME OF THE OWNER, THE ENGINE UNDER THE HOOD IGNITED, FLAMES ENGULFED UNDER THE HOOD. FIRE DEPARTMENT AND POLICE DEPARTMENT WERE CALLED TO EXTINGUISH FIRE WHICH WAS TEN FEET FROM GARAGE OF HOME. DAMAGE TO DRIVEWAY AS WELL, DUE TO MELTING OF RUBBER AND PLASTIC IN THE CAR. FIRE REPORTED TO INSURANCE COMPANY. CAR WAS NOT DRIVEABLE AS PER FIRE CHIEF-CAR WAS TOWED TO AUTO BODY SHOP.

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.