

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

02-AUG-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

726422

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of vehicle or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	CHEVROLET TRU	ASTRO	1995	

Purchase Date 01-MAY-1995	Dealer's Name _____	Engine Size (CID/CC/L _____)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☒ Van ☐ Minivan ☐ Other	Body Style ☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other
--	---	---	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02190000	Part Name(s) SUSPENSION:INDEPENDENT FRONT TORSION BAR	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) 10-JUL-2000 Mileage at Failure(s) 62000 Vehicle Speed at Failure(s) 30	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

TORSION BAR BROKE CAUSING \$1,100.00 REPAIR BILL AND INABILITY TO STEER PROPERLY. MECHANIC STATED IT IS A KNOWN PROBLEM WITH 95 ASTRO AND SHOWED PART AND WHY IT HAS BEEN A PROBLEM IN NORTHERN CLIMATES. HAD IDENTICAL VEHICLE IN FOR SAME REPAIR WITH SIMILAR MILEAGE. CLAIMS CHEVY KNOWS AND CHANGE SUBSEQUENT DESIGN FOR LATER VEHICLES. CHEVY WAS NOT RESPONSIVE AND REFERRED ME TO NHTSA. ANY INFORMATION WOULD BE APPRECIATED. IF IT IS A PROBLEM IN THE SNOW BELT STATES, SHOULDN'T THERE BE A RECALL? THANKS! *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.