

U.S. Department  
of TransportationNational Highway  
Traffic Safety  
Administration

DOT Auto Safety Hotline

**Vehicle Owner's Questionnaire (VOQ)**

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

02-AUG-2000

Od\_or \_\_\_\_\_  
rt\_dt \_\_\_\_\_  
od\_rt \_\_\_\_\_  
up\_ltr \_\_\_\_\_

Reference No.

726479

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_ Date \_\_\_\_/\_\_\_\_/\_\_\_\_

## VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) <small>(located at front of vehicle or on driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1HGCD5637TA299678	HONDA	ACCORD	1996	

Purchase Date 01-JUL-1996	Dealer's Name _____	Engine Size (CID/CCL) 2200	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injection
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Restraint System <input type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driver Side Airbag <input type="checkbox"/> Passenger Side Airbag <input type="checkbox"/> Inflator <input checked="" type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input checked="" type="checkbox"/> Front <input type="checkbox"/> Rear <input type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other <input type="checkbox"/> Sport Util <input type="checkbox"/> Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Station Wagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other
--	---	---	--	---	--	---

## FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000 12422000	Part Name(s) ENGINE INTERIOR SYSTEMS:INSTRUMENT PANEL:GAUGE:INDICATOR:OIL	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No. of Failures	Date(s) of Failure(s) 01-AUG-2000 Mileage at Failure(s) 87573 Vehicle Speed at Failure(s) 40	Failed Part(s) Available?   Yes   No	NHTSA Previously Contacted?   Yes   No

## APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	---------------------------	---

## NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

RE-SUBMIT//STATE REPORTED INCORRECTLY. WHILE DRIVING OIL LIGHT INDICATOR CAME ON/LOST ALL OIL IN ENGINE. NO PRIOR WARNING. ABLE TO MAKE IT TO DEALER TOLD THAT BALANCE SHAFT SEAL POPPED OUT AND ALSO CAM SHAFT SEAL POPPED OUT AT SAME TIME. REQUIRED TO REPLACE BOTH SEALS AND ALL FLUIDS/ALL BELTS REPLACED -COST - \$483.22. DEALER CLAIMED NO KNOWLEDGE OF PRIOR NOTIFICATION FROM MANUFACTURER OF PROBLEM OR OFFER TO CONTACT MANUFACTURER FOR PAYMENT AND COST RESPONSIBILITY. ABLE TO OBTAIN INFORMATION FROM THIS SITE THAT SERVICE BULLETINS ISSUED ON BOTH 1995/1996 HONDA ACCORDS WITH THIS PROBLEM. DISLODGED SEAL ON THE FRONT BALANCER SHAFT. DATED 10/96. BILL NOT PAID. CONTACTED MANUFACTURER AT FIRST ACKNOWLEDGED DEFECT AND REMED

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.