

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

07-AUG-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

726877

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMDU34X4NUD19041	FORD TRUCK	EXPLORER	1992	

Purchase Date 01-JUN-1992	Dealer's Name _____	Engine Size (CID/CC/L) 4.0 L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02700000 02000000	Part Name(s) TIRES SUSPENSION	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) 27-NOV-1999 Mileage at Failure(s) 110000 Vehicle Speed at Failure(s) 70	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

REPLACEMENT TIRES WERE SAME AS FACTORY ORIGINAL, RATED AT 50,000 MILES. AT 40,000 MILES, BEGAN TO EXPERIENCE VIBRATION, THE SOURCE OF WHICH COULD NOT ACCURATELY BE IDENTIFIED BY MECHANIC. (U-JOINT AND SEVERAL BEARINGS REPLACED TO NO EFFECT). DURING DRIVING TRIP TO LITTLE ROCK FOR THANKSGIVING, VIBRATION WORSENER, WHICH I ATTRIBUTED TO BAD ROAD SURFACE CONDITIONS IN MO AND AR. DURING RETURN TRIP TO KANSAS CITY FROM LITTLE ROCK, APPROX. 100 MILES WEST OF LITTLE ROCK ON WB I-40, RIGHT REAR TIRE TREAD FAILED, DELAMINATING COMPLETELY FROM TIRE CORE AT 70 MPH. LOST CONTROL OF VEHICLE AND TRAVELED DOWN GRASS EMBANKMENT OF CENTER MEDIAN, HIT CONCRETE DRAINAGE WAY AT CENTER, AND CONTINUED UP THE OPPOSITE EMBANKMENT TOWARD ONCOMING EB TRAFFIC. REGAINI

CONTINUED ON BACK (RELEVANT)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.