

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

258

Date Received

31-AUG-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

729670

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of vehicle or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
WV2YB025XH046199	VOLKSWAGEN	TD VANAGON	1987	

Purchase Date 01-JUN-1997	Dealer's Name _____	Engine Size (CID/CCL) <u>2.1 L</u>	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Driver's Side Airbag ☐ Passenger's Side Airbag ☐ Motorized ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☒ Van ☐ Minivan ☐ Other _____	Body Style ☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Station Wagon ☐ Pick Up Truck ☐ Other _____
--	---	--	--	---	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06130000	Part Name(s) FUEL: FUEL LINES FITTINGS AND PUMP	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures 1	Date(s) of Failure(s) <u>23-AUG-2000</u> Mileage at Failure(s) <u>180000</u> Vehicle Speed at Failure(s) <u>2</u>	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

PUMP CORROSION DUE TO STEEL/ALUMINUM INTERACTION. STEEL BRACKET CLAMPING ALUMINUM FUEL PUMP CAUSED PUMP CORROSION TO THE EXTENT THAT FUEL LEAKED FROM PUMP CASE

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.