

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

05-SEP-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

730290

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FAPP46V1WF209968	FORD	MUSTANG	1998	

Purchase Date 01-MAY-1998	Dealer's Name _____	Engine Size (CID/CC/L) 4.6	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000	Part Name(s) ENGINE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 2	Date(s) of Failure(s) 03-JUL-2000 Mileage at Failure(s) 37913 Vehicle Speed at Failure(s) 60	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE KNOCKS UNDER LOAD. KNOCK DISAPPEARS AT IDLE AND LOW LOAD. DEALER IS REPLACED ENGINE...ENGINE WAS NOT DISMANTLED TO DETERMINE ACTUAL CAUSE. REPLACEMENT ENGINE INSTALLED ALSO BLEW LAST WEEK (9/1/2000) AND THE DEALER IS ORDERING A SECOND REPLACEMENT. I HAD TO PURCHASE AN EXTENDED WARRANTY WITH THE FIRST REPLACEMENT AND MAY HAVE TO PAY SOME TYPE OF DEDUCTIBLE WITH THIS SUBSEQUENT REPLACEMENT. LOOKING FOR REPEATED INCIDENTS WITH THE COBRA 4.6 ENGINE. JUST FOR CLARIFICATION, THE DEALER HAS BEEN MORE THAN HELPFUL IN ATTEMPTING TO RESOLVE THE PROBLEM, BUT THE ENGINES BEING DELIVERED APPEAR TO BE REMANUFACTURED ENGINES.

CONTINUED ON BACK (RELEAS)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 258

Date Received

05-SEP-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

730290

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FAPP46V1WF209968	FORD	MUSTANG	1998	

Purchase Date 01-MAY-1998	Dealer's Name _____	Engine Size (CID/CC/L) 4.6	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000	Part Name(s) ENGINE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 2	Date(s) of Failure(s) 03-JUL-2000 Mileage at Failure(s) 37913 Vehicle Speed at Failure(s) 60	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE KNOCKS UNDER LOAD. KNOCK DISAPPEARS AT IDLE AND LOW LOAD. DEALER IS REPLACED ENGINE...ENGINE WAS NOT DISMANTLED TO DETERMINE ACTUAL CAUSE. REPLACEMENT ENGINE INSTALLED ALSO BLEW LAST WEEK (9/1/2000) AND THE DEALER IS ORDERING A SECOND REPLACEMENT. I HAD TO PURCHASE AN EXTENDED WARRANTY WITH THE FIRST REPLACEMENT AND MAY HAVE TO PAY SOME TYPE OF DEDUCTIBLE WITH THIS SUBSEQUENT REPLACEMENT. LOOKING FOR REPEATED INCIDENTS WITH THE COBRA 4.6 ENGINE. JUST FOR CLARIFICATION, THE DEALER HAS BEEN MORE THAN HELPFUL IN ATTEMPTING TO RESOLVE THE PROBLEM, BUT THE ENGINES BEING DELIVERED APPEAR TO BE REMANUFACTURED ENGINES.

CONTINUED ON BACK (RELEAS)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.