



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

Auto Safety Hotline

## Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393  
DC METRO AREA (202) 366-0123  
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

05-JAN-2001

Od\_or \_\_\_\_\_  
R\_dt \_\_\_\_\_  
Pd\_rt \_\_\_\_\_  
Ip\_ltr \_\_\_\_\_

Reference No.

738819

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_

Date \_\_\_\_/\_\_\_\_/\_\_\_\_

### VEHICLE INFORMATION

Vehicle Ident. No. (VIN): <small>(Located at bottom of windshield on driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	HONDA TRUCK	PASSPORT	1998	

Purchase Date <b>01-AUG-2098</b>	Dealer's Name _____	Engine Size (CID/CCL) _____	<input type="checkbox"/> Turbo
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No Cylinders _____	<input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input type="checkbox"/> Fuel Injection

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> Passengerside Airbag <input type="checkbox"/> Motorbelt <input type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input type="checkbox"/> Front <input type="checkbox"/> Rear <input checked="" type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other <input type="checkbox"/> Sport Util Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input checked="" type="checkbox"/> Other
--	---	--	--	---	--	--

### FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06640000 03250000	Part Name(s) EXHAUST SYSTEM:TAIL PIPE BRAKES:HYDRAULIC:ANTI-LOCK SYSTEM	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No. of Failures	Date(s) of Failure(s) 15-JUN-2099 Mileage at Failure(s) 10000 Vehicle Speed at Failure(s) 20	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No

### APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	---------------------------	---

### NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE PROBLEM THAT I STARTED HAVING WITH THE TRUCK AT ABOUT 10000 MILES IS THAT THE VEHICLE CONTINUES TO ACCELERATE ON ITS OWN WHEN I RELEASE THE ACCELERATOR AND PRESS THE BRAKE. THE PROBLEM HAS PERSISTED FOR QUITE SOME TIME DESPITE NUMEROUS TRIPS TO THE HONDA DEALERSHIP. IN AUGUST OF 99 I TOOK THE CAR INTO THE HONDA DEALERSHIP IN ALBANY, GA AND THEY INFORMED ME THAT THE PROBLEM WAS DUE TO AN ELECTRICAL PROBLEM. THEY SAID IT WAS FIXED. I TOOK THE CAR INTO THE SAME DEALERSHIP IN NOVEMBER OF 2000. THEY KEPT THE CAR FOR TWO DAYS AND SAID THAT THEY IDENTIFIED THE PROBLEM AND THAT THE PROBLEM WAS WITH SOME OF THE ELECTRICAL CONNECTORS. THE PROBLEM WAS NOT FIXED. THE VEHICLE IS CURRENTLY AT THE HONDA DEALERSHIP IN NEWBURG,

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-502 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.