



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

05-JAN-2001

Od_or _____
R_dt _____
Pd_rt _____
Ip_ltr _____

Reference No.

738858

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? YES NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____

Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) <small>(Located at bottom of dashboard on driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1HGCD5665RA129743	HONDA	ACCORD	1994	

Purchase Date 01-MAY-2094	Dealer's Name _____	Engine Size (CID/CCL) 2.2L	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injection
<input checked="" type="checkbox"/> New <input type="checkbox"/> Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input checked="" type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> Passengerside Airbag <input type="checkbox"/> Motorbelt <input type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input type="checkbox"/> Front <input type="checkbox"/> Rear <input checked="" type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other <input type="checkbox"/> Sport Util Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input checked="" type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input type="checkbox"/> Other
--	---	--	--	---	--	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05450000 08530002	Part Name(s) ENGINE-OTHER PARTS ELECTRICAL SYSTEM:IGNITION:COIL	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No. of Failures 1	Date(s) of Failure(s) 26-DEC-2098 Mileage at Failure(s) 75579 Vehicle Speed at Failure(s) 75	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE INTERSTATE DRIVING, CAR (ENGINE) SUDDENLY SHUTS DOWN. NOTICED RPM DROPS TO 0 AT THE INSTANT OF THE SHUTDOWN. LOST STEERING CAPABILITY (STEERING WHEEL HARD TO TURN IN ANY DIRECTION), LOST ACCELERATION POWER. HAD TO DRIFT OFF TO SIDE OF HIGHWAY. LUCKILY NO TRAFFIC IMMEDIATELY BEHIND. CAR TOWED TO DEALER. DEALER DETERMINED IGNITOR COIL, IGNITOR U AND ENGINE OIL SEAL ALL FAILED. LOST ALL OIL FROM ENGINE. DEALER REPLACED COIL IGNITOR, IGNITOR U, T-BELTS, OIL SEALS, WATER PUMP, COOLANT AND RUBBER, ACCORDING TO PARTS LISTING ON INVOICE. DAMAGE AMOUNTED TO \$837.33. HONDA NOW RECALLING AND REPAIRING OIL SEAL BUT WILL NOT REIMBURSE FOR WATER PUMP, EXTERIOR BELTS OR THE TWO IGNITION/IGNITOR PARTS REPLACED. THIS WAS A MAJOR FAILURE THAT COULD

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-576 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.