



U.S. Department  
of Transportation  
National Highway  
Traffic Safety  
Administration

Auto Safety Hotline

## Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393  
DC METRO AREA (202) 366-0123  
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

01-FEB-2001

Od\_or \_\_\_\_\_  
R\_dt \_\_\_\_\_  
Pd\_rt \_\_\_\_\_  
Ip\_ltr \_\_\_\_\_

Reference No.

740311

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?  YES  NO  
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner \_\_\_\_\_

Date \_\_\_\_/\_\_\_\_/\_\_\_\_

### VEHICLE INFORMATION

Vehicle Ident. No. (VIN) <small>(Located at bottom of windshield on driver's side)</small>	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	ISUZU TRUCK	TROOPER	2000	

Purchase Date <b>01-AUG-2000</b> <input checked="" type="checkbox"/> New <input type="checkbox"/> Used	Dealer's Name _____ City _____ State _____ Zip Code _____	Engine Size (CID/CCL) _____ No Cylinders _____	<input type="checkbox"/> Turbo <input type="checkbox"/> Diesel <input type="checkbox"/> Gas <input checked="" type="checkbox"/> Fuel Injection
--	--	---	---

Transmission Type <input type="checkbox"/> Manual <input type="checkbox"/> Automatic	Antilock Brakes <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Restraint System <input type="checkbox"/> 3-Point Belt <input type="checkbox"/> Driverside Airbag <input type="checkbox"/> Passengerside Airbag <input type="checkbox"/> Motorbelt <input type="checkbox"/> 2-Point Belt	Cruise Control <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No	Drive Train <input type="checkbox"/> Front <input type="checkbox"/> Rear <input checked="" type="checkbox"/> 4-Wheel	Vehicle Type <input type="checkbox"/> Car <input type="checkbox"/> Van <input type="checkbox"/> Minivan <input type="checkbox"/> Other _____ <input type="checkbox"/> Sport Util Truck <input type="checkbox"/> Motorcycle	Body Style <input type="checkbox"/> 2-Door <input type="checkbox"/> 4-Door <input type="checkbox"/> Stationwagon <input type="checkbox"/> Pick Up Truck <input checked="" type="checkbox"/> Other _____
--	---	---	--	---	--	--

### FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06410000 12420000	Part Name(s) FUEL THROTTLE LINKAGES AND CONTROL PEDAL INTERIOR SYSTEMS: INSTRUMENT PANEL GAUGE INDICATOR	Location <input type="checkbox"/> Left <input type="checkbox"/> Front <input type="checkbox"/> Right <input type="checkbox"/> Rear	Failed Part(s) <input type="checkbox"/> Original <input type="checkbox"/> Replacement
No. of Failures <b>4</b>	Date(s) of Failure(s) 24-OCT-2000 Mileage at Failure(s) 4500 Vehicle Speed at Failure(s)	Failed Part(s) Available? <input type="checkbox"/> Yes <input type="checkbox"/> No	NHTSA Previously Contacted? <input type="checkbox"/> Yes <input type="checkbox"/> No

### APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash <input type="checkbox"/> Yes <input type="checkbox"/> No	Fire <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
---	---	---------------------------	----------------------	---------------------------	---

### NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE CHECK ENGINE LIGHT KEPT COMING ON INTERMITTENTLY BACK IN OCTOBER (ABOUT ONCE A WEEK FOR THREE WEEKS) TOLD THAT IT WAS A PROBLEM WITH OUR FOOT TOUCHING THE ACCELERATOR BEFORE STARTING THE CAR. CAME ON AGAIN AND I DROVE IT RIGHT IN AND THEY SAID THEY COULDN'T FIND ANYTHING. WATCH OUR DRIVING HABITS! CAME ON AND STAYED ON FOR 9 DAYS STRAIGHT. BROUGHT IT OUT AND DEALER SAID IT DIDN'T HAPPEN WHEN THEY HAD IT BUT AFTER DOING THE OIL CHANGE THEY STARTED UP THE CAR AND SAID THAT IT CAME ON AND NEEDED A THROTTLE ADJUSTMENT. BROUGHT IT BACK OUT FOR THE THROTTLE ADJUSTMENT AND PROBLEM SEEMED TO HAVE DISSAPPEARED. ONE DAY IT CAME BACK ON AGAIN. BROUGHT IT OUT AND THE COMPUTER ACKNOWLEDGED ANOTHER MINOR ADJUSTMENT TO THE THROTTLE WAS

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.