



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

23-APR-2001

Ord. or
rt. dt
pd. rt
up. ltr

Reference No.

744415

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1G2WJ52K6VF269406	PONTIAC	GRAND PRIX	1997	

Purchase Date 01-FEB-1997	Dealer's Name _____	Engine Size (CID/CC/L) 3.8 L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08320000	Part Name(s) ELECTRICAL SYSTEM:WIRING:HARNES:UNDER DASH	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 12-APR-2001 Mileage at Failure(s) 36300 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WIRING HARNESS THAT PROVIDES ELECTRICITY TO BOTH THE DRIVER SIDE AND PASSENGER SIDE AIRBAGS WITHIN THE DASHBOARD HAD FAILED AS A RESULT OF A HIGH RESISTANCE CONNECTION FAILURE. THE PROBLEM WAS UNCOVERED BY THE DEALER AFTER THE AIRBAG WARNING LIGHT CAME ON. THE DEALER'S MECHANIC STATED THIS DISABLED BOTH AIRBAGS AND THAT HE HAD PERSONALLY REPLACED AT LEAST 20 OF THESE HARNESSES FOR SAME PROBLEM. ANOTHER PERSONAL CONTACT AT ANOTHER PONTIAC DEALER STATED THAT "DOZENS" OF THESE HARNESSES HAVE BEEN REPLACED IN THEIR SHOP. THIS IS AN EXPENSIVE REPAIR OF \$400.00 TO REMEDY THE PROBLEM IF NOT UNDER WARRANTY TIMEFRAME. PART HAS SINCE BEEN RE-DESIGNED TO CORRECT HIGH RESISTANCE CONNECTION PROBLEM.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.