



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

15-JUN-2001

Ord. or
rt. dt
pd. rt
up. hr

Reference No.

746893

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FMYU01131KE73665	FORD	ESCAPE	2001	

Purchase Date 01-AUG-2000	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____
--	---	---	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02100000	Part Name(s) SUSPENSION:INDEPENDENT FRONT	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failure 1	Date(s) of Failure(s) 11-JUN-2001 7600 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HAD SEVERE VIBRATION OF STEERING WHEEL AT SPEEDS OF 75 MPH OR GREATER. DEALER SAID IT WAS THE AFTER MARKET RIMS INSTALLED ON THE VEHICLE. WHEN DEALER INSTALLED THE STOCK RIMS AND TOOK IT OUT AND TESTED IT, THE VIBRATION WAS STILL THERE WHEN HE ACHIEVED A SPEED OF 75 MPH OR BETTER. DEALER RE-BALANCED THE WHEELS AND PROBLEM STILL OCCURED. DEAR CHECKED THE ALIGNMENT AND SAID IT WAS OUT OF ALIGNMENT AND PROBABLY CAME THAT WAY FROM THE MANUFACTURER. AFTER FRONT END ALIGNED NO MORE PROBLEMS. AS FOR PROB#2, I NOTICED SOME PINK FLUID LEAKING FROM UNDER THE VEHICLE. TOOK TO DEALER AND HAD THEM PUT IT ON A RACK TO INSPECT IT. THEY FOUND THAT THE POWER STEERING FLUID IS LEAKING AT THE LEFT SIDE OF BOOT. THEY HAVE TO REPLACE THE ENTIRE RACK & PINION UNIT. ARE THERE ANY OTHER ESCA

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.