



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

17-AUG-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

750658

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2GTFC29S2T1531713	GMC	C2500	1996	

Purchase Date 01-NOV-1996	Dealer's Name _____	Engine Size (CID/CC/L) 6.5L	☒ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other _____
--	---	---	--	---	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06300000	Part Name(s) FUEL:FUEL INJECTION SYSTEM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
-----------------------	--	--	---

No of Failure 6	Date(s) of Failure(s) 30-AUG-1998 18000 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
--------------------	--	--	--

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	--------------------------------	---------------------------	-------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FUEL INJECTION PUMP HAS FAILED AND BEEN REPLACED 6 TIMES OVER THE LIFE OF THE VEHICLE .ONE FAILURE RESULTED IN FUEL LEAKING ON EXHAUST SYSTEM THIS COULD HAVE BEEN EXTREMELY DANGEROUS.WIPER FAILURES IS AN ONGOING PROBLEM WICH OCCURS INTERMITTENTLY AND UNEXPECTEDLY -VERY DANGEROUS !!! MY FIANCE ALSO OWNS A 1996 GMC C1500 WHICH HAS THE SAME PROBLEM WE HAVE BEEN TOLD BY DEALER THAT ONLY A SELECT GROUP OF VEHICLES HAS A RECALL ISSUED AND A GM TECHNICIAN HAS TOLD US THAT THE SAME WIPER CIRCUIT BOARD HAS BEEN USED ON SEVERAL DIFFERENT GM VEHICLES OVER A TEN YEAR SPAN. GM SHOULD BE FORCED TO REPAIR ANY GM VEHICLE AFFECTED BY THIS SERIOUS SAFETY ISSUE AND OFFER A REFUND TO ANY CUSTOMER THAT HAS HAD AN OUT OF POCKET EXPENSE !!!!!*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.