



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

19-AUG-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

750735

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield and door side)	Vehicle Make FORD	Vehicle Model ESCAPE	Vehicle Year 2001	Current Odometer Reading
Purchase Date 01-OCT-2000	Dealer's Name _____		Engine Size (CID/CC/L) 3L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 07380000	Part Name(s) POWER TRAIN:TRANSMISSION:AUTOMATIC:COOLING UNIT AND	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 2	Date(s) of Failure(s) 17-AUG-2001 Mileage at Failure(s) 17000 40	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HOSE CLAMPS ON BOTH TRANS COOLER HOSES IN FRONT OF VEHICLE WERE NOT FIXED ONTO HOSE. TOP HOSE BLEW FROM TRANSMISSION COOLER AND RESULTED IN LOSE OF MOST ALL TRANS FLUID. TRANS STOPED WORKING. FLUID WAS ALL OVER FRONT LOWER PART OF VEHICLE INCLUDING BOTH INSIDES OF DISK BRAKES. WE WERE TRAVELING AT 40 MPH AND IN A RESIDENTIAL AREA. WARRANTY REPAIR IS IN PROGRESS. TOW TRUCK OPERATOR STATED THIS WAS NOT THE FIRST TIME HE HAD ENCOUNTERED THIS SITUATION WITH THIS PARTICULAR VEHICLE.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.