



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

19-NOV-2001

Ord. or
rt. dt
pd. rt
up. ltr

Reference No.

754681

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) JT3AC24S4S1045401	Vehicle Make TOYOTA TRUCK	Vehicle Model PREVIA	Vehicle Year 1995	Current Odometer Reading
--	-------------------------------------	--------------------------------	-----------------------------	--------------------------

Purchase Date 01-JUN-1995	Dealer's Name _____	Engine Size (CID/CC/L) 2.4 L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
	Drive Train ☐ Front ☐ Rear ☒ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150000	Part Name(s) ENGINE:OTHER PARTS	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 15-JUL-1998 Mileage at Failure(s) 53212 Vehicle Speed at Failure(s)	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

CAR LOSES POWER WHEN TURNING CORNERS AND CLIMBING HILLS. PROBLEM CURRENTLY DOESN'T OCCUR WHEN USING PREMIUM GAS, AS SUGGESTED BY OUR INDEPENDENT MECHANIC WHO WAS UNABLE TO DIAGNOSE THE PROBLEM WHEN IT FIRST OCCURRED IN 1998. DEALER SERVICE REP, WHO DIAGNOSED THE PROBLEM IN NOVEMBER 2000, SAYS THAT THE MATERIAL WHICH TOYOTA USED FOR THE ENGINE BLOCK IN THE SUPERCHARGED PREVIA WAS TOO SOFT SO THE ENGINE DEVELOPED SECONDARY AND TERTIARY RIDGE RINGS WHICH, AS I UNDERSTAND IT, CAUSE THE ANTI-KNOCK SENSOR TO CUT POWER TO THE ENGINE UNDER CERTAIN CIRCUMSTANCES. IT IS MASKED WHEN USING PREMIUM GAS WHICH BURNS HOTTER BUT HE SAID THAT AS THE RIDGE RINGS BECOME MORE PRONOUN

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.