



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

29-NOV-2001

Od or

rt dt

od rt

ip tr

Reference No.

755076

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield and door side) 1G8ZJ8271WZ141641	Vehicle Make SATURN	Vehicle Model SW2	Vehicle Year 1998	Current Odometer Reading
---	-------------------------------	-----------------------------	-----------------------------	--------------------------

Purchase Date 01-APR-1998	Dealer's Name _____	Engine Size (CID/CC/L) LL0 1.	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
		Drive Train ☒ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____
			Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06400000	Part Name(s) FUEL THROTTLE LINKAGES AND CONTROL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 3	Date(s) of Failure(s) 01-NOV-2001	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 61000		
	Vehicle Speed at Failure(s) 0		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THIS IGNITION-HIGH IDLE PROBLEM HAS EXHISTED SINCE OWNERSHIP AND FIRST PART REPLACEMENT UNDERWARRANTY WAS THE IDLE AIR CONTROL J5542 IN FEB. 2000. THE IDLE ACCELERATION PROBLEM STARTED IN 1999, HOWEVER, COULD NOT BE REPEATED DURING TESTS DRIVE UNTIL FEB. 15,2000. AT THE 42,000 SERVICE THE SAME COMPLAINT WAS ADDRESSED WITH THE IAC MOTOR REPLACED. THE 60,000 MILE SERVICE THE TEMP. SENSOR AND IGNITION MODULE WAS REPLACED FOR \$391.00, AND THE PROBLEM OF ACCELERATION CONTINUES WITH THE RPM'S OVER 2,000. I AM CONCERNED FOR MY SAFETY. THE CAR HAS ACTUALLY ACCELERATED WITHOUT GAS/OR CLUTCH CHANGES. IF I WERE ON ICE, WHICH THIS AREA IS NOTED FOR IN THE WINTER, I WOULD BE IN DANGER. AGAIN, THIS HAPPENS WH

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.