



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

23-JAN-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

757219

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield and door side) 3FCMF53G7VJA06227	Vehicle Make COACHMEN	Vehicle Model SANTARA	Vehicle Year 1997	Current Odometer Reading
Purchase Date 01-JAN-2000	Dealer's Name _____		Engine Size (CID/CC/L 460 CI)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☒ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08210000	Part Name(s) ELECTRICAL SYSTEM:WIRING:HARNES:FRONT:UNDERHOOD	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part's ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 10-NOV-2001	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 32904		
	Vehicle Speed at Failure(s) 0		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☒ Yes ☐ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

A DEFECTIVE WIRE HARNESS STARTED THE FIRE AS DETERMINED BY THE TECHNICIANS WHO REPAIRED THE VEHICLE. A LOCAL FIRE DEPARTMENT WAS REQUIRED TO EXTINGUISH THE FIRE COMPLETELY. VEHICLE HAD BEEN STOPPED FOR ABOUT 10 MINUTES WHEN FIRE BROKE OUT. I HAVE MUCH MORE DOCUMENTATION ON THE INCIDENT AVAILABLE TO ANYONE. A FIRE DEPARTMENT REPORT WAS MADE AND IS ALSO AVAILABLE AS WELL AS ALL INSURANCE COMPANY INFORMATION, REPAIR FACILITY INFORMATION, LETTERS TO THE MANUFACTURER, DETAILED DESCRIPTIONS OF THE FIRE EVENT, ETC.*AK

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.