



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

11-FEB-2002

Od_or _____
rt_dt _____
od_rt _____
up_lr _____

Reference No.

758089

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) 1B4GP44R3YB518787	Vehicle Make DODGE TRUCK	Vehicle Model GRAND CARAVA	Vehicle Year 2000	Current Odometer Reading
Purchase Date 01-MAR-2001	Dealer's Name _____		Engine Size (CID/CC/L) 3.7	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☒ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☒ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05100000 12430000	Part Name(s) ENGINE INTERIOR SYSTEMS:INSTRUMENT PANEL:SPEEDOMETER:ODOM	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 07-FEB-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 56190		
	Vehicle Speed at Failure(s) 60		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

SPEEDOMETER ERRATIC WHILE DRIVING FREEWAY SPEEDS. THE SPEEDOMETER WILL JUMP TO 120 CAUSING THE ENGINE TO STALL IF THE NEED IS NOT RELEASED. THIS HAPPEN ON THE FREEWAY AND HAD TO COAST OVER TO THE EMERGENCY LANE "IMEDIATLY". THE CAUSE WAS THE RSS SPEED SENSOR (203 C 4800879 AND THE OUTPUT RSS SPEED SENSOR 204 C) THIS IS A MAJOR SAFTY ISSUE WHEN IT STALL ON THE FREEWAY WITH MY FAMILY IN THE MINIVAN. THIS SHOULD NOT HAVE BEEN A REPAIR PAYED FOR BY THE CONSUMER FOR FAULTY DESIGN! *AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.