



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

11-MAR-2002

Od_or _____
rt_dt _____
od_rt _____
ip_lr _____

Reference No.

759233

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door) 1FTBR10A1HUB62351	Vehicle Make FORD TRUCK	Vehicle Model EXPEDITION	Vehicle Year 2000	Current Odometer Reading
Purchase Date 01-DEC-1999	Dealer's Name _____		Engine Size (CID/CC/L) 5.4L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 03273000	Part Name(s) BRAKES:HYDRAULIC:DISC:ROTOR:DISC HUB	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part's ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 03-MAR-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 27300		
	Vehicle Speed at Failure(s) 10		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag 0	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	--------------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WITH NO WARNING OR INDICATION, THE RIGHT BRAKE BEGAN A GRINDING SOUND AND WAS REPORTED TO THE DEALER FOR ANALYSIS. THOUGH UNDER WARRENTY, THE REPORT WAS A \$700 REPAIR FOR A NEW ROTOR. THE SERVICE MANAGER REPORTS THIS IS COMMON AND OWNERS NEED TO REPORT THIS.*AK

CONTINUE ON PAGE 2 IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.