



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

11-APR-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

760571

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side) 1FMRU17LX2LA51925	Vehicle Make FORD TRUCK	Vehicle Model EXPEDITION	Vehicle Year 2002	Current Odometer Reading
Purchase Date 01-DEC-2001	Dealer's Name _____		Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____		No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☒ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 15600000	Part Name(s) EQUIPMENT:ELECTRIC EQUIPMENT:RADIO:TAPE DECK ETC.	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 01-JAN-2002	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No
	Mileage at Failure(s) 100		
	Vehicle Speed at Failure(s)		

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
---	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

THE RADIO COMPONENT OVERHEATS TO THE EXTENT THAT CASSETTES AND CDS ARE HOT - NOT WARM- TO THE TOUCH. OTHER BUTTONS ON THE DASH ARE HOT TO TOUCH. DEALER INSTALLED A FAN BEHIND THE RADIO TO COOL IT DOWN, BUT THIS DID NOT SOLVE THE PROBLEM..IT ONLY REDISTRIBUTED THE HEAT. CLIMATE CONTROL BUTTONS ARE STILL HOT TO TOUCH. FORD SAYS THIS IS "NORMAL" AND THIS IS THEIR SOLUTION. SEEMS LIKE THEY ONLY TRIED TO TAKE CARE OF SYMPTOM, NOT SOLVE A PROBLEM. ALSO, BECAUSE FAN IS SILENT, WE WON'T KNOW IF FAN MALFUNCTIONS UNTIL IT'S TOO LATE. SOMETHING'S LIABLE TO MELT.*AK

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.