



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 258

Date Received

30-MAY-2002

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

762469

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Location at bottom of windshield and driver's side door) JTHBN30F710005065	Vehicle Make LEXUS	Vehicle Model LS430	Vehicle Year 2001	Current Odometer Reading
--	------------------------------	-------------------------------	-----------------------------	--------------------------

Purchase Date 01-OCT-2000	Dealer's Name _____	Engine Size (CID/CC/L) 4.3L	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No
	Drive Train ☐ Front ☒ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 15300000	Part Name(s) EQUIPMENT: SPEED CONTROL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 1	Date(s) of Failure(s) 14-APR-2002 Mileage at Failure(s) 12000 Vehicle Speed at Failure(s) 65	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☐ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
---	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

LASER SENSOR IS LOCATED, UNPROTECTED, IN RECESS IN FRONT BUMPER OF CAR. AT SOME TIME DURING RECENT ROAD TRIP AN OBJECT, PROBABLY A STONE, CAUSED A CRACK IN LENS OF CRUISE CONTROL MODULE. THIS CAUSED CRUISE CONTROL TO MALFUNCTION BY SUDDENLY MISREADING LOCATION AND DISTANCE OF CARS IN FRONT OF MY VEHICLE. NO PROTECTIVE COVER OR LENS REPLACEMENT IS PROVIDED TO PREVENT THIS PROBLEM OR MITIGATE EXPENSE OF CORRECTING THE PROBLEM.*AK

CONTINUE ON REVERSE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.