

784449

From: siracusa@publicinteractive.com
To: Young, Beverly <NHTSA>, Jimenez, Alberto <NHTSA>, Chiang, George <NHTSA>
Date: 1/27/00 8:20AM
Subject: Car Talk VOQ submission

* This data was submitted via a fill-in form at the Cartalk web site
* (<http://www.cartalk.cars.com/Tools/nhtsa.pl>) If you have any problems
* or suggestions regarding the format of this submission, send email
* to webmaster@cartalk.com

SUBMISSION DATE: Wednesday, January 26th 2000 at 5:23:09 PM

VEHICLE OWNER'S QUESTIONNAIRE
=====OWNER INFORMATION

NAME

ADDRESS
City

TELEPHONE: 6506651354

NHTSA authorized to send a copy of this report to the manufacturer: Yes

VEHICLE INFORMATION

VIN: JA3XE74C5MY012227
MAKE: Mitsubishi
MODEL: 3000GT VR4
YEAR: 1991

ODOMETER: 75414
PURCHASE DATE: NEW OR USED:

DEALER NAME:
ADDRESS: St.Louis, Mo

ENGINE SIZE: 3000cc
CYLINDERS: 6

FUEL INJECTION: Yes
TURBO: Yes
FUEL TYPE: Gas
ANTILOCK BRAKES: Yes
CRUISE CONTROL: Yes
DRIVETRAIN: 4 Wheel

DRIVER AIRBAG: Yes
PASSENGER AIRBAG: No
3-POINT BELT: Yes
MOTOR BELT: No
2-POINT BELT: No
BODY STYLE: Hatch Back

FAILED COMPONENT(S)/PART(S) INFORMATION

COMPONENT: ABS Hydraulic Unit
ECM Control Unit

PART NAME(S): MB668382
MB903852

LOCATION: Left Rear

NUMBER OF FAILURES: One

DATE(S) OF FAILURES: 12/26/99

MILEAGE AT FAILURE(S): 75414

SPEED AT FAILURE(S): 20Mph

MANUFATURER CONTACTED: Yes

NHTSA CONTACTED:

APPLICABLE ACCIDENT INFORMATION

ACCIDENT: No
FIRE: No

NUMBER OF PERSONS INJURED:
NUMBER OF FATALITIES:
ESTIMATED PROPERTY DAMAGE: \$

DRIVER AIRBAG DEPLOYED:
PASSENGER AIRBAG DEPLOYED:

REPORTED TO POLICE:

INFORMATION ON TIRE FAILURE(S) (IF APPLICABLE)

DOT NUMBER: DOT
TIRE MANUFACTURER:
TIRE NAME:
TIRE SIZE:

ADDITIONAL COMMENTS

Although this failure took place at low speed and thus no accident took place, the failure of the ABS system rendered the car immobile and had it taken place at a higher speed, could have been disastrous. The unit replaced cost \$4424.30 including labor. This is for only one side of the car.

END OF FORM
