



 DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline				FOR AGENCY USE ONLY 436	
U.S. Department of Transportation National Highway Traffic Safety Administration				Date Received 11 PM 2:00 04-DEC-2001	
OWNER INFORMATION (Type or Print) 				Od or rt dt od rt up_ltr Reference No. 8001241	
Do you authorize NHTSA to use the information you provide for the purpose of investigating safety defects? Signature of Owner _____ Address of your vehicle? _____ Vehicle manufacturer? ☒ YES ☐ NO Date 1/15/02					
VEHICLE INFORMATION					
Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side) NOT AVAILABLE 1G5D713582A1P6206		Vehicle Make GMC		Vehicle Model ENVOY	
Purchase Date 5/30/01		Dealer's Name MARINA MOTOR		Vehicle Year 2001	
☒ New ☐ Used		City Capitola State CA Zip Code 95073		Current Odometer Reading 9600	
Engine Size (CID/CCIL) 4200		No. Cylinders 6		☐ Turbo Diesel ☒ Gas Fuel Injection	
Transmission Type ☐ Manual ☒ Automatic		Antilock Brakes ☒ Yes ☐ No		Restraint System ☒ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☒ Passengerside Airbag	
Cruise Control ☒ Yes ☐ No		Drive Train ☐ Front Wheel ☒ 4-Wheel		Vehicle Type ☐ Car ☒ Sport Utility Vehicle ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other	
Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up ☐ Truck					
FAILED COMPONENT(S)/PART(S) INFORMATION					
Component 08310000		Part Name(s) ELECTRICAL SYSTEM: WIRING: HARNESS: FRONT: UNDERHOOD		Location ☐ Left Front ☐ Right Rear ☒ Original Replacement	
No. of Failures 1		Date(s) of Failure(s) 08-DEC-2001		Mileage at Failure(s) 7000	
Vehicle Speed at Failure(s) 65 mph		Failed Part(s) ☒ Yes ☐ No		NHTSA Previously ☐ Yes ☒ No	
APPLICATION INCIDENT INFORMATION					
(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)					
Crash ☐ Yes ☒ No		Fire ☐ Yes ☒ No		Number of Persons Injured /	
Number of Fatalities /		Estimated Property Damage /		Reported to Police ☐ Yes ☒ No	
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)					
VEHICLE STALLED OUT ON HIGHWAY AND DIED WITHOUT WARNING DUE TO A DEFECTIVE WIRE HARNESS. DEALER HAS INSPECTED VEHICLE AND WILL REPLACE WIRE HARNESS. *AK not wire harness - See Enclosed Letter & Documentation & other Reports in NHTSA Database					
CONTINUE ON BACK IF NEEDED					
The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response or a statistical summary thereof may be used in support of the agency's action.					


**THE FOLLOWING PAGES ARE WITHHELD TO
PROTECT UNWARRANTED INVASION OF
PERSONAL PRIVACY PURSUANT TO
EXEMPTION 6 OF THE FREEDOM OF
INFORMATION ACT, 5 U.S.C. § 552(b)(6)**


(Page 1 through Page 16)





[The following text is a dense, continuous block of characters and symbols, appearing to be a corrupted or heavily redacted document. It contains no legible words or phrases.]





The first part of the paper discusses the importance of understanding the cultural context of the research. It highlights the need for researchers to be sensitive to the values and beliefs of the communities they are studying. This is particularly important in the field of health research, where cultural differences can significantly impact the effectiveness of interventions.

The second part of the paper presents a case study of a health intervention in a rural community. The study found that the intervention was more successful when it was tailored to the local culture and beliefs. This suggests that a one-size-fits-all approach is not always the best solution.

The third part of the paper discusses the challenges of conducting research in a culturally diverse environment. It emphasizes the need for researchers to have a deep understanding of the community they are studying and to be open to learning from their participants.

The fourth part of the paper concludes by highlighting the importance of ongoing communication and collaboration between researchers and the community. This is essential for ensuring that the research is relevant and useful to the community it is intended to serve.

