



U.S. Department
of Transportation
National Highway

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123

FOR AGENCY USE ONLY 758

Date Received

08-APR-2002

Od_or	_____
rt_dt	_____
pd_rt	_____



U.S. Department of Transportation
 National Highway Traffic Safety Administration
 DOT Auto Safety Hotline
 1-888-DASH-2-DOT
 1-888-327-4238
 www.nhtsa.dot.gov/hotline

Vehicle Owner's Questionnaire (VOQ)

FOR AGENCY USE ONLY 758

Date Received: 08 APR 2002
 Office: DEFECTS INVESTIGATION
 Reference No: 8806998

OWNER INFORMATION (Type or Print)

Home Num: [Redacted]
 Work Num: 746941

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?
 YES NO
 In the absence of an authorized signature, please sign to the vehicle manufacturer.
 Signature of Owner: [Redacted] Date: 4/17/02

Vehicle Ident. No. (VIN): (Located at bottom or windshield on driver's side)
 ADD 1G2HX52K5WH316305
 Vehicle Year: 1998
 Vehicle Make: PONTIAC
 Vehicle Model: BONNEVILLE
 Current Odometer Reading: 115,000

Purchase Date: 1/15/01
 Dealer's Name: Top Line Motors
 City: Owensboro State KY Zip Code: 42302
 New Used

Transmission Type: Automatic Manual
 Restraint System: 3-Point Belt 2-Point Belt Motorcyclist
 Cruise Control: Yes No
 Drive Type: Front Rear 4-Wheel
 Vehicle Type: Car Van Minivan Other
 Body Style: Turbo Diesel Gas Fuel Injecto

Component: 00610000
 Part Name(s): EXHAUST SYSTEM:MANIFOLD:ENGINE
 Location: Left Right Rear
 Failed Part(s): Original Replacement

No of Failures: 1
 Date(s) of Failure(s): 05 APR 2002
 Mileage at Failure(s): 10000
 Vehicle Speed at Failure(s):

APPLICATION INCIDENT INFORMATION
 (Please describe in detail the incident(s), failure(s), crash(es), and injuries) on the back of this form)

Crash: Yes No
 Fire: Yes No
 Number of Persons Injured: 0
 Number of Fatalities: 0
 Estimated Property Damage: 0
 Reported to Police: Yes No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)
 WHILE DRIVING 10-15 MPH ENGINE WAS HEATING. CONSUMER NOTICED A BURNING SMELL. DEALER DETERMINED THAT PLASTIC INTAKE MANIFOLD HAD A HOLE AND WAS LEAKING FLUID ONTO ENGINE. ENGINE HAD TO BE REPLACED. *AK

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

CONTINUE ON BACK IF NEEDED