

DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) U.S. Department of Transportation National Highway Traffic Safety Administration NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 125 Date Received 02-FEB-2000		Od_or _____ Rt_dt _____ od_rt _____ up_ltr _____ Reference No. 856071	
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.					
Signature of Owner _____ Date ____/____/____					
VEHICLE INFORMATION					
Vehicle Ident. No. (VIN) (located at front of windshield on drivers side) 4A3AJ56G1RE107400		Vehicle Make MITSUBISHI	Vehicle Model GALANT	Vehicle Year 1994	Current Odometer Reading
Purchase Date ☐ New ☒ Used	Dealer's Name _____ City _____ State _____ Zip Code _____		Engine Size (CID/CC/L) _____ No Cylinders _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbell ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Ult. Truck ☐ Motorcycle
FAILED COMPONENT(S)/PART(S) INFORMATION					
Component 03281000	Part Name(s) BRAKES:HYDRAULIC:SWITCH:BRAKE WARNING		Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement	
No of Failures	Date(s) of Failure(s) _____ Mileage at Failure(s) _____ Vehicle Speed at Failure(s) _____		Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No	
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)					
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)					
RECALL 98V212000 CONCERNING STOP LAMP SWITCH. RECALL REMEDY DID NOT CORRECT THE PROBLEM. WHEN THE STOP LAMP SWITCH WAS ASSEMBLED GREASE WAS INADVERTENTLY APPLIED TO THE CONTACT POINT. PLEASE GIVE ANY FURTHER DETAILS. *AK					
CONTINUED ON BACK (SEE)					
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.					