

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 150

Date Received

02-MAR-2000

 Od_or _____
 Rt_dt _____
 od_rt _____
 up_ltr _____

Reference No.

857800

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield on drivers side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FALP4048SF222049	FORD	MUSTANG	1995	

Purchase Date	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150021	Part Name(s) ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) _____ Mileage at Failure(s) 62000 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE HEAD GASKET HAS BLOWN AT 62,000 CAUSING COOLANT TO LEAK INTO ENGINE.
 MANUFACTURER'S TSB WILL NOT COVER MUSTANG BECAUSE IT HAD DIFFERENT COOLANT SYSTEM.
 *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 160

Date Received

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

02-MAR-2000

Od or

n_dt

od_rt

up_itr

Reference No.

857800

Work Number

Home Number

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

☒ YES☐ NO

In the absence of an authorized signature, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date 3/22/00

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Recorded on bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FALP40483F222049	FORD	MUSTANG	1995	68989

Purchase Date

1995-July

Dealer's Name Mountain View Ford

Engine Size

(CID/CCAL) 3.8L

☐ Turbo☐ Diesel☒ Gas☐ Fuel Injection☒ New ☐ Used

City CHATTANOOGA

State TN

Zip Code 37408

No Cylinders 6

Transmission Type

☒ Manual☐ Automatic

Antilock Brakes

☒ Yes☐ No

Restraint System

☒ 3-Point Belt☐ Motorbet☐ Driverside Airbag☐ 2-Point Belt☐ Passengerside Airbag

Cruise Control

☒ Yes☐ No

Drive Train

☐ Front☒ Rear☒ 4-Wheel

Vehicle Type

☒ Car☐ Van☐ Minivan☐ Other☐ Sport Ult☐ Truck☐ Motorcycle

Body Style

☒ 2-Door☐ 4-Door☐ Stationwagon☐ Pick Up Truck☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 05150021	Part Name(s) ENGINE:GASKETS:VALVE COVER	Location ☐ Left ☐ Right ☒ Front ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
-----------------------	--	---	--

No of Failures

2

Date(s) of Failure(s)

Feb 00

Mileage at Failure(s)

82000

Vehicle Speed at Failure(s)

Failed Part(s)

Available?

☐ Yes ☒ No

NHTSA Previously

Contacted?

☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage 0	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	--------------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

ENGINE HEAD GASKET HAS BLOWN AT 82,000 CAUSING COOLANT TO LEAK INTO ENGINE. ~~3.0L~~ ~~ENGINE~~ MANUFACTURER'S TSB WILL NOT COVER MUSTANG BECAUSE IT HAD DIFFERENT COOLANT SYSTEM. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.