

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

156

Date Received

21-JUN-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

863940

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located between front fenders or on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
AGKFK16K9SJ716237	GMC	SUBURBAN	1995	

Purchase Date	Dealer's Name _____	Engine Size (CID/CCL) _____	☐ Turbo
☐ New ☒ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	☐ Diesel
			☐ Gas
			☐ Fuel Injection

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other	☐ Sport Vlt ☐ Truck ☐ Motorcycle ☒ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08100000	Part Name(s) ELECTRICAL SYSTEM: BATTERY	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Dates of Failure(s) 01-JUN-1995 Mileage at Failure(s) 6 Vehicle Speed at Failure(s)	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash	Fire	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police
☐ Yes ☒ No	☐ Yes ☒ No				☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

PE99013, DELCO BATTERY LEAKED, AND CAUSED ACID TO SPRAY INTO THE ENGINE COMPARTMENT. DEALER REPLACED BATTERY. PLEASE PROVIDE FURTHER INFORMATION.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 156

Date Received

JUL 18 PM 2:4
21-JUN-2000

OFFICE

DEFECTS INVESTIGATION

Od_or

St_dt

Od_rt

up_lr

Reference No.

863940

OWNER INFORMATION (Type or Print)

KASWELL

615171

Work No.

Home No.

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?
In the absence of an authorized representative, please provide your name and address to the vehicle manufacturer.

☒ YES☐ NO

Signature of Owner

Date 7/10/00

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at bottom of windshield on driver's side)

AGKFK16K8SJ716237

Vehicle Make

GMC

Vehicle Model

SUBURBAN

Vehicle Year

1995

Current Odometer Reading

Purchase Date

12-30-94

Dealer's Name VIKING GMC

Engine Size

(CID/CC/L 5.7

☐ Turbo☐ Diesel☐ Gas☒ Fuel Injection☒ New ☐ Used

City ROCHESTER State MN Zip Code 55906

No Cylinders 8

Transmission Type

☐ Manual☒ Automatic

Antilock Brakes

☒ Yes☒ No

Restraint System

☒ 3-Point Belt☐ Motorbelt☒ Driverside Airbag☐ 2-Point Belt☐ Passengerside Airbag

Cruise Control

☒ Yes☒ No

Drive Train

☐ Front☐ Rear☒ 4-Wheel

Vehicle Type

☐ Car☐ Van☐ Minivan☐ Other☒ Sport Ut☐ Truck☐ Motorcycle

Body Style

☐ 2-Door☐ 4-Door☐ Stationwagon☐ Pick Up Truck☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component
02100940

Part Name(s)

ELECTRICAL SYSTEM: BATTERY

Location

☐ Left☐ Front☐ Right☐ Rear

Failed Part(s)

☒ Original☒ Replacement

No of Failures

2

Date(s) of Failure(s)

-01-JUN-1996 --- 07-MAR-1997

Mileage at Failure(s)

830250

Vehicle Speed at Failure(s)

Failed Part(s)

Available?

☒ Yes☐ No

NHTSA Previously

Contacted?

☐ Yes☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash

☐ Yes☒ No

Fire

☐ Yes☒ No

Number of Persons Injured

Number of Fatalities

Estimated Property Damage

Reported to Police

☐ Yes☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

PE99013, DELCO BATTERY LEAKED, AND CAUSED ACID TO SPRAY INTO THE ENGINE COMPARTMENT.
DEALER REPLACED BATTERY. PLEASE PROVIDE FURTHER INFORMATION.*AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.