

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)**NATIONWIDE 1-888-DASH-2-DOT****1-888-327-4236****www.nhtsa.dot.gov/hotline****FOR AGENCY USE ONLY**

284

Date Received

11-AUG-2000

Od_or _____

rt_dt _____

od_rt _____

up_ltr _____

Reference No.

867487

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	FIRESTONE	ATX	1900	

Purchase Date	Dealer's Name _____	Engine Size _____	☐ Turbo
☐ New ☒ Used	City _____ State _____ Zip Code _____	(CID/CCL _____)	☐ Diesel
		No. Cylinders _____	☐ Gas
			☐ Fuel Injection

Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type	Body Style
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorcyclist ☐ 2-Point Belt	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other	☐ Sport Vlt ☐ Truck ☐ Motorcycle ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02740000	Part Name(s) TIRE: TREAD	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Dates of Failure(s) 20-JUN-2000 Mileage at Failure(s) 00 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form.)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

RIGHT REAR TIRE TREAD SEPARATED AT 70MPH, CAUSING DAMAGE TO VEHICLE. TIRE WAS ORIGINAL EQUIPMENT ON A 96 EXPLORER P235 SIZE. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) U.S. Department of Transportation National Highway Traffic Safety Administration NATIONALWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 284 Date Received 00 SEP 20 AM 9:55 11-AUG-2000 OFFICE DEFECTS INVESTIGATION Od or _____ in _____ on _____ up _____ Reference No. 867487 Work Number _____ Home Number _____	
OWNER INFORMATION (Type or Print) 526199			
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☒ YES ☐ NO In the absence of your name and address to the vehicle manufacturer. Signature of Owner Date 9/12/2000			
VEHICLE INFORMATION			
Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side) 1FMDU32X5TZA24779	Vehicle Make FIRESTONE	Vehicle Model ATX	Vehicle Year 1996 Current Odometer Reading 83511
Purchase Date 5-10-97 ☐ New ☒ Used	Dealer's Name Bob Tomus Ford, Inc. City McKinney State TX Zip Code 75069		Engine Size (CID/CCL) _____ No Cylinders 16 ☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☒ Driverside Airbag ☐ 2-Point Belt ☒ Passengerside Airbag	Cruise Control ☒ Yes ☐ No Drive Train ☐ Front ☐ Rear ☐ 4-Wheel Vehicle Type ☐ Car ☒ Sport Ut ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____ Body Style ☐ 2-Door ☒ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other SUV
FAILED COMPONENT(S)/PART(S) INFORMATION			
Component 02740000	Part Name(s) TIRES/TREAD	Location ☐ Left ☒ Right ☐ Front ☒ Rear	Failed Part(s) ☒ Original ☐ Replacement
No of Failures 1	Date(s) of Failure(s) 20-JUN-1999 Mileage at Failure(s) 107 Vehicle Speed at Failure(s) 72 mph		Failed Part(s) Available? ☐ Yes ☒ No NHTSA Previously Contacted? ☐ Yes ☒ No
APPLICATION INCIDENT INFORMATION (Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)			
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0 Estimated Property Damage \$675.12 Reported to Police ☐ Yes ☒ No
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)			
RIGHT REAR TIRE TREAD SEPARATED AT 70MPH, CAUSING DAMAGE TO VEHICLE. TIRE WAS ORIGINAL EQUIPMENT ON A 96 EXPLORER P235 SIZE. *AK			
CONTINUE ON BACK IF NEEDED			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer your response, or a statistical summary thereof, may be used in support of the agency's action.			

Fold to show Return Address (no stamp needed) Fasten with tape or staple and mail

INFORMATION ON TIRE FAILURE(S) (IF APPLICABLE)

TIRE IDENTIFICATION NO.*

D O T

MANUFACTURER/TIRE NAME

SIZE

Firestone ATX

P235/75R-15

* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.

NARRATIVE DESCRIPTION (CONTINUED)

★ U.S. G.P.O.: 1992-623-537/60000

U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

400 Seventh St., S.W.
Washington, D.C. 20590

Official Business
Penalty for Private Use \$300

BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL HWY TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Information Management Staff NSA-10.01
400 7th Street, SW
Washington, DC 20590

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES



CASO (RIS)

40475227) UNDERWRITING REVIEW

DRIVER

BIRTHDATE	LICENSE NUMBER	DRL EXP	ST	MVR
06/16/		Y	TX	01/98
10/18/		Y	TX	01/98

VEHICLE		CLASS	PRIN DOB	OCC DOB
1. 96 FORD	EXPLORER	61170201	06/16/19	
2. 88 FORD	MUSTANG	11270201	10/18/19	

L	DOL	CLAIM NO.	DRIVER OR POLICY	COVERAGES OR CAUSE	AMT PD
A	06/29/1999	43-R286-679	6391, PAMELA J	DR	431 C

CENTER PART OF THE TIRE TREAD RIPPED OFF AND DAMAGED THE REVERSE LIGHT COVER AND THE FENDER WAS BENT SLIGHTLY.

PF1-PREV SCR, PF2-MAIN TOC, PF3-1ST MR SCR, PF4-CHANGES
P-PRINT POLICIES, PF5-ACTION REQ

ENTER SELECTION
ACCEPT TO CONTINUE



RBZ00032
date: 06-28-99
time: 11:33 AM

route to: Busby, Vickie

STATE FARM MUTUAL AUTOMOBILE INSURANCE COMPANY

VEHICLE DAMAGE REPORT

claim number
43-R286-679

date of loss
06-20-99

* Estimate Vehicle Info *
*
* Vehicle Owner: PAMELA BISI *
* Vehicle Description: 96 FORD EXPLORER WAGON DARK GRE *
*

READ THE ATTACHED INFORMATION REGARDING
QUALITY REPLACEMENT PARTS MADE BY
THE ORIGINAL EQUIPMENT MANUFACTURER

BILL UTTER FORD
4901 I35 EAST
DENTON, TEXAS 76205
940-321-7476 FAX: 940-321-7599

CD LOG NO 981-2 DATE 06/24/99

SHOP: INSP DATE: 06/22/99
CONTACT: LARRY BLACKSHEAR
OWNER: [REDACTED] HOME PHONE: [REDACTED] 4
ADDRESS: [REDACTED] WORK PHONE: [REDACTED] 9
CITY STATE: [REDACTED]
ZIP: 762278929
CLAIM#: 43-R286-67901 CLAIM REP: CADE, SHERRI
INSURED: BISI, PAMELA TYPE OF LOSS: COMPREHENSIVE/SERVICE
LOSS DATE: 06/20/99 FIRST SUPPLEMENT
POINT OF IMPACT: 10
INS CO: STATE FARM CONTACT: CADE, SHERRI
LIC#: WDW94F STATE: VIN: 1FMDU32X5TZA84779
BODY COLOR: DARK GREEN MILEAGE: 60,414
CONDITION: GOOD ACCTNG CTL#: [REDACTED]
DRIVEABLE: YES VEH. INSP#: [REDACTED]

*=USER-ENTERED VALUE E=NEW PART
EC=QUALITY REPLACEMENT PART EU=QUALITY RECYCLED PART
EP=SEE PX REPORT ET=LABOR/PARTIAL REPLACE IT=LABOR/PARTIAL REPAIR
I=REPAIR/ALIGN/SUBLET L=REFINISH N=ADDITIONAL OPERATION
P=CHECK TE=PART/PARTIAL REPLACE AA=APPEARANCE ALLOWANCE
RP=RELATED PRIOR DAMAGE UP=UNRELATED PRIOR DAMAGE

<<<<<<<FINAL BILL OK TO PAY>>>>>>>>
THANK YOU FOR THE ASSIGNMENT
6-24-1999

1996 FORD EXPLORER XLT 4DR WAGON P8433B/B OPTNS A/34RPFECXBOIT

OPTIONS: TWO-STAGE - INTERIOR SURFACES TWO-STAGE - EXTERIOR - OPTION 3
POWER SEATS ELEC REMOTE CONTROL MIRRORS
POWER DOOR LOCKS POWER WINDOWS
LUGGAGE RACK HEATED BACK GLASS
PRIVACY GLASS REAR WIPER
TILT STEERING WHEEL CRUISE CONTROL

OP	CDE	MC	DESCRIPTION	MFG. PART NO.	PRICE	AJ%	HOURS	R
TE	0093	01	STRIPE ASSEMBLY	RT PART/PARTIAL RPLA	37.95			1
I	0075	01	DEFLECTOR, ROCKER PANEL	RT REPAIR			0.3	*1
I	0390		PANEL, QUARTER	RT REPAIR			5.0	*1
L	0390	09	PANEL, QUARTER	RT REFINISH			3.7	4
E	0372	01	MLDG, QUARTER LOWER	R/R F5T27829038CA	94.81		0.3	1

PAGE 1
06/24/99

1996 FORD EXPLORER XLT 4DR WAGON
CD LOG NO 981-2

ET 0275	STRIPE, QUARTER UPPER	RT LABOR/PART'L REPL			0.4 1
EP 0534	TAILLAMP ASSEMBLY	RT ** QUALITY REPL P	54.68	S1	0.3 1
I 0567	BUMPER, REAR	REPAIR			0.5*4*
CLEAN UP REAR BUMPER AND PADS					

8 ITEMS

MC MESSAGE(S)
01 CALL DEALER FOR EXACT PART NUMBER / PRICE
09 INCLUDES 0.6 HOURS MAJOR PANEL TWO-STAGE ALLOWANCE

FINAL CALCULATIONS & ENTRIES

GROSS PARTS					132.76
OTHER PARTS					54.68
PAINT MATERIAL					84.00
PARTS TOTAL					271.44
TAX ON PARTS & MATERIAL	@		7.250%		19.68
LABOR	RATE	REPLACE HRS	REPAIR HRS		
1-SHEET METAL	30.00	1.0	5.3		189.00
2-MECH/ELEC	58.00				
3-FRAME	30.00				
4-REFINISH	30.00	3.7	0.5		126.00
5-PAINT MATERIAL	20.00				
LABOR TOTAL					315.00
TAX ON LABOR		@	0.000%		
GROSS TOTAL					606.12
LESS: DEDUCTIBLE					250.00-
NET TOTAL					356.12
LESS: PREVIOUS NET TOTAL					288.48-
NET SUPPLEMENT TOTAL					67.64

ADP SHOPLINK U4592 SU CD LOG 981-2 DATE 06/24/99 11:54:30AM R.6.0 CD 06/99
PXN:Y/01/01/01/00 CUM:01/01/01/00 HOST LOG
COPYRIGHT 1997, AUTOMATIC DATA PROCESSING, INC.

1.1 HOURS WERE ADDED TO THIS ESTIMATE BASED ON ADP'S TWO-STAGE REFINISH
FORMULA: 20% OF REFINISH HOURS, AFTER OVERLAP, PLUS 0.6 HOURS FOR THE FIRST
MAJOR PANEL, WHERE NOTED.

"NOTICE - REPAIRS TO THIS VEHICLE MAY REQUIRE SPECIFIC
WELDING EQUIPMENT AS RECOMMENDED BY THE MANUFACTURER"
THIS IS NOT AN AUTHORIZATION TO REPAIR. ALL SUPPLEMENTS REQUIRE PRIOR APPROVAL
BY A STATE FARM CLAIM REPRESENTATIVE.

0.

QUALITY REPLACEMENT PARTS REPORT

BILL UTTER FORD
4901 I35 EAST
DENTON, TEXAS 76205
940-321-7476 FAX: 940-321-7599

GDE NO.	PART DESCRIPTION		SUPPLIER PART NUMBER	SUBSTITUTED FOR OEM PART NUMBER	SUPPLIER ID	CLS	SRC
0534	TAILLAMP ASSEMBLY	RT	16-61-FO280	F67Z13404AA	PXN0063		1
			FDEXTL03	F67Z13404AA	PXN6404		1
			+T099R	F67Z13404AA	PXN6427		1
			FO2801113	F67Z13404AA	PXN6439		1

KEY TO CLASSIFICATION/SOURCE CODES

CLS = CLASSIFICATION CODE:

- C - CAPA CERTIFIED PART QUOTED BY LISTED SUPPLIER
- R - RECONDITIONED PART

SRC = SOURCE CODE:

- 1 - NON-ORIGINAL EQUIPMENT MANUFACTURER PART
- 3 - ORIGINAL EQUIPMENT MANUFACTURER (OEM) PART

SPL ID	SUPPLIER / ADDRESS	CITY	ST ZIP	TELEPHONE
PXN0063	KEYSTONE AUTO 2637 OAKLAND STREET	2637 OAKLAND STR	TX 75041	(800) 822-0866
PXN6404	AUTO PANELS PLUS OSD 9520 E 55TH STREET	TULSA	OK 74145	(888) 892-6790
PXN6427	BRITE STAR OSD P O BOX 5317	WEST BABYLON	NY 11707	(800) 638-5901
PXN6439	AUTO BODY DEPOT 1320 CHEMICAL STREET STE A	DALLAS	TX 75207	(800) 626-9616

COPYRIGHT 1997, AUTOMATIC DATA PROCESSING, INC.

DATE 06/24/99 11:59:33AM
ADP # AUDATEX (A1)

AUDATEX CD SEQUENCE # 981-2

ELL UTTER • FORD, Inc.

FORD

4901 SOUTH I-35 E
DENTON, TEXAS 76205

DIRECT SERVICE
MAIN SWITCHBOARD
FAX

(940) 321-7510
(940) 321-7400
(940) 321-7597

SUB TOTAL	ALLOWANCE	PLUS PRICE DIFF.	LESS REC.
(CHECK ☒ APPROPRIATE BOX)			
☐ CLAIM REVIEW	☐ AUTHORIZATION TO SUBMIT CLAIM	☐ PARTS SCRAP OUT	
\$ PARTS	\$ LABOR	\$ TOTAL	
AUTHORIZED SIGNATURE AND DATE			

SERVICE INSTALLED PARTS				PROGRAM CODE(S)	DEALER CODE
DATE INSTALLED	ACCURATE MILEAGE	ORIGINAL R.O. NUMBER	REPAIR 1		52L406
MO. DAY YR.	NO. TENTHS	COMMITMENT CODE	REPAIR 2		
APPROVAL CODE OR NO.		REPAIR 3			
				REPAIR 4	92463-6

ON BEHALF OF SERVING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE, UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVING DEALER FOR INSPECTION BY REPRESENTATIVES OF FORD.

I ACKNOWLEDGE RECEIPT OF THE PARTS AND LABOR LISTED BELOW:

CUSTOMER SIGNATURE (SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

EXT: 8247

FOR OFFICE USE
MO: 0207 ADV: 141 BLACKSHEAR INVOICE: PRELIM BUD D LB VIN 1FTHU32N51Z84779 LICENSE NUMBER: TX N0M4F
TAX RULES: TYNM INVOICED AT: 06/24/99 13:15:48 96 FORD EXPLORER GREEN
ODOMETER IN: 60414 DIS: FMT
DATES BEGIN: 06/22/99 DONE: 06/24/99

CONCERN 51 BODY DAMAGE TO REAR AND UNDERSTIDE OPERATION TECH AMOUNT
CAUSE RT REAR QUARTER PANEL DAMAGE BODYLABOR 141 C 189.00
CORRECTION REPAIR RT REAR QUARTER PANEL AND TAILLAMP
COMMENT STATE FARM SERVICE 1ST CLAIM 43-0286-67901

PART NUMBER	POB	NOTE	DESCRIPTION	QTY	SELL	
FME F572 13404 AA			LAMP ASY - REAR, STO	1B	54.68	54.68
FME F512 7820000 BU			RT REAR QUARTER PANEL	1	37.95	37.95
FME F572 7829038 CB			RT REAR QUARTER PANEL	1	94.81	94.81

FACTORY TECH: 141 - PEDORA, PAUL



SUBTOTAL

PARTS	187.44
BODY SHOP METAL	189.00
TOTAL CHARGE FOR CONCERN	376.44

CONCERN 52 PAINT LABOR/PAINT TEAM OPERATION TECH AMOUNT
PAINT DAMAGE TO RT QUARTER PAINTLABOR 171 126.00
ACTION REFINISH REPAIRED RT QUARTER PANEL/CLEAN UP RT REAR BUMPER
3TH DUPONT PAINT MARK ON RT QUARTER PANEL

PART NUMBER	POB	NOTE	DESCRIPTION	QTY	SELL	
FME B/S-MATERIALS			PAINT	1B	84.00	84.00

TECH: 171 - LEYVA, ERNESTO

SUBTOTAL

BODY SHOP MET	84.00
BODY SHOP PAINT	126.00
TOTAL CHARGE FOR CONCERN	210.00

E.L.L. UTTER • FORD, Inc.



4901 SOUTH I-35 E
DENTON, TEXAS 76205

DIRECT SERVICE
MAIN SWITCHBOARD
FAX

(940) 321-7510
(940) 321-7400
(940) 321-7597

SUB TOTAL	ALLOWANCE	PLUS PRICE DIFF.	LESS REC.
(CHECK (X) APPROPRIATE BOX)			
☐ CLAIMS REVIEW	☐ AUTHORIZATION TO SUBMIT CLAIM	☐ PARTS SCRAP OUT	
\$ PARTS	\$ LABOR	\$ TOTAL	
AUTHORIZED SIGNATURE AND DATE			

SERVICE INSTALLED PARTS				PROGRAM CODE(S)	DEALER CODE
DATE INSTALLED		ACCUMULATED MILEAGE	ORIGINAL P.I.D. NUMBER	REPAIR 1	52L406
MO.	DAY	YR	NO. TENTHS	REPAIR 2	
APPROVAL CODE OR NO.			COMMITMENT CODE	REPAIR 3	
					P&A CODE
					02463-6

ON BEHALF OF SERVING DEALER, I HEREBY CERTIFY THAT THE INFORMATION CONTAINED HEREON IS ACCURATE, UNLESS OTHERWISE SHOWN. SERVICES DESCRIBED WERE PERFORMED AT NO CHARGE TO OWNER. THERE WAS NO INDICATION FROM THE APPEARANCE OF THE VEHICLE OR OTHERWISE THAT ANY PART REPAIRED OR REPLACED UNDER THIS CLAIM HAD BEEN CONNECTED IN ANY WAY WITH ANY ACCIDENT, NEGLIGENCE OR MISUSE. RECORDS SUPPORTING THIS CLAIM ARE AVAILABLE FOR (1) YEAR FROM THE DATE OF PAYMENT NOTIFICATION AT THE SERVING DEALER FOR INSPECTION BY REPRESENTATIVES OF FORD.

I ACKNOWLEDGE RECEIPT OF THE PARTS AND LABOR LISTED BELOW:

X CUSTOMER SIGNATURE (SIGNED) DEALER, GENERAL MANAGER OR AUTHORIZED PERSON (DATE)

- DRIVER/OWNER INFORMATION -- INVOICE: D05138

FOR OFFICE USE

VEHICLE INFORMATION

IN01 0207 ADV: 141 BLACKSHE (INVOICED) AT: 06/24/99 13:15:48 LB 95 EXPLORER GREEN LICENSE NUMBER: TX N0W54F

GRAND TOTALS

SUMMARY OF CHARGES FOR INVOICE D05138

PAYMENT DISTRIBUTION FOR INVOICE D05138

PARTS 197.44
BODY SHOP MAT 84.00
BODY SHOP PAINT 126.00
BODY SHOP METAL 189.00
SUB-TOTAL 586.44
TAX 19.68
TOTAL CHARGE 606.12

TOTAL CHARGE 606.12
CASH DUE 606.12

CUST PAYS \$250. DED//ST FARM SER 1ST 14356.12

IF YOU HAVE ANY QUESTIONS - PLEASE SEE LARRY W. BLACKSHEAR



(cust. owes 250.00)
Shop for 356.12
Coinixing

PAGE 2
LAST PAGE

JUN 24 1999

CASH
CK.#
CIC # 26-250.00

Ori

FREE CUSTOMER FLAT REPAIR

DISCOUNT

TIRE CO. INC.

FREE CUSTOMER ROTATION

1415891

1415891

DATE 06-21-1999 12:42 PM

SOLD
TOTXD 14 1
STORE # TRAN2245 S LOOP 288
STORE ADDRESSGARY (MRL) #275
SALESPERSONDENTON TX 76205-0000
940-891-0659940-440-2474
DI: 22432057(NC)

CODE	CC	QTY	SIZE	DESCRIPTION	F.E.T.	PRICE	AMOUNT
29009	1	2	P235/75R-15	ROWL FIRESTONE ATX		69.00	138.00
80017	1	2		CERTIFICATES		9.75	19.50
80224	1	2		WASTE TIRE DISPOSAL FEE		2.00	4.00
80018	1	2		LIFETIME COMPUTER SPIN BALANCE		9.99	19.98
TED REARS--R. R. TO SPARE EXPLORER							
80146	1	2		RUBBER VALVE		2.50	5.00
TAX: 11.39							
CHECK AMT: 99907354002567 NUM: 91325 AUTH# 00							TOTAL: 197.87
							CHECK: 197.87
							TENDERED: 197.87

WORK ORDER

- ☐ REPAIR
☐ ROTATION
☐ REBALANCE
☐ MOUNTING
☐ AIR CHECK
☐ RETURN TIRES
☐ CHANGE SNOWS

LF RF
 LR RR
 S

CUSTOMER
INITIALS

X
 Cardholder acknowledges receipt of goods and/or services in the amount of the Total shown hereon and agrees to perform the obligations set forth in the Cardholder's agreement with the issuer.