

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

118

Date Received

21-AUG-2000

Od_or

rt_dt

od_rt

up_ltr

Reference No.

868209

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
1FALP52U5SG205688	FORD	TAURUS	1995	

Purchase Date	Dealer's Name _____	Engine Size (CID/CCL) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other ☐ Sport Vlt ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other
--	---	--	--	--	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02113000	Part Name(s) SUSPENSION:INDEPENDENT FRONT ATTACHING MECHANISMS:SI	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Dates of Failure(s) 10-JUL-2000 Mileage at Failure(s) 50000 Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING ABOUT 35 MPH, THE FRONT COIL SPRING CAME APART AND THE SHARP EDGE SLICED THE TIRE, ON THE FRONT PASSENGER'S SIDE TIRE. THE VEHICLE WAS TOWED TO THE DEALERSHIP. THE COIL SPRING AND THE TIRE WAS REPLACED AT OWNER'S EXPENSE.

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 118

Date Received

21-AUG-2000

DEFECTS INVESTIGATION

 OCT 18 10:05
 RECEIVED
 DEFECTS INVESTIGATION

868209

OWNER INFORMATION (Type or Print)

627890

Work Number

Home Number

 Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.
☒ YES ☐ NO

Signature of Owner

Date 10/8/00

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of
w. located on driver's side)

1FALP52U5SG205688

Vehicle Make

FORD

Vehicle Model

TAURUS

Vehicle Year

1995

Current Odometer Reading

40400

Purchase Date

8-1995

Dealer's Name Lincoln Park Ford Mercury Inc

Engine Size

(CID/CC/L) 3.0

☐ Turbo☐ Diesel☒ Gas☒ Fuel Injection☒ New ☐ UsedCity MILFORD St MD Zip Code 21113

No Cylinders 6

Transmission Type

☐ Manual☒ Automatic

Antilock Brakes

☐ Yes☒ No

Restraint System

☒ 3-Point Belt☐ Motorbelt☐ Driverside Airbag☐ 2-Point Belt☐ Passengerside Airbag

Cruise Control

☐ Yes☒ No

Drive Train

☐ Front☐ Rear☐ 4-Wheel

Vehicle Type

☒ Car☐ Van☐ Minivan☐ Other☐ Sport Lift☐ Truck☐ Motorcycle

Body Style

☐ 2-Door☒ 4-Door☐ Stationwagon☐ Pick Up Truck☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component
02113000

Part Name(s)

SUSPENSION:INDEPENDENT FRONT ATTACHING MECHANISMS:S

Location

☐ Left☒ Front☒ Right☐ Rear

Failed Part(s)

☒ Original☐ Replacement

No of Failures

Date(s) of Failure(s) 10-JUL-2000

Mileage at Failure(s) 30000

Vehicle Speed at Failure(s) 25 MPH

Failed Part(s)
Available?☐ Yes ☒ NoNHTSA Previously
Contacted?☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash

☐ Yes☒ No

Fire

☐ Yes☒ No

Number of Persons Injured

None

Number of Fatalities

None

Estimated Property Damage

\$ 293.00

Reported to Police

☐ Yes☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING ABOUT 35 MPH FRONT COIL SPRING CAME APART, AND SHARP EDGE SLICED THE TIRE ON THE FRONT PASSENGER'S SIDE TIRE. VEHICLE WAS TOWED TO THE DEALERSHIP. THE COIL SPRING AND THE TIRE WAS REPLACED AT OWNER'S EXPENSE.*AK

Dealership where repair was done

DOZIER Ford

39300 W. ten mile Rd

Farmington Hills, MI 48335

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.