

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 137

Date Received

07-SEP-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

869952

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Listed at front of windshield or drivers side) JT2AE09B5R0070352	Vehicle Make TOYOTA	Vehicle Model COROLLA	Vehicle Year 1994	Current Odometer Reading
---	-------------------------------	---------------------------------	-----------------------------	--------------------------

Purchase Date	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☐ New ☒ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☐ 3-Point Belt ☒ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbell ☒ 2-Point Belt	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other _____ ☐ Sport Ult ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	---	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 06420000	Part Name(s) FUEL:THROTTLE LINKAGES:ACCELERATOR:RIGID	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures 2	Date(s) of Failure(s) 26-JUL-2000 Mileage at Failure(s) 74000 Vehicle Speed at Failure(s) 2	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------------------	----------------------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE PARKING ON A PARKING LOT VEHICLE SUDDENLY ACCELERATED. TOOK VEHICLE FOR SERVICE TO FIND OUT WHAT HAD CAUSED THIS PROBLEM ON TWO OCCASSIONS. TECHNICIAN STATED THAT THERE WAS A PROBLEM WITH THE THROTTLE CABLE. *AK

CONTINUED ON BACK (REVERSE)

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 197

Date Received

00 SEP 28 PM 1:42

07 SEP 2000

OFFICE

DEFECTS INVESTIGATION

Od. or

n. dt

od. n

up. ltr

Reference No.

869952

OWNER INFORMATION (Type or Print)

636555

Work Number *Serve*

Hon

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

In the absence of *Sister* provide your name and address to the vehicle manufacturer.

Signature of Owner

Date *9/15/00*

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Located at bottom of windshield on driver's side)

JT2AE09B5R0070362

Vehicle Make

TOYOTA

Vehicle Model

COROLLA

Vehicle Year

1994

Current Odometer Reading

48171

Purchase Date

194

Dealer's Name

Engine Size
(CID/CC/L)☐ Turbo☐ Diesel☒ Gas☐ Fuel Injected

No Cylinders

☒ New ~~Used~~

City State Zip Code

Transmission Type

☐ Manual☒ Automatic

Antilock Brakes

☐ Yes☒ No

Restraint System

☐ 3-Point Belt☒ Driverside Airbag☒ Passengerside Airbag☐ Motorbelt☒ 2-Point Belt*Did not deploy*

Cruise Control

☐ Yes☒ No

Drive Train

☒ Front☐ Rear☐ 4-Wheel

Vehicle Type

☒ Car☐ Van☐ Minivan☐ Other☐ Sport Utl☐ Truck☐ Motorcycle

Body Style

☐ 2-Door☐ 4-Door☒ Stationwagon☐ Pick Up☐ Truck

FAILED COMPONENT(S)/PART(S) INFORMATION

Component

06420000

Part Name(s)

FUEL THROTTLE LINKAGES ACCELERATOR RIGID

Location

☐ Left☐ Front☐ Right☐ Rear

Failed Part(s)

☒ Original☐ Replacement

No. of Failures

2

Date(s) of Failure(s)

26-JUL-2000 + Jul 31-2000

Mileage at Failure(s)

44000 + 48171

Vehicle Speed at Failure(s)

0

Failed Part(s)

☒ Yes ☐ No

NHTSA Previously

☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash

☒ Yes ☐ No

Fire

☐ Yes ☒ No

Number of Persons Injured

1 Chest soreness for 3 weeks

Number of Fatalities

0

Estimated Property Damage

\$2500 - \$3000

Reported to Police

☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE PARKING ON A PARKING LOT VEHICLE SUDDENLY ACCELERATED. TOOK VEHICLE FOR SERVICE TO FIND OUT WHAT HAD CAUSED THIS PROBLEM ON TWO OCCASIONS. TECHNICIAN STATED THAT THERE WAS A PROBLEM WITH THE THROTTLE CABLE. *AK

2nd failure, I called for tow truck to deliver car to auto center owned by Bill Pendergast. He found a throttle sticking. He cleaned it. The car was driven to a body shop for repair \$2500+.

1st time the car hit the side of a school building.

CONTINUE ON BACK OF FORM

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Fold to show Return Address (no stamp needed). Fasten with tape or staples and mail.																													
INFORMATION ON TIRE FAILURES (IF APPLICABLE)																													
TIRE IDENTIFICATION NO.																													
<table border="1"> <tr> <td>D</td> <td>O</td> <td>T</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td colspan="9"> MANUFACTURER/TIRE NAME </td> <td> SIZE </td> </tr> </table>										D	O	T								MANUFACTURER/TIRE NAME									SIZE
D	O	T																											
MANUFACTURER/TIRE NAME									SIZE																				
* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.																													
NARRATIVE DESCRIPTION (CONTINUED)																													