

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 150

Date Received

15-NOV-2000

 Od_or _____
 Rt_dt _____
 Od_rt _____
 Up_ltr _____

Reference No.

874980

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
 In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at front of windshield on drivers side) 2G4WS52JXY1328562	Vehicle Make BUICK	Vehicle Model CENTURY	Vehicle Year 2000	Current Odometer Reading
--	------------------------------	---------------------------------	-----------------------------	--------------------------

Purchase Date	Dealer's Name _____	Engine Size (CID/CC/L) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbell ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Ult ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other _____
--	---	---	--	--	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09500000	Part Name(s) COMMUNICATIONS:HORN ASSEMBLY	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) _____ Mileage at Failure(s) _____ Vehicle Speed at Failure(s) _____	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HORN DOES NOT ACTIVATE EASILY. CONSUMER MUST DEPRESS VERY HARD, AND AT EXACT SPOT. THEREFORE, IN A EMERGENCY SITUATION CONSUMER WILL NOT BE ABLE TO ACTIVATE HORN IN TIME, WILL NOT BE ABLE TO WARN OTHER DRIVERS, OR AVOID ACCIDENTS. *AK

CONTINUED BACK PAGE

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.



U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY

160

Date Received

15-NOV-2000

OFFICE
DEFECTS DIVISION

On or

at

by

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

up Mr

OWNER INFORMATION (Type or Print)

655650

Work Number

Home Number

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

☐ YES

☐ NO

In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner

Date

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (located at bottom of windshield on driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
2G4WS52JXY1328562	BUICK	CENTURY	2000	900

Purchase Date 6/28/00	Dealer's Name Mark Buick	Engine Size (CID/CC/L) No Cylinders 6	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City Yonkers State NY Zip Code 10704		

Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other
--	--	---	---	--	--	---

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 09500000	Part Name(s) COMMUNICATIONS HORN ASSEMBLY	Location ☒ Left ☐ Right ☒ Front ☐ Rear	Failed Part(s) ☒ Original ☐ Replacement
No of Failures	Date(s) of Failure(s) See Below Mileage at Failure(s) Vehicle Speed at Failure(s)	Failed Part(s) Available? ☐ Yes ☐ No	NHTSA Previously Contacted? ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

HORN DOES NOT ACTIVATE EASILY. CONSUMER MUST DEPRESS IT VERY HARD AND AT EXACT SPOT. THEREFORE, IN AN EMERGENCY SITUATION CONSUMER WILL NOT BE ABLE TO ACTIVATE HORN IN TIME, WILL NOT BE ABLE TO WARN OTHER DRIVERS, OR AVOID ACCIDENTS. *AK

THIS PROBLEM IS A MAJOR ONE FOR ANY SENSITIVE DRIVER. AGE 65+ AND EVEN YOUNG FEMALE DRIVER SPOTS TO ACTIVATE HORN. SOUND BEHIND AT TIMES. MAKE EASIER POINT OF ACTIVATION IDENTIFIED. - EXPLANATION AT 11/16/00

CONTINUE ON BACK, IF NEEDED

The Privacy Act of 1974 (Public Law 93-579) This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Fold to show Return Address (no stamp needed) Fasten with tape or staple and mail.

INFORMATION ON TIRE FAILURE(S) (IF APPLICABLE)

TIRE IDENTIFICATION NO.*

D O T

MANUFACTURER/TIRE NAME

SIZE

* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.

NARRATIVE DESCRIPTION (CONTINUED)

THE NATURE OF THE LOSS FOR THE HORN POSITION ON
THE SCREENING WHICH IS DIFFICULT TO FIND IT SHOULD BE
IN A DIFFERENT CORNER THAN THE HORN POSITION


U.S. G.P.O. 1982-403-807/80286

U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

400 Seventh St., S.W.
Washington, D.C. 20590

Official Business
Penalty for Private Use \$300



BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL HWY TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Information Management Staff NSA-10.01
400 7th Street, SW
Washington, DC 20590

10/11/80 10:11 AM