



U.S. Department
of Transportation

National Highway
Traffic Safety
Administration

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY

130

Date Received

20-NOV-2000

Od_or _____
rt_dt _____
od_rt _____
up_ltr _____

Reference No.

875244

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (located at front of vehicle or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
	LAND ROVER	RANGE ROVER	1996	

Purchase Date	Dealer's Name _____	Engine Size (CID/CCL) _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
☒ New ☐ Used	City _____ State _____ Zip Code _____	No. Cylinders _____	

Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☒ Yes ☐ No	Restraint System ☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Belt	Cruise Control ☒ Yes ☐ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel	Vehicle Type ☐ Car ☐ Van ☐ Minivan ☐ Other ☐ Sport Utl ☐ Truck ☐ Motorcycle	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other
--	---	---	--	--	---	--

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 08310000	Part Name(s) ELECTRICAL SYSTEM;WIRING;HARNES;FRONT;UNDERHOOD	Location ☐ Left ☐ Front ☐ Right ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No. of Failures	Dates of Failure(s) _____ Mileage at Failure(s) _____ Vehicle Speed at Failure(s) _____	Failed Part(s) Available? Yes No	NHTSA Previously Contacted? Yes No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), failure(s), crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☒ Yes ☐ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damage	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	---------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING AT APPROXIMATELY 50 MPH SUDDENLY AIR CONDITIONER TURNED OFF, AND CABIN FILLED WITH SMOKE WHICH WAS COMING FROM GLOVE BOX. SOMEONE LIFTED HOOD HEARD CLICKING NOISE, AND THEN ENGINE IGNITED. FRONT END COMPLETELY MELTED TO FRAME ,TOTALLY DESTROYED. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

U.S. Department
of TransportationNational Highway
Traffic Safety
Administration

DOT Auto Safety Hotline

Vehicle Owner's Questionnaire (VOQ)

NATIONWIDE 1-888-DASH-2-DOT

1-888-327-4236

www.nhtsa.dot.gov/hotline

FOR AGENCY USE ONLY 160

Date Received

RECEIVED

DATE

20-NOV-2006

OFFICE

DEFECTS INVESTIGATION

Reference No.

875244

Work Number

Home Number

OWNER INFORMATION (Type or Print)

656516

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle?

☐ YES☐ NO

In the absence of a signature, please print name and address to the vehicle manufacturer.

Signature of Owner

Date 12/20/06

VEHICLE INFORMATION

Vehicle Ident. No. (VIN.) (Located at bottom of windshield on driver's side)

Vehicle Make

Vehicle Model

Vehicle Year

Current Odometer Reading

SALPV1248TA340400

LAND ROVER

RANGE ROVER

1996

70,000

Purchase Date

8/96

Dealer's Name Baker Motors

Engine Size
(CID/CC/L)☐ Turbo☐ Diesel☐ Gas☒ Fuel Injection

No Cylinders

6

☒ New ☐ Used

City Charleston

State SC

Zip Code

Transmission Type

Antilock Brakes

Restraint System

Cruise Control

Drive Train

Vehicle Type

Body Style

☐ Manual☒ Yes☒ 3-Point Belt☐ Motorbelt☒ Yes☐ Front☐ Rear☒ Sport Utl☐ 2-Door☐ 4-Door☐ Stationwagon☐ Pick Up Truck☒ Other☒ Automatic☐ No☒ Driverside Airbag☐ 2-Point Belt☐ No☒ Wheel☐ Other☐ Motorcycle

FAILED COMPONENT(S)/PART(S) INFORMATION

Component

Part Name(s)

Location

Failed Part(s)

08340000

ELECTRICAL SYSTEM:WRING:HARNES:FRONT:UNDERHOOD

☐ Left☐ Right☐ Original☒ Front☐ Rear☐ Replacement

No of Failures

Date(s) of Failure(s)

9/4/00

Mileage at Failure(s)

70,000

Vehicle Speed at Failure(s)

65 mph

Failed Part(s)

Available?

☐ Yes ☐ No

NHTSA Previously

Contacted?

☐ Yes ☒ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash

Fire

Number of Persons Injured

Number of Fatalities

Estimated Property Damage

Reported to Police

☐ Yes ☒ No☒ Yes ☐ No

0

0

totaled

☐ Yes ☒ No

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

WHILE DRIVING AT APPROXIMATELY 50 MPH SUDDENLY AIR CONDITIONER TURNED OFF, AND CABIN FILLED WITH SMOKE WHICH WAS COMING FROM GLOVE BOX. SOMEONE LIFTED HOOD HEARD CLICKING NOISE, AND THEN ENGINE IGNITED. FRONT END COMPLETELY MELTED TO FRAME, TOTALLY DESTROYED. *AK

CONTINUE ON BACK IF NEEDED

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

Fold to show Return Address (no stamp needed) Fasten with tape or staple and mail

INFORMATION ON TIRE FAILURE(S) (IF APPLICABLE)

TIRE IDENTIFICATION NO.*

D O T

MANUFACTURER/TIRE NAME

SIZE

* The identification number consists of 7 to 10 letters and numerals following the letters DOT. It is usually located near the rim flange on the side opposite the whitewall or on either side of a blackwall tire.

NARRATIVE DESCRIPTION (CONTINUED)

1996 Range Rover had 2 recalls to replace underhood hoses that could cause fire. Recalls were performed ~~but~~ because of the extent of damage, cause of fire not determined. Fire department felt it was definitely not fuel line but they did smell gas.

★ U.S.G.P.O.: 1982-625-897 / 62286

U.S. Department
of Transportation
National Highway
Traffic Safety
Administration

400 Seventh St., S.W.
Washington, D.C. 20590

Official Business
Penalty for Private Use \$300

BUSINESS REPLY MAIL

FIRST CLASS PERMIT NO. 73173 WASHINGTON, D.C.

POSTAGE WILL BE PAID BY NATL HWY TRAFFIC SAFETY ADMIN.

U.S. Department of Transportation
National Highway Traffic Safety Administration
Information Management Staff NSA-10.01
400 7th Street, SW
Washington, DC 20590

NO POSTAGE
NECESSARY
IF MAILED
IN THE
UNITED STATES