



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 197

Date Received

20-MAR-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

883566

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side door)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
4UZ6FBC2WC942280	FLEETWOOD	DISCOVERY	1998	
Purchase Date ☐ New ☒ Used	Dealer's Name _____ City _____ State _____ Zip Code _____		Engine Size (CID/CC/L) _____ No Cylinders _____	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection
Transmission Type ☐ Manual ☐ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	Cruise Control ☐ Yes ☒ No	Drive Train ☐ Front ☐ Rear ☐ 4-Wheel
Vehicle Type ☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____		Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____		

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 15901203	Part Name(s) EQUIPMENT: OTHER PIECES: STOVE	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 0	Date(s) of Failure(s) 19-MAR-2001 48900 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FRONT CENTER BURNER ON MAGIC CHEFF STOVE GOT TOO HOT VALVE THAT CONTROLLED TGAS COULD NOT BE CONTROLLED. GOT SO HOT THAT IT MELTED PLASTIC ON T KNOB. HAD TO BE TURNED OFF WITH A PAIR OF PLYERS. CONSUMER HAD REPLACED VALVE ON HIS OWN.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.

 DOT Auto Safety Hotline Vehicle Owner's Questionnaire (VOQ) U.S. Department of Transportation National Highway Traffic Safety Administration NATIONWIDE 1-888-DASH-2-DOT 1-888-327-4236 www.nhtsa.dot.gov/hotline		FOR AGENCY USE ONLY 197 Date Received: <u>20-MAR-2001</u> OFFICE: <u>DEFENSE</u> EFFECTS: <u>INVESTIG</u>	
OWNER INFORMATION (Type or Print) [Redacted] 681418		Od or <u> </u> nt dt <u> </u> od_n <u> </u> up_itr <u> </u> Reference No. 883566	
Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.		☒ YES ☐ NO	
Signature of Owner: [Redacted]		Date: <u>4/6/01</u>	
VEHICLE INFORMATION			
Vehicle Ident. No. (VIN) (Located at bottom of instrument panel, driver's side [Redacted]	Vehicle Make FLEETWOOD	Vehicle Model DISCOVERY	Vehicle Year 1998
		Current Odometer Reading 49,536	
Purchase Date <u>NOV 99</u>	Dealer's Name <u>Private sale</u>		Engine Size (CID/CC/L) <u>5.9</u>
☐ New ☒ Used	City <u> </u> State <u> </u> Zip Code <u> </u>	No Cylinders <u>6</u>	
Transmission Type ☐ Manual ☒ Automatic	Antilock Brakes ☐ Yes ☒ No	Restraint System ☒ 3-Point Seat ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Belt ☐ Passengerside Airbag	Cruise Control ☒ Yes ☒ No
Drive Train ☐ Front ☒ Rear ☐ 4-Wheel		Vehicle Type ☐ Car ☐ Sport Lift ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☒ Other <u>Motorhome</u>	Body Style ☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other
FAILED COMPONENT(S)/PART(S) INFORMATION			
Component 16801203	Part Name(s) EQUIPMENT:OTHER PIECES:STOVE	Location ☐ Left ☒ Right ☐ Front ☒ Rear	Failed Part(s) ☒ Original ☐ Replacement
No of Failures 0	Date(s) of Failure(s) <u>19-MAR-2001</u> Mileage at Failure(s) <u>48800</u> Vehicle Speed at Failure(s) <u>0</u>		Failed Part(s) Available? ☐ Yes ☒ No
		NHTSA Previously Contacted? ☐ Yes ☒ No	
APPLICATION INCIDENT INFORMATION			
(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)			
Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0
		Estimated Property Damage 0	Reported to Police ☐ Yes ☒ No
NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)			
FRONT CENTER BURNER ON MAGIC CHEFF STOVE GOT TOO HOT VALVE THAT CONTROLLED TGAS COULD NOT BE CONTROLLED. GOT SO HOT THAT IT MELTED PLASTIC ON T KNOB. HAD TO BE TURNED OFF WITH A PAIR OF PLYERS. CONSUMER HAD REPLACED VALVE ON HIS OWN.*AK			
CONTINUE ON BACK IF NEEDED			
The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.			