



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 436

Date Received

21-MAY-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

888687

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
3B7HF12V9WG105255	DODGE TRUCK	RAM 1500	1998	
Purchase Date	Dealer's Name	Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☒ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train
☐ Manual ☒ Automatic	☒ Yes ☐ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag ☐ Motorbelt ☐ 2-Point Bel	☒ Yes ☐ No	☐ Front ☒ Rear ☐ 4-Wheel
Vehicle Type	Body Style			
☐ Car ☐ Van ☐ Minivan ☐ Other	☐ Sport Util ☐ Truck ☐ Motorcycle ☐ Other		☐ 2-Door ☐ 4-Door ☐ Stationwagon ☒ Pick Up Truck ☐ Other	

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 07463000	Part Name(s) POWER TRAIN:AXLE ASSEMBLY:BEARING:AXLE SHAFT	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 01-DEC-2000 39000 Mileage at Failure(s)	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured	Number of Fatalities	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	---------------------------	----------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FRONT AXLE STARTED MAKING A NOISE AT 35,000 MILES. IT WAS TAKEN TO DEALER, BUT PROBLEM COULDN'T BE DULPICATED FOR REPAIRS. CURRENTLY, AT 39,000 MILES BEARINGS ARE SHOT AT U-JOINT. DEALER OFFERS TO PAY FOR PART AT BOTH SIDES.*AK

COPIES OF REPORTS - FREE -

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.