



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY 252

Date Received

07-AUG-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

893693

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)		Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
3CWSA298MXXM09246		VOLKSWAGEN	JETTA	1999	
Purchase Date	Dealer's Name _____		Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☐ New ☒ Used	City _____ State _____ Zip Code _____		No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train	Vehicle Type
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Driverside Airbag ☐ Passengerside Airbag	☐ Yes ☒ No	☐ Front ☐ Rear ☐ 4-Wheel	☐ Car ☐ Van ☐ Minivan ☐ Other
		☐ Motorbelt ☐ 2-Point Bel			☐ Sport Util ☐ Truck ☐ Motorcycle ☐ Other
					Body Style
					☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☐ Other

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 13200000	Part Name(s) STRUCTURE: BUMPER ASSEMBLY	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure 0	Date(s) of Failure(s) 01-APR-2001 Failure(s) 40000 Mileage at Failure(s) 0	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and Injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

FRONT BUMPER IS TOO LOW AND STANDARD. RIGHT SIDE/ LEFT SIDE CONCRETE GRILL WILL TAKE FRONT BUMPER OFF COMPLETELY. *AK

COPIES OF REPORTS ARE KEPT

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.