



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

Auto Safety Hotline

Vehicle Owner's Questionnaire

NATIONWIDE 1-800-424-9393
DC METRO AREA (202) 366-0123
INTERNET: <http://www.nhtsa.dot.gov>

FOR AGENCY USE ONLY §20

Date Received

13-AUG-2001

Od_or _____
rt_dt _____
pd_rt _____
rp_lr _____

Reference No.

894197

Do you authorize NHTSA to provide a copy of report to the manufacturer of your vehicle? ☐ YES ☐ NO
In the absence of an authorization, NHTSA WILL NOT provide your name and address to the vehicle manufacturer.

Signature of Owner _____ Date ____/____/____

VEHICLE INFORMATION

Vehicle Ident. No. (VIN) (Locate at bottom of windshield or driver's side)	Vehicle Make	Vehicle Model	Vehicle Year	Current Odometer Reading
JF1SF6355WG769245	SUBARU TRUCK	FORESTER	1998	
Purchase Date	Dealer's Name	Engine Size (CID/CC/L)	☐ Turbo ☐ Diesel ☐ Gas ☐ Fuel Injection	
☒ New ☐ Used	City _____ State _____ Zip Code _____	No Cylinders _____		
Transmission Type	Antilock Brakes	Restraint System	Cruise Control	Drive Train
☐ Manual ☐ Automatic	☐ Yes ☒ No	☐ 3-Point Belt ☐ Motorbelt ☐ Driverside Airbag ☐ 2-Point Bel ☐ Passengerside Airbag	☒ Yes ☐ No	☐ Front ☐ Rear ☐ 4-Wheel
Vehicle Type	Body Style			
☐ Car ☐ Sport Util ☐ Van ☐ Truck ☐ Minivan ☐ Motorcycle ☐ Other _____	☐ 2-Door ☐ 4-Door ☐ Stationwagon ☐ Pick Up Truck ☒ Other _____			

FAILED COMPONENT(S)/PART(S) INFORMATION

Component 02170000	Part Name(s) SUSPENSION:INDEPENDENT FRONT:BEARING WHEEL	Location ☐ Left ☐ Right ☐ Front ☐ Rear	Failed Part(s) ☐ Original ☐ Replacement
No of Failure	Date(s) of Failure(s) 01-JUN-1999 44000 Mileage at Failure(s)	Failed Part(s) ☐ Yes ☐ No	NHTSA Previously ☐ Yes ☐ No

APPLICATION INCIDENT INFORMATION

(Please describe in detail the incident(s), Failure(s), Crash(es), and injury(ies) on the back of this form)

Crash ☐ Yes ☒ No	Fire ☐ Yes ☒ No	Number of Persons Injured 0	Number of Fatalities 0	Estimated Property Damag	Reported to Police ☐ Yes ☒ No
--	---	--------------------------------	---------------------------	--------------------------	---

NARRATIVE DESCRIPTION OF FAILURE(S), INCIDENT(S), INJURY(IES)

IN JUNE OF 1999 RIGHT FRONT WHEEL BEARING WAS REPLACED BECAUSE OF A LOUD NOISE BEING MADE DURING OPERATION OF VEHICLE. THEN, ON 27-JUL7-2001, LEFT FRONT WHEEL BEARING WAS CAUSING ANOTHER LOUD NOISE, AND WAS BEING REPLACED BY THE DEALERSHIP. MECHANIC INFORMED CONSUMER THAT A GROOVE HAS BEEN FOUND IN THE FRONT AXLE OF THE VEHICLE WHICH COULD HAVE CAUSED THE PROBLEM WITH THE 2ND WHEEL BEARING REPLACEMENT. PLEASE PROVIDE ANY ADDITIONAL INFORMATION/ATTACHMENTS.*AK

COPIES OF THIS FORM ARE:

The Privacy Act of 1974-Public Law 93-579 This information is requested pursuant to authority vested in the National Highway Traffic Safety Act and subsequent amendments. You are under no obligation to respond to this questionnaire. Your response may be used to assist the NHTSA in determining whether a manufacturer should take appropriate action to correct a safety defect. If the NHTSA proceeds with administrative enforcement or litigation against a manufacturer, your response, or a statistical summary thereof, may be used in support of the agency's action.