

Disfunctional front end height
raising front bumper to
grab when parking but
parking bumpers which have
lower the bumper/ender
also makes it so that it
bottoms out at normal
driving conditions, have
estimate from Toledo Body
shop/Kelley's + no parts
from Cleveland + Attorney
General Office + BBIB.

Describe any additional incidents. (Include date and mileage)

Mark Register by MCS ENT-2252267-11864261 M. d in U.S.A.
© Copyright 1888 by National Computer Systems, Inc. worded
H3 Form 35D (Rev. 8/88)

www.nhtsa.dot.gov/hotline