



"Tony Meneses"
<tony@thermoflexcorp.com>
03/19/2007 11:23 AM

To <Chris_Noshad@Toyota.com>
cc <Michael_Collinsworth@Toyota.com>, "Mike Negus"
<mike@thermoflexcorp.com>
bcc

Subject RE: Tundra All Weather Mat Missing Clip PQR, Ref #50873

History:  This message has been forwarded.

Attached are the ES350 Mat pictures we discussed. There are two options shown, a sticker on the header card, and a tag attached to the driver side retention hole.

Thank you,

Tony Meneses

-----Original Message-----

From: Chris_Noshad@Toyota.com [mailto:Chris_Noshad@Toyota.com]
Sent: Friday, March 16, 2007, 3:41 PM
To: tony@thermoflexcorp.com
Cc: Michael_Collinsworth@Toyota.com
Subject: Tundra All Weather Mat Missing Clip PQR, Ref #50873

Tony,

Here is the Tundra All Weather Mat with missing clips report. This PQR is rated as a QPI. Per our discussion, please make sure the root cause is identified and the process is fool proof as the issue severity rating may elevate if the issue continue to reoccur. Please refer to the cover sheet for replacement clip quantity & shipment direction.

(See attached file: Tundra All weather Mat PQR, Ref #50873.doc) (See attached file: Tundra all weather Mat PQR Cover Letter, Ref #50873.pdf)

Chris Noshad
Sr. Field Quality Assurance Engineer
(310) 468-2562
(310) 468-4075 FaxS



DSC_0005.JPG DSC_0006.JPG