




CONFIDENTIAL

**SSC (Safety Recall) 90L Phase 1 - Certain 2007 - 2010 Model Year Camry and Camry Hybrid Vehicles
Potential Floor Mat Interference with Accelerator Pedal
Vehicles Equipped with Accelerator Pedals Manufactured by Denso Corporation**



CONDITION

As communicated last Fall, the defect is the potential for an unsecured or incompatible driver's floor mat to interfere with the accelerator pedal and cause it to get stuck in the wide open position. A stuck open accelerator pedal may result in very high vehicle speeds and make it difficult to stop the vehicle, which could cause a crash, serious injury or death. **Toyota has determined that this defect does not exist in vehicles in which the driver's side floor mat is compatible with the vehicle and properly secured.**

INVOLVED VEHICLES

- There are approximately XXXX Camry and Camry Hybrid vehicles involved in the U.S.

REMEDY

To make it less likely that an unsecured or incompatible driver's floor mat can interfere with the accelerator pedal, dealerships are requested to do the following:

- Modify both the rigid plastic accelerator pedal and the floor surface in the driver's foot-well.
- If the vehicle is equipped with a set of optional genuine Toyota All Weather Floor Mats (AWFM), it will be inspected to determine if the AWFM set is of an older design. If it is, the older design AWFMs for the driver and the front seat passenger positions will be replaced with newly designed mats.
- As an additional measure independent of the vehicle-based recall remedy, a newly designed override system will be installed on non-hybrid Camry vehicles to provide an extra measure of confidence. This system will cut engine power in case of simultaneous application of both accelerator and brake pedals at certain speeds and driving conditions. The Camry Hybrid already contains a fuel supply cut feature for Hybrid motor protection that achieves a similar result as the override system newly designed for the non-hybrid models.
- This repair is expected to take up to approximately two hour.
- Possible Mailing Schedule
 - Region January 28, 2009
 - Dealer January 28, 2009

February 04, 2009

- Owner