



NISSAN NORTH AMERICA, INC.

Corporate Headquarters
One Nissan Way
Franklin, TN 37068

Mailing Address: P.O. Box 685001
Franklin, TN 37068-5001

Telephone: 615.725.1000


April 7, 2011

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,


John Gibbons
Senior Manager
Technical Compliance

Encl.

REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN IN A FOREIGN COUNTRY

1. Manufacturer

Tan Chong Motor Assemblies Sdn. Bhd., Malaysia

2. Vehicles Potentially Involved

Nissan Grand Livina vehicles produced from December 2007 to June 2010 and Nissan Latio and Latio Sport vehicles produced from May 2007 to June 2010 at Tan Chong Motor Assemblies Sdn. Bhd. in Malaysia. No substantially similar vehicles sold in the United States are affected because of certain unique characteristics of the fuel used in Malaysia. These fuel characteristics are absent in the U.S. market. No other Nissan vehicles are affected because they use a different fuel gauge design.

3. Total Number of Vehicles Potentially Involved

Approximately 41,400.

Nissan Grand Livina vehicles; Approximately 32,100.

Nissan Latio and Latio sport vehicles; Approximately 9,300.

4. Description of the Defect

Due to the quality of fuel, there is potential for electrochemical migration at the electrodes of the resistor-card in the fuel gauge sending unit, and the insulation resistance between the electrodes will lower. As a result, the fuel meter may incorrectly indicate the amount of fuel in the tank. This could result in the vehicle running out of fuel.

5. Foreign Country in which the Safety Recall or Other Safety Campaign is Being Conducted

Malaysia.

6. Date of Determination

March 31, 2011

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

The beginning of April 2011.

9. Descriptive of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The fuel gauge sending unit will be replaced with a counter-measured one.

10. Vehicles in the United States (If known)

Model year 2007-2011 Nissan Versa vehicles are not affected because the fuel characteristics causing this issue are absent in the U.S. market.