

**NISSAN GROUP
OF NORTH AMERICA**



Nissan North America, Inc.
One Nissan Way
Franklin, TN 37067

Mailing Address:
PO Box 685001
Franklin, TN 37068


July 18, 2018

Associate Administrator for Safety Assurance
National Highway Traffic Safety Administration
Attention: Early Warning Division (NVS-217)
Room 217
1200 New Jersey Avenue, SE
Washington, D.C. 20590

Dear Associate Administrator:

We are transmitting the enclosed Report of a Defect in a Vehicle in a Foreign Country.

Very truly,

A handwritten signature in black ink, appearing to read "Derek Latta".

Derek Latta
Manager
Technical Compliance

Encl.

REPORT OF A SAFETY RECALL OR OTHER SAFETY CAMPAIGN
IN A FOREIGN COUNTRY

1. Manufacturer

Nissan Motor Manufacturing (UK) Ltd.

2. Vehicles Potentially Involved

Nissan Qashqai vehicles produced at Nissan Motor Manufacturing (UK) Ltd. between April 2, 2015 and December 12, 2015. No vehicles sold in the United States are affected because the O2 sensor (Bosch type) and Electronic Control Unit (ECU) calibration are specific to this model, which is not sold in the United States.

3. Total Number of Vehicles Potentially Involved

Approximately 826 Qashqai vehicles

4. Description of the Defect

Due to an improper manufacturing process by the supplier (Bosch), an air bubble can occur during sealing which may trap water in the sensor. Water inside the sensor may increase the internal pressure when heated, which can lead to a crack in the sensing element causing a failure, which will turn the Malfunction Indicator Lamp (MIL) on. This does not conform to the Korean Authority regulation requirement for O2 sensor durability.

5. Foreign Country in Which the Safety Recall or Other Safety Campaign is Being Conducted

Korea

6. Date of Determination

July 11, 2018

7. Determination Made By

Manufacturer

8. Date the Recall or Other Campaign will Commence

To be determined

9. Description of Corrective Action

Owners of potentially affected vehicles will be notified to take their vehicle to a dealer. The dealer will replace the O2 sensor and reprogram the ECU with software containing the correct calibration value.

10. Vehicles in the United States (If Known)

- MY 2007-2012 Sentra
- MY 2008-2018 Rogue
- MY 2014-2015 Nissan Rogue Select
- MY 2017-2018 Nissan Rogue Sport

Vehicles sold in the U.S. are on a similar “platform” as the Nissan Qashqai sold in the above markets. However, these U.S. vehicles are not identical or substantially similar from an engineering standpoint. As noted above, this issue affects no vehicles sold in the U.S.