

**TEXAS INSTRUMENTS, INC.'S**

**09/10/03**

**REQUEST 6**

**BOX 7**

**PART A-P**

**PART G**

**Subject:**

**Date:** Tue, 6 Aug 2002 16:46:36 -0500

**From:** "Lisa K. Ford" <LMEEK@SusmanGodfrey.com>

**To:** "epha@io.com" <epha@io.com>

**CC:** Brian Melton <BMelton@SusmanGodfrey.com>

"Eric J. Mayer" <EMAYER@SusmanGodfrey.com>

"Edgar G. Sargent" <esargent@SusmanGodfrey.com>

00-41-15

**Subject:** Conference Call - Friday, August 9th

**re:** [REDACTED] (Allstate)

**Date:** Friday, August 9, 2002

**Time:** 2:00 p.m. CST

**Call-in:** 800-826-7151

**Passcode:** 46145#

Also, can you please send us two (2) copies of all the pictures you have regarding this case.

Thanks. If you need any additional information, please do not hesitate to call me directly.

*Lisa Kay Ford*

*Secretary to Brian Melton & Jeff Seely*

*713-655-5669*

LIST REQUESTED & EXTRA  
SET OF ALL PICS IN FILE  
WE WILL FEDEX THESE  
FOR FRI AM DELIVERY

TI-NHTSA 10235

Bag 2204


took debris under vehicle after lifted debris under car on  
curb - in bag

D/C in scope 2309 after cleanoff

photos of suspect - during artifact CFW under scope

spand - seals shattered - no typical dilon, cat etc incident  
no C, or R

@ car - from block - app AFW on main fence under all





**SCHAEFER ENGINEERING CORPORATION**  
**14712 Bothell Way Northeast, Suite 21**  
**Seattle, WA 98155-7608**

ALAN C. TORRES, RECEIVED  
 FAXED 05/24/01

Seattle Corporate Office 14712 Bothell Way NE, Seattle, WA 98155  
 206.361.5577 Fax 206.361.5733 ALAN 206.360.2244  
 aeg@schaefer-eng.com

Date: 10-23-01

File Name: Meylumina Res. Plan  
 File No.: 2196

Time

Name (Print)	Firm	Representing	Telephone	In	Out
[REDACTED]				12:00	
				12:30	
				12:31	
				12:31	
				12:31	

**E.P. HAMILTON AND ASSOCIATES, INC.**  
**ENGINEERING AND CONSULTING**

**E.P. HAMILTON, II, Ph.D., P.E.**  
**PRESIDENT**

1400 West Parkside Rd.  
 Ste. A, Box 100  
 Phoenix, Arizona 85009  
 www.ephamilton.com

612-951-4278  
 Fax 612-950-4785  
 e-mail: ep@epha.com

**RAYMOND S. WHELAN**  
 ATTORNEY AT LAW

**MILLA MEYERS SWARTLING**  
 1000 BROWN AVENUE, 8TH FLOOR  
 SEATTLE, WASHINGTON 98104-4004

TELEPHONE  
 206-461-1000  
 FAX/FACILE  
 206-461-7842

www.rswartling.com



*Small text below logo*

**Mark B. Hoffman**  
 Design Analysis Engineer  
 Design Analysis Department  
 Product Development

528 Parkside Towers West  
 West Parkside Engineering  
 Dearborn, MI 48120 USA

Tel: 313-283-7400  
 Fax: 313-994-4922  
 mhoffma1

mhoffm1@ford.com

**EDGAR G. SARGENT**  
 ATTORNEY AT LAW

**SHERMAN GODFREY L.L.P.**

Room 2800  
 1400 Third Ave.  
 Seattle, WA 98101-3000

TELEPHONE 206-461-3000  
 FAX 206-461-3000  
 www.shermangodfrey.com

71-NHTSA 10237

↳ Bags all marked 219T

- 1) Wires from engine compartment #17
- 2) Wires from engine comp. #18
- 3) Wires from engine comp #19
- 4) Wires for engine comp #16
- 5) Exemplar speed deactivation switch #21
- 6) Speed deactivation switch #20

3PS -

1) partially melted wiring

2) chd. parts

fit contact partly melted

wiring contact gone - can see insulation where wire - gone @ knotline

1 - 3/32" ± hole adj wiring contact

removed or lost after fire occurred -  
app to have been intact from bottom to top. chd.  
↳ indentation vis. hole

2 - 3/32" ± holes adj. fix ad contact

Ring some #s visible on melt

F2VCO

D/C 2309

some debris in  
LW002

↑  
(1) - AB

exemplar switch F2VCGFS24-AB 9145B

Lic # A 32 386C

1000 Nagayama

architect - refugee from Aomori Prefecture

arrived 4/27/91

doesn't know about LTC accident

also says was SAT

husband PR / TV

fire system

she in K damp dishes

heard noises maybe 2X

Sam came downstairs - small

lights on in PR / smoke from kitchen

→ LR → G

opened door saw fire

(22)

leaving thick smoke & fire right in front of door

[why wasn't door knocked out?]

from outside - front of LTC / fire

garden hose on DS on fire - on floor

part of hose on floor

(23)

Says husband went in to try to move LTC

gas cans empty - 1 small red canister had gas

(24)

T in law left home when studied

TLNHTBA 10230

Doesn't remember color of flames  
no unusual sounds while fire spreads  
like something blowing up

gas grill was presumably attached (280<sup>50</sup>)  
where was it?

Not listed on deck PTF 000142-4  
(Lubachi on deck \$2999)

handwritten list says grill PTF 000144 & 196  
on deck

100 gal of paint in garage

had hired contractor to do work in Russia

4 times for LTC  
2 times for Chung Han

Constantine Mejlumian

Came to U.S. 1992

former journalist USSR Minister of Culture of U.S.

60-70K/yr.

Last yr. RTK

wife part time helping elderly person

she was audited in USSR

purchased vehicle 9/97

used only Lincoln in business

bought vehicle used from Beltona L.M.

93 LTC. ~30K mi

was trade in

no knowledge re: acc./major repairs

loaded acc for CD player

some kind of anti theft device - he didn't install

used only for business

also owned Chevy Camaro

RV-type car - Chevy Van 20

svc history - (knows nothing re: cars)

changed brake pads, oil 3K mi

transmission fluid 25-30K mi

@ "Case Monkey" thru Normandy Park & Burien

had brakes done @ Checker Auto Repair

used lots of oil



garage - very full

planning to have remodeling done

cabinets all doors front wall of house & side wall  
of garage.

no ship stored on N. wall of garage adj. d.s. LTC

was gas can in garage - in cabinet E. wall

elect. on S. wall

sprinkler controls S. wall

1/20/00 - home ~ 7:30

FinLans there

watch TV

Fireplace not operating

wife & son home ~ 8:30 P

Smokes cigarettes

FinL & Son upstairs

W in K

he's in PR watches TV

son comes down - fill anything?

Saw smoke when sound hits on

→ Laundry room

opened garage door

white, heavy smoke from R side of wheels of car

Saw fire

TI-NHTSA 10242

both garage doors closed to street

more fire R/S LTC (DS)

flame under car

he opened garage door @ that point  
pushed button & door opened.

doesn't recall color of flame

Norm replaced battery

no problems w/ emissions or horn.

Also motor oil leaked -

Checker Cab can repair

Checker Body Repair

E. Marginal Way

went to the store

New Pacific Hwy

---

if he hits 3

2 gal gas can

5 gal gas can

green garden hose

20 waterproof seals

retinal gas grill

Date Wise - Neighbor 10:30 PM - upstairs in BL @ computer (Dad)

gas-type flame in front of car R → L  
blue/orange

also to L of car - looked like garden hose  
from front tire - back, toward back wheel  
between wall & car

was separate (laying beside car)

(T) he noticed ~~the~~ fire first, then hose  
wife noticed hose - by that time, hose on fire

410 min, full garage engulfed in flames

family already out when he went across street  
mother still in house

Wise down left the driveway

mother hysterical

father & saw not

no one tried to get anything out of garage

family certain nothing there but hose

looked like gas flame, did not know where that was

dad does not face window - heard noise

popping, crushing noise

hose not on fire when he 1st saw fire

very obvious there was a fire

TI-NHTSA 10244

Saw justice flame from inside his house

very little smoke

or 1/2' for the front bumper of car

when he gets to them driveway, front of house starting

to burn - walked its way down house

could not see end of house

00-41-21

1-23-02

Rolls 1-5

1 set

Garland

*Moore*



TI-NHTBA 10247




TI-NHTSA 10249





TI-NHTSA 10251






TI-NHTSA 10253





TI-NHTSA 10255




TI-NHTSA 10257




TI-NHTSA 10259




TI-NHTSA 10261


















TI-NHTSA 10271



TI-NHTSA 10273



TI-NHTSA 10275





TI-NHTSA 10277



TI-NHTSA 10279




TI-NHTSA 10281





TI-NHTSA 10283








TI-NHTSA 10285









TI-NHTSA 10291




TI-NHTSA 10293



TI-NHTSA 10295




TI-NHTSA 10207







TI-NHTSA 10299








TI-NHTSA 10301








TI-NHT8A 10305










TI-NHTSA 10311





TI-NHTSA 10313















TI-NHTSA 10321





TI-NHTSA 10323










TI-NHTSA 10329











TI-NHTSA 10337

10/10/77



TI-NHTSA 10339



TI-NHTSA 10341



TI-NHTSA 10343

