

PER 03-044

FORD

**FORD 12/03/03 LETTER
TO OH**

ATTACHMENT

1

BOOK 13 OF 24

PART 4 OF 4

WTR. C. ST. GR. DET	TOT. CO. LBS. GR. J.	DU. CO. LBS. D.	DU. CO. LBS. D.	RES. ON. D.	ST. P. CO. D.	CPIC. CO. J.	TECH. TEXT	TECH. TEXT	CUST. TXT	AREA. CO. ID.	COUNTY. CO. ID.	VEH. ID. CO. ID.	TOT. CO. ID.	CARR. SOLD.	GR. CO. ID.	WFO. CO. ID.	AWB. CO. ID.	ART. CO. ID.	THE. PLA. #
81.82	401.25	6.2	2814	MA	TX	31801			CUSTOMER STATES THEY AT WHEN AFTER TRUCKER STARTED THE TRUCK WILL NOT ACCELERATE THE TRUCK WILL NOT ACCELERATE ALL OF THE TIME ON FOR VEHICLE WILL NOT ACCELERATE AT TIMES	264	USA	10000	02	USA		141	FF	811	
80.4	81.25	6.2	2820	MA	TX	31801	REPLACED THE ACCELERATOR FROM JACOBS MOTOR FUEL INJECTION AND CHECK TEST. ENGINE VIBRATES HEAVILY IN SHORT DART LINE OF ACCEL. PERFORM TEST CODE 0122 0221. REMOVE AND REPLACE FUEL INJECT. PEDAL. RETURN ON TEST AND REPLACE ACCELERATOR FROM ARMY		264	USA	10000	02	USA		141	FF	811		
81.82	148.88	0.9	8461	MA	CA	31801	CLEAR SERVICE ROAD PULL CHECK TEST PASS NEED TO RUN PIDS AND MONITOR AP AND RELEASE INOFF NEED TO REPLACE PEDAL ASSEMB. NO LABOR OFF FOR ARMOTRAL. DASH ON PART REPLACEMENT NEED TO USE IN TEST		CUSTOMER STATES VEHICLE WILL NOT ACCELERATE AT TIMES		USA	17070	001	USA		144	FF	811	
78.88	108.88	1.8	1882	MA	VT	31801	CLEAR SERVICE ROAD PULL CHECK TEST PASS NEED TO RUN PIDS AND MONITOR AP AND RELEASE INOFF NEED TO REPLACE PEDAL ASSEMB. NO LABOR OFF FOR ARMOTRAL. DASH ON PART REPLACEMENT NEED TO USE IN TEST		WILL NOT ACCELERATE	307	USA	10000	001	USA		144	FF	811	
78.88	331.25	2.5	2820	MA	AZ	31801	REMOVED CLUTCH PRESS PRIORITY FEET PED MONITOR DOES NOT READ ON INSPIC PIZ TRANSMISSION. VOLTAGE IN SPIC NO PIDS FOR THE CHECK AT TIMES THE CURRENT CHANGE FROM THE OHMS-4 NO REPLACE ASSEMBLY		ENGINE WILL NOT ACCELERATE	308	USA	17170	02	USA		141	FF	811	
80.4	148.88	1.2	2820	MA	TX	31801			WILL NOT ACCELERATE	264	USA	10000	02	USA		141	FF	811	
78.88	87.25	1.4	7820	MA	CA	31801	CHECK AP SENSOR VOLTAGE OLD AP THAT WAS REPLACE VOLTAGE STORED AS VOLTAGE AT TIMES CHECK TO ACCELUTE ACCEL. PEDAL. NEW USED IN TIME TO REPLACE THE ACCEL. PEDAL RELEASE IS ACCURATE TEST DRIVE PUT NO BURNS OVER BY 1 MILE		WILL NOT ACCELERATE AT PEDAL PRESS STORED AFTER WHEN THE VEHICLE IS STARTED AND THEY TRY TO DRIVE IT AWAY IT WILL NOT ACCELERATE.	264	USA	17000	02	USA		141	FF	811	
78.88	101.04	0.8	8648	MA	CT	31801	DRY TEST, RELEASE CODES PER POINT TEST ON AP SENSOR REPLACE AP SENSOR ROAD TEST		CHECK FOR ENGINE WILL NOT ACCELERATE	308	CAN	40000	001	CAN		141	FF	811	
78.88	282.4	4.8	8720	MA	NY	31801	PERFORM VISUAL INSPECTION OF FUEL OR COOLANT ELEC AND HOSES NO LEAKS CLEAN FUEL DL LEVEL. O.K. INDIAN AGENT OK REC TEST ROSS HELP TEST P4111 CONF POWER THROTTLE POS	PERFORM HEAD ON FUEL PUMP HEAD ON PUMP LBS. PUMP PRESSURE. BE PUMP AIR IN FUEL. OK ELEC PU EL. PUMP PRESS. EICP. NO DASHES ALL OTHER TESTS NOT FOR PIDS. OK PUMP VOLTAGE OK OR GROUND OK		508	USA	14000	02	USA		144	FF	811	
78.88	894.41	1.8	1282	MA	PA	31801	REPL. LOW ROAD BREEZE P4111. THE HEAD FROM THE FUEL INJECTOR ON PEDAL DASH REPLACE THROTTLE BODY FUEL ASSEMBLY. LOOK UP BURN, RUN ALL CHECKS, FOUND GREEZE VENT, REMOVED AND REPLACED FUEL ASSEMBLY, CLEAN DOORS. RECHECK, OK		WILL NOT ACCELERATE AT TIMES WHEN DRIVING ACCEL. PEDAL. EASY CLUT. INTERMITTENT REPAIR ENGINE WILL NOT ACCELERATE	218	USA	10000	02	USA		141	FF	811	
81.82	388.31	6.1	2814	MA	TX	31801			CUSTOMER STATES VEHICLE WILL NOT ACCELERATE AT TIMES FROM GAS PRESS	264	USA	10000	001	USA		141	FF	811	
81.82	188.25	1.4	8820	MA	E	31801	PERFORM CHECK TEST (ENGINE) USE CAUTION PART DASH ONLY WHEN NO REPAIR. IN NECESSARY INCREASE TIME TO BRING THE VEHICLE INTO THE SERVICE BAY. NOOK U		ENGINE WILL NOT ACCELERATE AT TIMES ENGINE WILL ONLY IDLE	277	USA	14000	001	USA		141	FF	811	
81.82	170.88	0.7	1014	MA	NC	31801			CUSTOMER STATES VEHICLE WILL NOT ACCELERATE OK AND ABOVE	704	USA	12000	02	USA		141	FF	811	
78.88	282.21	2	8411	MA	MI	31801	3000 ROAD TEST AND CALIBRATE WET FOOT FEET PEDAL. TO ACT UP EIC TEST AND THERE WAS A P0122 CODE IN MEMORY. GO THROUGH THE POINT TESTS. REPLACED THE AP AND CLEAR THE ONE CODE. ROAD TEST. EIC TEST. NO	COOPER	CUSTOMER STATES VEHICLE WILL NOT ACCELERATE AT TIMES CLUT WHICH TO PULL ON THE WHEEL FROM BY MANUAL.	278	USA	40000	001	CAN		144	FF	811	

MTPL	TOT	CDL	DLR	RES	ST	CP	TRCH	TRCH	CONST	AREA	COUNT	BL	DL	DR	CHTRY	DRT	VR	APPR	VRT	TR
DET	CDL	GR	JFR	DLA	C	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
71.82	414.02	4.3	4417	NA	TX	31901	TRCH TCT1 4485 POWERTRAIN SECURITY DEDUCTIBLE INTERRUPTING LOSS OF POWER IDLE ONLY DOES NOT STALL PERFORM DIESEL PERFORMANCE DIAGNOSIS RETURN FOR NORMAL CODE NEED P1111 DONT P1114 REGR P1111 INJECTOR P1111	TRCH TCT1 11250 FUEL EXC P1111 TEST FUEL CP EBP AND BOOST ALL WITHIN NORMAL RANGE PERFORM TEST ON TIME TO REPLACE SPRING ACCEL PEDAL ASSEMBLY WITH ENGINE PERFORM NORMALLY AT THIS TIME	CONST TCT LAST NIGHT DRIVING ON HIGHWAY, TRUCK LOCK IDLE. IDLES ONLY IDLE, NO ACCELERATION, DID NOT DECEL. SLOW DOWN WITH M2 FROM 50MPH. REPORT POWERTRAIN SECURITY POWERTRAIN SECURITY WILL STOP ACCELERATING IDLE ON V, P, R, L, OVERLA TURN IGN OFF & ON WILL BE OK FOR APPROX	281	USA	12005	072	USA	*	744	PT	011		
81.82	355.75	1	7501	NA	CA	31901	ACCELERATOR PEDAL ASSEMBLY PEDALS-MIT RAMP ACCELERATOR PEDAL NEEDS TO BE REPLACED. ONLY IDLES ON TEST FROM ACCEL. ONLY IDLES ON TEST LIGHT COMES ON NORD PASS CODE CODE P0227 REPLACE FAULTY ACCEL PEDAL ASSEMBLY WITH NORD PASS CONT CODE PASS			88	USA	11907	012	USA	*	361	PT	011		
81.82	128.05	0.3	2289	NA	TX	31901				02	USA	12002	024	USA	*	351	PT	011		
81.82	282.35	2.3	4528	NA	LA	31901	ACC TEST DIESEL DASH PER SHEET REPLACED PEDAL ASSEMBLY			28	USA	12047	022	USA	*	341	PT	011		
81.82	189.35	1	214	NA	GA	31901	ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE CHECK THE CONNECTIONS CONNECT NOT TO THE VEHICLE ELD SELECT FOR RLM FUNCTION STD P1111 TP LE MAY BE P1111 PERFORMED DIAGNOSIS TROUBLE CODE TEST THE FAULTY ACCELERATOR PEDAL, REPLACED THE PEDAL ASSEMBLY			70	USA	12028	004	USA	*	353	PT	011		
81.82	178.7	1.5	3249	NA	NY	31901		RE PEDAL AND RE-COMD AND CLEARED DTC.		80	USA	14748	004	USA	*	346	PT	011		
81.82	128.32	1	3761	NA	A	31901	P0227 RAN HSD, SET CODE FOR AP FOR A/C PRESSURE			217	USA	12100	2	USA	*	350	PT	011		
81.82	359.28	4.5	2232	NA	CA	31901	2240 ENGINE PERFORMANCE TEST RAN FOUND THROTTLE PEDAL WAS FAILED NOT OPERATING PROPERLY MIT BE REQUESTED TO REPLACE THROTTLE PEDAL ASY DUE TO NO PUBLISHED LABOR OPER ROOM FOR REPAIR			814	USA	12002	072	USA	*	354	PT	011		
81.82	184.78	1.3	8641	NA	IL	31901	FAILED THROTTLE PEDAL TEST BEC SYSTEM REPLACE THROTTLE PEDAL ASBY M2 SWITCH AND RE TEST OK			202	USA	12547	004	USA	*	344	L1	011		
78.82	188.61	1.1	2886	NA	OR	31901	MIS PASS PID MONITOR THROTTLE POSITION VERIFIED INT. OPERATION REPLACED PID ASBY			822	USA	12001	004	USA	*	351	L1	011		
78.82	157.82	1	2012	NA	NY	31901	ACCEL PEDAL SHORTED REPLACED ACCELERATION PEDAL AND TEST (CHECK TO BE IN REPLACE ACCEL PEDAL AND SENSOR ASBY			72	USA	12137	1	USA	*	355	L1	011		
81.82	184.28	1	57	NA	VA	31901	2240 RAN HSD TESTS CODE P0227 P0227 PERFORM TESTS REPLACE THROTTLE PEDAL ASBY CLEAR CODES RE TEST REPLACED BY REWORKING PEDAL ASSEMBLY IN TIME NO SLTS FOR TEST			20	USA	12002	004	USA	*	341	L1	011		
81.82	272.69	2.5	0120	NA	IA	31901				78	USA	11087	004	USA	*	344	PT	011		
78.82	157.82	0.3	84	NA	MD	31901				301	USA	14004	2	USA	*	358	PT	011		

INTR. C. ST. GR. CSTR	TOT. CO. HR	LAB. HR	OUR. CO. D	OUR. CO. D	RESN. ST. F. CO. D	OPSC. CO. E	TECH. TEXT1	TECH. TEXT2	CURT. TEXT	AREA. CO. CD	COURT. ST. CD	BLK. CL. TSN. R. CD	CHRY. SCOUT. CD	GRN. VPS. CD	AWB. VL. CD	WRT. CO. CD	TR. PLA. S
11.02	15.00	1.0	303	NA	NY	21807	CHECK DTCS, PERFORM PIN POINT TEST, NO VOLTAGE TO LOW, CHECKED FOR OPENED WIRING, REPLACE PEDAL ASSEMBLY AND WIRING CONCERN, FOUND THROTTLE PEDAL ASSEMBLY BROKEN, NECESSARY TO RE-THROTTLE PEDAL, RECHECKED OPERATION ON AT THIS TIME.		CUSTOMER DAYS MIL ON, NO ACCELERATION WHEN PUBLISHING THE ACCELERATOR.	428	USA	77920	1	USA	NA4	FT	811
11.02	15.07	0.5	8918	NA	OR	21807	FUEL RELAY, RER FUSE & TRUCK ACCELERATED. CHECK CIRCUIT & FOUND SWITCH HAS A SHG SPOT, REPLACE PEDAL & SWITCH ASBY. RE TEST, NO CONCERN.		CUSTOMER STATES VEHICLE HAS NO ACCELERATION AT THIS	528	USA	77920	084	USA	NA4	FT	811
11.02	15.00	1.0	3800	NA	TX	21807	TRANS NOT POWER ELEC. DPM KORO NO ATCS KORO P0128 P0001 KORO NO ATCS PRESSURE TEST NORMAL AT 80% FLD LEVEL. CORRECT PMPORT TEST BRAVATIC SERIAL PROMPT SENSOR REPLACED TP SENSOR PORT ROAD TEST PASSED.		VEHICLE HAS NO ACCELERATION.	880	USA	70007	004	USA	NA4	FT	811
11.02	22.17	2.0	2028	NA	AZ	21807	TRANS NOT POWER ELEC. DPM KORO NO ATCS KORO P0128 P0001 KORO NO ATCS PRESSURE TEST NORMAL AT 80% FLD LEVEL. CORRECT PMPORT TEST BRAVATIC SERIAL PROMPT SENSOR REPLACED TP SENSOR PORT ROAD TEST PASSED.	TMS ATCS	TRANS NOT UP-SHIFTS AND NO ACCEL. LINE ELECTRICAL WHEN REAL. NOT OUTSIDE. SEE FOR NO ACCELERATION.	882	USA	77777	004	USA	NA4	FT	811
11.02	21.30	2.0	2028	NA	NY	21807	TRANS NOT POWER ELEC. DPM KORO NO ATCS KORO P0128 P0001 KORO NO ATCS PRESSURE TEST NORMAL AT 80% FLD LEVEL. CORRECT PMPORT TEST BRAVATIC SERIAL PROMPT SENSOR REPLACED TP SENSOR PORT ROAD TEST PASSED.		NO ACCELERATION	428	USA	11200	002	USA	NA4	FT	811
11.02	10.45	1.0	0790	NA	WA	21807	KORO FUEL, KORO SWITCH TEST PASSED. PFI METER AND PFI SENSOR FAILED. RE. REPLACE ACCELERATOR PEDAL ASBY. DRAIN EXCESS, RE TEST ALL OK. NO FAILED OPEN INTERNALLY.	CC 42-048	C 8 MEN HAS NO ACCEL. COMES TO AND FROM STOP VEHICLE HAS NO ACCEL. INTERMITTLY.	478	USA	10007	004	USA	NA4	FT	811
11.02	20.78	1.0	7028	NA	CA	21807	CHECK AND REPLACE ACCEL. ASBY. PERFORM 7.5 IN VEHICLE BRAKE DIAGNOSTICS & CORRECTIONS, PGM HAS EXCESS PRESS. FOR ACCELERATOR PEDAL & SENSOR ASBY, REPLACE PEDAL & SENSOR ASBY AT TIME, REPEAT FINAL TEST OK.		NO ACCEL. LINE ELECTRICAL WHEN REAL. NOT OUTSIDE. SEE FOR NO ACCELERATION.	787	USA	14004	2	USA	NA4	FT	811
11.02	21.01	2.0	2002	NA	IL	21807	VERIFY CUSTOMER CONCERN, DIAGNOSIS FOUND NO RESPONSE FROM ACCEL. PEDAL SENSOR REPLACE ASSEMBLY. CHECK OK. REPAIRABLE.		NO ACCEL. LINE ELECTRICAL WHEN REAL. NOT OUTSIDE. SEE FOR NO ACCELERATION.	308	USA	14100	1	USA	NA4	FT	811
11.02	11.00	0.0	1200	NA	PA	21807	REPLACE ASSEMBLY.		CUSTOMER STATES: HAS NO ACCELERATION. VEHICLE FORMERLY, CURT STATES VEHICLE WILL START BUT HAS NO ACCELERATION.	218	USA	17007	2	USA	NA4	FT	811
11.02	21.81	1.0	8028	NA	MA	21807	REPLACED AP ASSEMBLY, RETEST PUMP, NO XING OR DYING RESPONSES, POSSIBLE COLD WEATHER PUL. SENSOR FOR CUSTOMER'S PERFORMANCE. TESTS PULSES IN DONT PERFORM PFCST AND GEE REPLACE ETC ASBY. DRAIN AND RETEST OK. RE TEST, REPLACE ACCELERATOR PEDAL ASBY.		CUSTOMER STATES WHEN VEHICLE IS COLD START, VEHICLE BEING TOUCHED, NO ACCELERATION WHEN COLD. CHECK AND ASBY.	530	USA	10000	077	USA	NA4	FT	811
11.02	14.40	1.0	0200	NA	NY	21807	PERFORM PFCST AND GEE REPLACE ETC ASBY. DRAIN AND RETEST OK. RE TEST, REPLACE ACCELERATOR PEDAL ASBY.		NO ACCELERATION AT THIS	404	USA	17007	004	USA	NA4	FT	811
11.02	09.00	1.0	0000	NA	RI	21807	PERFORMED COMPLETION TEST, PERFORM TEST AND PID DATA, DIAGNOSED SENSOR ON ACCELERATOR PEDAL NOT WORKING PROPERLY, REPLACED ACCELERATOR PEDAL, RETEST, NO ACCELERATOR PEDAL SENSOR. VERIFIED CONCERN HAS TEST. PULSED. PFCST AND GEE REPLACE ETC ASBY.		OK FOR NO ACCELERATION AT THIS	788	USA	10000	077	USA	NA4	FT	811
11.02	10.00	0.0	0000	NA	TX	21807	PERFORMED COMPLETION TEST, PERFORM TEST AND PID DATA, DIAGNOSED SENSOR ON ACCELERATOR PEDAL NOT WORKING PROPERLY, REPLACED ACCELERATOR PEDAL, RETEST, NO ACCELERATOR PEDAL SENSOR. VERIFIED CONCERN HAS TEST. PULSED. PFCST AND GEE REPLACE ETC ASBY.		DIAGNOSED NO ACCELERATION, INTERMITTENT.	308	CAN	40000	004	CAN	NA4	FT	811
11.02	02.00	1.0	01	NA	VA	21807	PERFORMED COMPLETION TEST, PERFORM TEST AND PID DATA, DIAGNOSED SENSOR ON ACCELERATOR PEDAL NOT WORKING PROPERLY, REPLACED ACCELERATOR PEDAL, RETEST, NO ACCELERATOR PEDAL SENSOR. VERIFIED CONCERN HAS TEST. PULSED. PFCST AND GEE REPLACE ETC ASBY.		TOWNS IN INTERMITTENT. THROTTLE RCP. NO ACCEL.	708	USA	12000	2	USA	NA4	FT	811

INTL_CST	TOTY_CO	LABR	OUR_C	OUR_D	OUR_C	OUR_D	ST_P	OPED	TECH_TXT1	TECH_TXT2	CLST_TXT	AREA	COUNT	BASE	TOL	ENTRY	OPD	HPG	AWB	WRT	THE
CDT	OR	NR	D	D	D	D	CD	CD				CD	RY_CD	N_CD	CD	WORLD	CD	CD	CD	CD	PLA
81.88	248.35	1.2	778		NA	NY	31801		2ND DIAG PERFORMANCE DIAG FOUND PEDAL ASSEMBLY INCLUDING PSA PEDAL, RFR PEDAL ASSEMBLY CLEARED CODES.		CUSTOMER STATES VEHICLE WANTS TO DIE OR WILL NOT GO.	778	USA	179000	800	USA		748	FT	811	
81.88	345.87	4	831		NA	CO	31891		2ND DIAG PERFORMANCE PROBLEM YEAR OLD PERFORMANCE DIAG SHEET FOUND TP CODE P0221 AND FOUND NO OTHER PROBLEMS AT THIS TIME REPLACE ACCEL PEDAL ASSEMBLY		CHECK FOR GAS PEDAL WILL NOT GO WHEN YOU START OUT JUST IDLE	345	USA	135000	872	USA		744	FT	811	
81.88	168.82	1.2	812		NA	TX	31891		1 VEMPI CONCERN IS DIAG TEST CODES NOISE PASSENGER FOOT, PRESS, NOISE PASS PASSENGER TESTS, REPLACE ACCELERATOR PEDAL ASSEMBLY, CLEAR CODES MONITOR DIAG ON TEST DRIVE, RE-TEST		CLERK STATES AT TIMES WHEN BLOWING BUT NOT EXHAUST TO A STOP THEN REAPPLYING GAS PEDAL VEHICLE WILL NOT GO ACTS LIKE	812	USA	135000	872	USA		741	FT	811	
78.88	748.88	1	1472		NA	TX	31801		TEST SENSOR FAILURE CC IN 15 MIN TO HRS, NO OPS FOR REPAIR, VEMPI CONCERNING TEST CODES P0221 VERIFIED PASSENGER TESTER R AND REPLACE AP PEDAL, CLEAR CODES AND RE-TEST.		PRESS PEDAL TO THE FLOOR AND IT WILL NOT GO AT TIME HAS CODE IN IT P0221	808	USA	135000	884	USA		744	FT	811	
78.88	183.28	1.0	3891		NA	GA	31801		COMPLETED TEST CODE P0221 TP, OUT OF RANGE REPLACE GAS PEDAL, CLEAR ALL CODES RE-TEST OK		CUSTOMER STATES VEHICLE WILL NOT GO ABOVE 40	788	USA	911000	1	USA		741	FT	811	
81.88	244.12	2.8	3042		NA	FL	31801		PERFORMED A ENGINE PERFORMANCE DIAG THROUGH 14 DETRIED NO FAULT CODES WHEN TO P0200 OK AP AND FMI SWITCH HAD NO BATTERY VOLTAGE 0.8 TO 0.9 REPLACED PEDAL ASSEMBLY PERFORMED ENGINE DIAG, REPLACE ACCEL PEDAL ASSEMBLY		OK VEGH STAYS UP PLANE, BUT HAS NO THROTTLE. WILL NOT GO FROM IDLE TO 40 MPH	801	USA	911000	800	USA		743	FT	811	
78.88	114.84	0.8	4808		NA	FL	31801		PERFORMED ENGINE DIAG, REPLACE ACCEL PEDAL ASSEMBLY		OK WITH ACCELERATING RPM'S WILL NOT GO UP.	808	USA	226000	800	USA		748	FT	811	
81.88	148.87	0.8	8471		NA	AZ	31891		RE-TEST TO PASSENGER TEST TO BEEP TEST FOR ACC PEDAL AND TPA, REPLACED PASSENGER TESTER TO ROAD TEST, CLEARED THE CODES ALL PAS AT THIS TIME.		CUSTOMER STATES WILL APPLYING THE GAS PEDAL IT WONT GO BUT GO SOME TIMES TRUCK WONT GO AND ACCELERATOR PEDAL IS ON PLACE KOPS TP01777	888	USA	971170	800	USA		744	FT	811	8
78.88	218.47	0.8	3048		NA	TX	31891		RFR ACCEL PEDAL END			818	USA	188000	1	USA		748	FT	811	
81.88	279.88	2.8	3241		NA	MI	31801		8277 8PMS 42 800 CODES DIAGNOSIS AND PASSENGER TESTER PASSENGER FOOT, PASSENGER TESTER BUEZ TESTER LIP PRESSURE TESTER BUEZ STABILITY TESTER MONITOR AND RECORD FOR W HRS VEHICLE ROAD	TESTER ACP REACTS 1.1V AT TIMES AND NO THROTTLE RESPONSE, REPLACE ACCEL PEDAL ASSEMBLY, RE-TEST OK	WHILE DRIVING ACCEL PEDAL WONT MOVE TRY TO ACCEL AND WONT GO OUT SIDE WHEN TURNING STEERING WHEEL AND ACCEL IT WONT GO 70	279	USA	140010	872	USA		741	FT	811	8
78.88	173.88	1.2	484		NA	GA	31801		ACCELERATOR PEDAL BROKE PERFORMANCE DIAGNOSTIC T.S. IN TUBING ENGINE DIAG			778	USA	113000	1	USA		744	FT	811	
81.88	177.88	1.8	8388		NA	AR	31801		PERFORMED PERFORMANCE DIAG, PERFORMED PASSENGER TEST, REPLACED AP ASSEMBLY, CLEARED CODES AND TEST DRIVE.		CLERK STATES WHEN ACCELERATOR AND TRUCK WONT GO, HAVE TO PUMP ACCEL PEDAL TO GO WONT GO TO 30 MPH	870	USA	138000	884	USA		752	FT	811	
81.88	214.13	2.5	7281		NA	CA	31891		REPLACE SENSOR RFR VEMPI DIAG AND MONITOR TEST FOUND ACCEL PEDAL CIRCUIT FULLY PASSENGER TEST FOUND OPEN CIRCUIT IN T.P. SENSOR REPLACE PEDAL ASSEMBLY RE-TEST AND PID MONITOR T.P. SENSOR AND IDLE VALVE ACTION SWITCH ALL TEST	T.P. OK TEST DRIVE OK	C.S. AT TIMES WHEN PUSING THE ACCEL PEDAL THE TRUCK WONT GO LIKE NOT SETTING FUEL. CHECK AND ACCEL.	818	USA	172010	884	USA		741	FT	811	
81.88	174.88	1	7818		NA	CA	31891					818	USA	172010	884	USA		747	FT	808	

MTL_C	TOT	COL	DA	DA	RES	ST	P	CPSC	TECH	TECH	CUST	AREA	COMB	BL	DL	TN	CON	GR	VFD	AMB	WV	TR		
QTY	QTY	S	D	D	D	D	D	CD	TEXT	TEXT	TEXT	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD		
31.82	248.34	2.3	2018	MA	NY			31801	TP CODES SHORTED ACCEL PEDAL ELECTRONIC TRANSMISSION DAMPERE		THROTTLE PEDAL WOULD NOT MOVE IN GEAR AT IDLE PRESS TO ACCEL, ENGINE DOESNT EVEN REV	301	USA	448017	004	USA	*	144	PT	311				
79.88	238.38	2.8	2020	MA	VT			31801	RAN INTO HOUSE CODES PRIMARY PRESS GO TO PPT FOUND NO SWITCH DEFECTIVE NOT ALLOWED TP TO INPUT TO PCM REPLACE PEDAL ASSEMBLY ASSEMB		VEHICLE HAS NO THROTTLE YOU CAN START IT BUT IT WONT MOVE	301	USA	448017	002	USA	*	144	PT	311				
41.82	102.88	8.4	2021	MA				31801	PAGE PEDAL DEFECTIVE RAN IN FUEL FROM CLAYTONS HAD CRACKS IN BAWLER ABOUT THE CONCERN PART WAS CRACKED		O B VEHICLE WONT MOVE WHEN GIVE IT GAS, GAS PEDAL WERE, NOTE PARTS ORDERED BEFORE 20K MILES	304		102412	029	USA	*	144	PT	311				
51.82	188.08	1.8	2020	MA	TX			31801	RAN INTO HOUSE ON WOL WERE AP CRUIZ CODE, RAN PERPOINT TESTS USING DYNALOGGER MONITOR, FOUND OPEN IN PEDAL ASSEMBY REPLACED PEDAL ASSEMBLY, CLEARED CODES AND RETESTED ELEC PARTS		DID CUSTOMER STAGE WHEN PRESSING GAS PEDAL THE TRUCK WONT MOVE	317	USA	32448	004	USA	*	144	PT	311				
167.88	248.38	1	3116	MA	NJ			100004	PERFORM DIAG AND PER POINT TEST FOUND DEFECTIVE TP SENSOR REPLACE SENSOR CLEAR CODES RETEST SYSTEM ROAD TEST TRUCK		CUST STATES VEHICLE WONT MOVE IN GEAR	301	USA	100000	004	USA	*	144	PT	311				
51.82	232.88	2.8	2020	MA	FL			31801	SWIRL CLIPPER ROADTEST VEHICLE VERIFIED AT THIS ENGINE WILL JUST HOLD WONT ACCELERATE NO MATTER WHERE YOU PUT THE PEDAL, SECOND PERFORMANCE SHEET VEHICLE FUEL, OIL, OIL, OIL, BRAKE RESTRICTION, OIL, OIL	O PASS COME FROM ACED BY ELEC TEST PAGE FUEL, P PRESSURE B & B L O B O ELEC FLAMP PRESSURE BY FLEET RESTRICTION B KORN PAGE ICP TEST WITH LOW IDLE STABILITY AND CRANKCASE PRESSURE B CYL COAT	DID CUSTOMER REPORTS WHEN DEPRESSING ACCELERATOR SOMETIMES TRUCK WONT MOVE AS IF NO FUEL, CHECK AND ADVISE	301	USA	32448	004	USA	*	144	PT	311				
51.82	126.78	0.7	2022	MA	OR			31801	WARN TANK THROTTLE PEDAL ASSEMBLY		WHEN HITTING GAS CAR WONT MOVE	07	USA	100000	004	USA	*	144	PT	311				
79.88	81.38	0.2	2020	MA	MS			31801	SWIRL OPEN CIRCUIT IN ACCELERATOR PEDAL, 28 SPRING USING MMS REMOVE DTC CODES PRESS REPLACE ACCELERATOR PEDAL CLEAR ALL DTC CODES ROAD TEST AND RETEST		FOR VEHICLE WONT MOVE AT TIMES, HAVE TURN OFF & RESTART VEHICLE TO MOVE, CUST STATES CUSTOMER STATES BRUKE ON HARD ACCEL IS SLOWDOWN WONT MOVE	301	USA	100000	004	USA	*	144	PT	311				
80.84	238.18	1.8	2020	MA	CA			31801	PERFORM DIAG AND REEL AT SENSOR OK FOR SWIRL VALVE LIGHTEN SWITCH PERFORM ALL MISC TESTS ON P 288 TRUCK WITH T-3 D ISOL ENGINE, ALL TEST BONES WERE SWITCH PHASE, NO DTC AVAILABLE, RAN VIN THROUGH CHASS FOR R CLATED CONCERN WORK TO	UP BY THE YEAR, TESTS D ELEC VALIDATION SWITCH WITH OBM METER AND VIN H WERE PROE, ISLE VALIDATION SWITCH-ISE ATTEMPT TEST OPEN CIRCUIT, REPLACED THROTTLE PEDAL ASSEMBY, (INCLUDED SWIRL	CUSTOMER STATES WHEN BACKING UP, VEHICLE WONT MOVE, ALSO LOCKING POSITION WHEN CHASSIS	301	USA	148883	004	USA	*	144	PT	311				
476.88	308.38	8.8	240	MA	IA			31801	ABNORMAL, DASH REFL, GAS PEDAL		DASH OK FOR VEHICLE WONT FULL CUSTOMER STATES STARTS BUT WONT FULL	771	USA	351000	004	USA	*	144	PT	311				
79.88	128.31	0.6	2022	MA	GA			31801	REPLACE TPB SENSOR AND RAN DIAG ELEC TEST CODES FROM JEN TEST TO REPLACE ACCELERATOR PEDAL FOR CIRCUIT OUT OF RANGE, OK		PRESS ACCELERATOR AND ENGINE WONT REV UP AT TIMES	315	USA	100012	004	USA	*	144	PT	311				
80.84	281.87	2.7	2024	MA	NC			31801	DASH, REPLACE ACCELERATOR PEDAL ASSEMBLY		VEHICLE WONT RECEL	306	USA	172000	004	USA	*	144	PT	311				
76.84	116.88	0.7	1888	MA	OH			31801	TP SENSOR IN PEDAL ASSEMBY DEFECTIVE, 2881 PART NOT LISTED IN BULB		ENGINE WONT REV UP PART IDLE WONT THROTTLE UP	301	USA	100001	004	USA	*	144	PT	311				
80.84	187.34	0.8	1481	MA	MS			31801	DASH, REFL, THROTTLE ASSEMBLY			301	USA	100000	004	USA	*	144	PT	311				

MTPL C CST	TOT OCC CST	HR	DLR C	DLR C	REGN C	ST P C	OPSC C	TECH INT	TECH TACH	CURE TCT	AREA C	COUNT C	SLR JL C	TOL C	CARRY C	CRV C	WFO C	WAS C	WRT C	TRE C	
80.04	146.21	1.2	8796	*	NA	IN	31801	CHECKED FOR TRUCK NOT ACCELERATING. CHECKED CODES. FOUND CODE FOR ACCELERATOR PEDAL. MONITORED PDS AND ACCELERATOR PEDAL. REPLACED ACCELERATOR PEDAL AND RECHECKED OPERATION. ON DRIVE ROAD TEST VEHICLE. SENSOR WORKING. HOOKED UP WGS. NO TROUBLE CODES IN SYSTEM. PERFORMED PFM POINT TEST USING CHECK FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY.		TRUCK NOT ACCELERATE.	8796	USA	147822	824	USA	*	NA1	PT	871		
126.72	247.88	1	7888	*	NA	CA	30081	PERFORMED PFM POINT TEST USING CHECK FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY.	AND ROAD TEST AFTER REPAIRS.	CUSTOMER REPORTS WHEN ACCELERATING VEHICLE CODES NOT CLEAR. LIGHT GOES DIMMY FOR THE VEHICLE NOT ACCELERATING.	8796	USA	128822	824	USA	*	NA2	PT	871		
75.89	151.03	0.8	2088	*	NA	TX	31801	PERFORMED PFM POINT TEST USING CHECK FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY.		STARTS BUT WILL NOT ACCELERATE.	8796	USA	128822	824	USA	*	NA1	PT	871		
80.04	152.47	0.9	4437	*	NA	TX	31801	THROTTLE PEDAL SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY.		AIR WHILE IDLING ALL GAGES WOULD FLUCTUATE AND THEN ALL DROP TO ZERO. PUSHING IN VEHICLE WOULD NOT ACCEL. AFTER THAT	8796	USA	128822	824	USA	*	NA7	PT	871		
87.49	169.08	1.1	4888	*	NA	IN	31801	ACCELERATOR PEDAL AND SERVICE ASSEMBLY ASSEMBLY TEST. PERFORM TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.	IN CODES.	CUSTOMER STATES WHILE DRIVING VEHICLE STOPPED ACCELERATION THEN WOULD KICK BUT WOULD NOT ACCELERATE WHEN STOPPING ON GAS PEDAL.	8796	USA	142000	824	USA	*	NA8	PT	871		
75.89	218.85	1.2	5288	*	NA	CA	31801	PERFORM PFM POINT TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.		TRUCK WILL KICK BUT NOT ACCEL.	8796	USA	171422	824	USA	*	NA4	PT	871		
82.04	323.27	1	4288	*	NA	IL	31801	PERFORM PFM POINT TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.		CUSTOMER STATES WHILE DRIVING ATTEMPTED TO ACCELERATE TRUCK WOULD NOT ACCELERATE ALSO HAS HAPPENED AFTER START UP WOULD NOT MOVE WHEN PUT IN DRIFT.	8796	USA	128822	824	USA	*	NA4	PT	871		
76.88	148.84	0.8	3178	*	NA	OR	31801	PERFORM PFM POINT TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.		HAS NO GAS PEDAL WHEN STOPPING DOWN ON GAS PEDAL. CODE TO THE FLOOR AND DOES NOT CHANGE THE ACCELERATION AT ALL.	8796	USA	134022	824	USA	*	NA4	PT	871		
75.89	181.88	1.3	6388	*	NA	TX	31801	PERFORM PFM POINT TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.		CUSTOMER STATES WHEN DEPRESSING ON FUEL VEH DOES NOT GO.	8796	USA	128822	824	USA	*	NA4	PT	871		
81.88	135.0	0.7	7188	*	NA	MI	31801	PERFORM PFM POINT TEST. MONITOR PDS VOLTAGE. AS TO 3.0V WITH INVERTING TRANS. REPLACE PEDAL ASSEMBLY. CLEAR AND DO TEST ALL PDS USING PDS CHECK. GAS PULLED CODE 5 FOLDED SWAY BAR SPRING FROM GAS PEDAL. CLEARED GAS PEDAL. REPLACE THE ACCELERATOR PEDAL ASSEMBLY. PERFORM PFM POINT TEST.		CHECK IN ASSEMBLY IF YOU PUSH ON THE GAS PEDAL IT DOES NOT GO. BUT STAYS AT THE SAME RPM.	8796	USA	140000	824	USA	*	NA2	PT	871		
75.89	175.41	1.4	8088	*	NA	AZ	31801	PERFORMED GAS AND WITHHELD CODE P0122 AND P0221. PERFORMED PFM POINT TEST AND FOUND THE THROTTLE PEDAL FAULTY. REPLACED PEDAL AND ROAD TEST. CLEAR PDS. PERFORMED CHECK TEST AND PFM POINT TEST.		AT A STOP WHEN YOU TAKE OFF YOU PUSH ON THE GAS AND THE RPM GOES UP BUT THE TRUCK DOES NOT GO AND THEN IT WILL	8796	USA	171422	824	USA	*	NA2	PT	871		

MTRL_CST_BN	TOT_CD	LIBR	DLF_C	DLF_D	DLF_S_C	DLF_S_D	NSP_C	ST_P	CPSC	TECH_TXT1	TECH_TXT2	CUST_TXT	AREA_CD	COUNTY_CD	BLD_CD	TWR_CD	CTRY_CD	OFF_CD	VFB_CD	AWB_CK	WFO_CD	TRM_PLA
78.86	207.28	2	7784				NA	CA	21801	TIPS VOLTAGE CONFIRMED HESITATION DUE TO ACCCEL. GAS PEDAL ASSEMBLY FAULT CALIBRE INCORRECTIVE		WILL GO TO IDLE WHEN ON ACCELERATE.	707	USA	12388	1	USA	*	NA1	PT	BT1	
80.84	380.82	4.9	4381				NA	TX	21801	WILL TEST, REPLACED THE PEDAL PERFORMED PERFORMANCE DIAGNOSTICS STEPS 1 THRU 14 ON SERVICE CONTR HAD CODE P0122 AND P0221 POLDS INTERMITTENT OUCH BY REPLACE GAS PEDAL ASSEMBLY THAT CODE WITH SOLE VALIDATION SWITCH ROAD TEST PASS OK	K DC TECH 180	CUSTOMER STATES TRUCK DOES NOT MOVE AND IT FEELS LIKE IT STALLS OUT.	804	USA	12487	2	USA	*	NA1	PT	BT1	
78.88	247.73	2.8	2822				NA	TX	21801	INSPECTED WHEN PEDAL SENSOR SERVICE PERFORMANCE DIAGNOSTICS 7.24 DI TURNS ENGINE 2300 RPM TEST WITH POINT PD MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		CHECK FOR FOR NOT GOING WHEN HT ACCELERATE	804	USA	180478	2	USA	*	NA1	PT	BT1	
81.88	183.81	1.1	8384				NA	UT	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		CUSTOMER STATES VEH STAYS AT IDLE WHEN TRYING TO ACCELERATE. CHECK AND ADVISE	801	USA	147733	894	USA	*	NA1	PT	BT1	
78.88	127.28	8.8	88				NA	VA	21801	ECU TEST, PERFORMED, REPLACED CP. SENSOR, NO TEST.		WHEN YOU PRESS THE GAS PEDAL THE ENGINE DOES NOT MAKE ANY MORE RPM'S	703	USA	123088	2	USA	*	NA1	PT	BT1	
80.88	184.88	1.8	A882				NA	OK	21801	ECU TEST, PERFORMED, MONITOR POINT TO ACCELERATOR POSITION SENSOR OUT OF RANGE REPLACED ACCEL. SWITCH PEDAL ASSEMBLY.		CK THROTTLE CABLE, WONT ACCELERATE. REPORT	208	CAN	28278	884	CAN	*	NA1	PT	BT1	
80.88	184.88	1.8	7888				NA	SC	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		AT TIMES NO THROTTLE ON ACCEL. CUSTOMER STATES VEH WILL NOT CHANGE WHEN PUSHERS ACCEL. WHEN COLD. DOES FINE AFTER WARMED UP	808	USA	171173	884	USA	*	NA1	PT	BT1	
81.88	288.88	2.4	188				NA	NY	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		WHEN ACCEL. APPLIED VEHICLE WOULD NOT MOVE.	800	USA	187721	8	USA	*	NA1	PT	BT1	
81.88	187.88	8.8	8712				NA	UT	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		CUSTOMER STATES THAT THE TRUCK JUST DIES WHEN PRESSING ON THE GAS PEDAL.	801	USA	18880	822	USA	*	NA1	PT	BT1	
187.88	282.8	1.7	8812				NA	MI	10080	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		CUSTOMER STATES NO RPM CHANGE WHEN APPLYING ACCELERATOR, NO PRESSURE ON PEDAL.	808	USA	71188	884	USA	*	NA1	PT	BT1	
81.88	188.12	1.8	8888				NA	AR	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		CHECK VEHICLE FOR BLOWING PUFFS WHEN ACCELERATING CALIBRE VEHICLE NOT TO ACCELERATE	800	USA	128801	884	USA	*	NA1	PT	BT1	
81.88	188.82	2.3	8874				NA	AR	21801	PERFORMED DIAGNOSTIC MONITOR AND MONITOR PEDAL, VIB IS NOT RESPONDING INTERMITTENTLY REPLACED PEDAL SWITCH ASSEMBLY AND TESTED TO VERIFY PROBLEM OK TP SENSOR PEDAL ASSEMBLY VERIFY CONCERN NO ACCCEL. CK SERVICE LIGHT ON CK ECU SYSTEM RECEIVED CODE P0221 IN MEMORY AS WELL AS K0001 ECU TEST		VEHICLE HARD TO GET TO ACCELERATE	400	USA	128888	884	USA	*	NA1	PT	BT1	
81.88	188.81	1	4888				NA	FL	21801	TEST PEDAL ASSEMBLY FOUND INOP REPLACE PEDAL ASSEMBLY.		FROM ACCELERATOR AND NO RQ.	800	USA	88888	884	CAN	*	NA1	PT	BT1	

MTPL_C CST	TOT_COST BY_CAR COST	HR	OUR COST COST	RMSE COST	ST_P COST	CPRO COST	TECH_TXT1	TECH_TXT2	CHRY_DCT	AREA CD	COUNTY CD	BLD_DT CD	TOOL CD	CHRY CD	CHRY CD	AMTS CD	TRY CD	TRM FLA
81.81	187.4	1.1	2413	NA	TK	31801	ASST FAILED THROTTLE POSITION SENSOR ON CLAMPING VERIFIED CONCERN PERFORM PERFORMANCE DIAG. 1) PERFORM VACUUM INSPECTION 2) CHECK EXHAUST CLEAN FUEL PRESS 3) CHECK EXHAUST OIL LEVEL PRESS 4) STAKE WIRE	STRUTTER FROM SPINDLE RODS ON. PERFORM TEST PRESS REVERSE CONTROLLER DOORS P0222/P0221/P0208/P0207 TEST REPORT TO FAILED TP SENSOR. REPLACED ACCELERATOR PEDAL.	WHEN TRUCK IS IDLING AND PRESS RAB CAR DOES NOT MOVE ON TAKE OFF	877 USA	10813	273	08A	*	141	27	811	
80.81	143.46	7.3	4488	NA	TK	31801	RODS TEST PEDAL ON CLAMP AND RUB FOR POINT TEST TRACE WIRE LEAD TO REPLACE PEDAL ASSEMBLY. OPEN CIRCUIT		CUSTOMER STATES WONT ACCELERATE WITH PEDAL	887 USA	88181	1	USA	*	144	27	811	
81.82	150.32	1.8	8532	NA	ND	31801	DO SYMPTOM DIAGNOSTIC, RUN QUICK TESTS P0221, P0222 DO POINT TESTS, MONITOR PIDS, TEST AP CIRCUITS, WIR ACCEL PEDAL INSTALL NEW PEDAL CLEAR CIRCUIT DRIVE AND DRIVE		VEHICLE WONT ACCEL COLD	781 USA	48820	281	CAN	*	141	27	811	
87.82	288.44	2.8	8887	NA	AS	30971	DIAG CONFIRM CONCERN. PERFORMED TESTS 1.1L PERFORM TESTS FOR CODES P0222/P0221. TP VOLTAGE WOULD DROP OFF AT WOT. SOMETHING WOULD STAY TELEPHONED TO ASSEMBLY, REPLACED PEDAL ASSEMBLY. CLEAR CODES & TRY PEDAL. TEST. RUN PERFORMANCE DIAG. DIAGNOSIS THE ACCEL. PADK APRY TO BE DEFECTIVE. TEST REPLACED PEDAL ASBY AND TEST DRIVE. ALL OK AT THIS TIME. QUALITY CONTROL, BY KELL Y CORP	REG PIDS. TEST DRIVE OK NOW.	REPAIR FOR THE VEHICLE WONT ACCELERATE HAVE TO RECAL PEDAL	788 CAN	48848	284	CAN	*	141	27	888	
78.81	287.88	4.2	2417	NA	TK	31801	PERFORM DIAGNOSTIC TO FULL CODES, WENT TO POINT TESTS, FOUND PEDAL FAILURE. REPLACED PEDAL ASBY TECH PERFORMED SEC PEDAL POINT TEST FOUND THE ACCEL. PEDAL OPEN REPLACED ACCEL. PEDAL. RETESTED CLEARED CODES ON AT THIS TIME RUN PERFORMANCE DIAGNOSTIC & W TEST FOR CODES P0221, P0222 TO REPLACE PEDAL ASBY		NO ACCELERATION	877 USA	10820	1	USA	*	141	27	811	
81.82	128.31	0.8	3287	NA	TK	31801	PERFORM DIAGNOSTIC TO FULL CODES, WENT TO POINT TESTS, FOUND PEDAL FAILURE. REPLACED PEDAL ASBY TECH PERFORMED SEC PEDAL POINT TEST FOUND THE ACCEL. PEDAL OPEN REPLACED ACCEL. PEDAL. RETESTED CLEARED CODES ON AT THIS TIME RUN PERFORMANCE DIAGNOSTIC & W TEST FOR CODES P0221, P0222 TO REPLACE PEDAL ASBY		THINK NO PEDAL ACCELERATION	878 USA	10820	273	USA	*	144	27	811	
78.82	134.7	1	8887	NA	TK	31801	PERFORM DIAGNOSTIC TO FULL CODES, WENT TO POINT TESTS, FOUND PEDAL FAILURE. REPLACED PEDAL ASBY TECH PERFORMED SEC PEDAL POINT TEST FOUND THE ACCEL. PEDAL OPEN REPLACED ACCEL. PEDAL. RETESTED CLEARED CODES ON AT THIS TIME RUN PERFORMANCE DIAGNOSTIC & W TEST FOR CODES P0221, P0222 TO REPLACE PEDAL ASBY		WILL NOT ACCEL.	812 USA	10888	1	USA	*	144	27	811	
81.84	128.14	1.1	8877	NA	OK	31801	DIAG CONFIRM CONCERN. PERFORMED TESTS 1.1L PERFORM TESTS FOR CODES P0222/P0221. TP VOLTAGE WOULD DROP OFF AT WOT. SOMETHING WOULD STAY TELEPHONED TO ASSEMBLY, REPLACED PEDAL ASSEMBLY. CLEAR CODES & TRY PEDAL. TEST. RUN PERFORMANCE DIAG. DIAGNOSIS THE ACCEL. PADK APRY TO BE DEFECTIVE. TEST REPLACED PEDAL ASBY AND TEST DRIVE. ALL OK AT THIS TIME. QUALITY CONTROL, BY KELL Y CORP		VEHICLE WONT REV UP. CHECK CODES OF CODES OF ACCELERATION	880 USA	88888	281	08A	*	144	27	811	
87.85	128.23	0.8	8887	NA	OK	31801	DIAG CONFIRM CONCERN. PERFORMED TESTS 1.1L PERFORM TESTS FOR CODES P0222/P0221. TP VOLTAGE WOULD DROP OFF AT WOT. SOMETHING WOULD STAY TELEPHONED TO ASSEMBLY, REPLACED PEDAL ASSEMBLY. CLEAR CODES & TRY PEDAL. TEST. RUN PERFORMANCE DIAG. DIAGNOSIS THE ACCEL. PADK APRY TO BE DEFECTIVE. TEST REPLACED PEDAL ASBY AND TEST DRIVE. ALL OK AT THIS TIME. QUALITY CONTROL, BY KELL Y CORP		CUST. STATES UNABLE TO ACCEL, NO THROTTLE	888 USA	177888	281	08A	*	141	23	811	
78.88	188.45	1.8	2587	NA	CA	31801	TEST COMPLETE INSTALL PEDAL RECALIBRATE		NO ACCEL AT TIMES	840 USA	12788	1	USA	*	144	27	811	
78.88	128.7	0.8	8887	NA	VA	31801	PERFORMED CONCERN PERFORMED PERFORMANCE DIAG TEST 1.1 REPLACED PEDAL ASSEMBLY. REPLACED BLOW PLATE AND RELAY OPERATED		CUSTOMER STATES WHEN GO TO ACCELERATE VEHICLE DOES NOT WANT TO GO AT TIMES. FEELS LIKE ENGINE TIME CLOGGED UP???	838 USA	10882	2	08A	*	141	27	811	
81.88	287.88	3.2	8887	NA	VA	31801	TESTING WOT TESTED RECEIVED CODE P0221 P0222 IN H 8888 P0221 P0222 TACKLED CHAS TEST & VOLTAGE TEST IN PED TOOK P0221 TEST ON CIRCUIT. TEST WITH BREAK OUT BOX INSTALLED LOCKING FOR VOLTAGE TEST WITH WIRELESS	TEST WHILE DRIVING IN P0221 ON WOT DEL. DISPLAY FELT THAT THE VOLTAGE DROPPED TO 9 VOLT & ON ROAD TEST REPLACED ACCEL PEDAL ASBY CLEAR P0221 CODES & PERFORM TESTS OK NOW	CUST STATES GIVE GAS AND VEH DOES NOT MOVE	816 USA	12788	281	08A	*	141	27	811	

MTL_C	BY	GR	HR	DU	BU	REG	ST	P	OP	TECH	TECH	CURT	AREA	COUNT	BL	DO	ENTR	CH	PR	US	WRT	DL
INT	CS	S	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
19.78	388.4	3.7	3788	*	MA	NY	21801			DO ALL TESTS ON PERFORMANCE DIAGNOSTIC SHEET AND FOUND BAD TPS AND REMOVE AND REPLACE COMPLETE ACCEL. PEDAL ASSEMBLY NO LABOR TO DO SO USED 1875		CUSTOMER STATES NO ACCELERATION	718	USA	13208	2	USA	*	144	PT	811	
19.88	117.88	3.7	3497	*	MA	TX	21801			PERFORM NEW TEST REPLACE SPEEDOMETER PEDAL ASSEMBLY		CUSTOMER WANT ACCELERATE	278	USA	13208	1	USA	*	144	PT	811	
19.88	120.98	1.1	340	*	MA	NY	21801			NEW ESC TEST FOUND CODE P0021 IN WDS. REPLACED PEDAL CLEARED CODES		WONT ACCELERATE AT TIMES	607	USA	13208	2	USA	*	144	PT	811	
19.88	345.88	3.8	3888	*	MA	MO	21801			WAS OPEN ON NEW FRAME PERFORMANCE CHART AND REPLACED THE THROTTLE PEDAL 478		CUSTOMER STATES BUT NO ACC. CORRECT FOR	818	USA	13208	1	USA	*	144	PT	811	
19.88	181.88	1.8	1814	*	MA	NC	21801			TEST DRIVE 28 MILES NO PROBLEM FOUND NEW TEST CODE P0021 MONITOR PVS PD ON NEW DISPENSED		CUSTOMER STATES VEH WILL CLUT FELLING AT TIMES WHEN STARTING OFF FROM A DEAD STOP.	704	USA	13208	1	USA	*	144	PT	811	
19.88	287.87	1.8	3388	*	MA	CA	21801			NEW TEST PUSH TP SENSOR OUT OF FRAME FRONT TTY CL WERE NO SHRT OR OPEN MONITOR PVS RAR TP SENSOR SHEET DONE		CUT STATES W/LOCK NOT WANTING TO ACCEL	828	USA	13208	1	USA	*	144	PT	811	
19.88	178.87	1.8	3888	*	MA	TX	21801			NEW TEST 248 TEST ESC P0021 PERFORMED PO-POINT TEST BRKASOUT SIDE INSTALLED AND TEST PASSED NEW AND P0021 REPLACED TP SENSOR ACCELERATOR PEDAL SENSOR ASSEMBLY IDENTIFIED GOOD TEST OK		DO CHECK TRUCK BUT DOES NOT WANT TO ACCELERATE	671	USA	13208	1	USA	*	144	PT	811	

YR	LN	CD	LIB_C	LIB_D	MKT_D	MOD_C	MOD_D	DRIVE	ENR_C	TRNS	PLAN	PRODN	WRTY	NAME	DOC	PL	WAL	PRY	PRY	PRY	DIST	GOOD	ST	TR	CL	BL
YR	LN	CD	DET	CD	REV	AL	CD	CD	CD	S	T	ST	ST		N	N	CD	AL	AL	CA	CD	ST	W	KE	BL	
2001	FTW00001	000001	26.51	707	TF	700	700	7E	700	700	A1	21-Mar-01	24-Mar-01	COLUMBIA FORD SALES INC	000001	000001	0101	0000	0000	00	000	00	21-Mar-01	20	100000	0000
2001	FTW00002	000002	26.47	707	TF	700	700	7E	700	700	A1	19-Mar-01	22-Mar-01	CHRYSLER MOTOR COMPANY	000001	000001	0101	0000	0000	00	000	00	19-Mar-01	2	110000	0000
2001	FTW00003	000003	26.48	707	TF	700	700	7E	700	700	A1	11-Apr-01	22-Apr-01	CHRYSLER MOTOR LTD	000001	000001	0101	0000	0000	00	000	00	11-Apr-01	0	000000	0000
2001	FTW00004	000004	26.47	707	TF	700	700	7E	700	700	A1	19-Mar-01	21-Mar-01	RAINBOW FORD SALES INC	000001	000001	0101	0000	0000	00	000	00	19-Mar-01	20	140000	0000
2001	FTW00005	000005	26.47	707	TF	700	700	7E	700	700	A1	20-Mar-01	18-Mar-01	EL L. FORD SALES LTD	000001	000001	0101	0000	0000	00	000	00	20-Mar-01	20	000000	0000
2001	FTW00006	000006	26.44	707	TF	700	700	7E	700	700	A1	19-Mar-01	20-Mar-01	EL L. FORD SALES LTD	000001	000001	0101	0000	0000	00	000	00	19-Mar-01	0	000000	0000
2001	FTW00007	000007	26.50	707	TF	700	700	7E	700	700	A1	19-Mar-01	18-Mar-01	EVER CITY FORD TRK SLS INC	000001	000001	0101	0000	0000	00	000	00	19-Mar-01	20	100000	0000
2001	FTW00008	000008	18.61	707	TF	700	700	7E	700	700	A1	12-Mar-01	20-Mar-01	MOBILE FORD	000001	000001	0101	0000	0000	00	000	00	12-Mar-01	20	000000	0000
2001	FTW00009	000009	26.2	707	TF	700	700	7E	700	700	A1	20-Feb-01	24-Mar-01	BLACK FORD MOTORS INC	000001	000001	0101	0000	0000	00	000	00	20-Feb-01	7	400000	0000
2001	FTW00010	000010	27.07	707	TF	700	700	7E	700	700	A1	25-Mar-01	17-Apr-01	GAL NORTHBATCH FORD	000001	000001	0101	0000	0000	00	000	00	25-Mar-01	0	000000	0000
2001	FTW00011	000011	24.20	707	TF	700	700	7E	700	700	A1	20-Mar-01	18-Mar-01	COUNTRY FORD	000001	000001	0101	0000	0000	00	000	00	20-Mar-01	20	170000	0000
2001	FTW00012	000012	26.2	707	TF	700	700	7E	700	700	A1	18-Mar-01	22-Mar-01	A.M. FORD SALES LTD	000001	000001	0101	0000	0000	00	000	00	18-Mar-01	20	110000	0000
2001	FTW00013	000013	26.5	707	TF	700	700	7E	700	700	A1	20-Mar-01	14-Apr-01	CHRYSLER MOTOR LTD	000001	000001	0101	0000	0000	00	000	00	20-Mar-01	27	100000	0000
2001	FTW00014	000014	26.5	707	TF	700	700	7E	700	700	A1	10-Mar-01	20-Mar-01	FORTUNA MOTORS INC	000001	000001	0101	0000	0000	00	000	00	10-Mar-01	7	200000	0000

PRO3-044-A 5367

MOI_YR_VIN_CD	LSR_D_DST	VEH_LINE_CD	MTY_D_YEAR	SEC_C_YEAR	MILE_EMS_CD	DRIVE_CD	ENG_CD	TRAN_S_CD	PLAN_T_CD	FRONT_D_T	MTY_STA_DT	NAME	DOC_NO_M	PL_NO_M	WCC_CD	FRY_PAL_P	FRY_PAL_P	FRY_PAL_P	CURT_CODE_CD	COND_CD	REPL_DT	TRM_YEAR	CLM_NO	MLME
20011FTRW21F0400028		111077	TF	TRD	TCD	TE	TDS	TDS	A1	2-89-01	21-89-01	ROYAL FORD TRUCKS, INC.	202000	202001	STD1	1C3K	AF33	BA	D32	48	4-26-89	14	1199771	10114
20011FTRW21F0400110		101077	TF	TRD	TCD	TE	TDS	TDS	A1	14-89-01	8-29-89	ONCHARD FORD SALES LTD	00001A	000001	STD1	1C3K	AF33	BA	D32	48	18-04-89	0	100113	0
20011FTRW21F0400110		041077	TF	TRC	TCD	TE	TDS	TDS	A1	22-89-01	1-9-91	MILLON FORD	101104	070011	STD1	1C3K	AF33	BA	A49	44	10-29-89	15	1179400	10000
20011FTRW21F0400110		001077	TF	TRD	TCD	TE	TDS	TDF	A1	8-89-89	2-04-90	PORTUNA MOTORS INC.	000001	000001	STD1	1C1Z	AF33	AB	D32	48	02-04-90	00	000000	00000
20011FTRW21F0400110		101077	TF	TRC	TCD	TE	TDS	TDS	A1	22-89-89	21-09-90	DEERY ANDREWS FORD SALES INC.	100000	000000	STD1	1C3Z	AF33	BA	D11	48	14-09-90	17	001000	10000
20011FTRW21F0400110		172077	TF	TRC	TCD	TE	TDS	TDS	A1	22-89-89	21-09-89	LITINA FORD LINCOLN MERCURY OF	021000	000000	STD1	1C3K	AF33	BA	A47	48	20-09-89	21	1400104	00011
20011FTRW21F0400110		010177	TF	TRC	TCD	TE	TDS	TDS	A1	1-89-91	31-08-91	LAKE CITY FORD SALES LTD	000001	000000	STD1	1C3Z	AF33	BA	D19	48	11-08-91	1	000000	00000
20011FTRW21F0400110		001077	TF	TRC	TCD	TE	TDS	TDF	A1	8-09-89	16-19-91	DEARBORN MOTORS LTD	000000	000101	STD1	1C3K	AF33	BA	D00	48	8-09-89	20	1001000	00000
20011FTRW21F0400110		700177	TF	TRC	TCD	TE	TDS	TDS	A1	2-89-89	10-09-89	TRUCK PARTS AND EQUIPMENT CO	140001	000100	STD1	1C3K	AF33	AB	D42	20	10-09-89	20	1120000	00000
20011FTRW21F0400110		001077	TF	TRC	TCD	TE	TDS	TDS	A1	10-89-01	10-09-01	BROOK MOTOR, INC.	010104	000011	STD1	1C3K	AF33	BA	A06	48	2-09-91	7	001000	10000
20011FTRW21F0400110		711077	TF	TRC	TCD	TE	TDS	TDS	A1	4-09-89	20-09-89	LARRY N MILLER FORD - D	0700001		STD1	1C3K	AF33	BA	D00	48	4-09-89	20	000000	00000
20011FTRW21F0400110		10114	TF	TRD	TCD	TE	TDS	TDF	A1	7-89-91	8-89-91	STEVE MARSHALL FORDSALES LTD	0000001	000000	STD1	1C3K	AF33	BA	D00	48	11-29-91	21	000000	00100

REL YR	AVL CD	LAB L QTY	VEH LINE CD	MKT D REVEN	MOU S AL STL	VER S CD	ORIG CD	TRAY CD	PLAN T CD	PRODN D T	WROV STA RT ST	NAME	DOC NU M	PL NU M	WCC CD	PART NAM C AB P REF	PART NUM L AB L AGE	PART J UM CA UM REP P	CUST DEPT CD	COMM CD	WPR DT	TRE WROV	CLM AGE Y	MLCS	
2001	FTW0202111000000	346.15	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	9-24-00	17-44-00	HENDERERE TRUCK SALES, L.P.	270701	200000	STU	1002	8700	BA	000	40	25-00-00	10	1000000	2000
2001	FTW0202111000001	124.40	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	24-00-01	7-04-01	CAPITAL FUND MERCURY	122140	200000	STU	1002	8700	BA	000	40	25-00-00	10	1000000	2000
2001	FTW0202111000002	210.80	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	10-20-00	8-20-00	FIN GARY FORD	010004	200000	STU	1002	8700	BA	000	40	10-20-00	21	1000000	2000
2001	FTW0202111000003	244.20	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	11-00-00	1-00-00	BRUSH FORD, INC.	400204	200000	STU	1002	8700	BA	000	40	20-00-00	21	1000000	2000
2001	FTW0202111000004	20.20	TF4	TF	TBC	TCD	DR	TDR	TDR	AM	22-00-01	10-00-01	AL PALLADINO FINE TRUCKS	2001001	200000	STU	1002	8700	AA	000	40	12-00-00	20	1000000	2700
2001	FTW0202111000005	141.40	TF4	TF	TBC	TCD	DR	TDR	TDR	AM	10-00-00	0-00-00	MISSION VALLEY FORD TRUCKS	027104	200000	STU	1002	8700	AA	000	20	10-00-00	10	017000	2000
2001	FTW0202111000006	01.70	TF4	TF	TBC	TCD	DR	TDR	TDR	AM	01-00-00	10-00-00	NORTHWEST TRUCKS & EQUIPMENT	020704	200000	STU	1002	8700	AA	000	20	01-00-00	0	000000	2000
2001	FTW0202111000007	00.00	TF7	TF	TBC	TCD	DR	TDR	TDR	A1	0-00-00	22-00-11	LAKE CITY FORD SALES LTD	200001	200000	STU	1002	8700	AA	000	40	0-00-00	15	000000	0000
2001	FTW0202111000008	00.00	TF7	TF	TBC	TCD	DR	TDR	TDR	A1	7-00-00	10-00-01	WILLIAM H. BROWN MOTOR, INC.	000004	200000	STU	1002	8700	BA	000	40	10-00-00	20	000000	0000
2001	FTW0202111000009	41.00	TF4	TF	TBC	TCD	DR	TDR	TDR	AM	0-00-00	0-00-00	BRADSHAW TRUCK CENTER, INC.	100004	200000	STU	1002	8700	AA	000	40	0-00-00	20	000000	0000
2001	FTW0202111000010	00.00	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	0-00-00	0-00-00	BRIDGMAN FORD SALES	040104	200000	STU	1002	8700	BA	000	40	0-00-00	4	000000	0000
2001	FTW0202111000011	00.00	TF7	TF	TBC	TCD	TE	TDR	TDR	A1	0-00-00	0-00-00	WINDSOR MOTORS TRUCK LTD.	200001	200000	STU	1002	8700	BA	000	40	0-00-00	10	000000	0000

FE03-044-A 5369

DEL VE	VEH_CD	LRM_C DET	VEH_LRM_CD	MKT_D REVISED	ROD_C ALERT	VEH_L SERIES	DRIVE CD	TRNS CD	TRAM SLED	PLM T_CD	PROD_D T	WRTY_STA RT DT	NAME	DOC_MU M	PH_MU M	WCC CD	PROV MILE_F REP	PROV MILE_C MILE_ARE	PROV_J UN_CHK UN_SUP	CUNT CONC CD	COND CD	PRC_DT	TRL WHS Y	CLM_HR	SLAGE
2001	FTN027P11811252	82.17	TFT	TF	TED	TED	TRE	TDS	TDS	A1	7-10-88	28-09-88	WINDHOLM MOTORCYCLES	7000000	000000	STN	FCZ	0000	BA	000	42	15-09-88	14	000000	0000
2001	FTN027P11812222	82.57	TFT	TF	TED	TED	TRE	TDS	TDS	A1	20-09-88	27-09-88	RANGER TRUCK CENTRAL, INC.	7000000	000000	STN	FCZ	0000	BA	000	48	15-09-88	22	000000	0000
2001	FTN027P11813222	82.00	TFT	TF	TED	TED	TRE	TDS	TDS	A1	8-09-88	26-09-88	FRENCH FORD, INC.	7000000	000000	STN	FCZ	0000	BA	000	42	15-09-88	27	000000	0000
2001	FTN027P11814222	40.8	TFT	TF	TED	TED	TRE	TDS	TDS	A1	10-09-81	12-09-81	MULLER FORD	7000000	000000	STN	FCZ	0000	BA	000	42	2-09-81	0	000000	00
2001	FTN027P11815221	138.25	TFT	TF	TED	TED	TRE	TDS	TDS	A1	8-10-81	18-09-81	UPLANN MOTORS, INC.	7000000	000000	STN	FCZ	0000	BA	000	42	10-09-81	7	000000	0000
2001	FTN027P11816221	246.73	TFT	TF	TED	TED	TRE	TDS	TDS	A1	8-09-81	18-09-81	ROE FORD- MERCURY-ACCOLA, INC.	7000000	000000	STN	FCZ	0000	BA	000	42	10-09-81	21	000000	0000
2001	FTN027P11817221	201.47	TFT	TF	TED	TED	TRE	TDS	TDS	A1	12-09-81	20-09-81	SCHEIDT FORD	7000000	000000	STN	FCZ	0000	BA	000	42	8-09-81	21	000000	0000
2001	FTN027P11818221	85.81	TFT	TF	TED	TED	TRE	TDS	TDS	A1	20-09-81	12-09-81	HENRY CLYDE FORD-MERCURY	7000000	000000	STN	FCZ	0000	BA	000	42	10-09-81	18	000000	0000
2001	FTN027P11819221	84.2	TFT	TF	TED	TED	TRE	TDS	TDS	A1	5-09-81	20-09-81	PORTANA MOTORS INC.	7000000	000000	STN	FCZ	0000	BA	000	42	10-09-81	5	000000	0000
2001	FTN027P11820221	217.88	TFT	TF	TED	TED	TRE	TDS	TDS	A1	21-09-81	11-09-81	FORD COUNTY	7000000	000000	STN	FCZ	0000	BA	000	42	10-09-81	20	000000	0000
2001	FTN027P11821221	45.48	TFT	TF	TED	TED	TRE	TDS	TDS	A1	20-09-81	18-09-81	BOUNDARY FORD SALES LTD.	7000000	000000	STN	FCZ	0000	BA	000	42	20-09-81	1	000000	0000
2001	FTN027P11822221	71.9	TFT	TF	TED	TED	TRE	TDS	TDS	A1	11-09-81	20-09-81	JONES-WHEAT FORD	7000000	000000	STN	FCZ	0000	BA	000	42	20-09-81	27	000000	0000
2001	FTN027P11823221	80.88	TFT	TF	TED	TED	TRE	TDS	TDS	A1	20-09-81	8-09-81	BRIDGEMAN FORD INC.	7000000	000000	STN	FCZ	0000	BA	000	42	4-09-81	14	000000	0000
2001	FTN027P11824221	54.88	TFT	TF	TED	TED	TRE	TDS	TDS	A1	17-09-81	1-09-81	WHEAT FORD COMPANY, INC.	7000000	000000	STN	FCZ	0000	BA	000	42	20-09-81	0	000000	00

FD03-044-A 5370

PKL	VEH CD	APL_C	VEH	REV_D	REV_E	REV_F	REV_G	REV_H	REV_I	REV_J	REV_K	REV_L	REV_M	REV_N	REV_O	REV_P	REV_Q	REV_R	REV_S	REV_T	REV_U	REV_V	REV_W	REV_X	REV_Y	REV_Z
2001	12700210300000000000	121.20	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	20-Mar-01	SWITCH FORD LINCOLN MERCURY	4040001	4040001	STY1	1002	SP20	BA	000	42	20-Mar-01	25	1400000	40000	
2001	12700210300000000000	20.12	177	7F	TBC	TBD	CR	TDR	TDR	A1	21-Mar-00	12-Mar-01	CHAMPION FORD SAFARI	2040001	2040001	STY1	1002	SP20	BA	000	42	21-Mar-00	25	1200000	10000	
2001	12700210300000000000	63.20	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-00	20-Mar-00	OLM WOODFORD FORD	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-00	25	1000000	10000	
2001	12700210300000000000	20.10	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	20-Mar-01	PLATON FORD, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	70.10	177	7F	TBC	TBD	CR	TDR	TDR	A1	4-Mar-00	14-Mar-00	BRIDGE FORD, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	14-Mar-00	25	1000000	10000	
2001	12700210300000000000	61.47	177	7F	TBC	TBD	CR	TDR	TDR	A1	20-Mar-01	21-Mar-01	WINE BARBER FORD FAMILY FORD	2040001	2040001	STY1	1002	SP20	BA	000	42	21-Mar-01	25	1000000	10000	
2001	12700210300000000000	65.10	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	20-Mar-01	SMITH, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	20-Mar-01	25	1000000	10000	
2001	12700210300000000000	57.80	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	20-Mar-01	WILSON FORD, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	20-Mar-01	25	1000000	10000	
2001	12700210300000000000	144.20	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	10-Mar-01	RED VALLEY FORD	4040001	4040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	21.0	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	10-Mar-01	EDGE FORD, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	60.00	177	7F	TBC	TBD	CR	TDR	TDR	A1	20-Mar-00	10-Mar-01	MANCHESTER FORD MERCURY, INC.	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	211.2	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	11-Mar-01	STEVENS FORD LINCOLN MERCURY	4040001	4040001	STY1	1002	SP20	BA	000	42	11-Mar-01	25	1000000	10000	
2001	12700210300000000000	100.00	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	10-Mar-01	SHANNAN FORD LINCOLN/MER	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	60.00	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	10-Mar-01	COUNTRY FORD TRUCKS	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	
2001	12700210300000000000	61.00	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-00	10-Mar-00	MARTY FRANCH FORD LINCOLN/MER	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-00	25	1000000	10000	
2001	12700210300000000000	44.0	177	7F	TBC	TBD	CR	TDR	TDR	A1	10-Mar-01	10-Mar-01	MARCO CITY MOTOR CORPORATION	2040001	2040001	STY1	1002	SP20	BA	000	42	10-Mar-01	25	1000000	10000	

MODEL YEAR	VIN CD	LEAD COST	VEH LINE CD	ACT_D BOOKED	BOOK AN STD	VEH_S SPRIN CD	DRIVE CD	ENG CD	TRAN S CD	PLAN T CD	FRONT T	HWY_STA RT BT	NAME	DOC_M M	PH_M M	WOOD CD	PAINT PUB ALC_P CD	PAINT PUB ALC_B CD	PAINT PUB ALC_F CD	CURT CODE CD	COND CD	REP BT	TR MTH	CLM MTH	ML
2001	1F8M4JPH1A00000	8247	TL1	TF	72ND	72D	7E	72D	72S	A1	11-08-01	12-08-01	HERITAGE FORD	207201	207200	ST1	7CZ	8F00	BA	00	40	7-08-01	18	207200	2000
2001	1F8M4JPH1A00000	8247	TL1	TF	72ND	72D	7E	72D	72S	A1	11-08-01	12-08-01	HERITAGE FORD LINC-MERC, INC.	207201	207200	ST1	7CZ	8F00	BA	00	40	6-08-01	18	207200	1900
2001	1F8M4JPH1A00000	11618	TL1	TF	72ND	72D	7E	72D	72S	A1	8-08-01	21-08-01	HERITAGE FORD LINC-MERC, INC.	217101	207200	ST1	7CZ	8F00	BA	00	40	21-08-01	24	207200	2000
2001	1F8M4JPH1A00000	11449	TL1	TF	72ND	72D	7E	72D	72S	A1	6-08-01	2-08-01	GALLAGHER FORD LINC-MERCURY	200001	200141	ST1	7CZ	8F00	BA	00	40	7-08-01	20	200000	7000
2001	1F8M4JPH1A00000	1238	TL1	TF	72ND	72D	7E	72D	72S	A1	12-08-01	21-08-01	HERITAGE FORD	400001	200000	ST1	7CZ	8F00	BA	00	40	12-08-01	20	200000	2000
2001	1F8M4JPH1A00000	18720	7F7	TF	72ND	72D	7E	72D	72S	A1	12-08-01	21-08-01	WACE FORD, INC.	140000	000000	ST1	7CZ	8F00	BA	00	40	20-08-01	8	000000	2000
2001	1F8M4JPH1A00000	11270	7F7	TF	72ND	72D	7E	72D	72S	A1	11-08-01	20-08-01	JAMES FORD CORPORATION	000000	000000	ST1	7CZ	8F00	BA	00	40	6-08-01	21	200000	2000
2001	1F8M4JPH1A00000	12090	7F7	TF	72ND	72D	7E	72D	72S	A1	12-08-01	17-08-01	LANSING FORD	100000	200000	ST1	7CZ	8F00	BA	00	40	10-08-01	9	200000	2000
2001	1F8M4JPH1A00000	1311	7F7	TF	72ND	72D	7E	72D	72S	A1	6-08-01	10-08-01	HAYNES FORD INC.	400001	000000	ST1	7CZ	8F00	BA	00	40	21-08-01	4	000000	2000
2001	1F8M4JPH1A00000	1041	7F7	TF	72ND	72D	7E	72D	72S	A1	21-08-01	21-08-01	SHAWBLOWRY FORD, INC.	000000	000000	ST1	7CZ	8F00	BA	00	40	21-08-01	10	000000	2000
2001	1F8M4JPH1A00000	2040	7F7	TF	72ND	72D	7E	72D	72S	A1	21-08-01	21-08-01	BROADWAY MOTOR COMPANY, INC.	100001	000000	ST1	7CZ	8F00	BA	00	40	2-08-01	2	200000	00
2001	1F8M4JPH1A00000	2040	7F7	TF	72ND	72D	7E	72D	72S	A1	21-08-01	21-08-01	BROADWAY MOTOR COMPANY, INC.	100001	000000	ST1	7CZ	8F00	BA	00	40	12-08-01	1	200000	00
2001	1F8M4JPH1A00000	0042	7F7	TF	72ND	72D	7E	72D	72S	A1	21-08-01	10-08-01	COUNTRY FORD TRUCKS	000000	000000	ST1	7CZ	8F00	BA	00	40	6-08-01	2	200000	2000
2001	1F8M4JPH1A00000	0042	7F7	TF	72ND	72D	7E	72D	72S	A1	21-08-01	6-08-01	HERITAGE FORD	110001	200000	ST1	7CZ	8F00	BA	00	40	12-08-01	20	200000	2000

VEH. YR. MO. CD	VEH. L.C. CD	VEH. LNK. CD	ACT. D. MONTH	MO. L. AL. RT.	VEH. B. CD	DRIVE. CD	SEAT. CD	TRAN. S. CD	PLAN. T. CD	PROCN. D. Y	WRTY. STA. RT. DT	NAME	DOC. NO. M	PL. NO. M	SOC. CD	PART. REG. AL. F. SFP	PART. REG. AL. B. ASB	PART. AL. SA. UR. SLP. F	CURT. REG. CD	COND. CD	APP. DT	TTL. MILE. YR	CL. OR. CD	REG. NO.	
2001	1F00746R	00000000	04-01	TF7	TF	T08	T08	T08	T08	A1	8-20-01	20-08-01	FREEDOM FORD TRUCK SERVICE INC	888878	888880	8991	1C3Z	8F08	8A	008	42	21-08-02	20	11772889	20277
2001	1F00746S	00000000	02-03	TF7	TF	T08	T08	T08	T08	A1	11-08-02	23-08-01	FLAMET FORD	200080	143070	5701	1C3Z	8F08	8A	008	28	26-08-02	21	1720188	4808
2001	1F00746V	00000000	10-01	TF7	TF	T08	T08	T08	T08	A1	24-08-02	08-02-02	MAZZINI FORD	878701	888100	8701	1C3Z	8F08	8A	001	43	7-08-02	20	1281088	4828
2001	1F00746F	00000000	08-04	TF7	TF	T08	T08	T08	T08	A1	22-08-02	14-08-02	DAVIDSON FORD TRUCK SERVICE INC	888844	888200	8701	1C3Z	8F08	8A	008	48	22-08-02	9	150802	2008
2001	1F00746S	00000000	08-08	TF7	TF	T08	T08	T08	TF7	A1	18-08-01	21-08-01	LACROIX FORD SALES LTD	888844	788200	8701	1C3Z	8F08	8A	008	48	18-08-02	21	10817018	8848
2001	1F00746S	00000000	01-08	TF4	TF	T08	T08	T08	T08	AM	2-08-02	14-08-01	WICHITA HILL FORD LINCOLN MFR	877801	888100	8701	1C3Z	8F08	8A	008	28	28-08-02	20	1408088	20271
2001	1F00746S	00000000	01-08	TF4	TF	T08	T08	T08	T08	AM	2-08-02	14-08-01	WICHITA HILL FORD LINCOLN MFR	888801	888100	8701	1C3Z	8F08	8A	008	28	28-08-02	20	1408088	20271
2001	1F00746S	00000000	10-02	TF4	TF	T08	T08	T08	T08	AM	21-08-02	12-08-01	WICHITA HILL FORD LINCOLN MFR	100080	877800	8701	1C3Z	8F08	8A	008	42	14-08-02	11	088102	2000
2001	1F00746S	00000000	01-08	TF4	TF	T08	T08	T08	T08	AM	24-08-01	18-08-01	BARRETT FORD	888800	178200	8701	1C3Z	8F08	8A	008	48	18-08-02	17	108102	2000
2001	1F00746S	00000000	01-08	TF4	TF	T08	T08	T08	T08	AM	8-08-02	18-08-01	BARRETT FORD SALES INC.	110000	888200	8701	1C3Z	8F08	8A	008	48	28-08-02	14	0480712	2708
2001	1F00746S	00000000	07-04	TF7	TF	T08	T08	T08	TF7	A1	28-08-01	14-08-01	JEREMY WELTY FORD INC	188801	888111	8701	1C3Z	8F08	8A	011	42	5-08-02	22	1282088	20014
2001	1F00746S	00000000	07-08	TF7	TF	T08	T08	T08	T08	A1	18-08-01	21-08-01	RANDOLPH FORD RIVER CITY FORD TRUCKS INC	878801	488200	8701	1C3Z	8F08	8A	008	48	21-08-02	10	1378020	2000
2001	1F00746S	00000000	07-08	TF7	TF	T08	T08	T08	T08	A1	28-08-01	28-08-01	TRIPLE B INC	887780	888111	8701	1C3Z	8F08	8A	008	42	28-08-02	2	088444	2000
2001	1F00746S	00000000	08-02	TF7	TF	T08	T08	T08	T08	A1	18-08-02	28-08-02	ROMAN BURNS FORD INC	718800	488200	8701	1C3Z	8F08	8A	008	42	18-08-02	19	0881024	27021
2001	1F00746S	00000000	08-08	TF7	TF	T08	T08	T08	TF7	A1	28-08-01	10-08-01	NONVANCE FORD INC.	278802	888200	8701	1C3Z	8F08	8A	008	48	18-08-02	8	041088	1148
2001	1F00746S	00000000	08-08	TF7	TF	T08	T08	T08	T08	A1	21-08-01	17-08-01	OPHARA FORD CENTER INC	887780	481080	8701	1C3Z	8F08	8A	008	42	18-08-02	2	108024	88
2001	1F00746S	00000000	08-08	TF7	TF	T08	T08	T08	TF7	A1	28-08-01	28-08-01	BARRETT FORD	188810	788200	8701	1C3Z	8F08	8A	008	42	28-08-02	8	717802	2010

PE03-044-A 5373

DEL YR	VIN CD	LINE CD	MSL CD	ACT_D CD	MOD_C CD	VER_B CD	CPVE CD	ENG CD	TRAN CD	PLAN CD	PRDIN_D CD	WRTY_STA CD	NAME	DOC_NO	PL_NO	WCC CD	PART NUM	PART DESC	PART UNIT	CURR CD	COND CD	EMPL_DT	TR WED	CLM_K Y	MS_GE
2001	2DWF2T2E2E2E2E2E	81.48	T77	TF	T88	T82	TR	T88	T88	A1	1758-01	38-00-01	FREEDOM FORD SALES	814888	801488	ST01	100Z	8P08	BA	000	48	8-24-00	18	1070488	2488
2001	2DWF2T2E2E2E2E2E	82.48	T77	TF	T88	T82	TR	T88	T88	A1	1758-01	38-00-01	CAM CLARK FORD SALES LTD.	814888	800000	ST01	100Z	8P08	BA	000	41	20-08-01	1	478888	88
2001	2DWF2T2E2E2E2E2E	83.48	T77	TF	T88	T82	TR	T88	T88	A1	1758-01	38-00-01	MID-TERR FORD BLACK SALES, INC.	814888	200000	ST01	100Z	8P08	BA	000	42	4-24-00	3	888888	8888
2001	2DWF2T2E2E2E2E2E	102.48	T77	TF	T88	T82	TR	T88	T88	A1	1758-01	18-00-01	CLATS FORD SALES, INC.	814888	200000	ST01	100Z	8P08	BA	000	41	10-24-00	10	147888	4888
2001	2DWF2T2E2E2E2E2E	141.48	T77	TF	T88	T82	TR	T88	T88	A1	18-00-01	4-00-01	CUTLER FORD, INC.	814888	487888	ST01	100Z	8P08	BA	001	41	10-24-00	10	878888	8888
2001	2DWF2T2E2E2E2E2E	84.48	T77	TF	T88	T82	TR	T88	T88	A1	1758-01	18-00-01	WILL YERGEN FORD SALES	808148	808148	ST01	100Z	8P08	BA	000	41	20-08-01	18	888888	8888
2001	2DWF2T2E2E2E2E2E	234.48	T84	TF	T82	T82	TR	T88	T88	AM	2-00-01	2-00-01	CHAMPION FORD, INC.	1100001	347888	ST01	100Z	8P08	AA	000	41	21-08-00	17	1024888	2488
2001	2DWF2T2E2E2E2E2E	24.48	T84	TF	T82	T82	TR	T88	T88	AM	2-00-01	20-00-01	TRINITY SALES & SERVICE LTD	800000	800000	ST01	100Z	8P08	AA	000	41	14-08-00	8	278888	8
2001	2DWF2T2E2E2E2E2E	28.54	T87	TF	T82	T82	TR	T88	T88	A1	18-00-01	4-00-01	SCHWALBE MOTOR COMPANY	107888	788888	ST01	100Z	8P08	BA	000	41	8-00-00	18	112888	8888
2001	2DWF2T2E2E2E2E2E	142.7	T77	TF	T88	T82	TR	T88	T88	A1	20-00-01	20-00-01	FREEDOM FORD SALES LIMITED	200000	448888	ST01	100Z	8P08	BA	000	41	20-00-00	17	788888	8888
2001	2DWF2T2E2E2E2E2E	48.48	T87	TF	T88	T82	TR	T88	T88	A1	20-00-01	20-00-01	JERRY FORD SALES LTD.	800000	200000	ST01	100Z	8P08	BA	000	41	20-00-00	21	1000000	8888

PE03-044-A 5374

MODEL	YR	VR	CD	UBR_C	VSL	MKT_D	BOO_C	VELA	DRIVE	ENG	TRAN	PLAN	PROD_D	WRTY	STA	NAME	DOC_NO	PH_NO	TRC	PORT	PORT	PORT	CURT	COND	DATE	TR	CLM	RE	REGR
TR	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD														
2001	FTW0207P1800000	7620	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	21-Jan-01	21-Jan-01	FORD MOTOR CO.	200204	200200	STD	SCZ	WFSR	BA	DGR	01	4-00-01	2	200101					
2001	FTW0207P1800000	7640	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	21-Oct-00	4-Jan-01	AMERLIFE FORD	120701	200200	STD	SCZ	WFSR	BA	DGR	01	1-00-01	20	10-00-01	20	10-00-01			
2001	FTW0207P1800000	8157	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	8-Mar-00	12-00-00	JACKSON MOTOR SUPPLY LTD	000000	000000	STD	WYZ	WFSR	AB	DGR	01	10-00-01	4	10-00-01					
2001	FTW0207P1800000	2030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	20-Mar-01	2-Mar-01	MARTIN - THORN FORD LINCOLN	170000	000000	STD	SCZ	WFSR	BA	DGR	01	10-00-01	0	10-00-01					
2001	FTW0207P1800000	4741	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	10-Oct-00	8-00-01	RON-CARTER FORD, INC.	000000	000000	STD	SCZ	WFSR	BA	DGR	01	10-00-01	21	10-00-01					
2001	FTW0207P1800000	80107	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	8-Jan-01	7-00-01	FELMOTT FORD	100700	000000	STD	SCZ	WFSR	BA	DGR	01	10-00-01	7	10-00-01					
2001	FTW0207P1800000	8100	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	7-Mar-00	21-Mar-00	BROOKS HANNA FORD	000000	000000	STD	WYZ	WFSR	AB	DGR	01	10-00-01	21	10-00-01					
2001	FTW0207P1800000	8101	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	8-Jan-01	21-Mar-00	VICTORY FORD LINCOLN MERCURY	000000	000000	STD	WYZ	WFSR	BA	DGR	01	10-00-01	0	10-00-01					
2001	FTW0207P1800000	10042	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	10-Mar-00	1-00-00	DOH SANDERSON FORD, INC.	000000	000000	STD	WYZ	WFSR	AB	DGR	01	11-00-01	21	10-00-01					
2001	FTW0207P1800000	2030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	2-00-00	21-Oct-00	WOLETT LTD	000000	000000	STD	SCZ	WFSR	BA	DGR	01	2-00-00	27	00-00-00					
2001	FTW0207P1800000	2030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	20-Mar-01	20-Mar-01	MARTIN FORD, INC.	0000	000000	STD	SCZ	WFSR	BA	DGR	01	20-Mar-01	18	20-Mar-01					
2001	FTW0207P1800000	2030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	8-00-00	10-Dec-00	FELMOTT FORD	000000	000000	STD	SCZ	WFSR	BA	DGR	01	8-00-00	17	00-00-00					
2001	FTW0207P1800000	2030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	21-Mar-01	11-00-01	STANBIS FORD LINCOLN MERCURY	000000	000000	STD	SCZ	WFSR	BA	DGR	01	11-00-01	12	00-00-00					
2001	FTW0207P1800000	10030	TF7	TF	TBD	TBD	TR	TDR	TDR	A1	14-Mar-00	20-Mar-00	MILLEY FORD-SCOUTS	000000	000000	STD	WYZ	WFSR	AB	DGR	01	20-Mar-00	20	11-00-01					

PE03-044-A 5375

MOL VE	MFL VE	LBA C	YEL C	MET D	MOD C	VBL C	DRIVE C	ENG C	TRAN C	PLAN C	PRD D	WRTY ST	STA ST	NAME	DOC N	PK N	WCC C	FRY A	FRY L	FRY P	FRY S	CUT C	COND C	APP D	TRE D	CLM N	AL N
2001	FTWHEHSHWAZ280	21.88	1064	TF	TCD	TCD	TB	TCD	TCD	AM	1-Dec-00	12-Jan-01		JENSE FORD SALES CENTER	240264	807880	STG1	100K	BT20	AA	000	40	25-Mar-01	10	111111	11913	
2001	1P00000P00000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A1	1-Dec-01	28-Dec-01		REDFORD FORD MOTOR PART	200001	807880	STG1	100K	BT20	AA	000	40	18-Dec-01	7	800001	1000	
2001	FDAC000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A1	1-Dec-01	28-Dec-01		REDFORD FORD MOTOR PART	100001	807880	STG1	100K	BT20	AA	000	40	18-Dec-01	10	800000	200	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	1-Dec-01	27-Jan-01		STONERACE FORD BC	210001	807880	STG1	100K	BT20	AA	000	40	26-Mar-01	8	800001	400	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Dec-00	28-Dec-01		GRAND TRUCK CENTER	200004	807880	STG1	100K	BT20	AA	000	40	25-Dec-01	14	710010	1000	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Dec-00	1-Jan-01		COURTESY FORD OF WILMINGTON	817004	807880	STG1	100K	BT20	AA	000	40	18-Dec-01	14	100000	1000	
2001	FTD000000000000	17.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Apr-00	2-Dec-01		RED FORD MOTORS, INC.	200008	807880	STG1	100K	BT20	AA	000	40	20-Mar-01	17	800001	2100	
2001	FTD000000000000	17.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	6-Apr-01	2-Dec-01		COURTESY FORD MOTOR PART	810003	807880	STG1	100K	BT20	AA	000	40	6-Mar-01	8	100000	0	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Apr-01	9-May-01		SAVINGS BC	100000	807880	STG1	100K	BT20	AA	000	40	6-Dec-01	8	800100	777	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Apr-01	12-Dec-01		FRANK KERRY FORD LINCOLN SALES	200001	807880	STG1	100K	BT20	AA	000	30	22-Feb-01	8	710010	800	
2001	FTD000000000000	4.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	20-Apr-01	20-Apr-01		ORCHARDER, INC.	100002	807880	STG1	100K	BT20	AA	000	40	21-Apr-01	6	800000	77	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	15-Apr-00	20-Dec-00		CALVIN FORD	400000	807880	STG1	100K	BT20	AA	000	40	20-Apr-01	20	210000	1000	
2001	FTD000000000000	20.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	15-Apr-00	21-Dec-00		PHILPOTT FORD	100000	807880	STG1	100K	BT20	AA	000	20	10-Mar-01	11	800000	800	
2001	FTD000000000000	24.00	1077	TF	TBC	TCD	TB	TCD	TCD	A2	27-Sep-01	6-May-01		DAN WHEELER FORD	100001	807880	STG1	100K	BT20	AA	000	40	21-Apr-01	11	800000	1000	

PE03-044-A 5377

MOI_YR	VEH_CO	VEH_LMR_CO	VEH_LMR_OBT	MCT_D	MOCD	VEHLS	DRIVE	ENCL	TRAM	PLAN	PROCD	MRTY	STA	FLTY	NAME	DOC_NO	PLAU	VECD	FAU	FAU_P	FAU_L	FAU_R	FAU_C	FAU_D	FAU_E	FAU_F	FAU_G	FAU_H	FAU_I	FAU_J	FAU_K	FAU_L	FAU_M	FAU_N	FAU_O	FAU_P	FAU_Q	FAU_R	FAU_S	FAU_T	FAU_U	FAU_V	FAU_W	FAU_X	FAU_Y	FAU_Z						
2001	FTW000000000000	81.00	TF7	TF	TBC	TDC	TB	TDR	TEN	AE	2-00-00	2-00-01			ANDERSON FORD-MERSCURY	136500	888011	0701	1000	0700	BA	000	00	4-00-00	0	000000	0000																									
2001	FTW000000000000	81.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	2-00-00	20-00-01			HARREL FORD LINCOLN MERCURY	874000	888700	0701	1000	0700	BA	000	00	20-00-00	14	1140000	1200																									
2001	FTW000000000000	87.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	14-00-00	20-00-01			LUIGER FORD LINCOLN MERCURY	1888000	888800	0701	1000	0700	BA	000	00	2-00-00	14	0000000	2000																									
2001	FTW000000000000	82.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	2-00-00	2-00-01			LAMARLE NORTH SE-CRUI FORD, INC.	888800	888800	0701	1000	0700	BA	000	00	20-00-00	0	000000	0000																									
2001	FTW000000000000	272.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	20-00-00	20-00-01			CHAMPION FORD CITY	200000	888700	0701	1000	0700	BA	000	00	1-00-00	0	000000	0000																									
2001	FTW000000000000	81.70	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	20-00-00	20-00-01			JIM BLAKE FORD	417000	888800	0701	1000	0700	BA	000	00	20-00-00	2	000000	7000																									
2001	FTW000000000000	84.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	20-00-00	21-00-00			TED RUSSELL FORD INC	340000	888800	0701	1000	0700	BA	000	00	2-00-00	0	0000000	2000																									
2001	FTW000000000000	100.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	10-00-00	20-00-00			WOODRIDGE FORD LINCOLN LTD	1300000	888800	0701	1000	0700	BA	000	00	20-00-00	0	0000000	10000																									
2001	FTW000000000000	20.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	1-00-00	2-00-00			LANCER FORD	107000	888800	0701	1000	0700	BA	000	00	20-00-00	1	44000	1000																									
2001	FTW000000000000	81.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	5-00-00	10-00-00			BOMBY'S FORD, INC.	102100	888800	0701	1000	0700	BA	000	00	10-00-00	0	1070000	0700																									
2001	FTW000000000000	100.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	10-00-00	20-00-00			FAMILY FORD, INC.	888800	888800	0701	1000	0700	BA	000	00	10-00-00	17	0014000	10000																									
2001	FTW000000000000	80.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	2-00-00	10-00-00			LAMARLE NORTH LINCOLN FORD, INC.	070000	888800	0701	1000	0700	BA	000	00	10-00-00	4	107000	0000																									
2001	FTW000000000000	200.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	10-00-00	21-00-00			MARSHALL FORD OF ILLINOIS	0400000	888800	0701	1000	0700	BA	000	00	20-00-00	0	0011000	0000																									
2001	FTW000000000000	10.00	TF7	TF	TBC	TDC	TB	TDR	TEN	A1	4-00-00	4-00-00			APPEL FORD-MERCURY, INC.	000000	888800	0701	1000	0700	BA	000	00	10-00-00	1	100000	0000																									

PE03-044-A 5378

DEL YR	VEN CD	OR_C GRT	VEN LNK CD	MKT_D SRVCD	MDS_C AS_STL	VEN_L MDS_CD	ORWH CD	ENR CD	TRAK S_ID	PLAN T_DD	PRDPR_D T	WRTY_ITA WT_ST	NAME	DOC_NO M	PL_NO M	YOC CD	PRT1 MNU_P MFLT MSP	PRT2 MNU_P MFLS_P MSE	PRT3 MNU_P MFLS_P MSE	CLTY COND CD	COND CD	RPR_DT	TR YD	CLM_NE Y	MILE
2001	1	PR03-044-A 5379								A1	2-29-00	30-00-00	SOUTH PONTE LINCOLN MERCURY	00001A	000000	0001	1002	0000	00	00	00	29-00-00	00	000000	0000
2001	1	PR03-044-A 5379								A1	21-00-01	18-00-01	LEHMAN FORD	000010	000000	0001	1002	0000	00	00	00	27-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	12-00-00	26-00-00	DARRERS MOTOR COMPANY, INC.	000001	000000	0001	1002	0000	00	00	00	00-00-00	00	000000	0000
2001	1	PR03-044-A 5379								A1	20-00-01	15-00-01	WEN JAMES FORD SALES LTD.	000000	000000	0001	1002	0000	00	00	00	27-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	4-00-00	30-00-01	PRINCE GEORGE MCCORMICK LTD.	000000	000011	0001	1002	0000	00	00	00	30-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	21-00-00	18-00-00	SUN FURST FORD, INC.	000000	000000	0001	1002	0000	00	00	00	3-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	20-00-00	18-00-00	DRAKE FORD LINCOLN SALES LTD.	000000	000000	0001	1002	0000	00	00	00	00-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	20-00-00	12-00-00	PAUL LONG FORD, LLC.	000000	000000	0001	1002	0000	00	00	00	21-00-00	00	000000	0000
2001	1	PR03-044-A 5379								A1	17-00-00	3-00-01	HOLMES TITLE FORD	000000	000000	0001	1002	0000	00	00	00	21-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	20-00-00	14-00-01	OLSON CITY FORD INC.	000001	000000	0001	1002	0000	00	00	00	20-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	30-00-01	7-00-01	FORTUNA MOTOR INC.	000001	000001	0001	1002	0000	00	00	00	00-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	0-00-00	0-00-00	CAFETERIA FORD & MERCURY SALES	000000	000000	0001	1002	0000	00	00	00	4-00-00	00	000000	0000
2001	1	PR03-044-A 5379								A1	20-00-01	10-00-01	STAPP BROTHERS LINCOLN-MERCURY	000000	000000	0001	1002	0000	00	00	00	20-00-01	00	000000	0000
2001	1	PR03-044-A 5379								A1	31-00-01	10-00-01	SALENTRIED	000000	000000	0001	1002	0000	00	00	00	20-00-01	00	000000	0000

PR03-044-A 5379

MOI YR	VIN CD	LEN CMT	LEN CD	MT_D CD	MOD_C CD	YER_L CD	DRIVE CD	ENG CD	TRAN S_CD	PLAN T_CD	PROOD T	WRTY_STA RT DT	NAME	DOC_NO	PL_NO	WCC CD	PART NUM_L	PART NUM_R	PART NUM_CA	CURY COC_CD	COND CD	REPLY	TRM MTH	CLM MTH	DATE		
2001	1FT0W31Y7EAG2419	1133	1277	TF	FHC	1997	DR	DO6	DOB	A1	21-00-01	05-00-01	TORLETT FORD, INC.	433082	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	201	7204	TF	TND	1997	DR	DO6	DOB	AM	27-00-01	28-00-01	MID-TERM FORD TRUCK SALES, INC.	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	4841	7204	TF	TND	1997	DR	DO6	DOB	AM	27-00-01	27-00-01	DONALD FORD SALES	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	8030	7277	TF	TNS	1997	DR	DO6	DOB	A1	09-00-01	10-00-01	JACKSON FORD SALES, INC.	010000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	6184	7277	TF	TND	1997	DR	DO6	DOB	A1	01-00-01	01-00-01	GARNETT & OVER FORD INC.	001001	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	20010	7277	TF	TND	1997	DR	DO6	DOB	A1	11-00-01	27-00-01	GENE MEIER FORD	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	10291	7277	TF	TND	1997	DR	DO6	DOB	A1	10-00-01	20-00-01	LEE THOMSON FORD	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	60	7277	TF	TND	1997	DR	DO6	DOB	A1	10-00-01	20-00-01	ROBERT HUTTON FORD (MCKINNEY)	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	11721	7277	TF	TND	1997	DR	DO6	DOB	A1	2-00-01	14-00-01	MCALLEY FORD- MERCURY	000001	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	6720	7277	TF	TND	1997	DR	DO6	DOB	A1	11-00-01	27-00-01	RAYNER FORD INC.	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	6171	7277	TF	TND	1997	DR	DO6	DOB	A1	2-00-01	04-00-01	GRAND PRIVE FORD	010001	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	404	7277	TF	TND	1997	DR	DO6	DOB	A1	2-00-01	18-00-01	FREMONT MOTOR CONT. INC.	100000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	0000	7277	TF	TND	1997	DR	DO6	DOB	A1	01-00-01	27-00-01	HEMER HELLER FORD	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00
2001	1FT0004R7W0A0000	1230	7277	TF	TND	1997	DR	DO6	DOB	AS	01-00-01	21-00-01	MALLADA MOTORS, INC.	000000	000000	001	F002	F000	00	000	00	00	00	00	00	00	00

ML YR	VR CD	LIB_C DT	VD LINE CD	MTY_D ENR	SOC_C AS STL	VCR_L MODE CD	DRIVE CD	ENG CD	TRAN S_CD	PLAN T_CD	PROG_D T	WTRY_STA NY JT	NAME	DOC_NO M	PL_NO M	DOC CD	FINL NUM AULP RPT	FINL NUM AULS ABS	FINL NUM OR LSE NUM Y	CURT COMP CD	COND CD	RPL_DT	TTL RND Y	CLAS Y	BLGE
2001	FTN021F41EAB071	150.78	1777	TF	TSD	TSD	TE	TEB	TEB	A1	17-02-02	8-22-02	DOM CHALMERS FORD	258253	287288	ST1	1CSZ	SP28	BA	D41	42	17-20-01	8	287148	258253
2001	FTN021F41EAB008	108.18	1777	TF	TSD	TSD	TE	TEB	TEB	A1	21-20-01	2-24-02	DAVID HARDY FORD SALES COMPANY	520206	520202	ST1	PL2Z	SP28	AB	D36	43	20-24-01	11	287051	287048
2001	FTN021F41EAB044	130	1771	TF	TSD	TSD	TE	TEB	TEB	A1	20-20-01	25-24-01	EVJ ROSEN FORD	2004701	2004692	ST1	1CSZ	SP28	BA	D20	41	10-24-01	20	286878	286875
2001	FTN021F41EAB021	168.85	1777	TF	TSD	TSD	TE	TEB	TEB	A1	13-20-00	21-24-01	BICHFORD MOTORS, INC.	882724	882722	ST1	PL1Z	SP28	AB	D25	42	22-24-01	20	281879	281876
2001	FTN021F41EAB011	112.95	1777	TF	TSD	TSD	TE	TEB	TEB	A1	22-02-00	28-24-01	LANCERS FORD	183261	882703	ST1	1CSZ	SP28	BA	D26	41	27-24-01	8	286886	287
2001	FTN021F41EAB081	84.88	1777	TF	TSD	TSD	TE	TEB	TEB	A1	2-24-01	12-24-01	HEXON AUTOPLEX	2377530	2377520	ST1	1CSZ	SP28	BA	D36	28	9-24-02	24	281188	28770
2001	FTN021F41EAB093	34.18	1777	TF	TSD	TSD	TE	TEB	TEB	A1	21-20-01	21-24-01	GOODOLY FORD	884481	284730	ST1	1CSZ	SP28	BA	D20	39	4-24-02	22	287237	287236
2001	FTN021F41EAB071	31.25	1777	TF	TSD	TSD	TE	TEB	TEB	A1	2-04-00	20-24-00	SPRADLEYBANK FORD INC.	870001	282075	ST1	1CSZ	SP28	BA	D20	1	11-04-02	22	282076	282075
2001	FTN021F41EAB024	287.1	1771	TF	TSD	TSD	TE	TEB	TEB	A1	22-24-01	21-24-01	ANDERSON FORD MOTORCO	118828	882711	ST1	1CSZ	SP28	BA	D20	42	22-24-01	22	286923	28700
2001	FTN021F41EAB027	276.2	1777	TF	TSD	TSD	TE	TEB	TEB	A2	10-04-00	22-24-01	MAURITY FORD LINCOLN MERCURY	179274	179268	ST1	1CSZ	SP28	BA	D20	42	17-24-01	21	281219	281218
2001	FTN021F41EAB021	25.34	1777	TF	TSD	TSD	TE	TEB	TEB	A1	7-04-00	20-04-00	SMITH FORD MOTORCO	807753	807751	ST1	1CSZ	SP28	BA	D20	20	04-24-02	21	240188	240184
2001	FTN021F41EAB072	268.83	1771	TF	TSD	TSD	TE	TEB	TEB	A1	9-02-00	8-24-00	LA FORTA FORD	128847	271188	ST1	1CSZ	SP28	BA	D20	41	9-24-02	18	271189	271184
2001	FTN021F41EAB088	209.21	1777	TF	TSD	TSD	TE	TEB	TEB	A1	8-02-00	14-24-00	PLANT FORD	128822	270228	ST1	1CSZ	SP28	BA	D20	41	21-24-01	21	267210	267209

MOI_YR	YR_CD	MR_C	YR_CD	MKT_D	MR_C	MR_C	DRIVE	MR_C	TRAN	PLAN	PROSA_D	WRTY	RTA	NAME	DOC_NO	PH_NO	WCC_CD	PART	PART	PART	CURT	DEMO	REV_DT	TRM	CLERK	MRK
YR	YR_CD	MR_C	YR_CD	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C	MR_C
2001	FTM021F183897	187.94	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	11-06-01	21-06-01		VALLEY FORD LINCOLN-MERCUARY FOUR MERRICK FORD LINCOLN MERRICK	872881	884001	STN	10Z	8700	BA	D42	42	22-06-01	27	1200044	8700
2001	FTM021F192488	24.3	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	26-06-01	14-06-01		GRANITE TRUCK CENTER	872881	874101	STN	10Z	8700	BA	D42	42	26-06-01	21	1000000	8700
2001	FTM021F192488	228.26	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	4-06-01	5-14-01		GRANITE TRUCK CENTER	872881	874101	STN	10Z	8700	BA	D42	42	4-06-01	12	801000	8700
2001	FTM021F192488	178.57	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	16-06-01	20-06-01		EDGE FORD LINCOLN-MERCUARY	1114881	787111	STN	10Z	8700	BA	D42	42	24-06-01	4	104001	1100
2001	FTM021F1188089	8.26	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	12-06-01	20-06-01		JERRY FORD SALES LTD	882881	728441	STN	10Z	8700	BA	D42	42	12-06-01	8	200001	1100
2001	FTM021F1188089	14.52	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	22-06-01	24-06-01		SMITHFIELD FORD	882881	888441	STN	10Z	8700	BA	D42	42	22-06-01	21	1000011	8700
2001	FTM021F1188089	23.88	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	1-06-01	12-06-01		ANTOCH FORD	882881	787171	STN	10Z	8700	BA	D42	42	1-06-01	1	110001	8700
2001	FTM021F1848815	85.13	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	8-06-01	20-06-01		DEAN FORD	882881	888101	STN	10Z	8700	BA	D42	42	28-06-01	21	1000008	8700
2001	FTM021F1848815	288.18	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	6-06-01	21-06-01		LA FORTE FORD	13827A	471842	STN	10Z	8700	BA	D42	42	28-06-01	19	801244	8700
2001	FTM021F1848815	24.02	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	18-06-01	18-06-01		NORTHWEST FORD LINCOLN-MERCUARY MERRICK	118801	888284	STN	10Z	8700	BA	D42	42	24-06-01	6	888021	1100
2001	FTM021F1848815	184.54	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	21-06-01	26-06-01		FORD, INC.	18888A	877088	STN	10Z	8700	BA	D42	42	18-06-01	26	1000028	8700
2001	FTM021F1848815	27.23	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	27-06-01	11-06-01		STEVENS FORD LINCOLN-MERCUARY	870081	887088	STN	10Z	8700	BA	D42	42	27-06-01	2	884001	1100
2001	FTM021F1848815	107.84	7/27	TF	TBC	TBD	TR	TDR	TDR	A1	18-06-01	22-06-01		FORD COUNTY	882881	888077	STN	10Z	8700	BA	D42	42	18-06-01	20	884001	8700

PE03-04-A 5382

MODEL VIN CD	LEAF_C OUT	VEH LINE CD	WGT_D SERVED	BOO_C ANL ST	VEH_S ORNG CD	DRIVE CD	ENR_C CD	TRAN S_CD	PLAN T_CD	PROCK_D IT	WRTY_STA RT DT	NAME	DOC_NO M	PH_NO M	MOI CD	FRY HEM P	FRY HEM P AUB	PANTON AM OR LX SUP P	CURT COMD CD	COMD CD	PRF DT	TR WED Y	CLM YE	MILE
20011F00443010001000	0302	TR1	TF	TRND	TRND	TF	TRND	TRND	A1	22-Sep-01	22-Sep-01	NORTHSHORE FORD	2000001	2000000	STV1	FCZ	SPEN	AR	000	00	15-Mar-02	10	071100	21000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	19-Sep-01	19-Sep-01	TR-LAN BOSQUE FORD	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	10-Sep-02	6	030100	0000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	19-Sep-01	19-Sep-01	MELVILLE MOTORS LTD.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	15-Sep-01	0	001400	0017
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	11-Dec-01	11-Dec-01	L.J. TRACK CENTER, INC.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	02-Sep-02	27	141000	2000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	12-Sep-01	12-Sep-01	PERL CORP FORD OF CENTRAL ILL.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	9-Sep-02	20	100000	2700
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	20-Sep-01	20-Sep-01	JIM BURKE FORD	2000001	2000000	STV1	FCZ	SPEN	AR	000	00	1-Sep-02	3	000000	0000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	20-Sep-01	20-Sep-01	JIM BURKE FORD	2000001	2000000	STV1	FCZ	SPEN	AR	000	00	20-Sep-02	7	000000	0000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	22-Mar-01	10-Apr-01	GATEWAY FORD, INC.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	20-Jan-02	10	000000	0000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	20-Sep-01	20-Sep-01	DR. W. MILLER FORD SLAHER, INC.	2000001	2000000	STV1	FCZ	SPEN	AR	000	00	11-Sep-01	2	000000	1000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	7-Sep-01	20-Sep-01	HORIZON FORD	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	1-Jun-02	17	000000	2700
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	11-Jun-01	11-Jun-01	JIM BURKE FORD	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	1-Jun-02	13	000000	1000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	1-Jun-02	21-Jun-02	FORD CITY FORD SALES LIMITED	2000001	2000000	STV1	FCZ	SPEN	BA	001	00	04-Sep-02	20	100000	2100
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	19-Sep-01	20-Sep-01	BOB DAVIDSON FORD, INC.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	20-Sep-02	10	000000	0000
20011F00443010001000	0302	TR7	TF	TRC	TRC	TR	TRC	TRC	A1	20-Sep-01	20-Sep-01	DAVIDSON MOTOR COMPANY, INC.	2000001	2000000	STV1	FCZ	SPEN	BA	000	00	1-Sep-02	20	000000	0000
20011F00443010001000	0302	TR4	TF	TRC	TRC	TR	TRC	TRC	AM	20-Sep-01	24-Sep-01	DUNLAP FORD, INC.	2000001	2000000	STV1	FCZ	SPEN	AA	000	00	02-Sep-01	1	000000	000
20011F00443010001000	0302	TR4	TF	TRC	TRC	TR	TRC	TRC	AM	15-Sep-01	04-Sep-01	LANDERS FORD	2000001	2000000	STV1	FCZ	SPEN	AA	000	00	19-Sep-02	21	100000	1000

PE03-044-A 5393

INCL YL	VEH CD	UNIT DRT	VEH LINE CD	MKT_D SERVED	ICD_C AB STL	VEH_L SERIES CD	DRIVE CD	ENR CD	TRAN S.CO	PLAN T.CO	PROCD T	PARTY_STA RE DT	NAME	DOC_NO M	PH_NO M	ACC CD	PART MUL_C SER_P SER	PART MUL_C SER_L SER	PART MUL_C SER_L SER	CURT COND CD	COND CD	REF_DT	REL INDY	CULFGE INDY	NUMB	
001	F09050F4180205		2.8	Y84	TF	TCD	T84	T8	T08	T08	AM	21-09-01	24-09-01	DALE FORD LINCOLN SALES LTD.	1640201	888801	ST01	PC02	8700	AA	000	48	20-09-01	0	000111	18
001	F09050F4180207		28.85	Y84	TF	TCD	T84	T8	T08	T08	AM	18-09-01	4-09-01	HOLLY FORD TRUCK CENTER, INC.	877780A	880800	ST01	PC02	8700	AA	000	48	8-09-01	10	100270	2048
001	F09050F4180204		28.48	Y84	TF	TCD	T84	T8	T08	T08	AM	10-09-01	21-09-01	MELINDA STATE TRUCK CENTER	180205	882001	ST01	PC02	8700	AA	000	48	8-09-01	12	100000	2041
001	F09050F4180203		65.4	Y84	TF	TCD	T84	T8	T08	T08	AM	2-09-01	23-09-01	TOM'S FORD, INC.	180048	880801	ST01	PC02	8700	AA	001	48	21-09-01	10	100000	1800
001	F09050F4180202		85.4	Y87	TF	T8D	T8D	T8	T08	T08	A1	20-09-01	21-09-01	BLUNT BAY FORD TRUCK SALES, INC.	113580A	882400	ST01	PC02	8700	BA	002	48	11-09-01	20	100000	2040
001	F09050F4180201		21.63	Y87	TF	T8C	T8C	T8	T08	T08	A1	18-09-01	20-09-01	ADAM'S FORD INC.	180206	880700	ST01	PC02	8700	BA	000	38	7-09-01	20	100000	2070
001	F09050F4180200		18.08	Y87	TF	T8B	T8B	T8	T08	T08	A1	20-09-01	21-09-01	BOB CLIMBERN FORD INC.	180100	881000	ST01	PC02	8700	BA	000	41	21-09-01	20	100000	2000
001	F09050F4180200		118.26	Y87	TF	T8B	T8D	T8	T08	T08	A1	8-09-01	4-09-01	VEHICLE FORD SALES	180400	884000	ST01	PC02	8700	BA	000	48	8-09-01	0	240777	1200
001	F09050F4180200		67.98	Y87	TF	T8B	T8D	T8	T08	T08	A1	10-09-01	10-09-01	CLUTTER FORD, INC.	880200	880201	ST01	PC02	8700	BA	000	48	8-09-01	17	1001107	2070
001	F09050F4180200		62.24	Y84	TF	TCD	T8D	T8	T08	T08	AM	21-09-01	20-09-01	OWENS FORD SALES	780001	882700	ST01	PC02	8700	AA	000	48	2-09-01	1	100000	200
001	F09050F4180200		41.78	Y87	TF	T8D	T8D	T8	T08	T08	A1	18-09-01	1-09-01	PEACOCK FORD TRUCK SALES, INC.	880200	880201	ST01	PC02	8700	BA	000	1	20-09-01	1	200000	1100
001	F09050F4180200		24.88	Y87	TF	T8C	T8D	T8	T08	T08	A1	20-09-01	20-09-01	MCCORDS FORD LINCOLN LTD.	880801	880801	ST01	PC02	8700	AB	000	48	20-09-01	21	100000	2001
001	F09050F4180200		8.49	Y84	TF	TCD	T8D	T8	T08	T08	AM	2-09-01	12-09-01	MORTIMER FORD SALES LTD.	480001	881400	ST01	PC02	8700	AA	000	48	10-09-01	17	1001000	2010

FE03-044-A 5384

ACL YE	YR_CD	MR_C DT	MR_L CD	MR_D EP	MR_C STL	MR_L CD	MR_C CD	MR_C CD	TRM S_CD	PLAN T_CD	PRCD_D T	MRTY_STA ST_DT	NAME	DOC_NO M	PH_NO M	MOO CD	PAV AUB_P ST	PORT AUB_P ST	PAV AUB_P ST	CLMT CONC CD	COND CD	FFLT_DT	TR WED_Y	CLM_KH	BLNK
2001	15040221100000	08-02	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	DAVE FORD	00000	00000	0101	000	000	00	00	00	21-00-02	10	100000	0000
2001	15040221100000	12-02	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	BRAD FORD, LINCOLN, MARYLAND	00000	00000	0101	000	000	00	00	00	10-00-02	10	000000	0000
2001	15040221100000	11-02	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	CARON MOTOR, INC.	00000	00000	0101	000	000	00	00	00	11-00-02	11	000000	0000
2001	15040221100000	05-04	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	GALDEN FORD	17000	00000	0101	000	000	00	00	00	12-00-02	12	110000	0000
2001	15040221100000	07-02	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	WILL TERESA FORD MARYLAND	00000	00000	0101	000	000	00	00	00	12-00-02	12	100000	0000
2001	15040221100000	05-12	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	FRONTIER FORD LINCOLN MARYLAND	00000	00000	0101	000	000	00	00	00	12-00-02	12	100000	0000
2001	15040221100000	04-02	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	JOHNSON FORD LINCOLN MARYLAND	00000	00000	0101	000	000	00	00	00	01-00-01	10	000000	0000
2001	15040221100000	05-12	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	DUNN FORD	00000	00000	0101	000	000	00	00	00	05-00-01	0	000000	0000
2001	15040221100000	11-20	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	JOHNSON FORD W D BARBERSHOP FORD	00000	00000	0101	000	000	00	00	00	11-00-01	10	000000	0000
2001	15040221100000	07-08	107	17	TOR	TOR	TOR	TOR	TOR	A1	12-00-01	12-00-01	LEP JOHNSON FORD TRUCK CITY	00000	00000	0101	000	000	00	00	00	07-00-01	11	000000	0000
2001	15040221100000	05-07	107	17	TOR	TOR	TOR	TOR	TOR	A2	12-00-01	12-00-01	DAVE STAR FORD	00000	00000	0101	000	000	00	00	00	05-00-02	10	000000	0000

PR03-044-A 5385

DEL_YR	DEL_CD	LAB_D	LAB_CD	WRT_D	WRT_CD	SEC_C	SEC_CD	DRIVE	DRIVE_CD	ENR	ENR_CD	TRAN	TRAN_CD	PLAN	PLAN_CD	PROCD	PROCD_CD	WRT_STA	WRT_CD	NAME	DOC_NO	PL_NO	WCC_CD	PORT	PORT_CD	PART	PART_CD	INST	INST_CD	CONC	CONC_CD	COND	COND_CD	RPR_DT	TRE	CLM_YR	MLGE
2001	PTW03PT14A0000	212.00	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		22-Nov-01	12-Dec-01			RALPH FORD LINCOLN MERCURY	220001	220001	ST1	1002	ST00	BA	DB	42	22-Nov-01	22	200100	4000					
2001	PTW03PT14A0000	250.00	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		27-Feb-01	17-Mar-01			ELCYS ANAPWIK FORD, INC.	220002	220002	ST1	1002	ST00	BA	DB	42	24-Nov-01	3	200100	2001					
2001	PTW03PT14A0000	85.00	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		11-Nov-01	15-Nov-01			FORD	220003	220003	ST1	1002	ST00	BA	DB	42	7-Nov-01	3	200100	2001					
2001	PTW03PT14A0000	108.41	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		2-Nov-01	26-Nov-01			FREEDOM FORD, INC.	220004	220004	ST1	1002	ST00	BA	DB	42	20-Nov-01	8	200100	2001					
2001	PTW03PT14A0000	202.00	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		18-Nov-01	26-Nov-01			CAPITAL FORD INC	220005	220005	ST1	1002	ST00	BA	DB	42	4-Dec-01	20	200100	2001					
2001	PTW03PT14A0000	152.2	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		22-Nov-01	1-Nov-01			PRESTIGE FORD	220006	220006	ST1	1002	ST00	BA	DB	42	11-Nov-01	10	200100	2001					
2001	PTW03PT14A0000	74.8	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	AE		17-Oct-01	2-Nov-01			STEVENS FORD SPRINGVILLE FORD	220007	220007	ST1	1002	ST00	BA	DB	42	20-Nov-01	10	200100	2001					
2001	PTW03PT14A0000	48.20	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		22-Oct-01	22-Nov-01			INC	220008	220008	ST1	1002	ST00	BA	DB	42	24-Nov-01	20	200100	2001					
2001	PTW03PT14A0000	182.00	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		1-Nov-01	20-Nov-01			UNIVERSAL FORD INC	220009	220009	ST1	1002	ST00	BA	DB	41	2-Nov-01	7	200100	2001					
2001	PTW03PT14A0000	65.18	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		18-Nov-01	20-Nov-01			CLEVERSON FORD	220010	220010	ST1	1002	ST00	BA	DB	48	2-Nov-01	11	200100	14001					
2001	PTW03PT14A0000	62.42	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		18-Oct-01	22-Oct-01			SHIBALLA FORD, INC.	220011	220011	ST1	1002	ST00	BA	DB	38	18-Nov-01	20	200100	4700					
2001	PTW03PT14A0000	68.82	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		2-Nov-01	22-Nov-01			NEWTON FORD	220012	220012	ST1	1002	ST00	BA	DB	42	22-Nov-01	12	200100	2001					
2001	PTW03PT14A0000	68.4	TF7	TF	TBC	TCD	TE	TEB	TEB_CD	TEB	TEB_CD	TEB	TEB_CD	A1		2-Nov-01	21-Nov-01			TEACH FORD	220013	220013	ST1	1002	ST00	BA	DB	42	18-Nov-01	20	200100	2001					

MEL YR	LN CD	LIN CD	MIN CD	MKT CD	IND CD	VEH CD	TRN CD	PLAN CD	PRODN CD	WRKY CD	STA CD	NAME	SOC CD	PL CD	MOC CD	MAN CD	MUN CD	IND CD	CURT CD	CON CD	APR CD	TTL CD	CLM CD	MILE CD
2001	1120404437128000	49.99	12.1	TF	TRAD	TRD	TR	TRD	A1	20000	28-09-00	HAROLD ZIPOLER FORD INC.	071479A	000093	0701	1002	0700	BA	00	00	7-26-01	21	00000000	0000
2001	1120404437128000	114.96	14.1	TF	TRAD	TRD	TR	TRD	A1	21-01-01	21-06-01	COUNTRY FOOD MILLER FORD	000000	000177	0701	1002	0700	BA	00	00	8-26-01	20	00001113	0000
2001	1120404437128000	131.95	13.7	TF	TRC	TRD	TR	TRD	A1	12-01-00	2-24-01	LINCOLN SALES & SERVICE	000000	000111	0701	1002	0700	BA	00	00	26-11-01	1	00000000	0000
2001	1120404437128000	119.97	13.7	TF	TRD	TRD	TR	TRD	A1	20-01-01	1-24-01	DANIELLI FORD TRUCK SALES S.S.	017700A	000000	0701	1002	0700	BA	00	00	10-29-01	10	11000070	0000
2001	1120404437128000	39.97	13.7	TF	TRD	TRD	TR	TRD	A1	1-26-01	12-19-01	WELLS FORD SALES S.V.S.	1121000	000000	0701	1002	0700	BA	00	00	10-26-01	28	10000000	0000
2001	1120404437128000	61.98	13.7	TF	TRD	TRD	TR	TRD	A1	22-11-00	2-01-01	LINCOLN TRAIL FORD SECURITY	000000	000000	0701	1002	0700	BA	00	00	1-04-01	10	07000000	0000
2001	1120404437128000	18.7	13.7	TF	TRD	TRD	TR	TRD	A1	8-24-01	2-10-01	ROBINSON FORD SALES INC.	000000	000000	0701	1002	0700	BA	00	00	16-12-01	10	00000000	0000
2001	1120404437128000	34.42	13.7	TF	TRD	TRD	TR	TRD	A1	8-26-01	8-26-01	WYOMING SYSTEMS CORPORATION	000000	000000	0701	1002	0700	BA	00	00	20-01-01	20	00000000	0000
2001	1120404437128000	191.24	13.7	TF	TRD	TRD	TR	TRD	A1	11-26-01	12-26-01	CAPITAL FORD INC.	000000	000000	0701	1002	0700	BA	00	00	24-12-01	10	00010700	0000
2001	1120404437128000	112.28	13.7	TF	TRD	TRD	TR	TRD	A1	21-01-00	28-10-01	MORSON VALLEY FORD TRUCK S.S.	149070A	000000	0701	1002	0700	BA	00	00	28-09-01	15	10100000	0000
2001	1120404437128000	70.93	13.7	TF	TRD	TRD	TR	TRD	A1	26-11-01	2-26-01	JAN WILSON MOTOR	000000	000100	0701	1002	0700	BA	00	00	12-12-01	14	00000000	0000
2001	1120404437128000	24.93	13.7	TF	TRD	TRD	TR	TRD	A1	16-01-00		SMITH FORD INC.	000000	000047	0701	1002	0700	BA	00	00	21-11-01	7	10000000	0000
2001	1120404437128000	26.84	13.7	TF	TRD	TRD	TR	TRD	A1	1-26-01	21-04-00	BO DALBY FORD INC.	070040	000000	0701	1002	0700	BA	00	00	21-01-01	14	00000000	0000
2001	1120404437128000	17.28	13.7	TF	TRD	TRD	TR	TRD	A1	23-11-00	11-01-01	SMITH FORD INC.	000000	000040	0701	1002	0700	BA	00	00	12-12-01	8	00000000	0000
2001	1120404437128000	219.14	13.7	TF	TRD	TRD	TR	TRD	A1	23-01-00	1-26-01	MIDWAY FORD TRUCK CENTER INC.	000000	000000	0701	1002	0700	BA	00	00	25-11-01	3	10000000	0000

REL YR	REL CD	REP O CST	VEH LMD CD	MKT_D RTRM	SOR_D AS STL	VER B ENR3	ORRVE CD	ENR CD	TRAV S CD	PLAN T CD	PRODL T	VERTY_STA RT RT	NAME	DOC_NO N	PH_NO M	WDL CD	PROV. WBLD AAR_P RTR	PROV. WBLD AAR_P RTR	PROV. WBLD AAR_P RTR	OLBY. US_SALF CD	COND CD	WPK DT	TBL PRD Y	CLM_A1	BLSE
0001	1F0A0P0P0E000000	00.12	T07	T08	T08	T08	T08	T08	A1	10-Mar-01	10-Mar-01	FORD FORD SALES	0011001	001000	0701	Y02	0700	0A	000	40	20-Mar-01	0	000000	1000	
0001	1F0A0P0P0E000000	00.11	T07	T08	T08	T08	T08	T08	A1	17-Mar-01	04-Mar-01	EMSTGARE FORD SALES & SERVICE	1000002	0170011	0701	Y02	0700	0A	000	1	04-Mar-01	11	000000	0700	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	05-Apr-01	00-Oct-00	FORD FORD	0000000	000000	0701	Y02	0700	0A	000	40	17-Mar-01	20	000000	1000	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	11-Mar-01	11-Mar-01	STREAMBOAT MOTOR, LLC	0000000	0700000	0701	Y02	0700	0A	000	40	05-Mar-01	10	000000	1000	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	12-Mar-01	10-Mar-01	FHE LONG FORD OF MOTOR, LLC	0000000	000000	0701	Y02	0700	0A	000	40	10-Mar-01	1	000000	0700	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	04-Mar-01	12-Mar-01	MIDENA FORD MOTOR	0000000	0700000	0701	Y02	0700	0A	000	40	04-Mar-01	00	000000	0700	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	00-Mar-01	04-Mar-01	MOBLE FORD MOTOR, INC.	0000000	000000	0701	Y02	0700	0A	000	40	17-Mar-01	20	000000	1000	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	10-Mar-01	10-Mar-01	WICHITA MOTOR, INC.	0000000	000000	0701	Y02	0700	0A	000	1	10-Mar-01	0	000000	0700	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	01-Mar-01	01-Mar-01	PARK CITY FORD	0000000	000000	0701	Y02	0700	0A	000	20	01-Mar-01	0	000000	1000	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	17-Mar-01	20-Oct-01	TEAM FORD OF MOTOR	0000000	000000	0701	Y02	0700	0A	000	40	17-Mar-01	1	000000	0700	
0001	1F0A0P0P0E000000	00.00	T07	T08	T08	T08	T08	T08	A1	17-Mar-01	04-Mar-01	AKINS FORD CORPORATION	0000000	000000	0701	Y02	0700	0A	000	40	10-Mar-01	1	000000	0700	

PE03-044-A 5389

MCL	MR	MR_CD	MR_C	MR_L	MKT_D	DOC_C	MR_S	DRIVE	ENR	TRAN	PLAN	FRONT	WRTY	RT	NAME	DOC	PH	WCC	MRM	MRM_P	MRM_G	MRM_CA	CURT	COND	RTY	TR	CLM	MR
YR	YR		CD	CD		CD	CD	CD	CD	S	T	T	RT	CD		N	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
2001	FTNCHN	FTNCHN4074	78.37	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	2-Sep-00	20-Sep-00	FRENCH GROVER MOTOR CO LTD	1478261	308119	STU	TCZ	BTM	BA	CD	CD	CD	CD	28	28	28	28
2001	FTNCHN	FTNCHN5099	82.27	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	1-Jan-01	1-Jan-01	COASTAL FORD SALES LTD	212206	308202	STU	TCZ	BTM	BA	CD	CD	CD	CD	11	11	11	11
2001	FTNCHN	FTNCHN2020	78.2	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	18-Feb-01	2-Aug-01	FORD MOTOR CO	202102	308202	STU	TCZ	BTM	BA	CD	CD	CD	CD	2	2	2	2
2001	FTNCHN	FTNCHN2000	76.80	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	20-Sep-00	20-Sep-00	FORD MOTOR CO	212206	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	21	21	21	21
2001	FTNCHN	FTNCHN20110	116.7	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	2-Oct-00	1-Jan-01	FORD MOTOR CO	308202	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	20	20	20	20
2001	FTNCHN	FTNCHN17	82.44	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	17-Aug-01	8-Oct-01	FORD MOTOR CO	308202	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	2	2	2	2
2001	FTNCHN	FTNCHN16	81.13	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	2-Oct-00	22-Nov-00	FORD MOTOR CO	307202	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	10	10	10	10
2001	FTNCHN	FTNCHN2044	28.76	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	20-Sep-00	20-Sep-00	FORD MOTOR CO	247401	308202	STU	TCZ	BTM	BA	CD	CD	CD	CD	20	20	20	20
2001	FTNCHN	FTNCHN10	144	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	27-Feb-01	20-Mar-01	FORD MOTOR CO	307202	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	10	10	10	10
2001	FTNCHN	FTNCHN2007	126	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	18-Jul-01	23-Mar-01	FORD MOTOR CO	202201	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	17	17	17	17
2001	FTNCHN	FTNCHN1100	78.8	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	1-Feb-01	1-Jul-01	FORD MOTOR CO	307402	308211	STU	TCZ	BTM	BA	CD	CD	CD	CD	14	14	14	14
2001	FTNCHN	FTNCHN1400	87.83	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	2-Oct-00	20-Feb-01	FORD MOTOR CO	308201	308202	STU	TCZ	BTM	BA	CD	CD	CD	CD	28	28	28	28
2001	FTNCHN	FTNCHN150000	118.2	7/77	TF	TBC	TCD	TE	TCD	TCD	A1	18-Oct-00	20-Oct-00	FORD MOTOR CO	308101	308202	STU	TCZ	BTM	BA	CD	CD	CD	CD	25	25	25	25

ADL YE	VIN CD	LIB_C CD	VIN LINE CD	SKT_D SERVED	SEC_C ASSET	VIN_L SERIES CD	DRIVE CD	WGR CD	TRAN AL CD	PLAN T CD	PROCD T	PARTY_STA RT DT	NAME	DOC_NUM	PH_NUM	MCC CD	PRY AUE P SER	PRY AUE S SER	PRY AUE SUP SER	CLTY CD	COND CD	APP_DT	TRE WBY	CLM WBY	AMT
2001	1P1M2C2H2Z62099		64.4	TFT	TF	TBC	TBC	TBE	TBE	A1	25-04-01	5-14-01	AMERICAN MOTOR COMPANY	2000001	2004071	ST01	SCZ	BF00	BA	CS	00	25-04-01	21	2000001	1872
2001	1P1M2C2H2Z62149		30.4	TFT	TF	TBC	TBC	TBE	TBE	A1	14-04-01	25-04-01	FORD FORD-LINCOLN-MERCEDES, INC	2000000	2007011	ST01	SCZ	BF00	BA	CS	00	2-14-01	21	2000001	3078
2001	1P1M2C2H2Z62229		4.11	TFT	TF	TBC	TBC	TBE	TBE	A1	4-14-01	17-04-01	JOHNSON FORD, INC	4000000	2000000	ST01	SCZ	BF00	BA	CS	00	4-14-01	8	2000001	500
2001	1P1M2C2H2Z62269		32.4	TFT	TF	TBC	TBC	TBE	TBE	A1	25-04-01	7-04-01	WALSH FORD TRUCKS	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	1-14-01	17	2000001	4880
2001	1P1M2C2H2Z62349		20.4	TFT	TF	TBE	TBE	TBE	TBE	A1	25-04-01	25-04-01	BONNEL MOTORS INC	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	12-04-01	10	2000001	1412
2001	1P1M2C2H2Z62369		42.4	TFT	TF	TBE	TBE	TBE	TBE	A1	4-04-01	2-14-01	NORTHWEST FORD TRUCKS INC	1000000	2000000	ST01	SCZ	BF00	BA	CS	00	2-14-01	18	2000001	2022
2001	1P1M2C2H2Z62389		34.4	TFT	TF	TBC	TBC	TBE	TBE	A1	25-04-01	19-04-01	APPLE FORD WELLY HONEL FORD LINCOLN-MERCEDES	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	19-04-01	12	2000001	1402
2001	1P1M2C2H2Z62409		64.4	TFT	TF	TBC	TBC	TBE	TBE	A1	25-04-01	19-04-01	FORD LINCOLN-MERCEDES	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	19-04-01	16	2000001	3701
2001	1P1M2C2H2Z62429		44.4	TFT	TF	TBE	TBC	TBE	TBE	A1	12-04-01	6-14-01	FORD LINCOLN-MERCEDES TRUCK CENTER INC	2000001	2000000	ST01	SCZ	BF00	BA	CS	00	6-14-01	0	2000001	2182
2001	1P1M2C2H2Z62449		24.4	TFT	TF	TBC	TBC	TBE	TBE	A1	25-04-01	14-04-01	PAPASKY FORD SALES (SHELDON)	2000000	2000000	ST01	SCZ	BF00	AA	CS	00	25-04-01	1	2000001	800
2001	1P1M2C2H2Z62469		4-4	TFT	TF	TBE	TBE	TBE	TBE	A1	15-04-01	4-14-01	ROCHESTER FORD-LINCOLN-MERCEDES	2000001	2000000	ST01	SCZ	BF00	BA	CS	00	25-04-01	14	2000001	2580
2001	1P1M2C2H2Z62489		21.4	TFT	TF	TBE	TBE	TBE	TBE	A1	11-04-01	24-04-01	DAY FORD	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	25-04-01	9	2000001	9
2001	1P1M2C2H2Z62509		24.4	TFT	TF	TBE	TBE	TBE	TBE	A1	17-04-01	25-04-01	FAMILY & STEVENS LTD	2000001	2000000	ST01	SCZ	BF00	BA	CS	00	25-04-01	9	2000001	1312
2001	1P1M2C2H2Z62529		12.4	TFT	TF	TBE	TBE	TBE	TBE	A1	15-04-01	23-04-01	HOWE FORD SALES	2000001	2000000	ST01	SCZ	BF00	BA	CS	00	5-04-01	9	2000001	103
2001	1P1M2C2H2Z62549		22.4	TFT	TF	TBE	TBE	TBE	TBE	A1	14-04-01	11-04-01	PECK ROAD FORD TRUCKS INC	2000000	2000000	ST01	SCZ	BF00	BA	CS	00	10-04-01	21	2000001	2510

VEH. YR	VEH. CO	LSR_C	LANE_CD	MKT_D	MOD_C	VEH_S	DRIVE	ENGL	TRAN	PLAN	PRDNO	DRD	WREY_STA	ST	NAME	DOC_NO	PL_NO	WCC	SALE_P	SALE_B	SALE_F	SALE_SUP	COND	COND	PRD	TR	CLAS	MR
2001	FTWVW02P1E00004	141.11	TR7	TF	TRD	TRD	TR	TRD	TR7	A1	30-Jan-01	3-00-01			NORTHERN TRUCKS & EQUIPMENT	080026	001773	TR1	ICZ	0700	SA	TRD	TR	20	20-01-01	1	200001	10
2001	FTWVW02P1E00007	88.98	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-Jan-01	20-Jan-01			COLING MOTORS INC	001100	000070	TR1	ICZ	0700	SA	TRD	TR	40	10-00-00	20	000100	0000
2001	FTWVW02P1E00008	43.60	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	2-00-00	2-00-01			STATION MOTORS INC	070001	000000	TR1	ICZ	0700	SA	TRD	TR	40	2-00-00	20	000000	0000
2001	FTWVW02P1E00009	100.43	TR7	TF	TRD	TRD	TR	TRD	TR7	A1	1-00-01	1-Feb-01			EASTERN BENTON MOTORS	000001	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-01	2	100000	0000
2001	FTWVW02P1E00010	02.77	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	2-00-01	2-00-01			COUNTRY FORD-MERCURY, INC.	100000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-01-01	0	000000	0000
2001	FTWVW02P1E00011	206.40	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	7-00-01	22-00-01			DEVLIN FORD SALES INC.	100000	000000	TR1	ICZ	0700	SA	TRD	TR	20	20-00-00	20	000000	0000
2001	FTWVW02P1E00012	20.20	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	11-00-00	2-00-01			COUNTRY FORD-MERCURY, INC.	110000	000000	TR1	ICZ	0700	SA	TRD	TR	40	1-00-01	4	100000	0000
2001	FTWVW02P1E00013	14.0	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	2-Feb-01	20-Feb-01			FORD, INC.	100000	000000	TR1	ICZ	0700	SA	TRD	TR	40	2-00-01	0	000000	0000
2001	FTWVW02P1E00014	24.32	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	2-00-00	10-00-00			ALL STAR FORD-MERCURY, INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	2-00-00	20	000000	0000
2001	FTWVW02P1E00015	60.17	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-00-01	20-00-01			ALL STAR FORD-MERCURY, INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-00	0	100000	0000
2001	FTWVW02P1E00016	110.04	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-00-01	20-00-01			ALL STAR FORD-MERCURY, INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-01	0	210000	0000
2001	FTWVW02P1E00017	100.00	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-00-00	20-00-00			CROSSROADS FORD TRUCKS INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	1-00-00	20	100000	1000
2001	FTWVW02P1E00018	84.4	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	0-00-01	0-00-01			ALL STAR FORD-MERCURY, INC.	110000	000000	TR1	ICZ	0700	SA	TRD	TR	40	0-00-00	20	000000	0000
2001	FTWVW02P1E00019	44.00	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	0-00-00	2-00-00			CROWN FORD SALES INC.	070000	001000	TR1	ICZ	0700	SA	TRD	TR	40	2-00-00	20	100000	0000
2001	FTWVW02P1E00020	80.43	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	0-00-01	0-00-01			FORD	000000	000000	TR1	ICZ	0700	SA	TRD	TR	1	20-00-00	20	100000	0000
2001	FTWVW02P1E00021	17.01	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-00-01	20-00-01			COUNTRY FORD-MERCURY (A.C.)	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-00	0	000000	0000
2001	FTWVW02P1E00022	07.20	TR7	TF	TRD	TRD	TR	TRD	TR7	A1	20-00-01	20-00-01			FISHERY FORD, INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	0-00-01	0	000000	1000
2001	FTWVW02P1E00023	00.00	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	20-00-00	20-00-01			ONE BLACK FORD	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-01	0	000000	0000
2001	FTWVW02P1E00024	13.00	TR7	TF	TRD	TRD	TR	TRD	TR7	A1	20-00-01	0-00-00			FORD OF TEXAS INC.	000000	000000	TR1	ICZ	0700	SA	TRD	TR	40	20-00-01	0	001000	1000
2001	FTWVW02P1E00025	00.00	TR7	TF	TRD	TRD	TR	TRD	TRD	A1	10-00-01	1-00-01			WINDHAM FORD	100000	000000	TR1	ICZ	0700	SA	TRD	TR	40	10-00-01	0	000000	0000

REL. YR	REL. CD	REL. C. LINE CD	REL. C. LINE CD	MKT. D. CD	MO. C. CD	REL. S. CD	DRIVE. CD	REL. CD	TRAM. S. CD	PLAN. T. CD	DRIVE. D. CD	DRIVE. STA. CD	NAME	DOC. NO.	PH. NO.	ACC. CD	PART. ALI. F. CD	PORT. ALI. F. CD	REL. S. CD	CLUB. CD	COND. CD	RE. DT	RE. CD	RE. CD	RE. CD	
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	ALLAN VIEL FORD	212702	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	3MM PACK FIVE STAR FORD	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	PAUL CLARK FORD-SPENCER, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	PERDUE-HURST MOTOR COMPANY	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	HARRISON FORD COMPANY	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	HARRISON FORD INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	MARGOTTS FORD SALES INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	SAVON MOTORS INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	MORSE FORD, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	A-C COLLINS FORD, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	WILSON FORD-UNION SECURITY	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	SWEETWATER FORD, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	GREENLAW MOTORS, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	DEAN STALLARD FORD INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	STAYTON MOTORS INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	RENTZELMANN TRUCK CENTER INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	JOE COOPER FORD, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	MC WILLIAMS FORD TRUCK FORD	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7
2001	1	FTWVW02PH1E02000	111.21	TFF	TF	TBC	TCD	TB	TCE	TCE	A1	22-Mar-01	22-Mar-01	TITUSWILL FORD SALES, INC.	220000	220000	STD1	100Z	0F00	BA	DD	28	11-Mar-01	4	100000	7

ACL VE VIN CD	LAB_C OBT	VEH LINE CD	MKT_D FRM	BOC_L RE STL	VEH_S ENR CD	DRIVE CD	ENR CD	TRAN FLD CD	FLASH T CD	PROD_D T	WGT_STA RT WT	NAME	DOC_NO M	PL_NO A	WCC CD	PLT NUM D A	PLT NUM L A	PLT NUM R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A	PLT NUM L R A	PLT NUM R R A							
20011FTS224P1444842	91.48	754	TF	TBD	TBD	TR	TDR	TDR	A1	12-Nov-02	12-Nov-02	MERKURY FORD TRUCK CENTER, INC.	178202A	488208	STN	100Z	8P30	BA	000	42	28-Nov-02	3	207700	0																	
20011FTS224P1444842	8.50	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	24-Nov-01	DAN MERRY FORD SALES LTD.	0277801	000004	STN	100Z	8P30	BA	110	42	22-Oct-02	12	1100007	10000																	
20011FTS224P1444842	13.62	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	24-Nov-01	DAVE KOPPEL FORD SALES, INC.	000000	000000	STN	100Z	8P30	BA	000	48	1-Jul-02	23	1200000	20010																	
20011FTS224P1444842	12.20	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	24-Nov-01	DAVE KOPPEL FORD SALES, INC.	000000	000000	STN	100Z	8P30	BA	000	1	2-Feb-02	12	000000	10000																	
20011FTS224P1444842	27.24	757	TF	TBD	TBD	TR	TDR	TDR	A1	14-Nov-02	14-Nov-02	STEVENS MOTOR SALES	0702001	700000	STN	100Z	8P30	BA	000	48	22-Nov-02	11	1000000	17000																	
20011FTS224P1444842	23.2	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	24-Nov-01	DAVE KOPPEL FORD SALES, INC.	000000	000000	STN	100Z	8P30	BA	000	42	12-Nov-02	12	200000	20000																	
20011FTS224P1444842	26.7	757	TF	TBD	TBD	TR	TDR	TDR	A1	12-Nov-01	22-Nov-01	SCALTS LIVE OAK F-150	070200	000112	STN	100Z	8P30	BA	000	41	8-Nov-02	12	000000	12000																	
20011FTS224P1444842	2.08	757	TF	TBD	TBD	TR	TDR	TDR	A1	21-Nov-01	21-Nov-01	STANLEY FORD INC.	000000	000000	STN	100Z	8P30	BA	000	42	4-Nov-01	8	000000	00000																	
20011FTS224P1444842	77.78	757	TF	TBD	TBD	TR	TDR	TDR	A1	22-Nov-01	22-Nov-01	WING LINCOLN MERCURY INC	1073401	040000	STN	100Z	8P30	BA	000	42	8-Nov-01	12	1000000	21000																	
20011FTS224P1444842	20.07	757	TF	TBD	TBD	TR	TDR	TDR	A1	21-Nov-01	21-Nov-01	PATRIOT FORD-LINCOLN-MERCURY	000000	000000	STN	100Z	8P30	BA	000	1	2-Nov-01	4	000000	40000																	
20011FTS224P1444842	16.42	757	TF	TBD	TBD	TR	TDR	TDR	A1	18-Nov-01	21-Nov-01	FRANKEL FORD INC.	000001	000001	STN	100Z	8P30	BA	000	42	4-Nov-01	8	000000	00000																	
20011FTS224P1444842	13.14	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	24-Nov-01	WOODRIVER FORD SALES	000001	000000	STN	100Z	8P30	BA	000	42	22-Oct-02	12	1000000	20000																	
20011FTS224P1444842	25.4	757	TF	TBD	TBD	TR	TDR	TDR	A1	21-Dec-02	22-Nov-01	HENRY CURRY FORD-MERCURY	1073401	700000	STN	100Z	8P30	BA	000	1	2-Nov-02	11	000000	10000																	
20011FTS224P1444842	100.43	757	TF	TBD	TBD	TR	TDR	TDR	A1	24-Nov-01	18-Nov-01	EASTERN BARRA MOTORS	000001	000000	STN	100Z	8P30	BA	000	48	22-Nov-01	8	1100000	30000																	
20011FTS224P1444842	176.26	757	TF	TBD	TBD	TR	TDR	TDR	A1	17-Oct-02	11-Nov-02	RICHARDSON FORD SALES, INC.	700001	000000	STN	100Z	8P30	BA	001	42	12-Nov-02	21	1070000	24000																	
20011FTS224P1444842	25.4	757	TF	TBD	TBD	TR	TDR	TDR	A1	21-Nov-01	21-Nov-01	ALL STAR FORD-MERCURY INC.	1073401	700000	STN	100Z	8P30	BA	000	42	22-Nov-02	22	1000000	00000																	
20011FTS224P1444842	27.32	757	TF	TBD	TBD	TR	TDR	TDR	A1	21-Oct-02	22-Nov-01	MARTIN FORD OF OREGON	000001	000001	STN	100Z	8P30	BA	000	42	8-Nov-01	8	2000000	10000																	
20011FTS224P1444842	100.02	757	TF	TBD	TBD	TR	TDR	TDR	A1	22-Nov-01	24-Nov-01	LANCERS FORD SALES	1073401	000000	STN	100Z	8P30	BA	000	42	21-Nov-01	0	2100000	20000																	
20011FTS224P1444842	77.78	757	TF	TBD	TBD	TR	TDR	TDR	A1	12-Oct-02	12-Nov-02	DAVE KOPPEL FORD SALES, INC.	0702001	000001	STN	100Z	8P30	BA	000	42	22-Nov-02	21	0000000	00000																	

PC03-044-A 5394

MOI YR	VEN CD	LINK CD	VEN CD	MKT CD	SEC CD	VEN CD	ORIG CD	TRAI S CD	PLAN T CD	PRCD D T	WRTY STA WT BT	NAME	DOC NU M	PH NU M	WCC CD	PRY ALE P REF	PRY ALE B REF	PRY ALE S REF	CLUF CONC CD	COND CD	RPLD DT	TR WRTY	CLM AGE	AB SE
2001	FTN02P41EDT24	81.80	T77	TF	T8D	T8D	T8E	T8E	A1	10-Mar-01	20-Mar-01	COLLEENWAY FORD, INC.	400004	200000	STV1	100E	0700	BA	000	40	1-Mar-01	1	700000	00
2001	FTN02P41BABB19	204.80	T77	TF	T8D	T8D	T8E	T8E	A1	12-Oct-00	2-Jun-01	WILL BRADY FORD INC.	000000	000000	STV1	100E	0700	BA	011	40	17-Oct-01	10	000000	0000
2001	FTN02P41B0000K	43.8	T77	TF	T8D	T8D	T8E	T8E	A1	11-Dec-00	20-Mar-01	CRUTCHER FORD, INC.	070000	700000	STV1	100E	0700	BA	000	40	10-Mar-01	20	000000	0100
2001	FTN02P41B0000N	40.80	T77	TF	T8D	T8D	T8E	T8E	A1	20-Mar-01	20-Mar-01	CONVERT FORD, INC. CONVERTOR, FORD LINCOLN, INC.	200001	200000	STV1	100E	0700	BA	000	40	10-Oct-00	10	100000	0000
2001	FTN02P41B0000K	201.20	T77	TF	T8D	T8D	T8E	T8E	A1	1-Oct-00	14-Dec-01	WILL BRADY FORD INC.	210001	200000	STV1	100E	0700	BA	000	40	20-Mar-01	10	100000	0000
2001	FTN02P41B0000K	40.80	T77	TF	T8C	T8D	T8E	T8E	A1	1-Jun-01	1-Jun-01	WILL BRADY FORD INC.	070000	200000	STV1	100E	0700	BA	004	1	1-Jun-01	2	000000	0000
2001	FTN02P41B0000N	202.70	T77	TF	T8D	T8D	T8E	T8E	A1	2-Mar-00	22-Mar-01	MAC HIRE FORD	130004	000000	STV1	100E	0700	BA	000	20	2-Mar-01	0	000000	00
2001	FTN02P41B0000K	100.80	T77	TF	T8C	T8D	T8E	T8E	A1	0-Oct-00	20-Oct-00	SPENCER MOTORS INC	040001	100000	STV1	100E	0700	BA	000	40	0-Oct-00	21	000000	0000
2001	FTN02P41B0000N	200.80	T77	TF	T8C	T8D	T8E	T8E	A1	27-Feb-01	10-Oct-01	FORD OF COLA INC. CONVERSION FORD	000001	700000	STV1	100E	0700	BA	000	40	10-Mar-01	10	100000	0000
2001	FTN02P41B0000K	20	T77	TF	T8C	T8D	T8E	T8E	A1	20-Feb-01	18-Mar-01	MERCURY, INC.	200000	200000	STV1	100E	0700	BA	000	1	18-Mar-01	10	000000	0000
2001	FTN02P41B0000K	22.80	T77	TF	T8C	T8D	T8E	T8E	A1	20-Mar-01	24-Apr-01	HARWOOD FORD SALES LTD	000001	000000	STV1	100E	0700	BA	000	20	2-Oct-00	10	100000	1000
2001	FTN02P41B0000K	27.80	T77	TF	T8C	T8D	T8E	T8E	A1	10-Mar-01	31-Mar-01	ICE TONES FORD, INC.	000001	000000	STV1	100E	0700	BA	000	40	0-Mar-01	7	000000	0000
2001	FTN02P41B0000K	240	T77	TF	T8C	T8D	T8E	T8E	A1	0-Mar-01	20-Apr-01	JACK HOBBS FORD, INC.	000001	040000	STV1	100E	0700	BA	000	40	10-Mar-01	20	000000	0000
2001	FTN02P41B0000K	200.8	T77	TF	T8C	T8D	T8E	T8E	A1	20-Mar-01	22-Feb-01	LANDMARK FORD, INC.	070000	000000	STV1	100E	0700	BA	000	40	20-Mar-01	20	000000	0000
2001	FTN02P41B0000K	177.80	T77	TF	T8D	T8D	T8E	T8E	A1	10-Mar-00	1-Oct-00	FLIMMIE TRUCK CENTRE	000000	000000	STV1	100E	0700	BA	000	40	20-Mar-01	7	000000	0000
2001	FTN02P41B0000K	200.80	T77	TF	T8C	T8D	T8E	T8E	A1	20-Mar-01	20-Mar-01	FORD OF COLA INC.	000001	700000	STV1	100E	0700	BA	000	40	1-Mar-01	10	000000	0000

DEL YR_VIN_CD	LIB_C CD	VIN LINE_CD	MKT_B SERVED	DOB_C AB STL	VER_F BRNCH_CD	DRIVE CD	ENR CD	TRAN S_CD	PLAN F_CD	PROCD D_Y	WRTY_STA WT_YT	NAME	DOC_NO N	PL_NO N	WCC CD	PLNT M_B ALN_P REP	PLNT M_B ALN_P ASS	PLNT M_B ALN_P F	ELMT CONC CD	COND CD	APP_DT	TR VEND	CLM_NO Y	ML_02
2001	FTN0021	72.87	TF7	TF	TBC	TBD	TR	TCS	A1	20-00-01	2-00-01	BARBER-DYSON FORDS LLC	272401	220048	STD1	1002	SP08	BA	DB	42	27-00-01	22	070915	0001
2001	FTN0021	58.11	TF7	TF	TBC	TBD	TR	TCS	A1	21-00-00	2-00-00	FRENCHLY FORD FORDS FORD	070001	220048	STD1	1002	SP08	BA	DB	42	2-00-00	20	070001	7448
2001	WTF001	27.82	TF7	TF	TBC	TBD	TR	TCS	A1	20-00-01	2-00-01	FORDS FORD OF MONTGOMERY	110000	220048	STD1	1002	SP08	BA	DB	42	20-00-01	10	WTF001	1400
2001	FTN0021	148.24	TF7	TF	TBC	TBD	TR	TCS	A1	20-00-01	2-00-01	VALLEY FORD LANCOLN-MERCURY	400000	220048	STD1	1002	SP08	BA	DB	42	20-00-01	18	000000	0000
2001	FTN0021	88.5	TF7	TF	TBC	TBD	TR	TCS	A1	2-00-00	2-00-00	VALLEY FORD INC	200000	220048	STD1	1002	SP08	BA	DB	42	2-00-00	20	000000	0000
2001	FTN0021	28.48	TF1	TF	TBC	TBD	TR	TCS	A1	2-00-00	2-00-00	COLLIERIE FORD, INC	000100	220048	STD1	1002	SP08	BA	DB	42	2-00-00	20	000000	0000
2001	FTN0021	158.20	TF1	TF	TBC	TBD	TR	TCS	A1	20-00-01	11-00-01	THOMAS CURTIS FORD-MERCURY	000000	220048	STD1	1002	SP08	BA	DB	42	20-00-01	01	010000	1000
2001	FTN0021	61.80	TF1	TF	TBC	TBD	TR	TCS	A1	10-00-00	10-00-00	APPROXIMATE FORD OF HENNING	700000	220048	STD1	1002	SP08	BA	DB	42	10-00-00	1	000000	0000
2001	FTN0021	47.87	TF1	TF	TBC	TBD	TR	TCS	A1	10-00-00	1-00-00	HENNING FORD INC	100000	220048	STD1	1002	SP08	BA	DB	42	10-00-00	10	000000	0000
2001	FTN0021	75.40	TF7	TF	TBC	TBD	TR	TCS	A1	21-00-01	22-00-01	VALLEY FORD OF OHIO	400000	220048	STD1	1002	SP08	BA	DB	1	20-00-01	14	000000	0000
2001	FTN0021	39.28	TF7	TF	TBC	TBD	TR	TCS	A1	1-00-00	20-00-00	VALLEY FORD TRUCK SALES INC	100100	220048	STD1	1002	SP08	BA	DB	1	21-00-00	20	000000	2100
2001	FTN0021	188.20	TF7	TF	TBC	TBD	TR	TCS	A1	2-00-00	20-00-00	JOE COOPER FORD, INC	000100	220048	STD1	1002	SP08	BA	DB	42	2-00-00	2	000100	0001
2001	FTN0021	45.30	TF7	TF	TBC	TBD	TR	TCS	A1	1-00-00	2-00-00	JACK DEBBERS FORD, INC	000100	220048	STD1	1002	SP08	BA	DB	42	1-00-00	20	000100	0001
2001	FTN0021	78.00	TF7	TF	TBC	TBD	TR	TCS	A1	20-00-00	20-00-00	NORTHPOINT FORD	000000	220048	STD1	1002	SP08	BA	DB	42	10-00-00	21	000000	0000
2001	FTN0021	184.4	TF7	TF	TBC	TBD	TR	TCS	A1	2-00-00	20-00-00	WAGE FORD, INC	100000	220048	STD1	1002	SP08	BA	DB	20	27-00-00	11	000000	0000

INCL	VEH_VIN_CD	LEAD_OST	VEH_LIN_CD	INT_D	MOD_C	VEH_S	DRIVE	ENG	TRAN	PLAN	FRON_D	WRTY_STA	NAME	DOC_NO	PH_NO	WCC	FACT	PART	PART	PART	COND	RELT	TTL	CLAKE	MLGE
				REVISED	AR STL	CD	CD	CD	CD	T CD	Y	RT ST					PLANT	NUM_E	NUM_F	NUM_G	CD	UT	WEEK		
3001	1F00W0P2S000004	52.29	7F7	TF	T88	T08	T8	T08	T08	A1	20-00-00	20-00-01	SEVENS FORD SALES, INC.	1001004	0004000	STP1	1000	0000	00	000	20	0-00-00	20	1200000	2000
3001	1F00W0P2S000008	55.00	7F7	TF	T88	T08	T8	T08	T08	A1	10-00-00	20-00-01	JOE COOPER FORD CP SHANNON	1100401	0707001	STP1	1000	0000	00	000	20	0-00-00	20	2000000	2000
3001	1F00W0P2S000010	26.77	7E4	TF	T80	T08	T8	T08	T08	A1	20-00-00	2-00-01	RANDALL FORD INC	2000000	0001011	STP1	1000	0000	00	000	20	21-00-00	0	1000000	0
3001	1F00W0P2S000012	81.61	7E7	TF	T80	T08	T8	T08	T08	A1	20-00-01	7-00-01	MURPHY FORD, INC.	0177000	0710000	STP1	1000	0000	00	000	20	10-00-01	2	2000000	2000
3001	1F00W0P2S000018	118.00	7E7	TF	T88	T08	T8	T08	T08	A1	7-00-00	14-00-01	GREATER CLEVELAND FORD-MERCURY	100001A	0000011	STP1	1000	0000	00	000	20	20-00-01	7	2000000	2000
3001	1F00W0P2S000020	101.27	7E7	TF	T88	T08	T8	T08	T08	A1	2-00-01	20-00-01	PRESTIGE FORD	0000001	0000000	STP1	1000	0000	00	000	20	20-00-00	14	7000000	7000
3001	1F00W0P2S000040	65.8	7E7	TF	T80	T08	T8	T08	T08	A1	0-00-01	20-00-01	MISSION VALLEY FORD TRUCK SALES	140000A	0000000	STP1	1000	0000	00	000	20	10-00-00	24	1400000	140000
3001	1F00W0P2S000050	41.80	7E7	TF	T88	T08	T8	T08	T08	A1	1-00-01	0-00-01	MURPHY FORD, INC.	101400A	0000007	STP1	1000	0000	00	000	20	0-00-00	20	1400000	140000
3001	1F00W0P2S000057	65.44	7E7	TF	T80	T08	T8	T08	T08	A1	20-00-00	10-00-01	CONNOR FORD, INC.	1000000	0000000	STP1	1000	0000	00	000	20	17-00-00	20	1000000	100000
3001	1F00W0P2S000060	49.00	7E7	TF	T80	T08	T8	T08	T08	A1	7-00-01	20-00-01	LEONARD FORD, INC.	0000000	0000000	STP1	1000	0000	00	000	20	14-00-00	0	0000000	000000
3001	1F00W0P2S000068	50.10	7E7	TF	T80	T08	T8	T08	T08	A1	2-00-01	10-00-01	WILLIAMS FORD, LLC	2000000	0000000	STP1	1000	0000	00	000	20	17-00-00	24	1000000	100000
3001	1F00W0P2S000077	42.24	7E7	TF	T80	T08	T8	T08	T08	A1	01-00-01	20-00-01	L & B TRUCK CENTER	010000A	0000000	STP1	1000	0000	00	000	1	14-00-01	2	0000000	000000
3001	1F00W0P2S000080	019.00	7E7	TF	T88	T08	T8	T08	T08	A1	0-00-00	17-00-00	SPRINGS FORD-LIN	1700000	0000007	STP1	1000	0000	00	000	20	0-00-00	24	1700000	1700000
3001	1F00W0P2S000088	60.00	7E7	TF	T88	T08	T8	T08	T08	A1	2-00-01	21-00-01	GREATER FORD SALES INC	0100000	0000000	STP1	1000	0000	00	000	20	14-00-00	14	0000000	000000
3001	1F00W0P2S000095	10.41	7E7	TF	T88	T08	T8	T08	T08	A1	10-00-01	0-00-01	MURPHY FORD-MERCURY	0000000	0000000	STP1	1000	0000	00	000	1	21-00-01	7	0000000	000000
3001	1F00W0P2S000098	07.40	7E7	TF	T88	T08	T8	T08	T08	A1	10-00-01	2-00-01	WILLIAMS FORD, INC.	1000000	0000000	STP1	1000	0000	00	000	20	14-00-00	2	0000000	000000
3001	1F00W0P2S000100	66.01	7E7	TF	T88	T08	T8	T08	T08	A1	20-00-00	7-00-01	BLAIR WILSON CARTER, THE LLC	2000000	0000000	STP1	1000	0000	00	000	20	10-00-00	10	0000000	000000

FB03-044-A 5397

DEL YR	DEL CD	LIBL D CMT	VOL LINE CD	MKT D SERV CD	BOC C OR BR	VOL D BRN CD	DRIVE CD	ENG CD	TRAN BLD CD	PLAN Y CD	PRODM D Y	WRKY STA OR DT	NAME	DOC_MJ M	PL_MJ M	WCOL CD	PRO HEAD ALM_P	PROT LABEL G	PROT LABEL AGR	PROT M LABEL CD	CUST CONC CD	COND CD	APPL DT	TRG TRCD Y	CLL_VS Y	BLK_Z
2001	1	FORD	268	TF7	TF	788	788	78	788	78F	A1	25-Mar-01	25-Mar-01	JON KENNEDY FORD	302700	227700	STU	7CZ	8788	SA	000	1	25-Mar-01	17	1000000	2010
2001	1	FORD	268	TF7	TF	788	788	78	788	78F	A1	25-Mar-01	25-Mar-01	FORD OF OCALA INC	872200	112800	STU	7CZ	8788	SA	780	42	20-Mar-01	9	000000	1700
2001	1	FORD	27	TF7	TF	788	788	78	788	78F	A1	24-Mar-01	25-Mar-01	HENSON FORD INC	1302700	242800	STU	7CZ	8788	SA	780	42	24-Mar-01	7	7071000	2010
2001	1	FORD	35236	TF7	TF	788	788	78	788	78F	A1	22-Mar-01	24-Mar-01	MERRAY FORD TRUCK CENTER INC	240200	400000	STU	7CZ	8788	SA	000	20	19-Mar-01	16	000000	2004
2001	1	FORD	2325	TF7	TF	788	788	78	788	78F	A1	21-Oct-00	21-Feb-01	COURTESY FORD	7140000	389771	STU	7CZ	8788	SA	000	48	11-Mar-01	30	200000	17701
2001	1	FORD	1873	TF7	TF	788	788	78	788	78F	A1	20-Mar-01	20-Mar-01	FORD OF OCALA INC	370001	100000	STU	7CZ	8788	SA	042	48	21-Mar-01	22	1070100	0000
2001	1	FORD	973	TF7	TF	788	788	78	788	78F	A1	20-Mar-01	20-Mar-01	AMSTERDAM TRUCK SALES INC	800000	800012	STU	7CZ	8788	SA	000	42	19-Mar-01	12	000000	2000
2001	1	FORD	4742	TF7	TF	788	788	78	788	78F	A1	27-Feb-01	27-Mar-01	FORD TRUCKS & SALES	100000	100000	STU	7CZ	8788	SA	000	42	24-Mar-01	16	1000000	0000
2001	1	FORD	6582	TF7	TF	788	788	78	788	78F	A1	11-Mar-01	18-Feb-01	FORD OF OCALA INC	870001	100000	STU	7CZ	8788	SA	000	28	17-Mar-01	8	371000	0000
2001	1	FORD	3830	TF7	TF	788	788	78	788	78F	A2	27-Feb-01	17-Mar-01	BLVD'S GRAPHICS DESIGN INC	407100	800000	STU	7CZ	8788	SA	000	41	26-Mar-01	18	1000000	0000
2001	1	FORD	6738	TF7	TF	788	788	78	788	78F	A2	26-Mar-01	24-Mar-01	NEWBLEYBARK FORD INC	200000	200000	STU	7CZ	8788	SA	000	48	19-Mar-01	13	710000	4001
2001	1	FORD	37748	TF7	TF	788	788	78	788	78F	A2	5-Oct-00	15-Dec-00	CONVERT FORD INC	800001	240000	STU	7CZ	8788	SA	001	80	20-Mar-01	8	100000	20771
2001	1	FORD	70	TF7	TF	788	788	78	788	78F	A2	17-Dec-00	24-Nov-00	GANTON MOTORS, INC	000000	800000	STU	7CZ	8788	SA	000	42	1-Dec-01	14	000000	0000
2001	1	FORD	70	TF7	TF	788	788	78	788	78F	A2	21-Mar-01	17-Dec-01	BILL WILSON MOTOR COMPANY	100001	800011	STU	7CZ	8788	SA	000	42	18-Mar-01	0	100000	00
2001	1	FORD	3432	TF7	TF	788	788	78	788	78F	A1	23-Dec-00	25-Nov-00	FRIENDLY FORD INC	300000	200000	STU	7CZ	8788	SA	000	28	4-Jan-01	2	000000	0000
2001	1	FORD	6741	TF7	TF	788	788	78	788	78F	A1	20-Mar-01	24-Mar-01	SPURDIN FORD SALES	100000	100000	STU	7CZ	8788	SA	000	42	1-Mar-01	13	1000000	1000

VEH. VIN CD	LNK_D CDT	MEH. LNK. CD	ACT_D ENDED	DOCL. AB. ST.	VEH.L. CD	DRIVE. CD	ENG. CD	TRAN. S. CD	PLAN. T. CD	PRODL. T. CD	WRTY. STA. RT. ST.	NAME	DOCL. M.	FR. M.	MOD. CD	FOR. M. A. P. S. A.	PART. M. A. S. A.	PART. M. L. S. F.	CURT. COND. CD	COND. CD	APPL. DT	TR. YEAR	CL. Y.	PL. KE.
2001-1FTNXP0F0H000001	30.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	12-Dec-00	20-Dec-00	AUTO MAIL OF LINDA, INC.	200001	200001	ST01	FCSE	SP00	BA	D00	42	2-28-01	0	200001	9700
2001-1FTNXP0F0H000002	22.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	20-Mar-01	22-Oct-01	FORD FORD LINCOLN MERCURY SALES FORD- MERCURY	011001	000000	ST01	FCSE	SP00	BA	A00	42	11-Sep-00	71	110000	0000
2001-1FTNXP0F0H000003	8.90	TF7	TF	TBD	TCD	TE	T00	T00	A1	20-Mar-01	20-Mar-01	HUNTER FORD LINCOLN MERCURY	200001	000000	ST01	FCSE	SP00	BA	D00	42	1-Oct-00	10	100000	17000
2001-1FTNXP0F0H000004	18.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	12-Mar-01	21-Mar-01	HUNTER FORD LINCOLN MERCURY	200001	000000	ST01	FCSE	SP00	BA	D00	42	2-Mar-01	8	010000	7000
2001-1FTNXP0F0H000005	148.77	TF7	TF	TBD	TCD	TE	T00	T00	A1	2-Oct-00	4-Nov-00	ED WITTMER FORD LINCOLN- MERC	000001	000001	ST01	FCSE	SP00	BA	D00	42	2-Oct-00	20	100000	0000
2001-1FTNXP0F0H000006	212.40	TF7	TF	TBD	TCD	TE	T00	T00	A1	24-Mar-00	24-Mar-00	KELMER TUTTLE FORD	400000	000000	ST01	FCSE	SP00	BA	D00	30	18-Oct-00	20	110000	07700
2001-1FTNXP0F0H000007	24.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	12-Dec-00	24-Apr-01	MCDONELL FORD, INC.	200001	000000	ST01	FCSE	SP00	BA	D00	42	2-Dec-01	0	000000	17000
2001-1FTNXP0F0H000008	200.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	1-Sep-00	20-Dec-00	PAUL CORNAC FORD, INC.	000000	000000	ST01	FCSE	SP00	BA	D01	42	21-Sep-00	10	000000	00000
2001-1FTNXP0F0H000009	113.38	TF7	TF	TBD	TCD	TE	T00	T00	A1	2-Apr-00	21-Apr-01	FORD SALES FORD	400001	000000	ST01	FCSE	SP00	BA	P00	42	29-Oct-00	0	000001	0000
2001-1FTNXP0F0H000010	80.41	TF7	TF	TBD	TCD	TE	T00	T00	A1	11-Sep-00	20-Sep-00	LACE FORD	200001	000000	ST01	FCSE	SP00	BA	D00	42	18-Sep-00	10	000000	00000
2001-1FTNXP0F0H000011	180.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	12-Feb-01	21-Apr-01	NICKOLA FORD	200001	000001	ST01	FCSE	SP00	BA	D00	42	12-Dec-00	20	100000	00000
2001-1FTNXP0F0H000012	101.00	TF7	TF	TBD	TCD	TE	T00	T00	A1	27-Mar-01	20-Mar-01	HILFMAN FORD INC	000001	000000	ST01	FCSE	SP00	BA	D00	40	20-Mar-01	0	100000	11
2001-1FTNXP0F0H000013	240.1	TF7	TF	TBD	TCD	TE	T00	T00	A1	7-May-01	21-Mar-01	BURT'S ARAPAHO FORD, INC.	410000	000000	ST01	FCSE	SP00	BA	D01	42	20-Feb-01	20	100000	00000
2001-1FTNXP0F0H000014	207.20	TF7	TF	TBD	TCD	TE	T00	T00	A1	4-Mar-01	22-Feb-01	ARCHIE COCHRANE MOTOR, INC.	000001	000100	ST01	FCSE	SP00	BA	D10	42	22-Mar-01	4	200000	0000
2001-1FTNXP0F0H000015	150.17	TF7	TF	TBD	TCD	TE	T00	T00	A1	2-Oct-00	2-Nov-00	ED WITTMER FORD LINCOLN- MERC	000001	000101	ST01	FCSE	SP00	BA	D00	42	10-Oct-00	20	110000	07000

INCL YR	VIN CD	USR_C CRT	VIN_LNK CD	MKT_D CRVDN	DOC_C AS_B1	VER_3 CD	DRIVE CD	ENCL CD	TRAN S_CD	PLAN T_CD	FROM_D T	ACTY_STA RT DT	NAME	DOC_NUM M	PL_NUM M	WCC CD	FRY NUM_1 ANL_P REF	FRY NUM_2 ALB_3 REF	FRY NUM_3 UNL_4 SUP_5 CONC_6 CD	FRY NUM_4 VOUT_5 CD	COND CD	REF_DT	TRC_NSDY	CLM_VE Y	BLCH	
2001	1FD0R8HE1H14381	1512	T07	TF	T0C	T0B	T0	T00	T0F	A1	4-Jan-01	30-Mar-01	STEVENSONS GOLDEN FORD INC	11262A	079921	STN	1CZ	0F00	0A	000	00	00	10-Jan-03	30	1011000	2000
2001	1FD0R8HE1E0893	1762	T07	TF	T0B	T0B	T0	T00	T0F	A1	19-Jan-01	25-Apr-01	HANPER MOTORS	000001	040701	STN	1CZ	0F00	0A	000	00	00	21-Mar-03	22	1010004	2001
2001	1FD0R8HE1E0820	1818	T07	TF	T0B	T0B	T0	T00	T0E	A1	22-Feb-01	21-Mar-01	BROADWAY FORD TRUCK SALES INC	000000	001040	STN	1CZ	0F00	0A	000	00	00	0-Jun-03	27	1000007	2000
2001	1FD0R8HE1E0800	4782	T07	TF	T0B	T0B	T0	T0E	T0E	A1	13-Mar-01	14-Mar-01	CAPITAL FORD INC	000001	000000	STN	1CZ	0F00	0A	000	00	00	10-Mar-01	0	000000	00
2001	2FTW02F01M00181	10606	T07	TF	T0B	T0B	T0	T0E	T0E	A2	21-Aug-00	16-Jan-01	FLY BLACK FORD LINCOLN MERCURY	070001	001010	STN	0Y2	0F00	0A	000	00	00	20-Feb-03	20	0000775	0000
2001	2FTW02F01M00009	0630	T07	TF	T0B	T0B	T0	T0E	T0E	A0	0-Jun-01	25-Jun-01	JARRETT-BEEFORD FORD	000001	000071	STN	1CZ	0F00	0A	000	00	00	0-Jun-03	10	0000004	2000
2001	2FTW02F01M00000	2730	T07	TF	T0C	T0B	T0	T00	T0E	A2	14-Jan-01	0-Jun-01	TUPRON FORD INC	11262B	000000	STN	1CZ	0F00	0A	000	00	00	27-Feb-03	0	000000	0000
2001	1FTW02F01E01074	0670	T07	TF	T0B	T0C	T0	T0E	T0E	A1	21-Aug-00	17-Mar-01	JACKY W JONES FORD INC	000000	000000	STN	0Y2	0F00	0A	000	00	00	20-Feb-03	20	0000000	0000
2001	1FTW02F01E00004	0700	T07	TF	T0B	T0C	T0	T0E	T0E	A1	01-Mar-00	21-Oct-00	CAROLBY FORD	00000A	000011	STN	0Y2	0F00	0A	000	00	00	4-Jan-03	10	000000	0000
2001	1FTW02F01E00004	10020	T07	TF	T0C	T0B	T0	T0E	T0E	A1	0-Jun-00	20-Sep-00	WATER FORD TRUCK SALES INC	00000A	000000	STN	0Y2	0F00	0A	000	00	00	10-Feb-03	27	0000007	0001
2001	1FTW02F01E00004	0000	T07	TF	T0C	T0C	T0	T0E	T0F	A1	20-Sep-00	13-Oct-00	BARRETT & WHEELER COMPANY	000001	000000	STN	0Y2	0F00	0A	000	00	00	20-Mar-03	20	0000770	0000
2001	1FTW02F01E00007	2700	T07	TF	T0C	T0C	T0	T0E	T0E	A1	0-Jan-01	21-Mar-01	LAPORCHE FORD LINCOLN MERCURY	000001	000000	STN	1CZ	0F00	0A	000	00	00	0-Jun-01	1	000000	0000
2001	1FTW02F01E00011	2011	T07	TF	T0C	T0C	T0	T0E	T0E	A1	20-Feb-01	04-Jun-01	FALL MERRY FORD MERCURY INC	000000	000000	STN	1CZ	0F00	0A	000	00	00	4-Feb-03	20	000000	0000
2001	1FTW02F01E00000	1000	T07	TF	T0C	T0C	T0	T0E	T0E	A1	4-Jan-01	20-Feb-01	FORD FORD LTD	100000	000000	STN	1CZ	0F00	0A	000	00	00	20-Feb-03	20	000000	0000
2001	1FTW02F01E00000	0000	T07	TF	T0C	T0C	T0	T0E	T0E	A1	20-Mar-01	10-Apr-01	VECTOR COMPANY	000000	000011	STN	1CZ	0F00	0A	000	00	00	7-Mar-01	0	000000	0000

PE03-044-A 5400

ACQ. YR	LN CD	LNK C DET	LNK LINE CD	ACT D	MOD C	VEN CD	OR	TRN R CD	PLAN Y CD	PRCON D	WRTY STA	NAME	DOC NU	PH LN M	MCC CD	PAID	PAID	PAID	CUST	COND	TRF DT	TRF	CLM NY	BLNE
2001	FTWWS2115C7001	81.80	TF7	TF	TBC	TCD	TR	TDR	D00	A1	21-Mar-01	GRAYHILLS FORD	381014	888001	0701	1000	0700	SA	000	20	18-Mar-01	3	381014	20
2001	FTWWS2115C7002	57.8	TF7	TF	TBC	TCD	TR	TDR	D00	A1	8-Mar-01	RAM PACKS THE STORE CO	381007	888049	0701	1000	0700	SA	000	40	18-Mar-01	4	381007	39
2001	FTWWS2115C7003	11.2	TF7	TF	TBC	TCD	TR	TDR	D00	A1	21-Mar-01	FREDSON FORD INC.	282708	870171	0701	1000	0700	SA	000	40	20-Mar-01	27	282708	40
2001	FTWWS2115C7004	111	TF7	TF	TBC	TCD	TR	TDR	D00	A1	28-Mar-01	GWINNETT PLAZA FORD	1280001	878000	0701	1000	0700	SA	001	40	4-Mar-01	25	1280001	30
2001	FTWWS2115C7005	87.21	TF7	TF	TBC	TCD	TR	TDR	D00	A1	28-Mar-01	BATCHEL MOTOR COMPANY	381001	888000	0701	1000	0700	SA	000	40	2-Mar-01	18	381001	18
2001	FTWWS2115C7006	153.8	TF7	TF	TBC	TCD	TR	TDR	D00	A1	12-Mar-01	HANPER MOTORS NEW HOLLAND FORD	381002	881011	0701	1000	0700	SA	001	40	8-Mar-01	4	381002	37
2001	FTWWS2115C7007	37.8	TF7	TF	TBC	TCD	TR	TDR	D00	A1	18-Mar-01	FORD	381000	884001	0701	1000	0700	SA	000	1	28-Mar-01	12	381000	21
2001	FTWWS2115C7008	189.29	TF7	TF	TBC	TCD	TR	TDR	D00	A1	2-Mar-01	NORTH COUNTRY FORD	381001	887100	0701	1000	0700	SA	000	40	28-Mar-01	26	381001	48
2001	FTWWS2115C7009	140.38	TF7	TF	TBC	TCD	TR	TDR	D00	A1	28-Mar-01	VALLEY FORD - MOUNTAIN LIBERTY FORD	381001	888000	0701	1000	0700	SA	000	40	14-Mar-01	26	381001	38
2001	FTWWS2115C7010	72	TF7	TF	TBC	TCD	TR	TDR	D00	A1	28-Mar-01	MICHAEL MURPHY	881001	888001	0701	1000	0700	SA	000	40	27-Mar-01	12	881001	20
2001	FTWWS2115C7011	188.88	TF7	TF	TBC	TCD	TR	TDR	D00	A1	11-Mar-01	BAMES MOTOR COMPANY, INC.	878004	781000	0701	1000	0700	SA	000	20	1-Mar-01	20	878004	30
2001	FTWWS2115C7012	44.26	TF7	TF	TBC	TCD	TR	TDR	D00	A1	7-Mar-01	JANET'S FORD FORD	118004	788071	0701	1000	0700	SA	000	40	28-Mar-01	26	118004	28
2001	FTWWS2115C7013	23.58	TF7	TF	TBC	TCD	TR	TDR	D00	A1	6-Mar-01	NORTHERN LIGHTS FORD SALES	381001	888070	0701	1000	0700	SA	000	40	10-Mar-01	26	381001	28

VEH YR	VEH CO	LIBR CO	VEH LINE CO	MKT D FRN	SEC C AB	VER S CO	GRVE CO	ENL CO	TRAM S CO	PLAN T CO	PROD D CO	WRTY STA RT	WRTY STA FT	NAME	DOC NO	PK NO	WCC CO	PART NUM P AME	PART NUM C AUL	PART NUM CA LIB	DEPT CONC CO	COND CO	SPR DT	TR WEEK	CUM MILE	REAR
2001	FORD	2001	1844	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	28-01-01	GARRETT & TOWERS COMPANY	710001	200000	STN	SCZ	WFS	BA	CAI	4	8-01-01	11	200000	1200	
2001	FORD	2001	444	TF	TBD	TBD	TB	TDS	TDF	A1	20-01-01	4-01-01	FORD MOTOR	200001	200000	STN	SCZ	WFS	AB	CAI	4	8-01-01	4	200000	200	
2001	FORD	2001	844	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	20-01-01	LITHA FORD LINCOLN MERCURY CO	111001	200000	STN	SCZ	WFS	BA	CAI	4	10-01-01	20	200000	2000	
2001	FORD	2001	1044	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	3-01-01	KULLIGER MOTOR COMPANY	804101	200100	STN	SCZ	WFS	AB	CAI	4	20-01-01	4	200000	2000	
2001	FORD	2001	4	TF	TBD	TBD	TB	TDS	TDF	A1	10-01-01	17-01-01	MERCEDES FORD, INC.	202101	200000	STN	SCZ	WFS	AB	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	20	TF	TBD	TBD	TB	TDS	TDS	A1	10-01-01	20-01-01	MERCEDES FORD	202201	200000	STN	SCZ	WFS	AB	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	1117	TF	TBD	TBD	TB	TDS	TDS	A1	10-01-01	21-01-01	MERCEDES FORD	204100	200000	STN	SCZ	WFS	BA	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	204	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	20-01-01	BOY AREA FORD, INC.	110001	200000	STN	SCZ	WFS	AB	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	104	TF	TBD	TBD	TB	TDS	TDS	A1	10-01-01	21-01-01	ALL STAR FORD	20210	200000	STN	SCZ	WFS	BA	CAI	4	10-01-01	11	200000	2000	
2001	FORD	2001	716	TF	TBD	TBD	TB	TDS	TDS	A1	3-01-01	11-01-01	REYNOLDS FORD, INC.	20210	200000	STN	SCZ	WFS	BA	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	104	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	20-01-01	BOY AREA FORD, INC.	202101	200000	STN	SCZ	WFS	BA	CAI	4	20-01-01	1	200000	200	
2001	FORD	2001	20	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	20-01-01	WORLD FORD/MERCEDES FORD	202101	200000	STN	SCZ	WFS	BA	CAI	4	20-01-01	20	200000	2000	
2001	FORD	2001	84	TF	TBD	TBD	TB	TDS	TDS	A1	20-01-01	20-01-01	DON SANDERSON FORD, INC.	202101	200000	STN	SCZ	WFS	BA	CAI	4	4-01-01	17	200000	2100	
2001	FORD	2001	20	TF	TBD	TBD	TB	TDS	TDS	A1	10-01-01	10-01-01	BOY AREA FORD, INC.	202101	200000	STN	SCZ	WFS	AB	CAI	4	20-01-01	1	200000	200	

MDL YR YR CD	USR_C OBJ	MDL LINE CD	SKT_D SERIAL	POD_C ALBL	YRLS SPR	DRIVE CD	TRQ CD	TRAM S CD	PLAM T CD	PROD T	WRTY_STA RT DT	NAME	DOC_NO M	PL_NO M	WCC CD	PAID RES C ALB P REF	PART NUM D ALB B AGE	PART OR CA LIF SUP P	CONF CONC CD	COND CD	RPR DT	TTL WRTY Y	CLM_XR MILE	MILE
20011FTM02170500000	212.70	707	TF	TBC	TBD	TE	TDS	TDS	A1	2-00-01	20-Mar-01	TULSA AUTO GROUP	8001481	200008	STD	SCZ	PF08	BA	CR	45	20-00-01	8	140000	21
20011FTM02170500000	47.8	707	TF	TBC	TBD	TE	TDS	TVP	A1	2-00-00	20-Feb-00	BELLORE MOTOR COMPANY, INC.	830700	200071	STD	SCZ	PF08	BA	CR	45	20-00-00	8	970000	1901
20011FTM02170500000	132.25	707	TF	TBC	TBD	TE	TDS	TDS	A1	20-Mar-01	19-Mar-01	MIDVALLEY FORD-MERCEURY	802401	200041	STD	SCZ	PF08	BA	CR	45	2-00-00	10	000000	2020
20011FTM02170500000	61.1	707	TF	TBC	TBD	TE	TDS	TVP	A1	1-00-00	1-00-00	REEDMOUNT FORD INC	820400	200011	STD	SCZ	PF08	BA	CR	45	20-00-00	24	100000	14000
20011FTM02170500000	100.04	707	TF	TBC	TBD	TE	TDS	TDS	A1	11-00-01	11-00-01	LEWIS FORD SALES, INC.	8002	400001	STD	SCZ	PF08	BA	CR	45	21-00-01	2	200000	6000
20011FTM02170500000	105.20	707	TF	TBC	TBD	TE	TDS	TDS	A1	11-00-00	21-00-01	BOB DAVIDSON FORD INC	810000	200000	STD	SCZ	PF08	BA	CR	1	20-00-00	20	100000	20000
20011FTM02170500000	49.21	707	TF	TBC	TBD	TE	TDS	TDS	A1	2-00-01	21-00-01	DAVE REID FORD INC-MERC	141000	200000	STD	SCZ	PF08	BA	CR	45	20-00-01	8	100000	1
20011FTM02170500000	127.8	707	TF	TBC	TBD	TE	TDS	TDS	A1	2-00-01	18-Mar-01	BANPACKS FIVE STAR FORD	800001	200010	STD	SCZ	PF08	BA	CR	45	20-00-00	20	100000	20000
20011FTM02170500000	201.37	707	TF	TBC	TBD	TE	TDS	TDS	A1	12-00-01	24-Mar-01	MILLER FORD INC MD WYTHEVILLE FORD LINCOLN-MERC	800000	200000	STD	SCZ	PF08	BA	CR	40	2-00-01	8	000000	0000
20011FTM02170500000	149.8	707	TF	TBC	TBD	TE	TDS	TVP	A1	20-Feb-01	1-00-01	FORD LINCOLN-MERC	810000	200001	STD	SCZ	PF08	BA	CR	45	21-00-01	8	000000	100
20011FTM02170500000	80.42	707	TF	TBC	TBD	TE	TDS	TVP	A1	14-00-00	20-00-00	NORUM FORD INC	3111000	200000	STD	SCZ	PF08	BA	CR	45	20-00-00	1	000000	0000
20011FTM02170500000	274.67	707	TF	TBC	TBD	TE	TDS	TDS	A1	20-00-01	20-00-01	OSWAPEN FORD KATY	200000	200000	STD	SCZ	PF08	BA	CR	45	10-00-01	02	000000	20000
20011FTM02091500000	48.3	707	TF	TBC	TBD	TE	TDS	TDS	A1	10-00-00	20-00-00	HIBBON FORD INC	200000	200000	STD	SCZ	PF08	BA	CR	25	14-00-00	20	000000	0000
20011FTM02091500000	58.78	707	TF	TBC	TBD	TE	TDS	TDS	A1	20-00-01	20-00-01	COVINT FORD OF TAYLOR, INC.	200000	200000	STD	SCZ	PF08	BA	CR	45	20-00-01	0	000000	0000
20011FTM02091500000	208.01	707	TF	TBC	TBD	TE	TDS	TDS	A1	10-00-01	20-00-01	ELK GROVE FORD	200000	200000	STD	SCZ	PF08	BA	CR	45	20-00-00	77	000000	0000

PE03-044-A 5403

VEH YR	VEH CD	UNL CD	VEN CD	MKT_D REV	SOCL ST	VEH_B CD	DRIVE CD	ENG CD	TRAN N CD	PLAN T CD	PROCD T	WRTY ST	STA UT	NAME	DOC N	PL N	WCC CD	FRY ARE F	FRY ARE B	FRY UNL CA	CUR DEMO CD	COND CD	PRC DT	DE YR	CLM Y	MLGE
2001	FTM201205A010	34	TE7	TF	7200	7200	72	7225	7275	A1	14-08-00	24-08-00		CHRYSLER FORD, INC.	1001001	000001	0701	702Z	0700	0A	000	40	2-20-00	20	000001	2100
2001	FTM201205A000	35	TE1	TF	7200	7200	72	7200	7200	A1	4-08-00	7-08-01		FAMILY FORD, INC.	100210A	440000	0701	702Z	0700	0A	000	40	1-08-00	21	000000	2000
2001	FTM201205A000	36	TE1	TF	7200	7200	72	7200	7200	A1	1-08-00	21-08-01		BETHLEHEM-BUS MITSUBI INC.	200001	000001	0701	702Z	0700	0A	001	40	20-08-01	2	000000	1700
2001	FTM201205A000	34	TE1	TF	7200	7200	72	7200	7200	A1	23-08-00	4-09-01		DELTA FORD, INC.	2007201	00-0000	0701	702Z	0700	0A	000	40	14-08-00	15	112000	2000
2001	FTM201205A000	47	TE1	TF	7200	7200	72	7200	7200	A1	12-08-00	20-08-01		LAKE ELMORE FORD INC.	00000A	070100	0701	702Z	0700	0A	000	40	14-08-00	27	000000	2100
2001	FTM201205A000	36	TE1	TF	7200	7200	72	7200	7200	A1	22-08-00	25-08-01		BERKE FORD	1000000	000100	0701	702Z	0700	0A	000	20	12-08-01	2	210000	0000
2001	FTM201205A010	70	TE1	TF	7200	7200	72	7200	7200	A6	20-08-00	20-08-00		GENE-STEV FORD CORPORATION	0000001	000000	0701	702Z	0700	0A	000	40	20-08-00	20	000000	2000
2001	FTM201205A000	00	TE7	TF	7200	7200	72	7200	7200	A1	11-08-01	27-08-01		FORD	000000A	000000	0701	702Z	0700	0A	000	40	11-08-01	0	200000	2000
2001	FTM201205A000	14	TE7	TF	7200	7200	72	7200	7200	A1	11-08-00	20-08-00		ARAZEL FORD	000000A	000100	0701	702Z	0700	0A	000	40	10-08-00	20	000000	1000
2001	FTM201205A001	46	TE7	TF	7200	7200	72	7200	7200	A1	12-08-00	14-08-00		OMEGA FORD, INC.	0007001	700000	0701	702Z	0700	0A	000	40	22-08-01	12	000000	0000
2001	FTM201205A000	20	TE7	TF	7200	7200	72	7200	7200	A1	10-08-00	20-08-00		EMERSON FORD MERCURY INC.	0000001	000000	0701	702Z	0700	0A	000	40	20-08-00	10	000000	1100
2001	FTM201205A000	30	TE7	TF	7200	7200	72	7200	7200	A1	8-08-00	1-09-00		FRUIT FORD, LLC	1100000	000000	0701	702Z	0700	0A	001	20	8-08-00	27	000000	0700

INCL YR	YR	CD	UNCL LINE DET	LINE CD	ACT_D DEPT	BOO_C AL	VEN_P AL	DRIVE CD	ENR CD	TRAN S_CD	PLAK T_CD	PRCFLD 7	HWY STA	STA RT	NAME	DOC N	PL N	MOC CD	PART NUM L	PART NUM P	PART NUM R	UNL CA	CUST CD	COMD CD	WFR DT	TIR WFR	CLA N	BLGE			
2001	1	F	284	177	TF	TDR	TCD	TF	TDR	TDR	A1	18-Mar-01	2-Jul-01	VALLEY FORD MERCURY, INC.	000001	000001	0001	1000	0000	0000	00	000	00	00	00	00	00	00	00		
2001	1	F	285	177	TF	TDR	TCD	TF	TDR	TDR	A1	18-Mar-01	14-Aug-01	HENRIZELAND TRUCK CENTER INC	000004	000000	0001	1000	0000	0000	00	000	00	00	00	00	00	00	00	00	
2001	1	F	286	177	TF	TDR	TCD	TF	TDR	TDR	A1	18-Mar-01	14-Sep-01	NORTHWEST FORD TRUCK CENTER INC	000005	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	287	177	TF	TDR	TCD	TF	TDR	TDR	A1	14-Mar-01	29-Jun-01	SPIRITLAND, INC.	000006	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	288	177	TF	TDR	TCD	TF	TDR	TDR	A1	18-Feb-01	7-Aug-01	DAN SPRINGER FORD/BUICK/OLDSMOBILE INC	000007	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	289	177	TF	TDR	TCD	TF	TDR	TDR	A1	28-Sep-00	1-Dec-00	RED BUSH FORD	000008	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	290	177	TF	TDR	TCD	TF	TDR	TDR	A1	29-Jan-01	19-Dec-01	SPIN CITY FORD S. BOON MERCURY	100009	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	00
2001	1	F	291	177	TF	TDR	TCD	TF	TDR	TDR	A1	18-Jan-01	17-Aug-01	ARMER FORD, INC.	000010	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	292	177	TF	TDR	TCD	TF	TDR	TDR	A1	21-Feb-01	7-Aug-01	PRE LOAN FORD OF CHRYSLER, LLC	000011	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	293	177	TF	TDR	TCD	TF	TDR	TDR	A1	27-Mar-01	17-Sep-01	ATLANTIC FORD TRUCK SALES, INC	000012	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	294	177	TF	TDR	TCD	TF	TDR	TDR	A1	24-Feb-01	14-Sep-01	AMBI FORD CORPORATION	000013	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	295	177	TF	TDR	TCD	TF	TDR	TDR	A1	2-Feb-01	18-Mar-01	NICHOLS FORD ATLANTIC FORD	000014	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	1	F	296	177	TF	TDR	TCD	TF	TDR	TDR	A1	22-Mar-01	22-Jun-01	ATLANTIC FORD TRUCK SALES, INC	000015	000000	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	2	F	297	177	TF	TDR	TCD	TF	TDR	TDR	A1	22-Jan-00	28-Sep-01	BUICK FORD MOTOR INC.	000016	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	
2001	2	F	298	177	TF	TDR	TCD	TF	TDR	TDR	A1	28-Jan-01	21-Jun-01	PROVIDA FORD MERCURY	000017	000001	0001	1000	0000	0000	00	000	00	000	00	00	00	00	00	00	

DEL. VR	DEL. VR CD	LIBR. D. CDT	VEH. LINE CD	ACT. D. CD	MOD. C. AS. STL.	VEH. B. ENCL. CD	DRIVE. CD	ENCL. CD	TRAM. B. CD	PLAN. Y. CD	PRICED. D. IT	WRTY. STA. RT. DT	NAME	DOC. NU. Y	PH. NU. M	WOC. CD	FOR. RES. D. AS. L. P. TSP	FOR. RES. D. AS. L. D. OBE	FOR. RES. D. AS. L. CA. T	DEPT. CONC. CD	COND. CD	APP. DT	TBL. NEED. Y	CL. USE	MS. AM
2001	3FT3W41F01M400000	241.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	20-00-01	2-02-01	LARCO FORD, INC.	200410	000000	0701	1002	0700	0A	000	11	20-00-01	0	007001	0000
2001	3FT3W41F01M400000	280.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	22-00-01	12-00-01	BLUTE'S APPLANCE FORD, INC.	000070	000000	0701	1002	0700	0A	000	01	20-00-01	0	000000	0000
2001	3FT3W41F01M400000	37.0	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	10-00-00	25-00-01	WILSON MOTORS	077700	000000	0701	1002	0700	0A	000	00	0-00-00	00	000000	0000
2001	3FT3W41F01M400000	60.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	0-00-01	0-00-01	TELLAMOOK MOTOR COMPANY	000000	000000	0701	1002	0700	0A	000	00	00-00-00	00	000000	0000
2001	3FT3W41F01M400000	60.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	0-00-01	0-00-01	TELLAMOOK MOTOR COMPANY	000000	000000	0701	1002	0700	0A	000	00	00-00-00	00	000000	0000
2001	3FT3W41F01M400000	60.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	0-00-01	0-00-01	TELLAMOOK MOTOR COMPANY	000000	000000	0701	1002	0700	0A	000	00	00-00-00	00	000000	0000
2001	3FT3W41F01M400000	112.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	0-00-01	0-00-01	ROMANA MOTOR COMPANY	010070	000000	0701	1002	0700	0A	000	00	1-00-00	00	000000	0000
2001	3FT3W41F01M400000	100.17	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	21-00-01	0-00-01	FRLEY FORD, LLC	100000	000000	0701	1002	0700	0A	000	00	17-00-01	0	000000	00
2001	3FT3W41F01M400000	71.17	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	21-00-01	11-00-01	NORTHLAKE FORD-MERCLAY	000070	000000	0701	1002	0700	0A	000	00	20-00-00	00	000000	0000
2001	3FT3W41F01M400000	14.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	21-00-01	14-00-01	SEARHARBY FORD SALES COMPANY	000000	000000	0701	1002	0700	0A	000	00	12-00-00	00	000000	0000
2001	3FT3W41F01M400000	27.0	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	20-00-00	1-00-01	BILL HOLY FORD, INC.	000000	000000	0701	1002	0700	0A	000	00	20-00-01	0	000000	0000
2001	3FT3W41F01M400000	22.70	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	18-00-00	18-00-01	REIDMAN AUTO CENTER INC	000000	000000	0701	1002	0700	0A	000	00	00-00-00	00	000000	0000
2001	3FT3W41F01M400000	60.00	T07	T07	T0C	T0D	T0E	T0E	T0E	A2	10-00-01	21-00-01	FOLSOMLAKE FORD INC	000000	000000	0701	1002	0700	0A	000	00	20-00-00	00	000000	0000
2001	3FT3W41F01M400000	00.15	T07	T07	T0C	T0D	T0E	T0E	T0E	A1	20-00-01	00-00-01	COLUMBIE FORD, INC.	000000	000000	0701	1002	0700	0A	000	00	18-00-00	00	000000	0000

PE03-04-A 5406

ANL YR	VM CO	REF C DST	VDL LINE CD	TRF D REV	BOG C AS ST	VEH L BRN CO	DRIVE CO	ENG CO	TRAN S CD	PLAN T CD	PROOK D T	TRFV STA RT	NAME	DOC_NO M	PLA_NO M	BCC CD	FRG PAUL ASE	FRG PAUL ASE	FRG PAUL ASE	CURT CUR	COND CD	TRF DT	TRF AMO Y	CLAI KE Y	AMT
0001	1212001P1810888	24.81	1777	TF	TBC	TCD	TE	TCR	TDF	A1	2-00-90	20-00-90	AGRE COUNTY WOODS, NC.	488801	000000	STD	YCK	SPM	BA	000	41	4-00-91	12	448801	2024
0001	1212001P1810895	388.3	1777	TF	TBC	TCD	TE	TCR	TDF	A1	20-00-90	10-00-90	FORD OF WISCONSIN	448801	000000	STD	YCK	SPM	BA	000	41	20-00-91	17	448801	2020
0001	1212001P1810902	41.28	1777	TF	TBC	TCD	TE	TCR	TDF	A1	11-00-90	20-00-90	SOLTON FORD, NC.	1262731	014000	STD	YCK	SPM	BA	000	41	10-00-90	20	100000	0100
0001	1212001P1810909	99.08	1777	TF	TBC	TCD	TE	TCR	TDF	A1	12-00-91	24-00-91	THEBELL FORD-INDIANA	000000	000000	STD	YCK	SPM	BA	000	41	12-00-90	20	000000	0000
0001	1212001P1810916	81.61	1777	TF	TBC	TCD	TE	TCR	TDF	A1	20-00-90	12-00-90	SANTA MARGARITA FORD	220000	000000	STD	YCK	SPM	BA	000	41	10-00-90	14	000000	0000
0001	1212001P1810923	55.4	1777	TF	TBC	TCD	TE	TCR	TDF	A1	20-00-91	20-00-91	WELLS FORD, NC.	201000	000000	STD	YCK	SPM	BA	000	41	20-00-90	08	100000	0000
0001	1212001P1810930	98.22	1777	TF	TBC	TCD	TE	TCR	TDF	A2	20-00-91	20-00-91	WELLS FORD	120000	000000	STD	YCK	SPM	BA	000	41	20-00-90	02	200000	0000
0001	1212001P1810937	70.97	1777	TF	TBC	TCD	TE	TCR	TDF	A1	11-00-91	21-00-91	SOUTH FORD FORD	000000	000000	STD	YCK	SPM	BA	000	41	12-00-91	7	000000	0000
0001	1212001P1810944	94.4	1777	TF	TBC	TCD	TE	TCR	TDF	A1	2-00-91	21-00-91	ALL-STATE FORD TRUCK SALES, IN	000000	000000	STD	YCK	SPM	BA	000	41	20-00-90	24	000000	0000
0001	1212001P1810951	104.00	1777	TF	TBC	TCD	TE	TCR	TDF	A1	10-00-90	20-00-90	WILLIAMS FORD, LINCOLN, MASSACHUSETTS	000000	000000	STD	YCK	SPM	BA	000	41	2-00-91	1	000000	0000
0001	1212001P1810958	47.01	1777	TF	TBC	TCD	TE	TCR	TDF	A1	14-00-90	14-00-90	WAGNER AUTOPLEX OF BETHLEHEM, L. PENNSYLVANIA FORD-INDIANA	100001	000000	STD	YCK	SPM	BA	000	41	15-00-90	02	100000	0000
0001	1212001P1810965	84.8	1777	TF	TBC	TCD	TE	TCR	TDF	A1	1-00-90	13-00-91	WELLS FORD-INDIANA	000000	000000	STD	YCK	SPM	BA	000	41	11-00-90	20	000000	0000
0001	1212001P1810972	74.61	1777	TF	TBC	TCD	TE	TCR	TDF	A1	21-00-91	21-00-91	JOHNSON FORD-INDIANA	100000	000000	STD	YCK	SPM	BA	000	41	20-00-91	4	200000	0000
0001	1212001P1810979	30.01	1777	TF	TBC	TCD	TE	TCR	TDF	A1	5-00-90	10-00-90	NORTHEAST FORD-INDIANA	000000	000000	STD	YCK	SPM	BA	000	41	11-00-91	4	100000	0000
0001	1212001P1810986	20.17	1777	TF	TBC	TCD	TE	TCR	TDF	A1	10-00-91	24-00-91	CHRYSLER FORD	100000	000000	STD	YCK	SPM	BA	000	41	10-00-90	24	000000	0000

PE03-044-A 5407

DEL YR	YR CD	LNH DET	LNH CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD	DEL CD
2001	FTW02074180000000	1241	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	1459	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	1668	TF4	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	1877	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	2086	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	2295	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	2504	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	2713	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	2922	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	3131	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	3340	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	3549	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	3758	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	3967	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC
2001	FTW02074180000000	4176	TF7	TF	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC	TRC

DEL TR	YR CD	LBR_G DST	MRK LINE CD	WGT_D PROVD	DOC_C AS STL	VER_S SERIES CD	DRIVE CD	TRNS CD	TRNS BL CD	PLAN T CD	PRDMLD T	MRTY_STA RT ST	NAME	DOC_HU IN	PL_HU IN	WCOL CD	PART NUM_P REF	PART NUM_P REF	PART NUM_P REF	CURR COND CD	COND CD	WPL_DT	TTL WPLDT	CLM_KM	MILE
3001	1FTW021P18A4005	84.7	787	7F	780	780	7E	708	708	A1	18-Apr-01	18-Apr-01	DALE JARRETT FORD	1788301	2338301	87H1	781Z	8F88	8A	788	28	20-Mar-01	201188891	2821	
3001	1FTW021P18A4004	84.72	787	7F	780	780	7E	708	708	A1	4-Oct-01	28-Oct-01	FLUMBER TRUCK CENTER	2084524	3323301	87H1	781Z	8F88	8A	788	43	16-May-01	211870000	3026	
3001	1FTW021P118D1747	84.8	787	7F	780	780	7E	708	708	A1	22-Apr-01	14-Apr-01	ALL-STATE FORD TRUCK SALES, IN	2291182	8883301	87H1	781Z	8F88	8A	788	42	18-Mar-01	201433074	3016	
3001	1FTW021P118D2067	45.8	787	7F	780	780	7E	708	708	A1	28-Mar-01	14-Mar-01	HOUSTON FORD, INC.	1304880	8034418	87H1	781Z	8F88	8A	788	40	18-Mar-01	201324438	2714	
3001	1FTW021P118A0011	38	787	7F	780	780	7E	708	708	A1	4-Oct-01	28-Oct-01	PRESTON FORD WELLS FORD SALES	8884001	8883301	87H1	781Z	8F88	8A	788	43	2-Apr-01	201821582	3008	
3001	1FTW021P118A0011	24.2	787	7F	780	780	7E	708	708	A1	12-Mar-01	4-Oct-01		20181	7883301	87H1	781Z	8F88	8A	788	40	28-Mar-01	61191748	1088	
3001	1FTW021P118A0008	84.88	787	7F	780	780	7E	708	708	A1	7-Sep-01	26-Jun-01	REGENCY FORD	7883301	8124113	87H1	781Z	8F88	8A	788	42	8-Mar-01	201427083	2737	
3001	1FTW021P118A0005	84.88	786	7F	780	780	7E	708	708	A1	18-Jun-01	12-Apr-01	JEFF SCHNEER FORD, INC.	878484	8883301	87H1	781Z	8F88	8A	788	42	10-Mar-01	121888884	2885	
3001	1FTW021P118A0008	84.88	787	7F	780	780	7E	708	708	A1	24-Mar-01	28-Apr-01	LAWRENCE HARRIS FORD- MERCURY	8888800	8883301	87H1	781Z	8F88	8A	788	28	20-Mar-01	141893370	2678	
3001	1FTW021P118A0008	28.4	787	7F	780	780	7E	708	708	A1	24-Mar-01	13-Mar-01	YOUNG FORD, INC.	8871301	8883301	87H1	781Z	8F88	8A	788	28	20-Mar-01	10189194	488	
3001	1FTW021P118A0011	84.0	787	7F	780	780	7E	708	708	A1	17-Oct-01	24-Sep-01	HALLER FORD- MERCURY	2188301	4787301	87H1	781Z	8F88	8A	788	42	18-Mar-01	221844817	3028	
3001	1FTW021P118A0000	21.88	787	7F	780	780	7E	708	708	A1	8-Oct-01	28-Apr-01	TRIMER FORD- LINDEN-MERCURY INC.	7814184	4823301	87H1	781Z	8F88	8A	788	42	2-Mar-01	7188888	2788	
3001	1FTW021P118A0000	16.81	787	7F	780	780	7E	708	708	A1	8-Oct-01	18-Oct-01	FOR BLACKWELL FORD INC.	8883301	3383301	87H1	781Z	8F88	8A	788	42	18-Mar-01	4188888	1881	
3001	1FTW021P118A0008	26.28	787	7F	780	780	7E	708	708	A1	8-Oct-01	21-Apr-01	AL PALLADINI FORD TRUCK FORD	8883301	388777	87H1	781Z	8F88	8A	788	1	22-Mar-01	201408888	2604	
3001	1FTW021P118A0000	27	787	7F	780	780	7E	708	708	A1	18-Mar-01	18-Mar-01	MADE FORD, INC.	7883301	4383301	87H1	781Z	8F88	8A	788	42	27-Mar-01	271888881	3181	
3001	1FTW021P118A0011	17.08	787	7F	780	780	7E	708	708	A1	14-Oct-01	28-Oct-01	LAMBERT MOTORS TRUCK LTD.	7888	887884	87H1	781Z	8F88	8A	788	42	14-Mar-01	7188888	2888	
3001	1FTW021P118A0000	24.54	787	7F	780	780	7E	708	708	A1	28-Mar-01	27-Oct-01	GREENWOOD FORD CONVENTION MOTOR CORP.	188888	288881	87H1	781Z	8F88	8A	788	52	28-Mar-01	13188888	3088	
3001	1FTW021P118A0000	11.88	787	7F	780	780	7E	708	708	A1	28-Mar-01	17-Mar-01		217888	888881	87H1	781Z	8F88	8A	788	1	11-Mar-01	1418888	1488	

REL_YR	VIN_CD	WPLD_L	WPLD_R	WPLD_C	WPLD_S	WPLD_E	WPLD_O	WPLD_P	WPLD_Q	WPLD_T	WPLD_U	WPLD_V	WPLD_W	WPLD_X	WPLD_Y	WPLD_Z	WPLD_AA	WPLD_AB	WPLD_AC	WPLD_AD	WPLD_AE	WPLD_AF	WPLD_AG	WPLD_AH	WPLD_AI	WPLD_AJ	WPLD_AK	WPLD_AL	WPLD_AM	WPLD_AN	WPLD_AO	WPLD_AP	WPLD_AQ	WPLD_AR	WPLD_AS	WPLD_AT	WPLD_AU	WPLD_AV	WPLD_AW	WPLD_AX	WPLD_AY	WPLD_AZ
2001	1FTMWS221E24282	184	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	21-Dec-80	21-Feb-81	JAGRE FORD CORPORATION	79580	272208	ST1	1C3Z	8F38	BA	D8	48	25-Mar-81	15	888448	3288																
2001	1FTMWS221E24282	184	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	18-Dec-80	44-Mar-81	BROWN BRO FORD SALES & SER	117804	272208	ST1	1C3Z	8F38	BA	D8	48	24-Mar-81	14	871284	1817																
2001	1FTMWS221E24282	220	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	7-Dec-80	2-Mar-81	BUTTERFIELD FORD	788707	222241	ST1	1C3Z	8F38	BA	D8	48	1-Mar-81	8	101671	27																
2001	1FTMWS221E24282	318	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	2-Mar-81	22-Mar-81	CUMMINS MOTOR LTD	232201	222278	ST1	1C3Z	8F38	BA	D8	38	4-Mar-81	18	272208	1828																
2001	1FTMWS221E24282	248	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	17-Mar-81	22-Mar-81	TEVON EASLER FORD INC.	182280	222281	ST1	1C3Z	8F38	BA	D8	1	18-Mar-81	17	107208	2282																
2001	1FTMWS221E24282	212	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	8-Mar-81	21-Dec-80	SAV DENO POLICE - BENTON SA	222201		ST1	1C3Z	8F38	BA	D8	48	19-Mar-81	20	142208	2227																
2001	1FTMWS221E24282	248	784	TF	TBC	TCD	TR	TDS	TDP	TDP	AA	4-Mar-81	22-Mar-81	AL BILTON FORD, INC.	142201	222152	ST1	1C3Z	8F38	BA	D8	41	4-Mar-81	19	122208	1842																
2001	1FTMWS221E24282	274	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	19-Mar-81	22-Mar-81	GRIFITH FORD, INC.	242201	272208	ST1	1C3Z	8F38	BA	D8	1	4-Mar-81	8	772201	1678																
2001	1FTMWS221E24282	184	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	15-Mar-81	22-Mar-81	WEST-HERR FORD, INC.	142201	242208	ST1	1C3Z	8F38	BA	D8	48	26-Mar-81	18	1017208	2224																
2001	1FTMWS221E24282	148	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	19-Mar-81	22-Mar-81	BROWN BRO FORD SALES (IND) LTD	222201	222152	ST1	1C3Z	8F38	BA	D8	48	22-Mar-81	11	222208	2228																
2001	1FTMWS221E24282	248	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	20-Mar-81	22-Mar-81	PERFORMANCE FORD	272201	222152	ST1	1C3Z	8F38	BA	D8	38	15-Mar-81	18	122208	4088																
2001	1FTMWS221E24282	104	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	17-Dec-80	44-Mar-81	BANNER FORD	222201	222278	ST1	1C3Z	8F38	BA	D8	48	10-Dec-80	10	112208	3042																
2001	1FTMWS221E24282	484	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	28-Dec-80	28-Mar-81	HLS CITY FORD, INC.	272201	222152	ST1	1C3Z	8F38	BA	D8	42	12-Mar-81	24	122208	1744																
2001	1FTMWS221E24282	788	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	2-Jan-81	21-Dec-80	CROWFOOT FORD SALES LIMITED	222201	222118	ST1	1C3Z	8F38	BA	D8	42	2-Jan-81	8	122208	1428																
2001	1FTMWS221E24282	184	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	21-Mar-81	24-Mar-81	WINDYVILLE FORD WESTBRO FORD	182201	222208	ST1	1C3Z	8F38	BA	D8	38	21-Mar-81	4	122208	2228																
2001	1FTMWS221E24282	788	787	TF	TBC	TCD	TR	TDS	TDP	TDP	A1	18-Mar-81	8-Apr-81	WINDYVILLE FORD WESTBRO FORD	182201	222208	ST1	1C3Z	8F38	BA	D8	48	18-Mar-81	11	122208	2228																

PE03-044-A 5410

MODEL YR	VIN	CO	MPG	LITRE	WHL	ACT_D	MOD_C	WHL_B	DRIVE	WHL	TRAN	PLAN	PRDGLD	WHTY	STA	NAME	DOC	PH	WTD	FRNT	PRIC	WHL_C	COL	CLST	CONG	REG	TOL	CLAUZE	MLSE
2001	1FTNWS20912E481870	75	797	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	3-AUG-01	100048	170000	200001	FORD CITY FORD INC.	490001	000000	5101	1CSE	0700	BA	000	48	1-MAY-01	7	180000	1700	
2001	1FTNWS20912E481449	200	797	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	21-JAN-01	11-14-01	170000	200001	TED HUBBELL FORD INC.	257201	000001	5101	1CSE	0700	BA	000	28	21-JAN-01	0	140000	0	
2001	1FTNWS20912E481018	200	797	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	21-JAN-01	21-14-01	170000	200001	MURRAY FORD CO. INC.	212201	770000	5101	1CSE	0700	BA	000	31	12-NOV-00	17	180000	2100	
2001	1F3BLLSP818D04874	46	75.1	TF	TBD	TBD	TB	TDB	TDB	TDB	A1	20-MAR-01	2-24-01	200000	200001	PERAZE FORD-MERCURY, INC.	241201	000001	5101	1CSE	0700	BA	002	1	2-MAR-01	25	140000	5070	
2001	1FD0C428218E20708	20	81	TF	TBD	TDB	TB	TDB	TDB	TDB	A1	18-JAN-01	12-14-01	170000	200001	LEGACY FORD MERCURY	101201	010000	5101	1CSE	0700	BA	000	49	18-JAN-01	2	210000	0000	
2001	1FD0W428218E201705	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	12-FEB-01	20-14-01	170000	200001	CAPITAL MOTORS FORD/LTD	121001	100000	5101	1CSE	0700	BA	000	42	2-MAR-01	8	200000	1400	
2001	1FD0W428218E201597	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	12-OCT-00	18-14-01	170000	200001	BILL COLLINS FORD INC.	180000	000000	5101	1CSE	0700	BA	000	41	23-JAN-01	27	127000	0000	
2001	1FD0W428218E201017	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	2-JAN-01	12-14-01	170000	200001	MILBURN FORD INC. CLARK FORD SALES LTD	120101	000001	5101	1CSE	0700	BA	000	48	2-JAN-01	7	000000	1400	
2001	1FD0W428218E201018	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	27-MAR-00	25-14-01	170000	200001	MILBURN FORD INC. CLARK FORD SALES LTD	041001	000001	5101	1CSE	0700	BA	000	1	12-MAR-01	8	000000	0000	
2001	1FD0W428218E201002	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	20-OCT-00	27-OCT-00	170000	200001	TOM DENEME FORD COUNTY MOTOR FORD	201001	000001	5101	1CSE	0700	BA	000	1	11-JAN-01	18	000000	0000	
2001	1FD0W428218E201000	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	2-OCT-00	2-14-01	170000	200001	SHANE LTD SOUTH COUNTY MOTOR CO. INC.	020101	000001	5101	1CSE	0700	BA	000	48	23-JAN-01	27	000000	0000	
2001	1FD0W428218E201012	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	2-JAN-01	20-14-01	170000	200001	SOUTH COUNTY MOTOR CO. INC.	170001	000001	5101	1CSE	0700	BA	000	48	4-MAR-01	18	000000	0000	
2001	1FD0W428218E201001	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	14-MAR-00	17-MAR-01	170000	200001	SOUTH COAST FORD	120001	000001	5101	1CSE	0700	BA	000	41	2-MAR-01	12	121000	1200	
2001	1FD0W428218E201003	20	85	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	4-JAN-01	12-JAN-01	170000	200001	BRANDON FORD FOR FORD SALES LIMITED	200001	000000	5101	1CSE	0700	BA	000	41	19-JAN-01	12	000000	0000	
2001	1FTNWS20912E481012	18	87	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	12-JAN-01	2-14-01	170000	200001	BRANDON FORD FOR FORD SALES LIMITED	400001	000000	5101	1CSE	0700	BA	000	49	12-JAN-01	8	000000	1200	
2001	1FTNWS20912E481014	200	81	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	2-JAN-01	8-FEB-01	170000	200001	BOB LYNCH FORD INC.	000111	000000	5101	1CSE	0700	BA	000	42	28-MAR-01	18	000000	0000	
2001	1FTNWS20912E481019	20	87	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	14-MAR-01	12-JAN-01	170000	200001	WASHINGTON FORD, MERCURY, INC.	120201	000001	5101	1CSE	0700	BA	000	42	21-JAN-01	2	000000	0000	
2001	1FD0W428218E201011	20	87	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	22-FEB-01	22-MAR-01	170000	200001	BELO MOTOR SALES	200201	000001	5101	1CSE	0700	BA	000	48	2-OCT-00	21	000000	1400	
2001	1FTNWS20912E481013	20	87	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	22-MAR-01	12-OCT-01	170000	200001	MILBURN FORD INC. L.C. WILLIAMS	210101	000001	5101	1CSE	0700	BA	000	41	23-JAN-01	17	000000	1200	
2001	1FTNWS20912E481018	20	87	TF	TBC	TBD	TB	TDB	TDB	TDB	A1	2-SEP-00	22-MAR-01	170000	200001	MILBURN FORD INC. L.C. WILLIAMS	401001	000000	5101	1CSE	0700	BA	000	42	28-MAR-01	26	000000	7700	

PE03-044-A 5411

MODEL	YEAR	VEH	AMT	SOCL	VEH	DRIVE	ENG	TRAN	PLAN	PRODN	WKTY	NAME	DOC	PH	SEC	PRC	PRC	PRC	CURT	COND	PRC	TR	CLM	BLANK	
YR	VEH	CD	CD	AB	CD	CD	CD	CD	T	D	ST		NO	NO	CD	ALB	ALB	ALB	CD	CD	CD	WSD	NO		
2001	1F79W91F2A600205	20.30	T07	TF	T0C	T0C	T0E	T0B	A1	10-Oct-01	20-Nov-01	DON SANDERSON FORD, INC.	0720001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F2A600205	20.30	T07	TF	T0C	T0C	T0E	T0B	A1	10-Oct-01	21-Oct-01	FORD, INC.	100100A	000010	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F2A600205	01.20	T07	TF	T0C	T0C	T0E	T0B	A1	10-Oct-01	20-Sep-01	FORD, INC.	000000A	*	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	000.77	T07	TF	T0C	T0C	T0E	T0B	A1	1-MAR-01	10-MAR-01	CAPSTRAND FORD	0700101	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	001.04	T07	TF	T0C	T0C	T0E	T0B	A1	17-Oct-01	0-Nov-01	DON SANDERSON FORD, INC.	0700001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	100.4	T07	TF	T0B	T0C	T0E	T0B	A1	11-Sep-01	20-SEP-01	BARAT FORD FORD, INC.	1000001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	100.07	T07	TF	T0C	T0C	T0E	T0B	A1	0-Apr-01	24-Apr-01	FRIENDLY FORD, INC.	000000A	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	00.14	T07	TF	T0C	T0C	T0E	T0B	A1	12-Feb-01	2-Mar-01	MANVILLE FORD	0000001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	01.00	T07	TF	T0C	T0C	T0E	T0B	A1	23-Sep-01	20-Sep-01	FOREST CITY FARM FORD CO INC	000000	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	00.00	T07	TF	T0C	T0C	T0E	T0B	A1	0-Feb-01	2-Feb-01	MARTY FRANCHI FORD LINCOLN-MER	0000001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	000.1	T07	TF	T0C	T0C	T0E	T0B	A1	00-Mar-01	10-Mar-01	FALLONER FORD OF SOLDIERSON	000000A	000000	0701	1002	0700	0A	000	00	00	00	00	00	00
2001	1F79W91F18000000	00.10	T07	TF	T0C	T0C	T0E	T0B	A1	20-Oct-01	20-Nov-01	TOM BRANCHI FORD COUNTRY	0000001	000000	0701	1002	0700	0A	000	00	00	00	00	00	00

PRO3-044-A 5412

NEC TR	VER CD	USR_C OBT	VER_L CD	ACT_D SERVED	SECT_C AN STI	VER_L CD	DWNS CD	SECT_C CD	TRAN BL CD	PLAN T CD	PROG_D T	WRTY_STA RT DT	NAME	DOC_NO M	PH_NO M	TRCC CD	PROJ AUE_P SER	PROJ AUE_P ANE	PROJ UR_SUP F	CURT COIC CD	COND CD	RPL DT	TR MST	CAL_M T	MS00
2001	1PTBCH1P0SEC077	10770	1077	TF	TSD	TSD	TE	TSD	T07	A1	21-09-01	23-09-01	PRR LONG FORD LLC	2002002	2002001	0701	TCZ	SP00	BA	001	01	22-09-02	20	1000000	0000
2001	1PTBCH1P0SEC088	8105	1077	TF	TSD	TSD	TE	TSD	T08	A1	10-09-00	20-09-00	BROADWAY FORD, INC	2002001	2002001	0701	TCZ	SP00	BA	001	01	20-09-01	20	1000000	0000
2001	1PTBCH1P0SEC089	1700	1077	TF	TSC	TSD	TE	TSD	T08	A1	17-09-01	4-10-01	PERI SUPPLY CORP	2002001	2002001	0701	TCZ	SP00	BA	001	01	5-09-01	18	1101400	0000
2001	1PTBCH1P0SEC090	8100	1077	TF	TSC	TSD	TE	TSD	T08	A1	2-09-01	17-09-01	POWERSY ACTIONS	2002001	2002001	0701	TCZ	SP00	BA	001	01	18-09-01	18	1000000	0000
2001	1PTBCH1P0SEC091	8100	1077	TF	TSC	TSD	TE	TSD	T08	A1	11-09-01	25-09-01	GRAND VALLEY FORD-LINCOLN CORP	2002001	2002001	0701	TCZ	SP00	BA	001	01	2-09-01	18	800400	0000
2001	1PTBCH1P0SEC092	8100	1077	TF	TSC	TSD	TE	TSD	T08	A1	2-09-01	2-09-01	SMITHSON FORD	2002001	2002001	0701	TCZ	SP00	BA	001	01	25-09-01	18	800000	0000
2001	1PTBCH1P0SEC093	51	1011	TF	TWD	TSD	TE	TSD	T08	A1	1-09-00	20-09-00	CRYSTAL FORD LTD	2002001	2002001	0701	TCZ	SP00	AA	001	01	16-09-01	18	800000	0000
2001	1PTBCH1P0SEC094	1020	1011	TF	TWD	TSD	TE	TSD	T08	A1	4-09-01	29-09-01	FALL SPRING FORD	2002001	2002001	0701	TCZ	SP00	BA	001	01	2-09-01	18	800000	0000
2001	1PTBCH1P0SEC095	2071	1077	TF	TSD	TSD	TE	TSD	T07	A1	17-09-01	24-09-01	HILL HOLLOWDALE FORDLINE CORP	2002001	2002001	0701	TCZ	SP00	BA	001	01	20-09-01	20	1000000	0000
2001	1PTBCH1P0SEC096	2082	1077	TF	TSD	TSD	TE	TSD	T08	A1	24-09-01	10-10-01	LA FORTE FORD	2002001	2002001	0701	TCZ	SP00	BA	001	01	1-09-01	20	1000000	0000
2001	1PTBCH1P0SEC097	1010	1064	TF	TSD	TSD	TE	TSD	T08	AN	18-09-01	20-09-01	WELLSVILLE FORD LINCOLN BULL LTD	2002001	2002001	0701	TCZ	SP00	AA	001	01	20-09-01	8	400000	0000
2001	1PTBCH1P0SEC098	2081	1077	TF	TSD	TSD	TE	TSD	T08	A1	21-09-01	28-09-01	JOE ALLEN FORD, INC	2002001	2002001	0701	TCZ	SP00	BA	001	01	19-09-01	18	800000	0000
2001	1PTBCH1P0SEC099	240	1077	TF	TSD	TSD	TE	TSD	T08	A1	18-09-01	18-09-01	BUTCH GUNDALET INC	2002001	2002001	0701	TCZ	SP00	BA	001	01	18-09-01	14	1000000	0000
2001	1PTBCH1P0SEC100	2081	1077	TF	TSC	TSD	TE	TSD	T07	A1	25-09-01	27-09-01	HERBERT MCCARTHY FORD INC	2002001	2002001	0701	TCZ	SP00	BA	001	01	7-09-01	11	800000	0000

PE03-044-A 5413

REL. TR. VIN CD	ACT. C. CRT	ACT. D. CD	ACT. D. BRN	WGL. C. AS. STI	VER. B. EXP. CD	DRIVE. CD	ENCL. CD	TRAN. S. CD	PLAN. T. CD	FRONK. D. T	INVT. STA. RT. ST	NAME	DOC. ALI. IN	PL. IN. M	WCC. CD	FRY. A. HURL. AURL. P. RMP	FRY. A. HURL. AURL. B. AURL. P. RMP	FRY. A. HURL. CA. AURL. B. AURL. P. RMP	COM. COING. CD	COMD. CD	WPR. DT	TR. MTDY	CLM. J2	ML. OF
20011F0004971E80004	7149	TF7	TF	72B	72B	7B	72B	72B	A1	20-01-01	20-01-01	SEALEDGE FORD	010041	000000	0701	10Z	0700	BA	001	00	20-01-01	3	200000	371
20011F0004971E80005	7149	TF7	TF	72B	72B	7B	72B	72B	A1	2-01-01	20-01-01	TRUCK PARTS AND EQUIPMENT CO LITINA FORD	100001	000000	0701	10Z	0700	BA	001	00	20-01-01	1	100000	3007
20011F0004971E80006	01-01	TF7	TF	72B	72B	7B	72B	72B	A1	0-01-01	10-01-01	LINCOLN MERCURY OF	100001	000000	0701	10Z	0700	BA	001	00	20-01-01	1	100000	3077
20011F0004971E80007	106-00	TF7	TF	72B	72B	7B	72B	72B	A1	0-01-01	21-01-01	TOWN & COUNTRY FORD, INC.	000001	000000	0701	10Z	0700	BA	001	00	17-01-01	0	100000	2400
20011F0004971E80008	00-01	TF4	TF	72B	72B	7B	72B	72B	AM	00-01-01	2-01-01	PTT TRIPLE BROWN INC.	000001	000000	0701	10Z	0700	AA	001	00	0-01-01	10	100000	2070
20011F0004971E80009	00-20	TF4	TF	72B	72B	7B	72B	72B	A1	11-01-01	10-01-01	LINCOLN MERCURY, IN	000001	000000	0701	10Z	0700	BA	001	00	7-01-01	70	100000	2070
20011F0004971E80010	01-7	TF7	TF	72B	72B	7B	72B	72B	A1	1-01-01	20-01-01	MANORBACK FORD	000001	000000	0701	10Z	0700	BA	001	00	20-01-01	0	100000	19
20011F0004971E80011	106-00	TF7	TF	72B	72B	7B	72B	72B	A1	00-01-01	15-01-01	WOODWARD FORD- MERCURY, INC.	010001	000000	0701	10Z	0700	BA	010	00	0-01-01	0	100000	3130
20011F0004971E80012	101-00	TF7	TF	72B	72B	7B	72B	72B	A1	10-01-01	12-01-01	MILLARSON FORD LINCOLN MERCURY	000001	000000	0701	10Z	0700	BA	000	00	20-01-01	20	100000	2070
20011F0004971E80013	00-01	TF7	TF	72B	72B	7B	72B	72B	A1	00-01-01	11-01-01	LAKELAND FORD/MERCURY, INC.	000001	000000	0701	10Z	0700	BA	000	00	0-01-01	10	100000	2000
20011F0004971E80014	021-00	TF7	TF	72B	72B	7B	72B	72B	A1	20-01-01	2-01-01	CREATION FORD, INC.	000001	000000	0701	10Z	0700	BA	000	00	21-01-01	0	100000	10
20011F0004971E80015	00-20	TF7	TF	72B	72B	7B	72B	72B	A1	20-01-01	1-01-01	DEAN BELLEFON INC	000001	000000	0701	10Z	0700	BA	000	00	14-01-01	0	100000	200
20011F0004971E80016	100-00	TF7	TF	72B	72B	7B	72B	72B	A1	11-01-01	20-01-01	MYTA FORD OF CANNON	000001	000000	0701	10Z	0700	BA	000	00	1-01-01	10	100000	0000
20011F0004971E80017	100-00	TF7	TF	72B	72B	7B	72B	72B	A1	20-01-01	1-01-01	METRO FORD OF LANSING, INC.	000001	000000	0701	10Z	0700	BA	000	00	1-01-01	1	100000	0000
20011F0004971E80018	00	TF7	TF	72B	72B	7B	72B	72B	A1	00-01-01	00-01-01	TRIPLE J FORD	000001	000000	0701	10Z	0700	BA	000	00	17-01-01	77	100000	0000
20011F0004971E80019	00-07	TF7	TF	72B	72B	7B	72B	72B	A1	20-01-01	12-01-01	HAS CITY FORD- MERCURY INC	000001	000000	0701	10Z	0700	BA	000	00	20-01-01	7	100000	001
20011F0004971E80020	01-01	TF4	TF	72B	72B	7B	72B	72B	AM	21-01-01	12-01-01	MYTEL MOTORS INC.	000001	000000	0701	10Z	0700	AA	000	00	21-01-01	1	100000	000

MTA_CD	TOT_COOLER	MTA_CD	ST_CD	HR	BUILD	PLC	REGI	ST_P	CHRG	TRCH_DGT	TRCH_DATE	CLST_TAG	AREA_CD	COURT	PLA_CD	TRM_CD	ENTRY	SPD	WPS	AWB	WRY	TRM	
CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
00.04	191.07	1.1	715	MA	CA	3	991			TRUCK HAS NO THROTTLE RESPONSE, CUSTOMER STATES IT WAS INTERMITTANT TO START BUT NOW IT'S CONSTANT		000	USA	17000	000	USA	*	101	07	010			
01.02	184.27	1.3	712	MA	CA	3	991			HOOKED UP NEW SEC TEST FORD CONT WASH PERFORM TEST DONE NOB PD (DATA MONITOR ROAD TEST TO CHECK TP VOLTAGE CHECK AT THE TIME CALLED HOTLINE TALKED TO GREG ABOUT LACK OF THROTTLE RESPONSE INTERMITT	REPLACE ACCELERATOR		040	USA	17100	000	USA	*	101	07	011		
01.02	200.00	2.0	450	MA	CA	3	991			NOT OPERATING PROPERLY ENGINE PERFORMANCE DIAGNOSTICS PANEL OPEN CIRCUIT ENGINE PERFORMANCE DIAGNOSTICS T.S. DI TURBO ENGINE DIAG			210	USA	18000	000	USA	*	101	07	011		
01.02	053.11	2.0	000	MA	CA	3	991			WHEN SEC CODES ALL PASS, REPLACED			000	USA	18000	000	USA	*	101	07	011		
01.02	184.70	1.0	014	MA	CA	3	991			PERFORMED ECU QUICK TEST. FOUND CODE P0003			010	USA	16100	000	USA	*	101	07	011		
01.02	142.92	0.0	700	MA	UT	3	991			PERFORMED ECU QUICK TEST. FOUND CODE P0003			000	USA	18000	000	USA	*	101	07	011		
79.00	205.12	2.0	000	MA	CA	3	991			COILS REPLACED ACCELERATOR PEDAL			010	USA	17100	000	USA	*	101	07	011		
79.00	114.20	0.0	000	MA	CA	3	991			REPLACED AF SENSOR			000	USA	18010	000	USA	*	101	07	011		
01.02	189.10	1.0	017	MA	CA	3	991			PEDAL ASSEMBLY ENGINE PERFORMANCE DIAGNOSTICS T.S. DI TURBO ENGINE DIAG			001	USA	17100	000	USA	*	101	07	011		
00.04	204.00	4.2	000	MA	MA	3	991			PERFORMED ECU QUICK TEST. FOUND CODE P0003. TEST RESET PASS NO OPER FOR R SENSOR	ABBY CLEAR ALL CODES ROAD TEST RESET PASS NO OPER FOR R SENSOR			700	USA	17100	000	USA	*	101	07	011	
04.20	148.70	0.0	007	MA	CA	3	991			THROTTLE ASSEMBLY PERFORMED ECU TEST FWD INTERMITTENT PEDAL ASSEMBLY FOR PEDAL ASSEMBLY REPAIR			001	USA	17100	000	USA	*	101	07	011		
79.00	771.00	1.0	001	MA	CA	3	991			1 CHECK PEDAL OPERATION, CALL HOTLINE, ORDER UPDATED PARTS, INSPECT WIRING AND REPLACE PEDAL WITH UPDATED PARTS			000	USA	13000	000	USA	*	101	07	011		
01.02	180.10	1.1	017	MA	CA	3	991			PERFORMED ECU TEST FWD INTERMITTENT PEDAL ASSEMBLY FOR PEDAL ASSEMBLY REPAIR			001	USA	17100	000	USA	*	101	07	011		
01.02	174.00	1.0	000	MA	CA	3	991			PERFORMED ECU TEST FWD INTERMITTENT PEDAL ASSEMBLY FOR PEDAL ASSEMBLY REPAIR			700	USA	12100	000	USA	*	101	07	011		

WTRC_C CMT	TRF_C CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT	WTRC CMT	TRF CMT
21.02	98.00	1.4	8892	*	WA	WA	21801		NO TEST, REPORT TEST, MONITOR ON ROAD TEST. REPLACED THROTTLE PEDAL ASSEMBLY FOR INTERMITTENT RESPONSE. RETEST AND ROAD TEST. DEFECTIVE FUEL PEDAL ASSEMBLY. CHECK TEST. DIAGNOSE. (CLOCK TEST) DIAGNOSE. (DAG PUMP DIAGNOSIS. ORDER AND RFLC THROTTLE PEDAL.	TRM TXD			INTERMITTENTLY THERE IS NO THROTTLE RESPONSE. VEHICLE LOOSENS THROTTLE RESPONSE INTERMITTENTLY.	280 USA	12410	88	USA	*	WA	FT	821	48					
28.88	115.33	0.7	8507	*	WA	UT	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL.			OTHER ENGINE TROUBLE NO THROTTLE RESPONSE. CUSTOMER NO THROTTLE RESPONSE.	433 USA	7805	1	USA	*	WA	FT	817							
28.4	212.24	4.1	8700	*	WA	SC	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			WFR FOR NO THROTTLE RESPONSE.	210 CAN	48708	64	CAN	*	WA	FT	811							
28.27	74.45	0.4	8459	*	WA	AB	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL.	RETEST OK		OTHER ENGINE TROUBLE NO THROTTLE RESPONSE. CUSTOMER NO THROTTLE RESPONSE.	404 CAN	48000	54	CAN	*	WA	FT	811							
21.82	178.26	1.1	7970	*	WA	CA	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			ENGINE RUMBLE BUT NO THROTTLE RESPONSE.	885 USA	12800	873	USA	*	WA	FT	811							
28.28	75.22	0.8	8520	*	WA	AB	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			ENGINE RUMBLE BUT NO THROTTLE RESPONSE.	700 CAN	48884	2	CAN	*	WA	FT	801							
24.41	141.38	1	2018	*	WA	VA	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CHECK FOR ENGINE COORD. NO THROTTLE RESPONSE AT TIME.	882 USA	54308	872	CAN	*	WA	FT	811							
80.84	270.63	2.1	4485	*	WA	TX	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CHECK FOR NO THROTTLE RESPONSE.	882 USA	14908	884	USA	*	WA	FT	811							
78.26	148.19	1	8550	*	WA	WA	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.	ALL OK BODY		NO THROTTLE RESPONSE ON HARD ACCELERATION. NOT REPAIR NO THROTTLE RESPONSE. PERFORMED ENGINE PERFORMANCE DIAG.	280 USA	12480	828	USA	*	WA	FT	811							
78.80	125.83	1	8538	*	WA	AR	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CUSTOMER STATES THAT AT TIMES WHEN ENGINE THROTTLE IS NO THROTTLE RESPONSE HE PUSHES IT TO THE FLOOR AND NOTHING HAPPENS.	807 USA	71561	1	USA	*	WA	FT	811							
21.82	165.78	1	3178	*	WA	CO	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CUSTOMER STATES THAT AT TIMES WHEN ENGINE THROTTLE IS NO THROTTLE RESPONSE HE PUSHES IT TO THE FLOOR AND NOTHING HAPPENS.	283 USA	15808	84	USA	*	WA	FT	811							
28.4	153.89	1.3	7282	*	WA	SC	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CHECK FOR NO THROTTLE RESPONSE.	220 CAN	48728	84	CAN	*	WA	FT	811							
28.4	125.13	0.6	8780	*	WA	SC	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.	RPL. 36.43		REPAIR FOR NO THROTTLE RESPONSE AT TIME. WILL JUST GO TO ANOTHER AN IP FOOT.	220 CAN	48708	872	CAN	*	WA	FT	811							
28.28	153.89	0.6	7784	*	WA	CA	21801		VEHICLE CAME IN WITH NO RESPONSE ON THROTTLE TRIED TO CLAIM RECALL. BUT NOT ELIGIBLE AS PER ORANGE CODE. PER THE CODE P0221 REPORT TEST. FOUND FULLY THROTTLE PEDAL ON THROTTLE PEDAL ASSEMBLY. ACCELERATOR PEDAL. ORDER AND RFLC THROTTLE PEDAL.			CUSTOMER STATES A FEW DAYS AGO, HE WENT TO ACCELERATE AND NOTHING HAPPENED. NO THROTTLE RESPONSE.	220 USA	17205	1	USA	*	WA	FT	811							

PE03-04-A 5418

INTL_C	TCT_CD	LR	DLR	PRCE	ST_P	SPRC	TRCH_TXT1	TRCH_TXT2	GMT_TXT	AREA	COUNT	SUB_CD	TOI	ENTRY	GRV	WPS	AWB	WKT	TR	
CDT	CSG	HW	DLG	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
83.33	434.88	4	3871	NA	PA	21801	PO RENTONER IN SESSION FAILED. REPLACE SENSOR. ROAD TO HAVE LIGHT TOWED TO SHOP FOR REPAIRS.		ENGINE HAS NO THROTTLE RESPONSE.	815	USA	48840	872	CAN	*	144	F7	811	8	
84.84	204.38	1.8	7882	NA	NY	21801	11580 PERFORMANCE CONCERNS CC 42 ACCEL. PEDAL ASBY I PERFORMED ROAD TEST AND I VERIFIED CLUT CONCERN I RAN THRU PERFORMANCE SHEET STEPS 1 THRU 14 I FOUND CODES P0221 AP ASBN INPUT I PERFORMED RESPONSE P0221 FAILED THROTTLE PEDAL 42	THROTTLED STEPS DOT 003 WITH ASBN TRD DATA MONITOR I FOUND THE AP INDICATING MAX VOLTAGE PARTS ON ORDER I REPLACED THE ACCEL PEDAL ASBY CLEAR CODES ROAD TEST AND RETEST DEC SYSTEM P1111	INSPECT FOR LOSS OF THROTTLE RESPONSE	778	USA	17250	886	USA	*	144	F7	811		
81.42	262.31	2.6	8264	NA	UT	21801	PERFORM TESTS ON LINE 81 THRU 88 ON PERFORMANCE SHEET FOR DTC P221 IN CONTINUOUS MEMORY PERFORM PINPOINT TEST P21 THRU P24 FOR DTC P0221 TEST Y INDICATES INTERMIT	DONT FAILURE OF THROTTLE PE DCL. REPLACE THROTTLE PEDAL ASSEMBLY PERFORM ROAD TEST TO VERIFY RESPONSE OK PERFORM QUALITY REP AIR CHECK.	INSPECT FOR VEHICLE DROPPED TO A IDLE AND NO THROTTLE RESPONSE	881	USA	18880	824	USA	*	144	F7	811		
81.43	288.81	4.1	8277	NA	VA	21801	8848 W ROAD TEST PERFORM DIAGN DAG CODES P0221 PERFORM TEST FOUND THE TP SENSOR TO BE OUT OF ADJUST WHICH NOT OPEN CREDIT REPLACE THE TP SENSOR CLEAR CODES ROADTEST RETEST TO VERIFY		** CEL & NO THROTTLE RESPONSE ** COMMENTS SPECIAL INSTRUCTIONS:	787	USA	12704	872	USA	*	144	F7	811		
124.44	222.75	0.9	A18221	NA	ON	100201	CHK ON 7-THROTTLE RESPONSE PERFORM ENG DIAG FOUND DTC'S P0221/P221 CHK TP CIRCUIT POLLED INPUT SIGNALS REPL TP ASBY ROADTEST		CHK ON NO THROTTLE RESPONSE	410	CAN	48888	824	CAN	*	144	E1	811		
187.85	238.23	1.5	7728	NA	CA	100201	PULLED CODES P0221, AP SWITCH, P0113, AT CIRCUIT 11 HIGH INPUT, P1848, CRANK SHAFT SENSOR MALF FN TECH. PERFORMED TEST 81 21 13 FOR CODE P0221 AND INTERIM P1848, P1848 AND AP FUNCTIONING NORMALLY AT THE ROAD TEST VERIFIED CONCERN REMOVE CHECK ENGINE LIGHT ON FOUND P0221	5 TIME CALLED HOT LINE AND WAS DISTRUCTED TO CHECK BRACKET, FOUND PART UNDER CONNECTOR AT BRACKET @ 110, CLAMP AND REMOVED, HOT LINE RECOMMENDED REPLACING AP SWITCH REPLACED SW1	CHECK AND ADVISE ON NO THROTTLE RESPONSE TOWED IN	408	USA	121201	884	USA	*	148	E1	811		
187.85	249.26	1.5	8882	NA	CA	100201	PERFORM PIN POINT TEST AND ACC PEDAL INS OPEN REPLACE ACCEL ASBY OK. MED CHECK OK ROAD TEST PERFORM TEST REPLACED BASE PEDAL ASBY CLEAR CODES ROAD TEST GOOD		WT. NO THROTTLE RESPONSE TRAVELING MANUALLY PUTS TRAWY IN AND OUT OF GEAR TO GET THROTTLE RESPONSE BACK	800	USA	11881	824	USA	*	144	E1	811		
85.4	144.32	1.2	8728	NA	SC	21801	PERFORMED DIAGNOSIS, REPLACED THROTTLE PEDAL		REPAIR NOT THROTTLE RESPONSE INTERMITTENT MOST REV UP CUSTOMER STATED NO THROTTLE RESPONSE	200	CAN	48788	872	CAN	*	141	F7	811		
150.88	174.88	8.7	8822	NA	MI	21801	PERFORMED DIAGNOSIS, REPLACED THROTTLE PEDAL			208	USA	111488	872	USA	*	141	F7	811	8	
170.9	254.32	0.9	8218	NA	MI	100201	START THE ENR FOR CLUT CONCERN PUSH THICK IN SHOP. 878 RETRIEVED P0221 PERFORM PPT (P2) R R THROTTLE PEDAL CLEAR CODES AND CHK OPERATION ALL OK OK		TOWED IN NO THROTTLE RESPONSE	414	USA	141288	872	USA	*	141	E1	811		
85.4	422.28	1.8	8284	NA	AL	21801	1458 USR VOK ON TEST DRIVE AND VERIFIED CONCERN CHECKED WITH DASH AND THERE WAS NOTHING. RETRIEVED CODES WITH THE WDS. RETRIEVED CODE P0221, WENT TO O PINPOINT TEST D48 AND FOUND THAT THE TP	ENGINE R WAS TALLTY. 878 DIAG REPLACED TP SENSOR AND WENT ON TEST DRIVE TO VERIFY REPAIR JOB	REPAIR FOR NO THROTTLE RESPONSE, NOTICED BETWEEN 88878	788	CAN	48824	8	CAN	*	144	F7	811		
87.88	141.81	1	8888	NA	MI	21801	THIS REPAIR FOUND THROTTLE PEDAL SHORTING INTERMITTENTLY. RAR THROTTLE PEDAL ASBY ROAD TESTED OK. MET NO LABOUR OPERATIONS CODE IN 878 FOR REPAIR		LOOKING THROTTLE RESPONSE, FLUE BLOW ASSEMBLY	78	CAN	44828	824	CAN	*	144	F7	811		

YOT DO	ST	LR	DLR	REP	ST_P	OPR	TRCH	TRCH	TRCH	AREA	COUNT	SLD	DSL	ENTRY	ENT	MPG	AMB	VTL	TR		
DATE	ST	LR	DLR	REP	ST_P	OPR	TRCH	TRCH	TRCH	CD	BY	FL	CD	CD	CD	CD	CD	CD	FLA		
95-4	147-2	1	87188 *	NA	VT	31881	DISASSEMBLE AND REPLACE THROTTLE PEDAL ASSEMBLY														
78-88	190-80	1-2	0812 *	NA	NY	31881	STEP ONE REPLACED THROTTLE ASS. AND TEST DRIVE														
91-52	274-42	3-5	4227 *	NA	VA	31881	DRIVE W/ ROAD TEST PERFORMED DASH POZZE PMPONT TEST ROAD TEST TO MONITOR FOR POUND TH-AP SWITCH TO BE INTERMITTENT REPLACE AP ASSEMBLY COORD CODES RETURN TO VERIFY FOUND THE TUBBO INSOLE TO BE TESTED AND FOUND NORMAL, OPERATION TESTED AND RECEIVED CODES PROBLEMS ARE PERFORMED PMPONT TESTS AND RECEIVED PASS RESULTS, RECALIBRATED THE PEDAL ASSEMBLY AND REINSTALL ED A NEW THROTTLE PEDAL.	NO NORMAL OPERATION													
78-88	198-68	0-8	7880 *	NA	OR	31881		REJECTED PASS													
78-88	217-11	2-1	8530 *	NA	WA	31881	DRIVE TEST, NO CODES, CHECKED OASE, NOTHING APPLICABLE. REPROGRAMMED PCRAMD RETURNED TO CUSTOMER, WAS OK FOR 88 MILES AND THEN IT STARTED AGAIN. ATTACHED MONITOR AND ROADTESTED. PERFORMED PMPONT TEST.	TEST HAS INTERMITTENT FAULTY IN PEDAL AND SENSOR ASSY. REPLACED PEDAL AND SENSOR AND RE-EDGED, NOW OK													
91-52	287-38	3-8	6450 *	NA	SD	31881	AT TIME TO REPLACE ACCEL. PEDAL ASSY, COMPLETE ENGINE PERFORMANCE IMPROV														
91-52	285-18	2-4	8376 *	NA	MT	31881	NOTE: DO NOT CHANGE CUSTOMER STEERING DEPLOYABLE AIRBAG AS PERFORM														
91-52	281-02	1-1	7712 *	NA	CA	31881	ACCEL. PEDAL (SEE CHECK (TEST) DIAGNOSIS ACCEL. PEDAL SWIP, REPLACED ACCEL. PEDAL ASSY, RETEST OK														
80-84	145-04	1	7754 *	NA	CA	31881	DEFECTIVE THROTTLE PEDAL ASSY. PULL CODES. PMPONT DEFECTIVE THROTTLE PEDAL ASSY. (GOES TO IDLE AT FULL THROTTLE). REPLACE PEDAL ASSY														
94-28	202-17	2	1442 *	NA	WV	31881	DRIVE, SEE PMPONT DASH ROAD TEST (CP TEST) LOW IDLE STABILITY TEST (M) SELECT TEST CYL. CONTRIBUTION TEST (M) OK (M) (M) (M) FOR CONTRIBUTION OK (M) (M) (M) (M) AT EACH HEAD AND AT SELECT FUEL. PUMP OK BY PMPONT	BY PER CODES PZZ21 HHC TO REPL. ACCEL. PEDAL ASSY RETEST REACH TEST OK													
95-4	157-8	1	85780 *	NA	TX	31881	CHECK FOR NO ACC PEDAL RESPONSES CHECK THIRD DIAGNOSTIC CODE REE1 CHECK PDS AND RR PEDAL ASSY (S)														
91-52	284-52	8-9	7809 *	NA	NY	31881	1 SEC POZZE, PMPONT DASH, DCL 1.3 VOLTS. REPLACED PEDAL ASSY AND RETEST.														
78-88	188-82	1-3	2417 *	NA	TX	31881	TEST ELECTRONICS, REPLACE THROTTLE PEDAL ASSEMBLY RETURN PCM														
78-88	128-82	1	4881 *	NA	FL	31881	1 REJECT NO THROTTLE RESPONSE, NOS START UP CODE PZZ21 KOSB PZZ21 KOSR PZZ21 PMPONT TEST FAULTY ACCEL. PEDAL														

TOT DOY LBR	REG	ST P	TECH	TECH	CUST	AREA	COUNT	BUILD	TOL	CNTRY	CHG	VPS	ANS	VRT	PLA
MTR_C ST_QR	FR	OUR_C	ON_C	NOV	CPAC	CD_B	CD	BY_CD	R_CD	CD	CD	CD	CD	CD	R
QTY	QTY	ID	D	D	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
81.82	204.87	1.7	1754*	NA	CA	21801									
78.88	288.12	4.8	4872*	NA	TX	21801									
80.84	144.08	0.9	8926*	NA	SD	21801									
78.88	104.84	0.8	1883*	NA	SD	21801									
80.84	182.84	1.8	7185*	NA	NE	21801									
87.85	232.85	1.8	4824*	NA	IN	21801									
78.88	124.88	1	3088*	NA	AL	21801									
78.88	124.88	0.8	2888*	NA	CA	21801									
80.84	288.12	1.8	7782*	NA	CA	21801									
81.82	112.12	0.7	7188*	NA	NE	21801									
78.88	122.88	1	3824*	NA	NY	21801									
81.82	228.82	3.6	8824*	NA	OK	21801									
80.84	128.84	2.3	9187*	NA	OH	21801									
78.88	144.88	1	7782*	NA	CA	21801									
78.88	181.88	1.1	7785*	NA	CA	21801									
81.82	148.82	0.9	8782*	NA	VA	21801									

MTPL	CD	SA	CD	USA	MR	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD	DLR	CD						
78.00	140.00	0.0	0	5471*	NA	CA	31001	PEDAL ASSEMBLY TEST PEDAL INSTRUMENTS UNIT, CHECK FOR OK, OK, PULL IN RESTRICTIONS K.O.R. TEST, REPAIR PEDAL ASSEMBLY P3021, P3021, P3022	TECH DOX	CURT STATES OK FOR LACK OF THROTTLE RESPONSE AT TIMES SOME	681	USA	17148	004	USA	*	044	1.1	011																										
81.00	100	0.7	0	3488*	NA	CA	31001	DIAGNOSIS UNIT OK, PULL & OK HOLD TIME: REPAIR P1111, ASSEMBLY THROTTLE PEDAL P1111, PUMP, PUMP & PUMP, REPAIR P1111, TEST PEDAL ASSEMBLY. TP SENSOR FULLS, REPAIR PEDAL ASSEMBLY, RETEST, ROAD TEST	ST. OK	CURT STATES OK FOR LACK OF THROTTLE RESPONSE AT TIMES SOME	870	USA	18000	004	USA	*	044	1.1	011																										
81.00	300.70	1.0	0	3488*	NA	CA	31001	DIAGNOSIS UNIT OK, PULL & OK HOLD TIME: REPAIR P1111, ASSEMBLY THROTTLE PEDAL P1111, PUMP, PUMP & PUMP, REPAIR P1111, TEST PEDAL ASSEMBLY. TP SENSOR FULLS, REPAIR PEDAL ASSEMBLY, RETEST, ROAD TEST	ST. OK	INTERMITTENT LACK OF THROTTLE RESPONSE ACCEL PEDAL ADVISE & VERIFY FUEL COVERAGE OK, PULL & OK FOR NO THROTTLE RESPONSE AT TIMES THEN CRANK NO START	870	USA	18000	004	USA	*	044	1.1	011																										
78.00	100.21	3.0	0	3500*	NA	CA	31001	REPLACED THROTTLE PEDAL ASSEMBLY TEST OK		CURT STATES AT TIMES NO THROTTLE RESPONSE WHEN THE HAPPENS THRU HAND SHIFT AND JERKY, COMBINATION DID NOT OCCUR THIS MORNING ON THE WAY IN	770	USA	15000	004	USA	*	044	1.1	011																										
81.00	100.0	1	0	3471*	NA	CA	31001	THROTTLE PEDAL FAILED PERFORM DIAG (SOLD THROTTLE PEDAL ASSEMBLY RETESTED) TEST IN PERFORMANCE DIAGNOSIS BOOK STEP 14 IN PERFORMANCE DIAG PERFORM PERFORMANCE TEST, REPLACE THROTTLE PEDAL ASSEMBLY, RETEST THROTTLE		PERFORM DIAG (SOLD THROTTLE PEDAL ASSEMBLY RETESTED) TEST IN PERFORMANCE DIAGNOSIS BOOK STEP 14 IN PERFORMANCE DIAG PERFORM PERFORMANCE TEST, REPLACE THROTTLE PEDAL ASSEMBLY, RETEST THROTTLE	681	USA	17148	004	USA	*	044	1.1	011																										
80.00	270.12	3	0	470*	NA	CA	31001	ACCELERATOR PEDAL FAILED DIAGNOSIS PERFORMANCE DIAGNOSTIC 7.2L 2L TUNED ENGINE DIAG		CURT SAYS THAT VEH HAS NO THROTTLE RESPONSE. INTERM	770	USA	15100	004	USA	*	044	0.7	011																										
81.00	100.0	1.0	0	402*	NA	CA	31001	ACCELERATOR PEDAL ASSEMBLY FAILED TEST DRIVE AND VERIFIED NO THROTTLE RESPONSE SOMETIMES. SEC VERTICAL, RECEIVED CODE P002L, FOLLOWED PERFORMANCE TEST, AND REPLACE ACCEL. PEDAL ASSEMBLY 1. VERIFY DIAGNOSIS CHECKED		OK FOR VEH HAS NO THROTTLE RESPONSE	770	USA	15100	004	USA	*	044	0.7	011																										
80.00	211.70	2.2	0	0000*	NA	CA	31001	ACCELERATOR PEDAL ASSEMBLY FAILED TEST DRIVE AND VERIFIED NO THROTTLE RESPONSE SOMETIMES. SEC VERTICAL, RECEIVED CODE P002L, FOLLOWED PERFORMANCE TEST, AND REPLACE ACCEL. PEDAL ASSEMBLY 1. VERIFY DIAGNOSIS CHECKED		THE VEH HAS NO THROTTLE RESPONSE WHEN ACCELERATOR PEDAL WAS DEPRESSIONS	601	USA	10000	004	USA	*	044	0.7	011																										
78.00	200.00	2.3	0	3000*	NA	CA	31001	THROTTLE RESPONSE ACCELERATOR PEDAL BOARDED FOR CODES PERFORMED PERFORMANCE DIAGNOSTIC TESTS		CUSTOMER STATES THROTTLE RESPONSE PROBLEM SOMETIMES NO THROTTLE	840	USA	11000	004	USA	*	044	0.7	011																										
81.00	170.00	1.4	0	480*	NA	CA	31001	PERFORM CODE 20 M 0 21407 VERIFY CONCERN FOR CODES FOR ACCEL PEDAL IN CONN. PWD DATA MONITOR FORMS LOW INPUT, PERFORM TEST FOLLOWS FAULTY A F		NO THROTTLE RESPONSE ON FOOT FEED	600	USA	10100	004	USA	*	044	0.7	011																										
78.00	100.00	1.1	0	30*	NA	CA	31001	REPLACED TP SENSOR AND PEDAL ASSEMBLY		NO THROTTLE RESPONSE	600	USA	10100	004	USA	*	044	0.7	011																										
78.00	100.00	0.5	0	30*	NA	CA	31001	RUN ERIC TEST NO CODES. REPLACED ACCELERATOR PEDAL AND SENSOR ROAD TEST, ROAD TEST NO CODES WERE FOUND WHEN TH TROUBLE FOLLOWED TEST AND MONITORED PERFORMANCE. CIRCULATE NO PROBLEM FOUND AT THIS TIME. THE PEDAL IS REPAIRING DTP OF ASSEMBLY, REMOVED AND REPLACED THE PEDAL		TRUCK WILL IDLE BUT HAS NO THROTTLE RESPONSE	600	USA	10100	004	USA	*	044	0.7	011																										
80.00	100.00	1	0	700*	NA	CA	31001	TP SENSOR BAD BODY CONDUCT ELECTRICAL CHECK TEST	AL ASSEMBLY TEST OK	NO THROTTLE RESPONSE INTERMITTENT PROBLEM POSS ACCEL PEDAL	600	USA	10000	004	USA	*	044	0.7	011																										
81.00	100.0	0.8	0	0471*	NA	CA	31001	TP SENSOR BAD BODY CONDUCT ELECTRICAL CHECK TEST		CURT STATES OK FOR NO THROTTLE RESPONSE AT TIMES ACCEL	600	USA	10100	004	USA	*	044	0.7	011																										

YTD_DOLAR METH_COST_OR DST	YR D	CLD C	DLR BU S.C D	REG OR C	ST NOV CD	QTR CD	TRCH TXT1	TRCH TXT2	CHRT TXT	AREA CD	COUNT RY CD	MLR_IL R CD	TRM CD	CMTY SOLD	ENTY CD	WFO CD	WFO CD	TRM PLA G
81.82	184.25	6.4	7801	MA	CA	31981	VERIFY WIRING NO THROTTLE RESPONSE MOTOR TP PEDAL PEDAL NOT WORKING REPAIR WIRING PEDAL REPAIR CHECK WOLANSON		THROTTLE NOT THROTTLE RESPONSE	880	USA	172917	884	USA	*	MA	87	871
81.82	184.55	1.2	7801	MA	TX	31981	WORN 3R THROTTLE CONCERN PERFORMANCE DIAG CODES 0021 PFI POINT ELECTRICAL OPEN CIRCUIT TP SENSOR REPLACED TP RESET SYSTEM PASS		CUSTOMER STATES TRUCK HAS NO THROTTLE RESPONSE ENGINE RURSH	281	USA	140180	872	USA	*	MA	87	871
84.28	288.78	1.7	7801	MA	CA	31981	DIAGNOSTIC FOUND TP VEHICLE HAS NO CODES ON ALL ENGINE RUNNING CODES AND FOUND NO OTHER ROAD TESTED THE VEHICLE AND FOUND INSTALLED THE PANEL AND RETESTED AND ROAD TESTED		CUSTOMER STATES AT TIMES WHEN THROTTLE IS DEPRESSING VEHICLE WILL HAVE NO THROTTLE RESPONSE CHECK AND ADVISE	880	USA	140288	872	USA	*	MA	87	871
78.88	821.4	6.8	7844	MA	DE	31981	NO 7.3 ENGINE PERFORMANCE ISSUE DID NOT 5 MONITOR NOT OK 88P OK FOUND AP ERRATIC AT 61 STEERING HARDNESS MONITOR IT MONITOR 14401 HARDNESS NO 810000 ON 020000 MP DID NOT 5 MONITOR NOT OK 88P OK		NO THROTTLE RESPONSE	300	USA	118800	1	USA	*	MA	87	871
88.4	188.82	1.1	88217	MA	ND	31981	REPAIR THROTTLE SENSOR VEHICLE HAS NO THROTTLE RESPONSE ENGINE PERFORMANCE DIAGNOSIS 7.3 0 TURBO ENGINE DIAG		REPAIR NO THROTTLE RESPONSE	400	CAN	88217	821	CAN	*	MA	87	871
170.8	483.38	5.1	4181	MA	TX	88201	VEHICLE HAS NO THROTTLE RESPONSE ENGINE PERFORMANCE DIAGNOSIS 7.3 0 TURBO ENGINE DIAG		CUSTOMER REPORTS VEHICLE HAS NO THROTTLE RESPONSE AT TIMES	840	USA	184027	884	USA	*	MA	81	871
170.8	483.38	5.1	4181	MA	TX	88201	VEHICLE HAS NO THROTTLE RESPONSE ENGINE PERFORMANCE DIAGNOSIS 7.3 0 TURBO ENGINE DIAG		VEHICLE HAS NO THROTTLE RESPONSE AT TIMES CHECK FOR NO THROTTLE RESPONSE SEE HW	840	USA	184027	884	USA	*	MA	81	871
185.78	328.8	2.3	881	MA	VA	88201	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE	424	USA	142888	884	USA	*	MA	81	871
188.18	218.84	1.1	8147	MA	CA	88201	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE	370	USA	182188	884	USA	*	MA	81	871
178.22	434.84	5.7	88201	MA	OH	88201	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE DIAG REPLACE ACCELERATOR PEDAL ASSEMBLY	880	CAN	440887	884	CAN	*	MA	87	871
81.82	178.88	1.7	8708	MA	WA	31981	CHECK BEC POWERTRAIN FOR STOPS CHECK FOR CONT CODES P488 CHECK WOB0 OR 888888 P488 CHECK PFI DATA CHECK AP BUS AP FL AND P AP 888888 ROAD TECH CHECK BEC AND PFI OK		INTERMITT ON ACCEL FROM TOP NO THROTTLE RESPONSE	880	USA	178888	884	USA	*	MA	87	871
81.82	148.82	1.1	8824	MA	TX	31981	VERIFY CONCERN RUN 888 P0281/P0282 ROAD TEST AND MOTOR PFI8 BAD SENSOR REPLACE AND RETEST OK 888 488 888888 IN REPLACES THROTTLE AND 888888 ALL OK		ON VEHICLE HAS NO THROTTLE RESPONSE AT TIMES NO THROTTLE RESPONSE AT TIMES NO THROTTLE RESPONSE 80 MPH CUSTOMER STATES THE VEHICLE HAS NO THROTTLE RESPONSE CHECK FOR NO THROTTLE RESPONSE AT TIMES, CHECK THIS AT ALL SPEEDS	254	USA	188888	884	USA	*	MA	87	871
78.88	188.88	1	88186	MA	IA	31981	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE	888	USA	188188	884	USA	*	MA	87	871
88.84	188.48	1.4	887	MA	SC	31981	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE	884	USA	187188	884	USA	*	MA	87	871
88.84	188.48	1.4	887	MA	SC	31981	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE	477	USA	188480	1	USA	*	MA	87	871
78.88	188.88	1.2	8888	MA	CO	31981	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		888888 AND 888888 NO THROTTLE RESPONSE	388	USA	188888	2	USA	*	MA	87	871
88.84	188.48	1.4	88218	MA	AZ	31981	DIAGNOSTIC WIRING AND ADDITIONAL WIRING DIAG REPAIR THROTTLE PEDAL ASSEMBLY		NO THROTTLE RESPONSE NOT TRUCK INSTALLED	888	USA	188888	884	USA	*	MA	87	871

NTFL_CD	TYT_CD	LTN	BLK_D	BLK_D	PRGR	ST_P	CP90	TRCH_TXT1	TRCH_TXT2	CUST_TXT	AREA_CD	COUNT	SLR_FL	DSL_CD	ENTRY	QRT	VPS	VAL_CD	VTY_CD	TRFLA		
001	000	0	0	0	0	00	00.0				00	00	0.00	00	0000	000	00	00	00	0		
01.01	185.1	1.2	3528		NA	NY	21801	CK FOR BURN IN NO ACC DIAG AD REPLACE THROTTLE PERFORM PERFORM ENGINE AND ACC PED RESPOND FOR NO THROTTLE RESPONSE. CODE PERRI 04X VALIDATION SWITCH. REPLACED ACC. PEDAL ASSEMBLY		CR AT STOP NO ACCELERATION NO THROTTLE RESPONSE	04E USA	11848	3	USA	*	NA1	FT	011				
05.4	181.07	2.0004			NA	AR	21801	CHECK AND RUN ESC/HELP TEST FOR COOBS AND PERFORMANCE. PERRI RAR ACCEL PEDAL ASBY AND SENSOR AND CLUNK CODES ROAD TEST AND RETEST OK ONE MY TIME FOR ACC PEDAL. RER NO LABOR OPERATION (RER)		REPAIR FOR NO THROTTLE RESPONSE CUSTOMER COMPLAINS THAT AT TIMES THE ENGINE LOOSE THROTTLE RESPONSE SOMETIMES CAN LET COMPLETELY OFF THROTTLE AND REAPPLY WILL ACCEL.	01E USA	12083	2	USA	*	NA4	FT	011				
02.04	145.04	1	0027		NA	TX	21801	PERFORM ENGINE PERFORMANCE DIAG WITH 1 12 PERRI REPORT TEST FOUND NO THROTTLE PEDAL SENSOR ASBY AND TURN ON/ACC SENSOR SOLTE REPLACED THROTTLE PEDAL ASBY AND REPLACED TURN ON/ACC SENSOR		VEHICLE DIED OUT WHEN IT WAS RESTARTED IF HAD NO THROTTLE RESPONSE AND LAUGH POWER	01E USA	12083	2	USA	*	NA4	FT	011				
07.02	450.48	2.1	0020		NA	CA	21801	PERFORM ENGINE PERFORMANCE DIAG WITH 1 12 PERRI REPORT TEST FOUND NO THROTTLE PEDAL SENSOR ASBY AND TURN ON/ACC SENSOR SOLTE REPLACED THROTTLE PEDAL ASBY AND REPLACED TURN ON/ACC SENSOR		VEHICLE DIED OUT WHEN IT WAS RESTARTED IF HAD NO THROTTLE RESPONSE AND LAUGH POWER	01E USA	12083	2	USA	*	NA4	FT	011				
02.04	202.01	1.7	7028		NA	IL	21801	ENGINE ROAD TEST TO VERIFY CONCERN ENGINE LOOSES POWER/NO RESPONSE AT TIMES RER REPAIR CODES NO COOBS ROAD SELF TEST RVE PERRI CODES SELF TEST RVE PERRI 00P PRESSURE TEST PERRI IN 3PC ILE RER IN	AT 1811 0000 CLUNK CONFIRMATION TEST RER PERRI EXHAUST SYSTEM RESTRICTION TEST RER PERRI 0000 PERRI TEST RER PERRI 0000 PERRI MONITOR RER ROAD TEST, RER PERRI 00	(RER) CUST STATES ENGINE LOOSES POWER AND THROTTLE RESPONSE AT TIMES	00E USA	12010	024	USA	*	NA2	FT	011				
01.02	270.40	1.2	7047		NA	GA	21801	NO THROTTLE RESPONSE WHEN TAKING OFF FROM A STOP AT TIMES HAVE TO PUMP THE ACCELERATOR PEDAL BEFORE THE ENGINE WILL PERFORM. PERFORMED REG TESTS. TESTS INDICATE RESISTANCE READING IS TOO HIGH	ACCELERATOR PEDAL REPLACED THE ACCELERATOR PEDAL ASSEMBLY. RECHECKED OPERATION. OK	CUSTOMER STATES THERE IS NO THROTTLE RESPONSE WHEN TAKING OFF FROM A STOP AT TIMES HAVE TO PUMP THE ACCELERATOR PEDAL BEFORE THE ENGINE WILL PERFORM. REPAIR AND ADJUST.	00E USA	11921	004	USA	*	NA1	FT	011				
10E.04	414.00	4.3	0001		NA	VA	00001	ACCELERATOR PEDAL BYPASSING PERFORM ENGINE PERFORMANCE DIAGNOSIS 3 14, REPLACE ACCELERATOR PEDAL ASBY		CUST STATED THERE IS NO THROTTLE RESPONSE AFTER STARTING ENGINE	01E USA	11901	004	USA	*	NA4	FT	011				
10E.04	224.01	1.2	0020		NA	MS	10001	IS THROTTLE POSITION SENSOR REG TESTED WITH MSB, HARD PLAT PERRI. ON CHECKED SENSOR ON PID DATA REASONS NO/RE REASONS NEW CODES 0011 REPLACED THROTTLE PEDAL SENSOR ASSEMBLY. PERFORMED ELECTRONIC	ENGINE CONTROL TEST AND ROAD TEST TO VERIFY REPAIR (RER)	NO THROTTLE RESPONSE VEHICLE LOOSES THROTTLE RESPONSE CUSTOMER HAS TO CHECK PEDAL SENSOR TEST	00E CAN	00020	2	CAN	*	NA1	FT	011				
01.02	180.10	0.7	0007		NA	UT	21801	DEFECTIVE PEDAL ASSEMBLY SEC CHECK TEST. OK		VEHICLE LOOSES THROTTLE RESPONSE CUSTOMER HAS TO CHECK PEDAL SENSOR TEST	02E USA	10000	004	USA	*	NA1	FT	011				
06.4	204.07	2.0002			NA	AR	21801	CRUISE PEDAL DIAG PERFORMANCE DIAGNOSIS THE ACCELERATOR NEVER CUT OUT DURING THE ROAD TEST. THERE WAS A CODE FOR TP SIGNAL LOST, PERFORMED THE PERRI TESTS THERE WAS SLIGHT VARIANCE IN PERRI TESTS	AT THE IDLE VALIDATION SWITCH REPLACED THE IDLE VALIDATION SWITCH, CLEARED CODES AND RETESTED. OK	DEFECT ADN REPAIR VEH INDEPENDENTLY HAS NO THROTTLE RESPONSE RSP NOTICEABLE AFTER COLD START. LAUGH POWER	70E CAN	00070	004	CAN	*	NA4	FT	011				
05.4	140.20	0.8	0007		NA	AR	21801	TEST CLX FOR LOSS OF THROTTLE RESPONSE, R000 PERRI, MEMORY CODE R001, PERRI TESTS FOUND INTERMITTENT NO OPERATION CHECK CONNECTION OK REPLY ROAD TEST AND RETEST. OK	BY TIME TO REPLACE AN ASSEMBLY	DIAG LOSS OF THROTTLE RESPONSE	70E CAN	00007	004	CAN	*	NA1	FT	010				

TCT_CD	LTW	DLR	ST_P	CPSC	TECH_TXT1	TECH_TXT2	CUST_TXT	AREA	COUNT	SALE	DLR	CONTR	GRV	YR	MM	DAY	PLA	
MTPL_C	ST_PR	HR	DLR_CD	DLR_ID	ST_P	CPSC	TECH_TXT1	TECH_TXT2	CUST_TXT	CD	RT_CD	R_CD	CD	CD	CD	CD	CD	
01.00	228.84	2.2	7898*	NA	NY	21801	14380 I PERFORMED ROAD TEST AND I RAN THRU PERFORMANCE TEST STEPS I THRU 14 I FOUND CODE P0221 I PERFORMED POINPOINT TEST I FOUND THE ACCEL PEDAL ASBY TO BE FAULTY AS PER TEST RESULTS I POSED ON ORDER	I REPLACED THE ACCEL PEDAL, ASBY CLEAR CODES ROAD TEST AND RETEST WBC SYSTEM P1111 SYSTEM PASS	CUSTOMER STATES VEH HAD NO THROTTLE RESPONSE AT TIMES CHECK AND ADVISE	770	USA	11898	EM	USA	*	144	FF	011
01.00	344.4	0.6	81001*	NA	SC	21801	MSC TEST CODES P0221 AND P0222 PERFORM TEST REPLACE THROTTLE ASSEMBLY		REPAIR WORKER'S LOCKING THROTTLE RESPONSE WHILE OPENING THROTTLE RETURNS TO IDLE	289	CAN	44785	EM	CAN	*	144	FF	011
01.01	107.88	0.3	81288*	NA	ON	21801	CHECK AND REPLACE THROTTLE PEDAL W/ NO LAB TIME FOR REPAIR		DRIVER SAID NO THROTTLE RESPONSE AT TIMES	780	CAN	48282	EM	CAN	*	144	FF	011
01.00	291	2.8	8004*	NA	OK	21801	PERFORMANCE DIAGNOSTICS T.J. DI TURNING ENGINE OFF		DRIVER SAID NO THROTTLE RESPONSE AT TIMES	880	USA	12088	2	USA	*	144	FF	011
01.00	181.67	1.6	8018*	NA	OK	21801	VEHICLE HAD NO THROTTLE RESPONSE MSC (QUICK TEST) DIAGNOSIS PERFORMED, CHECK FOR DTCs, FOLDING PEDAL, PERFORMANCE TEST, COIL, CHK VOLUME IN VDC, CH VMAP 4.3 CALCULATIONS AND REPLACE PEDAL ASSEMBLY, CLEAR CODES, ROAD TESTED OK.		DRIVER SAID THAT THE VEHICLE HAD NO THROTTLE RESPONSE, CHECK AND ADVISE HAD TO HAVE ENGINE IN	601	USA	18008	2	USA	*	144	FF	011
01.00	181.28	1	8080*	NA	NU	21801	REPLACED ACCELERATION PEDAL ASBY BROUGHT ENGINE ON		CUSTOMER STATES VEHICLE LOSES THROTTLE RESPONSE INTERMITTENTLY ON VEHICLE START LOSES ALL THROTTLE RESPONSE	670	USA	11808	EM	USA	*	144	FF	011
01.00	114.37	0.9	1498*	NA	MI	21801	REPLACED ACCELERATION PEDAL ASBY BROUGHT ENGINE ON		CUSTOMER STATES VEHICLE LOSES THROTTLE RESPONSE	240	USA	14801	1	USA	*	144	FF	011
01.00	188.27	0.5	7979*	NA	CA	21801	REPLACED GAS PEDAL ASBY TEST ENGINE, FOUND INTERMITTENT THROTTLE, BOARDED FOR CODES, P0221 AND P0222, BOTH TP CODES PERFORMED POIN POINT TEST AND FOUND AIR TO BE OPEN INTERMITTENTLY, REMOVED PEDAL ASSEMBLY AND ORDERED PARTS.	WBC METALL NEW PEDAL ASSEMBLY CLEAR CODES AND ROAD TEST A/C, RETEST P.S.	CUSTOMER STATES VEH BY HAS NO THROTTLE RESPONSE OR IS VERY LOW POWERED.	880	USA	17802	EM	USA	*	144	FF	011
01.00	214.16	1.8	8028*	NA	OK	21801	RECALL TP WORK CODE P0221, DIAGNOSE & REPLACE THROTTLE PEDAL AND SENSOR CLEAR CODES		NO THROTTLE RESPONSE FROM GAS PEDAL	490	CAN	48888	EM	CAN	*	144	FF	011
01.00	139.38	1	8000*	NA	AR	21801	CHECK CODES, CLEAR AND RUN TEST SELF TEST FOR CODES AND PERFORM POIN POINT ON MSC TO ORDER PEDAL, ASBY AND REPLACE DATE REPAIR PREPARED THIS CODES @ PACE W/ TIME NO LABOR OPERATION SEVEN		DO NOT CUSTOMER COMPLAINS THAT THE ENGINE HAS NO THROTTLE RESPONSE	610	USA	8888	1	USA	*	144	FF	011
01.00	188.32	1	8208*	NA	WA	21801	CHECK THROTTLE SYSTEM AND REPLACE THROTTLE PEDAL ASBY STOCK AT THRU ROAD TEST ALL OK NOW DRIVE OPEN CAR PART TIME THRU ENGINE PERFORMANCE CHECK AND REPLACE THE THROTTLE PEDAL AS		VEHICLE HAS NO THROTTLE RESPONSE AT TIMES, AS IF THROTTLE IS NOT ATTACHED	280	USA	17887	EM	USA	*	144	FF	011
01.00	244.89	0.8	8088*	NA	MO	21801	CHECK FUEL PERFORMANCE TEST REPLACE AF ASBY AFTER POINPOINT TEST CLEAR CODES LEVER MECHANIC		ENGINE HAS NO THROTTLE RESPONSE	860	USA	12100	EM	USA	*	144	FF	011
01.00	172.4	1	7888*	NA	CA	21801	PERFORMANCE TESTS TRACE SHORT TO SHORT LEVER, REPLACE LEVER		CUSTOMER STATES NO THROTTLE RESPONSE/ADVICE	880	USA	17108	EM	USA	*	144	FF	011
01.00	208.88	1.8	7848*	NA	OK	18001	MSC QUICK TEST, DIAGNOSIS		ENGINE HAS NO THROTTLE RESPONSE	880	USA	14821	EM	USA	*	144	FF	011

WTR_C CST	TOT_CD ST_CD	LR S	PLU D	BU C	REN D	ST_P CD	CRG CD	TECH_TXT1	TECH_TXT2	CLNT_TXT	AREA CD	CLNT FL_CD	PLA FL_CD	DMR CD	DMRY CD	GRV CD	VPS CD	AMB CD	WTR CD	TR FLA CD
78.91	155.09	1.1	6592	*	NA	TKA	31891	1481 SUBJECT FOR NO RESPONSE ON HARD ACCEL. VERIFIED CONCERN BEC TIME HAS CODE P0130 ROAD TEST WITH WOB AND MONITOR DEL. DISPLAY ALL OK. PERFORM TEST AND REPLACE PEDAL ASSEMBLY ROAD TEST AND VERIFY DEL. THROUGH PEDAL, THROTTLE ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE. REPLACE	FINN CLEAR CODES, ALL OK NOW	NO PEDAL RESPONSE ON HARD ACCELERATION	380	USA	17580	2	USA	*	NA4	FT	311	
81.81	153.1	1	5471	*	NA	CA	31891			CLNT STATES OK FOR NO PEDAL RESPONSE	891	USA	171400	2	USA	*	NA4	FT	311	
80.81	84.34	0.5	8882	*	NA	AB	31891	REPLACED ACCELERATOR ASSEMBLY. PERFORM PERFORMANCE DIAG. NO CODES, MONITOR FUEL VOLTAGE ON ACC PEDAL, L, R, AND R PEDAL, RETEST, ROAD TEST		POOR ACCELERATOR PEDAL RESPONSE (CHITS OCCURED)	770	CAN	48000	2	CAN	*	NA4	FT	311	
78.95	339.43	4.7	684	*	NA	ND	31891			NO PEDAL RESPONSE AS IF COBLE UNHOOKED	888	USA	16700	1	USA	*	NA4	FT	311	
81.81	139.03	0.7	5418	*	NA	TK	31891	DRIVE THROTTLES UP WHEN HARD PRESS PEDAL. MONITOR ROAD TEST FOUND AP SENSOR TO STAY AT 10V AT TRIP. REPLACED ACCELERATOR PEDAL ASSEMBLY. RETEST. PASS. OK		CLNT STATES AT TIMES NOT PEDAL RESPONSE WHEN ACCELERATED	291	USA	18810	2	USA	*	NA4	FT	311	2
78.95	325.05	4	682	*	NA	TK	31891	OK NO PEDAL RESPONSE. RUN PERFORMANCE DIAGNOSTIC. REPLACE PEDAL ASSEMBLY (OPEN CIRCUIT) RETEST, OK (SEE P001)		OK NO PEDAL RESPONSE	420	USA	18200	2	USA	*	NA4	FT	311	
84.28	140.85	0.6	773	*	NA	MT	31891	OK CHANGE CODE FREEZE. PERFORM THROTTLE PEDAL ASSEMBLY SENSOR. BAD REPLACE THROTTLE PEDAL. CLEAR CODES. REBOOT OK		NO PEDAL RESPONSE AT TRIP	405	USA	17420	2	USA	*	NA4	FT	311	
78.95	352.27	1.6	2779	*	NA	QA	31891	NOISE TO RUN WILL NOT ACCELERATE HARD START. NO START DIAGNOSTICS. 7.5L DI TURBO ENGINE. D		NO PEDAL RESPONSE TO ACCELERATION	770	USA	25100	1	USA	*	NA4	FT	311	
84.28	165.05	1.6	2828	*	NA	AZ	31891	WIPER PEDAL ASSEMBLY. PERFORM DIAG. CONCERN WEG. TO ESC TEST CODE FREEZE IN MEMORY ROAD TEST MONITOR FUEL P0480 HAS STOPPED AT TRIP. WEG TO RETEST PERFORM TEST VERIFY WIPER TO PCM OR EPIC PEDAL ASSEMBLY	TO INTERNAL FALGURE ROAD TEST MONITOR FOR OK. REBOOT ALL P0480 P117	CHECK FOR NO PEDAL RESPONSE AT TRIP. PERFORM ACCEL PEDAL. RESPONSE FROM PULSATION. NO PEDAL RESPONSE. INTERMITTENTLY. NO ACCEL PEDAL RESPONSE.	780	USA	171170	2	USA	*	NA4	FT	311	
84.4	184.38	0.8	2828	*	NA	ME	31891	NECESSARY TO REPLACE AP SENSOR.			688	CAN	48000	2	CAN	*	NA4	FT	311	
81.81	107.17	0.8	3828	*	NA	ME	31891	REPLACED ACCELERATOR PEDAL. CHECK FOR NO PEDAL RESPONSE AT TRIP. PERFORM PERFORMANCE DIAG. CODES FREEZE. PERFORM TEST. CHECK FOR ON THROTTLE SWITCH. REPLACE PEDAL ASSEMBLY (OPEN CIRCUIT)		OK A FEW TIMES THERE WAS NO PEDAL RESPONSE. STARTED WIPERS AFTER LET UP. & RE APPLY	670	USA	18000	2	USA	*	NA4	FT	311	
80.81	257.47	3.4	684	*	NA	CK	31891	42 ENGINE PERFORMANCE DIAGNOSTIC. 7.5L DI TURBO ENGINE. GAS		OK AT TRIP WHEN LET START ENG. WHETHER HOT OR COLD HAS NO PEDAL RESPONSE AT ACCEL. PEDAL TO FLOOR ENG JUST BLEW LET OFF THROTTLE WORKS NORMALLY	880	USA	24070	2	USA	*	NA4	FT	311	
84.28	239.71	2	3828	*	NA	VT	31891	1 PERFORMED ENGINE PERFORMANCE DIAG. SUBJECT 1 14 CODES. PERFORM TEST. LATER THROTTLE PEDAL. WEG. PERFORMED CLEANITY CHECKS.		SUBJECT SAYS SOMETIME FEELS LIKE THERE IS NO PEDAL RESPONSE. LATER POWER	871	USA	28000	172	USA	*	NA4	FT	311	

WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT	WTRL_CHT	HTL_CHT						
NUM	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV	REV					
80.72	282.35	3.4	7884	NA	TX	31801	THROTTLE THROTTLE VEHICLE HAS NO RESPONSE WHEN APPLYING ACCELERATION PEDAL. PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY.	THROTTLE THROTTLE	CLUST TXT 0'S AT TIME, VEHICLE HAS NO RESPONSE WHEN APPLYING ACCELERATION.	291	USA	18142	292	USA	194	FF	871																								
81.82	157.12	8.8	7884	NA	CA	31801	THROTTLE THROTTLE DMS INSPECTED AND REPLACED THROTTLE PEDAL/INTAKE SYSTEM PASSAGE. RECHECK OK.		CHECK FOR INTER CK ACCEL NO RESPONSE.	170	USA	17282	285	USA	194	FF	871																								
81.82	148.34	1.3	4292	NA	PA	31801	TEST DRIVE THE VEHICLE TO DETERMINE IF THE PROBLEM IS REPEATABLE. PRESS AND PRESS FOUND THE 3-PROBLE P22		CUSTOMER STATES INTERMITTENT NO RESPONSE FROM ACCELERATOR. TEST DRIVE THE VEHICLE TO DETERMINE IF THE PROBLEM IS REPEATABLE. VEHICLE HAS NO RESPONSE FUEL PRESS. TEST.	126	USA	14472	289	USA	194	FF	871																								
80.84	104.78	6.4	8888	NA	LA	31801	MISS WARRANTY REPLACED THROTTLE PEDAL ASSEMBLY. CUSTOMER REPORTS THAT VEHICLE HAS NO RESPONSE FROM ACCELERATOR. PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY.		CUSTOMER STATES INTERMITTENT NO RESPONSE FROM ACCELERATOR. TEST DRIVE THE VEHICLE TO DETERMINE IF THE PROBLEM IS REPEATABLE. VEHICLE HAS NO RESPONSE FUEL PRESS. TEST.	126	USA	14472	289	USA	194	FF	871																								
78.62	384.62	4.2	4917	NA	TX	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.	L ASSEMBLY RETEST SYSTEM OK TEST DRIVE OK.	ENGINE STARTS BUT THERE IS NO RESPONSE WHEN PUSH PEDAL AT TIME.	281	USA	12384	283	USA	194	FF	871																								
78.62	148.48	1	8817	NA	CA	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		CLUST STAYS CK FOR NO THROTTLE RESPONSE AT TIMES.	80	USA	17128	285	USA	194	FF	871																								
81.82	150.7	1.3	3288	NA	TX	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		DIPPER RESPONSE WHILE DRIVING. NO RESPONSE FROM ACCELERATOR WHEN PRESSING. TRUCK LACKS POWER. D22		USA	12384	283	USA	194	FF	871																								
81.82	239.8	2.8	4888	NA	CA	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		CHECK FOR NO RESPONSE FROM THROTTLE.	422	USA	12384	283	USA	194	FF	871																								
78.62	171.45	0.4	8888	NA	TX	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		SOMETIMES THERE IS NO RESPONSE FROM THE ENGINE WHEN THE ACCELERATOR IS PRESSED.	81	USA	12384	283	USA	194	FF	871																								
81.82	165.82	1.4	488	NA	CA	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		CUSTOMER HAS COMPLAINED, ENGINE SHAKES, SHIMMERS GAS, NO RESPONSE WHEN YOUR OFF WITH SUDEN JERK. NO MIL.	234	USA	12384	283	USA	194	FF	871																								
80.84	273.32	3	382	NA	CA	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		CK CUSTOMER STATES AT TIMES THE THROTTLE HAS NO RESPONSE FROM GAS PEDAL. CK ACCELERATOR IS OK.	773	USA	12384	283	USA	194	FF	871																								
78.62	161.71	1	8888	NA	LA	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		NO NO RESPONSE FROM GAS PEDAL WHEN ACCELERATING.	888	USA	12384	283	USA	194	FF	871																								
78.62	458.18	8.4	2888	NA	TX	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		CUSTOMER STATES ENGINE INTERMITTENTLY HAS NO RESPONSE WHEN ACCELERATOR IS PRESSED.	813	USA	12384	283	USA	194	FF	871																								
78.62	151.81	1.3	8888	NA	TX	31801	PERFORM PNP POINT TEST. PUMP INSP PERF DIAG. P1133 REPLACED FUEL PRESS. ASSEMBLY. REPERFORM TEST. PROBLEM RESOLVED.		OCCASIONALLY NO RESPONSE FROM ACCELERATOR PEDAL. MUST PRESS GAS PEDAL THREE TIMES FOR RESPONSE.	871	USA	12384	283	USA	194	FF	871																								

DATE	TIME	TEST	DRIVER	VEHICLE	TEST	RESULT	REMARKS	TEST	AREA	COURT	FILE NO.	DATE	CHRYSLER	CHRYSLER	CHRYSLER	CHRYSLER	CHRYSLER	CHRYSLER	CHRYSLER	CHRYSLER			
7/23	10:47	2	7084	NA	CA	3/881	THROTTLE PEDAL CUSTOMER STATE LOSS OF POWER AND BLURRING AT TIMES WHEN GOLD STEP ON ACCEL AND ENGINE WOULD NOT RESPOND OR	718 USA	18881	02	USA												
7/28	12:21	8.7	7084	NA	CA	3/881	REPLACE THROTTLE PEDAL ASSEMBLY CHECK THROTTLE PEDAL ASSEMBLY. CUSTOMER STATES SOMETIMES NO RESPONSE FROM ACCELERATOR	718 USA	17100	02	USA												
8/1/81	12:50	8.8	8174	NA	MS	3/881	RESPONSE WILL NOW BE REPLACED GAS PEDAL	678 USA	11004	02	USA												
8/4	21:24	2.1	8724	NA	NC	3/881	REPLACE THROTTLE PEDAL	200 CAN	48218	02	CAN												
8/4	12:18	0.8	8703	NA	NC	3/881	DOGS AND REPLACED THROTTLE PEDAL	200 CAN	48200	04	CAN												
7/28	13:58	8.8	8055	NA	WA	3/881	RESTARTED IN AN ATTEMPT TO DIAGNOSE CONDITION OF NO THROTTLE RESPONSE FOR 30 TO 60 SEC. DID NOT DIAGNOSE ALTHO I DO NOTE THAT THE VEHICLE POWER LIGHTS BURNED UP A LITTLE THIS IS NORMAL DUE TO CHECKED FOR NO ACCELERATOR RESPONSE. PERFORMED EGRS, ROPE, INJECTOR AND FUEL TESTS. REPLACED THROTTLE POSITION SENSOR.	200 USA	17814	2	USA												
8/4	18:41	1.8	8703	NA	NC	3/881	PERFORMANCE DIAGNOSIS FOR PREPONT TESTS PD MONITOR, LOCATE FAULTY ACCEL PEDAL ASSEMBLY REPLACE RE RUN TESTS P1115 ON DRIVE CYCLE TESTS P1111 FUEL INJECTOR TESTS COOL ROAD TEST VEHICLE CHECK FLUID LEVEL AND CONDITION ELECTRONIC TRANSMISSION DMS CODES P0133 801 AP OUT OF RANGE AP FORCE	801 CAN	44703	04	CAN												
7/24	14:57	1.1	3140	NA	CO	3/881	THE OWNER STATES THERE IS NO RESPONSE FROM THE THROTTLE. THIS HAS HAPPENED AT LEAST THREE TIMES.	718 USA	18880	02	USA												
8/1/81	20:28	1.7	8332	NA	AZ	3/881	BASE PASSENGER SEATS THAT AT TIMES YOU CAN PUSH ON THE ACCELERATOR AND NO RESPONSE AND THE SHIFT TOWN END	800 USA	48980	04	CAN												
7/23	12:41	1	1889	NA	WI	3/881	NO RESPONSE FROM THROTTLE OWNER STATES THAT WHEN TAKING OFF THE VEHICLE FALLS ON ITS FACE, W/ ON AT TIMES NO THROTTLE RESPONSE.	718 USA	18838	04	USA												
7/28	18:17	1.4	7786	NA	CA	3/881	TEST DRIVE PERFORMED W/OUT DMS PREL/P001 MONITOR PER DMS TO INTERMITTENT (SOLE VALIDATION SWITCH REPLACED SWITCH CLEANED CODES) AND TEST OK	707 USA	17289	1	USA												
7/21	18:24	0.8	8230	NA	UT	3/881	INTERM NO NO RESPONSE WHEN PRESSING ACCELERATOR PERFORM FOR NO RESPONSE FROM ACCEL PEDAL INTERMITTENTLY S.O.P.	436 USA	18888	02	USA												
7/28	14:2	0.8	13082	NA	AK	3/881	PERFORMING PERFORMANCE DIAGNOSIS STEP 1 THRU STEP 6. REPLACED THROTTLE PEDAL	807 USA	48783	2	CAN												
7/28	20:44	4.4	788	NA	NY	3/881	PERF DMS OK AIR AND FUEL SYSTEM 20 W/ ON BOTH OIL HINDS IS NOT TEST I DID ALL ROAD TESTS HAD CODE P0021 DID ALL PERFORM TESTS AND REPLACE AIR PRESSURE SWITCH PEDAL ASSEMBLY NO CODES FOR T-TEST CLEAR AL	L CODES ROAD TEST REPEAT TEST	708 USA	17118	2	USA											

TOT_COST	TOT_DOLAR	MTPL_C	ST	GR	HR	DLR_C	BU	GRV	CD	REGN	ST_P	CD	CPSC	CD	TECH_DCT1	TECH_DCT2	TECH_DCT3	AREA	COUNT	BLK	DL	DR	CNTRY	PROV	VPR	MSB	WTL	TR	PLA
001	000	0	0	0	0	0	0	0	0	0	0	0	0000	0000				00	00	00	00	00	00	00	00	00	00	00	00
78.06	188.85	1.4	0312	*	NA	MI							31881		TECH_DCT1 REC TESTED NO CODES IN MEMORY. FOLLOWED PERFORM TEST AND MONITOR PED WHILE DRIVING. FOUND PEDAL SIGNAL MISSING AT TIMES. REPLACED SENSOR ASSEMBLY.	TECH_DCT2	TECH_DCT3 CUSTOMER STATES THROTTLE PEDAL UNRESPONSIVE INTERMITTENTLY, WHEN DRIVING FORWARD, PRESS ACCELL AND NO RESPONSE FROM ENGINE.	001	USA	16007	004	USA	*	004	07	011			
178.2	401.3	3.3	0807	*	NA	TX							10080		CHECK COMPLAINT AND PERFORMED ENGINE PERFORMANCE BENCH TEST AND PERFORMED TESTS FOR PEDAL AND SENSORS AND UPDATE CALIBRATION FOR PERFORMANCE NO OTHER PROBLEMS FOUND.		THE CUSTOMER COMPLAINS THAT AT TIMES WHILE DRIVING CEL CODES ON 3 & 5 BECOME LOCKED THROTTLE RESPONSE. ALSO COMPLAINS THAT ALL THE TIMES ENGINE SLURRS, ROUGH RUNNING.	016	USA	16128	003	USA	*	004	01	011			
170.72	284.47	1	0100	*	NA	OH							10080		PERFORMED SELF TEST, PERFORM TEST, OIL DISPLAY, AT TO REPLACE ACCELERATOR PEDAL.		CHECK INTERMITTENTLY NO RESPONSE FROM ACCELERATOR RESPONSE YOUNG PUSH ON PEDAL AND NO RESPONSE.	418	CAN	481042	004	CAN	*	004	01	011			
88.4	158.8	0.8	0100	*	NA	SC							31881		CHECK SYSTEM FOR PC AND PE PEDAL AND PERFORM PERFORM TEST MEMORY CODE PERFORM TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		THROTTLE PEDAL HAS NO RESPONSE NO RESPONSE TO ACCEL POSITION OCCASIONALLY ALSO SEEMED TO BACK AND AND JUMP SOMETIMES.	280	CAN	481042	003	CAN	*	003	07	011			
21.82	184.48	0.8	1001	*	NA	SC							31881		PERFORM TEST MEMORY CODE PERFORM TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		THROTTLE PEDAL HAS NO RESPONSE NO RESPONSE TO ACCEL POSITION OCCASIONALLY ALSO SEEMED TO BACK AND AND JUMP SOMETIMES.	008	USA	16100	003	USA	*	003	07	001			
140.1	326.88	4.2	0808	*	NA	TX							31881		PERFORMED TEST MEMORY CODE PERFORM TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		AT TIMES YOU ACCEL NO RESPONSE ON	008	USA	16100	003	USA	*	003	07	001			
81.98	281.78	2.1	0810	*	NA	CA							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		THROTTLE PEDAL HAS NO RESPONSE NO RESPONSE TO ACCEL POSITION OCCASIONALLY ALSO SEEMED TO BACK AND AND JUMP SOMETIMES.	008	USA	16100	003	USA	*	003	07	011			
81.82	258.82	1	0801	*	NA	CA							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		THROTTLE PEDAL HAS NO RESPONSE NO RESPONSE TO ACCEL POSITION OCCASIONALLY ALSO SEEMED TO BACK AND AND JUMP SOMETIMES.	008	USA	16100	003	USA	*	003	07	011			
81.82	128.22	1.8	0711	*	NA	CA							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		CUSTOMER STATES NO RESPONSE FROM ACCELERATOR PEDAL AT TIMES	008	USA	16100	003	USA	*	004	07	011			
78.06	188.85	0.8	0808	*	NA	MI							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		AFTER DRIVING A SHIFT THERE IS NO RESPONSE FROM THROTTLE	008	USA	16100	003	USA	*	003	07	011			
88.4	158.8	1.2	0808	*	NA	TX							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		GOOD CUSTOMER NOTES AT TIMES NOODING HAPPENS WHEN YOU PUSH ON ACCEL PEDAL. NO RESPONSE	008	USA	16100	003	USA	*	003	07	011			
88.4	158.8	0.8	0114	*	NA	MI							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		REPAIR THROTTLE HAS NO RESPONSE AT TIMES NOTHING	007	USA	16100	003	USA	*	003	07	011			
84.88	212.71	1	0808	*	NA	CA							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		INTERMITT NO RESPONSE FROM THROTTLE SEE 781	008	USA	16100	003	USA	*	004	07	011			
88.4	158.8	0.8	0708	*	NA	MI							31881		PERFORMED TEST MEMORY CODE PERFORMED TEST AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY AND UNIT DRIVE 1 HOUR RESPONSE TEST 1 1/4, FOUND ACCEL PEDAL ASSEMBLY OPEN CIRCUIT, WAS AIR FLOW SENSOR WOP, REPLACED ACCEL PEDAL, WASH AIR SENSOR, RESET TEST ENGINE TEST ENGINE AND WOULD SHUT OFF OR BACK TO IDLE AT TIMES AND WOULD NOT COME OFF IDLE. WOP SEC TEST, CODES WOP SEC.		BLUING RUSH NO RESPONSE ON ACCEL PEDAL	008	USA	16100	003	USA	*	003	07	011			

MITL_C CST	TOT_COLL ST BR CST	NR	CLR_C D	CLR_C D	NRN D	BT_P CD	CPAC CD S	TECH_TXT	TECH_CDZ	CLST_TXT	AREA CD	COUNT BY CD	MLE_D R CD	TDL CD	CHRY FIELD	ORDY CD	WFO CD	ARR VL CD	WRT CD	THE PLA S			
TELE	265.02	2.8	1487	NA	NA	NA	31881	PERFORMANCE DIAGNOSTIC, WIPER 1 17. FOR CONTINUOUS MEMORY ONLY FAULT CODE P0486, RUN PP TEST. VOLTAGE SWEEP-OF AP SENSOR SENDED AS LOG. DROPOUT AT APPROX 70% THROTTLE. REPLACE ACCELERATOR PEDAL.	ABBY. CLEAR CODES, ROAD TEST, RE TEST BEG PH11 TO VERIFY REPAIR.	NO RESPONSE FROM ACCELERATOR SENSOR PLUNTING PEDAL ALL THE WAY TO THE FLOOR, INTERMITTENT, WHEN HAPPENS SEEMS LIKE THE TRACK WOULD EVENTUALLY SET.	000	USA	18809	USA	NA	NA	NA	NA	NA	NA	NA		
TELE	188.44	1.5	2673	NA	NA	NA	31881	SENSOR P0486 P04C TEST CODE FOR P0486 POINT TEST OK AND CODES CONNECT AP SENSOR WITH NEW CONNECTOR. JUMPER WIRE FROM TO AP SIGNAL WIRE. SCAN READ AS VOLTS. REPLACE PNL. ACCELERATOR PEDAL ASY		C IS AT TIMES THERE IS NO RESPONSE FROM ENGINE WHEN ACCELERATOR PEDAL IS PRESSED	000	USA	17178	USA	NA	NA	NA	NA	NA	NA	NA		
ELI	201.42	1.8	2304	NA	NA	NA	31881	INSPECT FOR NO RESPONSE FROM THROTTLE PEDAL. RUN DRIVEL. CODE NO CODES, MONITOR P0486 ON ROAD TEST. P0486 TEST. NEEDS REPLACED THROTTLE PEDAL AND RESET OK.		CLIENT STATES POOR POWER NO RESPONSE AS ACCEL UP HILL AFTER COLD START INTERMITTENTLY. SEE HISTORY.	000	USA	17488	USA	NA	NA	NA	NA	NA	NA	NA	NA	NA
ELI	201.42	1.8	2304	NA	NA	NA	31881	NEED WASH SERVICE FOR CHECKING NO THROTTLE RESPONSE. CHECK CODES. HAD CODES P0486 IN MEMORY. GO TO PP7 S05. GO TO LEARN TO REPLACE CONDOR. USE NEW TO GET WFO DATA. ROAD TEST AND WIRE REC	OPENING OF AP VOLTAGE WOULD RELEASE TO DROP TRACKS WITH W/KEEP THROTTLE. REPLACE PEDAL ASSEMBLY. CLEAR CODES. ROAD TEST ASSEMBLY GET SERVIC AP READINGS AND CODES DO NOT RESET.	CLST REPORTS WASH SERVICE AND RECENTLY HAD NO RESPONSE FROM THROTTLE. CHECK AND REPORT.	000	USA	17488	USA	NA	NA	NA	NA	NA	NA	NA	NA	NA
TELE	181.42	1.8	2620	NA	NA	NA	31881	SEC TEST P0486/REPLACE PEDAL AND ASSEMBLY		THERE IS NO RESPONSE WHEN THE ACCELERATOR PEDAL IS DEPRESSED. RESPONSE WILL ACCELERATE IF PEDAL IS HELD DOWN.	001	USA	02884	USA	NA	NA	NA	NA	NA	NA	NA		
ELI	148.4	1.1	4026	NA	NA	NA	31881	OPEN IN TP SENSOR. TEST DRIVE, RUN PERFORMANCE DIAG. STEPS 1-6, PERFORM PP TEST P01 AND P0486. P0486 YES. REPLACE PEDAL ASSEMBLY. QUALITY DATA. THROTTLE PEDAL INSPECTOR REPLACED THROTTLE PEDAL AND RESET OK.		C IS AT TIMES ON START UP AND PRESSING ACCELERATOR PEDAL NO RESPONSE	000	USA	15229	USA	NA	NA	NA	NA	NA	NA	NA	NA	
ELI	201.76	2.4	7789	NA	NA	NA	31881			INSPECT FOR NO THROTTLE RESPONSE AT TIMES. C IS AND ASY/ CLST STATES THAT THERE IS A SENSOR ON THE ACCEL PEDAL. THERE IS NO RESPONSE FROM ACCEL PEDAL.	000	USA	17298	USA	NA	NA	NA	NA	NA	NA	NA		
ELI	178.88	0.5	3739	NA	NA	NA	31881	INTERNAL FAULT TEST SYSTEM AND REPLACE PEDAL ASSEMBLY ROAD TEST FOR CONDOR P0486 CHECK ENGINE LIGHT BLINKS AND GOES TO SOL. PERFORM DRIVEL. DRIVEL PERFORM DRIVEL. DISPLAY TEST PERFORM PERFORM ROAD TEST NECESSARY TO REPLACE PEDAL ASSEMBLY. P0486 TEST OK.		INSPECT FOR NO THROTTLE RESPONSE AT TIMES. C IS AND ASY/ CLST STATES THAT THERE IS A SENSOR ON THE ACCEL PEDAL. THERE IS NO RESPONSE FROM ACCEL PEDAL.	000	USA	08402	USA	NA	NA	NA	NA	NA	NA	NA	NA	
ELI	318.78	4	7492	NA	TX	NA	31881	INTERNAL FAULT TEST SYSTEM AND REPLACE PEDAL ASSEMBLY ROAD TEST FOR CONDOR P0486 CHECK ENGINE LIGHT BLINKS AND GOES TO SOL. PERFORM DRIVEL. DRIVEL PERFORM DRIVEL. DISPLAY TEST PERFORM PERFORM ROAD TEST NECESSARY TO REPLACE PEDAL ASSEMBLY. P0486 TEST OK.		NO C IS WHEN PARKING. VEHICLE HAS NO RESPONSE FROM ACCEL. PEDAL.	001	USA	18232	USA	NA	NA	NA	NA	NA	NA	NA	NA	
ELI	328.42	4.5	4283	NA	TX	NA	31881	NOV WASH PERFORMANCE TEST 1.23. REPLACED ACC ASSEMBLY PEDAL. RESET.	ACCEL PEDAL	AT TIMES WHEN DRIVING IT GAS THERE IS NO RESPONSE FROM PEDAL. LOCK A RESPONSE. AND	000	USA	38184	USA	NA	NA	NA	NA	NA	NA	NA		
ELI	173.66	0.9	8884	NA	TX	NA	31881	OPEN CIRCUIT NO OPS REPLACED ACCELERATOR PEDAL SENSOR ASSEMBLY		CLST STATES ACCELERATOR PEDAL TURNS NO RESPONSE AT TIMES.	000	USA	28840	USA	NA	NA	NA	NA	NA	NA			
ELI	359.07	4	3682	NA	TX	NA	31881	NEW ONE AND FULL TESTS P0486 P022 P022 MONITOR P0486 AND FOUND AP SENSOR FROM TV. REPLACE AP ASSEMBLY. RESET 1 RUN ALL PERFORMANCE DIAGNOSTIC TESTS. MONITOR P0486 ON ROAD TEST. PP7 POINT TEST CODES, P022 P022, REPLACED TP SENSOR		THERE THERE HAS BEEN NO RESPONSE WHEN PRESSING PEDAL	001	USA	05200	USA	NA	NA	NA	NA	NA	NA	NA	NA	
ELI	285.78	4.4	3081	NA	TX	NA	31881	NEW ONE AND FULL TESTS P0486 P022 P022 MONITOR P0486 AND FOUND AP SENSOR FROM TV. REPLACE AP ASSEMBLY. RESET 1 RUN ALL PERFORMANCE DIAGNOSTIC TESTS. MONITOR P0486 ON ROAD TEST. PP7 POINT TEST CODES, P022 P022, REPLACED TP SENSOR		SEE LITE COMES ON AND LOCKS ON PEDAL RESPONSE	000	USA	08177	USA	NA	NA	NA	NA	NA	NA	NA	NA	

MTR_C	TOY_CO	LR	LN	BLR	NR	ST_P	CPCC	TECH_TXT	TECH_TXT	CLBY_TXT	AREA	COUNT	BLR_D	TOL	CRTRY	GRD	VFB	AMB	WT	TBL
CDT	ST	HR	D	CD	CD	CD	CD				CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
81.82	275.85	3.4	7897*	NA	CA	31801	17; VERIFY VEHICLE DOES NOT ACCEL, FOR ALL TESTS PER T3E DIAG SHEET, FOUND NO VOLTAGE CHANGE FROM A/B SENSOR AT TERM, REPLACE ACCELERATION PEDAL ASSEMBLY, RECHECK DL AT THE TIME		CHECK WHITE BRUSH FROM 204-SUB1 INTERMITTENTLY CLUT (SUCH NO RESPONSE WHEN TRYING TO ACCEL)	620	USA	17848	872	USA	"	141	FT	811		
81.82	118.80	0.8	8804*	NA	MI	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		LACK OF RESPONSE ON ACCL. W/ HOLD, OK BY 3498M	225	USA	88034	884	CAN	"	141	FT	811		
118.80	418.34	4.7	9539*	NA	TX	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		REPAIR BUSHES CUTS CUT WHILE DRIVING, PERD. 1.0000 RESPONSE	230	USA	182148	884	USA	"	142	FT	811		
76.88	287.88	3.8	221*	NA	IL	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		OK ACCELERATION NO RESPONSE AT TIME	324	USA	211871	884	USA	"	141	FT	811		
85.4	134.88	1.1	78867*	NA	MI	31801	CHECK FOR NO THROTTLE RESPONSE, PERFORM BENCH PERFORMANCE TEST, MONITOR FOLDING FACILITY AP SENSOR, REPLACE THE FAULTY AP SENSOR AND RE-TEST, OK BY 8022		NO RESPONSE WHEN ACCELERATION DECREASED	790	CAN	659284	2	CAN	"	144	FT	811		
188.20	590.88	1.8	6484*	NA	UT	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM	BLEB REMOVED AND REPLACE ESP CLEAR CODES AND RE-TEST, CHECK TEST PASS IN 8943 OUT 8932	GUEST STARTS WHEN PRESSING ON FUEL PEDAL THERE IS NO RESPONSE, CHECK AND ADV, IT WAS FUEL COMING DOWN TO SHOP.	397	USA	129288	872	USA	"	141	FT	811		
76.88	382.81	2.8	3688*	NA	CA	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		RAB PEDAL, HAS NO RESPONSE B.C.P.	920	USA	170081	2	USA	"	147	FT	811		
81.82	176.77	1.4	3488*	NA	TX	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		CUSTOMER REPORTS NO ENGINE RESPONSE TO THROTTLE FOR A FEW SECONDS ABOUT THE TIME AFTER START UP.	817	USA	188487	874	USA	"	144	FT	811		
76.88	254.88	4	3828*	NA	TX	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		CUSTOMER STATES TRUCK WENT DOWN TO IDLE WHILE (DRIVING) AND NO RESPONSE WHEN PRESSING PEDAL B.C.	387	USA	129288	872	USA	"	141	FT	811		
80.84	114.88	0.4	3838*	NA	MO	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		NO ENGINE RESPONSE WHEN ACCELERATOR DECREASED OR NO RESPONSE FROM ACCEL PEDAL, JUST IDLE	920	USA	192887	2	USA	"	143	FT	811		
81.82	204.88	2	138*	NA	VA	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		CS INTERMITTENTLY WHEN START ENGINE WHEN PUT IN GEAR AND HIT ACCEL THERE IS NO RESPONSE AT ALL. ENGINE JUST STAYS AT IDLE	634	USA	52788	870	USA	"	141	FT	811		
76.88	106.81	0.4	8864*	NA	OK	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM		NO RESPONSE FROM ACCELERATOR PEDAL AFTER WARMED UP	880	USA	192887	1	USA	"	144	FT	811		
81.82	288.88	2.4	148*	NA	NV	31801	PERFORM BENCH PERFORMANCE TEST, POST-2012 CASE 35M (VALVES) REPLACE ACCEL PEDAL ASSEM	REPL. ACCEL. PEDAL ASSEM TESTED ROAD TEST OK			790	USA	211770	884	USA	"	144	FT	811	

INTR. C DNT	TOY_CD	LYR	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC	PLC					
78.99	18.18	1.3	419*	NA	TX	21891	TRSH	TRSH																								
							TRSH	TRSH																								
LED VALVE/IGNITION SWITCH SHORTED FROM NOT UPDATED ROAD TEST TO VERIFY CONCERN. WIRE START UP, WIRE SWO TEST POWER, DCL DISPLAY, PROPORT TEST PSL REPLACE ACCELERATOR PEDAL ASSEMBLY AND REPROGRAM PCM. RETEST										AND ROAD TEST			THE REPAIR HIT NO RESPONSE FROM ONE PEDAL	278	USA	10999	289	USA	*	349	L1	871										
81.81	26.13	3.1	446*	NA	TX	21891	TRSH	TRSH																								
							TRSH	TRSH																								
PERFORMANCE DIAGNOSTIC 7.3L DI TURBO ENGINE DME STAR TEST, ROAD TEST, ACCESS PDL PROBLEM IDLE VALVE/IGNITION SWITCH													NO RESPONSE FROM ACCELERATOR	889	USA	18280	3	USA	*	364	FT	871										
81.4	18.14	1.8	469*	NA	TX	21891	TRSH	TRSH																								
							TRSH	TRSH																								
REPLACE ACCELERATOR PEDAL PERFORM TESTS; MONITOR AND CHECK CODE FOR TP SWITCH; CHECKED CONNECTOR AND WIRING. REPLACED PEDAL ASSEMBLY; ROAD TESTED. CHECKED OK													DIRTY LACK OF RESPONSE FROM ACCELERATOR	288	CAN	48880	3	CAN	*	371	FT	874										
81.52	17.08	8.7	486*	NA	GA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
CUSTOMER STATED LOSS OF ACCELERATOR RESPONSE													ACCELERATOR RESPONSE	678	USA	14727	285	USA	*	344	FT	871										
81.52	21.52	8	5130*	NA	CA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
REPLACED PEDAL PART ONLY													THROTTLE HAS NO RESPONSE	208	USA	18880	285	USA	*	344	FT	871										
78.88	17.18	8.7	2477*	NA	CA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
ACC PEDAL ASSEMBLY. NEW TEST WOULD ACCELERATOR PEDAL. ROAD TESTED													CUSTOMER STATES OK FOR NO THROTTLE RESPONSE ON ACC	881	USA	17188	284	USA	*	344	FT	871										
81.01	18.01	1.4	28012*	NA	CA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
PERFORM TSB TESTS RECEIVED CODES P0248 P0249 P024A FOR ACCELERATOR PEDALS PERFORMED CHECKED OK													CUSTOMER SAYS THERE IS NO RESPONSE WHEN PRESSING ON THE ONE PEDAL	881	USA	16020	272	USA	*	341	FT	871										
78.88	21.88	3.3	8108*	NA	MD	21891	TRSH	TRSH																								
							TRSH	TRSH																								
CHECKED THROTTLE RESPONSE. DME DI, STEPS 1 & 4. CODES P0248 P0249 TEST PE R AND R. REPLACE ACC PEDAL ASSEMBLY													SOMEHOW THROTTLE HAS NO RESPONSE	878	USA	18820	1	USA	*	344	FT	871										
81.52	23.15	2	8830*	NA	VA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
INSPECTED AND RECORDED CONNECTION TO THROTTLE PEDAL ASSEMBLY. REPLACED THROTTLE PEDAL ASSEMBLY AND RE TESTED OK													REPAIR FOR THE VEHICLE HAD NO THROTTLE RESPONSE. CUSTOMER STATES WHILE DRIVING AT TIMES VEH HAS NO THROTTLE RESPONSE	208	USA	18880	272	USA	*	344	FT	871										
80.81	20.71	1.8	2477*	NA	CA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
PERFORMANCE DIAGNOSTIC 7.3L DI TURBO ENGINE DME STAR TEST, ROAD TEST WITH NEW CODE P0248. PROPORT TEST. REPLACED ACCELERATOR PEDAL ASSEMBLY AND CLEAN CONNECTIONS AND REPROGRAM PCM													REPORT NO RESPONSE WHEN APPLYING THE THROTTLE TO ACCELERATE	878	CAN	48880	184	CAN	*	348	FT	871										
81.4	18.14	1.1	28241*	NA	CA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
CHECK TP RESPONSE. DME DIAGNOSTIC PERFORM PROPORT TESTS AND REPLACE ACCELERATOR PEDAL ASSEMBLY													CHECK ACCELERATOR WONT OPERATE AT TIMES HAS NO RESPONSE	418	USA	14720	272	USA	*	341	FT	871										
81.52	14.52	0.8	8573*	NA	VA	21891	TRSH	TRSH																								
							TRSH	TRSH																								
REPLACED THE GAS PEDAL													ONE PEDAL NO RESPONSE	878	USA	11204	284	USA	*	341	FT	871										
82.78	22.78	1.8	788*	NA	TX	21891	TRSH	TRSH																								
							TRSH	TRSH																								
WIRING. CODES P0248. PERFORMED PROPORT, RAM ALL TESTS. CHECKED HCU PROBLEMS AND LEADDOWN. REPROGRAM PEDAL CHECKED WIRING AT ACC. PEDAL. FOUND ACC. PEDAL SWITCH STUCK. REPLACED ACC. PEDAL SWITCH										MISC ASSEMBLY. RETESTED OK			NO RESPONSE WHEN PRESSING THE ACCELERATOR	874	USA	12278	3	USA	*	341	FT	871										
78.1	8.1	8.3	8361*	NA	TX	18031	TRSH	TRSH																								
							TRSH	TRSH																								
ACCELERATOR PEDAL ASSEMBLY FALLY TEST DRIVE AND WIRING COMPLANE. RAM ALL ENGINE PERFORMANCE TESTS AND MONITORED ALL NECESSARY PEDALS													THERE IS NO RESPONSE WHEN THE ACCELERATOR PEDAL IS DEPRESSING COMPLETELY	874	USA	12280	285	USA	*	344	FT	871										

MTR, C ST, SA CST	TOT. CO EST.	LBR NR	DAR, C D	CUR BU C LC D	RESN CD	ST. P CD	CPRC CD	TECH. YST1	TECH. YCT2	CART. TST	AREA CD	COUNT CT	BLA. DL FL. CD	TOTAL CD	CHRY. SOLD	MPT CD	MFG CD	MGR L. M.	MGT CD	TR. PLA P.
180.28	240.2	6.4	A3038	*	MA	CA	100001	THROTTLE PEDAL ASSEMBLY & TPS WAS TEST & CLEAR CODES & ROAD TEST.		REPAIR FOR NO RESPONSE FROM THROTTLE.	804	GBH	44200	1	CAN	*	V44	ET	311	
172.3	338.85	2.9	32147	*	VA	VA	100001	32147-022 ROAD TESTED VEHICLE FOR TO WHEELS ON HIGHWAY AND COULD NOT VERIFY RESPONSE I DID NOTICE THAT ENGINE DOES NOT SOUND RIGHT LIKE A TURBO WHILE DIE A LOOSE CLAMP RAN OUT OF THE ENGINE FLUIDS ON 1964 START CHECKS OUT. HAS NUMEROUS CODES. D22Z DYS. M05. P201E1E. 110L1501 CHECK OUT T P CIRCUIT AND ORDER NEW T P ASSEMBLY. INSTALL NEW T P ASSEMBLY. ROAD TEST TO PLEASANT T AND MARK. ROAD TEST 1 T P IS INSTALLED SPECIAL ORDER PEDAL ASSEMBLY. TEST DRIVE PERFORMED REC TEST. ALL OK AT THIS TIME.	AG 304 INSTALL ACCELERATOR PEDAL. ROAD TEST VEHICLE, UNABLE TO DUPLICATE LOSS OF THROTTLE RESPONSE. 302	CUSTOMER STATES THROTTLE HAS ON RESPONSE AFTER DECEL. ON HIGHWAY IS AN INTERMITTENT PROBLEM.	473	USA	12000	304	USA	*	V47	ET	311	
159.56	543.91	4.9	3132	*	VA	CA	100001		TESTED THROUGH COMMERCE CITY. POWER GOOD AND NO CODES PRESENT AFTER ROAD TEST.	CUSTOMER COMPLAINS DUTY TRUCK NO THROTTLE RESPONSE LOW POWER INTERMITTENT INTERMITTENTLY VEHICLE WOULD NOT MOVE FROM PARK. WOULD PUT IN SEAR, PUSH ACCEL PEDAL, NO RESPONSE. ON THE HIGHWAY AFTER THE VEHICLE HAS BEEN SITTING, WHEN MOVING TO ACCEL THERE IS NO RESPONSE. ALSO HE STATES THAT HE HAS TO ADD OIL TO ENGINE EVERY 1000 MILES	303	USA	4900T	2	CAN	*	V41	ET	311	
183.70	309.19	0.8	3507	*	VA	NY	100001			NO RESPONSE WHEN PENDING ACCELERATION CUSTOMER STATES AT TIMES WHEN MOVING TO ACCELERATE, NO RESPONSE. CUSTOMER MY THE WANTS A COUPLE OF TIMES THEN WILL START TO ACCELERATE	718	USA	14479	1	USA	*	V48	ET	311	
81.98	177.28	1	7798	*	VA	CA	2140	1944 HUB SWITCH TEST, OK. VEHICLE, OK. NO CODES. ROAD TEST, VERY INTERMITTENTY WOULD ON HOT. HUB PEDAL, ASSEMBY.		ON THE HIGHWAY WHEN NOT MOVING WHEN PUSHING ON THE THROTTLE PEDAL. PERFORMED PERFORMANCE CHECK STEPS 1 TO 9 AND HAD A CODE OF P02E1. PERFORMED PERFORM TEST AND REPLACED THE THROTTLE PEDAL WAS TO P.		679	USA	17821	204	USA	*	V51	ET	311
81.93	115.85	0.6	8492	*	VA	LA	31921	8492-001 HUB TEST CODE P02E1. P02E1. D210P04 IN ACCEL. PEDAL. SWITCH REPLACE ACCEL PEDAL ASY. CODE 30 RUN ALL NECESSARY TESTS ON ENGINE OFF. KEY ON. ENGINE RUN. PERFORM TEST. HUB. P02E1. P02E1. REPLACE ACCELERATOR PEDAL, ASSEMBY		NO RESPONSE WHEN PENDING ACCELERATION CUSTOMER STATES AT TIMES WHEN MOVING TO ACCELERATE, NO RESPONSE. CUSTOMER MY THE WANTS A COUPLE OF TIMES THEN WILL START TO ACCELERATE	327	USA	18204	372	USA	*	V47	ET	311	
81.82	227.6	2.1	2166	*	VA	OH	31921	PERFORM VEHICLE WOULD NOT MOVE WHEN PUSHING ON THE THROTTLE PEDAL. PERFORMED PERFORMANCE CHECK STEPS 1 TO 9 AND HAD A CODE OF P02E1. PERFORMED PERFORM TEST AND REPLACED THE THROTTLE PEDAL WAS TO P.		276	USA	14492	372	USA	*	V41	ET	311		
78.86	189.72	1.7	8891	*	VA	VA	31921	PERFORM CHECK FOR CODES WITH HUB SENSOR ON. DISPLAY SELF TEST. P02E1. P02E1. HUB CLEAR NETWORK. CONT. DTC P02E1. CHECK CIRCUIT FOR SHORT TO GROUND. OK. CHECK CIRCUIT FOR SHORT TO POWER. OK. CHECK FOR POWER.	5 PROBLEMS. ROAD TESTED OK.	ON ACCELERATION PEDAL STOP AT CRUISE THERE IS NO RESPONSE	808	USA	12548	304	USA	*	V49	ET	311	
81.92	149.0	0.8	7808	*	VA	MI	31921	PERFORM CHECK FOR CODES WITH HUB SENSOR ON. DISPLAY SELF TEST. P02E1. P02E1. HUB CLEAR NETWORK. CONT. DTC P02E1. CHECK CIRCUIT FOR SHORT TO GROUND. OK. CHECK CIRCUIT FOR SHORT TO POWER. OK. CHECK FOR POWER.	OK. PERFORM RESISTANCE TEST WHILE DISPRESSING PEDAL. PEDAL STOP AT 3 DIFFERENT POSITIONS. REPLACED THROTTLE POSITION SENSOR. ROAD TEST. HUB TEST. 378 PASS.	OWNER STATES INTERIM THROTTLE STOPS NO RESPONSE BACK OFF CLAY	820	USA	18271	304	USA	*	V44	ET	311	
195.51	323.2	3.3	30850	*	VA	VA	100001	CHECKED AND REPLACED APVVE ASSEMBLY		CUSTOMER STATES GAS PEDAL HAS NO RESPONSE. PEEK & LOOKS FOR REPAIRS.	892	CAN	44070E	2	CAN	*	V17	ET	308	
78.86	127.89	0.7	8877	*	VA	VA	31921	CHECKED AND REPLACED ENGINE PEDAL ASY. ROAD TESTED OK. CHECK FOR INTERMITTENT CHECK ENGINE LIGHT ON. NO RESPONSE FROM ENGINE UPON ACCELERATION. PERFORM ENGINE PERFORMANCE TESTS 1, 7, REPERFORM DTC PERFORM TEST AND DATA MONITOR TEST. REPLACE ACCEL ASY.		CHECK ACCELERATOR FOR NO RESPONSE AT CRUISE	888	USA	13170	2	USA	*	V44	ET	311	
84.4	171.49	1.8	A3030	*	VA	VA	31921	CHECKED AND REPLACED ENGINE PEDAL ASY. ROAD TESTED OK. CHECK FOR INTERMITTENT CHECK ENGINE LIGHT ON. NO RESPONSE FROM ENGINE UPON ACCELERATION. PERFORM ENGINE PERFORMANCE TESTS 1, 7, REPERFORM DTC PERFORM TEST AND DATA MONITOR TEST. REPLACE ACCEL ASY.	OK PEDAL ASSEMBLY, ROAD TEST AND W/TEST. ALL TESTS PASS. VEHICLE OK.	REPAIR FOR NO RESPONSE FROM ENGINE WHEN HUB PEDAL DEPRESSED.	488	CAN	44070D	304	CAN	*	V47	ET	311	
181.44	281.5	1.8	38970	*	VA	OH	100001	PERFORM TEST CODE P02E1. NO RESPONSE FROM THROTTLE SENSOR. REPLACE PEDAL ASSEMBLY		CHECK THROTTLE PEDAL. NO RESPONSE	705	CAN	49200	304	CAN	*	V44	ET	311	

MPVLS CITY	TOTY_CD ST OR CSE	LR FR	DLR_CD D	DLR_C C	DLR ON	ST_P CITY	CPRO CD	TECH_TXT1	TECH_TXT2	CURT_CD	AREA CD	COUNT BY CD	MIL_CD R CD	DR CD	CHRY SOLD	CHRY CD	ANS VL CD	WTL CD	TBL PLA S
81.62	481.64	3.8	4853		NA	TX	21801	REINSTALLED OLD POMACHENGED FOR OPEN IN CIRCUITS AT TP SENSOR REPAIRED AND REPLACED THROTTLE POSITION PEDAL ASSEMBLY AND TO REMOVE CUSTOMER INSTALLED SILE ROOBER CONNECTOR AND BUILT OUT OF BODY TO BE RE INSPECTED AND CHECK TEST NO DTC COMMAND TEST KODJADDER NO DTC. PERFORMED PIN POINT TEST ON ACCELL PEDAL SENSOR RELIEVED AND REPLACED WITH NEW ACCELL PEDAL ASSEMBLY RESET SYSTEM AND ROAD TESTED SVTITE	OK/REPLACED AND TEST DRIVE CHECKED FOR CODE NONE RUNNING FINE.	CUS SAYS HAS NO RESPONSE FROM ACCELL PEDAL	804	USA	10000	004	USA	*	1448	FF	011
78.89	821.33	1.4	4472		NA	TX	21801	PERFORMED PIN POINT TEST ON ACCELL PEDAL SENSOR RELIEVED AND REPLACED WITH NEW ACCELL PEDAL ASSEMBLY RESET SYSTEM AND ROAD TESTED SVTITE	IN PARKED.	CUSTOMER STATES THAT VEHICLE WILL HAVE NO PEDdle RESPONSE AT THROTTLE WHEN TOWED.	800	USA	10162	004	USA	*	1441	FF	011
83.86	091.05	1.4	3395		NA	TX	21801	CHECK OUT .SEC TEST. TEST DRIVE WILL MONITORING. INTERMITTENTLY DOES T		OK/ACCELERATOR SOMETIMES HAS NO RESPONSE CHECK WHEN TRYING TO ACCELERATE THE VEHICLE WONT GO. ACTS LIKE NOT GETTING RESPONSE FROM PEDAL.	800	USA	10000	004	USA	*	1441	FF	011
78.86	144	8.8	7886		NA	NY	21801	INOP KODC P0201 0122 P0201 AND REPLACE TP SENSOR PEDAL ASSEMBLY. RETEST		CHECK WHEN TRYING TO ACCELERATE THE VEHICLE WONT GO. ACTS LIKE NOT GETTING RESPONSE FROM PEDAL.	700	USA	10000	004	USA	*	1441	FF	011
81.62	204.87	1.7	7877		NA	CA	21801	THE VEHICLE WAS TOWED IN THERE IS NO RESPONSE FROM THE ACCELERATOR PEDAL. TESTS INDICATE A FAULT IN THE ACCELERATOR PEDAL SENSOR. REPLACED THE ACCELERATOR PEDAL ASSEMBLY. RECHECKED OPERATION	OK. THIS REPAIR IS COVERED BY THE DIESEL ENGINE WARRANTY. THE CUSTOMER WYS A BARELO CREDIBLE FOR THIS REPAIR.	THE VEHICLE WAS TOWED IN. CUSTOMER STATES THERE IS NO RESPONSE FROM THE ACCELERATOR PEDAL. INSPECT AND ADVISE.	880	USA	14727	002	USA	*	1441	FF	011
81.62	132.34	1	1821		NA	VA	21801	SEC TEST CODE P0201 PRESENT NONE FOR FUEL PEDAL ASSEMBLY PERFORM PIN POINTS PER P0201 FOUND PEDAL ASSEMBLY OPEN CIRCUIT POINT TEST P1 NEED TO REPLACE FUEL PEDAL ASSEMBLY CLEAR DTC AND RESET SYSTEM PASS		CUSTOMER COMPLAINT OF NO RESPONSE FROM FUEL PEDAL ON HARD CLACK AND VIBRATION	200	USA	14247	004	USA	*	1441	FF	011
80.28	135.28	0.8	2111		NA	MA	21801	IS ACTUALLY FOR EOL. REQUIRED REWORKING.		CUSTOMER STATES THAT AFTER VEHICLE IS DRIVEN AWAY WITH CRUISE CONTROL ON. WHEN CUSTOMER STEPS ON GAS TO PASS. CEL FLASHER AND SETS NO RESPONSE.	410	USA	10000	004	USA	*	1448	FF	011
78.86	212.05	1.6	4880		NA	FL	21801	CONFIRM CONCERN. PERFORM PIN POINTS & OBTAIN DTC OF P0201. INVOKE ACCESS TO & REPLACE FAULTY ACCELL PEDAL ASSEMBLY. VERIFY REPAIR ALL AP FUNCTIONS ARE NORMAL AT THIS TIME. NO DTC, MO S.		CUS SAYS HAS NO RESPONSE FROM ACCELL PEDAL	804	USA	10000	004	USA	*	1441	FF	011
81.62	189.08	1.7	5071		NA	CA	21801	PEDAL ASSEMBLY REPLACE ACC PEDAL ASSEMB INOP		CUSTOMER STATES CK FOR NO THROTTLE RESPONSE OVER 40 MPH WHEN ACCELERATOR NO RESPONSE INTERMITTENTLY	801	USA	17171	004	USA	*	1441	FF	011
78.86	189.72	1.1	7782		NA	CA	21801	ROAD TEST AND INSPECT REPLACE PEDAL ASSEMBLY AND RETEST.		WHEN THE THROTTLE PEDAL IS PUSHED IN THERE IS NO RESPONSE IN THE VEHICLE.	200	USA	17201	004	USA	*	1441	FF	011
78.86	88.8	0.3	4893		NA	TX	21801	REPLACED FOOT PEDAL ASSEMBLY THROTTLE PEDAL ASSEMBLY. BAL. 12800. DRY. DNE ACCELL PEDAL GRM TIME DNE ENGINE WONT RESPOND AT THIS. SLES ONLY. FOUND CODES P0201, P134B, P1811, IN HARD COGNIZABLE. CODE P0201 IN HOBO.	AFTERMARKET CHIP. PERFORM PIN POINT TEST. REPLACED ACCELL PEDAL ASSEMBLY. CLEAR CODES. TEST. TEST. REPEAT. OK.	WHP. NO THROTTLE RESPONSE AT THROTTLE RANDOMLY. ACTS LIKE THROTTLE PEDAL NOT CONNECTED	810	USA	10000	004	USA	*	1441	FF	011

PE03-044-A 5436

ATVL_C	TOT_COL	ST_GA	HR	CL	CL	CL	CL	RESN	ST_P	OPAC	TECH_TXT1	TECH_TXT2	CLMT_TXT	AREA	COUNT	BLR	TML	CHRY	CRV	WFO	AMB	WFO	TFL
ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST	ST
81.88	208.18	4.7	2094	*	NA	AZ	3188				7.3 DIESEL ENGINE PERFORMANCE DIAG. STEPS 1 TH. ELECTRICAL PERFORM TEST. TRACE TO INTERMITTANT A.P. SENSOR. REMOVE AND REPLACE A.P. SENSOR. RESEAL OIL.		CUSTOMER STATES THAT VEHICLE IS LOOSER POWER PLEASE ADVISE NO THROTTLE RESPONSE.	888	USA	17147	578	USA	*	141	PT	811	
78.88	217.20	2.8	2182	*	NA	CO	3188				THIS IS A SERVICE BRANT WARRANTY, PREVIOUS RO 808888, DATED 05.28.81, ACCUMULATED MILES 207, PERFORMED DIESEL PERFORMANCE DIAGNOSTIC PERFORMED PERFORM TEST & REPLACED THROTTLE PEDAL ASSEMBLY. AP NOT CLOSING IN BATTERY, NECESSITY TO REPLACE AP.		CUSTOMER STATES WHEN VEHICLE IS WARM AND THE TRUCK IS FLOORED THERE IS NO RESPONSE TO THROTTLE PEDAL. CUSTOMER STATES HAS NO THROTTLE RESPONSE.	888	USA	18881	828	USA	*	141	PT	811	
78.88	218.88	1	2182	*	NA	IL	3188				3142 ACCEL. PEDAL ASBY INTERRUPT. CK THROTTLE. PERFORMED TEST, PLS 807, PERFORM TEST, 808 RECORD MONITOR READ TEST, TP SENSOR INTERRUPT ON, REPL. ACCEL. PEDAL ASBY, CLEAR CODES, ROAD TEST, OK.	TEST	CHECK SOMETIMES THROTTLE HAS NO RESPONSE.	718	USA	18811	1	USA	*	144	PT	811	
78.88	214.83	2.1	188	*	NA	VA	3188				OPEN CIRCUIT REPL. PEDAL ASBY. ENGINE PERFORMANCE DIAGNOSTIC 7.3. 12 TURNS ENGINE. 2008. PERFORMED ENGINE DIAGNOSTIC, REPLACED FOOT PEDAL DUE TO INTERMITTANT OPEN CIRCUIT.		NO THROTTLE RESPONSE.	787	USA	18880	3	USA	*	141	PT	811	
81.82	204.27	3.1	507	*	NA	NC	3188				PERFORMANCE DIAGNOSTIC 1 TH CONTINUOUS CODE P0201 PERFORM TEST D08 D08. REPLACE ACCELERATOR PEDAL ASBY.		SOMETIMES CAN STEP ON FOOT PEDAL, NO RESPONSE.	819	USA	12181	888	USA	*	146	PT	811	
81.82	208.82	1.8	2518	*	NA	TX	3188				PERFORMANCE DIAGNOSTIC 1 TH CONTINUOUS CODE P0201 PERFORM TEST D08 D08. REPLACE ACCELERATOR PEDAL ASBY.		CUSTOMER STATES WHEN ACCEL AT TIMES THERE IS NO RESPONSE HAS OCCURRED 2-3 TIMES RECENTLY ALSO ONLY 3 LBS-WT TRANS AT TIMES FOOT PEDAL HAS NO RESPONSE.	888	USA	17147	578	USA	*	144	PT	811	
81.82	208.87	0.8	887	*	NA	AR	3188				REPLACED FOOT PEDAL. WENT TO CHRY VEH WARM AND REPLACE ACCELERATOR PEDAL AND REPLACE ACCELERATOR PEDAL AND RESET FUSED W/OAD TEST VEHICLE PERFORMED PROPERLY. TEST OK FOR REPLACE THROTTLE PEDAL.		CUSTOMER STATES HE IS GETTING NO RESPONSE FROM ACCELERATOR PEDAL. CHECK AND ADVISE NO RESPONSE TO THROTTLE PEDAL AT 7840.	478	USA	18811	828	USA	*	144	PT	811	
81.82	204.84	3.8	888	*	NA	VA	3188				ROAD TESTED, PERFORM EEC TEST AND CH DEMAND TEST CODES P0201 AND P0202, PERFORM PERFORM WARM OK, ACCELERATOR PEDAL BECAME OPEN BRACKETING AND AP CIRCUIT IN PEDAL. REPLACED ACCELERATOR PEDAL. COMPLETED BEE CODES WITH NO TESTING. 18848 NO TO MONITOR P08 FOUND AT 7888 THROTTLE PEDAL RESPONSE WAS LOST UNDER LIGHT THROTTLE PEDAL MOVEMENT. REPLACE TP ASSEMBLY ALSO CLEAN OUT BRACKET BACH DR.	EMERGENCY WAS PARTIALLY CLOSED UP. CLEANING CODES W/ USED IN TIME FOR CLEANING OUT TUBE SINCE NO CODES.	REPAIR FOR NO THROTTLE RESPONSE DID.	888	USA	12181	888	USA	*	128	PT	810	
78.88	148.83	1.1	7845	*	NA	GA	3188				ROAD TESTED, PERFORM EEC TEST AND CH DEMAND TEST CODES P0201 AND P0202, PERFORM PERFORM WARM OK, ACCELERATOR PEDAL BECAME OPEN BRACKETING AND AP CIRCUIT IN PEDAL. REPLACED ACCELERATOR PEDAL. COMPLETED BEE CODES WITH NO TESTING. 18848 NO TO MONITOR P08 FOUND AT 7888 THROTTLE PEDAL RESPONSE WAS LOST UNDER LIGHT THROTTLE PEDAL MOVEMENT. REPLACE TP ASSEMBLY ALSO CLEAN OUT BRACKET BACH DR.		SOMETIMES WHEN AT A STOP THERE WILL BE NO RESPONSE FROM THROTTLE PEDAL FOR A FEW SECONDS.	818	USA	18812	877	USA	*	144	PT	811	81
78.88	172.88	1.3	8880	*	NA	WA	3188				3188 EEC TEST P0201 3.3 ROAD TEST EEC TEST P0201 RETRIEVED FROM MEMORY PERFORM TEST D08 D08. REPLACED ACCELERATOR PEDAL ASSEMBLY.		AT TIMES CUSTOMER STATES NO RESPONSE FROM ACCELERATOR.	888	USA	17147	578	USA	*	144	PT	811	
81.82	148.82	0.8	785	*	NA	IL	3188				3188 EEC TEST P0201 3.3 ROAD TEST EEC TEST P0201 RETRIEVED FROM MEMORY PERFORM TEST D08 D08. REPLACED ACCELERATOR PEDAL ASSEMBLY.		AT TIMES CUSTOMER STATES NO RESPONSE FROM ACCELERATOR.	401	USA	11188	884	USA	*	178	PT	808	

MTR	LOT	TGT COL MFR				MFR				RSH ST P	CPL	CRCL	TECH TEXT	TECH TEXT	CUST TEXT	AREA CD	COUNT	MILE CL	DOM	ENTRY	OR	M	ANS	MRT	TSL
		ST BR	LIN	OR	PL	PL	OR	CD	CD																
78.00	134.00	0.0	0143	NA	MA	2150				VERIFY CONDENS, INSTALL MSB AND MONITOR A P SWITCH AND EBLE EVALUATION SWITCH, CHECK FUSE, OK POWER IN OK. REPROGRAM TEST, REPLACE PEDAL AND RECHECK ALL OK. REPROGRAM AND CLEAR CODES, ALL OK.				CUSTOMER COMPLAINS PEDAL HAS NO RESPONSE	207	USA	17240	2	USA	*	041	FF	011		
87.00	134.74	0.0	0002	NA	CA	2150				DIAGNOSTIC FOR NO THROTTLE RESPONSE/FOUND ACCELERATOR PEDAL RESPONSE/REPAIR PEDAL & RECHECK. PERFORMED PERFORMANCE TEST AND FOUND ALL OK. CHECKED PSB AND FOUND INOPERATIVELY THE MS. TH. SO OPEN PERFORMED PIMPOT TEST AND FOUND MS FAULTY ORDERED PARTS REPLACED THROTTLE PEDAL, ADBY AND TEST.	TESTED THROTTLE RESPONSE IS OK BUT TRANS IS SHOWING AND CHIRPING			NO RESPONSE WHEN ACCELERATING (ACC)	208	CAN	08800	2	CAN	*	041	FF	011		
84.30	234.00	2	0030	NA	MA	2150									208	USA	17000	04	USA	*	041	FF	011		
78.00	150.00	0.0	1002	NA	CA	2150				FOUND NO RESPONSE FROM ACCELERATOR/REPLACED ACCELERATOR FROM ASSEMBLY.					270	USA	00000	1	USA	*	041	FF	011		
78.00	160.36	1	0130	NA	CA	2150				1 PERFORMED CLICK TEST P0318. REPLACED THROTTLE PEDAL ADBY					300	USA	00000	3	USA	*	041	FF	011		
81.00	170.00	1.3	7001	NA	CA	2150				ROAD TEST AND VERIFY COMPLAINT/HOOK UP WDS AND CHECK COOLANT BOOST PRESSURE CODE ONLY NOTHING ON APPS GO TO THE PID DISPLAY LOAD AND WATCH ACCEL PEDAL. POSITION SENSOR WORK WHEN SET IS TURNED ON FROM FRONT SENSOR. PEDAL (CODE) PERFORMED VISUAL INSPECTION. CHECKED FOR SUFFICIENT CLEAN FUEL. CHECKED ENGINE OIL LEVEL. CHECKED INTAKE RESTRICTION. PERFORMED HOOD DTC POINTS. PERFORMED HOOD DTC POINTS. PERFORMED HOOD DTC POINTS.	SEEN NO PEDAL MOVEMENT UNTIL PEDAL IS DEPRESSED THEN BACKED OFF THEN FROM ENGINE. MONITOR A COMMAND REPLACE APPS CLEAR CODES AND RETEST. NO PLACE APPS CLEAR CODES AND RETEST ROADTEST ALL			CUSTOMER STATES WHEN HE ACCELS NOTHING HAPPENS UNTE HE BACKS OFF OF ACCELERATOR	200	USA	17240	02	USA	*	041	FF	011		
180.00	018.1	2.0	2410	NA	CA	2150									210	USA	10000	02	USA	*	040	FF	011		
78.00	100.00	1.0	0000	NA	MA	2150				0000 WRR CUST REPORTS ACCEL PEDAL DOES NOT WORK. TEST DROPS AND CONFIRMED. BACK TEST ALL PAGES. HOOD TEST ALL PAGES AND HERR TEST AND ALL PAGES. LOOKED AT PEDAL AND FOUND PEDAL TO BE BURNED AND REPLA	HOOD TEST DONE AND ALL OK.			CUSTOMER WARRIES ACCEL PEDAL AND NOTHING HAPPENS. CHECK AND REPERIT.	200	USA	17400	2	USA	*	041	FF	011		
70.00	401.71	4.0	2400	NA	TX	2150				1 PERFORMED INTRN DIESEL OAD MICHROTEST ALL TEST PAGES TO CONTINUOUS CODES CODE POINT TP 3 OPEN PERFORMED PIMPOT					214	USA	00000	04	USA	*	041	FF	011		
78.00	201.17	2.0	0000	NA	CA	2150				APP SENSOR HIGH VOLTAGE DIESEL ENGINE DIAG/FF TEST/REPLACE ACCELERATOR PEDAL SENSOR VOLTAGE APPS ACCORDING BETNET ROADTEST	CC 02				770	USA	12100	1	USA	*	041	FF	011		
78.00	101.51	1	0000	NA	MA	2150				PEDAL ASSEMBLY FAILED COMPUTER TEST. REPLACE PEDAL ASSEMBLY.					770	USA	12100	1	USA	*	041	FF	011		

PRO3-044-A 5441

MTL_CD	TOT_COUNTR	HT_OBR	HR	CUL_COUNTR	HLR_JRU	PNR	HT_P	OPNC	TECH_TXT	TECH_TXT	CUST_TXT	AREA	COUNT	BLD_CL	TRML	ENTRY	OFF_TYP	AGE	WRT	TPL
CDT	CTE	E	D	D	D	CD	CD	CD				CT	CT	R_CD	CT	CD	CD	CD	CT	PLA
157A	325.97	2.4	87852	*	NA	SC	3180		PERFORMED WELDRONTOR PREDICTION TESTS. REPLACED RMP SENSOR & ACCELERATOR PEDAL. CLEARED CODES & RETEST. CURSED.		CUSTOMER REPORTS TO TIMES HE WILL STEP ON ACCELERATOR PEDAL AND NOTHING HAPPENS. SEEMS TO BE NOISE.	292	CAN	42799	294	CAN	*	NA	FT	811
173B	103.41	1.4	87852	*	NA	SC	3180		SOON DUE 48 ROAD TEST CAUSE OF ENGINE WONT REV JUST GILES CHECK CODES RECEIVED CODE P0017 PERFORM TEST MONITOR PID FOUND NO NOT SWITCHING WERE ACC PEDAL AND ROAD TEST D.L. CLEAN CODES WARP 2.5 MAYHORN. CHECK AND REPLACE THROTTLE PEDAL ASSEMBLY CHECK FOR HIS RESPONSE FROM ACCELERATION PEDAL. PERFORM ENGINE PERFORMANCE XDRS 1.7. RETRIEVED DTC P0017. PERFORM TESTING. PERFORM DATA MONITOR TEST, MB DOES NOT CHANGE STATE. REPLACE ACCELERATOR PED	P1 E1 PUD 2.1 PE 0.1 1288201 AS 256.92 DRT 84	CHECK AND REPAIR FOR ONE PEDAL INTERMITTENTLY PRESS DOWN NOTHING HAPPENS VEHICLE GOES MAYHORN WHEN PRESSING 5-8 GAS PEDAL. NOTHING HAPPENS. JUST GILES	204	CAN	42799	1	CAN	*	NA	FT	811
725D	138.06	1.0	1180	*	NA	ND	3180		AL ASSEMBLY. ROAD TEST AND PE TEST, ALL TESTS PASS. VEHICLE OK.	ACCELERATOR PEDAL ASSEMBLY NOT OPERATING PROPERLY.	CHECK AND ADVISE FOR WHEN YOU SPORT TRUCK IT IS NON RESPONSIVE. IF YOU PUSH THE GAS PEDAL TO THE FLOOR NOTHING HAPPENS AND THE HAPPENS 3-4 TIMES AND THEN IT GOES. CUST WERE WITH THE VEHICLE GILES FOR 3-4 MINUTES CAN PUSH ACCELERATOR AND NOTHING HAPPENS IF KEEP PUSING OVER AND OVER WILL TAKE OFF	210	USA	12000	2	USA	*	NA	FT	811
81.4	176.30	1.8	4020	*	NA	AB	3180		POTENTIAL ASSEMBLY THROTTLE POSITION SENSOR (TPS) PEDAL 1. NEED STRIP UP PEE SCRTOR. ACCEL. PEDAL. NO INTERMITTENT ACCEL. PEDAL IN SIGNAL. ON POINT TEST ACCEL. PEDAL WAST		CUSTOMER STATES INTERMITTENT PUSING GAS PEDAL DOWN NOTHING HAPPENS	220	USA	12149	294	USA	*	NA	FT	811
81.41	169.25	1.0	4020	*	NA	FL	3180		ACCELERATOR ASSEMBLY MALFUNCTION PERFORMED WDS AND PDI POINT TEST AND REPLACED ACCELERATOR ASSEMBLY		CHECK ACCELERATOR GASTOMENT GAS GOES TO A STOP AND PUSH GAS PEDAL. AND NOTHING HAPPENS	280	USA	12149	294	USA	*	NA	FT	811
81.42	140.37	1.3	8088	*	NA	MB	3180		BDP ENGIN PERFORMANCE DIAGNOSTICS T.L. OF TURBO BRING 2240		CUST STATES TRUCK HAS LOST POWER. WHEN PUSING ACCELERATOR NOTHING HAPPENS	290	USA	12238	294	USA	*	NA	FT	811
81.29	401.85	4.2	8333	*	NA	MI	3180		ROAD TESTED TO VERIFY CONCERN BEC TESTED NO COD BE INSTALLED WDS AND ROAD TESTED TO MONITOR PID 8 PERFORM MIGHTYTEST (DMS TESTED) ALL WIRING P OVER GOOD REPLACED PEDAL AND REROAD TESTED TO VERIFY RMP PERFORMANCE TEST 1.5 FOUND THROTTLE SWITCH AND REPLACED PEDAL ASSEMBLY. CLEARED CODES TEST RIDGE	REPAIR	CUST REPORTS SOMETIMES WHEN STEPPING ON GAS NOTHING HAPPENS JUST GILES NORMAL	298	USA	12323	294	USA	*	NA	FT	811
81.8	182.86	1.6	2824	*	NA	WA	3180		VERIFIED CONCERN WAS PERFORMED ENGINE DMS TEST 1.8 REPLACED ACCEL PEDAL ASSEMBLY		DIRTY. ENGINE PERFECT. GAS. AND REPORT OK. FOR NOTHING HAPPENS WHEN PUSING ON ACCEL. CUST REPORTS SOMETIMES WATER BUBBLE OVER BUMPY ROAD WHEN APPLYING GAS NOTHING HAPPENS. CHECK AND ADV	300	USA	12361	294	USA	*	NA	FT	811
81.82	204.82	2.0	2568	*	NA	TX	3180		DIRTY. ENGINE PERFECT. GAS. AND REPORT OK. FOR NOTHING HAPPENS WHEN PUSING ON ACCEL. CUST REPORTS SOMETIMES WATER BUBBLE OVER BUMPY ROAD WHEN APPLYING GAS NOTHING HAPPENS. CHECK AND ADV		CUSTOMER STATES PUSH GAS PEDAL DOWN NOTHING HAPPENS INSTEAD	308	USA	12427	294	USA	*	NA	FT	811
81.83	160.32	1.5	1288	*	NA	FL	3180		DIRTY. ENGINE PERFECT. GAS. AND REPORT OK. FOR NOTHING HAPPENS WHEN PUSING ON ACCEL. CUST REPORTS SOMETIMES WATER BUBBLE OVER BUMPY ROAD WHEN APPLYING GAS NOTHING HAPPENS. CHECK AND ADV		CUSTOMER STATES PUSH GAS PEDAL DOWN NOTHING HAPPENS INSTEAD	301	USA	12427	294	USA	*	NA	FT	811
81.84	276.15	2.6	4020	*	NA	FL	3180		FOUND TP SENSOR MALFUNCTIONING; REMOVED GAS PEDAL. REPLACED TP SENSOR AND GAS PEDAL.		WHILE AT A STOP. AND YOU TRY TO ACCEL. BRKLE. NOTHING HAPPENS THEN SUCCESSFULLY PICK UP. WILL SUSPICIONALLY DRIVE TO SHAW	301	USA	12704	294	USA	*	NA	FT	811

MTWL C CST	TOT CO BY BR Q99	LAB HR S	BLR C S	BLR S	NEW ON L NOV S	WT P NOV CD	DPNC CL S	TRCH TEXT	TECH TEXT	CLNT TEXT	AREA CD	COLONY REV CD	SLI CL PL CD	TOTL CS	CHRY WLD	GRVPS CS	AWB Y CD	WRT CD	TBL PLA S
78.86	219.87	3	8692	*	NA	CR	31891	SCANNED AND FOUND THROTTLE PEDAL OPEN INTERMITTENTLY REPLACED, CLEANED COILS AND ROAD TEST OK.		AFTER EVERY SHIFT WASH, LOOSE THROTTLE CONTROL FOR A FEW SECONDS	801 USA	178807	1	USA	*	168	FT	811	
81.81	154.3	1.1	2592	*	NA	TX	31881	NO CONCERN ACCEL PEDAL INOP RUN DRIVE NO SHAKES OR THIRTS PROBABLY TO CORROSION RUN SHAKES PERFORMANCE TEST 1.8 AFTER SCOUTED AT W	WITH FIBER TO SEE VOLTAGE RANGES REPLACE ACCEL PEDAL ASBY CAUSE INTERMITTENT INOP	C 2 ACCEL PEDAL INOP	811 USA	182882	804	USA	*	161	FT	811	
81.81	185.07	0.2	8537	*	NA	CR	31881	INOP SHORTED THROTTLE ASBY PERFORMED SYSTEM TESTS CODE POST1 REPLACED ACCEL SPACER FROM ASSEMBLY CLEANED CODES ROAD TEST OK		THROTTLE ASBY INOP	801 USA	178801	804	USA	*	167	FT	809	
78.86	188.28	1.8	2432	*	NA	CA	31881			ACCELERATOR INOP REMOVED RELAY FOR IGNITION SWRCH	781 USA	171880	1	USA	*	168	FT	811	
78.86	171.83	0.3	2484	*	NA	OK	31881	DIAG AND REPAIR		CLNT WTS ACC PEDAL INOP INOP - ACCELERATOR PEDAL INOP CUSTOMER WTS SHAKING AND ACCELERATOR PEDAL, WOULD NOT WORK	401 USA	182828	3	USA	*	166	FT	808	
81.81	217.23	3.4	8547	*	NA	TX	31881	RUN ENGINE, DIAG TESTS REPLACE OPEN FUSES		CLNT WTS GAS PEDAL INOP CUSTOMER STATES GAS PEDAL INOP	211 USA	182881	804	USA	*	165	FT	811	
78.86	187.81	0.3	3434	*	NA	OK	31881	DIAG AND REPAIR		CUSTOMER STATES GAS PEDAL INOP	401 USA	182828	804	USA	*	164	FT	809	
78.86	81.78	0.3	8638	*	NA	CR	31881	INOP - ACCEL PEDAL		INOP - ACCEL PEDAL INOP	801 USA	182477	804	USA	*	175	FT	808	
80.81	263.88	0.8	87	*	NA	CR	31881	INOP - ACCEL PEDAL ASBY		INOP - ACCEL PEDAL INOP	701 USA	182488	804	USA	*	162	FT	811	
78.86	148.83	0.8	8136	*	NA	L	31881	CHECK GAS PEDAL OPERATION REPLACE PEDAL		GAS PEDAL INOPERATIVE SHORT TRIMS	241 USA	182888	1	USA	*	164	FT	811	
78.86	187.4	3	8592	*	NA	MD	31881	PEDAL BINDER ASBY HARD START NO START DIAGNOSTICS T.J.L DI TURBO ENGINE IS		CHECK FOR CODES, PEDAL INOP AT TIMES CLUT BUCKLE GOLF TIE IN PEDAL TO GET TO WORK	571 USA	182888	2	USA	*	164	FT	811	
81.81	268.07	2.0	8142	*	NA	L	31881	18804 RPM DC 42 CHECKED REMAINING CONDITION FOUND CHECK ENGINE LIGHT TO BE CALMAN HORN PRESS PRESSURE IN DC PRESS POST1, JOHN POICE PRESSURE IN DC PRESS, ELECTRIC FUEL PRESSURE IN AIR M/FUEL SYSTEM, AIR IN CHECKED FOR EXCESSIVE FOUND GAS PRESSURE, BRKLS REPLACED ASBY WITH POST ONE 1	DIAGNOSTIC TESTS, ALL PRESSURE, CYLINDER COMPRESSION, FURNISH INSTRUCTION AND SOCIETY PRESSURE, INHIBIT ENGINE AND CHECKED FUEL, REPLACED ACCELERATOR	CLNT STATED THE FUEL PEDAL IN INOP BUT	211 USA	182888	804	USA	*	164	FT	811	
81.81	140.42	1	812	*	NA	TX	31881			CHECK FOR ACCELERATOR PROBLEMS INOP	801 USA	141888	872	USA	*	166	FT	811	
81.81	138.28	0.8	882	*	NA	CA	31881	1 VERIFY CONCERN AND RESPONSE FROM ACCEL PEDAL ASSEMBLY, REPLACED PEDAL ASSEMBLY AND RETESTED DEL. PEDAL ASBY, BUCKEN UP WASH REPLACE ACCEL. PEDAL ASBY.		CUSTOMER STATES VEH AP ASSEMBLY IS INOP INTERMITTENTLY OK AND ADVICE.	801 USA	172828	872	USA	*	164	FT	811	
81.81	102.88	0.8	1388	*	NA	MB	31881			THE GAS PEDAL INOP	801 USA	182888	804	USA	*	161	FT	811	
80.81	82.38	0.4	8144	*	NA	OK	31881	REPLACE ACC PEDAL INOP		OK ACC PEDAL INOP	801 USA	182888	804	USA	*	164	FT	811	
78.86	126.71	0.8	8542	*	NA	TX	31881	INOP - ACCEL PEDAL INOP		INOP - ACCEL PEDAL INOP	701 USA	182888	804	USA	*	168	FT	811	
78.86	112.88	0.8	8534	*	NA	CA	31881	INOP - ACCEL PEDAL INOP		INOP - ACCEL PEDAL INOP	701 USA	182888	804	USA	*	164	FT	811	
78.86	98.7	0.2	8148	*	NA	FL	31881	INOP - ACCEL PEDAL INOP		INOP - ACCEL PEDAL INOP	701 USA	182888	804	USA	*	164	FT	811	
78.86	88.17	0.2	8148	*	NA	MB	31881	INOP - ACCEL PEDAL INOP		INOP - ACCEL PEDAL INOP	701 USA	182888	804	USA	*	161	FT	811	

NYTR_C CST	TOT_COLLN ST_C CST	LN S	PLR SUB D	REGN C D	BY_P NOV, CD	OPRC CD	7524 7527	TRM_TZR	SLAT_TZY	AREA CD	COUNT RY_CD	SLA_DL FL_CD	7528 CD	CNTRY CD	GMT CD	VRS CD	AWP VAL CD	VVF CD	TRM FLA S	
7524	265.07	2.7	268	NA	TX	31901	TP SENSOR FAILED WAS START GAS THROTTLE REPLACED TP SENSOR 20771 43 0568 0569 2.001 T.048 3. 061 5.01 3 14 HNS TO PCM, R.C 0328 P0271. REPORT AND MONITOR AP PD P01 H 0568ML. REPLACE THROTTLE CONTROL PEDAL. CLIPER CODES TESTED AND REPLACED THE ACCEL PEDAL ASBY.	TRM TXR	ACCEL.PEDAL INOP	876	USA	197001	2	USA	*	1464	PT	911		
7524	175.81	1.4	268	NA	TX	31901			CHECK FOR THE CRUIZ CONTROL IS ON IF THE ACCEL. PEDAL IS INOP AT TIMES	876	USA	197010	004	USA	*	1464	PT	911		
7524	198.48	1.7	478	NA	FL	31901			IF THE ACCEL. PEDAL IS INOP AT TIMES	876	USA	197010	1	USA	*	1464	PT	911		
7524	85.86	0.3	268	NA	TX	31901	REPLACE GAS PEDAL BRONZE SHIM INSTALLED SOP GAS PEDAL ASSEMBLY RECHECKED GAS PEDAL OK RETURNED OLD PARTS C.D. 48		CK FOR GAS PEDAL INOP	876	USA	197010	004	USA	*	1464	PT	911		
81.42	102.88	0.3	1788	NA	L	31901			CUSTOMER STATES GAS PEDAL INOP RETAIL SHOP	795	USA	141888	072	USA	*	1464	PT	911		
81.42	87.88	0.3	678	NA	OR	31901	BROKEN SPEED GAS PEDAL SPEED SOP 14 VERIFIED CUSTOMER FOLLOW ACCEL PEDAL BROKEN. REMOVED OLD PEDAL INSTALLED NEW ONE OK NOW		GAS PEDAL INOP	228	USA	108888	004	USA	*	1464	PT	911		
7524	147.77	0.3	268	NA	TX	31901			CUSTOMER STATES ACCELERATOR RESPONSIVE TO ACCELERATION	412	USA	111888	1	USA	*	1474	PT	909		
81.42	172.86	0.6	887	NA	OH	31901	REPL. INOP SENSOR ASBY		ACCEL. PEDAL IS INOP	402	USA	174288	004	USA	*	1477	PT	909		
81.42	384.78	5.1	4443	NA	TX	31901	PERFORMED ENGINE PERFORMANCE DAB 118 REPLACED ACCELERATOR PEDAL ASBY FOR NOODLING. PERIOD OF HIGH RPM WAS FOUND. NO PROBLEMS COMPONENT RPM 51 RPM 51 14 RUN PER FORTE REPLACED ACCEL. PEDAL WAS TEST FOLLOW 0328		CK GAS PEDAL INOP.	281	USA	108888	004	USA	*	1464	PT	911		
7524	230.88	2.1	488	NA	TX	31901			CHECK ACCELERATOR PEDAL INOP ON SPEED LAMP IS ON ACCEL. PEDAL INOP. AT TIMES	881	USA	148288	1	USA	*	1464	PT	911		
7524	181.32	1.4	4978	NA	FL	31901	POSS. FUEL PUMP PEDAL DOES NOT WORK AT TIMING CODES P014P3 022 REPLACED PEDAL ASBY.		CUSTOMER STATES PEDAL INOP AT TIMES	387	USA	103471	072	USA	*	1464	PT	911		
84.28	112.82	0.5	2878	NA	NY	31901			CUSTOMER STATES ACCELERATOR PROBLE INOP	341	USA	482844	0	CAN	*	1468	PT	911		
7524	32.47	0.2	7810	NA	OR	31901	PEDAL HUBBE PIN WOULD NOT HOLD REPLACED ACCEL. PEDAL. DETECT P0268 48 028888 RD LAB CP TO REPL. PEDAL. EXAMINER & REPLACED ACCEL. PEDAL PEDAL ASSEMBLY. TEST AND REPL. ERATIC THROTTLE DETCTED		CUSTOMER STATES PEDAL INOP SOP HIMPL IS CUSTOMER STATES ACCEL. IS INOP AT TIMES	888	USA	30382	004	USA	*	1467	PT	909		
81.42	188.27	1.6	268	NA	TX	31901			CUSTOMER STATES ACCEL. IS INOP AT TIMES	428	USA	174288	004	USA	*	1477	PT	909		
81.42	187.14	1.7	268	NA	OH	31901														
81.42	184.78	0.8	268	NA	FL	31901	3-028 INTERNAL SHORT IN FLE VALVE POSITION SWITCH SHORT LE PEDAL CAUSED FUSE TO BLOW REPLACED FUSE AND REPLACED THROTTLE PEDAL. ROAD TESTED VEHICLE. VEHICLE OPERATING A NORMAL. VEHICLE WITH HNS AND PC PERFORMED TEST FOLLOW PEDAL INOP. REPLACED PEDAL. RE-RAN TESTS OK.	ED WERE DIAGRAM.	ACCEL. PEDAL INOP	402	USA	184200	004	USA	*	1464	PT	911		
7524	281.86	3	262	NA	OK	31901			C 3 THROTTLE PEDAL INOP REPORT ON DABMS OF GAS PEDAL INOP	402	USA	182888	004	USA	*	1464	PT	911		
87.42	188.78	0.3	14227	NA	OH	31901	REPLACED GAS PEDAL TEST TEST FOLLOW. RE-RAN DEL. AND DEL ROAD TESTS. NEW RESPONSE TESTS FOUND ERATIC AP OPERATION REPLACED PEDAL. SENSOR ASBY. TESTS OK.		CUSTOMER STATES ACCELERATOR IS INTERMITTENTLY INOP. DRIVE VEH COMES TO STOP. SO TO SO ACCELERATOR WILL NOT ENERGE.	281	USA	174288	2	USA	*	1477	PT	911		

PE03-04-A 5444

WVE	TEST	DIS	LABR	DIR	REF	ET	P	CPSC	TECH	TEXT	QUEST	AREA	COUNT	SUB	DL	TOL	CHTRY	QTY	WPS	AMB	WRT	TBL	
OST	DIST	SR	FR	DO	ON	CD	CD	CD	TEST	TEXT	TEXT	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD	
150.00	201.2	7.2	8007*	NA	ND	31001			INSPECT FOR LACK OF ACCELERATION PERFORM SECTIONS OF CHECK BUSHED SHIMM CHART. REPLACE PEDAL ASSEMBLY. REMEMBER TO CHECK OPERATION 14 TIME DUE TO NO PUBLISHED LABOR OPERATION														
05.4	100.7	0.2	8008*	NA	OH	31001			AT TO REPLACE ACCELERATOR PEDAL														
01.00	00.20	0.2	2702*	NA	MI	31001			GAS REPLACE PEDAL ASBY WAS TIME TO REPLACE GAS PEDAL ASSEMBLY BROKEN														
00.04	04.12	0.0	2140*	NA	CO	31001			THRT AND REPL SHORTING SUMMR														
00.04	118.06	0.8	8007*	NA	OH	31001			WRONG PART REORDERED REPLACE BROKEN ACCELERATOR PEDAL ASBY														
00.04	05.04	0.4	3005*	NA	OR	31001			WRONG PART REORDERED REPLACE BROKEN ACCELERATOR PEDAL ASBY														
00.04	118.04	0.7	204*	NA	IL	31001			RECALL AND REPLACE FUEL PEDAL PERFORM PERFORM TEST 1 18 REPLACE ACCELERATOR PEDAL REPAIR TESTING DIAGNOSTIC 100 40 000 000 000 000 ACCELERATOR PEDAL														
70.00	200.00	4.0	8008*	NA	AZ	31001			RECALL AND REPLACE FUEL PEDAL PERFORM PERFORM TEST 1 18 REPLACE ACCELERATOR PEDAL REPAIR TESTING DIAGNOSTIC 100 40 000 000 000 000 ACCELERATOR PEDAL														
00.04	00.00	1	3007*	NA	ND	31001			ANY FUEL PEDAL BROKEN INTO REPLACE FUEL PEDAL ASSEMBLY ON VERIFY CORRECT WORK TEST, HAD ACP CHECK POSITION W/BUCKET TEST POLAR PEDAL SENSOR BAD, REPLACED AND RETEST OK														
70.00	00.10	0.4	1000*	NA	WV	31001			ANY FUEL PEDAL BROKEN INTO REPLACE FUEL PEDAL ASSEMBLY ON VERIFY CORRECT WORK TEST, HAD ACP CHECK POSITION W/BUCKET TEST POLAR PEDAL SENSOR BAD, REPLACED AND RETEST OK														
70.00	107.4	1.4	180*	NA	SC	31001			REPLACE AS PERL 17 AS NO FUEL STYLE FOR ACCELERATOR ASBY. ACCEL PEDAL INOP														
00.04	100.00	0.5	8007*	NA	NE	31001			ACCELERATOR PEDAL ASSEMBLY ADJUSTABLE REPLACE PERFORM TEST 18 TEST CODE 80001 REPLACED ACCELERATOR PEDAL ASSEMBLY														
70.00	100.00	1.0	6400*	NA	CA	31001			FAILS PEDAL ASBY PERFORMANCE TEST 1 100000 POLAR ALL WIRING & PLUGS ON PEDAL LOCKED W/SP REPLACED WITH NEW STYLE PEDAL														
01.00	007.04	2.4	3000*	NA	NM	31001			CHECK FOR AT TIMES WILL NOT TAKE THROTTLE, PERFORM DIAG AND RETRIVE CODE P0221, PERFORM PPT AND FOLLO PEDAL ASBY AT FAULT. INSTALL NEW PEDAL ASBY AND VERIFY PERFORM OK														
01.00	111.00	0.5	012*	NA	TX	31001			RECALL AND REPLACE FUEL PEDAL PERFORM PERFORM TEST 1 18 REPLACE ACCELERATOR PEDAL REPAIR TESTING DIAGNOSTIC 100 40 000 000 000 000 ACCELERATOR PEDAL														
70.00	110.00	0.5	3003*	NA	CA	31001			FAILS PEDAL ASBY PERFORMANCE TEST 1 100000 POLAR ALL WIRING & PLUGS ON PEDAL LOCKED W/SP REPLACED WITH NEW STYLE PEDAL														
70.00	200.00	4	3000*	NA	AR	31001			PERFORM PERFORM PERFORM TEST 18 REPLACE ACCELERATOR PEDAL COMPLETE RETEST DIAG TEST														
01.00	100.10	1.0	000*	NA	GA	31001			RECALL AND REPLACE FUEL PEDAL PERFORM PERFORM TEST 1 18 REPLACE ACCELERATOR PEDAL REPAIR TESTING DIAGNOSTIC 100 40 000 000 000 000 ACCELERATOR PEDAL														

DE03-044-A 5A4B

TRF_C	ST	BR	TRF	LN	SR	PRN	ST	P	SPWL	TRCH	TRCH	TRCH	AREA	COUNT	BLD	TOTL	ENTRY	CRS	VRB	AWB	TRF
DET	025	5	2	0	0	02	00	02	00	TEXT	TEXT	TEXT	CD	CD	CD	CD	BOLD	CD	CD	CD	CD
43.84	078.80	1.2	9820		NA	TX			21821	TRCH TEXT			210	USA	102204	1	USA	*	V41	FF	E11
76.88	248.84	2.3	7872		NA	CA			21821	DISC. CHECK ACCELERATOR STOP AT THRESHOLD UNIT CUSTOMER STATES ACCEL PEDAL INTERMITTENTLY INOPERATIVE		220	USA	172620	224	USA	*	V42	FF	E11	
87.62	384.42	3.4	2621		NA	TX			21821	DISC ACCEL PEDAL STOP		230	USA	102420	272	USA	*	V44	FF	E11	
81.82	151.81	1	4527		NA	TX			21821	DISC CHECK ACC. PEDAL STOP ADVISE		230	USA	102220	224	USA	*	V41	FF	E11	
81.82	326.84	4.1	4482		NA	TX			21821	ACCELERATOR STOP		230	USA	102140	224	USA	*	V44	FF	E11	
76.88	126.72	0.8	8084		NA	CA			21821	ACCELERATOR PEDAL STOP		230	USA	141020	2	USA	*	V47	FF	E11	
80.26	282.27	1.6	4217		NA	TX			21821	DISC ACCELERATOR STOP CUSTOMER STATES THROTTLE STOP AT TIMED		230	USA	102027	1	USA	*	V48	FF	E11	
81.82	244.81	1.2	8801		NA	WA			21821	DISC ACCELERATOR STOP CUSTOMER STATES THROTTLE STOP AT TIMED		230	USA	100120	222	USA	*	V17	FF	E09	
81.82	402.27	6.3	2822		NA	TX			21821	DISC STATES GAS PEDAL STOP		230	USA	102620	272	USA	*	V44	FF	E11	
80.26	128.24	0.7	2842		NA	UT			21821	GAS PEDALS STOP		230	USA	102820	224	USA	*	V71	FF	E09	
82.4	128.24	0.6	8222		NA	AR			21821	CHECK GAS PEDAL BEARS RESPONDING		490	CAN	602220	224	CAN	*	V41	FF	E11	
76.88	151.78	0.4	2813		NA	TX			21821	DISC ACCELERATOR PEDAL STOP		230	USA	102420	2	USA	*	V44	FF	E11	
81.82	227.42	4.1	8222		NA	OK			21821	CUSTOMER STATES ACCELERATOR PEDAL STOP - MONTAGNINI ADVISE		240	USA	102820	224	USA	*	V41	FF	E11	
81.82	442.12	4.4	8222		NA	OK			21821	TURBO WAS STOP ONCE ON ACCELERATION		230	USA	174220	224	USA	*	V41	FF	E11	
76.88	238.81	2.3	888		NA	OK			21821	DISC ALL GAUGES IN DASH STOP ADVISE FOR WORK		490	USA	100120	224	USA	*	V42	FF	E11	
76.88	321.81	2.2	281		NA	IL			21821	CUSTOMER STATES GAS PEDAL STOP AT TIMED		230	USA	102227	224	USA	*	V42	FF	E11	

WTRLC	TOT_CD	LAB	DLR_CD	DLR_CD	DLR_CD	RESV	ST_P	OPRC	TECH_TKT	TECH_TKT	DRY_TKT	AREA_CD	COUNT	REL_CD	TOE_CD	CHTRY	CHTRY	WHS_CD	WHS_CD	WHS_CD	WHS_CD	WHS_CD	WHS_CD	WHS_CD	WHS_CD		
INTL_C	ST_OP	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN		
INTL_C	ST_OP	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN	LN		
81.02	354.98	1.4	772		NA	OK	31801		FROM EEC TEST FOR THROTTLE POSITION CONTINUOUS PERFORMED PIPPOINT TEST, P11 THROTTLE PEDAL, BAD REPLACED ACCEL. PEDAL, RETEST OK.		THROTTLE PEDAL NOP SOMETIMES WHILE DRIVING	882	USA	12881	872	USA		144	FT	811							
81.39	333.75	1.8	8147		NA	TX	31801		PLM CODES RETURNED CODES P0001 P1146 BAD PERFORMANCE P1108 RUN PERFORMANCE TEST REPLACED PEDAL ASSEMBLY P0008 OPEN IN W/S CIRCUIT CLEAR CODES AT RESTART P1146 RETURNS ALSO P1130 CLUT ADJUSTED WATER IN OIL	EL CODE		USA	12881	802	USA		177	FT	809								
80.84	103.85	0.4	3541		NA	PA	31801		REPLACE WITH NEW		FUEL PEDAL NOP	870	USA	12881	824	USA		144	FT	811							
88.81	230.75	2	7897		NA	CA	31801		171 WEARBY ACCELERATOR NOP AT 12000 RPM, VIBR DASH, FROM ALL ELECTRIC PEDAL TOOTH PER Y-34 IN 2000 INCH, FOUND OPEN IN W/S CIRCUIT, REPLACED PEDAL ASSEMBLY, P0008 OK AT THIS TIME INTERNALLY SHORTED ACCELERATOR PEDAL AND SENSOR ASSEMBLY PERFORM ELECTRICAL DIAG, AND REPLACE ACCELERATOR PEDAL AND SENSOR ASSEMBLY, CLEAR CODES AND RETEST OK.		CLIENT STATES AT TIME ACCEL NOP	828	USA	12881	881	USA		141	FT	811							
85.8	184.4	1.8	4863		NA	FL	31801		PERFORMED ECC TEST, FOUND BAD ACCELERATOR PEDAL ASSEMBLY, REMOVED AND REPLACED, RECHECK OK		CLIENT STATES ALL CALIBRATED WENT NOP FUEL FUEL BLOWN REPLACED WITH FUEL FROM CORN LIGHT FUEL BLOWN AGAIN	772	USA	12881	881	USA		177	FT	808	GR						
80.84	120.35	0.8	3218		NA	CO	31801		REMOVED AND REPLACED, RECHECK OK		ACCEL. PEDAL NOPPER, INTERLUPE BURNS UP TO 3000 THEN SHIFTS HARD	870	USA	12881	884	USA		144	LI	811							
80.84	185.39	1.2	7213		NA	CA	31801		INSTALL NEW GAS PEDAL ASSEMBLY		REMOVE FOR GAS PEDAL NOP	787	USA	12881	881	USA		174	LI	808							
75.05	142.84	1	4353		NA	FL	31801		ACCELERATOR PEDAL DOES NOT OPERATE PROPERLY DASH ACCELERATOR PEDAL ASSEMBLY, FOUND NO NOT RESPONSIVE, R.F. PEDAL ASSEMBLY AND RETEST OK.		C/S FUEL PEDAL NOP	305	USA	12881	1	USA		177	LI	808							
81.02	125.09	0.97	428		NA	AL	31801		FROM ECC TEST IN TIME TO REPLACE PEDAL ASSEMBLY.		GAS PEDAL NOP, ADVISE	305	USA	32187	872	USA		134	LI	813							
80.84	183.26	1	3203		NA	CA	31801		PEDAL ASSEMBLY BROKEN, TIME NEEDED TO REMOVE AND REPLACE PEDAL ASSEMBLY BROUGHT THROUGH THE PEDAL TIME TO REPLACE BROKEN THROTTLE PEDAL ASSEMBLY		C/S FUEL PEDAL NOP	825	USA	12881	881	USA		144	FT	811							
81.02	114.05	0.8	2185		NA	OH	31801		FROM PERFORMANCE TEST FOR CODES FOUND PEDAL, REPLACED PEDAL, RETEST OK		THROTTLE PEDAL NOP	818	USA	32308	884	USA		144	FT	811							
78.86	187.15	1.7	553		NA	OK	31801		TEST SHORTED TP SENSOR BLOWN FUEL CHECK FUEL BLOWN REMOVE AND REPLACE FUEL BLOWN BLOWN TEST TP SENSOR OK OK TEST TP SENSOR SHORTED, REMOVE AND REPLACE ACCELERATOR ASSEMBLY, VEHICLE OK AT THIS		C/S ACCELERATOR NOP	408	USA	12881	2	USA		144	FT	811							
81.4	125.59	0.8	2771		NA	MI	31801		ECC TEST OK DISPLAY AND PERFORMANCE TEST REPLACED ACCELERATOR POSITION SENSOR AND RETEST	TRM	OK ACCELERATOR PEDAL REPLACE POSSIBLE T.S.B.	784	USA	12881	881	USA		177	FT	808							
84.38	160.51	1.1	8114		NA	WI	31801		ECC TEST OK DISPLAY AND PERFORMANCE TEST REPLACED ACCELERATOR POSITION SENSOR AND RETEST		CHECK ACCEL PEDAL NOP LATE, ACTUAL SHUTTING OFF ENGINE	414	USA	12881	881	USA		144	FT	811							
75.05	203.59	2.5	478		NA	CA	31801		8484 PERFORMED DIAGNOSTICS ITEMS 1 & 14, RECEIVE NOISE CODES P0222 TEST AND REPLACE ACCELERATOR PEDAL ASSEMBLY, RETEST.		FUEL FOR THROTTLE POSITION NEEDS BLOWING, ALSO AC NOP	178	USA	32308	872	USA		141	FT	811							

TRAIL_C	ST_OR	HR	DLR_C	DLR	RESR	ST_P	OPRC	TRCH_TKT1	TRCH_TXT2	TRCH_TXT3	AREA	ACOUNT	SLC	CL	TAXL	CNTY	CRTRY	APRD	VL	VWT	TBL
097	069	48	0	0	0	00	0000				CO	BY	CL	CO	BOLD	CO	CO	CO	CO	CO	FLA
185.08	227.88	4.8	548	*	MA	TX	31891	PLM DRIVE, DIAG TESTS REPLACE OPEN PEDAL ASSY REPLACE ENGINE SENSOR			214	USA	10000	002	USA	*	1044	FT	811		
75.08	144.24	1.2	7585	*	MA	OH	31891	RUN PERFORMANCE TEST 1 & 2. SAME CODES PERSIST. REPAIR POINT TEST. FOUND FAULTY PEDAL ASSY. REPLACE PEDAL ASSY AND ROAD TESTED OK			682	USA	10000	002	USA	*	1044	FT	808		
120.02	138.02	0.4	3872	*	MA	AR	31891	NO HELP TEST, WITHSTAND CODES PERSIST; REPLACE ACCELERATOR PEDAL ASSY, POSITION SWITCH BAD			478	USA	10000	002	USA	*	1044	FT	805		
75.88	140.27	1.3	7828	*	MA	PA	31891	HAD CODES POINT THROTTLE POSITION POTENTIOMETER ASSEMBLY THROTTLE POSITION SENSOR TP REP			296	USA	10000	002	USA	*	1044	FT	811		
75.88	188.42	2.5	4284	*	MA	TX	31891	VERIFY CORRECT BDC TEST FOR NO RESPONSE DETERMINE NEED FOR PEDAL ASSEMBLY REPLACE PEDAL ASSEMBLY ROAD TEST TO VERIFY CUSTOMER CONCERN			28	USA	10000	002	USA	*	1044	FT	811		
85.04	183.11	1.9	2415	*	MA	TX	31891	PERFORMED ORIGINAL ENGINE PERFORMANCE TEST. FOUND FOOT PEDAL NOT WORKING PROPERLY, REPLACED FOOT PEDAL, RETEST			572	USA	10000	004	USA	*	1044	FT	811		
81.80	888.42	4.6	7712	*	MA	CA	31891	RUN PERFORMANCE SWEET DIAGNOSIS, PERFORMED SERIAL CODES, AND HARD PULSES IN DIAGNOSED AND IDENTIFY, FROM CENTER, COMPRESS OPEN ACCELERATOR PEDAL ASSY, REMOVED AND REPLACED PEDAL ASSY.			450	USA	10000	004	USA	*	1044	FT	811		
71.82	182.87	0.7	598	*	MA	GA	31891	FOUND DEFECTIVE ACCEL PEDAL TP SENSOR, REPAIR AND TO CORRECT BDC TEST CODE FOR ACCELERATOR PEDAL FAULTY CODE, TESTED ACC PEDAL, FOUND PEDAL NOT OPERATING PROPERLY, REPLACED PEDAL ASSY, RECHECK OK			478	USA	10000	004	USA	*	1044	FT	808		
84.28	127.82	0.8	1082	*	MA	SC	31891	VERIFY ENGINE HAD NO RESPONSE TO THROTTLE/ACC PEDAL			842	USA	10000	002	USA	*	1044	FT	811		
80.84	120.4	1	8285	*	MA	ME	31891	VERIFY THROTTLE POSITION SENSOR BDC, TP SENSOR PCA, REPLACED TP SENSOR			882	USA	10000	004	USA	*	1044	FT	811		
51.82	131.75	0.9	531	*	MA	MS	31891	DIAGNOSE AND REPLACE FAULTY THROTTLE POSITION SENSOR OPERATED CORRECTLY			802	USA	10000	002	USA	*	1044	FT	811		
75.88	121.1	0.7	8136	*	MA	HI	31891	ALL CASE 114 PWR POINT TO BY IN VE OPEN CIRCUIT HISS ACCNL PEDAL ASSY AND TEST DRIVE OK			878	USA	10000	002	USA	*	1044	FT	808		
80.44	183.88	1	3712	*	MA	NY	31891	NO TIME TO DIAGNOSE AND REPLACE FAULTY ACCNL PEDAL ASSY CODE P1788			842	USA	10000	004	USA	*	1044	FT	811		
75.88	87.24	0.3	2258	*	MA	TX	31891	CC BY SPEEDS REPLACE ACCELERATOR PEDAL SENSOR			572	USA	10000	002	USA	*	1044	FT	811		
75.88	100.28	0.5	1082	*	MA	SC	31891	VERIFY ACC PEDAL			842	USA	10000	002	USA	*	1044	FT	808		
81.82	148.48	0.8	185	*	MA	MD	31891	VERIFY DRIVE INK ON CODES, FOUND SEVERAL, REPAIR POINT TEST AND FOUND CIRCUITS OK, PLAYED WITH ACCEL PEDAL AND FOUND THAT WHEN PRESS, SHUTS BACK			308	USA	10000	004	USA	*	1044	FT	811		

MYR	TOY	CO	MR	CL	DLR	REV	SE	SP	TECH	TECH	TECH	WMA	COUNT	WMA	DL	CHRY	WMA	WMA	WMA	WMA		
CO	CO	CO	CO	CO	CO	CO	CO	CO	7001	7002	7003	CO	CO	CO	CO	CO	CO	CO	CO	CO	CO	
90.74	121.34	2.4	1989	NA	TX	3189			REPLACE PEDAL AND SWITCH WIP			600	USA	1989	USA		144	FT	211			
90.84	118.44	0.4	1989	NA	FL	3189			ACCELERATOR PEDAL ASSEMBLY			300	USA	1989	USA		174	FT	202			
90.84	178.34	1.0	1992	NA	TX	3189			RAN PID MONITOR JOSE KOER RETURNED CODE P0201 RAN P0201 TEST HAD TO REPLACE PEDAL ASSEMBLY			300	USA	1992	USA		144	FT	211			
91.02	274.87	2.7	1989	NA	ND	3189			PERFORMS PERFORMANCE CLEAR AND PERFORM CODES RETURNED. REPLACE THROTTLE PEDAL ASSEMBLY AND THROTTLE PEDAL ASSEMBLY			570	USA	1989	USA		141	FT	211			
91.02	105.41	0.4	1989	NA	OR	3189			THROTTLE PEDAL ASSEMBLY ASSEMBLY			600	USA	1989	USA		144	FT	211			
91.08	234.38	2.8	1989	NA	FL	3189			CK OUT ENG. CONTROLS PERFORMED RAN RECEIVED CODES P0217R OUT OF RANGE PERFORMED PERFORM TEST HOOK UP AND INSTALLED BRACE CLIP BOX MONITOR PEDAL FOUND FOOT PEDAL, ANY OTHER BLANKS REPLACED PEDAL	ANY CLEAR CODES RETURNED AFTER REPAIRS ALL CLEAR AT THIS TIME		300	USA	1989	USA		141	FT	211			
91.04	178.34	1.3	1989	NA	MA	3189			9000 ROAD TEST VEHICLE FOUND THE THROTTLE CABLE CLIP PERFORMS DIAGNOSTIC AND FOUND THE PEDAL ASSEMBLY. RETURNED TO UNRESPONSIVE REMOVE PEDAL ASSEMBLY AND INSTALL NEW PEDAL AND FOUND TEST OK			400	USA	1989	USA		140	FT	211			
91.02	128.82	0.8	7702	NA	CA	3189			REMOVED AND REPLACED PEDAL DUE TO NO THROTTLE RESPONSE OPERATOR			400	USA	1989	USA		147	FT	200			
79.08	128.14	0.8	1989	NA	FL	3189			CHANGE BLACKTAL BLUE TEST			300	USA	1989	USA		144	FT	211			
91.02	178.34	1.3	1989	NA	CO	3189			TS DI PERFORMANCE DIAG P0201 & REPLACE THROTTLE PEDAL ASSEMBLY BOTH-TURN ALL CONNECTIONS RETEST OK			300	USA	1989	USA		141	FT	211			
90.09	108.25	1	1989	NA	CO	3189			PEDAL ASSEMBLY	REPLACED PEDAL		600	USA	1989	USA		140	FT	211			
118.10	85.36	0.7	1989	NA	TX	3189			PERFORMS PERFORMANCE CLEAR TS DI TURNS ENGINE DIAG CHECKED DELT, MORE VOLTAGE, MORE PWTT, KOER PWT, PERFORM TEST BOLDEN, VOLTAGE OK, REPLACED FULLY AS SEMBLY, TESTED OK			600	USA	1989	USA		140	FT	211			
79.08	108.25	1.0	1989	NA	TX	3189			REPLACED FOOT PEDAL			600	USA	1989	USA		141	FT	211			
79.08	113.08	0.6	1989	NA	ND	3189			RAN P0201 PEDAL CC IS OPEN CIRCUIT CUSTOMER STATES THROTTLE DOES NOT RESPOND AT THIS TIME. TEST ENGINE AND MEMORY CONCERN PERFORMANCE HOOK UP, USED P0201, MORE PWTZ, PERFORM PID DATA, RECHECK, PER	RAN PERFORM TEST, FOUND CONCERN WITH PEDAL ASSEMBLY, REPLACE PEDAL ASSEMBLY. CLEAR CODES, TEST DRIVE AND REPAIR FINAL ON FOR TESTS. ALL TESTS PASSED. VERIFY REPAIRS.		477	USA	1989	USA		147	FT	200			
79.08	108.25	0.8	1989	NA	CA	3189			CHECKED THROTTLE RESPONSE AS OFF UP TO 75% RESPONSE IS AT 50%. CHECKED THROTTLE PEDAL ASSEMBLY. REPLACE PEDAL			600	USA	1989	USA		140	FT	211			

MTRC_QST	TOT_COL	LN	HR	DUR	SU	FRAG	ST_P	CPCL	TRCH_TXT1	TRCH_TXT2	CLNT_TXT	AREA	CDRT	REL_CL	TVAL	ENTRY	GRY	WFS	LAST	PRET	TR
QST	QST	QST	QST	QST	QST	QST	QST	QST				CD	CD	CD	CD	CD	CD	CD	CD	CD	CD
81.82	224.87	2	1778		NA	DD		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		CHECK ACCEL PEDAL DOES NOT RESPOND AFTER DISCEL LIFE PEDAL DISCONNECTED WORKS WHEN WORK	303	USA	180482	EM	USA	*	144	77	811	8
81.82	188.88	1.4	7785		NA	DA		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC	ENGINE OK CLEAR CODES REPAIR COMPLETE	CUSTOMER SAYS THROTTLE PEDAL DOES NOT RESPOND ALL THE TIME RANGE PROBLEMS RELAY TESTS	707	USA	172898	EM	USA	*	144	77	811	
81.82	223.43	1.8	2591		NA	MO		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		CUSTOMER STATES THE THROTTLE DOES NOT RESPOND AT TIMES	314	USA	180078	EM	USA	*	144	77	811	
78.88	134.48	0.8	878		NA	NC		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		TRUCK DOES NOT RESPOND	818	USA	181010	1	USA	*	144	77	811	
84.38	213.30	2.4	2443		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		THROTTLE WILL NOT RESPOND COLD	848	USA	180000	EM	USA	*	144	77	811	
81.82	173.88	1.8	481		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		CLNT STATES WHEN STARTING COLD VEH WONT RESPOND WHEN DEPRESSIONS ACCEL ALSO HEST. FOR JUST CHANGES	841	USA	181440	EM	USA	*	144	77	811	
80.84	188.70	0.8	8821		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		DIAG AT THREE ENGINE IS RUNNING BUT DOES NOT RESPOND TO ACCELERATION WHEN PRESSED THROTTLE SUCCESSFULLY ENGAGES	805	USA	114000	EM	USA	*	144	77	811	
78.88	147.81	1.1	788		NA	DA		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		CHECK ACCEL PEDAL WILL NOT RESPOND	708	USA	181478	EM	USA	*	141	77	811	
78.88	178.88	2	4810		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		ACCELERATOR DOESNT RESPOND	830	USA	180224	EM	USA	*	141	77	811	
78.88	285.11	2.5	4817		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		C B AT THREE ACCELERATOR PEDAL WILL NOT RESPOND HAVE TO SHUT OFF VEHICLE AND PRESSING TO GET VEHICLE TO RESPOND - TIME	818	USA	120000	EM	USA	*	144	77	811	
84.38	148.81	0.8	3788		NA	CO		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		CUSTOMER STATES WHEN ACCEL THE ENGINE WONT RESPOND	870	USA	180447	EM	USA	*	141	77	811	
78.88	118.88	0.8	5073		NA	LA		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		ACCELERATOR NOT RESPONDING	885	USA	180048	EM	USA	*	144	77	811	
81.82	232.72	4.4	3318		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		OK AC PEDAL WONT RESPOND INTERMITTENTLY	872	USA	180008	EM	USA	*	141	77	811	
81.82	282.87	1.8	4816		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		OK PEDAL DOES NOT ALWAYS RESPOND YOU HAVE TO PRESS IT TO GET IT TO GO	210	USA	180043	EM	USA	*	144	77	811	
78.88	288.78	3.1	3323		NA	TX		31801	PERFORMED DIAG SHEET, CONT DTC 0221 ONLY. POB OK CHECKED AND REPLACED AT ASSEMBLY PER DTC		ACCEL PEDAL WILL NOT RESPOND AT TIMES	808	USA	180448	EM	USA	*	144	77	811	

YOT_CD	MTPL_CST	YR	LR	DLR_CD	DLR_SU	REG	FT_P	CPCL	TECH_TXT1	TECH_TXT2	CLRT_TXT	AREA_CD	COUNT	DLT_CD	TPL_CD	CHRY	CRD_CD	WFO_CD	AMR_CD	WVT_CD	ZPL_CD
78.04	148.83	1	7823	NA	MD	31891			IN 1998 IN ESC TEST ADD TEST FORCE DOWN TEST AND ON DEMAND SELF TEST. BLEED SYSTEM TEST. REPLACE ACCELERATOR PEDAL ASSEMBLY AND TEST DRIVE FOR QUALITY.		CHECK WHICH PRESSURE ADJ. PEDAL ASSEMBLY COMPONENT RESPOND	808	USA	18224	1	USA		NA1	FT	811	
78.06	148.79	1	7823	NA	TX	31891			SCAN 1300R 8.2 0.48 8.3 0.88 0.3 0.81 8.1 0.1 0.5 1.8 VERIFY DIAGNOSTIC THROTTLE DID NOT RESPOND WHEN DEPRESSING PERFORM CID 2 (DIAGNOSTIC RETURN DIAGNOSTIC CODE P0221 TP LOW INPUT POSITION) AND RANBBE PWR	FORWARD SELECT PEDAL TO ACCELERATOR TP SENSOR VERIFY VOLTAGE REMAINS STUCK LOW NO INCREASEMENT REPLACE THE THROTTLE ASSEMBLY CLEAR CODES POSTEST AND ROAD TEST OK	CX LOW PEDAL WORK RESPOND WHEN DEPRESSING AT TIMES WHILE DRIVING ACCORDING ADULT'S TEST	973	USA	18224	1	USA		NA1	FT	811	
81.02	195.84	1.2	78	NA	MD	31891			8888 VERIFY CONCERN USE WDS TO DRIVE VEHICLE CODE P0221 STORED, PERFORM PPOINT AND WIND TESTS. WOUND THROTTLE PEDAL ASSEMBLY AND REPLACE PEDAL ASSY. CLEAR CODES. ROAD TEST PERFORM PPOINT. THE WDS NO POWER DIAGNOSTIC CODE P0221 PPOINT TEST REPLACED ACCEL ASSEMBLY RETEST ROADTEST'S MILES OK	T. NOBO PABL NOER PAS CONT PABL CONCERN HAS BEEN DIRECTED-	CUSTOMER STATES ENGINE HAS ON SEVERAL RECENT OCCASIONS NOT RESPONDED TO ACCELERATOR INPUT AT STOPPLACEDUNT CLIM	418	USA	12121	872	USA		NA1	FT	811	
81.02	182.82	1.5	7873	NA	CA	31891					C8 THAT THE VEHICLE WOULD NOT RESPOND TO THE THROTTLE DOES NOT RISE UP OR MOVE	778	USA	12148	872	USA		NA8	FT	811	
81.02	124.89	0.2	7823	NA	SC	31891			NO P DIAGNOSE	SEC (BLACK TEXT)	THE TRUCK WILL NOT RESPOND WHEN PRESSING THE ACCELERATOR AFTER IT HAS COME TO A STOP, THE AMBER CHECK	808	USA	12124	874	USA		NA8	FT	811	
78.88	212.89	2	7788	NA	CA	31891			READ ME TEST DRIVE COULD NOT VERIFY FROM PERFORMANCE TESTS 1 14 HAS CONF CODE FROM SCAN PPOINT TEST P021 P01 P04 NO BAO		CLIFF STATES AFTER HARD BRAKING LINE COMING OFF FREERWAY 1848 WILL NOT RESPOND TO THROTTLE HAVE TO RESET TRUCK TO	787	USA	172412	1	USA		NA1	FT	811	
80.04	118.33	0.5	1882	NA	PA	31891			DIAGNOSE FAULTY PEDAL SENSOR REPLACE PEDAL ASSEMBLY		THROTTLE WILL NOT RESPOND	717	USA	11881	884	USA		NA8	FT	811	
81.02	271.4	2.3	2738	NA	WA	31891			1 TEST ENGINE, VERIFIED CONCERN PERFORMED ESC TESTS, FOUND CODE P0221. CHECKED OARS, NOTHING RELATED FOUND. PERFORMED 1 PERFORMED ESC TESTS PERFORMED OARS TEST 1 14 CODES FOUND P0221 P0221 P0221 REPLACE THROTTLE PEDAL ASSY AND RANBBE		WHEN PRESSING GAS PEDAL ENGINE COULD NOT RESPOND ADVISE	783	USA	12801	872	USA		NA8	FT	811	
81.02	229.87	2	7823	NA	UT	31891			DIAGNOSTIC CODE P0221 TP SENSOR REPLACE PEDAL ASSEMBLY		CUSTOMER STATES ENGINE PLINGS POOR SOMETHING PEDAL COULD RESPOND	801	USA	17488	872	USA		NA8	FT	811	
78.06	150.25	1.4	7823	NA	OR	31891			REPLACED PEDAL ASSEMBLY WDS ACCEL PEDAL ASSY. 25 WINDUP TESTED AND VERIFIED CONCERN PERFORMED 2888, DIAL 800P 12. RETURNED OTC P0221 TP SENSOR. PERFORMED PPOINT TESTS AND FOUND TP SENSOR OPEN. 3.8 TP AND ACCEL	PEDAL ASSY. RETESTED AND PAS.	END CUSTOMER STATES VEH DOES NOT RESPOND AT TIMES WHILE DRIVING	808	USA	18221	884	USA		NA4	FT	811	
81.02	126.18	0.7	801	NA	FL	31891			PERFORMED ESC TEST PASSED ROADTEST VERIFY GAS PEDAL DID NOT WORK AT TIMES REPLACED GAS PEDAL RETEST VERIFY REPAIR		CUSTOMER STATES WHEN DEPRESSING ACCEL VEH WOULD RESPOND	801	USA	12844	884	USA		NA1	FT	811	
80.4	128.48	0.4	8000	NA	CA	31891			CHANGE AND CHECK P0221 REPLACE FAULTY THROTTLE POSITION SENSOR ROADTEST VERIFY PABL WORK CHECK WDS SHOULD HAVE BEEN 8881		CHECK THROTTLE KICK RESPONSE	783	USA	12808	884	USA		NA1	FT	811	

AREA	TOT	DOCTR	PLK	RES	ST	P	TRCH	TRCH	CARE	ANR	COLN	SLR	DL	TRFL	CHTR	CHTR	ANR	M	WRT	TRFL				
CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT	CDT				
ELAS	1848	14	2182	NA	CO	3181	TRCH1.TX11		CARE 187	521	USA	18047	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CO	3181	DO PERFORMANCE TESTS PERFORM TEST FLOOR OPEN TO SENSOR REPLACE THROTTLE PEDAL ASSEMBLY RETIRED CLEANED CODES		CUSTOMER STATES THE VEHICLE IS HAVING THROTTLE RESPONSE WENT RESPOND WHEN HITTING THE ACCELERATOR PLANK ADVISE	521	USA	18047	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	ACCELERATION PEDAL PHILIPS BODY DIAGNOSIS ELECTRICAL TEST		VEHICLE DOES NOT RESPOND TO ACCELERATOR 3 D PARTS	521	USA	17000	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	3181 CONFIRMED CUSTOMER CONCERN OF THROTTLE NOT RESPONDING AT TIMES PERFORMED PERFORM TEST AND FOUND THROTTLE PEDAL DAY OF SPEC AT TIMES. RECOMMEND REPLACE THROTTLE PEDAL AND INSPECT ELECTRIC PEDAL. ENGINE PERFORMANCE OK, PAUL CHECK TEST, M/TIME FOR 800R2,2,AAA,TAR,10,11,12		CHECK AND ADVISE: CUST STATE ENGINE WILL NOT RESPOND WHEN SAS PEDAL PRESSED REPEATS 3 OCCASIONS. RESPONSE HAPPENS WHEN ACCELERATION FROM A DEAD STOP	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	PERFORM TESTS FOLLOWING PPT DOX CHECK PMS TO TEST VOLTAGE OK DOX WITH SENSOR DISCONNECTED REPLACED AP SENSOR AND PMS ASSEMBLY TESTED AND ALL TESTS PERFORMED OK. DISCONNECTED AND REPLACED ACCEL. PEDAL DUE TO INTERMITTENT OPEN CIRCUIT		CUSTOMER STATES THAT AT TIMES THE ENGINE DOES NOT RESPOND TO THE ACC	521	USA	17000	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	DOX CHECK PMS TO TEST VOLTAGE OK DOX WITH SENSOR DISCONNECTED REPLACED AP SENSOR AND PMS ASSEMBLY TESTED AND ALL TESTS PERFORMED OK. DISCONNECTED AND REPLACED ACCEL. PEDAL DUE TO INTERMITTENT OPEN CIRCUIT		ACCEL DOES NOT RESPOND HOLD CURRENT BEFORE THE ENGINE WILL NOT RESPOND TO THE THROTTLE PEDAL	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	1 RUN TEST TEST AND RUN PMS FOR CODES TEST ACCEL. PEDAL TO REPLACE PEDAL ASSEMBLY AND CLEAN CODES AND RE-TEST		DOX CUSTOMER STATES REPEATS BY ACCELERATOR NOT RESPONDING WITH THE STARTER	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	DOX CHECK PMS TO TEST VOLTAGE OK DOX WITH SENSOR DISCONNECTED REPLACED AP SENSOR AND PMS ASSEMBLY TESTED AND ALL TESTS PERFORMED OK. DISCONNECTED AND REPLACED ACCEL. PEDAL DUE TO INTERMITTENT OPEN CIRCUIT		CEL CODES ON AT TIMES. WHILE DRIVING THE CAR WILL NOT RESPOND TO GAS	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	2781 PERFORMED CHECK. ENGINE PERFORMANCE DIAGNOSIS. HORN TEST PERFORMED CODES. FUEL INJECTOR ELECTRICAL SELF TEST. PERFORMED HORN TEST. PERFORMED PERFORM TEST TEST FOUND AP SENSOR. ENG. REPLAC PMS. HORN TEST. ENG. TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST	NO AP SENSOR AND RETIRED OK	C AT TIMES VEHICLE WILL NOT RESPOND TO ACCELERATOR PEDAL ENGINE DROPS BACK TO IDLE AFTER PUMP ACCEL. MAY COME BACK	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	2781 PERFORMED CHECK. ENGINE PERFORMANCE DIAGNOSIS. HORN TEST PERFORMED CODES. FUEL INJECTOR ELECTRICAL SELF TEST. PERFORMED HORN TEST. PERFORMED PERFORM TEST TEST FOUND AP SENSOR. ENG. REPLAC PMS. HORN TEST. ENG. TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST	NO AP SENSOR AND RETIRED OK	OK VEH DOES NOT RESPOND TO ACCEL. CODES AT TIMES	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	ENGINE PERFORMANCE DIAGNOSIS T.S. DI TURBO ENGINE SET ON ENGINE SET. HORN CHECK TEST		CUSTOMER STATES WHEN STOPPED TRUCK WILL NOT RESPOND IF YOU GIVE IT GAS AND ROCKS BACK AND FORWARD LIKE IT IS BEING DRIVEN CUST STATES REPAIRS FOR ACCELERATION TRUCK LOST POWER ENGINE STILL RUNNING NO RESPOND FROM THE ENGINE	521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	ONTION SENSOR REPLACE SENSOR CLEAR CODES RETEST ON VEHICLE RUNS NORMAL. HORN		CUST STATES AT TIMES THE VEHICLE WILL DROP TO IDLE OR ACCEL. WENT TO LET DPF SLOW DOWN AND ACCEL. AS PARTS REPAIRS ON G. S. REPAIRS DRAFTS FROM PMS WILL NOT RESPOND NO REPAIRMENT NECESSARY	521	USA	17179	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	RUN ENGINE PERFORMANCE TEST. LOAD PMS. CONTINUOUS PMS. REPLACE ACCEL. PEDAL AND RETEST SYSTEM PMS. HORN			521	USA	18001	USA	USA	*	NA	PT	811						
ELAS	1848	14	2182	NA	CA	3181	DIAGNOSIS. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST HORN TEST. HORN TEST. HORN TEST			521	USA	18001	USA	USA	*	NA	PT	811						

TOT_CD	CDLBA	DIR	REGI	EST_P	TECH_TXT1	TECH_TXT2	CURT_TXT	AREA	COUNT	BLD_CD	TYP	ENTRY	GRY	VHS	AGE	VRT	TIL	
UNIT	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	CDLBA	
78.00	201.00	3.8	2800	NA	OK	31801	SALES DEPT FREQ AT TIMES ENGINE WILL NOT RESPOND TO THROTTLE	718	USA	182200	2	USA		144	PT	811		
81.00	129.10	1	4800	NA	TK	31801	ENGINE WILL NOT RESPOND TO ACCELERATOR	838	USA	182100	2	USA		144	PT	811		
81.00	213.00	1.8	800	NA	CA	31801	THROTTLE PEDOLE NOT RESPONDING TO PRESSURE AT TIMES	200	USA	122010	2	USA		144	PT	811		
84.00	145.00	1	2800	NA	OH	31801	CUSTOMER STATES THE FUEL PEDAL IS NOT RESPONDING INTERMITTENTLY, NEVER ACTS UP WHEN ON CRUISE CONTROL.	878	USA	147000	2	USA		148	PT	808		
78.00	170.7	1.8	8076	NA	AR	31801	THROTTLE WILL NOT RESPOND TP THROTTLE	478	USA	100011	2	USA		144	PT	811		
81.00	248.00	2.5	80	NA	MD	31801	CRUISE ACCELERATOR HAS FLAT SPOT WHEN ACCEL. WONT RESPOND	488	USA	107000	2	USA		141	PT	811		
78.00	101.17	0.7	3700	NA	MA	31801	ACCELERATOR WONT RESPOND WHEN STOPPED ON	877	USA	100000	1	USA		144	PT	811		
81.00	288.12	1.7	2800	NA	TX	31801	CK GAS PEDAL WILL NOT RESPOND ON ACCEL. INTERM	878	USA	100000	2	USA		141	PT	811		
78.00	281.25	4.8	8188	NA	WI	31801	RETEST OK											
78.00	344.80	2.2	7700	NA	CA	31801	ENGINE WILL NOT RESPOND AT TIMES WHEN ACCELERATOR PEDAL IS DEPRESSSED. THE SERVICE ENGINE LIGHT	414	USA	110000	2	USA		144	PT	811		
78.00	167.00	1.8	8801	NA	WA	31801	CHECK FOR GAS PEDAL NOT RESPONDING CORRECTLY	808	USA	170000	1	USA		144	PT	811		
81.00	288.10	4.1	4817	NA	TX	31801	CUSTOMER STATES ACCEL. PEDAL MUST BE PUSHED 1/4 WAY DOWN BEFORE RESPONDING	208	USA	100000	1	USA		144	PT	811		
81.00	288.10	4.1	4817	NA	TX	31801	FOUND THROTTLE PEDAL DEFECTIVE REPLACED THROTTLE PEDAL ASSEMBY											
81.00	288.10	4.1	4817	NA	TX	31801	2008 BASE WARRANTY PERFORM DIAGN. PERFORMANCE DIAGNOSTIC RECEIVE PCM MODULE CODE P0111 R02NR P0111 CONT. P0221 INJECTOR P1111 CONTRIBUION P1111 TEST BOOST FUEL ICP AND WIP. PERFORMS WITHIN	SPECIFIC POINT TEST AP SENSOR CREDITS OK ON TIME TO REPLACE FAULTY FREQ ACCEL. PEDAL ASSEMBLY CLEARED CODES AND RETEST P1111 TEST ENGINE OK	801	USA	182040	2	USA		144	PT	811	
81.00	127.50	0.7	8815	NA	TX	31801	ACCELERATOR PEDAL NOT RESPONDING NECESSARY TO REPLACE AND RETEST DIAG ON RD 18077											
78.00	180.50	0.8	3842	NA	TX	31801	CUSTOMER STATES OIL ON AND WONT RESPOND TO ACCEL. ENGINE PEDAL ON THE THROTTLE WILL NOT RESPOND	838	USA	180770	2	USA		142	PT	811		
81.00	88.00	0.1	1000	NA	CA	31801	CUSTOMER STATES UPON ACCELERATION POWER FALLS AS IF NOT RESPONDING TO GAS PEDAL POSITION. CHECK & ADJUST	878	USA	180100	2	USA		144	PT	811		

MTL_C	TOT_COLLR	HR	DLR	REGI	ST_P	CPAC	TECH_TXT	TECH_UZ	CONT_TXT	AREA	COOR	SLR	DLR	CHRY	CRTY	WHS	MMR	WVL	TRM
DET	ST	GR	HR	DLR	GR	CD				CD	RY	R	CD	CD	CD	CD	CD	CD	CD
91.62	726.82	1	7492	NA	WV	21801	ACCEL ASSEMBLY NOT WORKING PROPERLY RUN EEC TESTS NOEC P0123 RUN PERFORM TEST AND CHECKED CHECK TO REPLACE FUEL PEDAL ASSEMBLY ASSEMBLED CORRECT ROAD TESTED AS TESTED ALL TESTS PASS THE CODE IS ACCELERATOR PEDAL SENSOR CIRCUIT LOW CIRCUIT RUN PERFORM TEST FROM SAG REPLACED ACCELERATOR PEDAL RUN CLICK TEST TEST DRIVE		CK CUNT STATED FUEL PEDAL WORK RESPOND WHEN PRESSING ON IT PARTS IN 2000	204	USA	14489	204	USA	*	201	27	211	
81.92	772.82	2	182	NA	GA	21801			CK CUSTOMER STATES SAG PEDAL DOESNT RESPOND AT TIMES WHEN YOU PUSH IT IN CK APPROX 02 028	770	USA	191437	204	USA	*	244	11	211	
78.82	284.2	5.1	1420	NA	PA	21801	ROAD TEST 20 MILES. STAR TEST KOMO CONT FUEL, FUEL RGR PASS, HISS P10 DATA MONITOR SCP, PERFORM TEST. 104 PER BREAKOUT BOX, REMOVE LOWER DASH PANEL, REPLACE ACCELERATOR PEDALS BY EVALUATION SW. CHECKED AND VERIFIED CONCERN, NAN BEC TEST AND ALL PASSED CODES, PERFORMED PERFORM TEST AND FOUND ACCELERATOR PEDAL SAG, RESEMED AND REPLACED PEDAL AND RESEMED FOR CONCERN NONE FOUND, WIPED	TOP OIL HAS SOME OF ABSENCE, LOW OIL STABILITY TEST. VEHICLE PERFORMED REPELLY DURING ROADTEST. INTERMITTENT CONCERN IF CONCERN CONTINUES CUSTOMER SHOULD NOTE UNDER WHAT CONDITIONS THIS OCCURS.	WIPERS LIGHT ON DRIVE FOR ABOUT 45 MIN SEEMS TO ALMOST CUT OUT TOTALLY ACCEL NO RESPONSE GOES DOWN TO 0	810	USA	118284	2	USA	*	252	11	211	
81.82	148.28	1	7792	NA	PA	21801		CLAND ALL DE	CHECK CUSTOMER STATES THAT THE VEHICLE SEEMS AT THE AM COLD THE VEHICLE WILL NOT RESPOND TO FUEL PEDAL WILL JUST	720	USA	148228	204	USA	*	241	11	211	
81.82	138.21	0.8	2014	NA	CA	21801	1788 ACCEL PEDAL. I HVE VERIFIED CONCERN. EEC TEST CONT MEN PRICES. TEST. REPLACED ACCEL PEDAL DUE TO INTERMITTENT FAULT. CALIBR. SPIN CODES 42		CUSTOMER STATES ENGINE DOESNT RESPOND TO ACCELERATOR AT THE 100 3 TIMES IN 2 140	820	USA	171429	204	USA	*	241	11	211	
78.82	222.46	2.9	20026	NA	AZ	21801	CALLED JORD HOTLINE, CONTACT ED 378 888 DTM NO RELATED INFO PER CONCERN. POLICE INTERMITTENT OPEN CIRCUIT IN PEDAL ASSEMBLY ELECTRICAL CODE P0221 AND REPROGRAM PCM UPDAT 4202P 2888 NO TEST DRIVE TO VERIFY, FEELS SLOW TO RESPOND TO ACCEL AND AT TIMES FEELS STOP. PERFORM F3 OUT TESTS VERIFY NEW INSTALLED CODES PERFORM PERFORM TESTS AND REPLACED ACCEL PEDAL ASSEMBLY TEST DROVE 2 TO 8 MILES ON		CUSTOMER STATES ON ACCEL, VEHICLE SEEMS TO NOT RESPOND TO ACCEL PEDAL UNITS. PRESSED MORE	480	USA	171178	2	USA	*	241	11	211	
81.82	164.82	0.8	7800	NA	WV	21801	ML ON RUN NORMALLY, EEC KOEM P0222.222. BOND/CIRCUIT PASS. PERFORM TEST, PED AT 20 YMS OFF, 2Y ONLS, 1 OIL, POSSIBLE GAS PEDAL. INTERMITTENT FAULT NAME AT THIS TIME. REPLACED GAS PEDAL CLEAN CODES.		CUSTOMER STATES TO CHECK FOR CAUSE WHEN ACCELERATING AT TIMES ENGINE WILL NOT RESPOND LIKE GAS PEDAL IS NOT HOOKED UP	770	USA	120228	204	USA	*	241	11	211	
78.82	282.8	1.2	7982	NA	CA	21801	CHECK AND REPLACE ACCEL PEDAL TEST SYSTEM, ROAD TEST, 2 YMS FOR NO OPERATION TOP/REPLACED PEDAL AND SENSOR ASSEMBLY		ACCEL PEDAL WILL NOT RESPOND WHEN PULSED INTERMIT	700	USA	147227	2	USA	*	244	27	211	
81.82	228.81	0.3	1888	NA	ME	21801	NO OPERATION TOP/REPLACED PEDAL AND SENSOR ASSEMBLY		CUSTOMER STATES SOMETIME THROTTLE WILL NOT RESPOND, GET NO RPM	200	USA	111228	204	USA	*	244	27	211	
78.82	128.28	0.7	8430	NA	CA	21801	UP SENSOR AND TESTED FUEL, 2 YMS OF 2 ASKED FOR TO RUN PER POINT TEST PER FUEL		TRUCK WONT RESPOND WHEN YOU PRESS GAS	700	USA	171181	202	USA	*	244	27	211	
78.82	192.88	0.5	872	NA	NY	21801	CHANGED WIRE ON PEDAL ASSEMBLY. BY TIME TO REPLACE PEDAL ASSEMBLY, NO UP TO 200 2 12 200 2		CUSTOMER STATES THE ENGINE WILL NOT RESPOND TO THE THROTTLE WHEN DEPRESS EVEN IF THE VEHICLE IS WARMED UP FOR A WHILE	710	USA	144224	1	USA	*	241	27	211	
84.24	181.41	1.1	1822	NA	TX	21801	PERFORMED DIAGNOSTICS CLEAN FUEL, CHECK OIL LEVEL, INTAKE RESTRICTION PERFORM MONITOR PER BUSINESS ACCELERATOR PEDAL		ACCEL PEDAL DOES NOT RESPOND	100	USA	100000	272	USA	*	252	27	211	

TRFL_CD	STL_OR	HR	DAI_CD	DAI_CD	ST_P	ST_P	OPC	TECH_TXT1	TECH_TXT2	CLTY_TXT	AREA_CD	COUNT_CD	BLK_CD	TRM_CD	CONTRY_CD	SPD_CD	VPS_CD	AWR_CD	VTY_CD	TRM_PLA
0	0	0	0	0	0	0	0													
76.96	188.58	0.8	808		NA	NC	31801	REPL ACCEL PEDAL		ACCELERATOR PEDAL WONT WORK AT TIME	388	USA	121977	884	USA		NA	FT	811	
76.96	187.34	1.4	788		NA	CA	31801	VERIFY CONNECTION AND RECHECK DOORS PERIOD MODE PERFORM PREPOINT TEST, FOUND SWITCH OPEN A PEDAL REPLACE A PEDAL SWITCH ASSY, CLEAN CODES AND RECHECK, OK AT TIME		CUSTOMER STATES WONT GET OFF IDLE THROTTLE WONT RESPONER AT ALL	767	USA	17262	884	USA		NA	FT	811	
76.96	180.8	0.7	8148		NA	LA	31801	OPEN CIRCUIT BLEP VALVE FROM SWITCH AT TIME PERFORM EEC TEST PERFORM DCL DMS REPLACE AP PEDAL ASSY OPEN CIRCUIT		INSPECT ACCELERATOR WONT RESPONER AT TIME	287	USA	18282	884	USA		NA	FT	811	
81.52	188.28	1.7	8944		NA	TX	31801	CODES WERE MONITORED PER PERFORMED PP TESTS REPLACED ACCELERATOR PEDAL ASSEMBLY CLEANED CODES PERFORM VEHICLE OPERATED PROPERLY		G & B TRUCK WONT TAKE OFF AT TIME HAD TO PLAY WITH PEDAL DMS	373	USA	18897	884	USA		NA	FT	811	
88.54	142.58	0.8	1687		NA	CA	31801	ASSEMBLY CHECK W/ISS CC 48 18000 03,048 DASH E3 TECH 183 88 FLAG 108 CONCERNING THROTTLE RESPONSE AT TIME, CAUSE PERFORMED EEC TEST AND RETRIEVED CODE P0268 AND P0261 PERFORMED PREPOINT TEST AND TIME	TERMINED THAT THROTTLE POSITION SENSOR PEDAL ASSY WAS NOT OPERATING PROPERLY, CORRECTION REMOVED AND REPLACED THROTTLE PEDAL ASSY, READ TESTED AND CHECKED FOR OPERATION OK AT	DMS THROTTLE WONT RESPON AT TIME	288	USA	17378	884	USA		NA	FT	811	
81.52	137.03	1.3	4378		NA	ME	31801	REPLACED THROTTLE PEDAL ASSEMBLY		ENGINE WONT COME ABOVE AN IDLE AT TIME	207	USA	11158	884	USA		NA	FT	811	
88.54	271.06	1.1	8582		NA	CA	31801	THROTTLE PEDAL PRESS, INSPECTING PEDAL, MODE P0268, MODE P0261, PREPOINT TEST, REPLACED THROTTLE PEDAL		CUSTOMER STATES THE ACCELERATOR PEDAL DOES NOT WORK WHEN INSTANTLY	881	USA	17188	884	USA		NA	FT	808	
78.88	137.43	1.3	2887		NA	OH	31801	OPEN CIRCUIT IN PEDAL, PERFORMED DMS, CHANGED AND FOUND ACCELERATOR PEDAL, W/TH INTERMITTENT OPEN CIRCUIT, REPLACED PEDAL ASSEMBLY, OK		CLTY STATES THAT AT TIME THE VEHICLE DOES NOT WORK PROPERLY FROM ACCELERATOR PEDAL	874	USA	15758	1	USA		NA	FT	811	
81.52	141.88	0.9	2788		NA	KY	31801	CHECK CODES CONT GET TP NOT RESPONER CHECK W 8888 R AND R ACCELERATOR PEDAL, CLEAN CODES PERFORM TEST OK		ACCELERATOR DOES NOT WORK ALL OF THE TIME	822	USA	14724	884	USA		NA	FT	811	
78.88	242.75	1.3	8284		NA	MI	31801	NO CRACK AP SENSOR & CRACK TEST DRIVE WHEN ACCELERATOR DEPRESSSED, AIR DAME ON AND TRUCK DID NOT MOVE, PERFORMED COMPLETE DMS, DMS, FOUND CODE P0268 PERFORM CHECK DMS MO HELP, CALLED NATURE RA	TP TO BE REPLACED AP SENSOR, ORDERED PART, PART PUT ON DMS, FOUND LOT TRUCK AND RECALIBRATED AP ASSEMBLY FROM IT, AND INSTALLED ON THE TRUCK AS PER ITEM. TEST DRIVE 4 MILES ALL OK, NO CHECK	CUSTOMER STATES GAS PEDAL DOES NOT WORK WHEN PERFORMED, ENGINE STAYS AT IDLE SPEED	881	USA	15887	2	USA		NA	FT	811	
78.88	182.87	1	3848		NA	LA	31801	EE ACCELERATOR/BLM EEC TEST, FOUND DTE CODE P0268 PERFORM PREPOINT TEST, FOUND PEDAL ASSEMBLY IN SHORT, REPLACED ASSEMBLY		EE ACCELERATOR DOES NOT WORK AT TIME	888	USA	12918	884	USA		NA	FT	808	
84.38	188.88	1.4	3887		NA	TX	31801	EEC TEST MONITOR PERFORM TEST, REPLACE BMAP EP SENSOR 1		G & B ACCELERATOR PEDAL DOES NOT WORK AT TIME	373	USA	18898	884	USA		NA	FT	811	
78.88	168.77	1.4	2821		NA	TX	31801	PERFORM EEC TEST, PREPOINT FOR CODE P0261, W/ MONITOR REPLACE ACCE PEDAL ASSY		GAS PEDAL DOES NOT WORK INSTANTLY	888	USA	15824	1	USA		NA	FT	811	
81.52	168.42	0.8	2788		NA	CA	31801	REPLACED ACCELERATOR PEDAL ASSEMBLY PER PREVIOUS DIAGNOSIS ON POWERTRAIN, RECHECKED FOR DOORS, SYSTEM OPERATION NORMAL, AFTER REPAIR		CUSTOMER STATES THAT ACCELERATOR DOES NOT WORK PROPERLY, REPAIR PER VEHICLE DIAGNOSIS ON RECHECKS	787	USA	17278	1	USA		NA	FT	811	
81.52	82.88	1.2	4378		NA	TX	31801	ACCELERATOR PEDAL		ACCELERATOR DOES NOT WORK PROPERLY	888	USA	18818	884	USA		NA	LA	811	

INTR. C	TOT. COLL	HR	DUR. C	CL. C	PRM. C	WT. P	SPNC.	TECH. TEXT	TECH. TEXT	CLERK. TEXT	AREA	COMP.	PL. IL.	TOL.	CMPY.	CRIT.	WPS	WPS	PLA.	
CD	CD	E	D	D	D	CD	CD				CD	CD	CD	CD	CD	CD	CD	CD	CD	
85.24	180.24	0.5	480		NA	GA	2190	PEDAL FAILED REPLACE ACCELERATOR PEDAL ASSEMBLY		CUSTOMER STATES CK AND ADJUSTS GAS PEDAL IS NOT WORKING PROPERLY	720	USA	21288	USA		NA	PT	211		
87.85	180.81	1.3	2700		NA	NC	2180	1 ROAD TESTED WITH CUSTOMER. VERIFIED CONCERN. CONNECTED NEG. DTC P0222 TO HIGH IMPACT PED DISPLAY MONITOR TEST. MONITORED AP AND MS BOTH PROB OPERATING AS DESIGNED. IN AT IDLE AND LOW AT WOT ENGINE PERFORMANCE TEST OK AND PERFORM ALL TESTS AND ONE AND WITHIN CODES FROM OK AND PROFOM AND FOLDING BAD ACCELERATOR PEDAL, INTERMITTENT AND REPLACED AND THEN RETEST AND PERFORMANCE TESTS AND	VE IS SWITCHING ON AND OFF JUST OFF IDLE. CHECK ENGINE LIGHT CODES AT TIME OF CONCERN. REPLACED AP SENSOR PEDAL ASSEMBLY TO TRY. WHEN PCM MET LAS REPL. ACCELAP SENSOR PEDAL ASSEMBLY	REPAIR FOR NOT WORKING GOOD	604	CAN	48701	USA	USA		NA	PT	211	
79.92	240.92	3.8	800		NA	VT	2190	READ FOLDER FOR LOCKS AND PEDAL FALLS OFF FOR LOCKS PEDAL, BODY TEST OK	ALL FINE NOW.	CUSTOMER STATES ACCELERATOR IS NOT WORKING CORRECTLY. PUSH PEDAL, DOWN ACCELERATE INTERMITTENTLY.	604	USA	20320	1	USA		NA	PT	211	
85.4	125.41	8.7	8000		NA	AB	2190	READ FOLDER FOR LOCKS AND PEDAL FALLS OFF FOR LOCKS PEDAL, BODY TEST OK		REPAIR FOOT PEDAL, NOT WORKING PROPERLY	720	CAN	48701	USA		NA	PT	211		
81.62	104.17	0.4	800		NA	NC	2190	CHECK ACCEL PEDAL BROKEN REPLACED ACCEL PEDAL, (STRE BROKEN CODE 81)		CUSTOMER STATES FUEL PEDAL, NOT WORKING CORRECTLY	604	USA	21288	USA		NA	PT	211		
85.28	81.28	0.4	4000		NA	CA	2190	FOUND IT TO BE BAD REPLACED THROTTLE PEDAL ASSEMBLY CHECKED OUT REPLACED ACCEL PEDAL PEDAL ASSEMBLY		THROTTLE PEDAL NOT WORKING PROPERLY ACCELERATOR PEDAL DOES NOT WORK AT TIMES		USA	17388	USA		NA	PT	211		
108.18	212.80	1	200		NA	ND	2000				604	USA	21288	USA		NA	PT	211		
80.2	100.20	0.8	400		NA	TX	2190	TESTED CIR TO THROTTLE POS. AND WIRE FOUND SENSOR OUT OF SPECIFICATIONS THROTTLE ASSEMBLY. CHECK ACCEL PEDAL, NOT WORKING. VERIFY ACCEL PEDAL, LAUNDRY CHASE APART, REMOVE OLD ACCEL PEDAL & REPLACE WITH NEW. VERIFY PROPER OPERATION.		GAS PEDAL, NOT WORKING	604	USA	20320	USA		NA	PT	211		
81.82	81.82	0.2	800		NA	NY	2190	CHECK AND REPLACE ACCELERATOR PEDAL		CUSTOMER STATES ACCEL PEDAL NOT WORKING AS IT SHOULD BE CUSTOMER CHECK ACCELERATOR PEDAL, NOT WORKING	720	USA	14418	USA		NA	PT	211		
85.4	100.40	0.3	4000		NA	AB	2190	CHECK FOR NO ACCEL, MAP DOD PEDAL, NO MONITOR, APSTP & ALL THING OPEN IN ITP. REPLACE PEDAL ASSEMBLY, & RETEST ALL PAGE			720	CAN	48701	USA		NA	PT	211		
81.62	124.52	1.1	800		NA	TX	2190	SPARK WASH CHECKED FOR NO SPARKS AND THROTTLE PEDAL, MAP CHECKED FOUND FUEL IN BLOWN CHECKED CIRCUIT FOR SHORTS REACHED INTERMITTENT CLUSTER TO GAIN ACCESS TO WIRE CHECKED REWOUND WIRE DICK P	WIRE FOUND ACROSS POWER CONTROL MODULE CONNECTOR AND SHORT IN CIRCUIT AIR PREPARED CIRCUIT REWOUND INTERMITTENT CLUSTER, TESTED OK BUT STILL HAD NO THROTTLE RESPONSE REPLACED	CUSTOMER STATES ACCELERATOR PEDAL NOT WORKING PROPERLY.	604	USA	18377	USA		NA	PT	211		
85.8	185.8	1.8	800		NA	LA	2190			O. CLERK SAYS WHILE DRIVING VEH ALL THE GAUGES SHUT OFF, THROTTLE ENGINE SHUT OFF, BUT GAS PEDAL, WORKS NOT WORK PLEASE ON TRUCK AT TIME WHEN YELL STRUT TRUCK IF ENGINE MAKES CRACKING SOUND THE ACCELERATOR NOT WORKING	604	USA	12340	USA		NA	PT	211		
81.62	78.62	0.8	800		NA	LA	2190	DOES NOT OPERATE PROPERLY ENGINE PERFORMANCE CHARACTERISTICS V.E. IS TURNING OVER BUT WHEN IN THROTTLE POSITION NO COARDS FROM MONITORING PEDAL AND FOLDING OPEN AT BETWEEN 80% IS THROTTLE CHANGE POSIBLE NOT AND RETEST ALL OK.		CHECK AND ADVISE FOR THROTTLE NOT WORKING AT TIMES PEDAL ASSEMBLY, IS NOT WORKING PROPERLY ACCELERATOR PEDAL, NOT WORKING	604	CAN	48701	USA		NA	PT	211		
79.82	87.82	0.4	800		NA	AR	2190	WIRE FOR ACCEL PEDAL			604	USA	18348	2	USA		NA	PT	211	
81.82	81.82	1	200		NA	CA	2190	ACCELERATOR PEDAL, CORRECT ADJUST			604	USA	17388	USA		NA	PT	211		

E203-044-A 5461

MTL	TOY	LAB	COL	FORM	REV	DATE	TECH	TECH	DATE	AREA	COUNT	DATE	TYPE	GROUP	AGE	AGE	TR		
NO	OTA	OR	NO	NO	NO	NO	TEXT	TEXT	TEXT	CD	CD	CD	CD	CD	CD	CD	CD		
79.86	183.28	1.3	6491	NA	LA	21891	MYSE TO REPLACE ACCELERATOR PEDAL			OR TRUCK ACCELERATOR PEDAL NOT WORKING	327	USA	19200	1	USA	NA4	F7	811	
79.86	183.28	4.8	2129	NA	TN	21891	PERFORMANCE DUAL DYS FORD E POWER BAD TPS NO REPLACED FUEL PEDAL			GAS PEDAL NOT WORKING	88	USA	12122	1	USA	NA4	F7	811	
81.82	120.84	0.7	0886	NA	MB	21891	ACCELERATOR PEDAL LOOSE (AND RUPRAL ASSEMBLY) DUE TO PEDAL FALLING OFF			CHECK ACCELERATOR PEDAL NOT WORKING PROPERLY	801	USA	19200	1	USA	NA4	F7	811	
81.82	120.84	0.8	2838	NA	TX	21891	INSPECTED AND FOUND GAS PEDAL PIN BUSHING REPLACED BY NEW ASSEMBLY PROBLEM LIKE TEST DISCOVERED BRACKET AND CHANGE WIRING W/NEW W/PAIR INSTRUMENT PANEL ADDRESS MOTOR REPAIR PARTS			CUSTOMER STATES GAS PEDAL NOT WORKING PROPERLY	800	USA	19200	1	USA	NA1	F1	811	
128.84	248.88	2.4	284	NA	GA	21891	W/PAIR INSTRUMENT PANEL ADDRESS MOTOR REPAIR PARTS			AIR BOND IS NOT WORKING PROPERLY	770	USA	11900	1	USA	V79	F7	808	
85.4	112.88	0.4	AD77	NA	BC	21891	NOVA TESTED OPERATIONAL TESTED & REPLACED FAULTY THROTTLE PEDAL ASSEMBLY/ADJUST OPERATION			GAS PEDAL NOT WORKING PROPERLY	300	CAN	45281	1	CAN	V43	F7	811	
81.82	114.28	0.5	0886	NA	NY	21891	1 PERFORMANCE TEST PLAT SPOT IN TPS REPLACED FROM ASSEMBLY			AFTER REPAIRS TO GET TRUCK REARWIDE FORD ACCELERATOR PEDAL AND RESPONSE NOT WORKING	882	USA	12180	1	USA	NA4	F7	811	
79.86	183.28	0.8	0886	NA	VA	21891	INSTALL NEW PEDAL ASY			CHECK GAS PEDAL NOT WORKING BRAKE PEDAL IS NOT WORKING PROPERLY	278	USA	12200	1	USA	NA4	F7	811	
85.4	180.48	0.2	8047	NA	AR	21891	REPLACE THE BRAKE PEDAL			CHECK GAS PEDAL NOT WORKING PROPERLY	180	CAN	48807	1	CAN	V01	F7	810	
81.82	177.78	0.0	8078	NA	OR	21891	INSPECT AND VERIFY REPLACE PEDAL ASSEMBLY. CHECK FOOT PEDAL BUSHING REPLACED PEDAL ASSEMBLY WAS NOT WORKING PROPERLY.			CUSTOMER STATES THROTTLE PEDAL IS NOT WORKING PROPERLY FUEL PEDAL IS NOT WORKING PROPERLY. PLEASE ADVISE.	800	USA	17400	1	USA	V74	F7	808	
85.4	118.88	0.4	8074	NA	MS	21891				CHECK GAS PEDAL NOT WORKING AT THREE	800	CAN	48800	1	CAN	V41	F7	811	
81.82	169.87	2.8	8888	NA	TN	21891	REPLACE TP SENSOR AND PEDAL ASSEMBLY WITH PEDAL PIVOT ROD REPAIR KIT REPLACED WITH			CHECK GAS PEDAL NOT WORKING PROPERLY	818	USA	12200	1	USA	NA4	F7	811	
80.88	80.78	0.4	45187	NA	CA	21891	NEW PEDAL ASSEMBLY			GAS PEDAL NOT WORKING PROPERLY		USA	17100	1	USA	NA4	F7	811	
							CHECK GAS PEDAL NOT WORKING PERFORMING TEST PERFORM TEST MONITOR TEST FINAL CHECK TEST CHECK AND REPLACE BRAKE CHECK CHECK AND REPLACE ALL FLUIDS CHECK OK M TIME TO REPLACE BRAKE PEDAL SWITCH NCL AR	OR OPERATION IN LOCK											
118.88	272.88	1.8	2870	NA	MI	21891				CUSTOMER STATES WHEN TAKING TURN AT 18 MPH GAS PEDAL NOT WORKING NOT WORKING	878	USA	19200	1	USA	NA4	F7	811	
85.4	111.77	0.4	8722	NA	SD	21891	RE LINE GAS PEDAL ASSEMBLY CHECK FOOT FOR LOOSE PART. LOOSE AND FURTHER TESTING INDICATES PEDAL REPAIR ASSEMBLY.			REPAIR GAS PEDAL NOT OPERATING	300	CAN	45280	1	CAN	NA4	F7	811	
80.84	241.77	2.8	778	NA	CA	21891	BAD ACCELERATOR TEST BROKE ACCELERATOR NOT WORKING, PIN POINT CHECKS CODE P104, P105 ACCELERATOR PEDAL. RETEST PROBLEM RESOLVED			PEDAL DOES NOT OPERATE PROPERLY	408	USA	12200	1	USA	V41	F7	808	
80.84	104.87	0.8	2887	NA	GA	21891	REPAIRING ACCELERATOR PEDAL ASSEMBLY COC DRO CC OR NOTED WHILE CHECKING OR STARTER CONCERN THAT ACCELERATOR PEDAL IS BINDING. PEDAL STEM P HAS SEPARATED FROM ASSEMBLY. CAN	CORN CORRECTED. MIF USED DUE TO NO LABOR OP FOR NON ADJUSTABLE PEDAL.			CUSTOMER STATED THE ACCELERATOR IS NOT OPERATING PROPERLY	708	USA	12470	1	USA	NA4	F7	811
81.82	118.72	0.8	882	NA	VA	21891	TEST AND REPLACE ACC PEDAL TO CORRECT			NOTED WHILE IN SHOP...ACCELERATOR PEDAL NOT OPERATING PROPERLY OR ACCELERATOR NOT RESPOND WHEN ACCELERATED	840	USA	12200	1	USA	NA4	F7	811	
81.82	126.09	1	2886	NA	VA	21891	INSPECTIVE ACC PEDAL REPLACED PEDAL			NO PEDAL REACTION	228	USA	12180	1	USA	V41	F7	811	
78.84	264.88	4	2882	NA	TX	21891													

AREA	COUNT	BLK	DL	TOL	DNTRY	CRD	WFS	AWR	WRT	TR	FLA										
CD	BY	CD	CD	CD	CD	CD	CD	CD	CD	CD	CD										
81.82	280.18	4.2	2891	*	NA	AZ	3189														
<p>PERFORMED DI CHART TEST 1 4 OK LSP 34 MOOSEY WALKED, KICKED WALK AND KICKER ALL. FUEL PRESSURE W/ PRESSURE CODE. FUEL PRESSURE W/ PRESSURE FOLLOW STEADY 480 THROTTLE PEDAL GOES OPEN INTERMITTENT. REPAIR INSTALLED NEW THROTTLE PEDAL ASSEMBLY AND TEST</p>											NO THROTTLE PEDAL	CUSTOMER STATES THROTTLE HAS NO RESPONSE AT TIME DI WARRANTY	828	USA	48028	EM	USA	*	144	PT	811
80.84	103.18	8.4	2810	*	NA	WY	3189														
<p>DRIVE PERFORMANCE WAS FOUND 2 THROTTLE POSITION SENSOR CODES P14 POINT DIAG FOUND THROTTLE POSITION SENSOR AND REPLACE Y POSITION SENSOR</p>												ENGINE WILL NOT THROTTLE UP	387	USA	48182	EM	USA	*	144	PT	811
81.82	122.88	8.8	1183	*	NA	OR	3189														
<p>PERFORM W/ RETRIEVE CODES CHECK MS SWITCH REPLACE MS SWITCH PEDAL ACCELERATOR ARM. CLEAR CODES RETEST OK</p>												INTERMITTENT LOSS OF THROTTLE CUSTOMER STATES W/IDE OPENING ACCELERATOR CONTROL IN LIGHT INTERMITTENTLY COMES BACK AFTER 10 SECONDS		USA	48187	EM	USA	*	141	PT	811
80.84	489.81	4.4	713	*	NA	CA	3189														
<p>CUTS OUT WHILE DRIVING PERFORMED DIAG CHART TEST 1 4 OK HOOD RETRIEVED INJECTOR AND HOOD ALL FUEL PRESSURE FUEL PRESSURE BY FUEL RESTRICTION CP FOLLOW STABILITY SELECT PRESSURE CLEAR</p>											4.80007 2/16 FUEL THROTTLE PEDAL CUTS OUT INTERMITTENT. REPLACE THROTTLE PEDAL. MT FUE TO NO LARGER CODES	CUSTOMER STATES THAT VEHICLE USES NO THROTTLE CUSTOMER STATES DRIVING 60MPH VEHICLE STAYS AT 60MPH WHEN YOU PRESS TO STOP ON THE PEDAL AGAIN AND THE VEHICLE WILL GO	848	USA	17188	1	USA	*	117	PT	808
81.82	272.88	4.1	20301	*	NA	AZ	3189														
<p>CODE P1522 GAS PEDAL. FUELING PERFORMED ROAD TEST AND VEHICLE COMPLAINT PERFORMED HOOD AND KICK TESTS CODE P1522</p>													883	USA	17111	EM	USA	*	141	PT	811
78.88	184.28	1.8	8137	*	NA	AR	3189														
<p>3/13 87008 PEDAL 41 ONOP ROAD TEST AND VERIFY CUSTOMER CONCERN BLUR DRIVE NO CONCERN FOUND 38888 ENGINE DIAG. SEE AT 3/13/87 8000 CONT. P0221 HOOD DIAGNOSTIC TEST PASS KICK TEST PASS OK TEST AND MON VERIFY CONCERN NO CONCERN PRESENT AT THIS TIME. ROAD TEST PEDAL NOT RESPONDING REPLACED GAS PEDAL AS PER SHOP POLICY</p>											FOR P0221 MONITOR TP AND NS FOUND SENSOR DATE OF FAILURE AT TIMES WHICH CONCERN IS PRESENT. PER POINT TEST AND FOUND PEDAL ARM. FULLY REPLACE PEDAL ARM. AND RETEST PASS ROAD TEST BLANKING	ON THROTTLE WILL GO DEAD WHILE DOWNSHIFT FROM 4M	417	USA	18088	1	USA	*	144	PT	811
81.88	183.78	1	4088	*	NA	FL	3189														
<p>RAN 800 TEST BEFORE TEST R AND R PEDAL ARM AND RESET W/PL 1. VERIFIED, TESTED AND FOUND TP OUT OF RANGE, REPLACED THROTTLE POSITION SENSOR</p>												CUSTOMER STATES ON ACC WILL HAVE NO PEDAL AT ALL DEEPEN FOR ACCELERATOR PEDAL. DOESN'T DO ANYTHING WHEN BLURD DOWN	883	USA	18008	EM	USA	*	144	PT	811
78.88	108.88	0.8	8281	*	NA	IA	3189														
<p>VERIFY GEL ON THROTTLE WORKS NORMALLY. W/MS PRESSURE TEST WITH SENSOR HOODUP. THROTTLE OK. POINT TEST OK. OK. W/PLUCH IN VOLTS. INJECTION CONT PRESSURE TEST. PASS. LOW CLW 80AS TEST. JUNE 08 PRESS. PASS. OK INSPECT AND VERIFY ECU TEST FULL CODES MONITOR FOR MS LINES IN SIGNAL AND ECU VALIDATION SWITCH NOT WORKING PROPERLY INSPECT WIRING OK REPLACE THROTTLE PEDAL ASSEMBLY CLEAR CODES RETEST TEST PASS. OK</p>											AT THE TIME. W/MS PRESSURE RESTRICTION TEST. PMS. BOOST TEST. PASS. FUEL DOWN. TEST. TEST. PASS. IN TAKE. TEST TEST. PASS. CLEAR CODES. REPROGRAM PCM. REPLACE THROTTLE PEDAL RETEST. PASS. ROAD TEST. OK	CUSTOMER STATES THE THROTTLE PEDAL STOPPED WORKING (WHEN DRIVING)	881	USA	18008	EM	USA	*	144	PT	811
81.88	183.81	1.8	8878	*	NA	OR	3189														
<p>CUSTOMER STATES THROTTLE DOESN'T WORK PROPERLY</p>													883	USA	17488	EM	USA	*	141	PT	811

WTRC EST	TOTL ST. SW 569	LBR LN 9	CLK CLK 0	OR OR 0	ST ST 0	PRN PRN 0	OPR OPR 0	TECH TEXT	TECH TEXT	CUST TEXT	AREA CD	COUNT BY CD	SLIP SLIP CD	DDL DDL CD	CHRY WORLD	GRU GRU CD	APR APR CD	WTR WTR CD	TR PLA 9
81.52	182.27	1.8	3142	MA	CA	3188		RAN ESC TEST ALL PMS CODES DCL. DISPLAY PD MONITOR TEST PMPONT TEST NO TIME TO REPLACE PEDAL. ASSEMBLY REJECT OK TEST DRIVE OK. RESPECTIVE ACCELERATOR PEDAL.		CUSTOMER STATES NO THROTTLE RESPONSE IMMEDIATELY WHEN REPARTED NEXT. LASTS FOR A GOODFUL OF MINUTES.	78	USA	18228	EN	USA		MA4	F7	811
81.52	188.8	0.8	3142	MA	CA	3188		WHEEL TO INSPECT TEST REPLACE PEDAL ASSEMBLY REJECT. REPLACED PEDAL ASSEMBLY AND RECHECKED DRIVE.		CUST REPORTS SOMETIMES FUEL PEDAL POINTS UP. FUELING CHECK AND ADJUST ACCEL PEDAL. WILL NOT RESPOND.	288	USA	18878	EN	USA		MA4	F7	811
81.52	188.81	1	3142	MA	CA	3188		TEST AND FOUND THE TP PEDAL SWITCH BAD. REPLACED SWITCH AND REJECT. METRIC FOR NO LABOR OPERATOR FOR THIS REPAIR.		C/E THE ENGINE WOULD WILL STAY AT IDLE WHILE PUSING THE GAS PEDAL. INTERMITTENT.	787	USA	17884	EN	USA		MA4	F7	811
81.52	77.81	1.4	3142	MA	UT	3188					48	USA	10884	EN	USA		MA4	F7	811
85.54	148.72	0.9	3178	MA	CA	3188		TESTED SYSTEM REPLACED ACCELERATOR PEDAL ASSEMBLY.		CUST STATED ON 3 OR 4 OCCASIONS, WHEN YOU APPLY THROTTLE THE ENGINE WILL JUST IDLE. APPLY THROTTLE SEVERAL TIMES AND TURNED ENGINE OFF AND ON AND IT WILL EVENTUALLY WORK.	63	USA	17289	EN	USA		MA4	F7	811
81.52	173.27	1.5	3187	MA	CA	3188		SEMS ON FOR INTERMITTENT NO ACCELERATION. INSPECT PERFORMED NEW DIAG. XEROX PARTS MONITORED. MSF PDS FOR AP AND MS. FOUND NO MS RESPONSE AT THROTTLE. ACCELERATOR PEDAL ASSEMBLY. REJECT OK. REJECT SHOP. METRIC FOR NO LABOR OPERATOR. TEST REPL ACCELERATOR PEDAL. SWITCH REJECT REPAIR.		OK FOR INTERMITTENTLY AFTER STAY UP WHEN YOU PUSH ON THE ACCELERATOR THE VEH. LIST IDLE BUT WHEN YOU LET OFF OF IT THEN BACK ON IT WORKS. PMS.	819	USA	14284	EN	USA		MA4	F7	811
TR.88	108.88	0.4	3177	MA	MD	3188				CUST STE ENGINE DROPS TO IDLE WHILE DRIVING AT TIMES.	301	USA	12708	EN	USA		MA5	L1	811
81.54	254.3	2.3	3174	MA	CA	3188		TEST ESC SYSTEM. ACC. PMS. FUEL. ROAD TEST WITH MONITOR. PMPONT TEST. IN TIME TO REPL. GAS PEDAL. SENSOR ASSEMBLY FOR WILL NOT ACCELERATE AT TIMES. CONCERN NO RESPONSE FROM ACC. PEDAL. ROAD TEST AND MONITOR. REPLACED AP AND ROAD TEST OK. NOW.		AT TIMES WITH IDLE ON AT TIMES NO THROTTLE.	788	USA	17108	EN	USA		MA1	L1	811
81.52	161.32	7.4	3188	MA	CA	3188		ACCEL. PEDAL. FUEL. TEST. PMS. FUEL. TEST. MONITOR. PMS. AND FOUND ACCELERATOR PEDAL ASSEMBLY FAULTY. REPLACE AP SENSOR ASSEMBLY. REJECT OKAY.		STEP ON ACCEL. PEDAL AT IDLE. WILL STAY AT IDLE.	988	USA	18828	EN	USA		MA1	F7	811
81.52	348.81	4.1	3188	MA	TX	3188		PERFORMED ENGINE PERFORMANCE DIAGNOSIS. ACC. PEDAL. 1821 MET. REPLACED ACCELERATOR PEDAL AND REJECT PARTS.		CUST STATES ENGINE GOES TO AN IDLE WHILE DRIVING.	381	USA	18228	EN	USA		MA1	F7	811
100.53	321.16	3.1	31792	MA	NC	10088			KAM SENSOR ENGINE. REPLACE KAM SENSOR. 1.8 ADDITIONAL TIME TO REPLACE KAM SENSOR DUE TO AFTERMARKET SET LIP ON FALLOFFS AND FTO SET UP. 3.7 HRS FOR ELECTRICAL DIAGNOSIS PLUS ALL. ESC.	THE VEH STARTS AND IDLES PMS BUT AS SOON AS YOU STEP ON THE GAS IT.	230	CAN	48224	EN	CAN		MA1	E1	811
102.84	848.25	8	3167	MA	MS	3188		SEMS ELECTRICAL W/ PERFORMANCE ESC TEST. PMS. TP ON PEDAL ASSEMBLY NEEDED. REPLACE PEDAL ASSEMBLY. NO CHANGES. OTHER CODES. PMS. GLOW PLUG INDICATOR. PMS. WATER PUMP INDICATOR NOT RESPONDING. PMS. REPAIRS. PMS. PMPONT TEST. REPLACED GAS PEDAL. ROAD AND ESC TEST. PMS. REPLACED ACCELERATOR PEDAL ASSEMBLY TEST DRIVE. VERIFIED REPAIR.		ONE OF THE ACCELERATOR HAS NO EFFECT ON ENGINE. ENGINE STAYS AT IDLE WHEN PUSHING ACCELERATOR.	819	USA	15727	2	USA		MA4	F7	811
81.52	178.82	0.8	3188	MA	ME	3188				CHECK VEHICLE GOES TO IDLE SOMETIMES.	220	USA	13828	EN	USA		MA4	F7	811
81.52	152.47	1.1	3188	MA	IL	3188					280	USA	17817	EN	USA		MA4	F7	811

REC-044-A 5464

WTR_L	TOT_COST	ST_QTY	LN	CUR_L	QUANTITY	UNIT	ST_P	CRIC	TECH TEXT	TECH TEXT	QUIT TEXT	AREA	COUNT	PAL_CD	TOL	QNTY	GRD	WPS	AVR	VKT	TRL			
CD	CD	CD		CD			CD	CD				CD	CD	CD	CD	CD	CD	CD	CD	CD	CD			
									DIAGNOSE FOR LOSS OF THROTTLE RETRIVE CODE FROM FOLLOW PERFORM TESTS, PERFORM TEST SUGGESTED FROM REPLACEMENT, DIAGNOSE FURTHER, EXTENSIVE ROAD TEST, DETERMINE MALFUNCTION OF PEDAL ASSEMBLY REPLACED ?	EQAL ASSY, PROBLEM CURED AT NO OPERATION FOR PART REPLACED, AFEM	REPAIR FOR LOSS OF THROTTLE													
02-26	261.54	3.3	30026	*			NR	AR	12001															
									PERFORMED EEC TEST AND REVISED NO CONC. PERFORMED ROAD TEST WITHING AND COULD NOT DUPLICATE CONCERN, DUE TO SYMPTOMS CUSTOMER EXPLAINED REPLACED THROTTLE PEDAL ASSEMBLY, ROAD TEST OK															
05-22	180.07	1.6	30430	*			NR	AZ	31001															
									DIAG FOR NO THROTTLE RESPONSE, DONE SCE TEST, SMP TEST, FOUND NEW THROTTLE SENSOR FAULTY, PER FAULTY SENSOR ASSY, TEST FAMILIARISE WITH TIME AS THERE IS DLTS PUBLISHED FOR PART															
07-26	180.06	1.6	37006	*			NR	BC	31001	ONLY REPLACED ON NO. 80000	CHECK FOR NO THROTTLE													
									DIAGNOSTIC SENSOR WAS TESTED AS ROAD TEST AND VERIFY, TEST PROBLEMS DISPLAY, NO MEMORY AND RECORD, PP TEST AND REPLACE PEDAL ASSEMBLY AND SENSOR PEDAL ASSEMBLY															
04-26	180.05	1.6	30430	*			NR	CK	31001															
									TEST, DIAGNOSE TEST TEST, ACCELERATOR TEST FUEL, FOUND ACCEL. PEDAL, AND R R PEDAL ASSEMBLY AND REPLACED ROAD TEST NO CONC. CONC.															
01-26	240.06	3	30430	*			NR	CA	31001															
									DIAGNOSTIC SENSOR WAS TESTED AS ROAD TEST AND VERIFY, TEST PROBLEMS DISPLAY, NO MEMORY AND RECORD, PP TEST AND REPLACE PEDAL ASSEMBLY AND SENSOR PEDAL ASSEMBLY															
01-26	114.2	0.6	30026	*			NR	CC	31001															
									BAD THROTTLE TPE CHECKED OUT AND REPLACED TPE ASSEMBLY DID NO TEST, DUAL, DATA WORKS, SET DUAL, STEPS 1-14 PERFORM TEST NR AND REPL. ACCELERATOR PEDAL, NO TEST, RETEST OK															
05-26	180.05	1.6	30430	*			NR	CA	31001															
									DIAGNOSTIC SENSOR WAS TESTED AS ROAD TEST AND VERIFY, TEST PROBLEMS DISPLAY, NO MEMORY AND RECORD, PP TEST AND REPLACE PEDAL ASSEMBLY AND SENSOR PEDAL ASSEMBLY															
07-26	261.54	3.3	30026	*			NR	CA	31001															
									DIAGNOSTIC SENSOR WAS TESTED AS ROAD TEST AND VERIFY, TEST PROBLEMS DISPLAY, NO MEMORY AND RECORD, PP TEST AND REPLACE PEDAL ASSEMBLY AND SENSOR PEDAL ASSEMBLY															