



U.S. Department
of Transportation
**National Highway
Traffic Safety
Administration**

400 Seventh Street, S.W.
Washington, D.C. 20590

NOV 12 2004

CERTIFIED MAIL
RETURN RECEIPT REQUESTED

Stephen J. Speth, Director
Vehicle Compliance & Safety Affairs
DaimlerChrysler Corporation
CIMS482-00-91
800 Chrysler Drive
Auburn Hills, MI 48236-2757

NVS-212mj
EA04-013

Dear Mr. Speth:

This letter is in reference to the Office of Defects Investigation's (ODI) Engineering Analysis (EA04-013) concerning driver's air bag clockspring failures in certain model year (MY) 1998 through 2000 DaimlerChrysler minivans manufactured by DaimlerChrysler Corporation (DaimlerChrysler). To assist us at this stage of the investigation, we are requesting additional information.

Unless otherwise stated in the text, the following definitions apply to these information requests:

- **Subject vehicles:** All MY 1998 through 2000 DaimlerChrysler minivans (i.e., Caravan, Grand Caravan, Voyager, Grand Voyager, and Town and Country) manufactured after February 1998 for sale or lease in the United States.
- **Subject components:** Driver's 7-circuit air bag clockspring assembly.
- **DaimlerChrysler:** DaimlerChrysler Corporation, all of its past and present officers and employees, whether assigned to its principal offices or any of its field or other locations, including all of its divisions, subsidiaries (whether or not incorporated) and affiliated enterprises and all of their headquarters, regional, zone and other offices and their employees, and all agents, contractors, consultants, attorneys and law firms and other persons engaged directly or indirectly (e.g., employee of a consultant) by or under the control of DaimlerChrysler (including all business units and persons previously referred to), who are or, in or after 1997, were involved in any way with any of the following related to the alleged defect in the subject vehicles:
 - a. Design, engineering, analysis, modification or production (e.g. quality control);
 - b. Testing, assessment or evaluation;



DOT AUTO SAFETY HOTLINE
888-DASH-2-DOT
888-327-4238

- c. Consideration, or recognition of potential or actual defects, reporting, record-keeping and information management, (e.g., complaints, field reports, warranty information, part sales), analysis, claims, or lawsuits; or
 - d. Communication to, from or intended for zone representatives, fleets, dealers, or other field locations, including but not limited to people who have the capacity to obtain information from dealers.
- **Alleged defect:** Failure of the subject component, illumination of the air bag warning lamp, failure of the horn, failure of the cruise control, and/or non-deployment of driver's air bag during a crash.
 - **Document:** "Document(s)" is used in the broadest sense of the word and shall mean all original written, printed, typed, recorded, or graphic matter whatsoever, however produced or reproduced, of every kind, nature, and description, and all non-identical copies of both sides thereof, including, but not limited to, papers, letters, memoranda, correspondence, communications, electronic mail (e-mail) messages (existing in hard copy and/or in electronic storage), faxes, mailgrams, telegrams, cables, telex messages, notes, annotations, working papers, drafts, minutes, records, audio and video recordings, data, databases, other information bases, summaries, charts, tables, graphics, other visual displays, photographs, statements, interviews, opinions, reports, newspaper articles, studies, analyses, evaluations, interpretations, contracts, agreements, jottings, agendas, bulletins, notices, announcements, instructions, blueprints, drawings, as-builts, changes, manuals, publications, work schedules, journals, statistical data, desk, portable and computer calendars, appointment books, diaries, travel reports, lists, tabulations, computer printouts, data processing program libraries, data processing inputs and outputs, microfilms, microfiches, statements for services, resolutions, financial statements, governmental records, business records, personnel records, work orders, pleadings, discovery in any form, affidavits, motions, responses to discovery, all transcripts, administrative filings and all mechanical, magnetic, photographic and electronic records or recordings of any kind, including any storage media associated with computers, including, but not limited to, information on hard drives, floppy disks, backup tapes, and zip drives, electronic communications, including but not limited to, the Internet and shall include any drafts or revisions pertaining to any of the foregoing, all other things similar to any of the foregoing, however denominated by DaimlerChrysler, any other data compilations from which information can be obtained, translated if necessary, into a usable form and any other documents. For purposes of this request, any document which contains any note, comment, addition, deletion, insertion, annotation, or otherwise comprises a non-identical copy of another document shall be treated as a separate document subject to production. In all cases where original and any non-identical copies are not available, "document(s)" also means any identical copies of the original and all non-identical copies thereof. Any document, record, graph, chart, film or photograph originally produced in color must be provided in color. Furnish all documents whether verified by the manufacturer or not. If a document is not in the English language, provide both the original document and an English translation of the document.

- **Other Terms:** To the extent that they are used in these information requests, the terms "claim," "consumer complaint," "dealer field report," "field report," "fleet," "good will," "make," "model," "model year," "notice," "property damage," "property damage claim," "type," "warranty," "warranty adjustment," and "warranty claim," whether used in singular or in plural form, have the same meaning as found in 49 CFR 579.4.

In order for my staff to evaluate the alleged defect, certain information is required. Pursuant to 49 U.S.C. § 30166, please provide numbered responses to the following information requests. Insofar as DaimlerChrysler has previously provided a document to ODI, DaimlerChrysler may produce it again or identify the document, the document submission to ODI in which it was included and the precise location in that submission where the document is located. When documents are produced, the documents shall be produced in an identified, organized manner that corresponds with the organization of this information request letter (including all individual requests and subparts). When documents are produced and the documents would not, standing alone, be self-explanatory, the production of documents shall be supplemented and accompanied by explanation.

Please repeat the applicable request verbatim above each response. After DaimlerChrysler's response to each request, identify the source of the information and indicate the last date the information was gathered.

1. Furnish a list of all repairs of the subject vehicles that require disconnecting the steering column assembly from the intermediate shaft. Also, furnish DaimlerChrysler's repair procedure, labor operation number, and problem code for each such repair.
2. State, by model and model year, a total count for all claims or repairs whether paid or not paid by DaimlerChrysler to date that relate to any repair described in Request No. 1 above for the subject vehicles associated with the alleged defect (i.e., clockspring complaint vehicles; see enclosed list of 1407 VIN's compiled by ODI).

Separately, for each such claim or repair, state the following information:

- a. DaimlerChrysler's claim or repair number;
- b. Vehicle owner or fleet name (and fleet contact person) and telephone number;
- c. VIN;
- d. Repair date;
- e. Vehicle mileage at time of repair;
- f. Repairing dealer's or facility's name, telephone number, city and state or ZIP code;
- g. Labor operation number;
- h. Problem code;
- i. Replacement part number(s) and description(s);
- j. Concern stated by customer; and
- k. Comment, if any, by dealer/technician relating to claim and/or repair.

Provide this information in Microsoft Access 2000, or a compatible format, entitled "REPAIR DATA."

3. In its Defect Information Report dated October 5, 2004, DaimlerChrysler stated that backwinding of the subject components in the subject vehicles probably occurred during an "intervening service or repair." Furnish a technical explanation and any supporting documents for this claim. Please include in your discussion, an explanation as to how the subject components may become backwound or overwound during service or repair given that the steering wheel/subject component is designed to lock upon ignition key-off and the subject component is designed to lock if it is removed from the steering column.
4. Describe all assessments, analyses, tests, studies, surveys, simulations, investigations, inquiries, and/or evaluations (collectively, "actions") that relate to, or may relate to, the alleged defect in the subject vehicles that have been conducted, are being conducted, are planned, or are being planned by, or for, DaimlerChrysler. For each such action, provide the following information:
 - a. Action title or identifier;
 - b. The actual or planned start date;
 - c. The actual or expected end date;
 - d. Brief summary of the subject and objective of the action;
 - e. Engineering group(s)/supplier(s) responsible for designing and for conducting the action; and
 - f. A brief summary of the findings and/or conclusions resulting from the action, whether final, tentative, or postulated.

For each action identified, provide copies of all documents related to the action, regardless of whether the documents are in interim, draft, or final form. Organize the documents chronologically by action. If an action is not complete, provide a detailed schedule for the work to be done, tentative findings and/or conclusions, and provide an update within 10 days of completion of the action.

This letter is being sent to DaimlerChrysler pursuant to 49 U.S.C. § 30166, which authorizes NHTSA to conduct any investigation that may be necessary to enforce Chapter 301 of Title 49 and to request reports and the production of things. It constitutes a new request for information. DaimlerChrysler's failure to respond promptly and fully to this letter could subject DaimlerChrysler to civil penalties pursuant to 49 U.S.C. § 30165 or lead to an action for injunctive relief pursuant to 49 U.S.C. § 30163. (Other remedies and sanctions are available as well.) Please note that maximum civil penalties under 49 U.S.C. § 30165 have increased as a result of the recent enactment of the Transportation Recall Enhancement, Accountability, and Documentation (TREAD) Act, Public Law No. 106-414 (signed November 1, 2000). Section 5(a) of the TREAD Act, codified at 49 U.S.C. § 30165(b), provides for civil penalties of up to \$5,000 per day, with a maximum of \$15 million for a related series of violations, for failing or refusing to perform an act required under 49 U.S.C. § 30166. This includes failing to respond to ODI information requests.

If DaimlerChrysler cannot respond to any specific request or subpart(s) thereof, please state the reason why it is unable to do so. If on the basis of attorney-client, attorney work product, or


other privilege, DaimlerChrysler does not submit one or more requested documents or items of information in response to this information request, DaimlerChrysler must provide a privilege log identifying each document or item withheld, and stating the date, subject or title, the name and position of the person(s) from, and the person(s) to whom it was sent, and the name and position of any other recipient (to include all carbon copies or blind carbon copies), the nature of that information or material, and the basis for the claim of privilege and why that privilege applies.

DaimlerChrysler's response to this letter, in duplicate, together with a copy of any confidentiality request, must be submitted to this office by December 22, 2004. Please refer to EA04-013 in DaimlerChrysler's response to this letter. If DaimlerChrysler finds that it is unable to provide all of the information requested within the time allotted, DaimlerChrysler must request an extension from Mr. Thomas Cooper at (202) 366-5218 no later than five business days before the response due date. If DaimlerChrysler is unable to provide all of the information requested by the original deadline, it must submit a partial response by the original deadline with whatever information DaimlerChrysler then has available, even if an extension has been granted.

If DaimlerChrysler claims that any of the information or documents provided in response to this information request constitute confidential commercial material within the meaning of 5 U.S.C. § 552(b)(4), or are protected from disclosure pursuant to 18 U.S.C. § 1905, DaimlerChrysler must submit supporting information together with the materials that are the subject of the confidentiality request, in accordance with 49 CFR Part 512, as amended (68 Fed. Reg. 44209 et seq; July 28, 2003) to the Office of Chief Counsel (NCC-110), National Highway Traffic Safety Administration, Room 5219, 400 Seventh Street, S.W., Washington, D.C. 20590. DaimlerChrysler is required to submit two copies of the documents containing allegedly confidential information (except only one copy of blueprints) and one copy of the documents from which information claimed to be confidential has been deleted.

If you have any technical questions concerning this matter, please call Mr. Michael Lee of my staff at (202) 366-5236.

Sincerely,

A handwritten signature in black ink, appearing to read 'K. DeMeter', with a long horizontal line extending to the right.

Kathleen C. DeMeter, Director
Office of Defects Investigation
Enforcement

Enclosures: List and file containing 1407 VIN's

1B4GP44G0W	1B4GP44G4V	1B4GP44G7X	1B4GP44GX
1B4GP44G0W	1B4GP44G4X	1B4GP44G7X	1B4GP44GXY
1B4GP44G0X	1B4GP44G4X	1B4GP44G7X	1B4GP44GXY
1B4GP44G0X	1B4GP44G4X	1B4GP44G8V	1B4GP44GXY
1B4GP44G0X	1B4GP44G4X	1B4GP44G8V	1B4GP44L0W
1B4GP44G0X	1B4GP44G4X	1B4GP44G8V	1B4GP44L0W
1B4GP44G0X	1B4GP44G4X	1B4GP44G8V	1B4GP44L0X
1B4GP44G0X	1B4GP44G4X	1B4GP44G8X	1B4GP44L0X
1B4GP44G0X	1B4GP44G4X	1B4GP44G8X	1B4GP44L0X
1B4GP44G0X	1B4GP44G4X	1B4GP44G8X	1B4GP44L0X
1B4GP44G0X	1B4GP44G4X	1B4GP44G8X	1B4GP44L1W
1B4GP44G0Y	1B4GP44G4X	1B4GP44G8X	1B4GP44L1W
1B4GP44G0Y	1B4GP44G4X	1B4GP44G8X	1B4GP44L1W
1B4GP44G1W	1B4GP44G4X	1B4GP44G8X	1B4GP44L2W
1B4GP44G1X	1B4GP44G4Y	1B4GP44G8X	1B4GP44L2W
1B4GP44G1X	1B4GP44G4Y	1B4GP44G8X	1B4GP44L2W
1B4GP44G1X	1B4GP44G4Y	1B4GP44G8X	1B4GP44L2W
1B4GP44G1X	1B4GP44G5V	1B4GP44G8X	1B4GP44L2X
1B4GP44G1X	1B4GP44G5V	1B4GP44G8X	1B4GP44L2X
1B4GP44G1X	1B4GP44G5V	1B4GP44G8Y	1B4GP44L3X
1B4GP44G1X	1B4GP44G5V	1B4GP44G8Y	1B4GP44L3X
1B4GP44G1Y	1B4GP44G5V	1B4GP44G9V	1B4GP44L3X
1B4GP44G2W	1B4GP44G5V	1B4GP44G9V	1B4GP44L3X
1B4GP44G2W	1B4GP44G5V	1B4GP44G9V	1B4GP44L4W
1B4GP44G2X	1B4GP44G5X	1B4GP44G9V	1B4GP44L4X
1B4GP44G2X	1B4GP44G5X	1B4GP44G9V	1B4GP44L4X
1B4GP44G2X	1B4GP44G5X	1B4GP44G9V	1B4GP44L4X
1B4GP44G2X	1B4GP44G5X	1B4GP44G9X	1B4GP44L4X
1B4GP44G2X	1B4GP44G5X	1B4GP44G9X	1B4GP44L5W
1B4GP44G2X	1B4GP44G5X	1B4GP44G9X	1B4GP44L5W
1B4GP44G2X	1B4GP44G5Y	1B4GP44G9X	1B4GP44L5W
1B4GP44G2X	1B4GP44G6V	1B4GP44G9X	1B4GP44L5X
1B4GP44G2X	1B4GP44G6V	1B4GP44G9X	1B4GP44L5X
1B4GP44G2X	1B4GP44G6W	1B4GP44G9X	1B4GP44L6X
1B4GP44G2X	1B4GP44G6W	1B4GP44G9X	1B4GP44L6X
1B4GP44G2Y	1B4GP44G6X	1B4GP44G9X	1B4GP44L6Y
1B4GP44G2Y	1B4GP44G6X	1B4GP44G9X	1B4GP44L7W
1B4GP44G2Y	1B4GP44G6X	1B4GP44G9X	1B4GP44L7X
1B4GP44G3W	1B4GP44G6X	1B4GP44G9X	1B4GP44L7X
1B4GP44G3W	1B4GP44G6Y	1B4GP44G9X	1B4GP44L7X
1B4GP44G3W	1B4GP44G6Y	1B4GP44G9X	1B4GP44L7X
1B4GP44G3X	1B4GP44G6Y	1B4GP44G9Y	1B4GP44L8V
1B4GP44G3X	1B4GP44G6Y	1B4GP44GXV	1B4GP44L8X
1B4GP44G3X	1B4GP44G6Y	1B4GP44GXV	1B4GP44L8X
1B4GP44G3X	1B4GP44G7V	1B4GP44GXV	1B4GP44L8X
1B4GP44G3X	1B4GP44G7V	1B4GP44GX	1B4GP44L8X
1B4GP44G3X	1B4GP44G7V	1B4GP44GX	1B4GP44L9X
1B4GP44G3X	1B4GP44G7V	1B4GP44GX	1B4GP44L9X
1B4GP44G3Y	1B4GP44G7X	1B4GP44GX	1B4GP44L9X
1B4GP44G3Y	1B4GP44G7X	1B4GP44GX	1B4GP44LXW
1B4GP44G4W	1B4GP44G7X	1B4GP44GX	1B4GP44LXW

1B4GP44LXX	1B4GP44RXW	1B4GP54G8X	1B4GP74L7Y
1B4GP44R0X	1B4GP44RXX	1B4GP54L0W	1B4GP74L7Y
1B4GP44R0X	1B4GP44RXX	1B4GP54L0W	1B4GP74L8X
1B4GP44R0X	1B4GP44RXY	1B4GP54L0W	1B4GP74L9X
1B4GP44R1W	1B4GP44RXY	1B4GP54L0X	1B4GP74LX
1B4GP44R1X	1B4GP45G0W	1B4GP54L1X	1B4GT44L0X
1B4GP44R1Y	1B4GP45G1W	1B4GP54L2W	1B4GT44L0X
1B4GP44R1Y	1B4GP45G1X	1B4GP54L2X	1B4GT44L1X
1B4GP44R2X	1B4GP45G2W	1B4GP54L3W	1B4GT44L1X
1B4GP44R2X	1B4GP45G2X	1B4GP54L4W	1B4GT44L2X
1B4GP44R2X	1B4GP45G2X	1B4GP54L5W	1B4GT44L2Y
1B4GP44R2X	1B4GP45G2X	1B4GP54L5Y	1B4GT44L4Y
1B4GP44R2Y	1B4GP45G2X	1B4GP54L6X	1B4GT44L8X
1B4GP44R2Y	1B4GP45G3X	1B4GP54L7W	1B4GT54L2X
1B4GP44R2Y	1B4GP45G3X	1B4GP54L7W	1B4GT74L3X
1B4GP44R3W	1B4GP45G4X	1B4GP54L7W	1B4GT74L4X
1B4GP44R3X	1B4GP45G4X	1B4GP54L7W	1B4GT74LX
1B4GP44R3X	1B4GP45G4X	1B4GP54L7W	1C4GJ44G0V
1B4GP44R3X	1B4GP45G4X	1B4GP54L7X	1C4GJ44G6V
1B4GP44R3X	1B4GP45G5W	1B4GP54L7Y	1C4GP44G0V
1B4GP44R3X	1B4GP45G5W	1B4GP54L8W	1C4GP44G2V
1B4GP44R3X	1B4GP45G5X	1B4GP54L8W	1C4GP44G4V
1B4GP44R3X	1B4GP45G6X	1B4GP54L8W	1C4GP44G4V
1B4GP44R3Y	1B4GP45G7W	1B4GP54L8W	1C4GP44G5V
1B4GP44R4W	1B4GP45G7X	1B4GP54L8X	1C4GP44R6V
1B4GP44R4W	1B4GP45G7X	1B4GP54L9W	1C4GP54G3V
1B4GP44R4X	1B4GP45G7Y	1B4GP54LXW	1C4GP54G8V
1B4GP44R5X	1B4GP45G8W	1B4GP54LXW	1C4GP54L0X
1B4GP44R5X	1B4GP45G8X	1B4GP54R2X	1C4GP54L0X
1B4GP44R6X	1B4GP45G8X	1B4GP54R8X	1C4GP54L0X
1B4GP44R6X	1B4GP45G8X	1B4GP74L0X	1C4GP54L0X
1B4GP44R6X	1B4GP45G8Y	1B4GP74L0X	1C4GP54L0X
1B4GP44R6Y	1B4GP45G9X	1B4GP74L0Y	1C4GP54L0X
1B4GP44R6Y	1B4GP45G9X	1B4GP74L1X	1C4GP54L0X
1B4GP44R7W	1B4GP45L2W	1B4GP74L1X	1C4GP54L0X
1B4GP44R7W	1B4GP45LXXE	1B4GP74L1Y	1C4GP54L0X
1B4GP44R7W	1B4GP45LXXE	1B4GP74L1Y	1C4GP54L0Y
1B4GP44R7W	1B4GP45R0W	1B4GP74L2X	1C4GP54L1X
1B4GP44R7X	1B4GP45R1X	1B4GP74L2X	1C4GP54L1X
1B4GP44R7X	1B4GP45R4Y	1B4GP74L3X	1C4GP54L1X
1B4GP44R7X	1B4GP45R5W	1B4GP74L3X	1C4GP54L1X
1B4GP44R7X	1B4GP45R7X	1B4GP74L3Y	1C4GP54L1X
1B4GP44R7X	1B4GP45R8W	1B4GP74L3Y	1C4GP54L1X
1B4GP44R7Y	1B4GP45R8X	1B4GP74L4X	1C4GP54L1Y
1B4GP44R7Y	1B4GP45R9X	1B4GP74L4X	1C4GP54L2X
1B4GP44R8W	1B4GP45RXX	1B4GP74L4X	1C4GP54L2X
1B4GP44R8X	1B4GP54G0W	1B4GP74L5Y	1C4GP54L2Y
1B4GP44R9W	1B4GP54G0W	1B4GP74L6X	1C4GP54L3X
1B4GP44R9X	1B4GP54G7W	1B4GP74L7X	1C4GP54L3X
1B4GP44RXV	1B4GP54G7W	1B4GP74L7X	1C4GP54L3X

1C4GP54L3X	1C4GP54L7Y	1C4GP84L3W	1C4GP84L7X
1C4GP54L3X	1C4GP54L8Y	1C4GP84L3X	1C4GP84L7X
1C4GP54L3X	1C4GP54L8Y	1C4GP84L3X	1C4GP84L7Y
1C4GP54L3X	1C4GP54L8Y	1C4GP84L3X	1C4GP84L7Y
1C4GP54L3Y	1C4GP54L8Y	1C4GP84L3X	1C4GP84L8X
1C4GP54L3Y	1C4GP54L8Y	1C4GP84L3Y	1C4GP84L8X
1C4GP54L3Y	1C4GP54L8Y	1C4GP84L3Y	1C4GP84L8X
1C4GP54L3Y	1C4GP54L8Y	1C4GP84L3Y	1C4GP84L8X
1C4GP54L4W	1C4GP54L9X	1C4GP84L3Y	1C4GP84L8X
1C4GP54L4W	1C4GP54L9X	1C4GP84L4W	1C4GP84L8X
1C4GP54L4X	1C4GP54L9X	1C4GP84L4W	1C4GP84L8X
1C4GP54L4X	1C4GP54L9X	1C4GP84L4X	1C4GP84L8X
1C4GP54L4X	1C4GP54L9X	1C4GP84L4X	1C4GP84L8Y
1C4GP54L4X	1C4GP54L9X	1C4GP84L4X	1C4GP84L8Y
1C4GP54L4X	1C4GP54L9X	1C4GP84L4X	1C4GP84L8Y
1C4GP54L4X	1C4GP54L8Y	1C4GP84L4X	1C4GP84L9W
1C4GP54L4X	1C4GP54LX	1C4GP84L4X	1C4GP84L8X
1C4GP54L4X	1C4GP54LX	1C4GP84L4X	1C4GP84L9X
1C4GP54L4X	1C4GP54LX	1C4GP84L4X	1C4GP84L8X
1C4GP54L4Y	1C4GP54LY	1C4GP84L4Y	1C4GP84L8X
1C4GP54L4Y	1C4GP55G2Y	1C4GP84L4Y	1C4GP84L8X
1C4GP54L4Y	1C4GP55G4Y	1C4GP84L4Y	1C4GP84L8X
1C4GP54L5W	1C4GP55L5X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP55L7X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0W	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0W	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L0X	1C4GP84L5X	1C4GP84L8X
1C4GP54L5X	1C4GP84L1W	1C4GP84L5Y	1C4GP84L8X
1C4GP54L5X	1C4GP84L1X	1C4GP84L5Y	1C4GP84L8X
1C4GP54L5X	1C4GP84L1X	1C4GP84L5Y	1C4GP84L8X
1C4GP54L5X	1C4GP84L1X	1C4GP84L6W	1C4GP84L8X
1C4GP54L5Y	1C4GP84L1X	1C4GP84L6X	1C4GP84L8X
1C4GP54L5Y	1C4GP84L1X	1C4GP84L6X	1C4GP84L8X
1C4GP54L6X	1C4GP84L2W	1C4GP84L6X	1C4GP84L8X
1C4GP54L6X	1C4GP84L2W	1C4GP84L6X	1C4GP84L8X
1C4GP54L6X	1C4GP84L2X	1C4GP84L6X	1C4GP84L8X
1C4GP54L6X	1C4GP84L2X	1C4GP84L7W	1C4GP84L8X
1C4GP54L6Y	1C4GP84L2X	1C4GP84L7W	1C4GP84L8X
1C4GP54L6Y	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X
1C4GP54L6Y	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X
1C4GP54L7X	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X
1C4GP54L7X	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X
1C4GP54L7X	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X
1C4GP54L7X	1C4GP84L2Y	1C4GP84L7X	1C4GP84L8X

1C4GT64L6Y	1P4GP44G4Y	1P4GP44L3W	1P4GP45G6X
1C4GT64L8V	1P4GP44G5W	1P4GP44L3X	1P4GP45G7X
1C4GT64LX	1P4GP44G5X	1P4GP44L4W	1P4GP45G8V
1C4GT64LX	1P4GP44G5X	1P4GP44L5X	1P4GP45G8X
1C4GT64LX	1P4GP44G5X	1P4GP44L5X	1P4GP45R0X
1FMYU24E0	1P4GP44G5X	1P4GP44L5X	1P4GP45R8V
1FTEX14H35	1P4GP44G5X	1P4GP44L6X	2B4FP258X
1GNEV18K6	1P4GP44G5X	1P4GP44L6X	2B4FP446XX
1P4GP44G0V	1P4GP44G5X	1P4GP44L7W	2B4FP2530W
1P4GP44G0X	1P4GP44G5X	1P4GP44L7X	2B4FP2530X
1P4GP44G0X	1P4GP44G5X	1P4GP44L7X	2B4FP2530X
1P4GP44G0X	1P4GP44G5X	1P4GP44L8W	2B4FP2530X
1P4GP44G1V	1P4GP44G6W	1P4GP44L8X	2B4FP2531W
1P4GP44G1V	1P4GP44G6W	1P4GP44L8X	2B4FP2531W
1P4GP44G1V	1P4GP44G6X	1P4GP44L9X	2B4FP2531X
1P4GP44G1X	1P4GP44G6X	1P4GP44LXW	2B4FP2531X
1P4GP44G1X	1P4GP44G6X	1P4GP44R0W	2B4FP2531X
1P4GP44G1X	1P4GP44G6X	1P4GP44R1X	2B4FP2531X
1P4GP44G1X	1P4GP44G6X	1P4GP44R1X	2B4FP2532W
1P4GP44G1X	1P4GP44G6Y	1P4GP44R2X	2B4FP2532W
1P4GP44G1X	1P4GP44G7W	1P4GP44R2X	2B4FP2532W
1P4GP44G1X	1P4GP44G7X	1P4GP44R4W	2B4FP2532X
1P4GP44G2V	1P4GP44G7X	1P4GP44R4X	2B4FP2532X
1P4GP44G2V	1P4GP44G7X	1P4GP44R4X	2B4FP2533X
1P4GP44G2X	1P4GP44G7X	1P4GP44R5W	2B4FP2534X
1P4GP44G2X	1P4GP44G7X	1P4GP44R5X	2B4FP2534X
1P4GP44G2X	1P4GP44G7X	1P4GP44R6W	2B4FP2534X
1P4GP44G2X	1P4GP44G7Y	1P4GP44R6W	2B4FP2534X
1P4GP44G2X	1P4GP44G8W	1P4GP44R8X	2B4FP2535X
1P4GP44G2X	1P4GP44G8W	1P4GP44R8W	2B4FP2535X
1P4GP44G3V	1P4GP44G8W	1P4GP44R8W	2B4FP2535X
1P4GP44G3V	1P4GP44G8X	1P4GP44R8X	2B4FP2536W
1P4GP44G3V	1P4GP44G8X	1P4GP44R9W	2B4FP2536X
1P4GP44G3X	1P4GP44G8X	1P4GP44R8X	2B4FP2536X
1P4GP44G3X	1P4GP44G8Y	1P4GP44R9Y	2B4FP2536X
1P4GP44G3X	1P4GP44G9X	1P4GP44RXW	2B4FP2537X
1P4GP44G3X	1P4GP44G9X	1P4GP44RXW	2B4FP2537X
1P4GP44G3X	1P4GP44G9X	1P4GP44RXW	2B4FP2538W
1P4GP44G3X	1P4GP44G9X	1P4GP45G0Y	2B4FP2538W
1P4GP44G3X	1P4GP44G9X	1P4GP45G1X	2B4FP2538X
1P4GP44G3X	1P4GP44G9X	1P4GP45G1X	2B4FP2538X
1P4GP44G3X	1P4GP44GXV	1P4GP45G2X	2B4FP2539W
1P4GP44G3X	1P4GP44GXV	1P4GP45G3W	2B4FP2539X
1P4GP44G3X	1P4GP44GXX	1P4GP45G3W	2B4FP2539X
1P4GP44G4V	1P4GP44GXX	1P4GP45G4W	2B4FP2539X
1P4GP44G4V	1P4GP44L0X	1P4GP45G4X	2B4FP2539X
1P4GP44G4V	1P4GP44L2W	1P4GP45G5X	2B4FP2539X
1P4GP44G4X	1P4GP44L2X	1P4GP45G5X	2B4FP2539X
1P4GP44G4X	1P4GP44L2X	1P4GP45G6X	2B4FP2539X
1P4GP44G4X	1P4GP44L2X	1P4GP45G6X	2B4FP2539X

2B4FP2539X	2B4FP25B5X	2B4GP2431Y	2B4GP2539Y
2B4FP253XV	2B4FP25B5X	2B4GP2432V	2B4GP2539Y
2B4FP253XV	2B4FP25B5X	2B4GP2432V	2B4GP25G0X
2B4FP253XV	2B4FP25B5X	2B4GP2432X	2B4GP25G0X
2B4FP253XV	2B4FP25B5X	2B4GP2432Y	2B4GP25G1X
2B4FP253XV	2B4FP25B5Y	2B4GP2432Y	2B4GP25G2X
2B4FP253XV	2B4FP25B5Y	2B4GP2433Y	2B4GP25G2X
2B4FP253XV	2B4FP25B6V	2B4GP2434Y	2B4GP25G2X
2B4FP253XV	2B4FP25B6X	2B4GP2436V	2B4GP25G3X
2B4FP25B0V	2B4FP25B6X	2B4GP2436V	2B4GP25G3X
2B4FP25B0X	2B4FP25B6X	2B4GP2436V	2B4GP25G4X
2B4FP25B0X	2B4FP25B6X	2B4GP2436X	2B4GP25G5X
2B4FP25B0X	2B4FP25B6X	2B4GP2436Y	2B4GP25G6X
2B4FP25B0X	2B4FP25B6X	2B4GP2437Y	2B4GP25G6X
2B4FP25B0X	2B4FP25B6Y	2B4GP2438V	2B4GP25G7X
2B4FP25B0X	2B4FP25B7V	2B4GP2438V	2B4GP25G8X
2B4FP25B0X	2B4FP25B7V	2B4GP2439V	2B4GP25G9X
2B4FP25B0X	2B4FP25B7V	2B4GP24G1X	2B4GP25G9X
2B4FP25B0X	2B4FP25B7X	2B4GP24G1X	2B4GP25G9X
2B4FP25B1V	2B4FP25B7X	2B4GP24G2X	2B4GP25G9X
2B4FP25B1V	2B4FP25B7X	2B4GP24G3X	2B4GP25G9X
2B4FP25B1V	2B4FP25B7Y	2B4GP24G4X	2B4GP25GX
2B4FP25B1X	2B4FP25B8V	2B4GP24G6X	2B4GP25R1X
2B4FP25B1X	2B4FP25B8V	2B4GP24G7X	2B4GP25R2V
2B4FP25B1X	2B4FP25B8X	2B4GP24G8X	2B4GP25R2X
2B4FP25B1X	2B4FP25B8X	2B4GP24G9X	2B4GP25R3V
2B4FP25B1X	2B4FP25B8X	2B4GP24R0V	2B4GP25R3V
2B4FP25B1Y	2B4FP25B8X	2B4GP24R1V	2B4GP25R3X
2B4FP25B1Y	2B4FP25B8X	2B4GP24R1X	2B4GP25R3Y
2B4FP25B1Y	2B4FP25B8X	2B4GP24R1X	2B4GP25R4V
2B4FP25B2V	2B4FP25B8Y	2B4GP24R1X	2B4GP25R4X
2B4FP25B2X	2B4FP25B8Y	2B4GP24R1X	2B4GP25R5V
2B4FP25B2X	2B4FP25B9V	2B4GP24R3Y	2B4GP25R5X
2B4FP25B3V	2B4FP25B9X	2B4GP24R4V	2B4GP25R6V
2B4FP25B3V	2B4FP25B9X	2B4GP24R4Y	2B4GP25R6X
2B4FP25B3V	2B4FP25B9Y	2B4GP24R5V	2B4GP25R7X
2B4FP25B3X	2B4FP25BXV	2B4GP24R5X	2B4GP25R7Y
2B4FP25B3Y	2B4FP25BXV	2B4GP24R5X	2B4GP25R8Y
2B4FP25B3Y	2B4FP25BXV	2B4GP24R5Y	2B4GP25R9V
2B4FP25B3Y	2B4FP25BXV	2B4GP24R6V	2B4GP25R9X
2B4FP25B4V	2B4FP25BXV	2B4GP24R6X	2B4GP25RXV
2B4FP25B4X	2B4FP25BXV	2B4GP24RX	2B4GP25RX
2B4FP25B4X	2B4FP25BXV	2B4GP2531Y	2B4GP4431W
2B4FP25B4X	2B4FP25BXV	2B4GP2533Y	2B4GP4432W
2B4FP25B4Y	2B4FP25BXV	2B4GP2534Y	2B4GP4433W
2B4FP25B5V	2B4FP25BXY	2B4GP2534Y	2B4GP4433Y
2B4FP25B5V	2B4FP25BXY	2B4GP2535Y	2B4GP4434W
2B4FP25B5V	2B4FP25BXY	2B4GP2536X	2B4GP4434W
2B4FP25B5X	2B4GP2430X	2B4GP2536Y	2B4GP4434W
2B4FP25B5X	2B4GP2431Y	2B4GP2537Y	2B4GP4434W

2B4GP4435W	2B4GP44G5X	2B4GP44R3Y	2C4GJ44G4Y
2B4GP4435W	2B4GP44G5X	2B4GP44R4X	2C4GJ44G7Y
2B4GP4436W	2B4GP44G5X	2B4GP44R4Y	2C4GJ44G8Y
2B4GP4436W	2B4GP44G5X	2B4GP44R4Y	2C4GP25G5X
2B4GP4437W	2B4GP44G6V	2B4GP44R5V	2P4FP250AX
2B4GP4438W	2B4GP44G6X	2B4GP44R5X	2P4FP2530W
2B4GP443XW	2B4GP44G6X	2B4GP44R5Y	2P4FP2530W
2B4GP443XW	2B4GP44G6X	2B4GP44R6X	2P4FP2530W
2B4GP44G0V	2B4GP44G6X	2B4GP44R6X	2P4FP2530X
2B4GP44G0X	2B4GP44G6Y	2B4GP44R6Y	2P4FP2530X
2B4GP44G0X	2B4GP44G6Y	2B4GP44R7V	2P4FP2530X
2B4GP44G0X	2B4GP44G7X	2B4GP44R7V	2P4FP2531W
2B4GP44G0X	2B4GP44G7X	2B4GP44R7X	2P4FP2531X
2B4GP44G0X	2B4GP44G7X	2B4GP44R7X	2P4FP2532X
2B4GP44G0X	2B4GP44G7X	2B4GP44R7X	2P4FP2532X
2B4GP44G1X	2B4GP44G7X	2B4GP44R7Y	2P4FP2532X
2B4GP44G1X	2B4GP44G7X	2B4GP44R8Y	2P4FP2532X
2B4GP44G1X	2B4GP44G7X	2B4GP44R9X	2P4FP2532X
2B4GP44G1X	2B4GP44G7Y	2B4GP44R9Y	2P4FP2532X
2B4GP44G1X	2B4GP44G8X	2B4GP44RX	2P4FP2533X
2B4GP44G1X	2B4GP44G8X	2B4GP44RXY	2P4FP2533X
2B4GP44G1X	2B4GP44G8X	2B4GP4532W	2P4FP2534W
2B4GP44G1X	2B4GP44G8X	2B4GP4533W	2P4FP2534X
2B4GP44G1X	2B4GP44G8X	2B4GP4536W	2P4FP2534X
2B4GP44G1X	2B4GP44G8X	2B4GP453XW	2P4FP2535W
2B4GP44G1X	2B4GP44G8Y	2B4GP45G0X	2P4FP2535X
2B4GP44G1X	2B4GP44G8Y	2B4GP45G1W	2P4FP2535X
2B4GP44G2X	2B4GP44G9W	2B4GP45G1X	2P4FP2535X
2B4GP44G2X	2B4GP44G9X	2B4GP45G2W	2P4FP2538W
2B4GP44G2X	2B4GP44G9X	2B4GP45G3Y	2P4FP2538X
2B4GP44G2X	2B4GP44G9X	2B4GP45G4W	2P4FP2537W
2B4GP44G2X	2B4GP44G9X	2B4GP45G5W	2P4FP2537X
2B4GP44G2X	2B4GP44G9X	2B4GP45G5X	2P4FP2538X
2B4GP44G2X	2B4GP44G9X	2B4GP45G6Y	2P4FP2538X
2B4GP44G2X	2B4GP44G8Y	2B4GP45G7W	2P4FP2539X
2B4GP44G3W	2B4GP44G8Y	2B4GP45G7Y	2P4FP253XW
2B4GP44G3X	2B4GP44GXW	2B4GP45G9X	2P4FP253X
2B4GP44G3X	2B4GP44GXW	2B4GP45G9X	2P4FP25B0X
2B4GP44G3X	2B4GP44GXX	2B4GP45R1X	2P4FP25B0X
2B4GP44G3X	2B4GP44GXX	2B4GP45R1X	2P4FP25B0X
2B4GP44G3X	2B4GP44GXY	2B4GP45R2Y	2P4FP25B0Y
2B4GP44G3X	2B4GP44R0X	2B4GP45R6X	2P4FP25B0Y
2B4GP44G3X	2B4GP44R0X	2B4GP45R6X	2P4FP25B1W
2B4GP44G3X	2B4GP44R0X	2B4GP45R9Y	2P4FP25B1W
2B4GP44G3Y	2B4GP44R0X	2C4FJ25B2YF	2P4FP25B1X
2B4GP44G4X	2B4GP44R1W	2C4FJ25B4YF	2P4FP25B1X
2B4GP44G4X	2B4GP44R1X	2C4GJ24R2YF	2P4FP25B1X
2B4GP44G4X	2B4GP44R1Y	2C4GJ2537YF	2P4FP25B1X
2B4GP44G4X	2B4GP44R2W	2C4GJ253XYF	2P4FP25B1X
2B4GP44G5W	2B4GP44R2Y	2C4GJ25G5YF	2P4FP25B2W

2P4FP25B2X	2P4FP25BXY	2P4GP25R3Y	2P4GP44G7X
2P4FP25B2X	2P4FP25BXY	2P4GP25R7X	2P4GP44G8X
2P4FP25B2X	2P4FP25BXY	2P4GP25R7X	2P4GP44G9V
2P4FP25B3V	2P4GH4535P	2P4GP25RX	2P4GP44G9V
2P4FP25B3X	2P4GH4535P	2P4GP25RX	2P4GP44G9X
2P4FP25B3X	2P4GP2430X	2P4GP4430W	2P4GP44G9X
2P4FP25B3X	2P4GP2430Y	2P4GP4433W	2P4GP44G9X
2P4FP25B4V	2P4GP2431X	2P4GP4434W	2P4GP44G9X
2P4FP25B4X	2P4GP2434W	2P4GP4434W	2P4GP44G9X
2P4FP25B4X	2P4GP2434X	2P4GP4435W	2P4GP44GX
2P4FP25B4X	2P4GP2435W	2P4GP4435W	2P4GP44GX
2P4FP25B4Y	2P4GP2436W	2P4GP4435W	2P4GP44GX
2P4FP25B4Y	2P4GP2436X	2P4GP4435W	2P4GP44GX
2P4FP25B4Y	2P4GP2437X	2P4GP4435W	2P4GP44R1W
2P4FP25B5W	2P4GP243XV	2P4GP4438W	2P4GP44R1X
2P4FP25B5X	2P4GP24G0X	2P4GP4439W	2P4GP44R1X
2P4FP25B5X	2P4GP24G0X	2P4GP443XV	2P4GP44R1X
2P4FP25B5Y	2P4GP24G1X	2P4GP443XV	2P4GP44R2X
2P4FP25B6W	2P4GP24G1X	2P4GP44G0X	2P4GP44R2X
2P4FP25B6W	2P4GP24G2X	2P4GP44G0X	2P4GP44R3X
2P4FP25B6W	2P4GP24G3X	2P4GP44G0X	2P4GP44R4W
2P4FP25B6X	2P4GP24G4X	2P4GP44G1X	2P4GP44R4X
2P4FP25B6X	2P4GP24G4X	2P4GP44G1X	2P4GP44R4X
2P4FP25B6X	2P4GP24G5X	2P4GP44G1X	2P4GP44R5W
2P4FP25B6X	2P4GP24G8X	2P4GP44G1X	2P4GP44R5W
2P4FP25B6Y	2P4GP24R2X	2P4GP44G1X	2P4GP44R5X
2P4FP25B7V	2P4GP24R4X	2P4GP44G1Y	2P4GP44R6W
2P4FP25B7V	2P4GP2535Y	2P4GP44G2X	2P4GP44R6X
2P4FP25B7X	2P4GP2537Y	2P4GP44G2X	2P4GP44R7X
2P4FP25B7Y	2P4GP2538Y	2P4GP44G2X	2P4GP44R7X
2P4FP25B7Y	2P4GP253XY	2P4GP44G3X	2P4GP44R7Y
2P4FP25B8W	2P4GP25G0X	2P4GP44G3X	2P4GP44R8W
2P4FP25B8W	2P4GP25G0X	2P4GP44G3X	2P4GP44R8X
2P4FP25B8X	2P4GP25G0X	2P4GP44G3X	2P4GP44R9X
2P4FP25B8X	2P4GP25G0X	2P4GP44G3X	2P4GP44R9X
2P4FP25B8X	2P4GP25G1X	2P4GP44G4X	2P4GP44R9X
2P4FP25B8X	2P4GP25G4X	2P4GP44G5V	2P4GP44RXV
2P4FP25B8X	2P4GP25G4X	2P4GP44G5X	2P4GP44RXV
2P4FP25B8X	2P4GP25G6X	2P4GP44G5X	2P4GP4534W
2P4FP25B9W	2P4GP25G6X	2P4GP44G5X	2P4GP4535W
2P4FP25B9X	2P4GP25G6X	2P4GP44G5Y	2P4GP4535W
2P4FP25B9X	2P4GP25G6X	2P4GP44G6X	2P4GP45G1X
2P4FP25B9X	2P4GP25G8X	2P4GP44G6X	2P4GP45G1X
2P4FP25B9X	2P4GP25G9X	2P4GP44G6X	2P4GP45G3X
2P4FP25B9X	2P4GP25GX	2P4GP44G6X	2P4GP45G3X
2P4FP25BXX	2P4GP25R0X	2P4GP44G7X	2P4GP45G3Y
2P4FP25BXX	2P4GP25R2X	2P4GP44G7X	2P4GP45G6X
2P4FP25BXX	2P4GP25R2X	2P4GP44G7X	2P4GP45G8X
2P4FP25BXX	2P4GP25R2X	2P4GP44G7X	2P4GP45G6X
2P4FP25BXX	2P4GP25R3X	2P4GP44G7X	2P4GP45R0X

