

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 6 OF 6**

**BOOK 6 OF 43**

<b>ID</b>	405
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	27
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	17-Apr-01
<b>WRTY_START_D</b>	27-Apr-01
<b>NAME</b>	GRAND PRAIRIE FORD, INC.
<b>DOC_NUM</b>	5905001
<b>PH_NUM</b>	6411334
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8-Aug-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	2588766
<b>MILGE</b>	9500
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2406
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORM RECALL 01S21 AND TEST SEATBELT BUCKLE. PASSES TEST. MO 8509

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01621 SEAT BUCKLE
<b>ARKA_CD</b>	214
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	182011
<b>TXN_CD</b>	01621
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07LX1K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TIF3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TIAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TVZ

<b>ID</b>	407
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	28
<b>TRANS_CD</b>	70U
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	18-Apr-01
<b>WRTY_START_D</b>	5-Aug-01
<b>NAME</b>	PENINSULA FORD OF SAN BRUNO
<b>DOC_NUM</b>	3588901
<b>PH_NUM</b>	8320600
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	25-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2597082
<b>MILGE</b>	10
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7785
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	

**TECH\_TXT1**

**CUST\_TXT**

**AREA\_CD** 850

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 172028

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** S0X

**TIS\_FLAG** ©

**VIN\_CD** 1FTRW07LX1KE

**LBR\_COST**

**VEH\_LINE\_CD** T75

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** T/B

**VER\_SERIES\_C** T1AM

**DRIVE\_CD** T/B

**ENG\_CD** TNZ

<b>ID</b>	408
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	20
<b>TRANS_CD</b>	TR0E
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	12-Apr-01
<b>WRTY_START_D</b>	11-May-01
<b>NAME</b>	BOBBY JONES FORD
<b>DOC_NUM</b>	086752
<b>PH_NUM</b>	7388000
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	27-Jul-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2578352
<b>MILGE</b>	8006
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	214
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	GA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	01921 SEATBELT INSPECTION OK

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01S21
<b>AREA_CD</b>	700
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121215
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	80X
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07LX1KE
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TREB
<b>VER_SERIES_C</b>	TIAM
<b>DRIVE_CD</b>	TRE
<b>ENG_CD</b>	TVZ

<b>ID</b>	408
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	30
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	17-Apr-01
<b>WRTY_START_D</b>	27-Jun-01
<b>NAME</b>	VAN BURKLEO MID-VALLEY FORD
<b>DOC_NUM</b>	5125302
<b>PH_NUM</b>	5852421
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	16-Oct-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	4787000
<b>MILGE</b>	0281
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4241
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	1 PERFORM RECALL AS PER INSTRUCTIONS



<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	958
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152122
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	80X
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07LX1H [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B0
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	410
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	31
<b>TRANS_CD</b>	TIDE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	5-Apr-01
<b>WRTY_START_D</b>	14-May-01
<b>NAME</b>	BOB DAVIDSON FORD, INC.
<b>DOC_NUM</b>	1000408
<b>PH_NUM</b>	6016400
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	14-Aug-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	2822318
<b>MILGE</b>	1418
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	88
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MD
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	1417 RECALL WF INSP

**TECH\_TXT2**

<b>CUST_TXT</b>	01S21 RECALL 2001 C.V. EXCURSION, EXPEDITION, F 150 650, G MARQ, NAVIGATOR, RANGER, TOWN CAR, AND WINDSTAR SEAT BELT BUCKLE RETENTION
<b>AREA_CD</b>	410
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	127032
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	S0X
<b>TIS_FLAG</b>	Q
<b>VIN_CD</b>	1FTRW07LX1K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F3
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B3
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	TVZ

<b>ID</b>	411
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	32
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	14-Mar-01
<b>WRTY_START_D</b>	29-Apr-01
<b>NAME</b>	TREADWELL FORD
<b>DOC_NUM</b>	27028401
<b>PH_NUM</b>	4783351
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	30-Jul-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	2750884
<b>MILGE</b>	6487
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	652B
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECT SEAT BELT BUCKLE PER RECALL, OK. 2 OF 2 WAITING.

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	GUST STATES RECALL 01521 SESAT BELT BUCKLE
<b>AREA_CD</b>	251
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124017
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VPG_CD</b>	V00
<b>AWS_YL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07LX1K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T1F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T1B3
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	T1B
<b>ENG_CD</b>	T1VZ

<b>ID</b>	412
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	33
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	15-Mar-01
<b>WRTY_START_D</b>	30-Apr-01
<b>NAME</b>	JOHN MARKEI, INC.
<b>DOC_NUM</b>	240862A
<b>PH_NUM</b>	3839700
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	30-Aug-01
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	8398051
<b>MILGE</b>	0000
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7232
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NE
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	CHECK ALL 8 SEAT BELTS PASSED TEST.

**TECH\_TXT2**

**CUST\_TXT**

RECALL 01S21: 2001 CRN VIC, EXCURSION,  
EXPEDITION, F150, F250 F350, RANGER, WINDSTAR, TWIN  
CAR, NAV, GRID MARK. SEAT BELT BUCKLE  
RETENSION.

**AREA\_CD**

402

**COUNTRY\_CD**

USA

**SLS\_DLR\_CD**

103807

**TXN\_CD**

01S21

**CNTRY\_SOLD**

USA

**QRT\_CD**

**VFG\_CD**

V00

**AWS\_VL\_CD**

F5

**VRT\_CD**

SXX

**TIS\_FLAG**

@

**VIN\_CD**

1FTRW07LX1K

**LRR\_COST**

**VEH\_LINK\_CD**

T/F5

**MKT\_DERIVED**

\*

**BOD\_CAB\_STL**

T/B C

**VER\_SERIES\_C**

T/AM

**DRIVE\_CD**

T/B

**ENG\_CD**

T/VZ

<b>ID</b>	419
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	34
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	20-Apr-01
<b>WRTY_START_D</b>	20-Sep-01
<b>NAME</b>	WESTWAY FORD
<b>DOC_NUM</b>	81432701
<b>PH_NUM</b>	0600333
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	18-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2564020
<b>MILGE</b>	7
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2500
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL CHANGED SET BELT.



**TECH\_TXT2**

**CUST\_TXT** PERFORM RECALL 01S21

**AREA\_CD** 972

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 162013

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** SXX

**TIS\_FLAG** Ⓢ

**VIN\_CD** 1FTRW07L81K

**LBR\_COST**

**VRH\_LINE\_CD** T/F5

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** T/C

**VER\_SERIES\_C** T/AM

**DRIVE\_CD** T/B

**ENG\_CD** T/VZ

<b>ID</b>	414
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	35
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	11-Apr-01
<b>WRTY_START_D</b>	18-May-01
<b>NAME</b>	WALDORF FORD, INC.
<b>DOC_NUM</b>	4421051
<b>PH_NUM</b>	8432400
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10-Aug-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2522458
<b>MILGE</b>	87508
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	149
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MD
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL SEAT BELT BUCKLE COMPLETED      RECALL IS COMPLETED

**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL SEAT BELTS
<b>AREA_CD</b>	301
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	127047
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L91K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFS
<b>MRT_DRIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	T/S
<b>ENG_CD</b>	TVZ

<b>ID</b>	418
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	38
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	11-Apr-01
<b>WRTY_START_D</b>	29-Dec-01
<b>NAME</b>	GREENWAY FORD, INC.
<b>DOC_NUM</b>	5129851
<b>PH_NUM</b>	2753200
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	24-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	3401088
<b>MILGE</b>	18
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LRR_HRS</b>	
<b>DLR_CD</b>	4822
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PER RECALL 01821 INSP, OK

**TECH\_TXT2**

**CUST\_TXT** RECALL 01821

**AREA\_CD** 407

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 124224

**TXN\_CD** 01821

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** SXX

**TIS\_FLAG** ③

**VIN\_CD** 1FTRW07L91K [REDACTED]

**LBR\_COST** [REDACTED]

**VEH\_LINE\_CD** TFF

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** TBC

**VER\_SERIES\_C** TIAM

**DRIVE\_CD** TB

**ENG\_CD** TVZ

<b>ID</b>	418
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	37
<b>TRANS_CD</b>	TIDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	5-Apr-01
<b>WRTY_START_D</b>	5-Jul-01
<b>NAME</b>	FIVE STAR FORD
<b>DOC_NUM</b>	18387902
<b>PH_NUM</b>	8483800
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	20-Sep-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	4013152
<b>MILGE</b>	2789
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LRR_HRS</b>	
<b>DLR_CD</b>	20411
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AZ
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL SAFETY CHECK ALL BUCLES ALL PASSED

**TECH\_TXT2**

<b>CUST_TXT</b>	01B21 SEATBELT
<b>AREA_CD</b>	602
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171174
<b>TXN_CD</b>	01B21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	83X
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L91K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T1F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	T1B
<b>ENG_CD</b>	T1Z

<b>ID</b>	417
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	35
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	30-Jan-01
<b>WRTY_START_D</b>	28-Mar-01
<b>NAME</b>	LOMPOG VALLEY FORD
<b>DOC_NUM</b>	077832B
<b>PH_NUM</b>	7357878
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	25-Oct-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	472314
<b>MILGE</b>	8822
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	542E
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECTED FOR SEAT BELT NO REPAIR NEEDED



<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	INSPECT FOR RECALL 01S21
<b>AREA_CD</b>	805
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171444
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	6XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L81K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/B
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	418
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	38
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	14-Dec-01
<b>WRTY_START_D</b>	24-Jan-01
<b>NAME</b>	SOUTHWAY FORD, INC.
<b>DOC_NUM</b>	43828A
<b>PH_NUM</b>	822222
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	7-Sep-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	3880842
<b>MILGE</b>	11788
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4522
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	BUCKLE INSPECTION. PASSED OK. 00821K 0.4

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	APR 01821 BEAT BELT RECALL
<b>AREA_CD</b>	210
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152057
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L81K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BG
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/V2

<b>ID</b>	418
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	40
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	18-May-01
<b>WRTY_START_D</b>	2-Jul-01
<b>NAME</b>	MIKE FITZPATRICK F-L-M
<b>DOC_NUM</b>	7949450
<b>PH_NUM</b>	5023673
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	18-Sep-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	3740608
<b>MILGE</b>	4488
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	1730
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	GA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL PERFORMED SEATBELT BUCKLE INSPECTION PER RECALL

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	PERFORM RECALL 01921 SEAT BELT BUCKLE
<b>AREA_CD</b>	770
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121985
<b>TXN_CD</b>	01821
<b>ENTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRWU7L81K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/BG
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	420
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	41
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	9-Apr-01
<b>WRTY_START_D</b>	10-Sep-01
<b>NAME</b>	MANY FORD-MERCURY, INC.
<b>DOC_NUM</b>	6368701
<b>PH_NUM</b>	2588288
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10-Sep-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	3827381
<b>MILGE</b>	178
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	0608
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	LA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01821.INSPECTED SEAT BELTS WITH TESTER.ALL BELTS PASSED.

<b>TECH_TXTZ</b>	
<b>CUST_TXT</b>	RECALL 01521.
<b>AREA_CD</b>	318
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123224
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWB_VL_CD</b>	FE
<b>VRT_CD</b>	6XX
<b>TIS_FLAG</b>	Q
<b>VIN_CD</b>	1FTRW07L91K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TNZ

<b>ID</b>	421
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	42
<b>TRANS_CD</b>	T0U
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	15-Mar-01
<b>WRTY_START_D</b>	3-Apr-01
<b>NAME</b>	AUDUBON FORD
<b>DOC_NUM</b>	204748C
<b>PH_NUM</b>	293900
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	1-Mar-02
<b>TIS_WSD</b>	12
<b>CLM_KEY</b>	7170121
<b>MILGE</b>	20430
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	0821
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	LA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	20430 SEAT BELTS CHECKED ALL O K



**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL 01821 SEAT BELTS
<b>AREA_CD</b>	225
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123203
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L81K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TF5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TBC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TN2

<b>ID</b>	422
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	43
<b>TRANS_CD</b>	TIDE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	1-Mar-01
<b>WRTY_START_D</b>	2-Apr-01
<b>NAME</b>	FORD OF CORAL GABLES
<b>DOC_NUM</b>	812700A
<b>PH_NUM</b>	8818111
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	31-Aug-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	3845508
<b>MILGE</b>	2882
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	3888
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECTION.

**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL 01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	305
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	113141
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L81K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TIAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TVZ

<b>ID</b>	423
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	44
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	25-Apr-01
<b>WRTY_START_D</b>	14-Jun-01
<b>NAME</b>	LJBBERS BROTHERS FORD-MERCURY,
<b>DOC_NUM</b>	13448801
<b>PH_NUM</b>	6403103
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10-Aug-01
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	2903828
<b>MILGE</b>	5267
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5074
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	KS
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	UPON TESTING, BUCKLES OK 1

Tuesday, December 14, 2004

Page 383 of 468

RQ04-011 E 3708

**TECH\_TXT2**

<b>CUST_TXT</b>	01821 SEAT BELT INSPECTION
<b>AREA_CD</b>	318
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	153835
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	FB
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L71K [REDACTED]
<b>LRR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TF5
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TBC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TAZ

<b>ID</b>	424
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	46
<b>TRANS_CD</b>	T/DX1
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	25-Apr-01
<b>WRTY_START_D</b>	14-Jun-01
<b>NAME</b>	LUBBERS BROTHERS FORD-MERCURY,
<b>DOC_NUM</b>	14014004
<b>PH_NUM</b>	5403103
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	23-Nov-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	6282278
<b>MILGE</b>	11820
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5071
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	KS
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	1 INSPECT BOTH BUCKLE AND BOTH PASS. T

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	310
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	153835
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	Ⓢ
<b>VIN_CD</b>	1FTRW07L71K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T1P5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T1BC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	T1B
<b>ENG_CD</b>	T1Z

<b>ID</b>	425
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	48
<b>TRANS_CD</b>	YDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	24-Apr-01
<b>WRTY_START_D</b>	20-Jun-01
<b>NAME</b>	ALLAN VIGIL FORD
<b>DOC_NUM</b>	416761
<b>PH_NUM</b>	4717801
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	24-Sep-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	3810179
<b>MILGE</b>	4743
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	508
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	GA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL 01621 RECALL



**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL #01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	770
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121022
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VBT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L71K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	428
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	47
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	20-Apr-01
<b>WRTY_START_D</b>	26-May-01
<b>NAME</b>	COVERT FORD, INC.
<b>DOC_NUM</b>	2001551
<b>PH_NUM</b>	3454343
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4-Sep-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	3488482
<b>MILGE</b>	3842
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4437
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL 01821A INSPECTED SEATBELT BUCKLE

**TECH\_TXT2**

<b>CUST_TXT</b>	01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	512
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152302
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L71W [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TF5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TVZ

<b>ID</b>	427
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	48
<b>TRANS_CD</b>	TIDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	20-Apr-01
<b>WRTY_START_D</b>	27-May-01
<b>NAME</b>	FUTURE FORD
<b>DOC_NUM</b>	428050A
<b>PH_NUM</b>	7883873
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	9-Aug-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	2941002
<b>MILGE</b>	2780
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7748
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL COMPLETED INSPECTION SEAT BELTS AJ. OK

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	SEAT BELT RETENTION, RENTAL OK
<b>AREA_CD</b>	816
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172208
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	Ⓟ
<b>VIN_CD</b>	1FTRW07L71K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	428
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	48
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	12-Apr-01
<b>WRTY_START_D</b>	27-Apr-01
<b>NAME</b>	MAXWELL FORD
<b>DOC_NUM</b>	5873408
<b>PH_NUM</b>	4435000
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPE_DT</b>	12-Oct-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	4481733
<b>MILGE</b>	13254
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2923
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	CHECK AND INSPECTED PER RECALL

**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL 01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	912
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152303
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L71K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TF6
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TBC
<b>VBR_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	429
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	50
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	29-Jan-01
<b>WRTY_START_D</b>	14-Feb-01
<b>NAME</b>	ACACIANA FORD, INC.
<b>DOC_NUM</b>	109307E
<b>PH_NUM</b>	6437126
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	1-Oct-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	4205828
<b>MILGE</b>	18534
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	6452
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	LA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	COMPLETED RECALL 01S21. TESTED SEAT BELT BUCKLES WITH TOOL. PASSED



**TECH\_TXT2**

<b>CUST_TXT</b>	01S21 SEAT BELT RECALL
<b>AREA_CD</b>	337
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123262
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L71K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>ROD_CAR_STL</b>	TBC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	TVZ

<b>ID</b>	430
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	51
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	18-Apr-01
<b>WRTY_START_D</b>	20-May-01
<b>NAME</b>	WATSON QUALITY FORD
<b>DOC_NUM</b>	154775B
<b>PH_NUM</b>	9687000
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8-Sep-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	3453837
<b>MILGE</b>	12050
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	8958
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MS
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	12050 PERFORMED RECALL 01821

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01921 SEAT BELT BUCKLE
<b>AREA_CD</b>	801
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	123308
<b>TXN_CD</b>	01921
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L81K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINK_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BG
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	431
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	52
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	30-Mar-01
<b>WRTY_START_D</b>	20-Jul-01
<b>NAME</b>	COLORADO RIVER FORD LINCOLN ME
<b>DOC_NUM</b>	16265801
<b>PH_NUM</b>	7573131
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	2-Jan-02
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	6012347
<b>MILGE</b>	2000
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	1586
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AZ
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL BUCKLE PASSED INSPECTION

<b>TECH_TXT</b>	
<b>CUST_TXT</b>	SEAT BELT BUCKLE
<b>AREA_CD</b>	928
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171488
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	B
<b>VIN_CD</b>	1FTRW07L81K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BC
<b>VER_SERIES_C</b>	T1AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	432
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	58
<b>TRANS_CD</b>	TIDE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	14-May-01
<b>WRTY_START_D</b>	22-Jul-01
<b>NAME</b>	SHAMROCK FORD, INC.
<b>DOC_NUM</b>	2018050
<b>PH_NUM</b>	8285211
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	18-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	3298187
<b>MILGE</b>	25
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7600
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01S21 INSPECTED SEAT BELTS

**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL 01821 SEAT BELT
<b>AREA_CD</b>	925
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172439
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	6XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L51K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	433
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	54
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	19-Apr-01
<b>WRTY_START_D</b>	31-Aug-01
<b>NAME</b>	JOE MYERS FORD, INC.
<b>DOC_NUM</b>	354636A
<b>PH_NUM</b>	898200
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	1-Aug-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2884016
<b>MILGE</b>	11
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4492
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	



<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	A69 RECALL 01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	713
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	162023
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	5XX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L51K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TBC
<b>VEH_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	434
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	55
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	22-Mar-01
<b>WRTY_START_D</b>	31-Aug-01
<b>NAME</b>	FRITTS FORD
<b>DOC_NUM</b>	8730648
<b>PH_NUM</b>	*
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	30-Oct-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	4785138
<b>MILGE</b>	4800
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5557
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL 01521 INSPECT ONLY AS PER RECALL

<b>TECH_TXTZ</b>	
<b>CUST_TXT</b>	RECALL 01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	*
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171155
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07L51H
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/BC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	435
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	58
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	14-Dec-00
<b>WRTY_START_D</b>	9-Feb-01
<b>NAME</b>	HONOLULU FORD INC
<b>DOC_NUM</b>	4803851
<b>PH_NUM</b>	5321700
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	1-Mar-02
<b>TIS_WSD</b>	13
<b>CLM_KEY</b>	7294265
<b>MILGE</b>	13908
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7705
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	HI
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PER RECALL 01821 PERFORMED INSPECTION

Tuesday, December 14, 2004

Page 489 of 468

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821
<b>AREA_CD</b>	808
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172200
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F6
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07LS1 [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	438
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	57
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	17-Apr-01
<b>WRTY_START_D</b>	2-Jul-01
<b>NAME</b>	SEWELL FORD, INC.
<b>DOC_NUM</b>	20749602
<b>PH_NUM</b>	3320421
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	7-Sep-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	3677226
<b>MILGE</b>	2036
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2661
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01821 INSPECTED SEATBELT BUCKLES OK

Tuesday, December 14, 2004

Page 411 of 469

RQ04-011 E 3734

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01S21 SEAT BELT BUCKLE AGR
<b>AREA_CD</b>	915
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152572
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	B
<b>VIN_CD</b>	1FTRM07L41H
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFF
<b>MKT_DERIVED</b>	
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TAZ

<b>ID</b>	437
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	58
<b>TRANS_CD</b>	TDCU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	11-Apr-01
<b>WRTY_START_D</b>	28-May-01
<b>NAME</b>	WORLD FORDKENDALL
<b>DOC_NUM</b>	8558452
<b>PH_NUM</b>	2880211
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	7-Nov-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	5191118
<b>MILGE</b>	8724
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4920
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL PERFORM RECALL PASSED

Tuesday, December 14, 2004

Page 413 of 468

RQ04-011 E 3736



**TECH\_TXT2**

<b>CUST_TXT</b>	RECALL # 01S21
<b>AREA_CD</b>	305
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	124005
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	50X
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L41K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	T7AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	TN2

<b>ID</b>	436
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	58
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	23-Mar-01
<b>WRTY_START_D</b>	22-May-01
<b>NAME</b>	FENTON FORD-MERCLURY, INC.
<b>DOC_NUM</b>	058831A
<b>PH_NUM</b>	4232600
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	14-Sep-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	4138414
<b>MILGE</b>	10288
<b>MYRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2388
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	OK
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECT SEAT BUCKLES PER RECALLS

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	INSPECT BUCKLE PER RECALL
<b>AREA_CD</b>	918
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171488
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	30X
<b>TIS_FLAG</b>	Q
<b>VIN_CD</b>	1FTRW07L41K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VRH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TNZ

<b>ID</b>	438
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	60
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	8-Nov-00
<b>WRTY_START_D</b>	1-Dec-01
<b>NAME</b>	ROCKWALL FORD-MERCURY
<b>DOC_NUM</b>	8037802
<b>PH_NUM</b>	2902200
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8-Nov-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	4978226
<b>MILGE</b>	6
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	9667
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	1 PERFORM RECALL 01B21

**TECH\_TXT2**

**CUST\_TXT**      PERFORM RECALL 01S21 SEAT BELT

**AREA\_CD**      972

**COUNTRY\_CD**      USA

**SLS\_DLR\_CD**      152520

**TXN\_CD**      01S21

**CNTRY\_SOLD**      USA

**QRT\_CD**     

**VFG\_CD**      V00

**AWS\_VL\_CD**      F5

**VRT\_CD**      S0X

**TIS\_FLAG**      0

**VIN\_CD**      1FTRW07L31R

**LBR\_COST**     

**VEH\_LINE\_CD**      T/F5

**MKT\_DERIVED**      \*

**BOD\_CAB\_STL**      TBC

**VER\_SERIES\_C**      T/AM

**DRIVE\_CD**      T/B

**ENG\_CD**      T/VZ

<b>ID</b>	440
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	61
<b>TRANS_CD</b>	T7DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	20-Nov-00
<b>WRTY_START_D</b>	4-Mar-01
<b>NAME</b>	DOBBS FORD AT WOLFCHASE
<b>DOC_NUM</b>	6002051
<b>PH_NUM</b>	2825656
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RFR_DT</b>	18-Oct-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	4548887
<b>MILGE</b>	6501
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4867
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TN
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORM RECALL #BX# INSPECTION ONLY

**TECH\_TXT2**

**CUST\_TXT** 01S21 RECALL

**AREA\_CD** 001

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 123002

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** SXX

**TIS\_FLAG** @

**VIN\_CD** 1FTRW07L31K

**LBR\_COST**

**VEH\_LINE\_CD** T/F6

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** T/BC

**VER\_SERIES\_C** T/AM

**DRIVE\_CD** T/B

**ENG\_CD** TNZ

<b>ID</b>	441
<b>MDL_YR</b>	
<b>SORT_INDEX</b>	
<b>TRANS_CD</b>	
<b>PLANT_CD</b>	
<b>PRODN_DT</b>	
<b>WRTY_START_D</b>	
<b>NAME</b>	
<b>DOC_NUM</b>	
<b>PH_NUM</b>	
<b>WCC_CD</b>	
<b>PART_NUM_CA</b>	
<b>PART_NUM_CA</b>	
<b>PART_NUM_CA</b>	
<b>CUST_CONC_C</b>	
<b>COND_CD</b>	
<b>RPR_DT</b>	
<b>TIS_WSD</b>	
<b>CLM_KEY</b>	
<b>MILGE</b>	
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	
<b>DLR_SUB_CD</b>	
<b>REGION_CD</b>	
<b>ST_PROV_CD</b>	
<b>CPSC_CD_6</b>	
<b>TECH_TXT1</b>	



**TECH\_TXT**

**CUST\_TXT**

**AREA\_CD**

**COUNTRY\_CD**

**SLS\_DLR\_CD**

**TXN\_CD**

**CNTRY\_SOLD**

**QRT\_CD**

**VFG\_CD**

**AWS\_VL\_CD**

**VRT\_CD**

**TIS\_FLAG**

**VIN\_CD**

**LBR\_COST**

**VEH\_LINE\_CD**

**MKT\_DERIVED**

**BOD\_CAB\_STL**

**VER\_SERIES\_C**

**DRIVE\_CD**

**ENG\_CD**

<b>ID</b>	442
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	1
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	19-Dec-00
<b>WRTY_START_D</b>	15-Jan-01
<b>NAME</b>	BILL ALEXANDER FORD L-M INC
<b>DOC_NUM</b>	23885701
<b>PH_NUM</b>	3442200
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4-Aug-01
<b>TIS_WSD</b>	7
<b>CLM_KEY</b>	2797500
<b>MILGE</b>	10180
<b>MYRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	20443
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	AZ
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	

**TECH\_TXT2**

**CUST\_TXT**

<b>AREA_CD</b>	928
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171438
<b>TXN_CD</b>	01521
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L31K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAE_STL</b>	T/B
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	443
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	2
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	25-Oct-00
<b>WRTY_START_D</b>	6-Jan-01
<b>NAME</b>	COURTESY FORD
<b>DOC_NUM</b>	7482040
<b>PH_NUM</b>	4222700
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	5-Oct-01
<b>TIS_WSD</b>	10
<b>CLM_KEY</b>	4186900
<b>MILGE</b>	23114
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	306
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	GA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED RECALL 01821

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	770
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	121081
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	Q
<b>VIN_CD</b>	1FTRW07L31K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TIF5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	444
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	3
<b>TRANS_CD</b>	TIDE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	7-May-01
<b>WRTY_START_D</b>	28-Jul-01
<b>NAME</b>	LLOVIO FORD
<b>DOC_NUM</b>	8271362
<b>PH_NUM</b>	9277888
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	28-Aug-01
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	3402784
<b>MILGE</b>	1481
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5449
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	CONCERN: RECALL 01S21 SEA BELT BUCKLE..CAUSE: 01S21..CORRE: INSPECTION PASSED..APROX TIME: 0.3 HRS JO BSTARTED 14.215.3

	DN 08 31 01
<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	RECALL 01821 SEAT BELT BUCKLE
<b>AREA_CD</b>	582
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171068
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V08
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07L91M [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/EC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	445
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	4
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	16-Apr-01
<b>WRTY_START_D</b>	17-May-01
<b>NAME</b>	DON THOMPSON FORD-MERCURY
<b>DOC_NUM</b>	3853901
<b>PH_NUM</b>	8492861
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	10-Oct-01
<b>TIS_WSD</b>	5
<b>CLM_KEY</b>	4804595
<b>MILGE</b>	8108
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	1135
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_YXT1</b>	TESTED FRONT SEAT BELT BUCKLES AS PER RECALL BOTH BUCKLES PASSED NO REPAIR NEEDED



**TECH\_TXT2**

**CUST\_TXT** RECALL 01S21

**AREA\_CD** 409

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 152131

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** BXX

**TIS\_FLAG** @

**VIN\_CD** 1FTRW07L31K [REDACTED]

**LBR\_COST** [REDACTED]

**VEH\_LINE\_CD** T/F5

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** T/BG

**VER\_SERIES\_C** T/AM

**DRIVE\_CD** T/B

**ENG\_CD** T/VZ

<b>ID</b>	448
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	6
<b>TRANS_CD</b>	TRDJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	11-Apr-01
<b>WRTY_START_D</b>	11-May-01
<b>NAME</b>	TOMBALL FORD, INC.
<b>DOC_NUM</b>	233077A
<b>PH_NUM</b>	3515427
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	11-Dec-01
<b>TIS_WSD</b>	8
<b>CLM_KEY</b>	6755614
<b>MILGE</b>	8108
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	6042
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	8108 PERFORMED 01321 RECALL NTF NRD AT THIS TIME

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	AB9 RECALL 01S21
<b>AREA_CD</b>	281
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	152032
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	8XX
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07L31K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F6
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	T/BG
<b>VER_SERIRS_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/NZ

<b>ID</b>	447
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	8
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	9-Apr-01
<b>WRTY_START_D</b>	20-May-01
<b>NAME</b>	VALLEY FORD LINCOLN-MERCURY
<b>DOC_NUM</b>	4028151
<b>PH_NUM</b>	6846631
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	8-Oct-01
<b>TIS_WSD</b>	5
<b>CLM_KEY</b>	4232800
<b>MILGE</b>	6472
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	7897
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	72: PERFORMED 01821 RECALL, INSPECTED SEATBELTS OK

**TECH\_TXT2**

<b>CUST_TXT</b>	PERFORM INSP FOR RECALL 01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	558
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	172440
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	Ⓢ
<b>VIN_CD</b>	1FTRW07L31K [REDACTED]
<b>LRR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T05
<b>MKT_DERIVED</b>	
<b>BOD_CAR_STL</b>	T/EC
<b>VER_SERIES_C</b>	T/AM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	T/VZ

<b>ID</b>	448
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	7
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	31-Jan-01
<b>WRTY_START_D</b>	20-Mar-01
<b>NAME</b>	SEABREEZE FORD, INC.
<b>DOC_NUM</b>	0548210
<b>PH_NUM</b>	8811800
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	17-Aug-01
<b>TIS_WSD</b>	6
<b>CLM_KEY</b>	3102855
<b>MILGE</b>	10252
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	20828
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	NJ
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	AS PER 01821 CHECKED SEATBELTS PASSED TEST

**TECH\_TXT2**

**CUST\_TXT** 01821 OWNER NOTIFICATION LETTER

**AREA\_CD** 782

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 113471

**TXN\_CD** 01821

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** 80X

**TIS\_FLAG** @

**VIN\_CD** 1FTRW07L31K [REDACTED]

**LBR\_COST** [REDACTED]

**VER\_LINE\_CD** TFS

**MKT\_DERIVED** \*

**BOD\_CAR\_STL** T&C

**VER\_SERIES\_C** TIAM

**DRIVE\_CD** TB

**ENG\_CD** TVZ

<b>ID</b>	448
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	8
<b>TRANS_CD</b>	T/DJ
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	9-Apr-01
<b>WRKY_START_D</b>	11-Aug-01
<b>NAME</b>	MCREE FORD, INC.
<b>DOC_NUM</b>	418218A
<b>PH_NUM</b>	3971529
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	17-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	247462D
<b>MILGE</b>	21
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4443
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	PERFORMED INSPECTION OK



**TECH\_TXT2**

**CUST\_TXT**      RECALL 01S21

**AREA\_CD**      281

**COUNTRY\_CD**      USA

**SLS\_DLR\_CD**      152062

**TXN\_CD**      01S21

**CNTRY\_SOLD**      USA

**QRT\_CD**

**VFG\_CD**      V00

**AWS\_VL\_CD**      F5

**VRT\_CD**      SXK

**TIS\_FLAG**      @

**VIN\_CD**      1FTRW07L21K

**LBR\_COST**      ██████████

**VEH\_LINE\_CD**      TIF6

**MKT\_DERIVED**      \*

**BOD\_CAB\_STL**      T/BC

**VER\_SERIES\_C**      T/AM

**DRIVE\_CD**      T/B

**ENG\_CD**      TVZ

<b>ID</b>	450
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	9
<b>TRANS_CD</b>	T/DE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	10-Apr-01
<b>WRTY_START_D</b>	7-May-01
<b>NAME</b>	BLUE SPRINGS FORD INC
<b>DOC_NUM</b>	4482898
<b>PH_NUM</b>	2294400
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	13-Aug-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	2903963
<b>MILGE</b>	4402
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5100
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MO
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECT SEAT BELTS

**TECH\_TXT2**

<b>CUST_TXT</b>	PERFORM RECALL 01821 SEAT BELT LATCH INSPECTION
<b>AREA_CD</b>	818
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	153008
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07L21K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAR_STL</b>	TBC
<b>VER_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TNZ

<b>ID</b>	461
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	10
<b>TRANS_CD</b>	TIDE
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	10-Apr-01
<b>WRTY_START_D</b>	7-May-01
<b>NAME</b>	BLUE SPRINGS FORD INC
<b>DOC_NUM</b>	458721A
<b>PH_NUM</b>	2294400
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	12-Nov-01
<b>TIS_WSD</b>	7
<b>CLM_KEY</b>	5040679
<b>MILGE</b>	8266
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	5100
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	MO
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECT SEAT BELT

**TECH\_TXT2**

<b>CUST_TXT</b>	01S21 SEAT BELT. DRIVERS SEAT BELT KEEPS UNSNAPPING
<b>AREA_CD</b>	810
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	153008
<b>TXN_CD</b>	01S21
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F3
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L21K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	TFS
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TVZ

<b>ID</b>	462
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	11
<b>TRANS_CD</b>	TADU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	29-Mar-01
<b>WRTY_START_D</b>	3-May-01
<b>NAME</b>	PLANET FORD
<b>DOC_NUM</b>	14432808
<b>PH_NUM</b>	7193700
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	6-Aug-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	3148920
<b>MILGE</b>	7481
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2081
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	INSPECTED SEAT BELT BUCKLES PER RECALL BOTH PASSED

**TECH\_TXT2**

**CUST\_TXT** 01S21 RECALL SEATBELT BUCKEL

**AREA\_CD** 281

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 132032

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F5

**VRT\_CD** SOX

**TIS\_FLAG** @

**VIN\_CD** 1FTRW07L21K [REDACTED]

**LBR\_COST** [REDACTED]

**VEH\_LINE\_CD** T/F5

**MKT\_DERIVED** \*

**BOD\_CAB\_STL** T/B C

**VER\_SERIES\_C** T1AM

**DRIVE\_CD** T/B

**ENG\_CD** T/VZ

<b>ID</b>	453
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	12
<b>TRANS_CD</b>	TDL
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	16-May-01
<b>WRTY_START_D</b>	2-Jun-01
<b>NAME</b>	TEXSTAR FORD LINCOLN MERCURY.
<b>DOC_NUM</b>	12179301
<b>PH_NUM</b>	0687000
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	16-Aug-01
<b>TIS_WSD</b>	3
<b>CLM_KEY</b>	3149703
<b>MILGE</b>	4582
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	2914
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	1 RECALL COMPLETED

Tuesday, December 14, 2004

Page 445 of 460

RQ04-011 E 3768



**TECH\_TXT2**

**CUST\_TXT** 01S21 RECALL SEAT BELT BUCKLE

**AREA\_CD** 264

**COUNTRY\_CD** USA

**SLS\_DLR\_CD** 152487

**TXN\_CD** 01S21

**CNTRY\_SOLD** USA

**QRT\_CD**

**VFG\_CD** V00

**AWS\_VL\_CD** F6

**VRT\_CD** SXX

**TIS\_FLAG** C

**VIN\_CD** 1FTRW07L11K

**LBR\_COST**

**VEH\_LINE\_CD** TFF

**MKT\_DERIVED**

**BOD\_CAB\_STL** TBC

**VER\_SERIES\_C** TIAM

**DRIVE\_CD** TFB

**ENG\_CD** TNZ

<b>ID</b>	454
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	13
<b>TRANS_CD</b>	TIDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	11-Apr-01
<b>WRTY_START_D</b>	14-Jun-01
<b>NAME</b>	DAVID WILSON'S FORD OF ORANGE
<b>DOC_NUM</b>	7178761
<b>PH_NUM</b>	9781880
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	4-Oct-01
<b>TIS_WSD</b>	4
<b>CLM_KEY</b>	4475422
<b>MILGE</b>	3687
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	751
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	CA
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL PASSED INSPECTION

<b>TECH_TXT2</b>	
<b>CUST_TXT</b>	01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	714
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	171064
<b>TXN_CD</b>	01821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	BXX
<b>TIS_FLAG</b>	0
<b>VIN_CD</b>	1FTRW07L11K
<b>LBR_COST</b>	
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	T/B
<b>VER_SERIES_C</b>	TIAM
<b>DRIVE_CD</b>	T/B
<b>ENG_CD</b>	TVZ

<b>ID</b>	455
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	14
<b>TRANS_CD</b>	T/DU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	10-Apr-01
<b>WRTY_START_D</b>	19-Jun-01
<b>NAME</b>	HELPMAN FORD INC
<b>DOC_NUM</b>	6480651
<b>PH_NUM</b>	2403873
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	27-Aug-01
<b>TIS_WSD</b>	2
<b>CLM_KEY</b>	3254144
<b>MILGE</b>	4918
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4587
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	TX
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	01821 01821 INSPECTED AND PASSED

**TECH\_TXT2**

<b>CUST_TXT</b>	01S21 SEAT BELT BUCKLE
<b>AREA_CD</b>	281
<b>COUNTRY_CD</b>	USA
<b>SLS_DLR_CD</b>	182182
<b>TXN_CD</b>	D1821
<b>CNTRY_SOLD</b>	USA
<b>QRT_CD</b>	
<b>VFG_CD</b>	V00
<b>AWS_VL_CD</b>	F5
<b>VRT_CD</b>	SXX
<b>TIS_FLAG</b>	@
<b>VIN_CD</b>	1FTRW07L11K [REDACTED]
<b>LBR_COST</b>	[REDACTED]
<b>VEH_LINE_CD</b>	T/F5
<b>MKT_DERIVED</b>	*
<b>BOD_CAB_STL</b>	TBC
<b>VER_SERIES_C</b>	TIAM
<b>DRIVE_CD</b>	TB
<b>ENG_CD</b>	TN2

<b>ID</b>	450
<b>MDL_YR</b>	2001
<b>SORT_INDEX</b>	15
<b>TRANS_CD</b>	TDU
<b>PLANT_CD</b>	AJ
<b>PRODN_DT</b>	12-Apr-01
<b>WRTY_START_D</b>	18-Aug-01
<b>NAME</b>	GARY YEOMANS FORD
<b>DOC_NUM</b>	31019901
<b>PH_NUM</b>	2638771
<b>WCC_CD</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>PART_NUM_CA</b>	*
<b>CUST_CONC_C</b>	*
<b>COND_CD</b>	*
<b>RPR_DT</b>	23-Jul-01
<b>TIS_WSD</b>	0
<b>CLM_KEY</b>	2475865
<b>MILGE</b>	28
<b>MTRL_COST</b>	
<b>TOT_COST_GRO</b>	
<b>LBR_HRS</b>	
<b>DLR_CD</b>	4700
<b>DLR_SUB_CD</b>	*
<b>REGION_CD</b>	NA
<b>ST_PROV_CD</b>	FL
<b>CPSC_CD_6</b>	*
<b>TECH_TXT1</b>	RECALL 01821 MI OUT 28 PERFORMEND RECALL INSPECTION PASSED INSPECTION FOR RECALL 01821.