

**RQ04-011**

**FORD**

**APRIL 26, 2005**

**REQUEST 8**

**PART 5 OF 6**

**BOOK 8 OF 43**

2001	826 T/DE	AP	12-Apr-01	30-Jun-01	TOMBALL FORD, INC.	223114C
2001	828 T/DE	AP	2-Apr-01	22-Jun-01	SOUTHWEST FORD INC	19618302
2001	831 T/DE	AP	8-Feb-01	4-Apr-01	TIPTON MOTORS, INC.	8642801
2001	834 T/DE	AP	3-Feb-01	27-Jun-01	LOU GRUBB FORD	4247851
2001	837 T/DE	AP	24-Oct-00	9-Nov-00	SAMES MOTOR COMPANY, INC.	636924B
2001	843 T/DE	AP	6-Mar-01	28-Aug-01	JIM TIDWELL'S WORLD FORD	8492851
2001	844 T/DE	AP	8-Dec-00	6-Aug-01	SHETLER-CORLEY MOTORS, LIMITED	11136801
2001	847 T/DE	AP	20-Apr-01	30-Aug-01	DON DAVIS FORD, INC.	403444B
2001	849 T/DE	AP	27-Mar-01	17-Dec-01	ROCKWALL FORD-MERCURY	8499101
2001	850 T/DE	AP	11-Mar-01	30-Mar-01	PECHELES FORD MERCURY	10823401
2001	851 T/DE	AP	2-Apr-01	10-Sep-01	GALPIN FORD	59361751
2001	853 T/DE	AP	4-Jan-01	12-May-01	LONE STAR FORD	28819201
2001	854 T/DE	AP	30-Oct-00	20-Dec-01	FORD GROVES	9845001
2001	856 T/DE	AP	14-Oct-00	15-Mar-01	GALPIN FORD	6082251
2001	860 T/DE	AP	24-Apr-01	11-May-01	DON DAVIS FORD, INC.	411654C
2001	862 T/DE	AP	4-Apr-01	6-Aug-01	EL CAJON FORD	8840151
2001	868 T/DE	AP	1-Feb-01	17-Aug-01	GWINNETT PLACE FORD	8912402
2001	869 T/DE	AP	28-Oct-00	18-Sep-01	J.C. LEWIS MOTOR CO., INC.	30824502
2001	872 T/DE	AP	24-Apr-01	11-May-01	DON DAVIS FORD, INC.	331338B
2001	874 T/DE	AP	14-Mar-01	28-Jul-01	BILLINGSLEY FORD, INC.	098356A
2001	878 T/DE	AP	5-Feb-01	7-Jun-01	JOHN BLEAKLEY FORD INC	7483951
2001	877 T/DE	AP	5-Feb-01	4-Jul-01	TOWN & COUNTRY FORD , INC.	26181501
2001	878 T/DE	AP	12-Jun-01	3-Sep-01	COURTESY MOTORS, INC.	084047A
2001	880 T/DE	AP	5-Jun-01	22-Oct-01	JENKINS AND WYNNE FORD LINCOLN	076500A
2001	884 T/DE	AP	27-Apr-01	17-Aug-01	SKYLINE FORD SALES, INC.	110133A
2001	888 T/DE	AP	10-Apr-01	18-Sep-01	DON DAVIS FORD, INC.	408273D
2001	888 T/DE	AP	7-Mar-01	18-Jun-01	SANDERSON L-M INC	84041901
2001	890 T/DE	AP	25-Jan-01	18-Aug-01	KING CHARLIE HILLARD FORD	19230503
2001	891 T/DE	AP	20-Nov-00	29-Jan-01	BEVERLY HILLS FORD	15152101
2001	893 T/DE	AP	27-Apr-01	22-May-01	WOODY ANDERSON FORD	8444852
2001	895 T/DE	AP	24-Apr-01	25-Jun-01	HOLLINGSWORTH RICHARDS FORD	15871401
2001	897 T/DE	AP	24-Apr-01	15-Sep-01	DON DAVIS FORD, INC.	401778B
2001	898 T/DE	AP	24-Apr-01	4-Aug-01	GWINNETT PLACE FORD	8957803
2001	899 T/DE	AP	24-Apr-01	25-May-01	SAWGRASS FORD	38288301
2001	900 T/DE	AP	10-Apr-01	5-Oct-01	DON DAVIS FORD, INC.	402214C
2001	901 T/DE	AP	12-Feb-01	21-Mar-01	D & D MOTORS, INC.	171072B
2001	902 T/DE	AP	29-Jan-01	11-Apr-01	RANCHO FORD L-M	28532902

2001	903 T/DE	AP	24-May-01	18-Sep-01	CAREY PAUL FORD	9789751
2001	904 T/DE	AP	25-May-01	12-Aug-01	VISTA FORD OF OXNARD	2597451
2001	907 T/DE	AP	9-Apr-01	27-May-01	DOWNTOWN FORD SALES	173582A
2001	908 T/DE	AP	7-Apr-01	9-Jun-01	GALPIN FORD	8333894
2001	914 T/DE	AP	6-Nov-00	17-Apr-01	ALL STAR FORD LINCOLN MERCURY,	240987A
2001	917 T/DE	AP	3-Apr-01	18-May-01	ANDREWS COUNTY FORD	026191B
2001	921 T/DE	AP	26-Oct-00	8-Aug-01	MAGARINO FORD-MERCURY, INC.	3887301
2001	922 T/DE	AP	15-May-01	13-Jun-01	ALL STAR FORD-MERCURY, INC.	8914303
2001	923 T/DE	AP	27-Apr-01	30-May-01	BOYER FORD TRUCKS, INC.	225757A
2001	925 T/DE	AP	18-Apr-01	6-Jul-01	GRIFFITH FORD-MERCURY, INC.	4387852
2001	929 T/DE	AP	4-Jan-01	28-Aug-01	VICTORY FORD MERCURY, INC.	8084201
2001	933 T/DE	AP	21-Aug-00	21-Nov-00	CERRITOS FORD	27271004
2001	934 T/DE	AP	22-Apr-01	6-Aug-01	VALLEY FORD-MERCURY, INC.	889543
2001	935 T/DE	AP	20-Apr-01	4-Sep-01	QUINIK FORD, INC.	336445B
2001	937 T/DE	AP	20-Apr-01	12-May-01	MIDDLEKAUFF FORD, INC.	518538A
2001	941 T/DE	AP	18-May-01	8-Jun-01	LOU GRUBB FORD	3571853
2001	945 T/DE	AP	28-Feb-01	7-Mar-01	TOMS FORD, INC.	207122A
2001	949 T/DE	AP	1-May-01	8-Aug-01	BUD SHELL FORD INC	8545201
2001	952 T/DE	AP	13-Apr-01	18-Jun-01	WEBB FORD INC	5889152
2001	954 T/DE	AP	9-Apr-01	30-Apr-01	LANDERS FORD	8548502
2001	958 T/DE	AP	20-Apr-01	30-Jun-01	TOWN EAST FORD	781523A
2001	958 T/DE	AP	5-Jan-01	27-Feb-01	SAYVILLE FORD	40900601
2001	961 T/DE	AP	5-Jun-01	10-Jul-01	AUFFENBERG FORD, INC.	068841A
2001	964 T/DE	AP	19-Apr-01	29-May-01	SIGNATURE FORD LINCOLN-MERCURY	075788B
2001	966 T/DE	AP	19-Apr-01	18-Jul-01	GEWEKE FORD	13333801
2001	971 T/DE	AP	29-Mar-01	28-Sep-01	BARBER-DYSON FORD L-M, L.L.C.	1385001
2001	973 T/DE	AP	27-Feb-01	4-Jun-01	APACHE FORD MERCURY, INC.	7701701
2001	974 T/DE	AP	14-Feb-01	28-Feb-01	O'DANIEL FORD, INC.	073840A
2001	981 T/DE	AP	27-Oct-00	15-Jan-01	RICHARDSON FORD	1821901
2001	984 T/DE	AP	1-May-01	27-Jul-01	LOU GRUBB FORD	2315551
2001	988 T/DE	AP	10-Apr-01	18-Jul-01	DICK BRANTMEYER FORD INC	1707301
2001	988 T/DE	AP	14-Mar-01	14-Sep-01	W & W FORD SALES, INC.	5190651
2001	989 T/DE	AP	14-Nov-00	29-Nov-00	TOWN & COUNTRY FORD	1980154
2001	990 T/DE	AP	19-Jun-01	31-Oct-01	ASTRO FORD	7808951
2001	991 T/DE	AP	6-Jun-01	2-Aug-01	FRIENDLY FORD	6371551
2001	992 T/DE	AP	27-Apr-01	15-May-01	LOU GRUBB FORD	3511551
2001	994 T/DE	AP	24-Apr-01	19-Aug-01	LANDMARK FORD INC	439728B

2001

885 T/DE . AP

24-Apr-01

29-Jun-01 JONES-WEST FORD

20097101

RQ04-011 00584

PH_NUM	WCC_CD	PART_NUM_CAUS_PREF	PART_NUM_CAUS_BASE	PART_NUM_CAUS_SUFF	CUST_CONC_CD	COND_CD
5284811	8R02	1L7Z	7861203	CAA	S25	42
9325000	8R02	1L7Z	7861203	BAA	S25	1
2614261	8R02	1L7Z	7861203	BAA	S25	33
9613333	8R02	1L7Z	7861203	BAA	S40	42
2708441	8R02	1L7Z	7861203	BAA	S25	42
3515427	8R02	1L7Z	7861203	CAA	S40	42
6634111	8R02	1L7Z	7861203	CAA	S40	42
4435000	8R02	1L7Z	7861203	BAA	S40	42
3885744	8R02	1L7Z	7861203	BAA	S40	12
3274500	8R02	1L7Z	7861203	CAA	S40	1
3371529	8R02	1L7Z	7861203	CAA	S40	42
3618100	8R02	*	7861203	"	S25	41
2759200	8R02	1L7Z	7861203	BAA	T90	33
9336571	8R02	1L7Z	7861203	BAA	S26	42
5325820	8R02	1L7Z	7861203	BAA	S25	41
9325000	8R02	1L7Z	7861203	BAA	T90	42
8590333	8R02	1L7Z	7861203	CAA	S25	33
8855554	8R02	1L7Z	7861203	BAA	S40	42
6580393	8R02	1L7Z	7861203	CAA	S25	7
8811200	8R02	1L7Z	7861203	BAA	S25	42
8233211	8R02	1L7Z	7861203	BAA	S40	1
3515427	8R02	1L7Z	7861203	CAA	S40	42
2334500	8R02	1L7Z	7861203	BAA	S25	42
7193700	8R02	1L7Z	7861203	BAA	S40	42
8894881	8R02	1L7Z	7861203	CAA	S40	D4
2482538	8R02	1L7Z	7861203	BAA	S25	42
4211300	8R02	1L7Z	7861203	BAA	A85	42
4435000	8R02	1L7Z	7861203	BAA	T90	42
3371529	8R02	1L7Z	7861203	CAA	S40	42
8303873	8R02	1L7Z	7861203	BAA	S40	42
2403873	8R02	1L7Z	7861203	CAA	S07	33
5302277	8R02	1L7Z	7861203	CAA	S26	42
2643023	8R02	1L7Z	7861203	CAA	S40	7
5799100	8R02	1L7Z	7861203	BAA	S26	42
9222700	8R02	1L7Z	7861203	CAA	S40	42
9622151	8R02	1L7Z	7861203	BAA	S25	41

8383859 8F02 1L7Z  
2853784 8F02 1L7Z  
2838900 8F02 1L7Z  
2462010 8F02 1L7Z  
8894861 8F02 1L7Z  
5354321 8F02 1L7Z  
5823873 8F02 1L7Z  
8991010 8F02 1L7Z  
8867300 8F02 1L7Z  
4759000 8F02 1L7Z  
8F02 1L7Z  
2403873 8F02 1L7Z  
3454343 8F02 1L7Z  
4673873 8F02 1L7Z  
8278130 8F02 1L7Z  
4432500 8F02 1L7Z  
8897600 8F02 1L7Z  
5302277 8F02 1L7Z  
2407000 8F02 1L7Z  
7844700 8F02 1L7Z  
8816111 8F02 1L7Z  
8897600 8F02 1L7Z  
7873800 8F02 1L7Z  
2319491 8F02 1L7Z  
7425771 8F02 1L7Z  
4439000 8F02 1L7Z  
4469171 8F02 1L7Z  
5522780 8F02 1L7Z  
3891816 8F02 1L7Z  
4598800 8F02 1L7Z  
7792272 8F02 1L7Z  
7873800 8F02 1L7Z  
2283300 8F02 1L7Z  
6842400 8F02 1L7Z  
7524171 8F02 1L7Z  
8991010 8F02 1L7Z  
8555383 8F02 1L7Z

7861203 BAB  
7861203 CAA  
7861203 BAC  
7861203 CAA  
7861203 GAA  
7861203 BAA  
7861203 BAA  
7861203 CAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 CAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA  
7861203 BAA  
7861203 CAA

S40 42  
S40 1  
S25 42  
S40 42  
S40 D4 42  
S25 42  
D50 42  
S40 1  
S26 42  
S40 42  
S26 1  
S40 42  
S40 1  
S40 1  
S26 42  
S40 42  
S26 42  
S40 42  
S40 42  
S40 42  
S25 42  
S26 42  
S40 42  
S40 42  
S25 42  
S25 42  
S40 41  
S40 42  
S26 42  
S26 42  
S40 42  
S40 42  
S26 68  
S25 42  
S40 42  
S26 42  
S40 42  
S40 42



7488244	8R02	1L7Z
7488244	8R02	1L7Z
3683184	8R02	1L7Z
3632870	8R02	1L7Z
4288218	8R02	1L7Z
3473000	8R02	1L7Z
9510300	8R02	1L7Z
8834330	8R02	1L7Z
2511441	8R02	1L7Z
6222900	8R02	1L7Z
2981000	8R02	1L7Z
6548541	8R02	1L7Z
5522780	8R02	F85Z
6580333	8R02	1L7Z
6847600	8R02	1L7Z
2212800	8R02	1L7Z
7803873	8R02	1L7Z
3726707	8R02	1L7Z
8465555	8R02	F85Z
8088011	8R02	1L7Z
2411800	8R02	1L7Z
9458900	8R02	1L7Z
3528030	8R02	1L7Z
9183673	8R02	1L7Z
8315300	8R02	1L7Z
6253030	8R02	F85Z
8380222	8R02	1L7Z
6483673	8R02	1L7Z
5302277	8R02	1L7Z
9885700	8R02	F85Z
6382518	8R02	1L7Z
5353673	8R02	F85Z
7700070	8R02	1L7Z
3658000	8R02	1L7Z
3477000	8R02	1L7Z
7282171	8R02	1L7Z
7518711	8R02	1L7Z

7861203	BAA	S40	42
7861203	BAA	S40	42
7861203	BAC	S40	42
7861203	BAC	S40	42
7861203	BAB	S40	42
7861203	BAA	S26	42
7861203	BAB	S26	42
7861203	BAA	S40	42
7861203	BAB	S40	42
7861203	BAA	S26	42
7861203	BAB	S40	42
7861203	BAC	S25	42
7861203	AAB	S40	42
7861203	BAA	S25	42
7861203	BAB	S25	42
7861203	BAA	S40	42
7861203	BAB	S40	42
7861203	BAA	S40	42
7861203	BAB	S40	42
7861203	BAA	S25	41
7861203	BAA	T90	42
7861203	BAB	S25	41
7861203	BAB	S40	42
7861203	GAA	S25	42
7861203	BAC	S40	42
7861203	BAB	S25	42
7861203	BBE	S25	1
7861203	BAB	S28	42
7861203	BAA	S40	1
7861203	BAC	S26	42
7861203	BBE	S40	42
7861203	BAA	S26	42
7861203	BBE	S40	42
7861203	BAA	S26	42
7861203	BAA	S40	42
7861203	BAA	T90	42
7861203	BAC	S40	42
7861203	AAH	S40	42















3268800 6F02 1LZ

7861203 CAA

S40

42

RPR_DT	TIS_WSD	CLM_KEY	MILGE	MTR1	COST	TOT_COST_GROSS	BR_HRS	DLR_CD	DLR_SUB_CD	REGION_CD	ST_PROV_CD	
7-May-02	12	8571444	8066		26.05	53.03	0.4	9195 *		NA	CT	c
24-Oct-01	4	4852618	5326		26.05	52.26	0.4	4511 *		NA	TX	b
24-Jan-02	6	6479521	6226		26.05	52.62	0.4	2417 *		NA	TX	c
11-Dec-01	6	5765454	10023		26.05	130.32	0.7	20323 *		NA	AZ	c
12-Nov-01	3	5107268	5122		26.05	51.86	0.4	6192 *		NA	TX	c
23-Jul-01	1	2906284	1012		26.05	90.33	1	6042 *		NA	TX	b
10-Jul-01	1	2322903	529		26.06	52.22	0.4	4572 *		NA	TX	c
7-Dec-01	6	5803834	8250		26.05	53.44	0.4	2828 *		NA	TX	c
18-Sep-01	7	3856747	5706		52.11	110.06	0.6	7851 *		NA	CA	a
12-Sep-01	4	3688633	5158		26.05	53.15	0.4	549 *		NA	TX	c
28-Dec-01	6	6041850	5436		26.05	62.35	0.4	4443 *		NA	TX	a
19-Nov-01	5	5277693	9128		0	13.63	0.2	2480 *		NA	TX	b
14-Nov-01	6	5133647	6426		26.05	51.44	0.4	4822 *		NA	FL	c
12-Mar-02	10	7370970	12158		46.32	86.06	0.6	4989 *		NA	FL	a
21-Nov-01	4	5293570	2071		26.05	48.34	0.4	290 *		NA	GA	a
2-Jan-02	11	6082424	33827		26.05	108.26	0.4	4511 *		NA	TX	c
14-Jan-02	9	6254696	14172		26.05	53.73	0.4	2586 *		NA	TX	c
9-Nov-01	11	5725597	18858		26.05	86.6	0.8	5401 *		NA	CA	a
26-Sep-01	2	3918054	8481		26.05	60.66	0.5	2588 *		NA	TX	a
10-Dec-01	5	6048976	5379		26.06	63.5	0.4	7729 *		NA	CA	b
16-Feb-02	7	6991671	7201		26.05	70.23	0.8	1118 *		NA	TX	a
21-Sep-01	4	4387468	3391		26.05	71.05	0.7	6042 *		NA	TX	a
21-Nov-01	5	5283913	6007		26.05	49.75	0.4	6461 *		NA	LA	a
18-Dec-01	9	5806708	9349		26.05	52.39	0.4	2081 *		NA	TX	c
12-Nov-01	6	5071109	14364		26.05	52.43	0.4	4474 *		NA	TX	c
28-Mar-02	14	7710017	18041		26.05	57.3	0.5	4424 *		NA	TX	c
9-Aug-01	1	2962351	448		26.05	83.95	0.8	2975 *		NA	MI	a
24-Sep-01	4	3882488	7545		26.05	53.44	0.4	2923 *		NA	TX	c
16-Aug-01	1	3088298	1559		26.05	52.35	0.4	4443 *		NA	TX	c
28-Mar-02	10	7718802	15989		46.32	128.48	1.2	7670 *		NA	TX	c
29-Nov-01	9	5578539	11075		26.05	52.55	0.4	4567 *		NA	TX	a
15-Mar-02	13	7548617	19901		46.32	104.97	0.9	4527 *		NA	TX	b
26-Jan-02	12	6577008	21401		26.06	49.14	0.4	4886 *		NA	FL	c
20-Feb-02	6	6999096	14584		26.05	52.26	0.4	4517 *		NA	TX	a
5-Jul-01	3	2220350	7593		26.05	62.36	0.4	369 *		NA	GA	a
10-Aug-01	0	4480192	5		26.05	77.4	0.9	2515 *		NA	TX	a



8-Sep-01	1	4684727	2336	28.05	50.14	0.4	4500 *	NA	TX	b
28-Mar-02	7	7731910	9187	28.05	49.21	0.4	1618 *	NA	TX	c
16-Jul-01	0	5372944	1500	48.32	114.84	1	6521 *	NA	LA	a
22-Jan-02	6	6549332	8790	28.05	44.86	0.9	6440 *	NA	LA	c
27-Nov-01	7	6464360	10788	28.05	92.01	1	4474 *	NA	TX	c
3-Oct-01	8	4116446	16705	28.05	41.85	0.3	5978 *	NA	AR	a
13-Aug-01	1	3749215	802	28.05	58.15	0.5	4956 *	NA	FL	a
25-Jul-01	1	2717553	1330	28.05	60.45	0.5	2531 *	NA	TX	a
15-Apr-02	10	8018514	11494	28.05	51.13	0.4	6554 *	NA	LA	a
8-Oct-01	1	4242457	1472	28.05	62.13	0.6	3558 *	NA	OK	b
4-Apr-02	11	7883809	15480	28.05	113.82	0.5	3795 *	NA	TN	c
21-Dec-01	8	5901041	15051	28.05	52.55	0.4	4587 *	NA	TX	c
5-Feb-02	13	6762142	20929	28.05	67.88	0.9	4437 *	NA	TX	b
26-Oct-01	14	4819424	26367	28.05	92.55	1	2488 *	NA	TX	b
14-Jan-02	7	6344268	18000	28.05	57.53	0.4	5412 *	NA	CA	b
4-Jan-02	8	6070891	6138	28.05	51.59	0.4	6531 *	NA	LA	c
19-Mar-02	10	7489847	17098	28.05	51.81	0.4	3073 *	NA	FL	c
27-Oct-01	1	4766739	885	28.05	91.22	1	4527 *	NA	TX	a
12-Nov-01	8	5294819	13127	28.05	85.89	0.8	712 *	NA	CA	a
12-Nov-01	7	5554509	8134	28.05	42.01	0.2	5524 *	NA	CA	c
13-Aug-01	4	2994813	7530	28.05	58.88	0.5	3898 *	NA	FL	a
4-Mar-02	9	7188471	20508	32.7	58.28	0.4	3073 *	NA	FL	a
14-Aug-01	0	4001132	58	48.32	92.17	0.8	5336 *	NA	CA	a
15-Jan-02	7	6467565	8329	28.05	82.38	0.8	4212 *	NA	TX	c
4-Jan-02	6	6082570	6381	28.05	49.79	0.4	348 *	NA	GA	c
27-Nov-01	11	5384410	21741	28.05	53.44	0.4	2923 *	NA	TX	a
29-Oct-01	2	5335539	2652	28.05	51.77	0.4	4482 *	NA	TX	c
29-Jan-02	6	6567107	8333	28.05	51.05	0.4	1071 *	NA	NC	c
8-Mar-02	10	7836804	12924	28.05	51.19	0.4	4448 *	NA	TX	a
17-Dec-01	9	6894590	10000	28.05	56.97	0.4	1597 *	NA	CA	a
6-Oct-01	10	4226080	10548	28.05	49.58	0.4	20455 *	NA	TX	a
15-Feb-02	8	6849451	9484	28.05	64.25	0.5	5536 *	NA	CA	a
28-Mar-02	10	7733212	18628	28.05	50.32	0.4	2414 *	NA	OK	b
12-Mar-02	10	7343404	9137	28.05	63.03	0.4	4889 *	NA	FL	c
12-Feb-02	4	6835775	9116	28.05	50.13	0.4	481 *	NA	FL	c
29-Aug-01	6	3385367	11425	28.05	60.45	0.5	2531 *	NA	TX	b
18-Jul-01	3	2813102	9024	28.05	48.78	0.4	892 *	NA	SC	c

18-Feb-02	7	8988912	7584	28.05	51.05	0.4	4544 *	NA	TX	a
30-Nov-01	5	5543153	10637	28.05	45.81	0.4	907 *	NA	SC	a
13-Sep-01	5	3747933	8500	46.32	85.79	0.8	4473 *	NA	TX	a
28-Dec-01	8	6087705	8038	28.05	75.39	0.8	4589 *	NA	TX	c
31-Jul-01	0	3257238	41	46.32	183.88	1.8	5538 *	NA	CA	a
7-Nov-01	4	5102434	6147	28.05	80.77	0.8	4356 *	NA	CA	c
28-Mar-02	12	7758558	13870	28.05	52.01	0.4	2463 *	NA	TX	c
12-Apr-02	-1	8018117	11732	28.05	74.07	0.9	6330 *	NA	TX	b
14-Aug-01	0	3525117	8	46.32	107.46	0.8	5538 *	NA	CA	a
1-Apr-02	8	7763408	6997	28.05	54.85	0.4	2478 *	NA	TX	a
14-Aug-01	0	3525118	82	46.32	107.46	0.8	5538 *	NA	CA	a
8-Nov-01	4	5003897	5772	46.32	82.54	0.8	2453 *	NA	TX	c
4-Apr-02	11	7897309	14274	28.05	51.73	0.4	4580 *	NA	TX	a
14-Jan-02	7	6886439	12390	28.05	50.73	0.4	4411 *	NA	TX	a
8-Feb-02	9	8765889	9533	28.05	48.89	0.4	6585 *	NA	LA	c
25-Feb-02	17	7078274	31699	28.05	53.44	0.4	2929 *	NA	TX	a
4-Oct-01	11	4320650	14181	46.32	72.38	0.4	6947 *	NA	TX	a
4-Dec-01	8	5487176	13891	28.05	74.86	0.8	989 *	NA	NC	c
27-Nov-01	8	5373887	7808	28.05	52.34	0.4	7232 *	NA	NE	a
26-Mar-02	6	7635148	6860	28.05	83.38	0.7	7749 *	NA	CA	a
6-Oct-01	1	4488796	821	28.05	53.88	0.4	5493 *	NA	CA	a
27-Sep-01	1	5044811	818	42	85.22	0.7	7430 *	NA	PA	b
1-Apr-02	18	7827628	34536	46.32	88.9	0.8	509 *	NA	GA	b
14-Feb-02	17	6954426	17243	28.05	81.18	0.7	9053 *	NA	ME	b
21-Jan-02	4	6410521	3721	28.05	50.73	0.4	9870 *	NA	MI	c
3-Dec-01	8	5487437	11787	28.05	107.05	0.4	1071 *	NA	NC	c
13-Mar-02	8	7384357	11408	28.05	57.07	0.5	2088 *	NA	KY	c
11-Apr-02	14	8020547	28318	28.05	50.19	0.4	8850 *	NA	CT	a
22-Dec-01	8	6984654	10328	46.32	79.72	0.5	9143 *	NA	ME	c
24-Sep-01	1	4215014	625	28.05	51.4	0.4	6190 *	NA	WI	b
11-Oct-01	5	4343888	8393	28.05	54.86	0.4	3025 *	NA	MI	a
19-Feb-02	4	7053813	3382	28.05	52.28	0.4	5688 *	NA	KY	c
21-Sep-01	2	4074194	1871	28.05	54.59	0.4	3050 *	NA	MI	b
27-Sep-01	8	4008889	10497	32.01	61.22	0.4	10526 *	NA	IL	b
22-Jan-02	1	6402478	590	28.05	44.15	0.3	4823 *	NA	IN	a
7-Feb-02	7	6818453	4288	28.05	70.18	0.5	3858 *	NA	NY	a
20-Aug-01	9	3282364	10828	28.05	82.08	0.5	2676 *	NA	MI	c

28-Oct-01	9	5730470	5485	28.05	52.88	0.4	8645 *	NA	WA	O
11-Dec-01	5	5730471	13152	28.05	52.88	0.4	8645 *	NA	WA	C
22-Aug-01	1	3478281	412	46.32	75.37	0.4	67 *	NA	VA	B
6-Mar-02	5	7517001	3944	28.05	52.73	0.4	1209 *	NA	PA	C
12-Mar-02	4	7350428	7301	28.05	81.95	1	8734 *	NA	MI	A
17-Apr-02	11	8175752	18718	28.05	78.78	0.7	20523 *	NA	NJ	A
4-Mar-02	7	7203804	6961	33.89	81.08	0.8	20527 *	NA	NJ	A
23-Nov-01	7	5902291	8995	28.05	82.49	0.8	5017 *	NA	MO	C
13-Aug-01	9	2935140	9142	28.05	51.01	0.4	4871 *	NA	IN	B
10-Apr-02	5	8040875	3775	28.05	49.28	0.4	3908 *	NA	MD	C
18-Oct-01	0	4886526	11	28.05	51.6	0.4	5035 *	NA	FL	A
25-Apr-02	12	8978501	9845	28.05	49.85	0.4	4408 *	NA	TX	E
4-Apr-02	11	7804993	7419	17.38	42.38	0.4	1071 *	NA	NC	D
13-Apr-02	12	7973834	10838	28.05	53.73	0.4	2598 *	NA	TX	B
12-Jul-01	2	2451504	1588	28.05	89.1	0.9	7923 *	NA	CA	C
7-Dec-01	7	5615288	7078	28.05	73.78	0.3	7887 *	NA	TX	C
27-Dec-01	5	8044011	4105	28.05	144.14	0.8	5449 *	NA	CA	C
28-Sep-01	1	4171745	1689	28.05	47.6	0.4	2588 *	NA	TX	C
12-Jul-01	3	2348082	2254	42	99.18	0.4	5555 *	NA	CA	C
29-Jan-02	9	6678176	11374	28.05	51.26	0.4	4570 *	NA	TX	O
12-Jan-02	9	8265824	9895	28.05	72.81	0.5	7891 *	NA	CA	A
25-Mar-02	11	7804545	11849	28.05	70.57	0.6	869 *	NA	CA	O
14-Jul-01	4	4115714	7018	28.05	52.19	0.4	3591 *	NA	CA	C
17-Nov-01	7	5183250	8157	28.05	84.03	0.8	5548 *	NA	CA	D
21-Dec-01	10	5945706	4289	28.05	48.55	0.4	210 *	NA	AL	C
12-Jul-01	2	2305921	3325	42	69.24	0.5	6435 *	NA	LA	C
16-Apr-02	18	8035730	30327	28.05	45.91	0.3	1899 *	NA	VA	A
4-Oct-01	2	4180379	1116	28.05	84.53	0.5	5583 *	NA	CA	A
14-Mar-02	8	7419533	4954	28.05	62.12	0.4	4527 *	NA	TX	C
23-Jul-01	2	2898889	3358	42	75.51	0.5	8642 *	NA	VA	O
23-Jan-02	4	8710019	4072	28.05	46.57	0.4	2508 *	NA	TX	B
23-Jul-01	1	2445215	1253	42	68.57	0.4	4947 *	NA	FL	C
28-Feb-02	4	7118185	4326	28.05	40.05	0.2	8990 *	NA	MA	C
1-Apr-02	12	7839988	38907	28.05	52.93	0.4	3042 *	NA	TX	O
5-Dec-01	7	6582288	10519	28.05	126.59	0.4	6582 *	NA	LA	B
7-Nov-01	3	5028081	3588	28.05	49.06	0.4	812 *	NA	TX	C
11-Dec-01	9	5724714	10225	20.27	45.73	0.4	4871 *	NA	FL	A

15-Oct-01	7	4418019	20676	46.32	95.42	0.7	4357 *	NA	TN	C
17-Jan-02	7	8820460	7895	26.05	52.85	0.4	4983 *	NA	FL	C
18-Jan-02	11	8374809	13069	46.32	96.7	0.7	5557 *	NA	CA	C
23-Aug-01	11	3275881	11268	26.05	51.85	0.4	284 *	NA	GA	B
2-Apr-02	8	7784013	9823	26.05	82.87	0.4	2677 *	NA	CA	B
17-Apr-02	10	8118754	12908	27.82	58	0.4	1528 *	NA	IL	B
18-Jul-01	0	3016220	2	26.05	50.25	0.4	960 *	NA	NC	B
14-Sep-01	-1	3923635	11	26.05	53.82	0.5	4686 *	NA	FL	B
10-Jan-02	6	8172475	9466	26.05	50.7	0.4	3567 *	NA	TX	B
30-Oct-01	4	4792184	7052	26.05	63.03	0.4	4989 *	NA	FL	C
26-Mar-02	4	7657890	6158	26.05	51.05	0.4	4546 *	NA	TX	C
27-Mar-02	4	7884997	5809	26.05	57.89	0.5	4434 *	NA	TX	C
12-Dec-01	6	8177909	10712	26.05	59.8	0.5	5805 *	NA	AR	C
10-Sep-01	4	4387464	2967	0	0	0	6042 *	NA	TX	C
13-Oct-01	6	4443119	6755	26.05	50.57	0.4	839 *	NA	SC	B
26-Apr-02	9	8287282	9534	26.05	97.35	1	5518 *	NA	CA	B
27-Aug-01	1	3361581	401	26.05	52.62	0.4	4647 *	NA	FL	C
5-Jul-01	4	2220080	5123	26.05	51.27	0.4	214 *	NA	GA	B
7-Sep-01	7	4858817	12486	26.05	49.85	0.4	6033 *	NA	AR	C
4-Mar-02	13	7243889	18004	26.05	50.41	0.4	4545 *	NA	TX	C
24-Sep-01	8	3879634	12370	26.05	52.39	0.4	2091 *	NA	TX	B
25-Sep-01	8	3945756	13305	26.05	66.17	0.6	448 *	NA	GA	B
20-Dec-01	14	6022111	32281	26.05	47.39	0.4	6480 *	NA	LA	B
17-Oct-01	3	5015625	4912	26.05	60.15	0.4	6027 *	NA	MO	O
2-May-02	19	6436371	14016	26.05	55.85	0.4	7923 *	NA	CA	B
19-Oct-01	1	4548858	647	26.05	51.73	0.4	4590 *	NA	TX	C
17-Jul-01	2	2721149	1461	26.05	64.59	0.4	3916 *	NA	NV	B
2-Aug-01	3	2783821	3017	26.05	53.47	0.4	4807 *	NA	FL	C
10-Dec-01	5	5884457	5709	26.05	62.62	0.4	2417 *	NA	TX	C
17-Aug-01	2	3117056	2413	46.32	91.06	0.7	3073 *	NA	FL	C
14-Dec-01	4	5918343	7756	26.05	50.07	0.4	409 *	NA	GA	B
11-Jul-01	1	2348447	516	26.05	55.04	0.4	7648 *	NA	CA	B
4-Apr-02	13	7816722	17246	26.05	59.24	0.4	7706 *	NA	HI	B
10-Apr-02	10	8290043	7832	26.05	51	0.4	6886 *	NA	TX	B
21-Feb-02	12	7074709	16368	46.32	66.16	0.6	2417 *	NA	TX	B
18-Jul-01	4	2536369	6469	26.05	66.23	0.4	5555 *	NA	CA	C
23-Aug-01	7	3358124	8816	26.05	57.82	0.4	3667 *	NA	CA	C

20-Mar-02	8	7559172	15858	26.05	54.05	0.4	20328 *	NA	AZ	a
8-Mar-02	10	7309845	17789	26.05	52.85	0.4	2488 *	NA	TX	a
19-Jan-02	7	6372057	14414	26.05	46.62	0.3	4807 *	NA	FL	c
10-Oct-01	4	4304342	1473	26.05	51.05	0.4	1071 *	NA	NC	c
20-Apr-02	11	8151223	12159	26.05	61.05	0.4	1071 *	NA	NC	c
6-Aug-01	1	3024384	435	26.05	51.05	0.4	4410 *	NA	TX	a
7-Jul-01	1	2328163	250	26.06	90.54	1	6192 *	NA	TX	b
25-Mar-02	6	7625173	13947	26.06	59.3	0.5	2511 *	NA	TX	c
30-Nov-01	7	5458858	10741	26.05	74.39	0.5	2624 *	NA	CA	c
20-Sep-01	0	4103538	98	26.05	77.8	0.8	1472 *	NA	TX	b
26-Oct-01	8	4720518	7448	48.32	110.63	1	4845 *	NA	FL	c
5-Apr-02	14	7870316	28715	28.05	52.11	0.4	6947 *	NA	TX	c
8-Jan-02	10	8139984	11723	28.05	40.89	0.2	869 *	NA	CA	a
19-Feb-02	12	6884560	16284	28.05	52.34	0.4	472 *	NA	GA	c
18-Jan-02	15	6551167	31116	44.17	73.18	0.4	7848 *	NA	CA	a
1-Aug-01	0	2963089	4	26.05	50.83	0.4	877 *	NA	SC	a
5-Jul-01	1	2723398	622	120.14	152.48	0.8	4834 *	NA	GA	c
18-Feb-02	9	6979993	9013	26.05	61.48	0.6	7869 *	NA	NV	a
13-May-02	13	8682862	15798	26.05	51.05	0.4	1071 *	NA	NC	c
13-Nov-01	2	5283847	3431	26.05	51.85	0.4	6192 *	NA	TX	c
10-Jul-01	3	2283511	1522	26.05	48.88	0.4	2403 *	NA	TX	b
19-Sep-01	3	3981848	3197	48.32	91.73	0.8	5401 *	NA	CA	c
25-Mar-02	8	7804283	15853	26.06	61.86	0.4	4892 *	NA	FL	c
15-Mar-02	11	7447982	10850	26.05	87.82	0.8	5563 *	NA	CA	b
17-Nov-01	3	5304003	3489	26.05	102.57	1.2	4039 *	NA	FL	c
10-Sep-01	6	4083702	7048	26.05	41.71	0.3	7016 *	NA	TX	c
12-Oct-01	3	4373214	3321	26.05	45.27	0.3	2198 *	NA	OH	a
9-Jul-01	1	2247661	389	26.05	66	0.8	4481 *	NA	TX	a
9-Mar-02	7	7305854	13458	26.05	50.25	0.4	960 *	NA	NC	a
17-Jan-02	4	6384104	4884	27.92	50.75	0.5	1777 *	NA	IL	b
12-Nov-01	8	5137237	13698	26.05	61.81	0.8	6481 *	NA	LA	a
18-Mar-02	10	7535389	12098	26.06	39.84	0.2	20323 *	NA	AZ	c
8-Apr-02	11	7885780	11198	26.05	96.08	1.2	1028 *	NA	NC	c
30-Aug-01	1	3468528	625	26.05	51.13	0.4	4158 *	NA	LA	c
13-Nov-01	3	5181101	2728	26.05	51.44	0.4	4822 *	NA	FL	c
15-Feb-02	11	7139174	10532	48.32	109.21	1	4498 *	NA	TX	c
1-May-02	12	8344764	33072	26.05	64.88	0.8	1472 *	NA	TX	c

2-Nov-01	2	4976737	2550	43.34	82.50	0.7	2874 *	NA	TX	c
17-Nov-01	9	5775242	11564	26.05	64.57	0.6	1625 *	NA	FL	a
20-Mar-02	7	8467229	5712	26.05	57.09	0.4	5476 *	NA	CA	c
16-Jul-01	0	2835079	2	26.05	50.25	0.4	960 *	NA	NC	a
20-Feb-02	9	7050124	13041	26.05	106.11	0.4	4480 *	NA	TX	a
16-Nov-01	6	5154766	4268	26.05	51.53	0.4	2232 *	NA	OH	c
14-Sep-01	1	4045134	623	26.05	51.85	0.4	6192 *	NA	TX	c
11-Jan-02	9	6485454	12653	48.32	80.70	0.7	4822 *	NA	FL	c
1-Nov-01	6	4973837	5840	26.05	64.11	0.8	1664 *	NA	CA	c
31-Jul-01	3	2666767	3092	42	56.62	0.2	5550 *	NA	CA	a
15-Nov-01	1	5151219	688	26.05	53.16	0.4	543 *	NA	TX	b
8-Apr-02	8	7855216	14120	26.05	49.94	0.4	290 *	NA	GA	a
27-Sep-01	5	3983957	6841	26.05	57.03	0.5	5965 *	NA	MS	b
23-Nov-01	6	5304806	8330	26.05	79.05	0.8	4402 *	NA	TX	b
26-Jan-02	4	6708406	7146	26.05	54.13	0.4	1665 *	NA	CA	b
8-Oct-01	5	4306403	6935	26.05	66.10	0.6	1695 *	NA	CA	b
27-Dec-01	9	5866695	19669	26.05	58.17	0.5	4999 *	NA	FL	c
23-Oct-01	7	5031205	15006	26.05	39.22	0.2	2091 *	NA	TX	b
9-Apr-02	11	7896821	11352	26.05	55.68	0.4	5550 *	NA	CA	a
12-Jul-01	4	2382823	3052	42	66.44	0.4	417 *	NA	AL	a
8-Feb-02	18	6783873	31170	26.05	80.85	0.8	2486 *	NA	TX	a
16-Jan-02	7	6358273	11026	26.05	57.83	0.4	31 *	NA	VA	c
28-Feb-02	9	7157793	13920	26.05	137.29	1.4	31 *	NA	VA	b
19-Feb-02	9	6969930	13057	26.05	53.25	0.4	2753 *	NA	LA	a
25-Jan-02	6	6952067	6923	26.05	62.08	0.6	7782 *	NA	CA	a
4-Feb-02	6	6731174	5677	26.05	51.05	0.4	1071 *	NA	NC	a
14-Jul-01	1	2364580	510	42	66.48	0.2	3250 *	NA	CA	a
21-Mar-02	10	7577139	14357	26.05	52.55	0.4	4990 *	NA	FL	c
1-Aug-01	3	2751250	2548	26.05	50.41	0.4	4545 *	NA	TX	c
18-Sep-01	2	3785299	2417	26.05	106.75	1.2	5379 *	NA	CA	b
13-Nov-01	7	5228595	7312	26.05	79.36	0.9	6481 *	NA	LA	c
3-Jan-02	7	6505426	12300	26.05	54.48	0.4	1440 *	NA	NV	c
18-Oct-01	5	4490656	16924	26.05	50.67	0.4	6529 *	NA	AL	c
6-Sep-01	4	3596212	3258	26.05	49.58	0.4	20455 *	NA	TX	c
20-Dec-01	9	5852810	12242	26.05	49.58	0.4	20455 *	NA	TX	c
2-Apr-02	12	7862076	18107	26.05	52.93	0.4	3042 *	NA	TX	c
1-Mar-02	8	7190573	5964	26.05	48.77	0.4	4127 *	NA	LA	c

11-Oct-01	2	4386647	1292	26.05	55.01	0.4	5598 *	NA	CA	c
6-Nov-01	8	4963256	8278	46.32	102.56	0.8	13569 *	NA	TX	c
26-Sep-01	8	4045133	3159	26.05	51.85	0.4	6182 *	NA	TX	c
6-Aug-01	6	2842906	9197	20.27	56.29	0.4	3921 *	NA	CA	a
27-Dec-01	8	5859667	18512	26.05	88.01	1	5985 *	NA	MS	a
27-Dec-01	11	6019011	12220	26.05	53.06	0.4	4820 *	NA	FL	a
12-Mar-02	13	7395177	14891	26.05	53.06	0.4	4820 *	NA	FL	a
25-Jul-01	0	2674216	21	47.78	91.09	0.6	5512 *	NA	CA	a
11-Feb-02	6	6841064	13360	26.05	45.77	0.4	2919 *	NA	KY	c
19-Dec-01	4	5883170	3306	26.05	53.44	0.4	2923 *	NA	TX	c
23-Mar-02	11	6352407	18516	26.05	52.36	0.4	4473 *	NA	TX	c
1-Feb-02	12	6892779	27293	26.05	69.33	0.4	7742 *	NA	CA	b
29-Dec-01	9	6013934	10112	26.05	53.21	0.4	2459 *	NA	TX	b
23-Apr-02	18	8196416	21775	20.27	49.14	0.4	5312 *	NA	CA	e
30-Nov-01	7	6485878	18521	26.85	53.91	0.4	243 *	NA	GA	o
13-Nov-01	6	5082687	9790	26.05	109.15	0.4	549 *	NA	TX	c
20-Aug-01	1	3322489	416	26.05	52.35	0.4	3573 *	NA	GA	c
7-Nov-01	6	5082705	8387	26.05	52.35	0.4	487 *	NA	GA	o
12-Dec-01	6	5839909	8429	26.05	52.63	0.4	4223 *	NA	CA	a
18-Feb-02	9	6998516	15515	26.05	53.44	0.4	4437 *	NA	TX	a
3-Oct-01	5	4143586	5716	26.05	49.51	0.4	3632 *	NA	GA	b
11-Feb-02	11	6844039	14841	26.05	51.05	0.4	4410 *	NA	TX	a
29-Aug-01	6	3363213	8482	46.32	127.81	1.1	5550 *	NA	CA	o
29-Mar-02	13	7737439	18389	26.05	51.86	0.4	4458 *	NA	TX	a
3-Jan-02	5	6691905	7841	26.05	48.35	0.4	6744 *	NA	NC	a
2-Jan-02	2	6365771	2928	46.32	66.44	0.7	2496 *	NA	OK	c
4-Dec-01	1	5638388	149	26.05	65.49	0.6	4443 *	NA	TX	c
29-Jan-02	11	6908792	8237	26.05	67.53	0.4	5412 *	NA	CA	c
12-Sep-01	7	3736738	17579	26.05	51.91	0.4	402 *	NA	GA	a
19-Dec-01	3	6176889	2597	26.05	60.63	0.5	6471 *	NA	CA	a
14-Dec-01	2	5815516	1440	46.32	92.17	0.6	5936 *	NA	CA	b
25-Mar-02	13	7901140	29448	26.05	49.05	0.4	3476 *	NA	FL	b
18-Feb-02	5	7192609	6719	26.05	51.11	0.4	4927 *	NA	GA	a
30-Mar-02	17	7713562	19811	26.05	55.45	0.4	5520 *	NA	CA	c
25-Jan-02	13	6516889	25001	26.05	52.69	0.4	5439 *	NA	CA	a
26-Oct-01	4	4689483	4810	26.05	51.24	0.4	8934 *	NA	NC	c
19-Dec-01	7	5858789	7528	26.05	94.83	0.9	6536 *	NA	CA	b

30-Jul-01	2	3828858	879	42	67.71	0.4	6042 *	NA	TX	c
31-Jan-02	8	6656864	5703	46.32	106.46	0.8	2448 *	NA	TX	a
10-Jul-01	4	2449007	4102	26.05	51.7	0.4	4421 *	NA	TX	a
28-Feb-02	9	7177307	12825	26.05	60.53	0.5	20323 *	NA	AZ	o
5-Dec-01	14	5622857	25555	26.05	96.23	1.1	4498 *	NA	TX	o
29-Dec-01	5	6476849	10855	26.05	39.2	0.2	472 *	NA	GA	o
19-Sep-01	2	3618382	2307	26.05	47.03	0.4	6558 *	NA	LA	b
20-Oct-01	2	4614386	3570	26.05	52.62	0.4	2417 *	NA	TX	a
7-Feb-02	2	6780435	2287	26.05	50.7	0.4	3567 *	NA	TX	a
18-Apr-02	13	8087127	18025	26.05	65.78	0.8	3878 *	NA	NC	c
30-Jul-01	0	3849805	28	46.32	115.1	0.8	5536 *	NA	CA	a
19-Oct-01	6	4728006	9645	26.05	52.11	0.4	8947 *	NA	TX	o
26-Dec-01	1	7248802	935	26.05	50.18	0.4	8029 *	NA	MO	b
16-Oct-01	8	4623848	9722	26.05	56.62	0.4	5536 *	NA	CA	a
27-Dec-01	8	5850830	3500	26.05	39.34	0.2	2417 *	NA	TX	b
24-Sep-01	2	4080767	3080	26.05	54.64	0.4	5456 *	NA	CA	a
7-Jan-02	5	6090079	7684	26.05	62.35	0.4	3573 *	NA	GA	a
15-Feb-02	6	6947868	3479	26.05	51.11	0.4	4827 *	NA	GA	a
20-Jul-01	3	2469423	3817	26.05	39.34	0.2	2417 *	NA	TX	c
25-Oct-01	3	5980509	4863	26.05	80.68	0.9	2414 *	NA	OK	b
16-Jan-02	8	6307159	10770	26.05	52.35	0.4	487 *	NA	GA	b
9-Nov-01	5	4942859	5863	26.05	45.08	0.3	1057 *	NA	NC	o
1-May-02	8	8434256	12169	26.05	62.17	0.7	6576 *	NA	MS	a
4-Oct-01	0	4422583	90	26.05	51.19	0.4	5616 *	NA	TN	a
10-Oct-01	2	4338700	3770	26.05	53.15	0.4	543 *	NA	TX	o
7-Dec-01	3	5801608	3272	26.05	52.62	0.4	2417 *	NA	TX	c
24-Sep-01	4	4221239	6182	26.05	63.77	0.8	10063 *	NA	AZ	c
17-Aug-01	0	3775901	88	20.27	48.67	0.4	2479 *	NA	TX	a
1-May-02	16	6374355	11967	26.05	56.4	0.4	2557 *	NA	CA	a
24-Oct-01	6	4788388	14742	43.34	68.18	0.4	5892 *	NA	AL	c
11-Jul-01	1	2316884	547	26.05	52.07	0.4	1196 *	NA	LA	b
8-Oct-01	1	4341438	1898	26.05	52.62	0.4	2417 *	NA	TX	b
29-Nov-01	4	5429380	8721	43.34	69.64	0.4	3573 *	NA	GA	c
16-Feb-02	9	6947752	11248	26.05	63.11	0.4	4908 *	NA	FL	c
10-Oct-01	1	4711612	31	26.05	52.62	0.4	2417 *	NA	TX	b
31-Jan-02	11	6809856	25554	26.05	51.09	0.4	976 *	NA	SC	a
7-Dec-01	9	6020368	17742	26.05	80.6	0.8	5432 *	NA	CA	b



4-Apr-02	7	7987488	17183	28.05	52.44	0.4	277 *	NA	GA	b
21-Jul-01	0	2870123	50	26.05	55.83	0.4	3893 *	NA	CA	a
18-Jan-02	8	6378526	13333	26.05	58.75	0.4	7853 *	NA	CA	c
18-Mar-02	10	7605880	20097	26.05	117.75	1.2	5538 *	NA	CA	c
16-Feb-02	11	8048855	17737	26.05	73.65	0.7	6489 *	NA	LA	a
6-Sep-01	4	4373781	18144	26.05	46.05	0.4	2386 *	NA	TX	a
23-Jan-02	6	6478296	4035	26.05	48.46	0.3	1662 *	NA	NJ	a
26-Dec-01	7	5646767	9240	26.05	43.31	0.3	612 *	NA	TX	a
3-Oct-01	6	4185789	9018	46.32	91.88	0.6	9441 *	NA	MN	c
14-Jul-01	1	2321018	167	26.05	48.04	0.4	3439 *	NA	LA	a
17-Dec-01	4	5779167	3088	26.05	50.01	0.4	3078 *	NA	MI	a
27-Mar-02	17	7712813	17537	26.05	78.03	0.7	5401 *	NA	CA	a
14-Aug-01	1	4214209	380	26.05	42.89	0.4	5881 *	NA	TN	a
3-Dec-01	4	5474883	3885	67.79	113.79	0.8	8990 *	NA	MA	c
1-Aug-01	3	2744388	8068	26.05	54.85	0.4	2478 *	NA	TX	b
27-Dec-01	7	6003823	18000	26.05	81.22	0.6	20323 *	NA	AZ	c
18-Oct-01	8	4499850	19659	59.96	104.87	0.8	20839 *	NA	NJ	b
20-Sep-01	2	4522589	2237	26.05	41.56	0.3	8088 *	NA	MO	c
25-Oct-01	5	4677257	7637	26.05	53.35	0.4	1882 *	NA	IN	a
1-Feb-02	10	7108445	15800	26.05	53.01	0.4	3820 *	NA	TN	c
12-Jul-01	1	2537578	207	26.05	77.64	0.8	6182 *	NA	TX	a
7-Dec-01	10	6483142	11147	26.05	80.82	0.4	3867 *	NA	NY	c
17-Oct-01	4	4483141	9687	26.05	56.12	0.4	8017 *	NA	IL	a
5-Dec-01	7	5680370	8851	26.05	48.73	0.4	9623 *	NA	MI	a
30-Jun-02	7	6613122	10948	26.05	58.57	0.4	7800 *	NA	CA	a
30-Oct-01	2	4789373	858	46.32	76.92	0.6	772 *	NA	OK	c
4-Mar-02	10	7211307	8979	27.82	53.38	0.4	1533 *	NA	IL	a
11-Jan-02	11	6198942	23508	26.05	59.29	0.5	2797 *	NA	IN	a
3-Jul-01	6	3645110	7368	26.05	45.9	0.4	3768 *	NA	SC	a
6-Sep-01	2	3595851	1007	46.32	60.11	0.2	20323 *	NA	AZ	c
18-Dec-01	6	5818503	5167	26.05	50.08	0.4	6107 *	NA	WI	a
21-Mar-02	7	7579311	8080	20.27	41.39	0.4	6883 *	NA	AR	b
31-Jul-01	9	2741570	16288	55.59	120.09	1	1468 *	NA	IN	a
1-Aug-01	0	2892931	60	26.05	71.58	0.8	1789 *	NA	MS	a
7-Nov-01	4	4883829	4490	26.05	54.38	0.4	5534 *	NA	NV	a
18-Dec-01	6	5877783	17282	26.05	46.74	0.3	20323 *	NA	AZ	c
16-Nov-01	3	5197998	3133	26.05	58.12	0.4	8559 *	NA	OR	c

18-Jan-02

7

6699704

6863

25.05

71.52

0.8

7809 \*

NA

NV

o















12001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
12001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
12001  
11001  
11001  
11001  
11001  
11001  
11001  
12001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001  
11001







11001

RC004-011 00617

TECH\_TXT1

DRIVER SEAT BELT DOESNT BUCKLE BROKEN REPLACED BUCKLE AND RETESTED OK  
5326 01 61203 R R DRIVER SEAT ACESS REPLACED DRIVER SEAT BELT BUCKLE BINDING  
8226 LOOSE REPLACE LOOSE LF SEAT BELT BUCKEL  
MTIME TO DIAG BELT BUCKLE NOT WORKING CORRECTLY REPLACED DRIVERS  
5122 TEST AND REPLACE DRIVER SIDE SEATBELT CC 42  
1012 FOUND SERAT BELT WOULD NOT STAY BUCKLED R&R DRIVER SEAT REPLACED SEAT BELT BUCKLE  
REPLACE THE DRIVERS SEAT BELT BUCKLE UNLATCHING AT TIMES WHILE DRIVING RETEST RAISE SEAT TO GAIN ACCESS TO SEAT BELT  
REPLACED SEATBELT ASSY  
TECHNICIAN VERIFIED CONCERN. TECHNICIAN REPLACED BOTH FRONT SEAT BELT BUCKLES AND VEHICLE TESTED GOOD.

DIAGNOSED AND TESTED TO VERIFY COMPLAINT,R'R DR IVER SIDE SEAT BUCKET TO REMOVE AND REPLACE SEA T BELT BUCKLE  
6128 STICKING WARR REPAIR STICKING RELEASE BUTTON ON LEFT MIDDLE ROW SEAT BELT BUCKLE.  
LOOSE SEATBELT ASSEMBLY FRONT REPLACE

SEATBELT ASSEMBLY FRONT REPLACE

DIAG AND RR SEAT BELT BUCKLE

33327 61203,42 DOES NOT OPERATE PROPERLY R R DRIVER SEAT REPLACED SEAT BELT BUCKLE TEST,OK  
1 R&R SEAT BELT BUCKLE.

DEFECTED RT FT SEAT BELT BUCKLE 1L7Z 7891203 BAA CC01 REPLACED RT FT SEAT BELT BUCKLE ALL SYSTEMS OK  
VERIFIED CUSTOMERS CONCERN, PERFORMED INSPECTION. FOUND BUCKLE SPRING BROKEN. REPLACED BUCKLE, RETEST OK...

SEAT BELT DEFECTIVE REPLACED SEAT BELT BUCKLES

REPL LEFT SEATBELT BUCKLE DUE TO COMING APART

3391 DRIVERS SEAT BELT DOES NOT LATCH AT TIMES. R R DRIVERS SEAT TO GAIN ACCESS TO SEAT BELT ANCHOR. REMOVE AND REPLA  
INOP SEATBELT ASSEMBLY FRONT REPLACE

VERIFIED CONCERN RETEST BUKCKLES WITH RECALL TEST BOTH BUCKLES PASS BUT DRIVERS WILL UNHOOK APROX 1 OUT OF 10 TIMES

14364 INSPECT AND VERIFY CONCERN DRIVERS EAT BELT BUCKLE UNBUCKLES WHILE DRIVING. REPLACE B7UCKLE AND VERIFY REPAIR..I

SEATBELT WONT BUCKLE REPLACED SEATBELT ASSY.

CC 42 A65 7861203 REMOVED DRIVERS SIDE SEAT AND REMOVED BUCKLE AND INSTALLED NEW AND RETESTED OK

SEATBELT INOP

R AND R SEAT T80 REPLACE DRIVERS SEAT BELT

REMOVED SEAT BUCKLE DRIVERS SIDE REPLACED WITH NEW REMOVED SEAT TO REACH BOTTOM OF SEAT REPLACED BUCKLE ON P,

42 REPLACE DRIVERS SEAT BELT BUCKLE WONT LATCH

16901 BOTH FRONT SEAT BELT BUCKLES WILL NOT STAY LATCHED. REPLACED BOTH FRONT SEAT BELT BUCKLES. CC 42 QUALITY CHECK

BUCKLE PASSED, 01821 COMES UNDONE INTERMITTENTLY REPLACED BUCKLE

14584 DRIVERS SEAT BELT BUCKLE IS HARD TO LATCH AND UNLATCH REPLACED BUCKLE AND RETESTED OK.

REPLACED LEFT FRONT SEAT BELT 61203

BINDING REPLACED LEFT SIDE SEAT BELT BUCKLE

1 REPLACED SEAT BELT ASSEMBLY. RETEST. O.K.  
SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE  
INSPECTED AND REPLACE BOTH FRONT SEATBELTS  
8780 DEFECTIVE SEAT BUCKLE 42 R AND R SEAT IN ORDER TO ACCESS SEAT BUCKLE. REPLACED SEAT BUCKLE AND TESTED. WORKS FINE  
10788 LEFT FRT SEAT BELT POPS LOOSE WHILE DRIVING. REMOVE SEAT AND REPLACE BUCKLE AND REINSTALL ALL PARTS AND VERIFY  
REPLACED DRIVERS SIDE FRONT SEAT BELT BUCKLE ASSEMBLY  
802 DOES NOT OPERATE PROPERLY 01S210 0.4 ADMIN 0.1 0.5HRS LG R R DRIVERS SEAT BELT BUCKLE, TESTED, OK. REMOVED DRIVERS :  
REPLACED SEAT BELT BUCKLE  
REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLY 61203 CAUS 42  
1472 01 REPLACED DRIVERS SEAT BELT BUCKLE WOULD NOT STAY LATCHED TECH 2625 M.D  
REPLACE D S SEAT BELT BUCKLE  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
BELT BUCKLE BELT BUCKLE BROKEN REPLACED, EXTRA TIME TO REMOVE SEAT TO GAIN ACCESS  
CONFIRMED CUSTOMERS COMPLAINT. REPLACED DRIVERS SEAT BELT BUCKLE FOR NOT LATCHING.  
NA REMOVE AND REINSTALL SEAT TOP REPLACE BUCKLE  
6133 BUCKLE LATCH 42 WARR VERIFIED CONCERN. REMOVED LT FR SEAT FROM VEHICLE FOR ACCESS TO REPLACE LT FR SEAT BELT BL  
17098 DR LF SEAT BELT INOP W CC42 INSP AND RR DR SEAT TO ACCESS SEAT BELT BUCKLE ASSY REPLACED LF DR SEAT BELT BUCKLE /  
885 LEFT FRONT SEAT BELT WILL NOT LATCH. ACCESS LEFT FRONT SEAT AND REPLACED BUCKLE AND HARNESS ASSEMBLY. 1.0 CC 42 Q  
VERIFIED, NEED NEW BUCKLE,  
SEAT BELT COMES APART REPLACE BUCKLE  
INOPERATIVE SEAT BUCKLE.  
20506 INOP W 42 REMOVE DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE ASY. INOP  
SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELT BUCKLES  
REMOVE FRONT SEAT AND REPLACE BUCKLE  
SEATBELT ASSEMBLY FRONT REPLACE  
SEATBELT BINDING  
CC42 DOES NOT OPERATE PROPERLY MILES IN 2662 MILES OUT 2664 TESTED DRIVERS SEATBELT BUCKLE WITH RECALL TESTED FOUND 7  
BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE  
FAIL TO LOCK SEAT CLIP R R SEAT BUCKLE ASSY  
10000 CP 61384 CC 38 PART REF. 892 61384A 0.4 0.4 REPLACE LH SEAT BELT BUCKLE WRONG COLOR  
S40 DRIVER SEAT BELT BUCKLE NOT LATCHING BELT REPLACE BUCKLE AND RETEST WORKING PROPERLY NOW  
CCG28 CHECKED OUT REPLACED DRIVERS SEAT BELT BUCKLE.  
INSPECT AND REPLACE LEFT SEATBELT ASSEMBLY.  
WOULD NOT HOLD REPLACE DRIVERS SIDE BUCKLE  
THE ORIGINAL SEAT BELT BUCKLE IS COMING UNLATCHED WHILE THE CUSTOMER WAS DRIVING I REPLACED IT WITH A NEW ONE.  
REPLACED SEAT BELT BUCKLE  
TEST AND REPLACE SEATBELT BUCKLE

CC.01 BROKEN BASIC#61203 REPLACE L F SEAT BELT

REPLACED FRONT 2 SEAT BELT BUCKLES

REPLACED SEATBELT BUCKLE

CCF12 REPLACE SEATBELT BUCKLES

SEAT BELT POPS OUT REFL DRV SEAT BELT BUCKLE, POPS OUT WHILE DRIVING, NO LIGHT

COMES UNLATCHED SEATBELT ASSEMBLY FRONT REPLACE

INSPECT SEAT BELTS AND REPLACE ONE SEAT BELT

REPLACE SEATBELTS WILL NOT LATCH

6887 SEAT BELT LATCH INOP 81172A .4 REPLACED SEAT BELT LATCH

REPLACE SEATBELT WILL NOT LATCH PROPERLY

1 TESTED SEAT BELTS AND FOUND BOTH FRONT BUCKLES FAILED REPLACED BOTH BUCKLES, POWER SEATS BUCKETS

TEST DRIVER SEATBELT BUCKLE NOT LATCHING PROPERLY, REPLACE

SEAT BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE

REMOVED AND REPLACED SEAT BELT BUCKLE TESTED OK

BUCKLE BINDING

REPLACED SEATBELT BUCKLES.

OK OUT R&R DRIVER SEAT BELT BUCKLE

REPLACED DRIVERS SIDE SEAT BELT BUCKLE

VERIFIED CONCERN. INSPECT FOUND DRIVERS BUCKLE FAULTY. REPLACED BUCKLE AND RECHECK, OK.

REMOVE AND REPLACE DRIVER SIDE SEAT BELT LATCH

TECHNICIAN #127 VERIFIED CONCERN REPLACED S O SEAT BUCKLE

BUCKLE INOP REPLACED BOTH FRONT SEATBELT BUCKLES

CHECK AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE

INSTALLED SOP DRIVERS SEAT BUCKLE RECEIVER VERIFIED REPAIR

BUCKLE & SWITCH BAD SEATBELT ASSEMBLY FRONT REPLACE

11408 REPLACE DRIVE SIDE SEAT BUCKLED

SEATBELT WONT LATCH SEATBELT ASSEMBLY FRONT REPLACE

REPLACED BOTH FRONT SEATBELT BUCKLES

REPLACE DRIVERS FRONT SEAT BELT

LEFT FRONT SEAT BELT BUCKLE NOT LATCHING CC 42 BP#7881203 BUCKET SEATS CHECKED OPERATION OF LEFT FRONT SEAT BELT BUC

REPLACED DRIVERS SEATBELT LATCH FOR NOT LOCKING CC01 FP7881203

1871 REPLACE DRIVERS SIDE BELT BUCKLE WILL NOT STAY BUCKLED

REPLACED LEFT FRONT SEAT BELT

580 LEFT FRONT SEAT BELT LATCH NOT OPERATING PROP 42 MT61203 VERIFIED CUSTOMER COMPLAINT THAT THE SEAT BELT LATCH ON

REPLACE DRIVERS SIDE SEAT BELT REPLACE SEAT BELT

SEAT BELT COMES LOOSE INTERMITTENTLY, REPLACED LEFT FRONT SEAT BELT ASSEMBLY. RECHECKED, OK.



VERIFIED CONCERN REPLACE SEAT BELT.  
VERIFIED BELT COMES UNHOOKED WAS REPLACED 10 26 01.....RO #44848 INSTALL NEW SEAT BELT, RETEST, OK  
REPLACE LT FRT SEATBELT ASSY  
REPLACED DRIVER SIDE SEAT BELT BUCKLE  
TESTED AND FOUND BAD LATCH, REPLACED LATCH ASSEMBLY.  
CHECK SEAT BELT OPERATION PERFORM DIAG FOUND LATCH NAT LATCHING REPLACE SEAT BELT LATCH RETEST OPERATION OK  
8881 INSTALLED NEW DRIVERS SEAT BELT BUCKLE CANT PERFORM 01821 RECALL W OUT TOOL D S BUCKLE WOULDNT LATCH  
8885 7881203 BUCKLE, 42 DNOP CONFIRMED CUST CONCERN OF DRIVER SIDE SEAT BELT BUCKLE NOT HOLDING. REPLACED LF BUCKLE &  
HARD TO BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY.  
D S SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE  
11 SEAT BELT NOT LATCHING 4 DR SEAT BELT BUCKLE NOT LATCHING. ORDERED NEW BUCKLE. INSTALLED PROBLEM FIXED  
RAN DIAG FOUND SEAT BELT WOULD NOT LATCH REPLACE SEAT BELT ASSY  
SEATBELT REPLACED LEFT FRONT BELT  
TESTED; DRIVER SIDE FAILED  
09 7881203 LEFT FRONT SEAT ACCESS TO REPLACE DRIVERS SEAT BELT BUCKLE THAT  
SEAT BELT BUCKLE INOP REPLACE DRIVER SEAT BELT BUCKLE  
INOP DRIVERS SIDE SEAT BELT BUCKLE MT TO REPL DRIVERS SIDE SEAT BELT BUCKLE  
REPLACE LEFT FRONT SEATBELT FEMALE INOP  
REMOVE DRIVE SEAT BELT BUCKLE TO REPLACE (POPPE D LOOSE WHILE DRIVING  
REPLACED DRIVER SIDE SEAT BELT BUCKLE CAME UNLATCH WHEN DRIVING.  
CK AND REPL DCTVE BUCKLE ASSY, REASSEMBLE AND RECK, OK  
11849 SOP PART 0.8MT REMOVED AND REPLACED FEMALE SEAT BELT BUCKLE AFTER DUPLICATING CONCERN RETESTED QUALITY OK  
R&R SEAT BELT BUCKLE  
FAULTY BELT BUCKLE L H SEAT BELT BUCKLE REPLACED  
DIAG. AND REPLACED SEAT BELT BUCKLE ON DRIVER SIDE  
REPLACED SEAT BELT LATCH.  
REPLACE SEAT BELT BUCKLE  
REPLACED BROKEN BUCKLE  
4064 CC 42, DRIVERS SEATBELT BUCKLE NOT WORKING PROPERLY, REPLACED DRIVERS SEATBELT BUCKLE, SYSTEM OK, QUALITY CHEC  
3388 INOP LATCH W VERIFY CONCERN, INSTALL DRIVERS SICE SEATBELT LATCH ASSEMBLY OK M TIME TO REPLACE PART, NO LABOR OP  
REPLACED LATCH ASSY  
42 TECH 14507 MO 1253 REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE  
VERIFY AND REPLACE BUCKLE 8820  
REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE  
10621 SOP PART CAME IN, REMOVED DRIVERS SEAT AND REPLACED DRIVERS SEAT BELT LATCH AND RETESTED O.K. WARRANTY CC 42 ( )  
CHECK FOR LEFT FRONT SEAT BELT FOR NOT LATCHING PROPERLY. CONCERN VERIFIED. REPALCED LEFT FRONT SEAT BELT. POST TEST  
REPLACE SEAT BELT

REPLACE BOTH FRONT SEATBELT BUCKLE REPLACE BOTH FRONT SEATBELT BUCKLES  
 INOP SEATBELT ASSEMBLY FRONT REPLACE  
 INSPECTED AND REPLACE BOTH BUCKLE ENDS DUE BUCKLE NOT LATCHING AND RETESTED OK  
 NA REPLACED DRIVERS SIDE SEATBELT BUCKLE MILEAGE IS CORRECT ENTERED INCORRECTLY AT SPALDING FORD ON 0:  
 LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH. REPLACED SEAT BELT BUCKLE NOW OKAY. 04 03 08.21 08.49.  
 REPL DRIVERS SEAT BELT BUCKLE WPI ADD ON AUTHO BY AS  
 REPLACED BUCKLE  
 REPLACE LEFT SEAT BELT BUCKLE NO TIME LISTED  
 REPLACED DRIVERS SEATBELT ASSY  
 INOP REPLACE DRIVERS SIDE SEAT BELT BUCKLE  
 NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE  
 5821 WARR REPLACE DRIVERS SIDE SEATBELT BUCKEL.  
 INSTALLED DRIVER SEAT BELT LATCH  
 2887 SEAT BUCKLE REPL LFT FRT SEAT BELT BUCKLE  
 REPLACED DRIVERS SEAT BELT  
 9534 81203 42 BAD SEATBELT. 61174A 0.4, 61704AC 0.8 CORRECTION: REMOVED THE SEAT TO REPLACE THE BUCKLE. NOW IT IS OPERATIA  
 VERIFY CONCERN REPLACED SEAT BELT TECH 300  
 REPL LF SEATBELT BUCKLET ASSEMBLY  
 12486 FP 81203 CC 42 MT 61203 .4 \* AUTH 3191 REPLACED THE DRIVERS SEAT BUCKLE  
 SEAT BELT BUCKEL REPLACED SETA BELT BUCKLE  
 INSTALL NEW SEATBELT IN DRIVERS SEAT NOT LATCHING PROPERLY RETEST OK C C 42  
 REPL SEAT BELT LATCH REPL SEAT BELT LATCH ASSY  
 D SIDE FRONT SEATBELT WILL NOT LATCH... VERIFIED CONCERN..DIAG AND REPLACED D SIDE FRONT SEATBELT...  
 INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE  
 14 7861203 REPLACE LEFT FRONT SEATBELT  
 REPLACE LEFT FRT SEATBELT BUCKLE  
 BAD SEAT BELT TONGUE AND ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE  
 VERIFY SEAT BELT INOP REPLACE DRIVERS SEAT BELT  
 5708 FOUND DRIVERS SEAT BELT BUCKLE TO BE COMING APART INTERNALLY. REPLACED DRIVERS SEAT BELT BUCKLE + TEST. \*\*\* QUALIT  
 2413 ERRATIC W 42 REMOVE RT AND LEFT FRONT SEATS AND REPLACE SEAT BELT BUCKLES ON BOTH SEATS,ERRATIC  
 A REPLACED R SEAT BELT BNUCKLE  
 REPLACE RECEIVER RECHECK OPERATION AND NOW OK.  
 VERIFIED, REPLACED LEFT FRONT SEAT BELT LATCH, RIGHT SIDE OK  
 RR DRIVERS SEAT TO REPLACE SEAT BELT BUCKLE WOULD NOT LATCH AT TIMES  
 16388 LOOSE REPLACE BOTH FRONT SEAT BELT BUCKELS LOOSE  
 SREPLACE LEFT FRONT SEAT BELT BUCKLE  
 INSPECTED DR SEAT BELT REPLACED REMOVED LF FR D OOR FOUND BAD REGULATOR REPLACED MOTOR AND REGU LATOR ASM WORK

R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT LATCH.  
DRVS SEAT BELT WOULD NOT LATCH AT TIMES I REPLACED THE DRVS SEATBELT AT THIS TRIME IT LATCHES AS INTENDED  
REPLACED SEAT BELT BUCKLE  
BUCKLE ASSEMBLY MALFUNCTION SEATBELT ASSEMBLY FRONT REPLACE  
SEAT BELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE  
BROKEN VERIFY CUSTOMER CONCERN. REMOVE AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE.  
250 TIME TO REPLACE DRIVERS SIDE FRONT FEMALE END OF SEAT BELT ASSEMBLY TIME TO R AND I SEAT ASSEMBLY TO GAIN ACCESS  
1 REPLACED L F SEAT BELT BUCKLE  
REPLACED SEAT BELT BUCKLE RETENTION  
98 01S21D 0.8 REPL D SIDE SEAT BELT  
7881202 CODE 89 7448 M O R I BOTH FRONT BUCKET SEATS.REPLACED BOTH FRONT SEATBELTS. RETEST PASS.  
ACCESS AND REPLACE SEATBELT BUCKLE.  
11725 SEAT BELT INOP 899A 0.2 61203 0.3 CONFIRMED CUST CONCERN INSP AND TESTED OPERATIO N OF SEAT BELTS DRIVERS BUCKLE A  
R&R DRIVER SEAT,REPL BROKEN SEAT BELT BUCKLE,RETEST.  
REPLACED SEATBELT BUCKLE AND NOW OK.  
OK AND REPLACED LEFT FRT SEAT BELT BUCKLE ASSY.  
SEAT BELT LATCHES DEFECTIVE REPLACE SEAT BELTS FRT.  
SEAT BELT NOT WORKING PROPERLY CK SEAT BELT BUCKLE NOT LOCKING IN ALL TIMES REPLACE SEAT BELT BUC  
BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT REPLACE  
3456 BROKEN 01 REPLACED LT FT SEAT BELT ASSY  
REPLACE DRIVERS SEAT BELT BUCKLE  
TEST AND REPLACE BOTH FRONT SEAT BELT BUCKLES  
INOP DIAG & VERIFY CONCERN.REPLACE DRIVERS SEAT BELT LATCH  
E REPLACED DRIVERS SEAT BELT BUCKLE  
REPLACED THE FRONT DRIVER SIDE SEAT BELT BUCKEL. THE DRIVER SIDE SEAT BLET BUCKLE WAS DEFECTIVE.  
REPLACED SEAT BELT BUCKLE WITH NEW ONE  
3321 REPLACED DRIVER SIDE SEAT BELT BUCKLE.

INOP SEATBELT ASSEMBLY FRONT REPLACE  
INSTALLED DRIVERS SEAT BELT LATCH  
DOESNTOPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE  
REPLACED DRIVERS SEAT BELT BUCKLE DUE TO LOOSE  
CHECKED OUT, R AND R DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE  
CP 7881203 OC 42 DRIVERS SIDE SEATBELT TEST SEATBELT OPERATION, REPLACED SEATBELT  
INOP SEATBELT ASSEMBLY FRONT REPLACE  
10533 SEAT BUCKLES 30 WR INSPECTED AND FOUND BOTH SEAT BUCKLES INOP. R R BOTH FRONT SEAT BUCKLES AND RIETESTED.PASS.  
33072 MT 7881203 .8 .8 REPLACED DRIVER SEAT BELT BUCKLE.

CHECK AND FOUND SEAT BELT WOULD NOT STAY LATCHED. REPLACED BUCKLE ON LEFT FRONT SEAT.

REPLACE DRIVERS SEAT BELT BUCKLE

NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

REPLACED LEFT BUCKLE

1 DIAG UPON INSP REVEALED INTER MIT NO LATCH CAUSED BY BUCKLE INTERNAL DAMAGED BROKE REPLACED BUCKLE ASMBLY & CKD F  
4268 REPLACED BELT Y

823 42 REPLACED DRIVERS SIDE SEAT BELT BUCKEL DUE TO COMING LOOSE AT TIMES

INOP SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

INSPECT AND REPLACE DRIVER SIDE SEAT BELT

REPLACE SEAT BELT BUCKLE ADDITIONAL MISC. REPAIRS

DIAG AND RIR SEATBELT

8841 REPLACE DR FT SEAT BELT

REPLACED DRIVERS SIDE BUCKLE

UNHOOKS WHILE DRIVING MTIME REPLACED DRIVERS SEAT BELT BUCKLE

FOR CUSTOMER SATISFACTION M TIME NO LABOR OPP IN MANUAL TO R & R DRIVERS SIDE SEAT BELT BUCK

TRACK ASSEMBLY FRONT SEAT REPLACE

VERIFIED CONCERN, REPLACED DRIVERS SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY , OK AT THIS TIME

SEAT BELT BROKE SEATBELT ASSEMBLY FRONT REPLACE

3062 FOUND DRVS SEAT BELT BUCKLE NOT LATCHING REMOVED AND REPLACED BUCKLE

31170 BUCKEL R, LT FT SEAT TO REPLACE SEAT BELT BUCKLE

INSPECT 7 TEST SEAT BELT BUCKLE & VERIFIED NOT WORKING PROPERLY. R&R SEAT ASSB TO GAIN ACCESS, REPLACE DRIVERS SEAT BEL

INSPECT & TEST DROVE & VERIFIED SEAT BELT LIGHT COMES ON, LAST VISIT NGS TESTING, NO CODES. NGS PIDS MONITOR WHILE MOVE IN

13057 REPLACED DRIVER SIDE SEAT BELT BUCKLE ORDERED DRIVER SEAT BELT LATCH ASSY

FOUND SEAT BELT BUCKLE DEFECTIVE REPLACED THE DRIVERS SIDE SEAT BELT

BUCKLE MALFUNCTION SEATBELT ASSEMBLY FRONT REPLACE

VERIFIED CONCERN, REPLACED BAD SEAT BELT BUCKLE.

RENEW DRIVER SEAT BELT ASSY

SEATBELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE

INSTALLED LH SEAT BELT BUCKLE. NEEDED TO REMOVE FRONT SEAT TO INSTALL NEW PART AND PUT ALL BACK

01S21 RECALL PERFORMED 01S21 RECALL PERFORMED

SEATBELT FAILED SEATBELT ASSEMBLY FRONT REPLACE

DRIVERS SEAT BELT WILL POP LOOSE REPLACE DRIVERS SEAT BELT WAITING.....

3258 42 DOES NOT OPERATE PROPERLY REPLACED L FRONT BUCKLE

12242 VERIFIED SEATBELT BUCKLE REALES ES REMOVED AND REPLACED WITH NEW ONE RETESTED NEW ONE WORKS OK

REPLACED DRIVERS SEAT BELT

SEAT BELT BUCKLE DEFECTIVE REPLACE DRIVER SIDE SEAT BELT BUCKLE

CONFIRM SEATBELTS UNBUCKLE. REPLACE BOTH FRONT SEAT BELT FEMALE ENDS. CONFIRM REPAIR. 41 81202

3158 42 REPLACED DRIVER SEAT BELT BUCKLE DUE TO COMING LOOSE AT TIMES

1 REPLACED SOP DRIVERS SEAT BELT BUCKLE ASSEMBLY

18512 R&I BAD DRIVERS FT SEAT BELT 42 7881203

12220 W TECH 598, VERIFIED CONCERN, R I DR SEAT TO GAIN ACCESS, RR BAD DR SIDE SEAT BELT BUCKLE, RETEST, ALL OPER OK AT THIS

14891 W 302 VERIFIED CONCERN. REPLACE DRIVER SEATBELT RECEIVER DUE TO INOP. RETEST, OK AT THIS TIME. QUALITY INSPECTED BY  
REPLACE BOTH FRONT SEAT BELTS.

CK & RPL DRIVERS SEAT BELT, DOES NOT WORK, RECK OK

SEATBELT BUCKLE CAME APART

REPLACED DRIVER SIDE BUCKLE

CHECKED OUT, CONFIRMED INTERMITTANT CONCERN. REPLACE DRIVERS SEATBELT ASSY. RETESTS OK

10112 42 81384A 0.4 0.4 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE

LEFT SEATBELT BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE

REMOVE SEAT ASSY. AND REPLACE SEATBELT ASSY.

BROKEN SEATBELT ASSEMBLY FRONT REPLACE

INOP SEATBELT ASSEMBLY FRONT REPLACE

REPLACED BUCKLE DUE TO NOT WORKING PROPERLY

DEFECTIVE REPLACED LF SEAT BELT BUCKLE

REPLACED SEAT BELT LATCH

REPLACE LEFT SEAT BELT BUCKLE, WILL NOT HOLD

ACCESS BOTH SEATS, REPL BUCKLES TRACK ASSEMBLY FRONT SEAT REPLACE

FOUND SEAT BELT RECIVER NOT HOLDING REPLACED AND RECHECKED OPERATION

REPLACED FRONT SEAT BUCKLE

R AND R DRIVER SEAT, REPLACE SEAT BELT WITH NEW, RAND R PASSENGER SEAT, REPLACE SEATBELT.

R&R SEAT CAPTAINS CHAIR TO REPLACE SEAT BELT AS SEMBLY, LOOSE.

X REMOVE REPLACE BELT BUCKLE

DRIVERS SEAT BELT FAILED SEATBELT ASSEMBLY FRONT REPLACE

LEFT SEAT BELT BUCKLE BINDING DG, RPLD SEAT BELT BUCKLE

CC487 REPLACED BOTH SEAT BELT BUCKLES

RF SEAT BELT WONT STAY LATCHED SEATBELT ASSEMBLY FRONT REPLACE

NO OPERATING PROPERLY REPLACE DRIVER SEAT BELT BUCKLE ASSY

19811 81172A .4 REPLACED SEAT BELT WAS POPPING OUT CC 42

SEATBELT BUCKLE INOP DIAGNOSIS REMOVED AND REPLACED LEFT FRONT SEATBELT BUCKLE.

SEATBELT RECEIVER INOP CK REPLACED DRIVERS SEATBELT BUCKLE RECEIVER

CC487 REPLACED SEAT BELT BUCKLE

REPLACED LEFT FRONT SEAT BELT BUCKLE  
CHECKED SEAT BELT LATCHES BOTH FAILED REPLACED FRONT SEAT BELT LATCHES  
REPLACE FAULTY SEAT BELT LATCH AS NEEDED DONE.  
DIAG BELT BUCKLE ON DRIVER SEAT NOT WORKING PROPERLY R AND R DRIVER SEAT BELT BUCKLE TESTED  
25555 SEAT BELT WOULD COME LOOSE (NOT RECALL) 42 WR VERIFIED CUSTOMERS CONCERN AND ROAD TESTED VEHICLE FOUND THAT  
42 REPLACED DRIVERS SIDE SEAT BELT LATCH. WOULDNT STAY LATCHED.  
REPLACE BUCKLE INOP  
3570 FAULTY BUCKLE R R SEAT, REPLACED PASS SEATBELT BUCKLE \*\*\*QUALITY CONTROL BY ANDREW FADER\*\*\*  
REPLACE DRIVERS SIDE SEAT BELT  
REPLACED SEAT BELT LATCH  
REPLACE SEAT BELTS WONT LATCH PROPERLY  
REPLACED SEAT BELT BUCKLE  
1 CHECKED OUT AND REPLACED DRIVERS SIDE FEMALE END  
CC487/Q44 REPLACED SEAT BELT  
3500 1.0 REPLACED SEAT BELT LOCK  
BUCKLE WOULD NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE  
DRIVER SIDE SEAT BUCKLE WOULD NOT HOLD REPLACE DRIVER SIDE SEAT BUCKLE  
REPLACED DRIVER SIDE BUCKLE; WAS NOT LATCHING PROPERLY  
3617 DRIVERS SEAT BELT BUCKLE MALFUNCTIONING. REPLACED DRIVERS SEAT BELT BUCKLE \*\*\* QUALITY CONTROL BY JOHN MEDROW \*  
INSPECT AND REPLACE LEFT FRONT SEAT BELT  
LEFT SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE  
42 REMOVE D S SEAT R R BUCKLE 7881209  
12162 W CHECKED DRIVERS SEAT BELT OPERATION TO FIND FAULTY SEAT BELT BUCKLE ASSY R&R BUCKLE ASSY TO FIX CONCERN RETEST  
REPLACED LEFT FRONT SEATBELT  
  
3272 NOT STAYING LOCKED R I DRIVERS SEAT TO TEAR DOWN AND REPLACE DRIVERS SEAT BELT BUCKLE. \*\*\*QUALITY TESTED BY LOUIE  
LF SEATBELT WILL NOT LATCH REPLACED LF SEATBELT BUCKLE M 1 USED FOR REPAIR DUE TO LACK OF LABOR OP AND TIME ESTABLISH  
VERIFY CONCERN.REMOVED DEFECTIVE SEAT BELT BUCKLE AND REPLACED.OPERATES AS DESIGNED AFTER REPLACEMENT  
INTERMITTENT CONCERN,BUCKLE WILL NOT LATCH. REPLACE DRIVERS SIDE SEAT BELT AND BUCKLE ASSY  
PINPOINT TESTS R&I DRIVER SEAT R&R SEAT BELT RECEIVER NOT LATCHING  
REPL SEAT BELT BUCKLE  
1886 DEFECTIVE SEATBELT R R SEAT, REMOVED SEATBELT CONNECTOR FROM UNDER SEAT, REPLACED DRIVER SIDE SEATBELT \*\*\*QUALITY  
DEFECTIVE SEAT BELT BUCKLE REPLACE D S SEAT BELT BUCKLE  
DRIVER SEAT BUCKLE ASSY DOES NOT LATCH 811 INSPECT AND TEST, REMOVE DRIVER SEAT, RREPLACE SEAT BUCKLE ASSY, TEST OP  
31 NOT STAYING BUCKLED TESTED DRIVERS SEAT BELT OPERATION, R I SEAT AND REPLACED SEAT BELT BUCKLE, RETEST, ALL FINE AT TR  
25554 TESTED SEAT BELT OPERATION REPL SEAT BELT BUCKLE FOR DRIVERS SEAT C.C. 42  
REPLACED L F SEAT BELT BUCKLE ASSY

INOP SEATBELT ASSEMBLY FRONT REPLACE  
SEATBELT INOP REPLACE LEFT SEAT BELT BUCKLE DID NOT LATCH RETEST OK  
REPLACED DRIVERS SEAT BELT BUCKLE  
COG98 CHECKED AND REPLACED DRIVERS SEAT BELT BUCKLE  
REPLACE ONE SEAT BELT BUCKLE  
SEAT BELT ON LEFT HAND OF THIRD SEAT WILL NOT BUCKLE. REPLACED SEATBELT ASSEMBLY. INSPECTED BELTS ON CAPTAINS SEATS. C  
INSTALLED SEAT BELT BUCKLE ASSEMBLY WOULDNT LATCH  
VERIFY CONCERN AND CK. SEAT BELT ON LEFT FRONT SEAT BELT FAILED TO LATCH, REPLACE SEAT BELT LATCH. VERIFY REPAIR,OK.  
8016 REPLACED BOTH FRONT BELT LATCHES AND TEST THE OP.  
DRIVERS SEATBELT WONT LATCH. REPLACED LATCH ASSEMBLY  
REPLACE LF. SEAT BELT LATCH AND CHECKS OK FW.  
WF CODE 42 M1 0.7 REPLACED DEFECTIVE DRIVERS SEATBELT BUCKLE.  
REPLACED LEFT FRNT SEATBELT BUCKLE  
VERIFY AND REPLACE SEAT BELT ASSEMBLY  
8058 WONT LATCH REPLACE DRIVER SEAT BUCKLE  
REPLACED DRIVERS SEAT BELT BUCKLES DUE TO FAULTY AND NOT STAYING  
18859 INSTALL SOP8 REMOVED AND INSTALLED SEAT BELT BUCKLE FRONT SEATS BOTH SIDES.  
REPLACE DR SEATBELT BUCKLE  
BINDING SEAT BELT BUCKLE REPLACED LEFT FRONT SEAT BELT BUCKLE  
VERIFY CONCERN LEFT SEAT BELT UNLATCHES INTERMITTENT, R&R LEFT SEAT BELT BUCKLE  
210 42 VERIFY CUSTOMER CONCERN, INSPEXCT AND FOUND DRIVER SEAT BELT BUCKLE NOT HOLDING SEAT BELT AT TIMES, REPLACED  
CONFIRMED. REMOVED AND REPLACED DRIVERS SEAT BELT LATCH TO CORRECT  
9587 DEFECTIVE SEAT BELT BUCKLE DRIVERS SEATBELT BUCKLE INTERMITTENTLY INOP. REMOVED AND REPLACED SEATBELT BUCKLE.  
REPLACED LEFT FRONT SEAT BELT BUCKEL BN 7881209 CC 42 TECH 178  
VERIFIED CONCERN, SEAT BELT WILL NOT HOLD. NEC TO REPLACE BUCKLE ASSY.  
REPLACE BOTH ASSYS  
BUCKLES WILL NOT LATCH REPLACE SEAT BELT BUCKLES  
REPLACED DRIVERS SEATBELT BUCKLE, DID NOT LATCH PROPERLY.  
REPLACE SEAT BELT  
REPLACED BOTH SEAT BELT BUCKLES POP PUT CODE  
BELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE (811A72 811A73) S40 42  
DIAG AND REPLACED DRIVERSIDE SEATBELT BUCKLE  
WILL NOT LATCH REPLACED SEAT BELT  
INOPERATIVE REPLACE LEFT SEAT BELT BUCKLE  
BUCKLE SEATBELT ASSEMBLY FRONT REPLACE  
MTIME TO REPLACE DRIVER SIDE SEAT BELT BUCKLE NO OPS FOUND  
3133 REPLACE DRIVERS SEAT BELT BUCKLE

1 REPLACED DRIVERS SEAT BELT BUCKLE



TECH\_TXT2

' LATCHED INPUT CONNECTOR WORKING PROPERLY

MILEAGE ON RO 224538 SHOULD HAVE BEEN 2420 NOT 24206.

CCD4..M:14384.

ASSENGER SIDE

ED BY MJM

IE.  
REPAIR..CCD4..M:10788

SEAT

SHOCK LATCH ASSY. REINSTALLED ALL TEST ALL OK.  
ASSY RETEST OK  
QUALITY CHECKED BY MJM

TEST DID NOT PASS REPLACED DRIVERS SEATBELT BUCKLE AND RETEST

FRONT SEAT BELT BUCKEL OK

ONE

RC004-011 00831

SEAT BUCKLE ASSEMBLY. RETEST, WORKING PROPERLY AFTER REPAIR.

TESTED BY A RANDEL

CASUAL PART 1L7Z 7881203 BAA

71801

ING PROPERLY.

TY CONTROL BY JOHN MEDROW —

IS OK

RC04-011 00633

NOT STAYING LATCHED REPLACED SEAT BELT BUCKLE DRIVERS SEAT QUALITY TESTED OK

FOR PROP

.T BUCKLE ASSE.  
ACCESS.REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSB..TEST DROVE AFTER REPAIRS.

TIME  
302.14891.



REMOVED SEAT IN ORDER TO ACCESS SEAT BELT BUCKLE. R R SEAT BELT BUCKLE ON DRIVER SIDE. ROAD TESTED AND FOUND BELT BL

\*\*\*

ST.

S TREVINO\*\*\*\*  
ED IN LABOR MANUAL

ITY CONTROL BY ANDREW RADER\*\*\*

IS TIME. \*\*\*\*QUALITY TESTED BY LOUIS TREVINO\*\*\*\*\*

OK

DRIVERS SIDE SEAT BELT BUCKLE, REINSTALL ROAD TEST RETEST OK.

CUST\_TXT

CS DRIVER SIDE SEAT BELT BUCKLE KEEPS UNBUCKLING

S25 LT FT SEAT BELT WONT STAY LATCHED

D SIDE SEAT BELT KEEPS COMING OFF

CS DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING

DRIVER SIDE SEATBELT RELEASE WHEN STOPPING...SOP PARTS..

S40 CK DRIVER SEAT BELT WONT STAY BUCKLED REPORT

CUSTOMER SAYS THAT DRIVERS SEATBELT WILL UNLATCH WHILE DRIVING

L.F. SEAT BELT BUCKLE COMES LOOSE AT TIMES SOP IN

CUSTOMER STATES BOTH FRONT SEAT BELTS WILL NOT HOLD. PPC PARTS HERE

S40 CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING

DRIVERS SIDE SEATBELT WONT STAY BUCKLED

CUSTOMER STATES 2ND ROW LH SIDE SEAT BELT LATCH WONT STAY IN LATCHED POSITION

O R L F SEATBELT BUCKLE COME LOOSE

CUST STATES BOTH FRT SEAT BELTS DONT LATCH

CSUT STATES DRIVERS SEAT BELT WONT CATCH BUCKLE AND STAY FASTENED

T90 DRIVER SEAT BELT UNBUKLE ST TIMES BY IT SELF

DRIVERS SEAT BELT BUCKLE RELEASES WHILE DRIVING..NO WARNING

CUSTOMER STTAAES RIGHT FRONT SEAT BELT BUCKLE DOES NOT LATCH

CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT STAY LATCHED

SPECIAL ORDER PARTS IN MIDDLE SEAT MIDDLE SEAT BELT RECEPTICLE AND REAR BENT LEFT OUT RECEPTICLE DO NOT STAY

CUSTOMER STATES SEATBELT WONT LATCH

S40 OWNER STATES DRIVERS SEAT BELT WONT STAY LATCHED AT TIMES, RED CAP DOESNT COME BACK UP PROPERL

CUST STATES DRIVERS SEATBELT BUCKLE WONT LATCH AT TIMES

S40 CUSTOMER STATES LEFT SEAT BELT BUCKLE POPS OUT DOES NOT RETAIN SEAT BELT.

S40 INSTALL SOP PARTS, DR FRONT SEAT BELT UNBUCKLES WHILE DRIVING

DR SEAT BELT WILL COME UN LATCHED

DRIVERS SEAT BELT WONT BUCKLE PART IS HERE

C S DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING CHECK AND ADVISE

DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING

C S DRIVERS AND PASS SD BUCKLES COME UNLOCKED INTERM. SOP

DR SEAT BELT BUCKLE COMES UNBUCKLED WHEN DRIVING

S28 BOTH FRT. SEAT BELT BUCKLES HAVE POPPED OPEN AT TIMES WHEN DRIVING

CUST STATES DRIVERS SEAT BELT COMES UNLATCHED AFTER DRIVING A WHILE

DRIVERS FRONT SEAT BELT BUCKLE DOES NOT LATCH INTERM. WHEN IT DOES IT IS HARD TO GET BELT UN LACTCHED

CUSTOMER STATES DRIVERS SEAT BELT BUCKLE WILL NOT CLOSE

SEAT BELT WILL NOT LATCH

LEFT FRONT SEAT BELT DOES NOT STAY LATCHED. CHIME FOR SEAT BELT GOES OFF EVEN AFTER SEAT BELT IS BUCKLED  
DRIVERS SEAT BELT COMES UNBUCKLED  
CK SEATBELT WILL NOT BUCKLE  
CHECK L F SEATBELT ERRATIC COMES UNLOCKED WHILE DRIVING S40  
S40, CUSTOMER STATES DRIVER SIDE SEAT BELT WILL NOT STAY FASTEN, IT KEEPS POPPING LOOSE  
SEAT BELT WILL NOT LATCH YOU HAVE TO PRESS THE RED BUTTON TO LATCH  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE DOES LOCK  
S40 CUSTOMER STATES THAT DRIVER SEAT BELT WONT LATCH  
CS DR SEAT BELT WONT LATCH S28  
CUST STATES THAT DRIVERS SEAT BELT WILL NOT STAY LATCHED  
OWNER REPORTS D S FRONT SEAT BELT COMES UNHOOKED BY SELF CK ALL BELTS S28  
DRIVER SEAT BELT COMES UNLATCHED WHILE DRIVING  
DRIVER SIDE SEAT BELT LATCH WONT HOLD  
CUSTOMER REPORTS DRIVER S SEAT BELT BUCKLE WILL NOT LATCH.. WILL NOT HOLD BELT.  
CUSTOOMEER STATES THAT LEFT FRONT SEAT BELT COMES UNDONE  
S40 O R LEFT FRONT SEAT BELT BUCKLE COMES UNDONE WHEN DRIVING  
S28 CUST STS LEFT FRONT SEATBELT UNLATCHES BY ITSELF SOP ROK329083 MI 13720 1 2 02  
S40 DRIVERS SEAT BELT WILL NOT LATCH  
CUSTOMER STATES THE DRIVERS SEAT BELT DOES NOT ALWAYS LOCK IN 3  
CUSTOMER STATES WHILE DRIVING SEAT BELT COMES APART.  
S28 DRIVERS SIDE SEAT BELT WILL NOT GO INTO CLAMP AT TIMES  
S28 CUST STS LEFT FRONT SEATBELT WILL NOT LATCH SOP ROK329734 MI 18980 1 14 02  
SEAT BELTS WILL NOT LATCH PROPERLY  
DFL SEAT BELT BUCKLE HAS COME LOOSE TWICE SINCE RECALL PERFORMED.  
DRIVERS SEAT BELT COMES UNLATCHED AT TIMES PART IN  
L.F. SEAT BELT BUCKLE WONT LATCH SOP IN  
CUSTOMER STATES:DRIVERS SEAT BELT COMES UNBUCKLED WHILE DRIVING.  
C S LF SEATBELT KEEPS COMING LOOSE AT LATCH  
C S LF SEAT BELT WONT LOCK CK AND ADVISE  
T99 SEE DUANE DRIVERS FRONT SEAT BELT WONT LATCH INT TRIM TAN 1H  
C S DRIVER SEAT BELT BUCKLE NOT LATCHING  
CUST STATES DRIVERS SEAT BELT WILL NOT LOCK  
CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY BUCKLED  
CUST TSS DRIVER SIDE SEAT BELT WHEN BUCKLED IT DELATCHES  
CUST STATES D S FT SEATBELT WILL COME UNLATCHED WHEN DRIVING  
S40 DRIVERS FRONT SEATBELT WILL NOT STAY LATCHED .. DUPLICATED CONCERN ON SERVICE DRIVE..  
CK DR SEATBELT COMES UNDONE WHILE DRIVING

QUALITY CHECK INITIALS SEAT BELT ON DRIVERS SIDE DOES NOT BUCKLE S40  
DRIVERS SIDE SEAT BELT WONT LATCH  
BOTH FRONT SEAT BELT BUCKLES DONT LATCH  
SEATBELT BUCKLE UNLATCHES  
SEAT BELTS WILL NOT LATCH PROPERLY  
CUSTOMER STATES WHILE DRIVING THE LEFT FRONT SEAT BELT WILL POP OUT OF THEBUCKLE ASY.  
SEATBELT BUCKLE COMES UNLATCHED WHILE DRIVING, SOP HERE SEE 88397 TECH 351  
SEAT BELT WILL NOT STAY LATCHED

S40 SEATBELT CUST STATES THEDRIVERS SEATBELT WILL NOT HOLD LATCH

CUST STATES DRIVERS SEAT BELT COMES UNDONE WHEN DRIVING  
DRIVERS SEAT BELT BUCKLE NOT LATCHING PROP  
SEAT BELT CHIMES,SEAT BELT DOESNT CLICK IN ALL THE WAY  
DRIVERS SEATBELT WILL POP LOOSE INSTALL PARTS..  
C S DRIVERS SEAT BELT DOES NOT BUCKLE SEE TOM IN PARTS  
CHECKED IGH FRONT SEAT BELTT LATCH WONT WORK  
CUSTOMER STATES DRIVER SEAT BELT KEEPS COMING LOOSE WHILE DRIVING  
CUSTOMER STATES THE DRIVERS SIDE SEAT BELT WILL NOT HOLD (SOP)  
CUST STATES SEATBELT NOT LATCHED WARNING LAMP AND BUZZER INTERMITTENTLY GOES OFF EVEN WHEN SEATBELT IS LATCHED  
DRIVER SIDE SEATBELT DOEN T HOLD  
CUST STATES DRIVERS SEAT BELT WILL NOT STAY IN BUCKLE  
DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCHED  
DRIVERS SEAT BELT DOES NOT STAY BUCKLED

S25 INSTALL SPECIAL ORDERED DRIVERS SEAT BELT RECIEVER INTERMITTANT CONCERN COMES UNLATCHED WHILE DRIVING  
CK. DRIVERS SIDE FRONT SEAT HAS COME LOOSE WHILE DRIVING  
CUST. STATES THAT THE DRIVERS SEAT BELT COMES UNBUCKLED S.O.P IS IN  
DRIVERS SEAT BELT WONT LATCH  
DRIVERS SIDE SEAT BELT BUCKLE RELEASES ON IT S OWN INTERMITANTLY  
DRIVERS SEAT BELT WONT STAY LATCHED  
CUSTOMER STATES DRIVERS SIDE SEAT BELT RECEPICLE DOES NOT ALWAYS LATCH. BUCKLE WAS INSPECTED LAST MONTH PER RECAI  
S28 DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED WHILE DRIVING.INSTALL SOP 1L7Z788  
S25 CK DRIVERS SEAT BELT SHOULDER HARNESS FEMALE PART WILL NOT STAY BUCKLE COMES UNBUCKLED AFTER LOCKED WHILE C  
LEFT FRONT SEAT BELT WILL NOT STAY LATCHED  
S40 CUS STS THAT THE LF SEAT BELT WONT LATCH, S O PART  
CUSTOMER STATES DRIVERS SEAT BELT DONT LOCK ALL THE TIME  
CUST STATES DRIVERS SEATBELT KEEPS COMING UNHOOKED

CUST STATES DRS SEAT BELT KEEPS COMING UNLATCHED, JUST HAD 01821 AND CHECKED OK, RECHECK SERVICE PART WARR. SEAT BELT COMES UNHOOKED. REPLACED ON RO 44808

LEFT FRONT SEAT BELT WONT LATCH

DRIVER SIDE SEAT BELT UNLATCHES WHEN DRIVING.

INT DR SEAT BELT DONT LATCH, CANT HEAR IT CLICK

CUSTOMER STATES INSTALL SPO SEAT BELT PART LEFT FRONT SEAT BELT WILLNOT LATCH

CUST STATES D S FRONT SEATBELT DOES NOT LATCH IN SPO PART CHECK ALSO FOR 01821 RECALL SEATBELT BUCKLE

C S DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING . . .

CK DRIVERS SEATBELT HARD TO BUCKLE , WONT STAY BUCKLED , INSTALL SOP PART

CUSTOMER STATES DRIVER SEAT BELT UNFASTENS WHILE DRIVING

C.S LEFT FRONT SEAT BELT INOP. CH ADVISE

CUSTOMER STATES SEAT BELT ON DRIVER SIDE DOES NOT WORK

L F SEAT BELT COMES UNHOOKED. PLS R R (PARTS SHOULD HAVE BEEN ORDERED

CUST REPORTS DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES...POPS OUT

CUST STATES DR FRT SEAT BELT WILL POP OUT OF RECEPTACLE WHILE DRIVING INTERM AND TAKES ABOUT 3 4 TIMES BEFORE WILL LOX

THE DRIVERS SIDE SEAT BELT COMES UNLATCH WHILE DRIVING 328 CK AND SAYS THEY ARE OK

CUST SAYS DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING

C S DRIVERS SEATBELT COMES OFF DRIVING DOWN THE ROAD

DRIVERS SEAT BELT WONT STAY LATCHED

DRIVERS SEAT BELT KEEPS COMING UNLATCHED WHEN DRIVING

CUSTOMER REPORTS SECOND SEAT RT.SIDE SEAT BELT WILL NOT BUCKLE.

CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING

C S DRIVE SIDE SEAT BELT COME UNBUCKELED

DRVRS SIDE SEAT BELT KEEPS POPPING OUT AT TIMES WILL NOT STAY LATCHED

CUST. STATES DRIVER FRONT SEAT BELT COMES OUT OF BUCKLE WHILE DRIVING PARTS IN

FRT DRIVERS SEAT BELT COMES UNLATCHES

CHECK FOR SEAT BELT NOT LATCHING AT TIMES

CK DRIVERS SEAT BELT WONT LATCH. BUCKLE INOP

328 DRIVERS SEAT BELT BUCKLE COMES UNBUCKLED WHILE DRIVING

CUSTOMER STATES THAT THE DRIVERS FRT SEAT BELT COMES LOOSE CONTINUOSLY WHILE DRIVING

DRIVER SEAT BELT WONT STAY BUCKLED.

340 CUST STATES SEAT BELT POPS OPEN DRIVERS SIDE SOP PART IS IN UNDER NEIL HARVEY

CUSTOMER STATES DRIVER SEAT BELT COMES UNFASTENED ON IT OWN.

340 PER CUST, THE DRIVERS SEAT BELT COMES UNLATCHED. SEE HISTORY

T90 C S DRIVERS SEAT BELT WONT STAY LATCHED SOP

LEFT FT. SEAT BELT COMES UNHOOKED WHILE DRIVING SOP HERE.

CUST STATES D S SEATBELT BUCKLE WONT LATCH

SEAT BELTS COMING UNLATCHED. PART HERE  
CUST STATES DRIVERSIDE SEAT BELT COMES OUT AFTER YOU CLICK IT IN BY ITSELF  
CLIENT STATES BOTH FRONT SEATBELTS AFTER 5 MINUTES OF DRIVING POP OFF ON THEIR OWN. ADVISE  
SEAT BELT ON DRIVERS SIDE WILL NOT STAY LOCKED  
CHECK LEFT FRONT SEAT BELT WONT LATCH TO BUCKLE  
SEATBELT WILL NOT LATCH AND STAY HOOKED ALL THE WAY IT POPS BACK OUT.  
DRIVER'S SEAT BELT BUCKLE WILL NOT HOLD T FH  
LEFT SEAT BELT WILL NOT STAY LATCHED  
DRIVER SEAT BELT WILL NOT FASTEN  
CUST STATES DRIVER SIDE SEATBELT KEEPS COMING UNBUCKLED SOP PART IN STOCK  
DRIVERS SEATBELT UNBUCKLES WHILE DRIVING  
DRIVERS SIDE SEAT BELT IS RELEAEING BY ITSELF  
CUSTOMER STATES CHECK DRIVER SEAT BELT RELEASES ON ITS OWN AT TIMES  
RECALL 01821 CUST STATES DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING  
INSTALL SOP FOR SEAT BELT RECALL DRIVERS BELT  
S26 CUST. REPORTS DRIVERS SIDE SEAT BUCKLE WONT LATCH  
CUST STATES DRIVER SEAT BELT CAME APART WHILE DRIVING  
SEAT BELT WILL NOT BUCKEL SOP HERE  
S40 C S THE DRIVERS SEAT BELT POPS LOOSE WHEN DRIVING  
CUS STATES D SDIE SEAT BELT COMES UNDONE RO 98954 RECHECK TECH 160  
SOP SEAT BELT INOP S40  
SEAT BELT ON DRIVERS SIDE WILL NOT BUCKLE  
CUSTOMER SAYS THAT DRIVERS SIDE SEATBELT INOP...  
CK DRIVER SEAT BELT WILL COME UN LATCH BY ITSELF  
CUST STATES DR SIDE SEAT BELT WONT LATCH  
OWNER STATES DRIVERS SEATBELT COMES UNLATCHED WHEN PULLED ON  
DRIVERS SEAT BELT DOESNT LATCH, INSTALL SOP PARTS USE SOP 01188002  
C S DRIVER SIDE SEAT BELT KEEPS COMING OUT OF CLIP SOP IS IN  
DRIVERS SEAT BELT BUCKLE POPS OUT OF RECEPTACLE OFTEN  
S40 DRIVERS SIDE SEAT BELT UNCLICKED OVER BUMP TWICE  
CK DR SIDE BELT WONT LOCK  
DRIVERS SIDE SEAT BELT RECEMER WONT HOLD ALL THE TIME  
CHECK TWO FRT SEAT BELT LATCH AT TIMES DOESNT LATCH  
CUSTOMER STATES INSPECT FOR DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY ADVISE  
BOTH FRONT SEAT BELTS NOT BUCKLING INTERMITTENT PROBLEM  
CHECK AND ADVISE ON DRIVERS SEAT BELT WILL COME UNLOCKED WHEN DRIVING SOP HERE  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE POPS IN AND OUT

DRIVERS SEATBELT IS INOP  
INSPECT FOR SEAT BELT NOT LATCHING SOP HERE  
C S DRIVERS SIDE SEAT BELT COMES UN FASTENED AT TIMES  
LEFT FT SEAT BELT COMES UN CLASP SOP PARTS  
LEFT FT SEAT BELT SEAT BELT COMES UNBUCKLED FOR NO REASON  
S40 CUST STATE CK LEFT FT SEAT BELT WILL NOT LATCH  
DRIVERS SEAT BELT WILL NOT STAY LATCHED AT TIMES, ALSO COMES LOOSE AT TIMES WHILE DRIVING, ADVIS  
S40 CUST STATES LEFT FRONT SEAT BELT WILL NOT BUCKLE AT TIME POPS OUT WHILE DRIVING  
CUSTOMER REPORTS DRIVERS SIDE SEAT BELT COMES OUT OF RECEPTICLE WHILE DRIVING, CHECK AND ADVISE  
CK SEATBELT WONT LATCH  
CUSTOMER STATES:DRIVERS SEAT BELT KEEPS COMING UNLATCHED PLS RECHECK PASSENGERS AS WELL  
LEFT FRONT SEAT BELT COMES UNLATCHED  
CUSTOMER STATES: FRONT DRIVER SIDE SEAT BELT DOES NOT STAY LATCHED ALL THE TIME. CHECK ALL SEAT BELTS  
CUSOTMER STATES DRIVERS SEAT BELT WILL COME LOOSE WHEN DRIVING SPO PARTS IN  
DRIVER SIDE SEATBUCKLE WONT LATCH. SOP  
DRIVERS SEATBELT WILL NOT LATCH  
CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES LOOSE FOR NO REASON  
RECALL ON SEATBELT WAS DONE BUT SEATBELT IS NOT LATCHING LEFT FRONT SEAT BELT CK BOTH FT SEAT BELTS  
C S LEFT FRONT SEAT BELT BUCKLE COMES UNLATCHED WHILE DRIVING INT.  
S06 FRT DRIVERS SIDE SEAT BELT COMES UNLATCHED AT TIMES  
DRIVERS SEAT BELT BUCKLE WILL NOT STAY FASTENED  
CUSTOMER STATES LEFT FORNT SEAT BELT UNBUCKLES AT TIMES WHILE DRIVING  
CUST STATES THE DRIVERS SEAT BELT POPS OPEN WHILE DRIVING  
CUSTOMER STATES: THE DRIVER S SEAT BELT WILL NOT STAY LATCHED, SOP IN  
S40 D S F RESTRAINT UNLOCKS WHILE DRIVING  
DRIVERS SEAT BELT COMES UNDONE WHILE DRIVING LIGHT TAN  
REP. DRIVERS SEAT BELT WILL NOT LATCH  
DRIVER SIDE SEAT BELT WILL NOT LATCH  
DRIVER SEATBELT WILL NOT BUCKLE AT TIMES USE SPO 02058001  
DRIVERS SEATBELT WILL NOT STAY LATCHED INSTALL SOP  
CK THE SEAT BELT DRIVER SIDE NOT LATCHING PROPERLEY  
CUST STATES THAT DRIVER SEAT BELT COMES UNDONE SOMETIMES WHILE DRIVING  
DR. SEATBELT COMES UNFASTENED AT TIMES  
C S THE SEAT BELT WILL COME UNLATCHED  
O R DRIVERS SEATBELT CAN BE PULLED OUT, OR WHEN IT IS PUT UNDER PRESSURE IT WILL COME OUT OF BUCKLE.  
S40 CUSTOMER STATES DRIVER SEAT BELT COMES UNBUCKLED  
THE DRIVERS SEAT SEATBELT RECIEVER KEEPS LETTING LOOSE OF THE BELT, CHECK AND ADVISE



CUST STATES DR SIDE SEAT BELT BUCKLE COMES UNDONE...  
STS DR SEATBELT WONT STAY LATCHED  
CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES.  
CRIVER'S SEAT BELT BUCKLE WILL NOT HOLD.  
DRIVER SEAT BUCKLE WILL NOT ALWAYS LATCH  
CUST STATES THE DRIVERS SEAT BELT CONSTANTLY COMES LOOSE AFTER IT HAS BEEN FASTENED.  
DRIVERS SIDE FRONT SEAT BELT COMES UNLATCHED AT TIMES  
CB BOTH SEAT BELT BUCKLES KEEP COMING UNDONE WHEN DRIVING?  
CUST STATES THE DRIVERS SEAT BELT WILL NOT STAY LOCKED POPS OFF WHILE DRIVING  
INSTALL SPO PART HERE DRIVER SEAT BELT BUCKLE NOT LOCKING INTERMIT  
S40\*\*DRIVERSIDE DEAT BELT LATCH WILL NOT STAY LATCHED  
CUSTOMER STATES SEAT BELT WILL NOT LATCH SOP HERE  
S25 DRIVERS SIDE SEAT BELT WONT STAY LATCHED  
DRIVERS SIDE SEAT BELT WONT LATCH  
CHECK DRIVER SIDE SEAT BELT BUCKLE UNHOOKS WHILE DRIVING  
CHECK DRIVERS SEAT BELT WILL NOT STAY LATCHED INTERMITTENT  
C S DRIVERS FRONT SEAT BELT UNBUCKLES WHEN STOPPING  
A99 DRIVER SIDE SEAT BELT WILL NOT STAYED BUCKLE  
LEFT SEAT BELT WILL NOT LATCH  
C S DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT  
INSP. L F SEAT BELT WILL NOT BUCKLE AT TIMES AND IS HARD TO BUCKLE AT OTHER TIMES  
DRIVERS SIDE FRONT SEAT BELT KEEPS COMING LOOSE...INSTALL SOP  
DRIVER SEAT BELT HAS COME LOOSE SEAT BELT LIGHT ON INSTALL SOP SEATBELT  
CUST STATES DRIVER SEAT BELT LATCH WILL NOT HOLD AT TIMES(REFER TO RO #95200)  
D S FRONT SEAT BELT WILL NOT STAY LATCHED  
C S LEFT FRONT SEAT BELT BUCKLE WONT LATCH  
CK REASON WHY DRIVERS SEAT BELT BUCKLE WONT LOCK BELT AT TIMES.INSTALL S.O.P.  
CUST STATES DRIVERS SEAT BELT COMES UNHOOKED  
SEAT BELT DRIVERS SIDE COMES LOOSE WHILE DRIVING SOP PART HERE  
CUSTOMER STATES THAT THE DRIVERS SEAT BELT BUCKLE IS NOT HOLDING BELT. REFER TO LINE A  
CK THE DRIVER SIDE SEAT BELT LATCHES THEN WHEN DRIVING COMES LOOSE OR PULLS OUT OF LATCH  
CK DR SEATBELT POPS OUT WHILE DRIVING  
CUST STATES DRIVERS SEAT BELT WILL POP LOOSE WHEN DRIVING, REBUCKLE AND WILL POP LOOSE AGAIN  
DRIVER SHOULDER HARNESS POPS LOOSE AT TIMES WHILE DRIVING  
C S DRIVERS SEATBELT BUCKLE REALESES  
S26 THE DRIVERS SEAT BELT BUCKLE COMES UNLATCHED.  
SEAT BELT N DR SIDE COMES APART WHILE DRIVING WILL NOT STAY LATCHED

SPO# 01159003

LEFT SEAT BELT DOES NOT KEEP BELT IN PLACE  
CUST STATES THE FRONT SEATBELTS ARE UNBUCKLING. WE PERFORMED RECALL TEST 8 28 01 RO# 25824 AND PASSED  
DRIVERS SEAT BELT COMES LOOSE, UNBUCKLES AT TIMES, S.O.P. AT PARTS  
CLIENT STATES DRIVERS SEAT BELT WONT LATCH. SOP HERE TO REPAIR.  
S25 DRIVERS SEAT BELT WONT LATCH, PART IN  
S40 CHECK CUST CONCERN FOR DRIVER SIDE SEAT BELT BUCKLE WILL NOT LATCH.  
S40 DRIVERS SEAT BELT WONT LATCH, ALL TIMES, CUST STATES.  
BOTH FRONT SEAT BELTS WONT LATCH  
S25 DRIVERS SEAT BELT COMES OPEN WHEN DRIVING AT TIMES  
C S DRIVERS SEAT BELT POPS LOSE WHILE DRIVING  
CHECK DRIVER FRONT SEAT BUCKLE COMES LOOSE WHILE DRIVING  
CUSTOMER REPORTS DRIVERS SEATBELT WILL NOT HOLD AT TIMES  
CK DRIVERS SEAT BELT WONT STAY ATTACHED  
DRIVERS SEAT BELT WONT LATCH  
CUSTOMER STATES THE DRIVERS SEAT BELT COME UNLATCHED  
S40 PASS SIDE MIDDLE SEAT BELT LATCH COMING APART  
CUST STATES DRIVER SEAT BELT SNAPS LOOSE BY ITSELF POPS OUT BY ITSELF  
CUSTOMER STATES DRIVERS SEAT BELT KEEP COMING UNBUCKLED  
CK DRIVER SEAT BELT BUCKLE NOT HOLDING  
S25 L F SEAT BELT COMES UNFASTENED  
DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED  
S40 CUST STATES LEFT FRONT SEAT BELT BKL DOES NOT HOLD SAYS DISENGAGES WHILE DRIVING  
DIAG DRIVER AND PASS SEAT BELTS UNLOCK WHILE DRIVING DOWN THE FREEWAY  
DRIVER SIDE SEATBELT RECIVER DOES NOT HOLD  
LH FRT SEAT BELT BUCKLE IS NOT HOLDING ALL THE TIME  
CK BOTH FRONT SEAT BELT BUCKLES COMING UNLATCH  
THE DRIVERS SEAT BELT RELEASES WHILE DRIVING  
CUSTOMER STATES THAT LEFT FRONT SEAT BELT KEEPS COMING UNLATCHED WHILE DRIVING  
CK FOR DRIVER SIDE FRT SEATBELT DOES NOT LATCH AT TIMES  
CUST STATES DRIVER SEAT BELT NOT LATCHING  
S40 INSTALL SOP FRONT SEAT BELTS WONT STAY LATCH SPOT 138534/ 138533  
CUSTOMER STATES SEAT BELT KEEPS UN LOCKING  
STATES SEAT BELT WILL NOT LATCH S40  
CUST REPROTS THAT WHEN DRIVING AND DRIVERS SEATBELT IS LOCKED IN PLACE,WILL AUTOMATICALLY UNLOCK,DOES CLICK WHEN U  
D S SEAT BELT INOP DOES NOT BUCKLE AT TIMES  
CK DRIVERS SIDE SEATBELT UNBUCKLES ON ITS OWN  
S40 CUSTOMER STATES DRIVERS SEAT BELT CLICKS IN BUT WILL NOT HOLD LATCH IN BUCKLE

S40CUST STATES SEAT BELTS COME APRT WHILE DRIVING  
S26 CUST STATES DRIVERS SIDE SEAT BELT BUCKLE DOES NOT LATCH EASILY ENOUGH HARD TO LATCH REQUEST CHECK PASSENGER  
S25 STATES RT FRONT SEAT BELT DOES NOT LATCH  
CS DRIVERS FRT SEAT BELT WILL COME UNBUCKLED WHEN DRIVING  
S39 CUSTOMER STATES SEAT BELT BUCKLE LOOSE  
DRIVERS SIDE SEATBELT KEEPS POPPING OUT WHILE DRIVING  
CUSTOMER STATES DR SEAT BELT DOES NOT BUCKLE ALL THE TIME  
SOP PART IN PASSENGERS SIDE SEATBELT BUCKLE WILL NOT STAY BUCKLED  
CUST. STATES DRIVERS SIDE SEAT BELT WILL NOT HOLD KEEPS RELEASING SOP IS HERE  
CUSTOMER STATES DRIVERS SEATBELT BUCKLE RELEASES

CK DRIVERS SEAT BELT POPS LOOS DRIVING  
CUSTOMER STATES: THE DRIVERS SIDE FRONT SEATBELT WILL NOT STAY LATCHED  
CUST STATESW DRIVER SIDE SEAT BELT INOP WILL NOT BUCKLE  
DRIVER SIDE SEAT BELT WONT STAY ATTACHED  
CUST STATES LEFT FRONT SEAT BELT WILL NOT NOT STAY LATCH IN THE BUCKLE COMES LOOSE  
SEAT BELT WONT BUCKLE  
CUSTOMER STATES DRIVER S SIDE BUCKLE BECOMES UNLATCHED FROM TIME TO TIME  
DRIVERS SEAT BELT COMES LOOSE SOP HERE  
CUST STATES DRIVERS SEAT BELT WONT STAY BUCKLED INTERMITTENTLY  
LEFT SEAT BELT WONT STAY LATCHED PART HERE WAIT  
CUST STATES SEAT BELT COMES UNFASTENED,JUST DID RECALL CC S25  
CK DRIVER SEATBELT WILL NOT HOLD  
LEFT FRONT SEAT BUCKLE WONT LATCH  
840\*CUSTOMER STATES THAT DRIVERS SIDE FRONT SEAT BELT UNLATCHES WHILE DRIVING  
DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING  
DRIVER SEAT BELT KEEPS COMING LOOSE  
SEAT BELT BUCKLE ON DRIVERS SIDE WILL NOT LATCH  
CUST STATES THE DRIVERS SEAT BELT IS INOP  
CK DRIVERS SEATBELT KEEPS COMING UNBUCKLED  
DRIVERS SEAT BELT WILL NOT STAY BUCKLED  
SOP HERE DRIVERS SEAT BELT WONT STAY LATCHED  
CUST STATES DRIVER SEAT BELT RELEASES BY ITSELF  
CUSTOMER STATES LEFT FRONT SEAT BELT UNLATCH BY SELF DRIVERS SEAT  
DRIVER SEAT BELT WILL NOT STAY BUCKLED  
DRIVERS SEAT BUCKLE WILL NOT LATCH  
DRIVER SEAT BELT WHEN BUCKLED AND CAN BE PULLED AND RELEASED WITHOUT,PUSHING BUTTON

DRIVERS SIDE FRONT SEAT BELT KEEPS SLIPPING OUT..WILL NOT STAY LATCHED GOOD  
DRIVERS SEAT BELT RECEPTACLE INOP  
DRIVERS SEAT BELT COMES UNDONE AS DRIVING  
S28 CUSTOMER STATES THAT DRIVERS FRONT SEAT BELT BUCKLE UNLOCKS BY ITSELF WHILE DRIVING.  
SEAT BUCKLE WOULD NOT LATCH  
CHECK LAST SEAT SEATBELT BUCKLE  
CUST STATES LEFT FRONT SEAT BELT BUCKLE DOESNT STAY LATCHED  
CUST. REQUEST CK. FOR LF SEAT BELT WILL NOT LATCH AT TIMES  
SEAT BELT COMES UNBUCKLED AT TIMES INSTALL SOP  
DRIVER SEATBELT WONT LATCH PART HERE  
DRIVERS SEAT BELT WONT LATCH  
LEFT FRONT SEAR BELT WONT LATCH  
CHECK DRIVER SIDE SEAT BELT COMES LOOSE  
CUSTOMER STATES DRIVERS SEAT BELT COMES UNFASTENED WHILE DRIVING..  
S40 DRIVERS SEAT BELT WILL NOT STAY LATCHED  
CUST STATES THAT DRIVER SEATBELT COMES UNDONE SOMETIMES WHILE DRIVING  
CUST STS BOTH FRONT SEATBELT BUCKLES DONT HOLD PROPERLY, STICK CCC S40  
CHECK LEFT FRONT SEAT BELT UNLATCHES WHILE DRIVING  
CHECK VEHICLE DRIVERS SIDE FRONT SEAT BELT WILL NOT BUCKLE AT TIMES  
DRIVERS SIDE SEATBELT WILL COME LOOSE BY ITSELF  
S25 DRIVERS SEAT BELT WONT STAY LATCHED  
C S DRIVERS SEAT BELT COMES UNLATCHED SOP IS IN  
S40 SEATBELT WOULD NOT LATCH  
LEFT FRONT SEAT BELT WILL NOT STAY LATCHED  
CUSTOMER STATES THE DRIVER SIDE BELT WILL NOT STAY LATCHED...SOP HERE  
LH FRONT SEAT BELT BUCKLE WILL NOT RELEASE RH FRONT BELT BUCKLE CAME APART

INSTALL SOP SEATBELT PER RECALL  
DRIVER SEAT BELT NOT LATCHING  
CUST STATES BOTH FRONT SEAT BELTS POPP OUT WHEN DRIVING  
CK SEAT BELT WONT STAY LATCHED  
DRIVERSIDE SEATBELT WILL NOT STAY BUCKLED  
CUST STATES 2 ND SEAT CENTER SEAT BELT BUCKLE INOP WONT LATCH CUST STATES PASSENGERR SIDE 2 ND SEAT BELT BUCKLE INO  
SEAT BELT DOES NOT LATCH LEFT FRONT  
DRIVERS SIDE SEATBELT NOT LOCKING IN  
CUSTOMER STATES DRIVERS SEAT BELT BUCKLE WILL COME UN DONE AT TIMES AND SOMETIMES YOU WILL HAVE TO PLAY WITH RED B  
DRIVERS SEATBELT BUCKLE COMES UNLATCHED SOMETIMES

CUST SAYS THGE LF SEATBELT BUCKLE COMES UNLATCHED SOP TECH 502

RC04-011 00649

AREA_CD	COUNTRY_CD	SLS_DLR_CD	TXN_CD	CNTRY_SOLD	QRT_CD	VFG_CD	AWS_VL_CD	VRT_CD	TIS_FLAG	
	203	USA	124009	2	USA	Q21	V05	B3	S08	0
	719	USA	152031	1	USA	Q21	V05	B3	S08	
	817	USA	152016	1	USA	Q21	V05	B3	S08	
	802	USA	171176	1	USA	Q21	V05	B3	S08	
	972	USA	152002	1	USA	Q21	V05	B3	S08	
	281	USA	152055	1	USA	Q21	V05	B3	S08	
	713	USA	152026	1	USA	Q21	V05	B3	S08	
	512	USA	152309	1	USA	Q21	V05	B3	S08	
	850	USA	172013	2	USA	Q21	V05	B3	S08	
	214	USA	152003	1	USA	Q21	V05	B3	S08	
	281	USA	152052	1	USA	Q21	V05	B3	S08	
	214	USA	152006	1	USA	Q21	V05	B3	S08	
	407	USA	124224	1	USA	Q21	V74	B3	S08	
	818	USA	124521	E84	USA	Q21	V05	B3	S08	
	770	USA	121405	2	USA	Q21	V05	B3	S08	
	719	USA	152031	E84	USA	Q21	V74	B3	S08	
	972	USA	152017	E84	USA	Q21	V05	B3	S08	
	562	USA	171047	E84	USA	Q21	V05	B3	S08	
	972	USA	152013	1	USA	Q21	V05	B3	S08	
	510	USA	172013	1	USA	Q21	V05	B3	S08	
	915	USA	152540	1	USA	Q21	V05	B3	S08	
	281	USA	152020	2	USA	Q21	V05	B3	S08	
	337	USA	123271	1	USA	Q21	V05	B3	S08	
	281	USA	152032	1	USA	Q21	V05	B3	S08	
	713	USA	152241	E84	USA	Q21	V05	B3	S08	
	210	USA	152143	E84	USA	Q21	V05	B3	S08	0
	734	USA	148019	2	USA	Q21	V17	B3	S08	
	512	USA	152303	1	USA	Q21	V74	B3	S08	
	281	USA	152052	1	USA	Q21	V05	B3	S08	
	512	USA	152302	E84	USA	Q21	V05	B3	S08	
	281	USA	152024	2	USA	Q21	V03	B3	S08	
	713	USA	152049	E84	USA	Q21	V05	B3	S08	
	804	USA	124455	E84	USA	Q21	V06	B3	S08	
	281	USA	152054	E84	USA	Q21	V05	B3	S08	
	770	USA	121024	2	USA	Q21	V05	B3	S08	
	214	USA	152464	1	USA	Q21	V05	B3	S08	

978 USA	152734	2 USA	Q21	V05	B3	S08
938 USA	152518	2 USA	Q21	V05	B3	S08
225 USA	123203	1 USA	Q21	V05	B3	S08
504 USA	123027	1 USA	Q21	V05	B3	S08
713 USA	152241	1 USA	Q21	V05	B3	S08
870 USA	123551 E84	USA	Q21	V05	B3	S08
305 USA	124601	1 USA	Q21	V44	B3	S11
214 USA	152013	2 USA	Q21	V05	B3	S08
318 USA	123038	1 USA	Q21	V05	B3	S08
405 USA	152558	2 USA	Q21	V05	B3	S08
USA	121420 E84	USA	Q21	V05	B3	S08
281 USA	152024 E84	USA	Q21	V05	B3	S08
612 USA	152303 E84	USA	Q21	V05	B3	S08
817 USA	152020 E84	USA	Q21	V05	B3	S08
714 USA	171052 E84	USA	Q21	V05	B3	S08
504 USA	123020	1 USA	Q21	V05	B3	S08
407 USA	124227 E84	USA	Q21	V05	B3	S08
719 USA	152048	2 USA	Q21	V05	B3	S08
949 USA	171034 E84	USA	Q21	V05	B3	S08
310 USA	171025	1 USA	Q21	V05	B3	S08
305 USA	124008	2 USA	Q21	V05	B3	S08
407 USA	124227 E84	USA	Q21	V05	B3	S08
618 USA	171040	1 USA	Q21	V05	B3	S08
972 USA	152017	1 USA	Q21	V05	B3	S08
478 USA	121500	2 USA	Q21	V05	B3	S08
512 USA	152308 E84	USA	Q21	V05	B3	S08
281 USA	152048	1 USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08
958 USA	152104 E84	USA	Q21	V05	B3	S08
949 USA	171074	1 USA	Q21	V05	B3	S08
915 USA	152210	1 USA	Q21	V05	B3	S08
618 USA	171040	1 USA	Q21	V05	B3	S08
580 USA	152558 E84	USA	Q21	V05	B3	S08
954 USA	124010	1 USA	Q21	V05	B3	S08
813 USA	124448	1 USA	Q21	V05	B3	S08
214 USA	152508	1 USA	Q21	V05	B3	S08
854 USA	121792	1 USA	Q21	V05	B3	S08

210 USA	152056	1 USA	Q21	V05	B3	S08
843 USA	121888	2 USA	Q21	V05	B3	S08
713 USA	152044	2 USA	Q21	V05	B3	S08
210 USA	152063	2 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
909 USA	171150	1 USA	Q21	V05	B3	S08
940 USA	152406 E84	USA	Q21	V05	B3	S08
903 USA	152446	2 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
972 USA	152001	1 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
254 USA	152481	1 USA	Q21	V05	B3	S08
281 USA	152037 E84	USA	Q21	V05	B3	S08
879 USA	152134 E84	USA	Q21	V05	B3	S08
337 USA	123248	1 USA	Q21	V05	B3	S08
512 USA	152020 E84	USA	Q21	V05	B3	S08
261 USA	152032 E84	USA	Q21	V05	B3	S08
704 USA	171095 E84	USA	Q21	V05	B3	S08
402 USA	153024	2 USA	Q21	V05	B3	S08
916 USA	172206	1 USA	Q21	V05	B3	S08
805 USA	171486	1 USA	Q21	V05	B3	S08
412 USA	144017	1 USA	Q21	V05	B3	S08
770 USA	141293 E84	USA	Q21	V05	B3	S08
207 USA	111559 E84	USA	Q21	V05	B3	S08
816 USA	148072	1 USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08
859 USA	147011	2 USA	Q21	V05	B3	S08
860 USA	111407 E84	USA	Q21	V05	B3	S08
207 USA	111212	1 USA	Q21	V05	B3	S08
262 USA	141304	2 USA	Q21	V05	B3	S08
810 USA	148048	1 USA	Q21	V05	B3	S08
859 USA	147301	1 USA	Q21	V05	B3	S08
313 USA	148020	1 USA	Q21	V05	B3	S08
708 USA	18958R	2 USA	Q21	V05	B3	S08
812 USA	147527	1 USA	Q21	V05	B3	S08
516 USA	113082	1 USA	Q21	V05	B3	S08
810 USA	148048	2 USA	Q21	V05	B3	S08



360 USA	174011	2 USA	Q21	V05	B3	S08
360 USA	174011 EB3	USA	Q21	V05	B3	S08
703 USA	127049	1 USA	Q21	V05	B3	S08
610 USA	116402	1 USA	Q21	V05	B3	S08
668 USA	148595	2 USA	Q21	V05	B3	S08
973 USA	113482 EB4	USA	Q21	V05	B3	S08
732 USA	113055	1 USA	Q21	V05	B3	S08
417 USA	153480	1 USA	Q21	V05	B3	S08
317 USA	147027	1 USA	Q21	V05	B3	S08
410 USA	127558	1 USA	Q21	V05	B3	S08
407 USA	124900	1 USA	Q21	V05	B3	S08
361 USA	152096	2 USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08
972 USA	152013	1 USA	Q21	V05	B3	S08
818 USA	171043	1 USA	Q21	V05	B3	S08
972 USA	152007	1 USA	Q21	V05	B3	S08
562 USA	171047	1 USA	Q21	V05	B3	S08
918 USA	152498	1 USA	Q21	V05	B3	S08
908 USA	171108	1 USA	Q21	V05	B3	S08
630 USA	152752	1 USA	Q21	V74	B3	S08
408 USA	172402	2 USA	Q21	V05	B3	S08
760 USA	171078	2 USA	Q21	V05	B3	S08
760 USA	171423	1 USA	Q21	V05	B3	S08
628 USA	171068	1 USA	Q21	V05	B3	S08
205 USA	121406	1 USA	Q21	V05	B3	S08
337 USA	123276	1 USA	Q21	V05	B3	S08
757 USA	124016 EB4	USA	Q21	V05	B3	S08
310 USA	171015	1 USA	Q21	V05	B3	S08
713 USA	152049	1 USA	Q21	V05	B3	S08
757 USA	127080	1 USA	Q21	V05	B3	S08
903 USA	152440	2 USA	Q21	V05	B3	S08
727 USA	124202	1 USA	Q21	V05	B3	S08
617 USA	121213	2 USA	Q21	V05	B3	S08
612 USA	152302 EB1	USA	Q21	V05	B3	S08
604 USA	123008	1 USA	Q21	V74	B3	S08
903 USA	152707	1 USA	Q21	V05	B3	S08
305 USA	124003	1 USA	Q21	V05	B3	S08

801 USA	123002 EB4	USA	Q21	V05	B3	S08
819 USA	124208	2 USA	Q21	V05	B3	S08
USA	171154 EB4	USA	Q21	V05	B3	S08
770 USA	121488	2 USA	Q21	V05	B3	S08
828 USA	171083	1 USA	Q21	V05	B3	S08
708 USA	141053 EB4	USA	Q21	V05	B3	S08
810 USA	121224	1 USA	Q21	V05	B3	S08
388 USA	124444	1 USA	Q21	V05	B3	S08
872 USA	152007	2 USA	Q21	V05	B3	S08
854 USA	124010	1 USA	Q21	V05	B3	S08
210 USA	182007	2 USA	Q21	V05	B3	S08
512 USA	152087	2 USA	Q21	V05	B3	S08
870 USA	123001	2 USA	Q21	V05	B3	S08
281 USA	152055	1 USA	Q21	V05	B3	S08
848 USA	121338	1 USA	Q21	V05	B3	S08
819 USA	171088	1 USA	Q21	V05	B3	S08
727 USA	124202	1 USA	Q21	V05	B3	S08
708 USA	121215	1 USA	Q21	V05	B3	S08
501 USA	123205 EB4	USA	Q21	V05	B3	S08
210 USA	152057 EB4	USA	Q21	V05	B3	S08
281 USA	182032 EB4	USA	Q21	V05	B3	S08
404 USA	121007 EB4	USA	Q21	V05	B3	S08
337 USA	123208 EB4	USA	Q21	V05	B3	S08
314 USA	153078	2 USA	Q21	V05	B3	S08
818 USA	171029 EB4	USA	Q21	V05	B3	S08
281 USA	152037	1 USA	Q21	V05	B3	S08
702 USA	171187	1 USA	Q21	V05	B3	S08
727 USA	124205	1 USA	Q21	V05	B3	S08
817 USA	152018	1 USA	Q21	V05	B3	S08
407 USA	124227	1 USA	Q21	V05	B3	S08
708 USA	121205	2 USA	Q21	V05	B3	S08
805 USA	171472	1 USA	Q21	V05	B3	S08
808 USA	172203 EB4	USA	Q21	V05	B3	S08
815 USA	152211	1 USA	Q21	V05	B3	S08
817 USA	152001 EB4	USA	Q21	V05	B3	S08
809 USA	171108	1 USA	Q21	V05	B3	S08
530 USA	172208	2 USA	Q21	V05	B3	S08

602 USA	171176 EB4	USA	Q21	V05	B9	S08
817 USA	152018 EB4	USA	Q21	V05	B9	S08
727 USA	124205 EB4	USA	Q21	V03	B9	S08
704 USA	121213	1 USA	Q21	V05	B9	S08
704 USA	121213 EB4	USA	Q21	V05	B9	S08
210 USA	152204	2 USA	Q21	V05	B9	S08
972 USA	152002	1 USA	Q21	V05	B9	S08
817 USA	152009 EB4	USA	Q21	V05	B9	S08
925 USA	172023	1 USA	Q21	V05	B9	S08
939 USA	152166	1 USA	Q21	V05	B9	S08
841 USA	124480	1 USA	Q21	V05	B9	S08
281 USA	152029 EB4	USA	Q21	V05	B9	S08
780 USA	171079	2 USA	Q21	V05	B9	S08
770 USA	121023 EB4	USA	Q21	V74	B9	S08
803 USA	171251 EB4	USA	Q21	V05	B9	S08
834 USA	121226	1 USA	Q21	V05	B9	S08
228 USA	121573	1 USA	Q21	V05	B9	S08
702 USA	171189	1 USA	Q21	V05	B9	S08
704 USA	121213 EB4	USA	Q21	V05	B9	S08
972 USA	152002	1 USA	Q21	V05	B9	S08
915 USA	152573	1 USA	Q21	V05	B9	S08
562 USA	171055	1 USA	Q21	V05	B9	S08
407 USA	124214 EB4	USA	Q21	V71	B9	S08
310 USA	171015	1 USA	Q21	V05	B9	S08
305 USA	124001	1 USA	Q21	V05	B9	S08
936 USA	152158	2 USA	Q21	V05	B9	S08
814 USA	147018	1 USA	Q21	V05	B9	S08
409 USA	162771	1 USA	Q21	V05	B9	S08
910 USA	121025 EB4	USA	Q21	V74	B9	S08
708 USA	141052	2 USA	Q21	V05	B9	S08
337 USA	123271 EB4	USA	Q21	V03	B9	S08
802 USA	171178 EB4	USA	Q21	V05	B9	S08
338 USA	121619	2 USA	Q21	V05	B9	S08
318 USA	123223	2 USA	Q21	V05	B9	S08
407 USA	124224	1 USA	Q21	V05	B9	S08
958 USA	152772	1 USA	Q21	V05	B9	S08
936 USA	152166 EB4	USA	Q21	V05	B9	S08

915 USA	152018	2 USA	Q21	V05	B3	S08
407 USA	124228	1 USA	Q21	V05	B3	S08
714 USA	171009	2 USA	Q21	V05	B3	S08
910 USA	121224	1 USA	Q21	V05	B3	S08
281 USA	152024 EB4	USA	Q21	V05	B3	S08
814 USA	147312	1 USA	Q21	V05	B3	S08
872 USA	152482	2 USA	Q21	V05	B3	S08
407 USA	141448 EB4	USA	Q21	V05	B3	S08
881 USA	171481	1 USA	Q21	V05	B3	S08
828 USA	171072	1 USA	Q21	V05	B3	S08
214 USA	152003	1 USA	Q21	V05	B3	S08
770 USA	121405 EB4	USA	Q21	V05	B3	S08
801 USA	123308	1 USA	Q21	V05	B3	S08
713 USA	152188	2 USA	Q21	V05	B3	S08
909 USA	171183	1 USA	Q21	V05	B3	S08
908 USA	171153	1 USA	Q21	V05	B3	S08
813 USA	124208 EB4	USA	Q21	V05	B3	S08
281 USA	152032 EB4	USA	Q21	V05	B3	S08
828 USA	171072	2 USA	Q21	V05	B3	S08
206 USA	121011	1 USA	Q21	V05	B3	S08
817 USA	152020 EB4	USA	Q21	V05	B3	S08
703 USA	127044	2 USA	Q21	V05	B3	S08
703 USA	127044 EB4	USA	Q21	V05	B3	S08
225 USA	123148 EB4	USA	Q21	V05	B3	S08
510 USA	172008	1 USA	Q21	V05	B3	S08
704 USA	121213	1 USA	Q21	V05	B3	S08
323 USA	171007	1 USA	Q21	V05	B3	S08
813 USA	124445 EB4	USA	Q21	V05	B3	S08
210 USA	152057	1 USA	Q21	V05	B3	S08
819 USA	171078	1 USA	Q21	V05	B3	S08
337 USA	123271	1 USA	Q21	V03	B3	S08
702 USA	171189 EB4	USA	Q21	V05	B3	S08
251 USA	124017 EB4	USA	Q21	V05	B3	S08
915 USA	152210	1 USA	Q21	V05	B3	S08
915 USA	152210 EB4	USA	Q21	V05	B3	S08
512 USA	152740 EB4	USA	Q21	V05	B3	S08
986 USA	123050	1 USA	Q21	V05	B3	S08

818 USA	171088	2 USA	Q21	V05	B3	S08
872 USA	152012	2 USA	Q21	V05	B3	S08
872 USA	152002	1 USA	Q21	V05	B3	S08
408 USA	172039	1 USA	Q21	V05	B3	S08
601 USA	123808 E84	USA	Q21	V05	B3	S08
954 USA	124015 E84	USA	Q21	V05	B3	S08
954 USA	124015 E90	USA	Q21	V05	B3	S08
780 USA	171102	1 USA	Q21	V05	B3	S08
606 USA	171104 E84	USA	Q21	V05	B3	S08
512 USA	152903	1 USA	Q21	V05	B3	S08
713 USA	152024 E84	USA	Q21	V05	B3	S08
209 USA	172402 E84	USA	Q21	V05	B3	S08
214 USA	152014	1 USA	Q21	V74	B3	S08
780 USA	171102 E84	USA	Q21	V05	B3	S08
770 USA	121003 E84	USA	Q21	V05	B3	S08
214 USA	152003	1 USA	Q21	V05	B3	S08
770 USA	121025	2 USA	Q21	V05	B3	S08
770 USA	121039	1 USA	Q21	V05	B3	S08
828 USA	171037	1 USA	Q21	V05	B3	S08
512 USA	152802 E84	USA	Q21	V05	B3	S08
229 USA	121408	1 USA	Q21	V05	B3	S08
210 USA	152083 E84	USA	Q21	V05	B3	S08
828 USA	171072	1 USA	Q21	V05	B3	S08
409 USA	152753 E84	USA	Q21	V05	B3	S08
252 USA	121641	2 USA	Q21	V03	B3	S08
918 USA	152535	1 USA	Q21	V05	B3	S08
281 USA	152052	1 USA	Q21	V05	B3	S08
714 USA	171052	1 USA	Q21	V05	B3	S08
770 USA	121480 E84	USA	Q21	V05	B3	S08
905 USA	171439	1 USA	Q21	V05	B3	S08
818 USA	171040	2 USA	Q21	V05	B3	S08
386 USA	124200 E84	USA	Q21	V05	B3	S08
912 USA	121209	1 USA	Q21	V05	B3	S08
828 USA	171015 E84	USA	Q21	V05	B3	S08
780 USA	171427 E84	USA	Q21	V17	B3	S08
919 USA	121026	2 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08

281 USA	152055	1 USA	Q21	V05	B3	S08
817 USA	152408	1 USA	Q21	V05	B3	S08
956 USA	152093	1 USA	Q21	V05	B3	S08
602 USA	171178 E84	USA	Q21	V05	B3	S08
956 USA	124125 E84	USA	Q21	V05	B3	S08
770 USA	121858	2 USA	Q21	V05	B3	S08
337 USA	123264	2 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
972 USA	152520	2 USA	Q21	V05	B3	S08
252 USA	121820 E84	USA	Q21	V05	B3	S08
818 USA	171040	2 USA	Q21	V05	B3	S08
281 USA	152241	2 USA	Q21	V05	B3	S08
573 USA	152183	2 USA	Q21	V05	B3	S08
818 USA	171040	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
619 USA	171078	1 USA	Q21	V05	B3	S08
770 USA	121025	2 USA	Q21	V74	B3	S08
912 USA	121208	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
580 USA	152510	2 USA	Q21	V05	B3	S08
770 USA	121058	1 USA	Q21	V05	B3	S08
704 USA	121212	1 USA	Q21	V05	B3	S08
601 USA	123307 E84	USA	Q21	V05	B3	S08
931 USA	123073	1 USA	Q21	V05	B3	S08
214 USA	152093	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
USA	171171	2 USA	Q21	V05	B3	S08
817 USA	152010	2 USA	Q21	V05	B3	S08
310 USA	171040 E84	USA	Q21	V05	B3	S08
258 USA	121707 E84	USA	Q21	V05	B3	S08
225 USA	123978	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
770 USA	121025	2 USA	Q21	V74	B3	S08
954 USA	124009	1 USA	Q21	V05	B3	S08
817 USA	152016	1 USA	Q21	V05	B3	S08
864 USA	121795 E84	USA	Q21	V05	B3	S08
908 USA	171424 E84	USA	Q21	V05	B3	S08

770 USA	121007 E84	USA	Q21	V05	B3	S08
USA	171448	1 USA	Q21	V05	B3	S08
916 USA	172201 E84	USA	Q21	V05	B3	S08
818 USA	171040 E84	USA	Q21	V06	B3	S08
225 USA	123145 E84	USA	Q21	V05	B3	S08
915 USA	152580 E84	USA	Q21	V05	B3	S08
973 USA	113510	1 USA	Q21	V05	B3	S08
903 USA	152707	2 USA	Q21	V05	B3	S08
812 USA	158900	1 USA	Q21	V05	B3	S08
712 USA	153554	1 USA	Q21	V05	B3	S08
517 USA	148517	2 USA	Q21	V05	B3	S08
562 USA	171011 E84	USA	Q21	V05	B3	S08
931 USA	123253	1 USA	Q21	V05	B3	S08
617 USA	111010	1 USA	Q21	V05	B3	S08
972 USA	152001	1 USA	Q21	V05	B3	S08
802 USA	171178 E84	USA	Q21	V05	B3	S08
732 USA	18921N E84	USA	Q21	V05	B3	S08
573 USA	123230	2 USA	Q21	V05	B3	S08
312 USA	141075	1 USA	Q21	V05	B3	S08
901 USA	123006 E84	USA	Q21	V05	B3	S08
972 USA	152002	1 USA	Q21	V05	B3	S08
631 USA	113103	1 USA	Q21	V05	B3	S08
618 USA	118538	2 USA	Q21	V05	B3	S08
989 USA	148525	1 USA	Q21	V05	B3	S08
209 USA	158011	2 USA	Q21	V05	B3	S08
580 USA	152851	1 USA	Q21	V05	B3	S08
515 USA	141432	2 USA	Q21	V05	B3	S08
219 USA	148025 E84	USA	Q21	V05	B3	S08
643 USA	121305	2 USA	Q21	V05	B3	S08
802 USA	171178	1 USA	Q21	V05	B3	S08
920 USA	141603	1 USA	Q21	V05	B3	S08
501 USA	123090	1 USA	Q21	V05	B3	S08
812 USA	124325 E84	USA	Q21	V05	B3	S08
228 USA	123074	1 USA	Q21	V05	B3	S08
702 USA	158543	2 USA	Q21	V05	B3	S08
802 USA	158582 E84	USA	Q21	V05	B3	S08
503 USA	174022	1 USA	Q21	V05	B3	S08

702 USA

172404

1 USA

Q21

V05

BS

S08