

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 4 OF 6
BOOKS 20 OF 43

WFO40. 026 CUSTOMER SAYS SEAT BELTS COME UNLATCHED WHILE DRIVING . POSSIBLE PART #1C32 2541303 CA

RECALL #01821 BOP HERE

CUSTOMER STATES CHECK DRIVERS SEAT BELT COMES LOOSE WHILE DRIVING, CHECK AND ADVISE

SEAT BELT LATCH NOT WORKING

INSTALL INSTALL BOP SEATBELT

R.C. PASSENGER FRONT SEAT BELT WILL NOT STAY LATCHED

SEAT BELT BUCKLE HARD TO SNAP IN

RT SEAT BELT WONT BUCKLE

REPLACE SEAT BELT

SEAT BELT BUCKLES

REPLACE DRIVERS BUCKLE AND MIDDLE SEAT BUCKLE PARTS ARE HERE

REPLACE R SEATBELT BUCKLES IN AN F200

SEAT BELT WONT ENGAGE PROPERLY PASS SIDE

BUCKLE COVER UNDONE

OK SEAT BELT WONT HOLD

TECH IS INSTALL PASSENGER SEAT BELT AND COVER

CUSTOMER STATES THAT THE FRONT SEAT BELT ON THE PASSENGER SIDE POPS OUT OF THE BUCKLE 5-8

INSTALL ORDERED SEAT BELTS

REPLACE THE RIGHT SIDE SEAT BELT ASSEMBLY AS PER PREVIOUS DIAGNOSIS

PASSENGER SIDE SEAT BELT FRONT LATCH

INSTALL RPT SEAT BELT RECEPTACLE

RECHECK SEAT BELTS

DRS PASS SEAT BELT VIBRATES LOOSE (AND TRIP) 1ST TIME WIND PART WONT STAY LOCKED.

AFTER INTERIOR OF CAB IS HOT (DRIVERS SEATBELT DOES NOT ALWAYS BUCKLE WILL POP OUT WHILE DRIVING

IF SEAT BELT COMES UNBUCKLED PART ON ORDER STEVE KRULL R 61 BUCKLE R FROM STOCK UNIT 15229 TAB 3845

BOTH SEAT BELT BUCKLES ARE BAD

SEAT BELTS IN VEHICLE STICK AND HARD TO REMOVE

CS DRIVERS SEATBELT BUCKLE MISSING

CUSTOMER STATES VEH SEAT BELT BOP

INSTALL BPO

SEAT BELT

USE BPO 01 254008

DRIVERS SEAT BELT BUCKLE INSTALL, BOP HERE

CUSTOMER STATES RIDE SEATBELT COMES UNLATCHED WHILE DRIVING PARTS IN

DRIVERS SEATBELT BUCKLE INCP

SEAT BELT ON DRIVERS SIDE KEEPS COMING UNLATCHED

CUSTOMER STATES PASS SIDE SEAT BELT COMES UNDONE BY ITSELF

DRS FRONT SEAT BELT WONT LATCH

CHECK AND REPAIR DRIVERS SEATBELT DOES NOT LATCH

INSTALL BCP SEATBELT BUCKLES

CHECK FOR SEATBELT ON DRIVERS SIDE WONT LOCK WHEN IT DOES IT WILL UNLOCK ITSELF

REPLACE DRIVERS SIDE SEAT BELT

PERFORM RECALL #1621

THE DRIVERS SEATBELT DOES NOT LATCH AND UNLATCH PROPERLY

PASSENGER SEAT BELT WILL NOT STAY LATCHED

DRIVERS SEAT BELT WONT STAY LATCHED

REPL SEAT BELT BUCKLE

REPLACED RIGHT FRONT SEATBELT.

LEFT FRONT SEAT BELT BUCKLE FAULTY REPLACE LEFT FRONT BUCKLE

REPLACED SEAT BELT PASSENGER SIDE MISSING

PERFORMED THE RECALL AS OUTLINED

INSPECTED AND ORDERED SEATBELT BUCKLE AS PER RECALL #01 S 21

REPLACED RIGHT FRONT SEAT BELT BUCKLE

WAS BY WASH. ROAD TEST. NEED TO UNLATCH BUCKLE, INSERT ON BELT, RETEST BELT RETRACTOR AND LOCK, OK.

PERFORMED DIAG. PULLED CODE P1260 REPROGRAM HYDRO INSTRUMENT CLUSTER WITH 2 KEYS

DRIVERS SIDE SEAT BELT BUCKLE REPLACE SEAT BELT BUCKLE

DEFECTIVE PARTS @SEATBELT ASSEMBLY FRONT REPLACE

REPLACED THE BUCKLE

INSPECT AND REPL SEATBELT

SEAT BELT LOCKS AT BEGINNING OF BELT

23848 01321 RECALL W. INSPECTED AND REPLACED BOTH FRONT SEAT BELT BUCKLES WITH NEW. RETESTED ALL OK AT THIS TIME 2280

PERFORMED THE RECALL AS OUTLINED

WINNIG HARNESS LOCKS AND SEAT BELT BUCKLE HAD HIGH RESISTANCE. REPLACED SEAT BELT BUCKLE AND REPAIRED HARNESS 136506 1 1000001 2 1000001X1 1 1000002 3 140004 4

REPLACE PERFORMED

1 INSTALLED SEATBELT RECEPTILES

SEATBELT ASSEMBLY FRONT REPLACE

PERFORMED THE RECALL AS OUTLINED

INSPECTED AND REPLACED RIGHT FRONT BUCKLE

PERFORMED THE RECALL AS OUTLINED

PERFORM DIAG FOR INTERMITTENT AIR BAG LIGHT CODE B386 F IN POINT TESTS CONCLUDE BUCKLE DEFECTIVE REPLACE AND RECHECK OK

RAR DRIVERS SEAT TO DISCONNECT WIRE CONNECTOR FOR SEAT WARNING IN BUCKLE RAR BUCKLE

1 DIAGNOSE ELECTRICAL SYSTEM REPLACE LEFT FRONT SEAT BELT ASSEMBLY

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

42 TESTED BOTH FT SEAT BELT BUCKLES AS PER RECALL BOTH FAILED TEST REPLACED BOTH FT SEAT BELT BUCKLES AS PER RECALL

PERFORMED THE RECALL AS OUTLINED

VERIFIED CONCERN, DIAG AIR BAG SYSTEM, PINPOINT TEST, REPAIR SEAT & REPLACED SEAT BELT BUCKLE. HES ON DEMAND TEST, CLEAR DODGES

PERFORMED THE RECALL AS OUTLINED

REPLACE SEAT BELT BUCKLES

PERFORMED THE RECALL AS OUTLINED

SAFETY RECALL COMPLETE

REPLACE RIGHT FRONT SEAT BELT FOR SOLD UNIT STOCK NO 13827 SEAT BELT DISCOLORED ON BINING

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

REPLACED DRIVERS SEAT BELT BUCKLE ASBY

REPLACE SEAT BELT ON DR SIDE

REPLACED SEAT BELT AND PASS FRONT SIDE

DIAG AND REPLACED SEAT BELT LATCH ASBY

END FRONT HOLD. REPLACE WITH NEW CP851172A

FRONT LATCH SEATBELT ASSEMBLY FRONT REPLACE

INSTALLED NEW SEAT BELT BUCKLE QC481644

REPLACED RIGHT FRONT SEATBELT.

1 REPLACE DRIVERS SEAT BELT

REPLACED DRIVERS FRONT SEAT BELT BUCKLE ASSEMBLY.

LATCH INOP

VERIFY CONCERN SEAT BELT DOES NOT LATCH AT TIMES REPLACED DRIVER'S

BY 764 0.9 DIAMETER, HAD TO REMOVE L.F. SEAT TO TAKE SEAT BELT OUT, STUD WAS CROSS THREADED, RE TAP STUD AND INSTALL NEW BUCKLE TURN IN OLD SEAT BELT BUCKLE, FOR WF

REPLACED SEAT BELT BUCKLE

REPLACED PASSENGERS FRONT SEAT BELT BUCKLE

SEAT BELT DOES NOT STAY BUCKLED RMR BUCKLE RECHECK GOOD

RMR DRIVERS SEAT BELT LATCH

SEAT BELTS RELEASE INTERMITTENTLY, SEAT BELT LOOSE REPLACE BOTH FRONT SEAT BELTS AND 540120R 42

R004-011 05347

CHECKED FOUND BUCKLE ON ONE BELT HARD TO LOCK AND THE OTHER THE TENSION IS NOT HOLDING. REPLACED BOTH

REPLACE SEATBELT'S BONDING

REPLACE SEAT BELT BUCKLE

LATCH INOP. SEATBELT ASSEMBLY FRONT. REPLACE

30143 DRIVERS BELT BUCKLE NOT PERFORMED TEST ON BUCKLE BUCKLE NOT WORKING, DISCONNECTED WIRING, NEW BUCKLE, CODE 45, PART# 2881285, BUCKLE NOW WORKING

REMOVED SEAT BELT LATCH BUCKLE FROM BORROWED EXCURSION AND TEMPORARILY INSTALLED TO THIS R.O. DEFECTIVE LATCH BUCKLE IS ON MY TOOLBOX WHILE WAITING FOR ORDERED BUCKLE. REMOVED BORROWED SAFETY BUCKLE.

REMOVED AND REPLACED DRIVERS SIDE REMOVED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE

REPL BUCKLE ASSY W/PI

REPLACED RIGHT SEAT BELT BUCKLE

TEST ALL SEAT BELTS PASSENGER SIDE FAILED R AND R SEAT TO INSTALL NEW SEAT BELT BUCKLE ASSY DUE TO BEING BROKEN

2124 VERIFIED THAT THE DRIVERS SEATBELT BUCKLE NOT LATCHING ALL OF THE TIME. FOUND IT NECESSARY TO REMOVE DRIVERS SEAT FOR ACCESS AND REPLACE BUCKLE. RETEST OK HAD TO ORDER ONE SEAT BOLT FROM G

BROKEN SEATBELT ASSEMBLY FRONT REPLACE

FAILED BUCKLE TEST REMOVED RT FRNT SEAT TO GAIN ACCESS & REPLACED SEAT BELT PASSENGER

1) AND 1 PASS SEAT AND REPLACE BUCKLE

REPLACED FAULTY PASSENGER BUCKLE

REPLACE RS SEAT BELT BUCKLE

1) VERIFIED COMPLAINT. REPLACED BUCKLE WITH NEW ONE. BEST OK, WORKING PROPERLY.

1) REPLACED DRIVERS SIDE SEAT BELT AND PULLED CENTER SEAT BELT OUT OF COVER AND REPAIRED

REMOVE BOTH FRONT SEATS AND REPLACED BOTH SEAT BELT BUCKLES, RETEST OK

VERIFIED CONCERN AND INSPECTED THE SEAT BELT ASSEMBLY FOUND THE DRIVERS SEAT BUCKLE TO BE WOP NOT ALLOWING THE BELT TO LATCH REPLACE THE DRIVERS SEAT BELT BUCKLE ASSEMBLY ON CAPTAINS CHAIR AND RETE

SEAT BELT DEFECTIVE, REPLACE SEAT BELT BUCKLE ASBY

REPLACE LT SEAT BELT BUCKLE

REPL SEAT BELT

BUCKLES DEFECTIVE NECESSARY TO REPLACE

DRIVERS SEATBELT WILL UNLATCH AT TIMES BY ITSELF. REPLACE SEAT BELT. RETEST, OK

REOPEN LATCH

REPLACE L F SEAT BELT LATCH

2826 SOMONE ORDERED LF SEAT BELT BUCKLE 7179 INSTALLED NEW BUCKLE SEAT BELT IS WORKING PROPERLY AT THIS TIME NOTE HAD TO REMOVE CHILD SEAT BEHIND DRIVER SEAT TO GET UNDER SEAT DID NOT REINSTALL CH

REPLACE BOTH FRONT SEATBELT LATCHES FOR CUSTOMER SAFETY CONCERN

CHECK DRIVERS SEAT BELT DIAGNOS AND REPLAC DRIVERS SIDE SEAT BELT BUCKLE COMES LOOSE

INSPECTED AND FOUND LOOSE DRIVERS SIDE SEAT BELT BUCKLE, REPLACED BUCKLE IN TIME LINED AS NO OPS AVAILABLE FOR BUCKLE, OK FOR PA.

SEAT BELT TONGUE WILL NOT HOLD REPLACE SEAT BELT TONGUE ON DRIVERS SEAT

REPLACED DRIVERS SIDE SEAT BELT BUCKLE

RE VERIFIED COMPLAINT REPLACE DRIVERS SIDE SEAT BELT BUCKLE

NOT LOCKING PROPERLY REPLACE DR SIDE SEAT BELT BUCKLE

10456 2561200 CC 42 VERIFY CONCERN REPLACE DRIVERS SEAT BELT BUCKLE VERIFY REPAIR TECH 4441

REPLACED BOTH FRONT BUCKLES.

FOUND SEATBELT WILL NOT ALWAYS LATCH CORRECTLY. REPLACE LEFT FRONT SEATBELT

REAR INSTRUMENT TIME TO REPLACE SEAT BELT BUCKLES

FRONT INSTRUMENT TIME TO REPLACE SEAT BELT BUCKLE

RECALL

RECALL

WOULD NOT RETRACT SEATBELT ASSEMBLY FRONT REPLACE

TIME TO REPLACE LEFT FRONT SEAT BELT BUCKLE

OUT OF ALIGNMENT WASH REALIGN BELT FOR SHIP, MIDDLE SEAT BELT

20 REGALL #1821 INSPECTED BOTH FRONT SEAT BELT BUCKLES BOTH FAILED. REMOVED AND INSTALLED BOTH FRONT SEAT BELT BUCKLES. POWER BUCKETS. NO SIR

1 REPLACED ON SEAT BELT LATCH

LOCK (SEIZED) AIR SEAT BELT LOCK RETEST OK

DIAGNOSIS FOUND THAT THE SWITCH IN BUCKLE IS NOT WORKING, DOESNT OPEN CIRCUIT WHEN BELT IS INSERTED. REPLACED BUCKLE. NO LABOR OR USED IN TIME

VERIFIED CONCERN. FOUND RIGHT FRONT SEAT BELT BINDING IN BUCKLE ASSEMBLY. NOW OPS NORMALLY

7109 REPLACED L SEAT BELT BUCKLE

BUCKLE INSTALL BOTH SEATBELT BUCKLE

S SEATBELT WAS CHECKED AND FAILED THEN WAS REPLACED AND RETESTED AND PASSED THE MILEAGE SHOULD BE 11

RIGHT FRONT SEAT BUCKLE INOP. REPLACE BELT BUCKLE ASSEMBLY, BRINDAL INOP

RECALL 81381 REPLACED L AND R SEAT BELT BUCKLES PER RECALL POWER BUCKET SEATS

RENTAL RENTAL

RENTAL RENTAL

NEED TO REPLACE SEAT BELT

LONG REMOVE DRIVER SEAT AND REPLACE BELT.

FR B PILLAR TRIM FR SEAT BELT INSTALL BUDDER TRIM ALSO REPL BELT BUCKLE MOF

REPLACED SEAT BELT FR FR ED KARAZIN

6000 41 REPLACE FRONT SEATBELT BUCKLE

01821 01821

REPLACE SEATBELT ASSEMBLY FRONT REPLACE

RT AND LT SEATBELT BUCKLES WILL NOT STAY LATCH ONTO BELT

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

LUBED HOOD AND DOOR HINGES

PERFORMED THE RECALL AS OUTLINED

PERFORMED THE RECALL AS OUTLINED

REPLACE R FRONT SEAT BELT BUCKLE ASSY FOR WILL NOT LATCH CONCERN

REPLACED SEAT BELT BUCKLE

BROKEN SEAT BELT ASSEMBLY FRONT REPLACE

REPLACED FRONT FRONT SEAT BELT BUCKLE BRINDEN 4L

REPLACE SEAT BELT ASBY

REMOVED SEAT BELT SEAT BELT ASBY, RECHECKED OK

REPLACED RIGHT SEATBELT BUCKLE

REPLACED SEAT BELT ASBY

TEST AND FOUND PASSENGER SEAT BELT BUCKLE INOP. DISINTEGRATED. WON'T LATCH PROPERLY. REMOVE AND REPLACE PASSENGER SEAT BELT BUCKLE. OK. RETEST OK.

DOESN'T OPERATE PROP. SEATBELT ASSEMBLY FRONT. REPLACE

REPLACED SEAT BELT AND BUCKLE

REPLACED BELT & BUCKLE

1 REPLACED LEFT FRONT SEAT BELT BUCKLE

TIGHTENED ALL BELT BOLTS 1

INSPECT BELTS, BELT RETRACTED INTO SEAT BELT COVER, IF IN SEAT BELT ASSEMBLY, REMOVE RIVETS THAT HOLD COVER TO BELT

OPENS REPLACES SEAT BELT

0001 Repair (vehicle) (type) TECH TX12

PLACED PARKING BRACKET PER RECALL. THERE ARE NO MY719 FOR DRIVERS BUOY REPLACEMENT.

RELEASED ON NO REASON SHOULD HAVE BEEN MADE NOT 24208

1324 42 WMB40 ROAD TEST TEST SEAT BELT SYSTEM REPLACED BOTH FRONT SEAT BELT BUCKLE ASSYS POST TEST

PERFORMED RECALL 1421 REPLACED BOTH SEAT BELT BUCKLES RECALL WAS CLOSED OUT BY BRITTE FORD SEATBELTS WERE NOT REPLACED

INSPECTED AND REPLACED DEFECTIVE SEAT BELT LATCH ASSY. RE TESTED OK
ORDERED PART. REPLACED SEAT BELT ASSEMBLY

REPLACE SEAT BELT

1422 INSTALL SOP SEATBELT REPL DRIVER SIDE RECEIVER CHECKS OK

REPLACED PASS SIDE AND INR PASS SIDE BUCKLE

SEAT BELT WONT LOCK REPLACE SEAT BELT

REPLACE BOTH SEAT BELT BUCKLES

48 REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE

REPLACED BOTH SEATBELT ABY

SEAT BELT WILL NOT ENGAUGE PROPERADDITIONAL MISC REPAIRS

REPLACE BUCKLE

REPLACE PASS SIDE SEAT BELT

REPLACED MAT AND COVERS

CAUS 7891232 C02 B40 DC 501 REPLACED SEAT BELT BUCKLE ON PASS SIDE FRONT SEAT OLD ONE WOULD NOT LATCH

8102 SEAT BUCKLE INSTALL FRONT LH R SEAT BUCKLE SEAT BULK

REPLACE THE RIGHT SIDE SEAT BELT ASSEMBLY

PASS FRONT SEAT BELT LATCH WONT ALWAYS LATCH REMOVE SEAT AND REPLACE BELT BUCKLE

10025 REPLACED PASS SEAT BELT RECEPTACLE/SEAT THAT

SEAT BELT ASSEMBLY SEATBELT ASSEMBLY FRONT REPLACE

REPL R R R RTT SEAT ASSY, REPLACED RIGHT SEAT BELT BUCKLE BUCKLE PRETENSIONER ASSY, CK OR COG

REPLACE LF SEAT BELT BUCKLE

REMOVED DRV SEATBELT BUCKLE AND REPLACED WITH BUCKLE FROM STX UNIT NECESSARY TO REMOVE DRV SEAT FOR ACCESS. FULL CLAIM JUNE APPROVAL #771W

1. REPLACED LPT AND RT FRT SEAT BELT BUCKLES

REPLACED BELTS AND LOCKS. TRIED TO CLEAN STILL DONT WORK

REMOVED DRIVERS SEAT INSTALL SEAT BELT AND BUCKLE ASSEMBLY

CHECK AND REPLACE BOTH FRONT SEAT BELT BUCKLES BOTH FRONT BUCKLES JAMMING UP

INSTALLED LT SEAT BELT

INSTALLED DRIVERS SEAT BELT BUCKLE INNER BUCKLE INOPERATIVE

BT184 PASS SIDE SEAT BELT BUCKLE INCP (CODE 42) IMPROV VERIFY PASS SIDE SEAT BELT BUCKLE. INOP WOULD NOT BUCKLE RM PASS SIDE SEAT BAR PASS SIDE SEAT BELT BUCKLE & WIRING TO SEAT REASSEMBLE & RETEST

BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE

OK SEAT BELT DOES NOT LATCH PROPERLY INSIDE LEFT FEMALE END OF BUCKLE. REMOVE SEAT AND REPLACE SEAT BELT.

R AND R PASS SIDE SEAT BELT BUCKLE

REPLACE DRIVER SIDE SEAT BELT

REMOVE AND REPLACE LATCH SIDE OF BELT DUE TO STICKING TEST OK

REMOVE LEFT FRONT SEAT TO REPLACE BUCKLE

SEAT BELT BUCKLE WAS MALFUNCTIONING. REPLACED SEATBELT BUCKLE

REPLACED DRIVERS SIDE SEAT BELT ASSEMBLY CHECK OK

COMPLETE AND INSTALL NEW BUCKLE DRIVERS SIDE
REPLACE SEATBELT LATCH ON LEFT SIDE

REPLACED SEAT BELT LATCH ASBY

REPLACED PASSENGER SEAT BELT

871 LATHED WONT REPLACE LATCHED

RIGHT AND LEFT FRONT SEATBELT BUCKLES NOT REPLACE RIGHT AND LEFT SEATBELT BUCKLES

<p>8901 Speed control system, CURT, TXZ</p>	<p>2801 Exp of next year, AREA, CD</p>
<p>CURT STATES THE DRIVERS SEAT BELT UNLATCHES WHILE DRIVING. CONCERN OCCURS INTERMITTENTLY. CK & ADM</p>	<p>808</p>
<p>RIGHT FRONT SEAT BELT WILL NOT CONNECT</p>	<p>818</p>
<p>RECALL SEAT BELT BUCKLE APPEARS TO PD 581718</p>	<p>291</p>
<p>848 OWNER STATES DRIVERS SEAT BELT WON'T STAY LATCHED AT TIMES. RED CAP DOESN'T COME BACK UP PROPER.</p>	<p>281</p>

CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING	764

CUSTOMER STATES LEFT FRONT SEATBELT UNLATCHES BY ITSELF FOR ROSSIGNOL M 13750 1 2 92

467

CUSTOMER STATES DR SEAT SEATBELT POPS OUT OF BUCKLE WHILE DRIVING

764

SEAT BELT ON DRIVERS SIDE WILL NOT STAY LOCKED	778
REPLACE DEFECTIVE SEATBELT BUCKLE	843
BPW	
FRONT SEAT BELTS DIFFICULT TO LATCH AT TIMES	898
PASSENGER SIDE SEAT BELT WILL NOT LATCH INTERMITTENT	921

	457
	76
	638
	612
	718
	917

	804
	830
	841
	818
	880
	777
	888
	488
	788
	800

	300
	300
	300
	300
	300
	300
	410

RC004-011 06385

RD04-011 06396

	701
	702
	703
	704
	705
	706
OK	707
	708
	709

	001
	100
	200
	300
	400
	500
	600
	700
	800
	900

	717
	818
	800
D & SEAT BELT DOESNT LOCK	.
RIGHT FRONT SEATBELT NOT LOCKING	808
DRIVER'S SEAT BELT WILL NOT LOCK	801
SEAT BELT MISSING ON DEALER TRANSFER ON PASS SEAT	708

RECALL 01821 DUE

CHECK AND ADVISE ON SEATBELT RECALL. ALSO MENTIONED SOMETHING ABOUT SECURITY SYS. PROB ON VEHICLE

808

849 FRONT PASS. SEATBELT INOP

817

GUEST STATES THE PASS SDE FRT SEATBELT MAY LOCK YOU IN ON BUMPS OR WHEN HITTING THE BRAKES

804

STALLS INTERMITTANTLY WHEN DRIVING WILL RESTART AFTER BITTING

828

CUST STATES DRIVERS SIDE SEAT BELT BUCKLE NOP	914
SEAT BELTS SOP	911
DRIVER SIDE FRONT SEAT BUCKLE NOP	
SEATBELT BUCKLE	913
	909
01821 FRONT SEAT BELT BUCKLE RECALL (TESTING AND REPLACEMENT IF FAILED). R Y IF PARTS ARE ORDERED.	312

RD04-011 06391

RECALL 01821 DUE	
CUSTOMER STATES AIR BAG LIGHT COMES ON AND OFF	738
RIGHT FRONT SEAT BELT FAILED PER RECALL 01821	538
INSTALL SEAT BELT RECEPICLES FOR RECALL	317
RT FT SEAT BELT POOR RETRAC	804

RO04-011 0539Z

RECALL 01821 DUE

CS REF TO RI 73139 MILES 21084 DATE 3 27 02 SEAT BELT

RECALL 01321 DUE

CHECK FOR INTERMITTANT AIR BAG LIGHT

INSTALL DRIVERS SEAT BELT

AIRBAG LIGHT ON IN DASH	
RECALL 01821 DUE	
PERFORM RECALL 01821	
RECALL 01821 DUE	
PERFORM OPEN CAMPAIGN... 01821... SEAT BELT BUCKLE.	814

RECALL 01S21 DUE

AIR BAG WARNING LIGHT IS ON

251

PERFORM RECALL 01S21

SEAT BELT BUCKLES INOP

815

PERFORM RECALL 01S21

RECALL 01S21 DUE