

RQ04-011
FORD
APRIL 26, 2005
REQUEST 8
PART 6 OF 6
BOOKS 21 OF 43

Windsor Recall Partname_MKT_DERIVED Windsor Recall Partname_BOD_CAS_BTL Windsor Recall Partname_VER_SERIES_CD Windsor Recall Partname_DRIVE_CD Windsor Recall Partname_ENG_CD

Waste Recd Performed_TRANS_CD Waste Recd Performed_PLANT_CD Waste Recd Performed_PROD_DT Waste Recd Performed_WREY_START_DT Waste Recd Performed_NAME

RCD4-011 06596

Windsor Recall Performed_DOC_NUM Windsor Recall Performed_PH_NUM Windsor Recall Performed_WGCC_CD Windsor Recall Performed_PART_NUM_CAUSE_PREF Windsor Recall Performed_PART_NUM_CHLIS_BASE

Windsor Recall Performed_PART_NUM_CAUSE_SUPP Windsor Recall Performed_COST_CODE_CD Windsor Recall Performed_CODE_CD Windsor Recall Performed_RPR_DT Windsor Recall Performed_TIS_WSD

RC004-011 06697

Windsor Recall Performed_CLM_KEY Windsor Recall Performed_MLOG Windsor Recall Performed_MTI COST Windsor Recall Performed_TOT_COST_GROSS Windsor Recall Performed_LBR_HRS

Windsor Recall Performed_DUR_CD Windsor Recall Performed_DUR_SALES_CD Windsor Recall Performed_REGION_CD Windsor Recall Performed_ST_PROV_CD Windsor Recall Performed_CPSC_CD
19982 19982 19982 19982 19982

Weldar Recell Performed TECH_TXT1

PERFORM NUMBER 0001, BOTH BELTS FAILED, REMOVED AND REPLACED WITH PVC BELT BY C.C. 88

Weldar Recell Performed TECH_TXT2

Weldar Recell Performed CUST_TXT

Weldar Recell Performed AREA_CO

RQ04-011 08800

Windows Retail Performed_COUNTRY_CD Windows Retail Performed_SLS_DIR_CD Windows Retail Performed_TON_CD Windows Retail Performed_ENTRY_SOLD Windows Retail Performed_QTY_CD
Q48 2004 2004 2004 2004 2004

Winter Recal Performed_VFG_CD Winter Recal Performed_AWR_ML_CD Winter Recal Performed_WRT_CD Winter Recal Performed_TIE_FLAG Winter Repeat_ID Winter Repeat_MDI_YR Winter Repeat_VA_CD
2001 2PMDAUS4218076403

RQ04-011 06602

Welder Report

R_COST Welder
10 24 TMB

Repeats_VEH_LINE_CD

Welder/Repeats_MKT_DERIVED

Welder Repeats_BOD_CAB_STL
TMB

Welder Repeats_VER_SERIES_CD

Welder Repeats_DRIVE_CD
TMB

Welder Repeats_EVG_CD
TMB

Writor: Repairs_TRANS_CD Writor: Repairs_PLANT_CD Writor: Repairs_PRODN_DT Writor: Repairs_WRTY_START_DT Writor: Repairs_NAME Writor: Repairs_DOC_NUM Writor: Repairs_PL_NUM
VCK AG 4/18/201 8/29/2011 DUNSWALL FORD SALES LTD 16703401 4680443

Windsor Reports_MCC_CD Windsor Reports_PART_NUM_CAUS_PREF Windsor Reports_PART_NUM_CAUS_BASE Windsor Reports_PART_NUM_CAUS_SUFF Windsor Reports_CURT_CONC_CD
5902 1F82 100000 AAA 540

Waste-Repairs_COND_CD	Waste-Repairs_RPR_DT	Waste-Repairs_TR_WHD	Waste-Repairs_CLM_KEY	Waste-Repairs_MLSE	Waste-Repairs_MTY_COST	Waste-Repairs_TOT_COST_GROSS
42	12/19/2001	6	562800	8018	16.70	38.73

RQ04-011 06806

Wisconsin Reports_LBR_HRS Wisconsin Reports_DLR_CD Wisconsin Reports_DLR_SUB_CD Wisconsin Reports_REGION_CD Wisconsin Reports_ST_PROV_CD Wisconsin Reports_CFSC_CD_#
04 0000 . NA OH 11001

4 1

RD04-011 08907

Wincdar Repairs_TECH_TXT1
REMOVED PAS FRNT SEAT BELT BUCKLE S DUE TO NOT STAYING LATCHES

Wincdar Repairs_TECH_TXT2
Wincdar Repairs_CUST_TXT
CHECK FOR PASSENGER SEAT BELT BUCKLE NOT STAYING LATCHED

Fwk58 Wincdar Repairs_AREA_CD
B 807

Winstar Reports_COUNTRY_CD	Winstar Reports_SLS_DLP_CD	Winstar Reports_TSNL_CD	Winstar Reports_CNTRY_SOLD	Winstar Reports_ORI_CD	Winstar Reports_MFG_CD	Winstar Reports_AWS_VL_CD
CAN	488002	1	CAN	021	406	A3

Window Reports_VRT_CD W-1000-Reports_TIS_FLAG
308

Days Between Repor /
42

Messages Between Repor
1794

RQ04-011 08610

Vendor Recall Performance_ID	Vendor Recall Performance_MDL_YR	Vendor Recall Performance_MN_CD	Vendor Recall Performance	PL_COST	Vendor Recall Performance	Vendor Recall Performance
88	2001		SPRZM4818	28.8	TRQ	
88	2001		SPRZM4818	47.08	TRQ	
88	2001		SPRZM14X18	48.47	TRQ	

Windsor Recall Performed_MKT_DERIVED	Windsor Recall Performed_SOI_CARTL	Windsor Recall Performed_VER_SERIES_CD	Windsor Recall Performed_DRIVE_CD	Windsor Recall Performed_ENG_CD
TAB	TAB	TAB	TAB	TAB
TAB	TAB	TAB	TAB	TAB
TAB	TAB	TAB	TAB	TAB

Windsor Recall Performed_TRANS_CD	Windsor Recall Performed_PLANT_CD	Windsor Recall Performed_PROD_DT	Windsor Recall Performed_WRTY_START_DT	Windsor Recall Performed_VIAM
1200	AS	3/28/00	3/28/00	42742801 LEO VENTURA MOTORS INC
1200	AS	1/28/00	1/28/00	37142801 ANTELOPE VALLEY FORD
1200	AS	4/28/00	4/28/00	12742801 PHILLIPS FORD, LLC

RQ04-011 06613

Widener Recall Performed_DOC_NUM	Widener Recall Performed_PH_NUM	Widener Recall Performed_WCC_CD	Widener Recall Performed_PART_NUM_CAUSE_PREF	Widener Recall Performed_PART_NUM_CAUSE_BASE
7988708	7488777			
8710540	8488888			
8810581	8688999			

Windsor Recall Performed_PART_NUM_DASH_SUFFIX Windsor Race Performed_CUST_CONC_CD Windsor Recall Performed_CONC_CD Windsor Recall Performed_RPR_DT Windsor Race Performed_TRL_WBD
0
8
0

Wendstar Recs- Performed_CLM_KEY	Wendstar Recall Performed_MLOG	Wendstar Recall Performed_MTP	OBT	Wendstar Recall Performed_TOT_COST_GROSS	W	Wendstar Recall Performed_LBR_HPS
2007144			224		54.22	
0210247			224		75.17	
0799001			448		97.38	

Winter Retail Performed_DUR_CD Winter Retail Performed_DUR_SUB_CD Winter Retail Performed_REGION_CD Winter Retail Performed_ST_PROV_CD Winter Retail Performed_CPSQ_CD_S
001 NA NA NC CA
002 NA NA CA CA
003 NA NA CA CA

Welder Recall Performed TECH_TXT1

Welder Recall Performed TECH_TXT1 Welder Recall Performed CUST_TXT1 Welder Recall Performed AREA_CD

RECALL 01821 INSPECT SEATBELT BUCKLES AND REPLACE IF FRONT BUCKLE PER RECALL
PERFORMED (RECALL 01821) INSPECTED AND REPLACED LEFT AND RIGHT SEAT BELT BUCKLES

Writer Race	Performed_COUNTRY_CD	Writer Race	Performed_USL_DLR_CD	Writer Race	Performed_TX_CD	Writer Race	Performed_CNTRY_SOLD	Writer Race	Performed_ORY_CD
USA		USA	01000	USA	01000	USA		USA	
USA		USA	01000	USA	01000	USA		USA	
USA		USA	01000	USA	01000	USA		USA	

WhoStar Recall Performed_VIN_CD	WhoStar Recall Performed_AWS_ML_CD	WhoStar Recall Performed_VRT_CD	WhoStar Recall Performed_TR_FLAG	WhoStar Repeat_ID	WhoStar Repeat_MDL_YR	WhoStar Repeat_VIN_CD
1000	AS	3001	0	100	2001	2FMZAS74G1ED09171
1000	AS	3001	0	111	2001	2FMZAS481R009060
1000	AS	3001	0	110	2001	2FMZAS14C1880220

Wrester Reports...	CSST	Wrester Reports_VEH_LINE_CD	Wrester Reports_MKT_DERIVED	Wrester Reports_BOOL_GAS_STL	Wrester Reports_VEH_SERIES_CD	Wrester Reports_DRYVS_CD	Wrester Reports_EAG_CD
	21 28	000	*	TANB	-	TAA	TALM
	21 80	000	*	TANB	-	TAA	TALM
	55 42	006	*	TANB	-	TAA	TALM

RC04-011 00621

W order Repeat TRANS_CD	W order Repeat PLANT_CD	W order Repeat FROM_DT	W order Repeat WRTY_START_DT	W order Repeat NAME	W order Repeat DOC_NUM	W order Repeat PH_NUM
TDX	AS	3/25/2001	03/12/01	LED VENTERS MOTORS INC	0152102	7488171
TDX	AS	10/8/2001	01/12/01	ANTILLOPE VALLEY FORD	0948121	9483288
TDX	AS	6/8/2001	12/12/01	PHIL LONG FORD OF CHAPEL HILL	28572188	5792200

W*ndstr* Rep*str*_MDC_CD	W*ndstr* Rep*str*_PART_NUM_CAUS_PREF	W*ndstr* Rep*str*_PART_NUM_CAUS_BASE	W*ndstr* Rep*str*_PART_NUM_CAUS_SUFF	W*ndstr* Rep*str*_CUST_CONC_CD
0F00	1FEZ	1001200 AAG		B00
0F00	1FEZ	1001200 BAA		B40
0R02	1FEZ	1001200 BAA		B40

Wrecker Repairs_COND_CD	Wrecker Repairs_RPR_DT	Wrecker Repairs_TUS_MSD	Wrecker Repairs_CLM_KEY	Wrecker Repairs_MILE	Wrecker Repairs_INTL_COST	Wrecker Repairs_TOT_COST_09038
41	11/22/01		4824399	3210	32.4	43.88
42	8/20/00		3431847	1507	32.4	48.29
43	1/22/00		6054880	1626	32.4	77.57

RD04-011 06824

Windsor Repairs_LBR_HRS	Windsor Repairs_DLR_CD	Windsor Repairs_DLR_SUB_CD	Windsor Repairs_REGION_CD	Windsor Repairs_ST_PROV_CD	Windsor Repairs_CFSQ_CD_FL
04 0911	*	*	NA	NC	11801
04 0428	*	*	NA	CA	11801
06 0134	*	*	NA	CO	11801

Wrench Repair TECH_TXT1

BUCKLE INSP SEATBELT ASSEMBLY FRONT REPLACE
INSP AND VERIFY LEFT FRONT SEAT BELT BUCKLE WORKS. REPLACED LEFT FRONT SEAT BELT BUCKLE. CHECK OPERATION OK

Wrench Repair TECH_TXT2

Windstar Reports_CUST_TXT
STATES PASSENGER SEAT BELT KEEPS COMING UNBUCKLED
CUST STATES DRIVERS SEAT BELT COMING OUT OF BUCKLE
CUST STATES DRIVER SEAT BELT POPS OUT ON ITS OWN CHECK ALL SEAT BELTS.

Field#	Windstar Reports_AREA_CD	Windstar Reports_CONTRY_CD	Windstar Reports_BRL_DRL_CD	Windstar Reports_TRX_CD
C	852 USA		121828	1
C	885 USA		171459	1
C	718 USA		188201	2

Winder Reports_CNTRY_SOLD	Winder Reports_CRT_CD	Winder Reports_VFR_CD	Winder Reports_AWS_VL_CD	Winder Reports_VTT_CD	Winder Reports_TUE_FLAG	Days Between Reports
USA	001	V05	A3	505		98
USA	021	V05	A3	505		48
USA	021	V05	A3	501		137

Chicago Business Center
3007
1-430
1-907

RQ04-011 06629

Washer Recal Performed_ID	Washer Recal Performed_MDL_YR	Washer Recal Performed_VIN_CD	Washer Recal Performed_L	COST	Washer	Washer Recal Performed_VEN_LINE_CD
77	2001	2R62261482		35.00	TRAP	
	2001	2R62261481		35.00	TRAP	

Windsor Recall Performed_MKT_DERIVED Windsor Recall Performed_BOD_CAR_STL Windsor Recall Performed_VER_SERIES_CD Windsor Recall Performed_DRIVE_CD Windsor Recall Performed_ENG_CD
TMB TA TA TA TA

Vendor Recall Performed_TRANS_CD Vendor Recall Performed_PLANT_CD Vendor Recall Performed_PROD_CD Vendor Recall Performed_WRTY_START_DT Vendor Recall Performed_NAME
3011991 3011991 3011991 3011991 BUDGET PAC: DENVER INTL AP
3011991 3011991 3011991 3011991 BUDGET PAC: DENVER INTL AP

Windsor Recall Performed_DOC_NUM Windsor Recall Performed_PH_NUM Windsor Recall Performed_WCC_CD Windsor Recall Performed_PART_NUM_CAUSE_PREF Windsor Recall Performed_PART_NUM_CAUSE_BASE

Widalar Recall Performed_PART_NUM_CAUSE_BUFF Widalar Recall Performed_CUST_COAG_CD Widalar Recall Performed_COND_CD Widalar Recall Performed_RPR_DT Widalar Recall Performed_TIS_WSD

Wendell Retail Performed_CLM_KEY	Wendell Retail Performed_MLSE	Wendell Retail Performed_UTP	OST	Wendell Retail Performed_TOT_COST_GROSS	W	u Retail Performed_LBP_HFS
2600000			884	784		0.7
2600000			884	784		0.7

Winstar Recall Performed_DLR_CD Winstar Recall Performed_DLR_BUS_CD Winstar Recall Performed_REGION_CD Winstar Recall Performed_ST_PROV_CD Winstar Recall Performed_CPSC_CD_S
4881
4882

Vendor Recall Performed_TECH_TXT1 Vendor Recall Performed_TECH_TXT2 Vendor Recall Performed_OUST_TXT Vendor Recall Performed_VISA_CD Vendor Recall Performed_COUNTRY_CD
RECALL 01881
RECALL 01881

Windsor Recall Performed_BLR_DLR_CD Windsor Recall Performed_TAM_CD Windsor Recall Performed_ONTRT_SOLD Windsor Recall Performed_CRT_CD Windsor Recall Performed_VPB_CD
984187 01821
124187 01821
USA USA USA USA USA

RC04-011 08638

Welder Recs_Performed_AYS_VL_CD	Welder Recs_Performed_VRT_CD	Welder Recs_Performed_TIS_FLAS	Welder Recs_ID	Welder Recs_MDL_YR	Welder Recs_VIN_CD	Welder Recs_LBR_COST
AS			148	2001	2P4ZAG1401	42.0
AS			134	2001	2P4ZAG1401	42.0

RC04-011 08639

Windsor Reports_VEHICLE_CD
T2A3
T2A5

Windsor Reports_MKT_DERIVED
-

Windsor Reports_BOD_CABL_BTL
T2WB
T2WB

Windsor Reports_VEST_SERVES_CD
-
-

Windsor Reports_DRIVE_CD
T2A
T2A

Windsor Reports_ENG_CD
T2LM
T2LM

Windsor Reports_TRANS_CD
T2CX
T2CX

Warranty Receipts_PLANT_CD	Warranty Receipts_PROD_DT	Warranty Receipts_WRTY_START_DT	Warranty Receipts_NAME	Warranty Receipts_DOC_NUM	Warranty Receipts_PL_NUM	Warranty Receipts_YR_CD
AS	1/24/2001	2/21/2001	PHIL LONG FORD OF DENVER, LLC	02100002	0328573	SP02
AS	1/24/2001	2/21/2001	PHIL LONG FORD OF DENVER, LLC	01002001	0328573	SP02

Windsor Reports_PART_NUM_OAUS_PREF	Windsor Reports_PART_NUM_OAUS_BASE	Windsor Reports_PART_NUM_OAUS_SUFF	Windsor Reports_CMT_CONC_CD	Windsor Reports_OAUS_CD	Windsor Reports_RPT_DT
1F3Z	1881202 AAB	1881203 AAB	340	48	12/18/2001
1F3Z		1881203 BAA	340	42	11/29/2001

RC004-011 08042

Welder Reports_TRE_MSD	Welder Reports_CLM_KEY	Welder Reports_MLGE	Welder Reports_AMT	COST	Welder Reports_TOT_COST_GROSS	Welder Reports_LBR_HRS	Welder Reports_DUR_CD
11	0923100	24200		224	45 8	0 8 0130	
10	0320004	09435		224	46 3	05 0130	

Winder Reports_DUR_BUB_CD	Winder Reports_REGION_CD	Winder Reports_ST_PROV_CD	Winder Reports_CPSC_CD_3	Winder Reports_TECH_TXT1	Winder Reports_TECH_TXT2
.	MA	CO		11001 RFR SEAT, REPLACED BUCKLE 4897	
.	MA	CO		11001 RFR DRIVERS SEAT REPLACED SEAT BELT BUCKLE 3399	

Windsor Repairs_CUST_TXT
CUSTOMER STATES PASSENGER SEAT BELT UNLOCKS WHILE DRIVING DOWN THE ROAD.
CUSTOMER STATES SEAT BELT ON DRIVERS SIDE POPPS LOOSE WHEN DRIVING

F-438	Windsor Repairs_AREA_CD	Windsor Repairs_COUNTRY_CD	Windsor Repairs_BLS_DLR_CD	Windsor Repairs_TKN_CD
D	303	USA	124126	EM
D	303	USA	124125	EM

Welder Reports_CNTRY_SOLD	Welder Reports_QRT_CD	Welder Reports_WFO_CD	Welder Reports_MNS_VL_CD	Welder Reports_YRT_CD	Welder Reports_TTB_PLAS
USA	Q21	V88	A3	805	
USA	Q21	V88	A3	805	

Days Between Pages
144
118

Message Between Pages
11002
10000

RQ04-011 08647