

**RQ04-011**  
**FORD**  
**APRIL 26, 2005**  
**REQUEST 8**  
**PART 3 OF 6**  
**BOOKS 27 OF 43**

8-Apr-02	7	106274	14278	25.13	120.88	1.4	4825 *	NA	FL	11001
18-May-02	3	1370130	6201	22.4	29.87	0.1	788 *	NA	RI	11001
9-May-02	0	8882108	3848	22.4	48	0.4	591 *	NA	NY	11001
23-Feb-02	8	7108044	6288	22.4	101.25	0.8	3467 *	NA	NY	11001
2-May-01	-1	352115	18	22.4	28.75	0.4	2650 *	NA	NY	11001
15-Oct-01	0	288215	12	22.4	129.39	1.4	5285 *	NA	CA	11001
2-Oct-01	4	4388830	4488	22.4	28.88	0.4	25525 *	NA	NJ	11001
18-Jul-01	0	2412887	18	8	28.88	0.4	2288 *	NA	OH	11001
13-May-02	8	1888804	7184	22.4	27.22	0.8	879 *	NA	NC	11001
10-Apr-02	2	1222215	2887	18.2	74.2	1	4222 *	NA	MI	11001
17-Aug-01	2	3182881	1801	22.4	77.14	0.7	3750 *	NA	CT	11001
18-Apr-02	7	1144543	2288	22.4	22.21	1.2	2284 *	NA	ND	11001
22-Jan-02	4	8422011	2147	22.4	77.22	0.8	2528 *	NA	MN	11001
10-Dec-01	4	412208	2201	22.4	178.21	2.2	2887 *	NA	WI	11001
7-Nov-01	2	5182712	2201	22.4	75.14	0.8	2728 *	NA	MI	11001
21-Dec-01	8	8881884	8818	22.4	87.7	1.1	2865 *	NA	OH	11001
7-May-02	4	1322282	2247	22.4	84.8	0.4	2888 *	NA	NY	11001
13-Apr-02	8	7882288	2881	18.78	84.8	1.2	2822 *	NA	SC	11001
14-Jan-02	8	2282728	4288	18.78	87.4	0.9	2102 *	NA	ON	11001
24-Sep-01	1	4722222	378	18.78	121.22	2.1	2102 *	NA	ON	11001
18-Apr-02	-1	1142728	5	18.78	81.1	1.2	2812 *	NA	ON	11001
30-Jul-01	0	2242721	3	18.78	28.42	0.4	2251 *	NA	PQ	11001
30-Jul-01	0	3222222	15	27.22	28.24	0.7	2222 *	NA	PQ	11001
21-May-02	7	8722228	2755	18.78	47.22	0.4	2222 *	NA	PQ	11001
18-Feb-02	2	2222222	2780	18.78	28.42	0.6	2222 *	NA	PQ	11001
11-Oct-01	2	4222222	2284	0	10.2	0.2	2244 *	NA	PQ	11001
22-Oct-01	8	4222228	1217	18.78	27.44	1	2222 *	NA	ME	11001
11-Nov-02	8	7221222	2288	18.78	28.78	0.4	2212 *	NA	ON	11001
7-Sep-01	2	2471221	2225	18.78	27.42	0.4	2222 *	NA	PQ	11001
18-Jul-01	1	2521222	1122	18.78	22.22	1.2	2222 *	NA	PQ	11001
26-Feb-02	2	7222222	2284	18.78	28.22	0.8	2141 *	NA	ON	11001
22-Apr-02	2	1122221	2225	18.78	42.22	0.4	2227 *	NA	PQ	11001
14-Apr-01	11	2122278	22201	18.78	40.2	0.4	2212 *	NA	ON	11001

11-Mar-02	8	720453	17074	18.78	87.08	0.4	88254	*	NA	ON	11801
27-Mar-02	8	708808	8884	18.78	88.88	0.4	88254	*	NA	AB	11801
7-Feb-02	5	687271	18710	18.78	84.78	1.3	88258	*	NA	PQ	11801
28-Dec-01	1	887000	886	18.78	108.73	1.8	87088	*	NA	BC	11801
27-May-02	10	8803078	11483	18.78	80.72	0.8	88231	*	NA	AB	11801
18-Nov-01	2	528802	2880	18.78	82.1	0.1	84628	*	NA	NS	11801
17-Apr-02	5	8887828	3181	18.78	84.85	1.8	88187	*	NA	ON	11801
8-May-02	4	1888874	8788	18.78	88.82	0.4	84688	*	NA	NS	11801
27-Dec-01	2	8847774	2888	18.78	81.82	1.3	88187	*	NA	AB	11801
5-Mar-02	1	884882	888	18.78	88.81	1	81318	*	NA	ON	11801
28-Nov-01	1	8488720	881	27.81	88.07	0.6	9578	*	NA	MI	11800
7-May-02	4	1888114	4808	0	81.85	1.8	88828	*	NA	ON	11800
8-Dec-01	4	8187842	4808	27.8	88.18	0.5	42782	*	NA	AZ	11800
25-Sep-01	2	3882088	1084	48.88	73.87	0.6	4473	*	NA	TX	11800
30-Mar-02	4	888877	2857	24.11	85.82	0.4	88888	*	NA	AB	11800
17-Oct-01	2	8888088	3018	27.81	48.48	0.3	888	*	NA	NY	11800
30-May-02	8	1488888	8812	28.18	82.88	0.8	4878	*	NA	FL	11801
16-Jan-02	2	848888	1887	28.18	83.82	0.6	4878	*	NA	FL	11801
28-Feb-02	8	7887170	8883	18.41	88.44	0.7	88230	*	NA	AB	11800
14-Aug-01	8	3888418	18	48.58	138.7	0.8	3888	*	NA	CA	11800
11-Oct-01	1	4883337	431	28.87	48.88	0.4	81388	*	NA	ON	11800
8-Dec-01	1	484187	408	28.18	88.88	0.7	1888	*	NA	TN	11801
11-Feb-02	2	888887	821	27.81	48.88	0.4	2887	*	NA	MI	11800
20-Jul-01	8	3787180	18	28.18	88.88	0.7	8888	*	NA	KY	01000X
12-Feb-02	2	878871	1808	28.18	88.37	0.6	488	*	NA	AL	11801
27-Jul-01	8	2881888	178	18.41	101.8	1.7	88801	*	NA	NS	11801
21-May-02	4	7882788	4777	28.07	88.54	0.7	88841	*	NA	PQ	11800
17-Jul-01	8	3388881	28	8	28.58	0.4	2888	*	NA	ON	11800
26-Apr-02	8	1178848	2817	18.41	88.88	0.7	88880	*	NA	ON	01000X
8-Jul-01	8	2711888	8	8	8	0	28807	*	NA	PQ	01000X
13-Apr-02	7	8848884	1088	27.81	83.58	0.7	1788	*	NA	AB	11800
8-Feb-02	4	1882788	8177	87.18	108.81	1	88187	*	NA	AB	11800

23-Apr-02	0	8251788	10128	42.89	87.18	0.4	4488 *	NA	TX	11000
29-Jul-02	2	881324	8188	48.18	108.88	0.8	1982 *	NA	CT	11001
27-Feb-02	1	888789	1488	33.16	72.7	0.8	3888 *	NA	OH	11001
6-Mar-02	2	888425	88	0	82.57	0.5	181 *	NA	OH	01180X
8-Aug-01	0	8888374	114	33.67	88.11	0.2	8888 *	NA	MI	11008
11-Oct-01	1	4877885	188	28.16	53.84	0.7	1882 *	NA	OH	01100X
16-Oct-01	2	4888889	3811	23.07	48.87	0.7	8188 *	NA	OH	11000
28-Mar-02	0	8148888	18843	23.87	47.74	0.8	8188 *	NA	OK	11001
18-Oct-01	2	8788878	2182	18.41	38.23	0.2	8807 *	NA	OH	11001
5-Feb-02	0	848888	18	28.4	78.88	0.9	7487 *	NA	PA	11001
3-Apr-02	4	1081487	8888	28.4	88.4	0.9	888 *	NA	MD	11001
11-Dec-01	0	8678882	10151	48.8	118	1.2	7188 *	NA	ME	11001
14-Aug-01	0	4881888	18	48.87	184.78	1.1	8888 *	NA	CA	11000
17-Sep-01	1	4882181	27	48.88	124.74	1.1	8888 *	NA	CA	11008
14-Mar-02	0	7441884	4811	28.18	63.77	0.7	2888 *	NA	TX	11008
27-Jun-02	0	8888888	8278	28.18	74.28	0.7	148 *	NA	MD	11008
17-Sep-01	0	4882182	18	48.88	78.88	0.8	3888 *	NA	CA	11008
17-Sep-01	0	4881888	18	48.88	124.74	1.1	8888 *	NA	CA	11008
14-Aug-01	0	3488884	47	23.18	88.22	0.4	3888 *	NA	GA	11008
14-Aug-01	0	8881878	18	88.87	104.18	0.7	8888 *	NA	CA	11008
25-Aug-01	0	8881878	27	88.87	127.88	1	8888 *	NA	CA	11008
17-Sep-01	0	4882184	48	48.88	122.28	1.2	2888 *	NA	CA	11008
10-Oct-01	1	8883188	24	27.81	88.81	1	3888 *	NA	VA	11008
22-May-02	0	8848882	18888	28	88.8	0.7	8188 *	NA	MD	01100X
27-Mar-02	1	882787	3287	23.18	84.23	1.1	1478 *	NA	TX	11088
21-May-02	11	8887781	14286	22.18	48.22	0.4	5218 *	NA	MD	81100X
18-Jul-01	0	2888884	8	0	28.88	0.4	2888 *	NA	OH	11000
25-Apr-02	0	8888878	13881	23.18	88.75	0.7	4788 *	NA	W	11008
17-Sep-01	0	4882185	10	48.88	78.88	0.6	2888 *	NA	CA	11000
8-Jan-02	0	8188882	13873	23.18	84.71	0.7	348 *	NA	GA	11008
28-Sep-01	1	4881888	888	23.18	74.88	0.7	7888 *	NA	CA	11008
18-Jul-01	0	2888888	3	0	38.88	0.4	2888 *	NA	OH	11000
18-Jul-01	0	2888887	5	0	28.88	0.4	2888 *	NA	OH	11000
17-Aug-01	0	3114888	88	88.67	127.88	1.2	2188 *	NA	OH	11000
24-Oct-01	3	4848187	1178	0	0	0	48 *	NA	VA	11000
17-Sep-01	1	4888187	13	48.88	147.87	1.4	8888 *	NA	CA	11000
6-Oct-01	2	4887888	1842	28.18	108.88	1	1842 *	NA	NJ	11000
17-Sep-01	1	4882188	22	48.88	71.28	0.4	8888 *	NA	CA	11000

21-Jul-01	1	3818813	28	23.18	83.78	0.4	2588 *	MA	CA	11000
13-Aug-01	1	3432885	813	23.15	114.88	1.2	2528 *	MA	CA	11000
26-Jul-01	0	3388883	3	0	20.88	0.4	2828 *	MA	OH	11000
27-Jul-01	0	3481883	8	27.51	110.77	1.1	2481 *	MA	CA	11000
17-Sep-01	8	4422180	12	40.88	147.87	1.4	2488 *	MA	CA	11000
17-Sep-01	1	8281882	1188	88.87	28.87	0.7	D8477 *	MA	OH	11000
27-Feb-02	8	7184880	3881	23.18	88.81	1	2548 *	MA	WV	11001
16-Jan-02	4	8888876	3888	40.88	188.88	0.8	3018 *	MA	MD	11000
17-Jul-01	0	2884888	1	40.88	88.81	0.4	3082 *	MA	OH	11000
7-Feb-02	4	8884744	4213	23.15	48.88	0.4	4788 *	MA	IN	810000
7-Feb-02	8	8788882	11235	0	44.17	1	7488 *	MA	WV	810000
17-Jul-01	0	2288882	18	0	88.88	0.4	2288 *	MA	OH	11000
6-Aug-01	0	2884488	8	0	0	8	3028 *	MA	TN	11000
17-Jul-01	0	2288882	18	0	88.88	0.4	2228 *	MA	OH	11000
19-Jul-01	0	2888880	8	0	28.88	0.4	2228 *	MA	OH	11000
14-Feb-02	7	7188721	14887	88.8	48.88	0.2	1188 *	MA	AR	11001
8-Aug-01	0	3181888	18	87.8	181.88	1.2	10428 *	MA	PA	11001
19-Mar-02	8	7888830	18847	23.8	88.88	0.4	1878 *	MA	KS	11001
20-Aug-01	0	3811487	4	48.1	218.88	0.2	18888 *	MA	NJ	11001
18-Apr-02	1	1188888	488	23.8	148.44	1.7	18175 *	MA	CA	11001
28-Apr-02	2	1881738	888	23.8	88.2	0.8	18287 *	MA	NY	11001
28-Aug-01	0	3871888	2	23.8	47.88	0.2	18388 *	MA	NY	11001
27-Oct-01	4	4828776	1281	23.8	88.46	0.7	18388 *	MA	NY	11001
20-Jul-01	0	3888878	8	0	28.88	0.4	18784 *	MA	PA	11001
11-Oct-01	1	4428888	888	23.8	71.11	0.8	18848 *	MA	IL	11001
11-Jan-02	8	888430	877	23.8	73.84	0.8	18884 *	MA	GA	11001
23-Jan-02	8	788888	8888	23.8	88.87	0.5	1187 *	MA	NY	11001
17-May-02	-1	1278228	7	23.8	188.28	2	11887 *	MA	FL	11001
21-Mar-02	-1	817877	4	28.8	88.74	0.8	12814 *	MA	VA	11001
11-Sep-01	0	3828844	11	87.2	121.8	1.2	18184 *	MA	TX	11001
28-Feb-02	8	728888	8848	0	88.85	1.8	81887 *	MA	OH	11001
28-Apr-02	8	1187888	18848	88.8	88.17	0.8	11848 *	MA	FL	11001
22-Feb-02	8	788888	8812	87.8	188.14	1.5	18888 *	MA	TX	11001
21-Aug-01	0	4288288	7	87.2	134.85	1	18138 *	MA	MA	11001

1-Aug-01	0	8641841	8	35.17	83.3	0.7	10000 *	MA	OH	11801
14-Jun-02	2	880871	115	35	81.15	0.5	10000 *	MA	IL	11801
8-Apr-02	3	1648318	7	35.5	81.15	0.4	10000 *	MA	PA	11801
29-Nov-01	4	8803825	2389	0	46.85	0.7	10100 *	MA	GA	11801
11-Oct-01	2	4888849	8888	85.5	84.8	0.4	12500 *	MA	MI	11801
14-Mar-02	8	1861128	2	45.85	186.74	2.8	10100 *	MA	FL	11801
21-May-02	-1	1474877	11	38.6	146.84	2	19647 *	MA	FL	11801
20-Feb-03	7	788267	7801	33.5	186.8	1.8	10000 *	MA	AZ	11801
14-May-02	8	1320180	3372	35.5	81.70	0.3	10000 *	MA	FL	11801
21-Jun-02	5	6410864	6558	35.5	83.13	0.4	10001 *	MA	FL	11801
28-Jul-01	1	3182328	801	35.4	175.88	2.2	11400 *	MA	TX	11801
7-Dec-01	4	5707526	8844	35.8	88.54	1	11887 *	MA	FL	11801
11-Mar-02	7	7328848	4228	35.8	83.81	8.7	10987 *	MA	TX	11801
25-Oct-01	2	8471182	3610	35.8	85.10	8.3	8083 *	MA	MS	11801
18-Feb-02	8	328841	8814	38.8	83.86	8.2	19167 *	MA	GA	11801
18-Dec-01	4	487888	2880	35.8	228.88	2.7	10878 *	MA	OH	11801
29-Jun-02	-1	588371	10	0	108.4	1.8	10888 *	MA	AR	11801
11-Apr-02	0	1883285	10	0	112.88	1.5	12888 *	MA	NJ	11801
1-Apr-02	8	8828148	8827	87.2	88.1	8.4	8881 *	MA	GA	11801
11-Apr-02	2	1187737	882	0	105.88	1.8	18488 *	MA	PA	11801
24-May-02	5	1481888	8832	87.2	138.48	1.8	11888 *	MA	FL	11801
14-Mar-02	0	878880	18	88.5	281.88	4.2	18187 *	MA	AL	11801
25-Mar-02	-1	1178880	8	35.4	171.1	2.6	8488 *	MA	LA	11801
1-Oct-01	1	4088048	1	35.8	84.48	2.7	10882 *	MA	NJ	11801
24-Jul-01	0	3878888	9	35.8	77.35	0.7	18828 *	MA	FL	11801
1-Apr-02	8	888848	1878	85.4	288.18	2	18184 *	MA	MD	11801
29-Mar-02	1	1088882	87	83.8	112.88	0.8	11881 *	MA	NY	11801
20-Jul-01	0	2272731	7	0	48.18	0.7	12828 *	MA	IA	11801
21-Aug-01	0	8874861	8	87.2	124.48	1	18138 *	MA	MA	11801
28-Jun-01	0	2188447	5	0	87.57	1.5	2387 *	MA	OH	11801

24-Apr-08	-1	1289231	5	88.6	75.84	0.6	10188 *	MA	GA	11081
18-Sep-01	D	8714418	18	87.2	107.86	0.8	11408 *	MA	TX	11081
4-Sep-01	D	3038283	20	33.6	79.3	0.8	13823 *	MA	MI	11081
4-Dec-01	D	289793	85	28.6	174.48	1.8	12807 *	MA	MD	11081
16-Apr-02	D	1138888	1127	33.6	70.88	0.8	11642 *	MA	FL	11081
26-Apr-02	2	1181348	4528	26	88.4	0.4	10228 *	MA	IL	11081
18-Aug-01	0	3418646	8	33.6	63.28	0.8	11034 *	MA	FL	11081
12-May-02	11	8039028	22287	28.8	60.88	0.4	48912 *	MA	CA	11081
18-Dec-01	8	5848117	18035	28.8	128.21	2	45284 *	MA	TX	11081
8-Aug-01	0	3101381	5	33.6	308.23	4	12018 *	MA	MD	11081
27-Feb-02	3	788526	2546	33.6	81.18	0.4	1471 *	MA	CA	11081
19-Mar-02	15	7882881	6853	33.6	212.66	2.7	11604 *	MA	TX	11081
3-Jan-02	7	8888073	21603	28.8	168.8	1.8	48228 *	MA	IL	11081
18-Aug-01	8	2882088	28	0	37.71	0.7	8777 *	MA	KY	11081
8-May-02	18	8870748	22224	8	20.88	0.4	48281 *	MA	TX	11081
28-Mar-02	8	7822328	6848	25.8	28.84	0.5	5878 *	MA	AR	11081
28-Apr-02	7	1238282	18817	28.8	188.12	2.7	48286 *	MA	NJ	11081
4-Dec-01	1	378881	784	33.6	68.8	0.6	2208 *	MA	MD	11081
31-Jan-02	2	843881	2881	33.6	85.67	0.5	11838 *	MA	FL	11081
7-Apr-02	8	1188288	13822	28.8	62.8	0.4	42888 *	MA	NY	11081
18-Jan-02	2	881884	7880	28.8	55.5	1.2	48140 *	MA	KY	11081
8-Apr-02	1	1881778	3412	33.6	282.71	4.2	18838 *	MA	MI	11081
11-Feb-02	5	8828828	828	28.8	47.58	0.3	11482 *	MA	TX	11081
16-Aug-01	0	4277304	8	63.2	87.8	0	2288 *	MA	NY	12901
17-Sep-01	2	3288284	887	87.2	142.48	1.2	17811 *	MA	FL	11081
22-Jul-01	0	2882881	8	87.2	148.41	1.8	3888 *	MA	FL	10881
1-Aug-01	0	2877883	27	87.2	128.54	1	11441 *	MA	TX	12881
28-Jul-01	0	2882881	8	87.2	88.48	0.4	18234 *	MA	PA	11881
28-Sep-01	2	4388148	2885	28.8	84.28	0.7	42228 *	MA	FL	11881
18-Oct-01	2	8827825	2185	28.8	28.8	0.3	48888 *	MA	NJ	11881
28-Aug-01	D	3888284	11	0	128.34	1.8	18144 *	MA	MA	11081
11-Feb-02	4	748184	7881	33.6	88.28	0.4	12277 *	MA	TN	11081
21-Oct-01	1	428228	1287	0	88	1	42277 *	MA	TX	11081
1-Jul-02	4	1081412	4885	88.87	108.47	0.8	18818 *	MA	NJ	11081
1-Apr-02	0	1088181	7	33.6	178.48	2.1	10178 *	MA	GA	11081
8-Apr-02	8	1188884	2887	28.8	108.8	1.4	48848 *	MA	WA	11081

b

09-Mar-02	1	001830	00	33.8	180.71	2.7	10200 *	NA	LA	11001
14-May-02	1	1344200	418	0	21.61	0.3	13020 *	NA	MS	11001
10-Jul-01	0	2000000	3	33.8	80.15	0.7	11450 *	NA	TX	11001
8-Aug-01	0	0000000	4	33.8	93.00	0.7	10001 *	NA	FL	11001
23-Aug-01	3	4472000	708	07.2	148.74	1.2	84 *	NA	MD	11001
12-Sep-01	2	4880700	1051	33.8	88.8	0.7	40000 *	NA	TX	11001
23-Sep-01	0	4300000	31	33.8	82.16	0.7	13010 *	NA	NV	11001
0-Apr-02	4	1100000	8700	33.8	33.80	0.9	10107 *	NA	TX	11001
23-Feb-02	0	000700	0000	33.8	82.0	0.6	40111 *	NA	FL	11001
02-Apr-02	1	1210000	1007	33.8	43.36	0.2	10077 *	NA	FL	11001
14-May-02	5	1000000	2025	33.8	84.5	0.4	1013 *	NA	ND	11001
4-Mar-02	1	000502	100	33.8	100.00	0.4	30700 *	NA	OH	11001
26-May-02	0	0070000	15	33.8	301.5	1.3	11007 *	NA	CA	11001
20-Apr-02	5	0070000	4700	33.8	33.7	1.1	40000 *	NA	FL	11001
20-Nov-01	5	3000000	17000	00.0	70.0	1	00111 *	NA	FL	11001
20-Oct-01	3	0000000	7000	25.0	70.0	1	00001 *	NA	TX	11001
3-Dec-01	1	0000000	047	03.0	100.00	0	4000 *	NA	GA	11001
22-Apr-02	-1	1140001	40	33.8	100.00	0.8	0001 *	NA	TX	11001
0-May-02	4	1070000	00077	44.74	000.00	0	10000 *	NA	NJ	11001
15-Nov-01	0	000000	10	33.8	71.00	0.8	10077 *	NA	IL	11001
16-May-03	-1	1004400	44	33.8	140.04	1.7	10700 *	NA	OH	11001
0-May-02	1	1070000	007	0	44	0.8	070 *	NA	SC	11001
1-Apr-02	1	1000000	1070	20.0	00.0	0.8	40007 *	NA	OH	11001
17-Apr-02	10	0470000	10400	20.0	00.1	1	40000 *	NA	MI	11001
24-Aug-01	2	0001000	040	07.2	100.00	1.3	11000 *	NA	AZ	11001
9-Oct-01	0	4000100	4000	33.8	107.00	0.6	0000 *	NA	ME	11001
09-Aug-01	1	4000000	000	20.0	01.1	1	40000 *	NA	TX	11001
20-Apr-02	7	1000700	10400	30.0	30.04	0.2	40000 *	NA	FL	11001
0-Nov-01	1	001000	070	20.0	00.11	0.7	00000 *	NA	FL	11001
0-Apr-02	1	1140700	00	00.0	100.12	2.7	00000 *	NA	NJ	11001
0-May-02	11	0440000	00700	20.0	70.04	0.0	1000 *	NA	FL	11001



10-May-02	71	5742293	22745	33.5	62.84	0.5	8881 *	NA	TX	11001
9-Feb-02	8	7882294	4483	33.8	64.81	0.2	18914 *	NA	NE	11001
18-Oct-01	4	6882294	8930	33.0	64.78	0.7	48288 *	NA	GA	11001
5-Jun-02	3	7382293	8986	33.3	43.8	0.2	48288 *	NA	FL	11001
29-Mar-02	6	1021420	18437	33.0	72	0.8	48111 *	NA	FL	11001
23-Jan-02	3	402748	2847	33.8	34.18	0.1	48282 *	NA	AZ	11001
7-Jun-02	2	488221	910	33.0	47.01	0.2	18148 *	NA	MI	11001
6-May-02	1	1204980	573	33.5	238.2	2.3	18288 *	NA	MI	11001
8-May-01	4	5018891	3384	33.0	102.18	1.2	18888 *	NA	CA	11001
4-Jun-02	8	6018798	4818	33.78	62.18	0.8	1237 *	NA	NJ	11001
8-Aug-01	1	4281848	374	33.0	143.84	1.8	48888 *	NA	NJ	11001
19-Apr-02	10	8881415	21788	33.8	83.88	0.8	48188 *	NA	CA	11001
13-Mar-02	8	508876	11312	33.0	87.2	0.8	48111 *	NA	FL	11001
6-May-02	7	1448887	11817	33.8	88.34	0.7	48282 *	NA	AZ	11001
14-Mar-02	3	1088730	8918	33.0	47.46	0.2	2787 *	NA	MI	11001
18-Apr-02	-1	1887478	8	87.2	388.48	8.8	248 *	NA	GA	11001
23-Jul-01	0	3488940	4	33.6	84.84	0.8	10888 *	NA	FL	11001
28-Sep-01	1	4888228	148	33.0	84.84	0.5	18288 *	NA	FL	11001
9-Oct-01	3	4543461	3801	33.5	88.8	0.4	278 *	NA	MI	11001
7-May-02	7	1884888	3884	33.5	76.14	0.7	12321 *	NA	VA	11001
18-Jun-02	4	304814	5832	0	84.18	0.7	48081 *	NA	LA	11001
12-Oct-01	8	644830	3883	33.8	28.2	0.3	48881 *	NA	IL	11001
28-Feb-02	1	784138	837	0	131.8	1.8	11888 *	NA	AZ	11001
3-Apr-02	4	1622280	7381	0	88.4	1.3	48111 *	NA	FL	11001
27-May-02	2	1418285	838	0	81.8	1	888 *	NA	SC	11001
21-Apr-02	1	1488988	1838	0	48	1	48278 *	NA	TX	11001
22-Jul-01	0	2881838	7	33.0	77.38	0.7	3888 *	NA	FL	11001
18-Aug-01	1	3087912	14	33.8	83.28	0.7	11828 *	NA	CA	11001
18-Apr-02	10	8471835	17888	33.0	203.48	2.7	48288 *	NA	NY	11001
7-Mar-02	8	7488180	23818	33.0	38.8	0.8	48888 *	NA	TX	11001
17-Jun-02	8	6888838	8718	33.8	188.88	2.7	48881 *	NA	GA	11001
23-Mar-02	8	7821844	8887	33.5	204.57	2.7	12284 *	NA	LA	11001
17-Jun-02	4	324278	4137	33.8	88.12	0.4	18381 *	NA	MA	11001
14-May-02	8	1377774	4888	33.8	78.37	0.8	18881 *	NA	MA	11001
4-Mar-02	8	3081847	8483	33.8	34.18	0.1	48282 *	NA	AZ	11001
17-Apr-02	8	1348288	8488	33.8	104.18	1.4	48282 *	NA	AZ	11001
18-Feb-02	4	782885	18481	33.8	72	0.8	48111 *	NA	FL	11001
24-Apr-02	6	1221423	8004	33.8	62.8	0.5	48111 *	NA	FL	11001
2-Apr-02	8	3081885	2	33.8	188.18	2	18184 *	NA	ND	11001
20-Jul-01	8	2848821	1	37.48	88.47	0.7	78488 *	NA	NJ	11001
21-Aug-01	8	2884183	8	33.6	88.38	0.7	11817 *	NA	GA	11001
16-Jun-02	8	8088884	1778	88.8	74.38	0.8	18804 *	NA	MD	11001
8-Oct-01	8	8887888	4878	33.8	80.8	0.8	288 *	NA	AL	11001
18-Jul-01	8	2481838	8	0	38.88	0.8	11888 *	NA	FL	11001
1-Aug-01	8	4221483	11	87.2	123.2	0.8	18184 *	NA	TX	11001
22-May-02	18	8877880	34388	0	134.88	2.2	18127 *	NA	AL	11001

20-Mar-02	5	801940	2070	22.6	83.91	0.6	10702 *	NA	OH	11001
21-Feb-08	6	838438	7922	22.8	83.0	2.7	48299 *	NA	FL	11001
27-Feb-02	4	799678	11518	35.6	807.84	2.7	139 *	NA	VA	11001
18-Mar-08	3	888493	8891	22.6	72.5	0.9	10091 *	NA	TX	11001
23-Apr-02	0	1489348	31	32.8	88.91	0.9	10648 *	NA	IN	11001
15-Oct-01	1	4481981	288	23.18	81.18	0.2	9008 *	NA	MO	12001
21-Sep-01	4	4488901	8301	22.18	88.34	0.4	7914 *	NA	CA	12001
24-Jul-01	0	4029017	18	26.82	85.39	0.8	8511 *	NA	TX	11001
17-Jul-01	0	2992788	15	43.43	140.22	1.1	20402 *	NA	AZ	12001
24-Apr-02	7	2220288	23905	22.18	85.21	0.8	2488 *	NA	TX	12001
11-Oct-01	3	4940945	3821	0	88.91	0.8	8108 *	NA	MO	12001
4-Sep-01	1	3821781	178	29.18	85.08	0.8	4879 *	NA	TX	12001
14-Aug-01	1	8988284	31	43.43	104.67	0.9	5936 *	NA	CA	12001
25-Jul-01	0	5864722	7	43.43	89.86	0.8	2175 *	NA	OH	12001
11-Sep-01	3	4848878	2014	28.82	86.5	1	8825 *	NA	LA	11001
24-Aug-01	0	8984754	8	32.18	88.22	0.8	2178 *	NA	OH	12001
8-Sep-02	9	8888078	10371	29.27	88.28	0.8	2208 *	NA	IA	12001
31-Jul-01	0	8774719	14	28.82	130.88	1	1440 *	NA	NY	12001
9-May-02	8	1288830	8247	29.27	82.78	0.6	1188 *	NA	OR	12001
20-Jun-02	8	8821188	14714	18.05	82.88	0.8	8574 *	NA	TX	11001
2-Aug-01	1	2488227	1787	19.08	54.67	0.8	2814 *	NA	TX	12001
14-Feb-02	8	8888888	8888	18.08	21.88	0.5	4813 *	NA	TX	11001
23-May-02	5	1288288	15188	18.05	87.98	0.6	4888 *	NA	TX	11001
17-Jul-01	8	2088880	17	20.27	88.41	0.8	1882 *	NA	CO	12001
1-Aug-01	8	2821884	7	8	8	8	7889 *	NA	CA	11001
6-Aug-01	8	2781883	3	42.43	108.48	0.8	7784 *	NA	CA	12001
13-Mar-02	4	8788888	7988	18.18	82.82	0.7	7878 *	NA	TX	12001
19-Aug-01	0	2888321	2	22.18	85.88	0.8	4107 *	NA	MO	12001
28-Oct-01	4	4888848	6288	15.88	48.28	0.4	8022 *	NA	TX	11001
18-Jul-01	0	2788288	18	43.43	108.92	0.6	7941 *	NA	CA	12001
3-Nov-01	1	8888821	20	43.43	80.44	1	4981 *	NA	TX	12001
17-Jul-01	8	2888888	18	28.27	88.41	0.8	1882 *	NA	CO	12001
2-Aug-01	1	2874888	17	18.08	44.88	0.8	8088 *	NA	AZ	12001
8-Mar-02	8	8888880	4881	22.18	28.2	0.4	2788 *	NA	MO	11001
24-Jul-01	8	2088880	27	18.08	48.84	0.4	8884 *	NA	VA	12001
8-Apr-02	8	8017422	18818	22.18	74.82	0.3	7328 *	NA	PA	12001
12-Sep-01	3	5884188	7888	18.08	80.07	0.6	3288 *	NA	TX	11001

27-Apr-01	D	2481882	8	20.27	68.89	0.8	5481 *	NA	CA	12001
24-Apr-01	2	2322823	1420	23.16	83.8	0.8	3184 *	NA	SD	12001
10-Mar-02	5	264888	13775	88.39	71.38	0.5	2891 *	NA	TX	11001
7-Jan-02	7	888888	18850	52.58	122.83	0.8	7880 *	NA	CA	11001
4-Apr-01	9	7822212	8718	85	131.88	1.1	28423 *	NA	AZ	11881
25-Jul-01	0	2871240	27	126.88	142.78	0.8	7105 *	NA	NE	12581
28-Mar-02	8	8888888	16821	88	117.88	1.1	5284 *	NA	KS	11881
2-May-02	5	8882788	12804	88.24	841.88	2.2	482 *	NA	GA	11881
20-Apr-02	4	7848881	288	88	104.42	0.8	2627 *	NA	MI	11881
9-Dec-01	9	428881	4542	43.85	78.28	0.8	4885 *	NA	FL	11281
18-Dec-01	0	428223	7	48.22	104.88	1	880 *	NA	GA	11281
12-Dec-01	0	428470	18	0	40.78	0.7	2281 *	NA	OH	11001
12-Oct-01	1	254886	288	23.18	88.77	0.7	22284 *	NA	NM	01002X
1-Mar-02	3	841887	8738	23.16	82.88	0.7	5280 *	NA	AR	11880
18-Feb-02	1	778827	1018	28.18	228.74	4.8	2477 *	NA	TX	01002X
18-Jul-01	8	2828121	8	28.27	88.88	0.4	8488 *	NA	MD	12001
8-Mar-02	7	2777791	8228	22.18	28.8	0.1	7784 *	NA	CA	12281
8-Mar-01	2	282884	4184	22.28	48.18	0.4	8888 *	NA	TX	11281
18-Apr-02	8	1878888	18278	18.22	88.28	0.6	2022 *	NA	TX	11881
18-Oct-01	3	4812825	2824	22.28	88.14	0.5	878 *	NA	NC	12881
15-Mar-02	7	7821222	22278	21.48	88.22	0.5	7828 *	NA	UT	11281
29-Jul-01	0	2828288	11	22.18	102.88	1.1	8278 *	NA	MD	12881
11-Apr-02	18	8818334	8878	28.28	27.7	0.8	7884 *	NA	CA	11001
18-Jul-01	8	2828874	18	28.28	21.84	0.8	4728 *	NA	MI	12281
10-Aug-01	9	8188823	8	28.27	24.42	0.4	7777 *	NA	CA	12001
24-Oct-01	2	4788277	787	28.22	28.81	0.7	8488 *	NA	CA	12001
12-Mar-02	8	8888428	18221	20.27	88.21	0.8	8882 *	NA	WA	12001
12-Apr-02	18	8288848	18888	114.78	228.74	1.8	8278 *	NA	UT	11881
28-Jul-01	8	2788282	28	88	142.77	1.1	8878 *	NA	AZ	11001
21-Jul-01	8	2878288	14	8	87.28	0.7	8128 *	NA	MD	11880
18-Jul-01	8	2828477	14	88.18	148.27	1	8128 *	NA	MD	11280
29-Jul-01	0	2778118	28	88.18	111.88	0.7	2288 *	NA	FL	11000
21-Jul-01	0	2488128	8	48.28	82.82	0.7	7841 *	NA	CA	11000
24-Jul-01	0	8187128	28	88.18	141.28	1	7841 *	NA	CA	11080

19-Jul-01	0	2452275	8	27.21	64.20	0.7	8100 *	NA	MO	11000
14-Sep-01	1	2701810	387	43.88	89.2	0.7	22200 *	NA	AZ	11000
19-Jul-01	8	2812804	14	68.18	178.05	1.4	7704 *	NA	CA	11000
20-Oct-01	2	4778222	608	22.4	78.35	0.7	2486 *	NA	TX	11000
11-Dec-01	4	5762222	2808	48.22	114.8	1.3	11824 *	NA	FL	11001
17-Jul-01	8	4637288	4	30.27	73.24	0.5	11827 *	NA	FL	11001
25-Oct-01	4	4882272	4120	8	14.05	0.2	13800 *	NA	TX	11001
28-Oct-01	1	871844	1222	23.05	66.42	0.4	11820 *	NA	CA	11001
21-Jan-02	1	812877	248	25.28	65.27	0.4	10288 *	NA	CA	11001
4-Sep-01	8	172884	47	48.32	88.24	0.5	10277 *	NA	CA	11001
19-Jul-01	8	2027144	8	20.27	43.88	0.4	3426 *	NA	CA	11001
6-Sep-01	1	2882222	884	28.05	48.81	0.4	11825 *	NA	FL	11001
28-Mar-02	4	1008801	2708	23.08	64.87	0.4	10827 *	NA	CA	11001
28-Mar-02	4	1288888	8888	20.27	48.28	0.4	1818 *	NA	SO	11001
14-May-02	3	1431888	2188	28.88	51.88	0.4	11820 *	NA	FL	11001
28-Sep-01	8	225128	28	28.25	57.08	0.4	10472 *	NA	CA	11001
6-Sep-01	1	8884883	211	20.27	68.22	0.5	11827 *	NA	CA	11001
25-Jul-01	0	2887180	3	20.27	22.45	0.8	11803 *	NA	CA	11001
28-Jul-01	0	3087288	8	20.27	68.12	0.8	11406 *	NA	TX	11001
28-Jul-01	0	2882248	11	48.22	68.22	0.5	12824 *	NA	TX	11001
17-Jan-02	3	682288	3428	26.05	72.27	0.5	10822 *	NA	FL	11001
22-Apr-02	2	1172481	4728	48.28	112.01	1	12828 *	NA	TX	11001
14-Mar-02	5	2812884	2742	20.27	48.45	0.4	18765 *	NA	CA	11001
18-Apr-02	1	1114822	720	28.08	62.42	0.4	11820 *	NA	CA	11001
25-Dec-01	4	4822842	18277	42.21	64.1	0.4	424 *	NA	CA	11001
8-Nov-01	0	228228	128	28.08	42.88	0.4	4840 *	NA	TX	11001
29-May-02	2	1482288	2828	20.27	48.05	0.4	11822 *	NA	FL	11001
18-Apr-02	4	1128128	2811	26.05	72.27	0.8	10828 *	NA	FL	11001
12-Mar-02	1	482228	2811	20.27	22.1	0.2	11842 *	NA	FL	11001
28-Jul-01	0	482227	11	48.28	62.22	0.5	15164 *	NA	TX	11001
18-Jul-01	0	2812274	28	28.27	61.24	0.5	5422 *	NA	CA	11001
18-Apr-02	18	2822274	12715	28.05	48.22	0.4	4825 *	NA	TX	11001
22-Mar-02	8	1124417	2226	28.05	54.88	0.4	12822 *	NA	MI	11001
5-Nov-01	1	8122281	204	8	12.41	0.2	10748 *	NA	MI	11001
20-May-02	-1	1281271	2841	25.05	68.22	0.4	12828 *	NA	NY	11001
22-Apr-02	7	1172785	2728	20.27	22.8	0.5	12708 *	NA	OH	11001
18-Apr-02	2	1174848	2228	25.05	61.04	0.4	2824 *	NA	FL	11001
21-Sep-01	-1	4722225	8	25.08	64.2	0.4	12828 *	NA	MI	11001

18-Feb-82	B	7031088	15884	20.27	47.1	84	18148 *	NA	RM	18001
4-Feb-82	7	5775387	8178	21.85	43.81	84	AD182 *	NA	ON	18001
27-Jul-81	1	8892889	88	17.88	40.48	84	W5382 *	NA	ON	18001
10-Sep-81	B	6488878	70	48.33	148.7	1.2	13880 *	NA	NY	11001
21-Feb-82	B	782188	8274	20.27	48.7	84	12780 *	NA	NV	11001

TECH_TXT1	TECH_TXT2	Bypass Code	Bypass Desc	CUST_TXT	ARGA_CD
INSPECTED AND REPLACED DRIVERS SIDE SEAT BELT BUCKLE RETESTED OK BY NO LABOUR OPERATIONS CODE IN SLTS FOR REPAIRS		X	Other	DRIVER SIDE SEAT BELT WOULD HOOK UP	788
REPLACE RIGHT FRONT SEAT BELT BUCKLE WONT INTERMITTANTLY LATCH (42)		A	Wont Latch	RIGHT FRONT SEATBELT BUCKLE WONT STAY LATCHED	908
REPLACED SEAT BELT		X	Other	CUSTOMER STATES SEAT BELT BUCKLE WONT STAY LATCHED	903
REPLACED SEAT BELT		A	Wont Latch	LEFT SEAT BELT BUCKLE WONT LATCH	513
REPLACE LEFT FRONT SEAT BELT BUCKLE		A	Wont Latch	DRIVERS SEAT BELT DOES NOT BUCKLE	708
DIAG FOR RIGHT SEAT BELT WILL NOT LATCH,FAULTY LATCH ASSY,TRT PASS		A	Wont Latch	CHECK FOR PASSENGER SIDE SEAT BELT LATCH NOT WORKING	390
INSPECTED VEHICLE FOR CUSTOMER CONCERN, FOUND LEFT FRONT SEAT BELT BUCKLE BROKEN AND NOT OPERATING P PROPERLY. REMOVED AND REPLACED LEFT FRONT SEAT BELT BUCKLE ASSEMBLY.		A	Wont Latch	CUSTOMER STATES LEFT FRONT SEAT BELT WILL NOT LATCH.	217
FOUND BUCKLE STUCKS SOME RUMBLE AND RETESTED		X	Other	CUSTOMER STATES SEAT BELTS STUCKS SOMETIMES	888
700 DRIVER INDICATED SEAT BELT BUCKLE RECEIVER WONT STAY LATCHED AT TIMES. FAILED TEST. INSTALLED NEW BUCKLE TECH 4 COND CODE X3		C	Unlatches/Release	CUSTOMER STATES DR SIDE SEAT BELT COMES UNDONE WONT STAY BUCKLED	770
84810 788103		C	Unlatches/Release	CUSTOMER STATES SEAT BELT BUCKLES COMES UNDONE	395
BUCKLE FAILED REPLACED SEAT BELT		B	Wont Stay Latched	S40 REPAIR RT FT SEAT BELT WONT STAY FASTENED (INSTALL SOP	210
RT FT SEAT BELT WILL NOT STAY FASTENED. 1. INSTALLED NEW PASS SIDE SEAT BELT BUCKLE		D	Unlatches/Release	UP SEATBELT BUCKLE POPS OUT DURING	788
BUCKLE SEATBELT ASSEMBLY FRONT REPLACE		A	Wont Latch	DRIVERS SEAT BELT BUCKLE WILL NOT LATCH.	888
DRIVERS SEAT BUCKLE STUCK REMOVE AND REPLACED BUCKLE		C	Unlatches/Release	CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES UNDONE BY ITSELF	802
REPLACED DRIVERS LEFT FRONT SEATBELT BUCKLE THAT WOULD BE ON IT'S OWN UNLATCH ON ITS OWN		A	Wont Latch	CHECK DR SEATBELT WONT LATCH	618
REPLACE LEFT SEATBELT BUCKLE		X	Other	CUSTOMER STATES SEAT BELT BUCKLE WILL STAY ON WHEN SEAT BELT IS ATTACHED	707
SEAT BELT LIGHT COMES ON SEATBELT ASSEMBLY FRONT REPLACE		A	Wont Latch	CUSTOMER STATES SEAT BELT BUCKLE WILL NOT LATCH	881
REPLACED SEAT BELT BUCKLE		X	Other	DRIVERS SIDE SEAT BELT RECT. BROKEN	880
DRIVE SEAT-42 W FULL PASS SIDE SEAT AND REMOVED OLD SEAT BELT BUCKLE AND INSTALLED NEW ONE Y		A	Wont Latch	DRIVERS SEAT BELT WILL NOT LOCK	708
FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE		X	Other	PASS SIDE SEAT BELT FAIL	618
DRIVERS SIDE SEAT BELT BUCKLE WILL NOT LOCK REMOVED AND REPLACED. RECHECKED OPERATION. OK. USED BTIME DUE TO NO LABOR OPERATION BEING FOUND.		C	Unlatches/Release	CUSTOMER STATES THE SEATBELT ON THE PASS SIDE IS RELEASED	908
ODD81111 REPLACE RT SIDE SEAT BELT BUCKLE		C	Unlatches/Release	CUSTOMER STATES PASSENGER FRONT SEAT BELT COMES UNLATCHED	512
PASS SIDE SEAT BELT WONT CHECK ALL BELT OPERATIONS. PASS BUCKLE WONT. REPLACED BELT BUCKLE		B	Wont Stay Latched	CUSTOMER STATES PASSENGER SEAT BELT DOES NOT STAY LATCHED WHEN IN USE	841
REMOVED SEAT FOR ACCESS AND REPLACED RIGHT FRONT SEAT BELT		C	Unlatches/Release	SEAT BELT POPS LOOSE, SOP IN	581
781188 CC 42 8478 NO VERIFIED CUSTOMER CONCERN. REMOVED PASS SEAT, R J NEW SEATBELT BUCKLE. INSTALLED PASS SEAT, RETEST PASS LATCH WONT AT TIMES, NOT HOLDING. REPLACED SEAT BELT LATCH		X	Other	CUSTOMER STATES DRIVERS SIDE SEATBELT UNLATCHES INTERMITTENTLY	888
REPLACED SEATBELT.		X	Other	PASSENGER SIDE FEMALE PART OF SEAT BELT MISSING	978
1 VERIFIED CONCERN R AND N SEAT TO GAIN ACCESS REPLACED BUCKLE. VERIFIED REPAIRS		R	Reckl Performed	PERFORM RECALL 01821 LEFT BUCKLE PASSED, RIGHT FAILED	208
REPLACED RIGHT SIDE BUCKLE PER RECALL		B	Wont Stay Latched	CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WONT STAY LATCHED	332
VERIFIED CONCERN AND REPLACED DRIVER FRONT SEAT BELT BUCKLE		X	Other	SOP PASS SIDE SEAT BELT	440
REPLACE SEAT BELT RT FRONT		C	Unlatches/Release	PASS SEAT BELT UNLATCHES ON ITS OWN	808
REPLACE RIGHT FRONT SEAT BELT BUCKLE		C	Unlatches/Release	(S40) INSTALL B O LF SEATBELT (BUCKLE UNLATCHES INTERM)	808
784 PULLED B.O. PART (LEFT FRONT SEAT BELT BUCKLE FRONT SEAT BELT BUCKLE, TESTED OPERATION) OKAY.		A	Wont Latch	LEFT FRONT SEAT BELT WONT LATCH	815
SEATBELT SEATBELT ASSEMBLY FRONT REPLACE					

REPLACED RIGHT SEAT BELT BUCKLE PER RECALL.  
 RE PLACED PASSENGER FRONT SEATBELT THAT WAS BROKEN  
 VERIFIED REPAIR OK  
 31001 REPLACED LEFT BUCKLE HAD TO FIX SEAT  
 VERIFY CONCERN. REPLACED BUCKLE  
 VERIFY CONCERN AND FOUND DRIVER SIDE SEAT BELT NOT HOLDING  
 RECALL WAS PREVIOUSLY DIED BUT PASSED R AND R DRIVER SEAT BELT  
 AND RECHECK OK  
 8286 01801C 0.7 8267 REPLACED RT. FRONT SEATBELT BUCKLE PER  
 RECALL

REPLACE BUCKLE  
 FOUND SEATBELT WILL NOT ALWAYS LATCH CORRECTLY. REPLACE LEFT  
 FRONT SEATBELT  
 DOES NOT OPERATE PROPERLY ADDITIONAL MISC. REPAIRS  
 1 REPLACED LEFT FRONT BUCKLE  
 SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE  
 824 42 REPLACE R F SEATBELT  
 RIGHT SEAT BELT WILL NOT BUCKLE REPLACED RIGHT SEAT BEL BUCKLE  
 & RECHECKED ALL OK  
 VERIFY CONCERN REMOVED SEAT BELT OUT OF PLASTIC HOLDER  
 GOODWILL REPAIR

AIR DUCT, IMPROPERLY ADJUSTED. INSTRUMENT PANEL ACCESS  
 SHORT IN BUCKLE ASSY. REPLACE BUCKLE AND HARNESSE ASSEMBLY AND  
 RETEST

SOVER OF SEAT BELT LATCH WTY CHECKED OPERATION. REPLACED SEAT  
 BELT LATCH

REPLACED RIGHT FRONT SEAT BELT BUCKLE. 8286MS 41.  
 REBANDS BOTH FRONT SEATS AND REPLACED BOTH SEAT BELT  
 BUCKLES. RETEST OK

RT FRT SEAT BELT LATCH INOP. REPLACE BELT BUCKLE ASSY DUE TO  
 STEERING WHEEL 228 40 22 40 MANUAL SEAT

BROKEN SEATBELT ASSEMBLY FRONT REPLACE  
 REPLACE BUCKLES BOTH SIDES

REPLACED BOTH FRONT BUCKLES

DR SEAT BELT BUCKLE BAD REPLACED THE DR SEAT BELT BUCKLE ASSY

REPLACE BUCKLE

BROKEN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT

REPLACE

REPLACE DRIVERS SIDE BUCKLE ASSEMBLY RETEST OK

VERIFY CONCERN AND REPLACED BUCKLE

DRILL BUCKLE COME OUT BLANK NUMBER SEAT TO ACCESS OCCUPANTS  
 SEAT BELT BUCKLE R AND R BUCKLE AND RETESTED AND CHECKED OK  
 BENDING SEAT BELT BUCKLE REPLACED RIGHT FRONT SEAT BELT  
 BUCKLE

CHECKS DONE TESTED AND FOUND SEAT BELT SWITCH BAD SHORTED  
 REPLACED BELT ASSY AND RECHECKED AND RETESTED GOOD  
 1 NO TIME LISTED NOW PULLED FROM DOOR, 81872, RUN BLUE PH TEST G,  
 TRACED TO DRIVER SEAT BELT PRETENSIONER, REACHED DRIVER POWER  
 SEAT  
 DIED REPLACE SEAT BELT BROKEN

R	Recall Performed	PERFORM RECALL 01821 LEFT BUCKLE PASSENGER FRONT BUCKLE FAILED	828
X	Other	CUSTOMER STATES PASSENGER FRONT SEATBELT WONT WORK	405
X	Other	SEATBELT 01821	410
A	Won't Latch	DRIVERS SIDE SEAT BELT BROKEN WONT LOCK	843
X	Other	CUST STATES HAS OPEN RECALL 01821 (SOP DRIVER SEAT BELT HERE)	251
X	Other	REPLACE RIGHT FRONT SEAT BELT BUCKLE SOP IS HERE	808
X	Other	CHECK PASSENGER SEAT BELT BUCKLE HARD TO FASTEN BUCKLE	908
D	Unlatches While Driving	BACKWARDS? CUSTOMER STATES DRIVERS SIDE SEATBELT COMES LOOSE WHEN GOING	804
A	Won't Latch	OVER BUMPLE. OK DRIVERS SEAT BELT WONT BUCKLE	370
X	Other	DRIVERS SEAT BELT WILL NOT ALWAYS LATCH. REFER TO NCM 81323	828
X	Other	PASSENGER SEAT BELT NOT LATCHING PROPER	382
X	Other	R F SEATBELT INOP	382
X	Other	INOP ALL SOP SEAT BELT	801
X	Other	CHECK SEAT BELT FELL IN PLASTIC HOLDER	815
X	Other	PASSENGER SEAT BELT INOP FOR CUSTOMER SOP IN PARTS	482
X	Other	USE BPO 8138044	482
X	Other	SEATBELT LIGHT STAYS ON	517
X	Other	SEAT DR SEAT BELT COMES APART 18480	581
A	Won't Latch	348 OWNER STATES THE RIGHT FRONT SEAT BELT WILL NOT BUCKLE	581
A	Won't Latch	SEE CUST STATES FRONT SEAT BELTS WONT LATCH INTERMITTENTLY	600
X	Other	CUSTOMER STATES RP SEAT BELT LATCH IN OP AT TIMES BUTTON WILL	600
X	Other	STICK DOWN AND REPAIR	600
X	Other		608
A	Won't Latch	CHECK DRIVERS SEATBELT, CUST SAYS WONT LATCH.	770
A	Won't Latch	FRONT SEATBELT BUCKLE WONT HOLD	808
D	Unlatches While Driving	OK SEAT BELTS DRIVERS BELT POPS OUT DRIVING	291
D	Unlatches While Driving	DR FT SEAT BELT COMES UNDONE WHEN GOING DOWN ROAD	409
X	Other	CHECK DRIVER SEAT, SEAT BELT BUCKLE STICKING AND WONT RELEASE	318
C	Unlatches/Plays Snap	CHECK DRIVERS SEAT BELT BUCKLE NOT LATCHING ALL TIME. AT TIMES	317
X	Other	WILL POP OUT.	410
X	Other	SEATBELT HARD TO BUCKLE	528
X	Other	SOP PASSENGER FRONT SEAT BELT. NOT CLICKING IN	528
X	Other	ADD RECALL 01821 SEAT BELT BUCKLE SOP HERE	812
X	Other	CHECK SAFETY BELT FAILED CHECK TEST SOP PARTS IN	812
X	Other	CUST STATES SEAT BELT LIGHT STAYS ON	843
X	Other	CUST SAID THE AIR BAG LIGHT IS ON	303
B	Won't Stay Latched	CUST STATES DRIVERS SIDE SEAT BELT WONT STAY LATCHED	688

PERFORMED CHECK OF CUSTOMER CONCERN OF VEHICLE FRONT PASSENGER SEAT BELT INOP. VERIFIED CONC. ERN AND PIN POINT TESTED CAUSE TO FAILED SEAT B BELT. REMOVED AND REPLACED FAILED SEAT BELT BUCK. L.E. R (568R BR5555 QD AS VERIFY CONCERN/REPLACED DRIVERS SEAT BELT BUCKLE/VERIFY REPAIR TECH 444) REPLACE SEAT BELT WILL NOT LATCH PROPERLY

DRV SEAT BELT BUCKLE POPE OFF REPL DR INOP SEAT BELT BUCKLE 4878 HAD TO REORDER PART FOR BUCKLE JAMMED REPLACE BUCKLE ASSEMBLY SEAT BELT BUCKLE COARS UNBUNDLED INTERMITTENTLY VERIFY CUSTOMER CONCERN REPLACE BUCKLE NECESSARY TO REMOVE PASS SEAT RETEST OK  
WONT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE CHECK OUT AND REPLACE DRIVERS SIDE SEAT BELT BUCKLE.  
1 REPLACED DRIVER SIDE BUCKLE.  
REPLACED PASS BELT BUCKLE DS  
1 REPLACED DRIVERS SIDE SEAT BELT AND PULLED CENTER SEAT BELT OUT OF COVER AND REPAIRED  
DRIVERS SEATBELT WILL UNLATCH AT TIMES BY ITSELF REPLACE SEAT BELT, RETEST, OK  
REPLACED THE RF BUCKLE ASBY  
FOUND FRONT SEAT BELT BUCKLE TO BE FAULTY REPLACED SEAT BELT BUCKLE RECHECK OK NOW

DIAG AND REPLACED DRIVERS SEAT BELT BUCKLE.  
REPLACE DRIVERS SEAT BUCKLE  
REPLACED ONE SEAT BELT. 2714  
REPLACE ONE BELT  
TEST AND REPLACE ERN/ATIO RF SEAT BELT BUCKLE ASBY NORMAL  
OPERATION RESTORED  
REPLACED DRIVER SEAT BELT BUCKLE  
1 VERIFIED COMPLAINT REPLACED BUCKLE WITH NEW ONE. RETEST OK WORKING PROPERLY.

REPLACED DRIVERS SEAT BELT BUCKLE  
REPLACE RF SEAT BELT BUCKLE  
REMOVED SEAT RAR SEAT BELT ASBY. RECHECKED OK  
VERIFY CONCERN REMOVE SEAT TO ACCESS BUCKLE. REPLACE BUCKLE AND REINSTALL SEAT. QC-CHECK, OPERATES PROPERLY  
REPLACE RF SEAT BELT BUCKLE  
PERFORM RECALL SEAT BELT BUCKLE UNBOLT CENTER SEAT REMOVE HARDWARE UNBOLT PASSENGER SIDE SEAT AND BRACKET PULL OUT TRUCK UNBOLT SEAT BELT BUCKLE INSTALL NEW SEAT BELT BUCKLE PLACE SEATS BACK IN TRUCK TRK  
REPLACED FAULTY PASSENGER BUCKLE  
REPLACED LEFT FRONT SEAT BELT BUCKLE  
REPLACED FRONT RIGHT SEAT BELT ASBY  
REPLACED SEAT BELT BUCKLE  
REAR BELT STUCK BEHIND REAR SEAT BOTTOM, RR SEAT AND REMOVE BELT. 1  
MISSED JHR TEST BELTS/REPLACE R FRONT SEAT BELT BUCKLE  
REPLACED BUCKLE  
VERIFY EJECT DIAG. PINPOINT FOUND DRIVERS SIDE PISTON/SHOER HIGH RESISTANCE REPLACE PISTON/SHOER. RETEST ALL OK  
SEAT BELT DEFECTIVE RSP PASS BELT BUCKLE

CHECK FOR LATCH OPERATION FOUND SEATBELT LATCH WITH FALLYTY LATCH NED TO REPLACE SEAT BELT LATCH ON PASSENGER SIDE

X	Other	540 CHECK CUSTOMER STATES THAT VEHICLE PASSENGER FRONT SEAT BELT IN INOP	825
D	Unlatches While Driving	655 DRIVERS SEATBELT WILL COME UNDOING AT TIMES WHILE DRIVING.	817
X	Other		816
D	Unlatches While Driving	CUSTOMER STATES DRIVERS SIDE SEAT BELT POPE OFF WHILE DRIVING	889
X	Other	INSTALL SEATBELT	847
X	Other	CHECK FOR DRIVERS SIDE SEAT BELT JAMMED	810
C	Unlatches/Releases	CUST. STATES PABLE SEAT BELT COMES UNBUCKLED ALL THE TIME	872
C	Unlatches/Releases	CUST REPORTS DR SIDE SEAT BELT COMES UNBUCKLED	806
X	Other	SEAT BELT CHIME WORKS INTERMITTEN	818
X	Other	DRIVERS SEAT BELT INOP.	823
X	Other	PASS SIDE SEAT BELT INOP.	309
A	Won't Latch	DRIVERS FRONT SEATBELT AND CENTER REAR DONT LATCH	807
B	Won't Stay Latched	CUST STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED	619
X	Other	RIGHT FRONT SEAT BELT BUCKLE INOP	
X	Other		408
B	Won't Stay Latched	CUSTOMER STATES BOTH FRONT SEAT BELTS INTERMITTENTLY WILL NOT STAY BUCKLED	851
X	Other	DRIVERS SEAT BUCKLE INOP	
A	Won't Latch	RT SIDE SEAT BELT BUCKLE WILL NOT LATCH CHECK FOR RECALL	406
X	Other	SEAT BELT BUCKLE RETENTION	781
X	Other	R SIDE FRONT SEAT BELT BUCKLE STICKS WHEN CLIPS STICKS	802
X	Other	D S SEAT BELT BUCKLE BUTTON BROKEN	
A	Won't Latch	PASSENGER FRONT SEAT BELT WONT LATCH	801
X	Other	DRIVER SEATBELT IN OPERATIVE	732
A	Won't Latch	PASSENGERS SEAT BELT WONT LATCH	
C	Unlatches/Releases	DRIVERS SEAT BELT UNLATCHES	888
A	Won't Latch	DRIVERS SEAT BELT DOES NOT LATCH INTO BUCKLE	702
A	Won't Latch	SEAT BELT W NOT BUCKLE	
X	Other	INSTALL SO SEATBELT	301
A	Won't Latch	USE SP0 DIZERS	570
X	Other	SEAT BUCKLE HERE WILL NOT LATCH	
X	Other	SEAT BELT LIGHT W NOT GO OFF	
X	Other	C B SEAT BELT ON DRIVER NOT WORKING RIGHT	261
A	Won't Latch	DRIVERS SEAT BELT WONT LATCH	
X	Other	CHECK FOR BELT IN CENTER SEAT, CANNOT FIND	888
X	Other	CUSTOMER STATES FRONT FRONT SEAT BELT INOPERATIVE	802
X	Other	SEAT BELT BUCKLE NOT WORKING PROPERLY	281
X	Other	HIS AIR BAG LIGHT IS ON	814
A	Won't Latch	REPORTS P R FRONT SEAT BELT BUCKLE WILL NOT LATCH	888
B	Won't Stay Latched	CHECK FOR PASSENGER SIDE SEATBELT DOESNT STAY LATCHED	409



BROKEN WIRE AT BUCKLE TRACK ASSEMBLY FRONT SEAT NISM TO RM									
DRIVERS DOOR MAKES A NOISE CORRECTION OF SQUEAKS & RATTLES, OR PERFORM MINOR INTERNAL D	X	Other	DRIVERS SIDE SEAT BELT BUCKLE PULLED OUT OF HARNESS						727
SEAT BELT CENTER SEAT BELT BUCKLE WENT INSIDE	X	Other	CURT. STATED DRIVERS DOOR MAKES A NOISE WHEN CLOSED						491
RETRACTOR REMOVE SEAT AND SEAT BELT ASBY, REMOVE BELT AND REINSTALL BELT ASBY AND SEAT AND VERIFY REPAIR	X	Other	CENTER SEAT BELT MISSING						308
R AND P PASS SEAT AND REPLACE BUCKLE	A	Wont Latch	PASSENGER SEAT BELT DOES NOT ALWAYS LATCH IN						693
REMOVE SEAT LATCH, INSTALL NEW LATCH, RECHECK OK	A	Wont Latch	DRIVERS SEAT BELT DOESNT LATCH						618
30 124 REPLACED LEFT BUCKLE ASBY.	C	Unlatches/Releases	THE CUSTOMER STATES THAT THE DRIVER (DRIVE) SEAT BELT CAME LOOSE ON THE LATCH SIDE						410
REPLACE SEAT BELT BUCKLE ASSEMBLY	X	Other	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE JAMMED						410
REPLACE SEAT BELT BUCKLE	X	Other	SEAT BELT BUCKLE NOT WORKING PROPERLY						281
LATCH BROKEN VERIFY CUSTOMER CONCERN AND REPLACE PASS SIDE BUCKLE.	D	Unlatches While Driving	SEAT BELT BUCKLE SOUNDS LIKE IT BUCKLES BUT COMES UNLATCHED WHILE DRIVING						910
DOESNT OPERATE PROP SEATBELT ASSEMBLY FRONT REPLACE 1 (REINSTALLED) SEAT BELT INERT PROPERLY.	C	Unlatches/Releases	PLEASE CK AT TIMES THE DRIVER SIDE SEAT BELT COMES LOOSE						327
REPLACE BOTH SEAT BELT ASSEMBLIES	X	Other	AND FROM RIGHT SIDE SEAT BELT INERT CAME OFF						379
FAIRLY BUCKLE TEST REMOVED RT FRT SEAT TO GAIN ACCESS & REPLACED SEAT BELT PASSENGER	X	Other	CUSTOMER STATES SEAT BELT'S BUCKLE						323
BUCKLES DEFECTIVE NECESSARY TO REPLACE	A	Wont Latch	SEAT BELT WONT LOCK SECURELY						581
30 W ASB VERIFIED CONCERN PERFORM RECALL N1821 REPLACE PASS FRONT RECOVER PARTS/ASSEMBLY. OK AT THIS TIME/QUALITY INSPECTED BY 88238	B	Wont Stay Latched	SEAT BELT BUCKLES WILL NOT STAY FASTENED						590
OVERIFY CUST COMPLAIN SEAT BELT INOP REPLACED BUCKLE	X	Other	INSPECT SEAT BELT BUCKLES FOR RECALL 01821						664
REPLACE LEFT FRONT SEAT BELT	X	Other	SEAT BELT BUCKLE INOP						684
VOH1 1.8 HRS TESTED OLD SEATBELT, REPLACED WITH NEW. CP	X	Other							326
NOT LOCKING PROPERLY REPLACE DR AND SEAT BELT BUCKLE	C	Unlatches/Releases	CUSTOMER SAYS THE LEFT SEATBELT COMES UNBUCKLED						381
BROKEN SEATBELT ASSEMBLY FRONT REPLACE	B	Wont Stay Latched	DRIVERS SEAT BELT BUCKLE WILL NOT STAY LATCHED						291
REPLACED CONSOLE LID.	D	Unlatches While Driving	CUSTOMER STATES DRIVERS SEAT BELT BUCKLE COMES UNLATCHED WHILE DRIVING DOWN THE ROAD						941
REPLACE DEFECTIVE SEAT BELT	A	Wont Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH						512
COX88 REPLACED DRIVERS SEAT BELT	X	Other	INSTALL SOP PART CENTER CONSOLE						628
3111111111	X	Other	CK THAT THE DRIVERS SEAT BELT IS HANGING UP, SOP PART IS IN RECALL 01821 LAR						592
31UN VERIFIED THAT THE DRIVERS SEATBELT BUCKLE NOT LATCHING ALL OF THE TIME, FOUND IT NECESSARY TO REMOVE DRIVERS SEAT FOR ACCESS AND REPLACED BUCKLE, RETEST OK HAD TO ORDER ONE SEAT BOLT TRIM C	A	Wont Latch	948 DRIVERS SEAT BELT WILL NOT HOLD						618
INOP REPLACE DRIVERS SEAT BELT BUCKLE	X	Other							608
REPL SEAT BELT	A	Wont Latch							618
E VERIFIED COMPLAINT REPLACED SEAT BELT BUCKLE	X	Other							608
E VERIFIED COMPLAINT REPLACED DRIVERS SEAT SEAT BELT BUCKLE	A	Wont Latch	DR SEATBELT WONT LOCK ALL THE TIME VERIFIED ON THE DRIVE						602
6737 42 HRS VERIFIED SEAT BELT NOT BUCKLING PROPERLY REPLACED BUCKLE AND RECHECK ALL OK AT THIS TIME	A	Wont Latch	DRIVERS SEAT BELT ORANGE RELEASE DOES NOT POP UP						770
X SEATBELT ASSEMBLY FRONT REPLACE	B	Wont Stay Latched	SEATBELT WILL NOT STAY HOOKED						770
OK SEAT BELT AND REPLACE INOP	A	Wont Latch	CUSTOMER STATES DRIVERS SEAT BELT WONT LATCH						310
A ROAD DRIVERS WIPER ARM DRIVERS SIDE COWL PANEL	D	Unlatches While Driving	CURT STATES DRIVERS SIDE SEAT BELT UNLATCHES WHILE DRIVING						310
SEAT BELT POPS LOOSE REPLACED	X	Other	CUSTOMER STATES THE INTERMEDIATE SEAT LEFT SEAT BELT BUCKLE IS IN OP SOP REFER ROSSBOR 11 3 01 8411 MILES PER						325
MOULDING MOULDING REAR DOOR REPLACE	X	Other	CURT STATES SEATBELT ALARM BEEPS BEEPING SPACE REPLACED BUCKLE UNDER RECALL						663
TEST ALL SEAT BELTS PASSENGER SIDE FAILED R AND R SEAT TO INSTALL NEW SEAT BELT BUCKLE ASBY DUE TO BEING BROKEN	X	Other	OK SEAT BELT OPERATION						648
REPLACED RIGHT SEAT BELT BUCKLE	X	Other	WEATHERSTRIPPING AROUND DRIVERS SIDE FRONT WINDOW HAS COME LOOSE						788
	O	Unlatches/Releases	249 CUSTOMER STATES LEFT FRONT SEAT BELT POPS LOOSE						476
	X	Other	CUSTOMER STATES DRIVERS SIDE REAR DOOR MOULDING LOOSE (SEE NEXT DROP)						770
	A	Wont Latch	CUSTOMER STATES AT TIMES PASSENGER SIDE FRONT SEATBELT BUCKLE STICKS AND WILL NOT FASTEN						298
	A	Wont Latch	RIGHT FRONT SEATBELT BUCKLE WONT LATCH						780

REPLACED DRIVERS SIDE BUCKLE

61 SEATBELT ASSEMBLY FRONT REPLACE  
 PERFORM RECALL INSPECT SEATBELT BUCKLES REPLACE LEFT  
 FRONT BUCKLE  
 RECALL INSTALLED SPECIAL ORDERED PART FOR SEATBELT BUCKLE  
 RECALL ASS  
 REPLACE SEAT BELT ASSY

LEFT MIDDLE SEAT LEVER OFF REINSTALLED LEVER

REPLACED SEAT BELT BUCKLE  
 REPLACE SEATBELT ASSEMBLY FRONT REPLACE

64 2891269 REPLACE LEFT FRONT SEAT BELT BUCKLE

OPENING REPLACE SEAT BELT

1 REPLACE SEAT BELT

REPL BUCKLE ASSY RPT

757 INSPECTED SEAT BELT BUCKLES IN FRONT SEAT WITH BUCKLE  
 TESTER FOUND THE PRESSURE BUCKLE TO BE BAD RECOMMEND  
 REPLACING AND NOT HAVING ANYONE USE THAT SEAT UNTIL REPAIRED  
 807 P A

01521 01521  
 INSPECT BELTS BELT RETRACTED INFO SEAT BELT COVER, R R SEAT BELT  
 ASSEMBLY, DRILL OUT BOWTIE THAT HOLD COVER TO BELT  
 VERIFIED CONCERN AND REPLACED DRIVER SIDE SEAT BELT.  
 OPEN IN SEAT BELT SWITCH REMOVE AND REPLACED SEAT BELT  
 BUCKLE

REPLACE BOTH FRONT SEAT BELTS WONT STAY BUCKLED  
 CHECK DRIVERS SEAT BELT DIAGNOSIS AND REPLACE DRIVERS SIDE  
 SEAT BELT BUCKLE COMES LOOSE

61209 41 REPLACE FRONT SEATBELT BUCKLES

REPLACED SEAT BELT FOR MID KAWAZIN

OK FOR THE RIGHT FRONT SEAT BELT WONT LOCK VERIFY R/R  
 PASSENGER SIDE FRONT SEATBELT BUCKLE

R/R DRIVERS SEAT TO REPLACE SEAT BELT BUCKLE WOULD NOT LATCH  
 R/R B PILLAR TRIM R/R SEAT BELT INSTALL BUDDER TRIM, ALSO REPL BELT  
 BUCKLE INOP

REMOVE END ROW MIDDLE SEAT BELT TONGUE OUT OF HOLDER  
 12805 REMOVE DRIVER SEAT AND REPLACE BELT.

REPLACED DRIVERS SIDE SEAT BELT BUCKLE

REPLACE LEFT FRONT SEAT BELT  
 N80 TO REPLACE SEAT BELT  
 SEAT BELT BUCKLE WILL NOT LATCH. VERIFIED CONCERN REPLACED  
 SEAT BELT LATCH RECHECKED OK  
 RENTAL RENTAL  
 RENTAL RENTAL  
 REPLACED BUCKLE

1173 DEF BUCKLE W UNABLE TO VERIFY REPLACED SUSPECT DRIVERS  
 SEAT BELT BUCKLE ASSY RETEST OK  
 REPLACED AT FRNT SEATBELT ASSY.

11843 INSTALL NEW BULE FOR DRIVER SEATBELT  
 & RECALL 01521 REPLACED L AND R SEAT BELT BUCKLES PER RECALL  
 POWER BUCKLE SEATE  
 13212 DRIVERS SEAT BELT WONT STAY BUCKLED WARN. REPLACED L F  
 SEATBELT BUCKLE

A	Worn Latch	CUSTOMER STATES THAT THE DRIVERS SIDE SEAT BELT WILL NOT BUCKLE SOMETIMES	812
A	Worn Latch	CUSTOMER STATES THE PASSENGERS FRONT SEATBELT BUCKLE WONT BUCKLE	818
X	Other	INSTALL SEAT BELT BPO	790
X	Other		608
X	Other	LH SEAT BELT WONT LATCH (SPECIAL ORDER PARTS LEVER FOR LEFT SIDE MIDDLE SEAT PELL OFF	316
X	Other	BY WPI	815
A	Worn Latch	DRIVER SEATBELT WONT STAY LATCHED	713
X	Other	SOP SEAT BELT BUCKLE	828
X	Other	CUST STATES THE LEFT FRONT SEAT BELT & SOP SEAT BELT	818
X	Other	CUST STATES DR SEAT BELT POPS OPEN SOP	818
X	Other	01521 SOP POPS SEAT BELT	878
A	Worn Latch	DRIVERS SEATBELT FRONT LOCK AT TIMES	790
		CUST STATES RIGHT FRONT SEAT BELT BUCKLE AT TIMES AFTER SEEMINGLY BUCKLED, WILL COME UNBUCKLED AFTER HARD STOP CHECK	
D	Driving	AND ADVISE CODE 840	707
X	Other	REPLACE BOTH SEAT BELT BUCKLES PER RECALL	808
X	Other	CUST STATES CENTER SEAT BELT IN CENTER ROW IS PUSHED UNDER SEAT	732
C	Unlatches/Releases	DRIVER SIDE SEAT BELT KEEPS COMING UNBUCKLE CHECK SEAT BELT WARNING BELLINGER, GOES OFF WHEN DRIVING (CHIMES)	358
X	Other		868
C	Unlatches/Releases	BOTH SEAT BELTS COME UNBUCKLED AUTOMATICALLY ISOP 840	418
C	Unlatches/Releases	CHECK DRIVERS SEAT BELT COMES LOOSE	890
X	Clear	FRONT SEATBELT BUCKLES STICK	891
X	Other	CUST STATES SEAT BELT FAILED	818
A	Worn Latch	OK FOR THE RIGHT FRONT SEAT BELT WONT LOCK	848
A	Worn Latch	C-4 LFT. SEAT BELT WONT BUCKLE UP, ADVISE S O PART	818
X	Other	TRIM DR SIDE BELT PLASTIC MISSING	867
X	Other	MIDDLE SEAT BELT MISSING, SOP HUBBIE	861
X	Other	DRIVERS SEAT BELT BUCKLE SOP	812
	Unlatches While	CUSTOMER STATES DRIVERS SIDE SEAT BELT WILL UNFASTEN ITSELF WHILE DRIVING	
D	Driving		810
X	Other		870
X	Other	REPLACE SOP SEATBELT	847
X	Other	CH-60K SEAT BELT LODGE	628
A	Worn Latch	CUST STATES THE DRIVERS SEAT BELT WONT LATCH OK AND ADVISE ESP RENTAL WPI PO 88312 HERTZ#8883278 FOR 82 88 PO#186784	767
X	Other	RECALL WCH FOR THREE DAMG BEL PO 88388 PO 18268 3L88	
X	Other		
C	Unlatches/Releases	DRIVERS SEATBELT KEEPS COMING UNDOING " " LEFT FRONT BUCKLE HARD TO RELEASE AT TIMES " " SEAT BELTS BUCKLE " OTHER FRONT DRIVERS SIDE #48 OTHER RESTRAINT CONCERN L:	828
X	Other	R F SEATBELT WILL NOT STAY BUCKLED. S O P.	757
B	Worn Stay Latched	INITIAL NEW BULE FOR SEATBELT. PART IS IN	520
X	Other		767
X	Other	01521 SEAT BELT BUCKLE RETENTION ADMIN APPLIES	718
B	Worn Stay Latched	DRIVERS SEAT BELT W STAY BUCKLED SOP	418

REPLACE R FRONT SEAT BELT BUCKLE ASBY FOR WILL NOT LATCH CONCERN  
 888 TROUBLE 42 REPLACED PASS FRONT SEATBELT  
 8888 REPLACE L F SEATBELT  
 REPLACE BUCKLE  
 SEAT BELT TONGUE WILL NOT HOLD REPLACE SEAT BELT TONGUE ON  
 DRIVERS SEAT

REPLACED SEAT BELT AND BUCKLE  
 RIGHT FRONT SEAT BUCKLE POP REPLACE BELT BUCKLE ASSEMBLY,  
 BENDING BOP  
 3 SEATBELT WAS CHECKED AND FAILED THEN WAS REPLACED AND  
 RETESTED AND PASSED THE MILEAGE SHOULD BE 13  
 BUCKLE INSTALL BOTH SEATBELT BUCKLE  
 REPLACE BOTH FRONT SEAT BELT BUCKLES  
 SEATBELT BUCKLE JAMMED REPLACE BELT BUCKLE  
 REPLACED DRIVERS SEAT BELT BUCKLE  
 INSPECTED AND FOUND LOOSE DRIVERS SIDE SEAT BELT BUCKLE  
 REPLACED BUCKLE IN TIME USED AS NO OPS AVAILABLE FOR BUCKLE. OK  
 FOR PA  
 DRIVERS SIDE SEAT BELT INSTALLED  
 INSPECTED AND FOUND SEATBELTS BAD, REPLACED PER RECALL

REPLACED SEAT BELT  
 REPLACE LT SEAT BELT BUCKLE  
 7888 REPLACE L SEAT BELT BUCKLE  
 REPLACED FRONT PASSENGER SEAT SEATBELT, WOULD POP OUT BY  
 ITSELF  
 VERIFIED CONCERN, FOUND RIGHT FRONT SEAT BELT BUCKLE NAR  
 BUCKLE ASSEMBLY NOW OPS NORMALLY  
 REPLACE FRONT SEATBELT ASBY  
 REPLACE BOTH FRONT SEATBELT LATCHES FOR CUSTOMER SAFETY  
 CONCERN

DIAGNOSE FOUND THAT THE SWITCH IN BUCKLE IS NOT WORKING.  
 DOESNT OPEN CIRCUIT WHEN BELT IS INSERTED. REPLACED BUCKLE, NO  
 LABOR CHG USED IN TIME  
 BUCKLE COMES LOOSE, REPLACE  
 8788 SOMETHING STICKY IN LATCH WARR REPLACE DRIVERS SEAT BELT  
 BUCKLE  
 REPLACE SEATBELT WILL NOT LATCH PROPERLY  
 1 INSTALL BOP SEAT BELT ENDS IN NEW CAR

REPLACED SEAT BELT

DIAG REP VERIFIED CONCERN AND REPLACED BOTH SEAT BELT BUCKLES

RAR DRIVERSIDE SEATBELT  
 REPLACED THE BUCKLE

REPLACE SEAT BELT BUCKLE, PASSENGER SIDE  
 1 REPLACE SEAT BELT BUCKLES  
 REPLACE DRIVERS SEAT BELT BUCKLE  
 COACH PERFORMED RECALL 018710  
 REPLACED DRIVERS SIDE SEAT BELT  
 BUCKLE INOPERABLE. REPLACED RIGHT FRONT OUTBOARD SEATBELT  
 BUCKLE NO LYS FOUND  
 8888 FOUND THAT SEAT BELT WAS BROKEN INTERNALLY AND WOULD  
 NOT LATCH. REMOVED SEAT AND REPLACED SEATBELT. REINSTALLED SEAT

A	Won't Latch	PASSENGER SIDE SEAT BELT WILL NOT LATCH BOP PART HERE	780
X	Other	PASS FRONT SEATBELT, BOP HERE	818
X	Other	INSTALL BOP L F SEATBELT	780
G	Unlatches/Releases	DUST STATER: DRIVERS (BOP) SEAT BELT KEEPS POPPING OUT	846
	Unlatches While	DRIVER SIDE SEAT BELT KEEPS POPPING OPEN WHILE DRIVING DOWN THE	
D	Driving	HWY	770
	Unlatches While		
D	Driving	DRIVER SEATBELT WILL COME UNLATCHED WHEN DRIVING	314
X	Other	DUST STATER RIGHT FRONT SEAT BELT IN BOP BOP IS IN	881
X	Other	DRIVER SEATBELT BOP	847
X	Other	SEATBELTS BROKE	818
X	Other	SEAT BELT IS NOT WORKING PASSENGER SIDE	784
A	Won't Latch	DRIVER FRONT SEATBELT WILL NOT ENGAGE	780
X	Other	DRIVERSIDE SEAT BELT BUCKLE INOP	713
	Unlatches While		
D	Driving	CUSTOMER STATES DRIVERS SIDE SEAT BELT COMES UNLATCHED ON BUMPY	
X	Other	ROADS OK AND ADVISE	807
X	Other	INSTALL DRIVERS SIDE SEAT BELT BOP	816
X	Other	01821 SPECIAL ORDER PARTS	488
	Unlatches/Releases	CUSTOMER STATES DRIVERS SEAT BELT COMES UNLATCHED AT	
D	Driving	TIMES COULD NOT VERIFY FOR RECALL	784
B	Won't Stay Latched	LT SEAT BELT WONT STAY LATCHED	718
X	Other	SEAT BELT BUCKLE BOP	718
G	Unlatches/Releases	REPLACE SEATBELT ON PASSENGER SEAT	488
X	Other	CUSTOMER SAYS PASSENGER SIDE SEAT BELT INOP	818
X	Other	CHECK FRONT SEATBELTS LOCKS	843
	Unlatches/Releases	CHECK FOR DRIVERS SIDE SEAT BELT KEEPS COMING LOOSE, BUCKLE NOT	
G	Unlatches/Releases	HOLDING, PLEASE CHECK ALL, ADVISE.	788
X	Other	WHEN DRIVING WITHOUT DRIVERS SIDE SEAT BELT ALARM IS NOT GOING	
C	Unlatches/Releases	OFF TO WARN YOU.	781
	Unlatches/Releases	PASSENGER SEAT BELT DOES NOT HOLD	418
A	Won't Latch	"SEAT BELTS BUCKLE WONT LATCH FRONT DRIVERS SIDE 848 OTHER	
X	Other	RESTRAINT CONCERN L:	787
X	Other	BOP SEATBELT ENDS	818
X	Other	DRIVERS SEAT BELT WONT RETRACT PROP BOP IS IN BOP ORDERED RD	847
X	Other	27708	888
X	Other		888
A	Won't Latch	CUSTOMER STATES FRONT SEAT BELTS WILL NOT LATCH, BOP THE DRIVERS SEAT,	
X	Other	RT SEAT BELT BUCKLE BROKEN	780
X	Other	OTHER DRIVERS SIDE TROUBLE NO SEAT BELT IN V4 WEED ONE	
X	Other	ORDERED	818
X	Other	FACTORY WARRANTY FRONT SEATBELTS WONT HOLD SEATBELTS	888
X	Other	LEFT FRONT SEAT BELT BUCKLE INOP	872
X	Other	ELCJP 185721 BEL & BILE ABY FRT ST LH, LEFT FRONT SEAT BELT	818
X	Other	DRIVERS SIDE RIGHT SEAT BELT MISSING	831
A	Won't Latch	CUSTOMER REQUESTS REPLACE 6 O SEATBELT, RIGHT FRONT BUCKLE	
A	Won't Latch	DOES NOT LATCH	807
A	Won't Latch	BOP IN FROM R077017 INSTALL TECH 8 848 03 22 2002 PASSENGER SIDE	
A	Won't Latch	FRONT SEAT BELT DIFFICULT TO LATCH	840

REPLACED LH SEAT BELT BUCKLE USED W/ TIME TO REMOVE CROSS  
THREADED NUT  
INSTALLED NEW SEATBELT BUCKLES

INSTALL NEW SEAT BUCKLES LEFT FRNT SEAT W/ AIR 42  
REPLACED THE BUCKLE  
BUCKLE WOULD NOT LATCH INSTALLED NEW BUCKLE  
REPLACED LEFT FRONT SEAT BELT  
CHECK AND REPLACE SEAT BELT LEFT SIDE SEAT BELT BUCKLE  
REPLACED RIGHT SIDE SEAT BELT  
1 REPLACED SEAT BELT BUCKLE PER RECALL  
REPLACED BUCKLE ASBY WIRES WERE PINCHED CUTTING INTO SEAT  
TRACK  
SYSTEMS AT WPI

REPLACED DRIVERS SIDE SEATBELT  
RR DRIVERS SIDE BUCKLE ASBY PROBLEM WPI  
CHECK SEAT BELT OPERATION/REPLACE LEFT FRONT SEATBELT (42)  
LF SEAT BELT COMES ONLATCHED TEST REPLACED MULT ASS  
BUCKLE SEATBELT ASSEMBLY FRONT REPLACE  
NOPERATIVE REPLACE LEFT SEAT BELT BUCKLE  
REMOVED SEAT AND REPLACED SEAT BELT LATCH  
4799 R/R PASSENGER FRONT SEAT R/R FEMALE SEAT BELT BUCKLE  
REPLACED & REINSTALLED SEAT  
REPLACE RT HAND SEAT BELT  
REPLACED PASSENGER SIDE SEAT BELT BUCKLE  
NEO TO REPLACE SEAT BELT  
SUSPECTED AND REMOVED RIGHT SEAT TO REPLACE SEAT BELT BUCKLE  
AND RETESTED OK.

860 DEFECTIVE SEAT BELT BUCKLE DRIVERS SEATBELT BUCKLE  
INTERMITTENTLY INOP, REBORN AND REPLACED SEATBELT BUCKLE.  
CONFIRMED CUSTOMER CONCERN, REPLACED SEATBELT ASSEMBLY  
REPLACE RT HAND SEAT BELT.  
REPLACE RT HAND SEAT BELT.  
FALTY RECEIVER INSPECT AND REPLACE RECEIVER  
REPLACE SEAT BELT  
REPLACED DRIVER SIDE SEAT BELT

SEAT BUCKLE ON SIDE CUST  
RETURNED FOR BUCKLE  
REPLACEMENT R/R DR SEAT  
ASBY R/R SEAT BELT BUCKLE  
ASBY REPLACED RETESTED  
OK AT THIS TIME CAUSAL'S  
PENDING

8077 WARR TESTED DR SEAT BELT BUCKLE ROAD TESTED 10 MILES LAMP  
WONT COME ON INSPECTED IN FET HARNESS AND NBS TESTED GEM NO  
CODES WORKS PROPERLY AT THIS TIME POSS INTERMITTENTLY SHORTING IN  
BUCKLE CIRCUIT  
REPLACE DRIVER SEAT BELT  
PART ON ORDER ON BE OR REPLACE LEFT FRONT SEAT BELT BUCKLE .  
DRIVER SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT  
REPLACE  
REMOVED & REPLACED LEFT FRONT SEAT BELT BUCKLE  
REPLACED LEFT FRONT SEATBELT  
REPLACED SEAT BELT

1216 W CHECKED DRIVERS SEAT BELT OPERATION TO FIND FAULTY  
SEAT BELT BUCKLE ASBY FMR BUCKLE ASBY TO FIX CONCERN RETEST  
INSTALLED REVISED SEAT BELT BUCKLES  
W/ TIME IS LHM TO REPLACE SEAT BELT BUCKLE ON DRIVERS SIDE PER  
#1821. NOTE: VEHICLE NOT LISTED IN DAIMS AS INVOLVED IN #1821  
RECALL, BUT OPTED TO GO AHEAD AND REPLACE BUCKLE SINCE SAFETY  
ISSUE ON A NEW

STOCK UNIT IS INVOLVED

A	Went Latch	SEATBELT WOULD NOT LATCH INTERMITTENT PROBLEM DRIVERS SEAT	802
A	Went Latch	LP & MIDDLE REAR SEAT BELTS FRONT LATCH CHECK FOR REASON THE VEHICLE DID NOT HAVE A DRIVERS SEAT BELT BUCKLE FROM THE FACTORY	703
X	Other	LH SEAT BELT INOP	785
X	Other	RT FRNT SEAT BUCKLE INOP	888
A	Went Latch	CHECK LEFT FRONT SEAT BELT DOES NOT OPERATE PROPERLY	818
X	Other	CUSTOMER STATED SEAT BELT NOT WORKING PROPERLY/ BELT IS	820
X	Other	CUSTOMER REQUESTED TO CHECK SEAT BELT FUNCTION	
X	Other	INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION	
X	Other	SEAT BELT ALARM GOES OFF WHEN SEAT BELT IS LATCHED	840
X	Other		
C	Unlatches/Retains	CUST STATES DRIVERS SEAT BELT RELEASED BY ITSELF INTERMITTANTLY	821
X	Other		
A	Went Latch	CHECK LEFT FRONT SEAT BELT WONT CLICK INTO THE BUCKLE (440)	308
C	Unlatches/Retains	DRIVER SEAT BELT COMES DISCONNECTED	808
A	Went Latch	DRIVERS SIDE SEATBELT NOT LOCKING IN	702
A	Went Latch	SEAT BELT DOES NOT LATCH LEFT FRONT	228
X	Other	PASS SIDE SEAT BELT IN OP	781
X	Other	CUSTOMER STATES THE RIGHT FRONT PASS. SIDE SEATBELT IS JAMMED	
A	Went Latch	LP, ROP & Y1877A	703
A	Went Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH	817
B	Wont Stay Latched	PASSENGER SEAT BELT WONT STAY BUCKLED	853
X	Other		770
D	Unlatches/Retains	CLIENT STATES FRONT PASSENGER SEAT BELT UNBUCKLES ON ITS OWN INTERMITTENTLY. ADVISE	
A	Went Latch	846 SEATBELT WOULD NOT LATCH	816
X	Other	CUSTOMER STATES SEAT BELT BINDING	803
A	Went Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Went Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH.	817
A	Went Latch	PASSENGERS FRONT SEAT BELT BUCKLE WILL NOT RECEIVE BELT.	380
X	Other	DRIVERS SEAT BELT WORKS UNUSUALLY	318
X	Other		
X	Other	THE SEAT BELT LIGHT COMES ON WHILE DRIVING EVEN THOUGH THE SEAT BELT IS BUCKLED	360
X	Other	CUST STATES SEAT BELT INOP ROP BELT	724
A	Went Latch	826 DRIVERS SEAT BELT WILL NOT LATCH	214
C	Unlatches/Retains	DRIVERS SEAT BELT WONT HOLD COMES UNDONE	864
X	Other	CONDUCT FOR LEFT FRONT SEAT BELT BUCKLE INOP	888
A	Went Latch	LEFT FRONT SEAT BUCKLE WONT LATCH	821
X	Other	LEFT SEATBELT IS INOP	691
A	Went Latch	OK DRIVER SEATBELT WILL NOT HOLD	601
X	Other	SEAT BELT LATCHES UNUSUALLY	818
A	Recall Performed	DRIVERS SIDE SEATBELT BUCKLE FAILED #1821 INSPECTION	801

BUCKLE R/R SEAT BELT ASBY REPLACED BELT BUCKLE  
 REPLACE DRIVER SEAT BELT BUCKLE  
 REPLACE BUCKLE  
 2001 VERIFIED DRIVERS SEAT BELT LATCH FAILURE, RECONYED AND  
 REPLACED SEAT BELT RECEIVER AND RETESTED,ALL FUNCTIONS  
 NORMAL.(BUCKET7)  
 7804R INOPERATIVE VERIFY RT SEATBELT NOT FASTENING REPLACE RT  
 SEATBELT BUCKLE

1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE  
 220E ELECTRICAL DIAG PIN POINT TEST RESTRAINT SYSTEM, FOUND  
 DRIVERS SEAT BELT BUCKLE TO HAVE AN OPEN R/R DRIVERS SEAT &  
 REPLACE SEAT BELT BUCKLE. \*\*\* QUALITY CONTROL BY JOHN MEDROW  
 \*\*\*

INSTALLED SEATBELT REPLACED SEATBELT  
 COILS REPLACED RIGHT FRONT SEAT BELT BUCKLE ASBY  
 DRIVERS SEAT BELT WONT LATCH REPLACE SEATBELT

1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE

SEATBELT MAKES NOISE R SEATBELT ASSEMBLY FRONT REPLACE  
 REPLACED SEAT BELT BUCKLE NOISY  
 REPLACED SEAT BELT 01821 RECALL  
 RECALL PERFORMED RECALL, REPLACED SEAT BELT  
 BUCKLE RT FRONT FRONT

480S FAULTY RT SIDE BUCKLE INIC TO REPLACE RT SIDE BUCKLE  
 OK LFT FT SEAT BELT OPER, FOUND FAULTY LFT FT SEAT BELT BUCKLE  
 REPLACED, RETEST, OK NO OP CODE UT 0180 7  
 8071 REPLACE SEAT BELT BELT WAS BROKEN CODE 01 PART NO 1LZ  
 780186 848

RECALL 01821  
 REPLACE O CENTER BUCKLE MISMATCHED  
 BROKEN LATCH. R & R PASSENGER FRONT SEATBELT LATCH  
 SEAT BELT INOP. REPLACED PASSENGER SIDE SEAT BELT  
 SEAT BELTS WILL NOT RETRACT  
 MO.1888 COILS VERIFIED CUSTOMERS CONCERN. REPLACED DRIVER SEAT  
 BELT BUCKLE.

1 INSPECT AND REPLACE R FRONT SEAT BELT BUCKLE  
 SEAT BELT WONT HOLD. REPLACED DRIVERS SEAT BELT  
 17M YR1888 28 WTY RAN BODY CHASSIS ELECTRICAL, TEST AND PINPOINT  
 TEST AND DIAGNOSIS AND REPLACED DRIVERS SEAT AND RELEASE SEAT  
 BELT BUCKLE ASBY FOUND THAT IT HAD INTERMITTENT INOP @ SWITCH  
 INTERHALL Y, RETEST AND OK

NOT LATCHING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT  
 REPLACE  
 CUST STATE THAT FRONT PASSENGER SIDE SEAT BELT BUCKLE IS INOP  
 PART IS HERE. CAUSE SEAT BELT BUCKLE COILS. RECALLED DEFECTED  
 SEAT BELT BUCKLE APPROX TIME 0 4 HRS JOB STARTED 12/8/12 3 ON 08 08  
 02

SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE  
 REPLACE RT SIDE BELT  
 REPLACED BUCKLE ASSEMBLY  
 REP BELT BUCKLE RATTLING  
 INSPECT PASS SIDE SEAT BELT REPLACE DEFECTIVE SEAT BELT

RECALL REPLACE RT FT BUCKLE

B	Wont Stay Latched	CHECK LEFT FRONT SEATBELT WILL NOT STAY LATCHED	770
C	Unlatched/Releases	SEATBELT COMES UNLATCH DR FRNT ...SOP	882
X	Other	DRY SEAT BUCKLE INOP	
B	Wont Stay Latched	CUST STATES DRIVERS SEAT BELT SOMETIMES WONT STAY LATCHED	480
A	Wont Latch	RP SHOULDER HARNESSES WILL NOT BUCKLE	916
X	Other	RECALL 01821 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12	941
X	Other	SEAT BELT LIGHT AND CHIME COMES ON WHILE DRIVING, DRIVERS SEAT BELT IS BUCKLED WHEN THIS HAPPENS	917
X	Other	REMOVE SEATBELT FOR NO 8804 WRONG PART ORDERED EMERGENCY ORDER L F SEATBELT BUCKLE	901
X	Other	REPLACE SEAT BELT MISSEME BUCKLE ON PASS SIDE	919
A	Wont Latch	DRIVERS SIDE SEAT BELT DOES NOT LATCH PROPERLY	818
X	Other	RECALL 01821 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 77	941
X	Other	INSTALL SPO FRONT PASS SIDE SEAT	400
X	Other	SEATBELT RATTLING	801
A	Wont Latch	SEAT BELT BUCKLES DONT LATCH	727
R	Recall Performed	RECALL IN SEAT SAFETY RECALL SEAT BELT BUCKLES	910
A	Wont Latch	RT FT SEATBELT WILL NOT LATCH	801
X	Other	CUST STATES DRIVERS SIDE SEATBELT INOP	914
X	Other	DRIVERS SEAT BELT IS INOPERATIVE	251
R	Recall Performed	DRIVERSIDE AND PASSENGER SIDE SEAT BELT BUCKLES INOP	702
X	Other	INSTALL SOP SEAT BELT	900
X	Other	CUSTOMER STATES PASSENGER SEAT BELT INOPERATIVE	280
X	Other	CUSTOMER STATES PASSENGER SIDE SEAT BELT INOP	829
X	Other	COILS NOT OPERATE PROPERLY DRIVERS SIDE SEAT BELT INOP	928
A	Wont Latch	840 DRIVER SIDE FRONT SEAT BELT DOES NOT BUCKLE	814
X	Other	RECALL 01821 SEAT BELT BUCKLE REPLACEMENT RIGHT FRONT TRIM CODE 12	941
X	Other	CUSTOMER STATES DRIVERS SEAT BELT INOP SOP	861
X	Other	ASB O B SEAT BELT LIGHT DOESNT COME ON AT TIMES	804
C	Unlatched/Releases	CUSTOMER STATES DRIVERS SEAT BELT UNLATCHES AT TIMES	714
X	Other	CUST STATES THAT FRONT PASSENGER SIDE SEAT BELT BUCKLE IS INOP PART IS HERE AND RAISE. USE SPO 8208811	882
X	Other	CUST STATES PASS SEAT BELT INOP INSTALL SOP (7088 72.3 30 OR 88	780
X	Other	CUSTOMER STATES THAT RT SIDE BELT INOP	817
X	Other		895
X	Other	L F FEMALE SEATBELT RECYCLE RATTLES INSIDE	824
A	Wont Latch	PASS SIDE SEAT BELT BUCKLE WONT LATCH	840
X	Other	CUSTOMER STATES FRONT PASSENGER SEAT BELT DOES NOT LATCH PROPERLY	806

LFT FRNT SEAT BELT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE  
 CK AND REPLACED LFT FRNT SEAT BELT BUCKLE ASSY,  
 REPLACED LFT FRONT SEAT BELT ASSY

REPLACE DRIVERS SEAT BELT BUCKLE  
 COMING APART SEAT BELT ASSEMBLY REAR RIGHT OR LEFT  
 REPLACE

NOISE DRIVERS SIDE SEAT BELT BUCKLE SHORTED TO GROUND VERIFIED  
 CONCERN PERFORMED B C E BELT TEST, RECEIVED DRIVERS SIDE SEAT  
 BELT BUCKLE CONCERN DTC, PERFORMED B C E PINPOINT TEST, FOUND  
 DRIVE RS

PERFORMED RECALL: REPLACED AND RETEST LEFT HAND SEATBELT  
 REPLACE SEAT BELT  
 I REPLACE BELT BUCKLE  
 RIGHT FRONT SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT  
 REPLACE  
 R AND R DRIVERS SEAT FOR ACCESS, REPLACE BELT BUCKLE WONT  
 LATCH

SEAT BELT INOP REPLACED PASSENGER SEAT BELT BUCKLE  
 1018 DO BY WARRANTY REPLACED DRIVER SIDE SEAT BELT BUCKLE AND  
 SEATBELT WARNING NOTAL

REMOVE REPLACE LEFT FRONT SEATBELT BUCKLE ASSEMBLY

INOP SEATBELT ASSEMBLY FRONT REPLACE  
 SEAT BELT JAMMED REPLACED DRIVERS SEAT BELT  
 FAULTY SEATBELT (STRIP) DIAGNOSIS AND REPLACED LF SEAT BELT  
 BUCKLE  
 REPLACE LEFT SEAT BELT BUCKLE, NO TIME LISTED  
 REPLACE RIGHT SEAT BELT,  
 REPLACED BUCKLE

REPL. DRIVERS SEAT BELT BUCKLE WPLADD ON AUTHD BY AS  
 LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH, REPLACED SEAT BELT  
 BUCKLE NOW OK. IN OR ON IN OR AL

REPLACED SEAT BELT  
 WONT LOCK REPLACED PASS SEAT BELT BUCKLE  
 DISEN RECALL INSPECTED AND REPLACED RT SIDE SEAT BELT  
 BUCKLE AS PER RECALL 0188

BELT INOP IN TIME TO TEST BUCKLE OPG REPLACED BUCKLE  
 PERFORMED SEAT BELT TEST DRIVER BELT FAILED RAR SEAT AND RAR  
 SEAT BELT TEST OK  
 SEAT BELT BUCKLE INOP RAR PASS FRONT SEAT TO REPLACE SEAT  
 BELT BUCKLE

STR RECALL 02 TESTED AND REPLACED BOTH FRONT SEATBELTS  
 18 W TECH 888 VERIFIED CONCERN I DR SEAT TO BARN ACCESS TO FR  
 SHD SEAT BELT BUCKLE RETEST, SEAT BELT LATCHES AND UNLATCHES AT  
 THIS TIME QUALITY INSPECTED BY 888, 18  
 INTERNAL BUCKLE FAILURE M.O. 1871 REPLACED RIGHT FRONT SEAT BELT  
 BUCKLE TEST WORKS PROPERLY

SIDE SEAT BELT BUCKLE  
 SHORTED TO GROUND FBI  
 DRIVERS BUCKLE SEAT FOR  
 ACCESS, REPLACED DRIVER R  
 SIDE SEAT BELT BUCKLE,  
 RETESTS AND VERIFIED  
 REPAIR.

X	Other	CLUT STATED SEAT BELT BUCKLE STUCK	770
A	Wont Latch	DRIVERS SEATBELT WILL NOT LATCH	884
X	Other	SEATBELT DOES NOT WORK	888
	Unlatches While Driving	SHD CUSTOMER STATES DRIVERS SEATBELT RELEASES WHILE DRIVING DOWN THE ROAD	881
D			
X	Other	O R SEAT BELT COMING APART SOP HERE	407
X	Other	SEAT BELT LIGHT COMES ON WITH BELT LATCHED SOP IN CUSTOMER REPORTS WHIN AT A STOP IN GEAR AND DRIVERS SEAT BELT ATTACHED SEAT BELT WARNING LIGHT AND WARNING CHIME WILL SOUND AT TIMES	878
X	Other	SEAT BELT DEFECTIVE	809
X	Other	INSPECT SEAT BELT BUCKLE FOR PROPER INTENTION	819
		CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT WILL NOT LATCH CHECK AND ADVISE	820
A	Wont Latch		805
A	Wont Latch	DRIVERS SEATBELT IS INOP	803
X	Other	FRONT PASS SIDE SEAT BELT IS INOP SPO IS HERE	770
X	Other	CK SEAT BELT STAYS ON AND CHIME GOES OFF EVEN WITH SEAT BELT ON DRIVER REPORTS LEFT FRONT SEAT BELT INTER. COMES UNBUCKLED WHILE DRIVING	814
D	Unlatches While Driving	PASS SIDE SEAT BELT BUCKLE TECH 188	820
X	Other	FRONT SEAT BELTS WILL NOT SPAS SOMETIMES CHECK AND ADVISE	404
X	Other	SHD PER CUSTOMER THE DRIVERS SEAT BELT BUCKLE WONT T RECEIVE THE MALE END INSTALL SOP PARTS TECH 488	888
A	Wont Latch	LEFT SEAT BELT WILL NOT STAY LATCHED	813
B	Wont Stay Latched		386
A	Wont Latch	CUSTOMER STATES THAT RIGHT SEAT BELT WILL NOT LATCH	817
A	Wont Latch	DRIVERS SEAT BELT BUCKLE WILL NOT HOLD T PH SEATBELT WILL NOT LATCH AND STAY HOOKED ALL THE WAY IT POPS BACK OUT.	810
C	Unlatches While Driving		708
A	Wont Latch	CHECK LEFT FRONT SEAT BELT WONT LATCH TO BUCKLE	828
X	Other	SEAT BELT NOT INORDIMS	787
A	Wont Latch	PASS SEAT BELT WONT LOCK	848
		CLUT STATED THE RT FRONT SEAT BELT BUCKLE IS NOT LATCHING SOP PART IS HERE	714
A	Wont Latch	CUSTOMER STATES THAT DRIVER SEAT BELT BUCKLE WILL UNLATCH WHILE DRIVING.	714
D	Unlatches While Driving		
B	Wont Stay Latched	DR SEAT BELT WILL NOT STAY LATCHED	713
A	Wont Latch	CUSTOMER STATES THAT RT SEATBELT WILL NOT LOCK IN BUCKLE	770
D	Unlatches While Driving	CLUT STATED WHILE DRIVING DRIVERS SEAT BELT CAME UNLATCHED BY ITSELF	825
X	Other	SHD CLUT CONCERN DRIVER SIDE SEAT BELT NOT WORKING	884
A	Wont Latch	SHD RIGHT FRONT SEAT BELT WONT BUCKLE AT ALL INOP	817

11 SEAT BELT NOT LATCHING A OR SEAT BELT BUCKLE NOT LATCHING  
ORDERED NEW BUCKLES-INSTALLED PROBLEM FIXED

1 INSPECT SEATBELTS REMOVE AND REPLACE RIGHT REAR SEATBELT

SEATBELT POPS OUT REPL LH BUCKLE, NOT LATCHING

SEAT BELT BUCKLE REPLACED SEAT BELT

REPLACE BROKEN SEAT BELT

RNR SEAT BELT BUCKLE L & FRONT SEAT.

REPLACED PASG. FRONT SEATBELT BUCKLE

VERIFY CONSUMER SEATBELT BUCKLE WONT LATCH NEED TO REPLACE  
VERIFY OK

INSTALLED BOP FOR AIR BAG LIGHT

PASSENGER SIDE SEATBELT WILL NOT HOLD, REMOVED PASSENGER

FRONT SEAT TO ACCESS SEATBELT BUCKLE, REPLACED SEATBELT

BUCKLE, NO LABOR CHG, USE H TIME

34 INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL REPLACED SEAT  
BELT

8887 SEAT BELT LATCH BOP IN 172A & REPLACED SEAT BELT LATCH

REPLACE SEATBELTS WILL NOT LATCH

SEAT BELTS WONT LATCH REPLACE BUCKLES

8844 AS CHECKED OPERATION OF LEFT FRONT SEATBELT BUCKLE, WILL

NOT LATCH, REMOVED SEAT TO ACCESS, REPLACED SEATBELT BUCKLE,

ASSEMBLED, RECHECKED, PASSED.

8877 RNR DRIVERS SEAT & REPLACE SEAT BELT BUCKLE ASSEMBL

REPLACED LEFT AND RIGHT SEATBELTS.

CCPLS REPLACE SEATBELT BUCKLES

REPLACE ONE SEAT BELT BUCKLE OHL

8723 SEATBELT ASSEMBLY FRONT REPLACE

8895 REPLACED PASSENGER SEAT BELT RECEIVER AIR PER MANAGEMENT.

CC847 TECH 807

REPLACE LEFT SEATBELT BUCKLE

SEAT BELT REPLACED DRIVERS SEAT BELT ASSEMBLY

SEAT BELT BUCKLE BOP LIGHT ON BODY CHAIRS ELECTRICAL (BCE)

TEST REPLACED SEAT BELT BUCKL

6 TESTED SEAT BELTS AND INSTALLED BOTH LEFT AND RIGHT SIDE SEAT

BELT LATCHES R L/S

8797 DRIVERS BUCKLE NOT HOLDING FOUND DRIVERS BUCKLE NOT

HOLDING BELT, REMOVED AND REPLACED SEAT BUCKLE (FEMALE END)

CHECKS OK

REMOVED FRONT SEAT REPLACED SEATBELT LATCH ON PASG SIDE

CCJ41 BROKEN BAMBORN888 REPLACE L F SEAT BELT

12888 RIGHT FRT SEAT BELT RECEIVER DOES NOT HOLD INSPECT FOUND

CAN VISIBLE SEAT BELT AND WILL COME UNLATCHED, REPLACE SEAT

BELT RECEIVER OK AFTER REPAIR, CC 43

RR 8787 FRONT SEAT RR SEAT BELT BUCKLE

8877 LOOSE REPLACE LOOSE RR SEAT BELT BUCKLE \*\*\*\*\*QUALITY

CONTROL BY JAMES PENNOCK\*\*\*\*\*

1 INSPECT AND REPLACE R FRT SEAT BELT BUCKLE

CC888 CHECKED OUT REPLACED DRIVERS SEAT BELT BUCKLE

REPLACE SEATBELTS WILL NOT LATCH PROPERLY

REPLACE BOTH FRONT SEATBELT BUCKLES

8844 VERIFIED CONSUMER DRIVERS SEAT AND REPLACED SEAT

BELT BUCKLE.

88 0421D 8 & BOP AND REPL SEAT BELT

A	Went Latch	C-8 LEFT FRONT SEAT BELT BOP. CH ADVISE	407
X	Other	CUSTOMER STATES RIGHT REAR SEATBELT BOP	880
D	Unlatches While Driving	CUSTOMER STATES WHILE DRIVING THE LFT FRONT SEAT BELT WILL POP OUT OF SEAT BELT BUCKLE AT TIMES	808
D	Unlatches While Driving	CUST STATED DRIVERS SIDE FRONT SEAT BELT WILL COME UNLATCHED WHEN DRIVING	818
X	Other		787
A	Went Latch	DRIVER SIDE SEAT BELT WONT LATCH	808
A	Went Latch	RITE FRONT SEAT BELT WONT BUCKLE PLEASE OK ALL.....	808
A	Went Latch	CUSTOMER STATES FRONT PASG SEAT BELT WONT LATCH	821
X	Other	BOP AIR BAG LAMP ON	838
A	Went Latch	CUSTOMER STATES SEATBELT BUCKLE WILL NOT HOLD	737
R	Recall Performed	INSPECT PER 88871 RECALL INSTRUCTIONS	825
A	Went Latch	888 SEATBELT CUST STATES THE DRIVERS SEATBELT WILL NOT HOLD	802
A	Went Latch	LATCH	818
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	818
C	Unlatches/Releases	DRIVERS SEAT BELT KEEPS POPPING LOOSE	884
B	Wont Stay Latched	C-8 DRIVERS SEAT BELT WONT STAY BUCKLED, INSTALL BOP TO REPAIR.	888
X	Other	CHECK SEATBELTS BOP	848
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	818
X	Other	SEAT BELT ON PASSENGER	770
A	Went Latch	DRIVERS SEATBELT WILL NOT LATCH AT TIMES	823
X	Other	C-8 PASSENGER SEAT BELT COVER LOCKS BOP PART	713
C	Unlatches/Releases	C-8 THAT THE L F SEAT BELT KEEPS POPPING OUT BY ITSELF 840	813
B	Other	DRIVERS SIDE SEAT BELT DOESNT WORK PROPERLY	818
X	Other	CUST STATES THE SEATBELT LIGHT COMES ON INTERMITTANTLY, WHEN THE SEATBELTS ARE ON, CHECK AND ADVISE	888
B	Wont Stay Latched	825 SEATBELT WONT STAY LOCKED	425
D	Unlatches While Driving	DRIVER SEAT BELT COMES UNBUCKLED WHEN DRIVING	757
X	Other	OK PASG FRONT SEAT BELT HARD TO GET IT TO LOCK	848
A	Went Latch	QUALITY CHECK INITIALS SEAT BELT ON DRIVERS SIDE DOES NOT BUCKLE	218
C	Unlatches/Releases	888 CUSTOMER STATES THAT PASG FRONT SEAT BELT COMES UNDOING	713
X	Other	PASSENGER FRONT SEAT BELT HANGES WHEN TRY TO PULL OUT	808
X	Other	SEAT BELT BUCKLE NOT ENGAGING SOMETIMES ON P SIDE FRONT	817
R	Recall Performed	RECALL 81881 SEAT BELT BUCKLE REPLACEMENT FRONT FRONT THIM	841
A	Went Latch	CODE 14	818
X	Other	CUST STATES DRIVERS SEAT BELT WILL NOT LOCK	818
X	Other	LEFT STRIKE RT FRT AND LEFT FRT SEATBELT BOP IS IN	884
A	Went Latch	CUSTY STATES DRIVER SEAT BELT WILL NOT LATCH	817
R	Recall Performed	81881 RECALL SEAT BELT	838

31 INSTALL SEAT BELT LEFT SIDE 01281D 0 8 INSTALL SEAT BELT BINDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE  
 FOUND RIGHT SIDE FRONT SEAT BELT WOULD NOT STAY BUCKLED R R RETEST OK

SEAT BELT REPLACED SEAT BELT BUCKLE  
 VERIFIED CONCERN LOCKING PLATE JAMMED, REMOVE & REPLACE  
 DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY, BUCKETS W O SR  
 BUSH IN OP W 48 REMOVE DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE ASY IN OP  
 004 REPLACE 2 BULBS  
 10 RECALL 01281D 0 8 PERFORM RECALL, INSPECT SEAT BELT BUCKLES AND REPLACE LEFT BUCKLE  
 LEFT SEATBELT WILL NOT STAY BUCKLED REPLACE BUCKLE END TO RESOLVE CONCERN  
 REPLACE RIGHT SEAT BELT BUCKLE INTERMITTENTLY WOULD UNLATCH NO LATCH C/P FOR SEAT BELT BUCKLES USED TIME FOR EXCISE TIME  
 REPLACED FRONT FRONT SEAT BELT BUCKLE  
 REPLACED SEAT BELT BUCKLE  
 REMOVED SEAT AND REPLACED THE SEATBELT FOR THE PASSENGER FRONT SEAT  
 REPAIR DRIVER SEAT BELT TO LATCH

DIAG OUT AND REPLACE SEAT BELT BUCKLE INOP WILL NOT LATCH  
 RECALL 01281D SEATBELT PERFORMED 01281 SEATBELT RECALL  
 REPLACE RT HAND SEATBELT,  
 BINDING REPLACED LEFT SIDE SEAT BELT BUCKLE  
 35 01281D 0 8 INOP AND REPL L FRONT SEAT BELT

INOP SEATBELT ASSEMBLY FRONT REPLACE

VERIFY CONCERN REPLACED BINDING SEAT BELT BUCKLE RETEST OK  
 VERIFIED CONCERN, PERFORMED SAFETY BELT INSPECTION MISC TO REPLACE DRIVERS BELT BUCKLES TO CORRECT  
 01281 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE  
 CG 48 AS 7961208 REMOVED DRIVERS SIDE SEAT AND REMOVED BUCKLE AND INSTALLED NEW AND RETESTED OK  
 UNTWISTED SEATBELT AND REPLACED BUCKLE  
 CLUT STATES THE DRIVER SIDE SEAT BELT BUCKLE IS INOP  
 CALIBR SEAT BELT CORE REPLACE SEAT BELT BUCKLE

APPROX TIME 8.4 HRS  
 JOB STARTED 7:08 7 ON 01  
 23 01

PERFORM RECALL 01281D REPLACE PASSENGER SEAT BELT BUCKLE INOP SEATBELT ASSEMBLY FRONT REPLACE  
 01281 D PASS SIDE FAILED RPL PASS SIDE BELT BUCKLE INOP REPLACED BOTH FRONT SEAT BELT BUCKLES

RIGHT SEATBELT WONT BUCKLE REPLACED RIGHT SEATBELT BUCKLE

1 RPL BOTH FRONT SEAT BELT BUCKLES

OK OUT REPLACED PY PASS SIDE SEAT BELT LATCH END INOP SEATBELT ASSEMBLY FRONT REPLACE  
 RATTLE IN LEFT SEAT BELT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE

RIGHT SEATBELT WONT LATCH REPLACED RIGHT SEATBELT BUCKLE  
 3848 DRIVER SIDE SEAT BELT BUCKLE WOULD NOT LATCH REPLACED DRIVER SIDE SEAT BELT BUCKLE

Y	Recall Performed	ADD PERFORM CODE 1 SEAT BELT BUCKLE	930
X	Other	PASS SEAT BELT HARD TO BUCKLE	810
B	Wont Stay Latched	CUSTOMER STATED PASSENGER SEAT BELT DOES NOT HOLD	818
X	Other	CUSTOMER STATED PASSENGER FRONT SEAT BELT BUONLE IS RATTLEING	810
A	Wont Latch	CLUT STS DRVR SIDE SEAT BELT WONT LATCH	864
A	Wont Latch	389 CLUT STS LEFT FRONT SEATBELT WILL NOT LATCH SOP R0492734 M 1880 1 14 02	407
X	Other	CUSTOMER STATED BOTH FRN SEAT BELT BUCKLES WONT WORK	381
R	Recall Performed	ADD PERFORM CODE 1 SEAT BELT BUCKLE	630
D	Unlatches While Driving	DRIVERS SEATBELT COMES UNLATCHED WHILE DRIVING	284
C	Unlatches/Release	RIGHT FRONT SEAT BELT WONT STAY LATCH	608
A	Wont Latch	PASSENGER SEAT FRONT BUCKLE WILL NOT LATCH 848	291
A	Wont Latch	340 CUSTOMER STATED THAT DRIVER SEAT BELT WONT LATCH	672
X	Other	CUSTOMER STATED THAT FRONT PASSENGER SEAT BELT INOPERABLE	210
X	Other		
A	Wont Latch	DRIVER SIDE SEAT BELT WILL NOT LATCH	677
R	Recall Performed	PERFORM 01281 RECALL SEATBELT	678
A	Wont Latch	CUSTOMER STATED THAT RIGHT SEAT BELT WILL NOT LATCH	677
A	Wont Latch	SEAT BELT WILL NOT LATCH	214
R	Recall Performed	01281 SEAT BELT CAMPAIN	636
A	Wont Latch	CLUT STATES THE DRIVERS SIDE FRONT SEAT BELT WONT GO IN THE ACCEPTICAL	386
A	Wont Latch	DRIVER SIDE SEAT BELT WILL NOT LATCH 686	672
B	Wont Stay Latched	CLUT STATED D B SEAT BELT WILL NOT STAY LATCHED SUSPECT	672
R	Recall Performed	PERFORM RECALL 01281	362
A	Wont Latch	DRIVERS SEAT BELT WONT BUCKLE PART IS HERE	734
X	Other	CLUT STATES DRIVERS SIDE SEATBELT TWISTED SOP IS IN	810
X	Other	CLUT STATES THE DRIVER SIDE SEAT BELT BUCKLE IS INOP	583
R	Recall Performed	PERFORM RECALL 01281 SEAT BELT BUCKLES RECALL	862
A	Wont Latch	CLUT STATES DRIVERS SEATBELT BUCKLE WONT LATCH AT TIMES	337
R	Recall Performed	PERFORM RECALL 01281	882
X	Other	BOTH FRONT SEAT BELT BUCKLES INOP	727
A	Wont Latch	RIGHT SEAT BELT BUCKLE WONT LATCH	780
D	Unlatches While Driving	OK FRONT SEAT BELT BUCKLES RELEASE WHILE DRIVING	291
C	Unlatches/Release	826 RT FT PASS SEAT BELT INTERMITTENTLY WILL RELEASE, A SOP REPLACEMENT IS IN	727
C	Unlatches/Release	O R L P SEATBELT BUCKLE RELEASES SEATBELT	407
X	Other	RATTLE IN LEFT SEAT BELT SOP IN STX	770
A	Wont Latch	RIGHT SEAT BELT BUCKLE WONT LATCH	760
B	Wont Stay Latched	CONCERN CODE 888 SEAT BELT BUCKLE, DRIVERS SIDE SEAT BELT BUCKLE WILL NOT STAY LATCHED	282



INSPECTED AND REPLACED TWO SEATBELT BUCKLES

INOP SEATBELT ASSEMBLY FRONT REPLACE  
01021 D DRIVER SIDE FAILING RPL DRIVER SIDE BELT BUCKLE

WV 001D PERFORMED SEAT BELT RECALL RIGHT FRONT SEAT.  
01021 D DRIVER SIDE FAILED RPL DRIVER SIDE BUCKLE  
01021 R BOTH BELT BUCKLES FAILED RPL BOTH BELT BUCKLES  
REMOVED AND REPLACED DRIVERS SIDE REMOVED AND REPLACED  
DRIVERS SIDE SEAT BELT BUCKLE  
LOCK BUCKLE FOR SEAT BELT LOCK RETEST OK  
1 REPLACED R/R SEAT BELT LATCH

TEST AND FOUND PASS SEAT BELT BUCKLE INOP, DISASSEMBLE, WORK Y  
LATCH PROPERLY, REASSEMBLE AND REPLACE PASS SEAT BELT BUCKLE OK  
RETEST OK

SO RECALL 01021 INSPECTED BOTH FRONT SEAT BELT BUCKLES BOTH  
FAILED REASSEMBLED AND INSTALLED BOTH FRONT SEAT BELT BUCKLES.  
POWER BUCKETS, NO AIR  
1998S INSTALLED NEW SEATBELT BUCKLE ASSEMBLY IN ADD N OLD  
BUCKLE AND INSTALLED NEW ONE

SEAT BELT BUCKLE REPLACED DRIVER SIDE SEAT BELT BUCKLE  
RPN 9108L, ODD 828 CC 42 INSPECTED OPERATION OF DRIVER BUCKLE.  
REPLACED DRIVER BUCKLE SEAT BUCKLE WITHOUT PRETENSIONER AND  
NON GR

FAULTY SEAT BELT BUCKLE REPLACED SEAT BELT BUCKLE, RETESTED  
OK  
RPL ON SEAT BELT BUCKLE COMING APART  
SEAT BELT BUCKLE LATCH BINDING REPLACED L/F SEAT BELT BUCKLE  
LATCH LOCK OPER OK, CC, DO

REPLACED SEAT BELT ASBY  
BUCKLE INOP REPLACE SEAT BELT BUCKLE  
SEATBELT BUCKLE MALFUNCTIONS SEATBELT ASSEMBLY FRONT  
REPLACE  
REPLACED DRIVER SEAT BELT BUCKLE  
197 HOOKED UP NOS AND SOP CODE 31988 FROM RCM MODULE  
PERFORMED PREPOINT TESTS AND FOUND PASS SEATBELT  
PRETENSIONER BAD REMOVED B PILLAR MOLDING AND REPLACED  
PRETENSIONER ASSEMBLY RETESTED AND GOOD E DONE

INOP REPLACED SEAT BELT BUCKLE  
REPLACED DRIVERSIDE SEAT BELT BUCKLE  
2008 SOMEONE CHANGED L/F SEAT BELT BUCKLE 7128 INSTALLED NEW  
BUCKLE SEAT BELT IS WORKING PROPERLY AT THIS TIME NOTE HAD TO  
REMOVE CHAIR SEAT BEHIND DRIVER SEAT TO GET UNDER SEAT DID NOT  
REINSTALL CH  
1998S RIGHT FRONT SEAT BELT BUCKLE DIFFERENT THAN LEFT ONE  
REPLACED RIGHT FRONT SEAT BELT BUCKLE  
REPLACED BELT ASBY  
408 DRIVER SIDE FRONT SEAT BELT BUCKLE NOT LATCHING REPLACE  
DRIVER FRONT SEAT BELT BUCKLE AND TEST OK  
REPLACE SEAT BELT ASBY

DRIVER SEAT BELT WILL NOT LATCH PROPERLY REPLACE DRIVER SEAT  
BELT BUCKLE

D	Unlatches While Driving	BOTH FRONT SEAT BELTS COME UNDONE WHILE DRIVING. INSTALL SOP IN	841
D	Unlatches While Driving	CHECK THE FRONT SEAT BELTS LATCHES WILL POP OPEN AND RELEASE	407
R	Recall Performed	WHILE DRIVING INTERMITTENTLY RECALL 01021	802
A	Won't Latch	INSTALL SPECIAL ORDERED PART, RIGHT FRONT SEAT BELT BUCKLE PART	502
R	Recall Performed	WAS SPECIAL ORDERED, NOT LATCHING	802
R	Recall Performed	PERFORM RECALL 01021	802
R	Recall Performed	PERFORM RECALL 01021	802
A	Won't Latch	DRIVERS SEAT BELT WONT BUCKLE	719
X	Other	QUEST 873 D S SEAT BELT WONT LOCK	890
X	Other	CUSTOMER STATED INSTALL SOP SEATBELT SEE HIST	305
C	Unlatches/Releases	C S PASS PRT SEAT BELT OVERLAPES ON ITS OWN AT TIMES	801
A	Won't Latch	CHECK DRIVER SIDE SEAT BELT WILL NOT LATCH PROPERLY RECALL 01021 CAPTAIN SEAT CROWN VEG SEATBELT 1180/F180/F180 F180, GRAND MARQ, MARJUNG, TOWN CAR, S WINDSTAR VEH- SEAT BELT BUCKLE INTERACTION	802
X	Other		802
D	Unlatches While Driving	DRIVERS SEAT BELT COME UN HOOKED WHILE DRIVING	308
A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH	308
A	Won't Latch	THE DRIVERS SIDE FRONT SEAT BELT WILL NOT LATCH INTO THE BUCKLE	819
X	Other	DRIVERS SEATBELT RECEPTACLE IS CRACKING	722
X	Other	QUEST STATES LEFT FRONT SEAT BELT HAS COME LOOSE	808
A	Won't Latch	DRIVERS SIDE SEAT BELT WONT LATCH REPLACE DEFECTIVE DRIVERS SEAT BELT BUCKLE, CUSTOMER CLAIMS BELT TAB KEEPS RELEASING.	918
C	Unlatches/Releases	REPORTS DRIVERS SEAT BELT INOP ADVISE THE PASSENGER RIGHT FT SEAT BELT WILL COME UNLASH FOR AT TIMES	808
C	Unlatches/Releases	SEATBELT RELEASING BY ITSELF	704
C	Unlatches/Releases		604
X	Other	UPON INSPECTION FOUND AIR BAG LIGHT IS ON	732
X	Other		817
D	Unlatches While Driving	C S THE DRIVERS SIDE FRONT SEAT BELT COMES UNBUCKLED AS YOU DRIVE AT TIMES	318
X	Other	DRIVERSIDE SEAT BELT BUCKLE INOP	716
C	Unlatches/Releases	CUSTOMER STATES L/F SEAT BELT KEEPS POPPING OUT OF BUCKLE	301
X	Other	CUSTOMER STATES SET R/F SEAT BELT TO MATCH LEFT SIDE, SOP	301
C	Unlatches/Releases	CHECK DRIVERS SEATBELT DOWN UNHOOKED BY ITSELF SOP	603
B	Won't Stay Latched	DRIVERS SIDE FRONT SEAT BELT WILL NOT STAY LATCH IN BUCKLE	181
B	Won't Stay Latched	DRIVERS SEAT BELT WONT STAY LATCHED	878
X	Other		308
C	Unlatches/Releases	D S SEAT BELT RELEASES FOR NO REASON.	301

8078 0172A.4 0188P.4000 \*\*\* REPLACE RIGHT FRONT SAFETY BELTS

COMING UNLATCHED WHILE DRIVING. REPLACED DRIVERS SIDE BOLT LATCH

CHECKED THE DRIVERS FRONT SEATBELT BUCKLE WOULD NOT STAY LATCHED. REPLACED THE BUCKLE. TESTED NEW BUCKLE WORKS FINE. SEAT WAS A CAPTIVE CHAIR. WENT OUT OF ALIGNMENT WARR REALIGN SLEEVE FOR 2ND ROW, MIDDLE SEAT BELT. 30118 41 STOWING SEAT BELT BUCKLE NY FOR R/R DRIVERS SEAT BELT BUCKLE

W/O P REPAIR HARNESS FRICED BETWEEN HEATER BOX AND INSTRUMENT PANEL. REMOVE AND INSTALL RADIO ACCESS INSTRUMENT PANEL. PULL WIRE OUT REMOVE GLOVE BOX AND OSM

TIGHTENED ALL BELT BOLTS 1  
INSTALLED SOP SEAT BELT BUCKLE. . . . .  
VERIFIED CONCERN. DEFECTIVE PART REPLACE SEAT BELT BUCKLE  
WIRES PULLED OUT DASHBOARD CONDITION. REPLACED LEFT FRONT SEAT BELT BUCKLE  
REPLACED SEAT BELT BUCKLE  
REPLACED RIGHT SEATBELT BUCKLE  
BROKEN LATCH REPLACE L.F SEAT BELT LATCH

MT TIME TO REPLACE LEFT FRONT SEAT BELT BUCKLE  
1 REPLACED LEFT FRONT SEAT BELT BUCKLE

SEAT BELT LATCH BROKEN. REPLACE RIGHT FRONT SEAT BELT BUCKLE  
REPLACED BELT & BUCKLE  
CHECK OUT FOUND RECEIPTICLE BAD REPLACE SEAT BELT RECEIPTICLE (NOT LATCHING)

WOULD NOT RETRACT SEATBELT ASSEMBLY FRONT REPLACE  
W/P R/R SEAT BELT OK NOW  
REPLACE BROKEN BUCKLES  
01306 840 42 SEAT BELT DOGS NOT HOLD REPLACE DRIVERS SEATBELT LATCH ASSEMBLY

11 3011803 DIAGNOSED AND REPLACED R FRONT SEAT BELT BUCKLE ASSEMBLY; EXTRA

SEAT BELT DEFECTIVE. RECALLED SEAT BELT  
SEAT BELT LATCH. REPLACE LATCH  
REMOVED SEAT BELT LATCH BUCKLE FROM BORROWED EXCLUSION AND TEMPORARILY INSTALLED TO THIS R.O. DEFECTIVE LATCH BUCKLE IS ON MY TOOLBOX WHILE WAITING FOR ORDERED BUCKLE. REMOVED BORROWED SAFETY BUCKLE.

SEAT BELT BUCKLE INOP. REPLACED WITH NEW SEAT BELT BUCKLE  
FOUND BOTH BUCKLES BAD. REPLACED SEAT BELT BUCKLES IN FRONT PER RECALL

RECALL  
30148 DRIVERS BELT BUCKLE INOP PERFORMED TEST ON BUCKLE, BUCKLE NOT WORKING. DISCONNECTED WIRES, PART BUOKE CODE 02. PARTS SERVICE, BUCKLES NOW WORKING  
SEATBELT WILL NOT LATCH PROPERLY REPLACE SEATBELT  
REMOVED ON SEAT ASSEMBLY AND REPL. DR SEAT BELT P/B EVERYL MT TIME FOR REPAIR

X	Other	PO AND BY FOR PASS SIDE SEAT BELT TIGHTENS WHEN DRIVING	617
X	Other	CUSTOMER REQUEST SEAT BELT LATCH BE REPLACED UNHOOKS ON DRIVERS SEAT INT TRIM COLOR LN	997
C	Unlatches/Release	CUSTOMER STATES THE DRIVERS SIDE FRONT SEAT BELT KEEPS COMING UNLATCHED	385
X	Other	2ND LATCH FOR MIDDLE SEAT BELT 2ND ROW INOP	814
C	Unlatches/Release	DRIVERS SEATBELT BUCKLE COMES UNLATCHED.	892
X	Other	SEAT BELT ALARM STAYS ON	810
X	Other	CUSTOMER STATES D/S SEATBELT MAKES NOISE AT HIGH WAY SPEEDS	383
X	Other	INSTALL SOP SEAT BELT BUCKLES	818
X	Other	C B RT FT SEAT BELT INOP	718
X	Other	CURT STAYS ON SEAT BELT CAME UNBUCKLED FROM FLOOR CHECK ALL SEAT BELTS	396
X	Other	DR SEATBELT CHING KEEPS CHINGING, EVEN WHEN BELTS ARE ON	314
C	Unlatches/Release	CHECK DRIVER SIDE SEATBELT COMING UNBUCKLED	381
C	Unlatches/Release	DRIVERS SEAT BELT COMES UNLATCHED FACTORY CHAMPAIN 01821 SEAT BELT POWER BUCKLE LEFT SIDE ONLY	400
X	Other	TRIM CODE IN	719
X	Other		767
A	Won't Latch	CUSTOMER STATES THAT SEAT BELTS ARE NOT WORKING CORRECTLY	696
X	Other	FRONT SEAT BELT HARD TO LATCH SEAT BELT BUCKLE DISCOLORED	885
X	Other	PASSENGER SEAT BELT NOT WORKING PROPERLY FRONT SEAT BELT WOULD NOT RETRACT SOP IN USE BPO 0123018	301
X	Other		867
X	Other	BUCKLES BROKEN	817
B	Won't Stay Latched	CUSTOMER STATES DRIVERS SEAT BELT WILL NOT STAY LATCHED	219
C	Unlatches/Release	CURT STATES FRONT PRT SEAT BELT POPS OUT OF RECEIPTACLE TECH 118 RECALL USE BPO 0189817	816
X	Other	CUSTOMER STATES B SIDE SEATBELT STICKS WHILE REMOVING AND INSTALLING BELT CLIP	767
A	Won't Latch	THE DRIVERS SEAT SEATBELT IS INOP	812
A	Won't Latch	REPAIR DRIVER SIDE SEATBELT WONT LATCH DRIVERS SIDE SEAT BELT BUCKLE KEEPS POPPING LOOSE INSTA SOP SEAT BELT BUCKLE	880
C	Unlatches/Release		689
Z	Other	FRONT SEAT BELT BUCKLES DO NOT LATCH PROPERLY	321
X	Other	RECALL 01821	
A	Won't Latch	C B THAT THE L FRONT SEAT BELT WILL NOT BUCKLE	770
X	Other	DRIVERS SEAT BELT DOGS NOT LATCH PROPERLY	818
A	Won't Latch	CUSTOMER STATES, DR. SIDE SEAT BELT RECEIVER NOT HOLDING	388

SEAT BELT DEFECTIVE REPLACE SEAT BELT BUCKLE ASBY INSTALL NEW SEAT BELT	D	Unlatches/Release	CUSTOMER STATES THE DRIVER SEAT BELT WILL NOT STAY SECURED AND THE FALLS OUT.	908
VERIFIED CONCERN AND INSPECTED THE SEAT BELT ASSEMBLY FOUND THE DRIVERS SEAT BUCKLE TO BE INOP NOT ALLOWING THE BELT TO LATCH REPLACE THE DRIVERS SEAT BELT BUCKLE ASSEMBLY ON CAPTAINS CHAIR AND RETE	O	Unlatches/Release	SEAT BELT UNLATCHES RANDOMLY	287
DIAG INSP IN TIME TO REPLACE SEAT BELT BUCKLE	B	Won't Stay Latched	DRIVERS SEATBELT WILL NOT STAY BUCKLED	719
DIAG INSP IN TIME TO REPLACE SEAT BELT BUCKLE	X	Other		989
REPLACE SEAT BELT	X	Other	TEST AND REPLACE SEAT BELT	838
REMOVED DRIVERS SEAT, REPLACED LEFT FRONT BUCKLE	X	Other	LEFT SEAT BELT DOESN'T BUCKLE	767
	A	Won't Latch		320
REPLACED FAULTY RT SIDE SEATBELT (RECLAY CAB) RE REPLACED SEAT BELT	X	Other	SEATBELT DOESN'T WORK PROPERLY	618
REPLACE DRIVERS SEAT BELT (BUCKLE MY LINE) NO LABOR OPP	X	Other	SEAT BELT DOESN'T WORK PROPERLY	947
WILL NOT LATCH REPLACE FRONT PASSENGER SEAT BELT	A	Won't Latch	CUSTOMER STATES DRIVER SEAT BELT BUCKLE WILL NOT LATCH	800
W/INFL SEAT & TRACK ASBY REPLACE PASSENGER	A	Won't Latch	CUSTOMER STATES PASSENGER SIDE FRONT SEAT BELT INOP	702
	X	Other		688
REPLACED SEAT BELT	B	Won't Stay Latched	CUSTOMER STATES THAT THE DRIVERS SEAT BELT WILL NOT STAY LATCHED	757
1 REPLACE SEAT BELT BUCKLE	A	Won't Latch	CHECK DRIVERS SEAT BELT WILL NOT LATCH	218
OD 48 CP 1988 REPLACE DRIVER FRONT SEAT BELT BUCKLE,SPECIAL ORDERED RIGHT REAR SEAT BELT BUCKLE,TESTED,POED VEHICLE		Unlatches While Driving	SEAT BELT AND RIGHT REAR PASSENGER BELT DO NOT LATCH PROPERLY	581
REPLACE SEAT BELTS DO NOT LATCH	A	Won't Latch	SEAT BELT DOES NOT LATCH PROPERLY	800
300 48 W/IN DRIVER SIDE SEAT BELT BUCKLE, WOULD NOT LATCH		Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH	641
REPLACED SEAT BELT BUCKLE	A	Won't Latch	RIGHT FRONT SEAT BELT BUCKLE WILL NOT ALWAYS LATCH AND HOLD	408
INSPECT AND ORDERED NEW BUCKLE REPLACED SEAT BELT BUCKLE WORKS GOOD	X	Other	DRIVER SEAT BELT LATCH WILL NOT LATCH PROPERLY	770
BUCKLE FAILED SEATBELT ASSEMBLY DRIVERS FRONT REPLACE	R	Recall Performed	RECALL SEAT BELT PART HAS BEEN ORDERED AND IS HERE.	542
REPLACED SEATBELT	X	Other	SEAT BELT BROKEN	408
CK SEAT BELT FOR BEING BROKE REM AND REPLACED RIGHT SIDE LOWER SEAT BELT	A	Won't Latch	SEE CK DR SIDE SEAT BELT	281
CHECK BELT OPERATION WILL NOT LATCH REMOVE DRIVERS SEAT INSTALL NEW BUCKLE AND REINSTALL SEAT RETEST CK	R	Recall Performed	RECALL 0182H	770
NEG TO REPLACE SEAT BELT	D	Recall Performed		770
DIAG AND IN SEAT BELT	X	Other	CUSTOMER STATES PASSENGER SIDE SEAT BELT IS HARD TO LATCH	713
FOUND INTERNAL FAILURE OF RT SEAT BELT BUCKLE 40 23 48 FT SEAT ASBY REMOVED AND REPLACED RT FT SEAT BELT BUCKLE	A	Won't Latch	CHECK SEAT BELT WON'T LATCH	716
REMOVED AND REPLACED PASSENGER SIDE SEAT BELT BUCKLE NOT LATCHING SEATBELT ASSEMBLY FRONT REPLACE	A	Won't Latch	CK SEAT BELT NOT LATCHING PROPERLY	840
PASSENGER SEAT BELT BUCKLE UNBUCKLES INSPECT & REPLACE PASSENGER SEATBELT BUCKLE	A	Won't Latch	CHECK PASSENGER SEAT BELT BUCKLE WILL NOT HOLD	702
RT SEAT BELT BUCKLE DEFECTIVE SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	X	Other	RE SEATBELT RECEPTACLE INOP OR SEAT BELT WILL NOT STAY LATCHED	264
NEG TO REPL DRIVERS RT SEAT BELT ASBY	B	Won't Stay Latched	OR SEAT BELT WILL NOT STAY LATCHED	818
1 REPLACE RIGHT FRONT SEAT BELT BUCKLE DONE	C	Unlatches/Release	RT SEAT BELT COMES UNLATCHED SPEED ORDERED	818
REPLACE RT FRONT SEAT BELT	D	Won't Stay Latched	RT FRONT SEAT BELT WILL NOT STAY BUCKLED.	440
6498 SEAT BELT BUCKLE-NEP-SPRINGS 1.8 TEST AND DIAG SEAT BELT BUCKLE ACCESS LEFT FRONT SEAT AND REPLACE SEAT BELT BUCKLE, INOP, RETEST, CODE 48 CALIBRAL PART 6182H	A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH	634
BUCKLE NOT HOLDING SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	A	Won't Latch	DRIVERS SEAT BELT IS INOP	714
REPLACED LEFT AND RIGHT SEAT BELT BUCKLE PER 01821. CHECK AND REPLACED WITH NEW ONE RETEST	R	Recall Performed	PERFORM RECALL 0182H LPT & JET IN BUCKET CENTER W F L F RT HP.	828
REPLACED SEATBELTS	A	Won't Latch	CHECK RIGHT SIDE SEAT BELT DOESN'T LATCH	791
REPLACED DRIVERS SEATBELT	X	Other	SEATBELTS WONT RETRACK	791
	A	Won't Latch	CUSTOMER STATES DRIVER SIDE SEAT BELT WON'T CATCH	712
LATCH DOES NOT HOLD SEATBELT ASSEMBLY FRONT REPLACE	A	Won't Latch	DRIVERS SIDE FRONT SEATBELT WILL NOT LATCH (S D PART HERE)	688

SEAT BELT BUCKLE MALFUNCTIONING REAR OR SEAT REPLACED SEAT BELT BUCKLE NO 2529	X	Other	SEAT BELT INOP PARTS IN	880
REPLACE R H SEAT BELT BUCKLE BRINDING INTERNALLY AND NOT LATCHING	A	Worn Latch	CHECK FOR PASS SIDE SEATBELT BUCKLE WILL NOT FASTEN SEAT BELT	918
TORN SEAT BELT ASSEMBLY REAR RIGHT OR LEFT REPLACE	X	Other	R H SEAT BELT SOP HUNG	270
LEFT FRONT SEATBELT BUCKLE NOT FUNCTIONING PROPERLY, R AND R BUCKLE	X	Other	O B L F SEAT BELT BUCKLE DOES NOT FASTEN PROPERLY,INSTALL SOP	881
CHECKED SEAT BELT FUNCTION NECESSARY TO REPLACE SPRINGER SEATBELT BUCKLE	X	Other	DR DRIVERSIDE SEAT BELT INOP	400
REPLACED RIGHT SEAT BELT BUCKLE PER RECALL	R	Recall Performed	PERFORM RECALL O B L LEFT BUCKLE PASSED, FRONT BUCKLE FAILED	300
REPLACED WROD SEATBELT BUCKLE	K	Other		808
LEFT SEAT BELT BUCKLE SEIZED,REPLACE LEFT SEAT BELT BUCKLE	X	Other	LEFT SEAT BELT IS HARD TO LOCK	808
VERIFIED CONCERN FOUND AND TRACED BUCKLE ASBY FAULTY REMOVED AND REPLACED BUCKLE ASBY RETESTED ALL OK	A	Worn Latch	O B PASSENGER SIDE FRONT SEAT DOES NOT LOCK IN WHEN TRYING TO BUCKLE UP	631
42 REPLACE RP SEATBELT BUCKLE RATTLING INTERNALLY RETEST	X	Other	CUSTOMER STATES FRONT PASS SEAT BELT BUCKLE RATTLES WHILE DRIVING	713
3000 WARRANTY RIGHT FRONT SEATBELT WOULD NOT LATCH AT TIMES				
REMOVED PASSENGER SIDE SEAT ASSEMBLY TO ENABLE REPLACEMENT OF RECEIVER BUCKLE ASSEMBLY FOR RECEIVER BUCKLE ASSEMBLY. REINSTALLED SEAT ON	A	Worn Latch	RT FRNT SEAT BELT AT TIMES WILL NOT LATCH	500
RH FRONT SEAT BELT BUCKLE WONT LATCH JUR SEAT AND REPLACE BUCKLE	A	Worn Latch	RH SEAT BELT BUCKLE WONT LATCH	258
DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE	A	Worn Latch	CUST STATES THE DR SEAT BELT DOES NOT BUCKLE IN SOP IS IN USE DPO 01880041	841
INOP SEATBELT ASSEMBLY FRONT REPLACE	D	Chewing	CHK PASS SIDE FRONT SEAT BELT BUCKLE COMES LOOSE WHEN DRIVING	
REPL SEAT BELT	X	Other	CUSTOMER STATES PASSENGER FRONT SEATBELT IN OP, SOP	581
BUCKLE FAULTY REPLACED LF BUCKLE AND RECHECKED OKAY	A	Worn Latch	CUSTOMER STATES LF SEAT BELT BUCKLE WILL NOT LATCH	608
DATA REPLACER BUCKLE DE CENTURE AWANT LH ERROR	X	Other	CENTURE AWANT BUCKLE ATTACHE PAS	418
REPLACED DRIVER SEAT BELT END	A	Worn Latch	SEAT BELT ON DRIVERS SEAT WILL NOT LATCH	418
ORDERED AND INSTALLED NEW PASS FRONT SEAT BELT BUCKLE	X	Other	CHECK PASS SEAT BELT DOES NOT LATCH PROPERLY	388
ACCESS AND REPLACE SEATBELT ASBY SEAT BELT ASSEMBLY REAR R/SH T OR LEFT REPLACE	A	Worn Latch	CUSTOMER REPORTS PASS SEAT BELT WILL NOT LATCH	414
VERIFIED FOUND DRB SIDE SEATBELT LATCH NOT LATCHING AND DEFECT IN BUCKLE ORDERED AND REPLACED OK NOW	A	Worn Latch	DRB SIDE SEATBELT LATCH IS NOT WORKING, WILL NOT LATCH BELT	788
INSPECT AND REPLACED STICKING SEAT BELT BRINDING SEATBELT ASSEMBLY FRONT REPLACE	X	Other		802
	X	Other	CUST STATES SEAT BELT DOES NOT BUCKLE CORRECTLY	717
	A	Worn Latch	CUST STATES DRIVERS SEATBELT BUCKLE WILL NOT LATCH	788
REPL SEATBELT ASBY SEATBELT ASSEMBLY FRONT REPLACE	A	Worn Latch	SEAT BELTS WILL NOT HOLD	494
REPLACED SEAT BELT BUCKLE	X	Other	SEAT BELT BUCKLE INSPECTION AND REPLACEMENT IF NEEDED	538
REPLACED DRIVERS BUCKLE IN	A	Worn Latch	INSTALL SOP DRIVERS SEAT BUCKLE, OLD ONE WONT LATCH.	817
REAR AND REPL. RIGHT FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY AT THIS TIME	B	Worn Stay Latched	PASS FR SEAT BELT WILL NOT STAY LATCHED	908
INSPECT AND REPLACED WITH NEW	A	Worn Latch	DRIVER SIDE SEAT BELT BRINDING WILL NOT LOCK	701
REPLACED RT FRONT SEAT BELT BUCKLE 4827	X	Other	SEAT BELT BUCKLE DOES NOT WORK PROPERLY	408
REPLACED SEAT BELT BUCKLE	X	Other	REPLACE SEATBELT TO CORRECT LATCH COMES APART	818
WARRANTY A RH CASEL THEN RH SEAT BELT (SAGE 1 FOUND THE PASSENGER FRONT SEAT BELT MISTRATOR IS BRASHEN ALSO TEST DRIVERS SIDE BUCKLE OPERATION BUCKLE WILL NOT LATCH BELT INTERNAL DAMAGE TO BUCKLE RPH SEAT AND REPLACE SEATBELT BUCKLE ASBY RETEST OK	B	Worn Stay Latched	CHECK AND ADVISE ON R B FRONT PEBBLE SEAT BELT WONT STAY LATCHED, SUB TROY PRST	801
RT REPLACED SEAT BELT BUCKLE	A	Worn Latch	CK FOR DRIVERS SEAT BELT WILL NOT BRIDGE	915
NEED TO REPLACE FRONT SEAT BELT BUCKLES NOT WORKING ALL THE TIME	A	Worn Latch	DRIVERS SEAT BELT WILL NOT LATCH	641
FRM LF SEAT BELT BUCKLE FROM STOCK 11889	A	Worn Latch	CHECK SEAT BELT BUCKLE, IS NOT CATCHING	391
REPLACE LEFT SEAT BUCKLE LATCH	X	Other	R H LF SEAT BELT BUCKLE FOR STOCK #11889	608
	A	Worn Latch	SEAT BELT BUCKLE DOESNT LATCH	318
	X	Other		428

TEST NEED TO REPLACE SEAT BELT REPLACED AS PER FORD	X	Other	SEAT BELT ON RT SIDE DOESNT WORK	701
	X	Other	DRIVERS SEAT FAILED BELT INSP	916
SEAT BELT BUCKLE FAILED SEATBELT ASSEMBLY FRONT REPLACE STICKS BENDS OR GRABS REPLACED SEAT BELT 40 28 46 DRIVERS SIDE BELT FAILED	X	Other	OK PASSENGER SEAT BELT INSP	770
VERIFIED, INSTALL MISSING BELT AND BUCKLE ASBY	X	Other	SAME WARRANTY 8 28 C 2 8 28 28 BELT DOES NOT LATCH CORRECTLY	880
	X	Other	CUST STATES RF SEATBELT BUCKLE IS MISSING OK AND ADVISE	704
INSPECT AND VERIFY LEFT FRONT SEAT BELT WONT LATCH, BUCKLE BROKEN, REPLACE LEFT FRONT SEAT BELT AND RECHECK OPERATION	A	Won't Latch	CUSTOMER STATES THE DRIVERS SEAT BELT WONT LATCH	880
SEAT BELT RECALL FOR LEFT BUCKLE	R	Recall Performed	PERFORM RECALL IN SET LEFT BUCKLE FAILED, RIGHT BUCKLE PASSED	808
REPLACED DRIVERS SIDE SEAT BELT.	X	Other	DRIVERS SIDE SEAT BELT DOESNT WORK	408
REPAIRED SEATBELT	B	Won't Stay Latched/ Unlatches While Driving	OK DRIVERS SIDE SEAT BELT WILL NOT STAY LATCH OK ALL OTHERS	803
REPLACED DRIVER SEAT BELT BUCKLE END	D	Driving	CHECK DRIVER SEAT BELT BUCKLE POPP LOCKS WHEN DRIVING	808
NOF REPLACE R 8 SEAT BUCKLE	A	Won't Latch	R 8 SEAT BELT DOESNT BUCKLE	810
1 REPLACED BUCKLE.	C	Unlatches/Releases	SEAT BELT POPP OUT OF RIGHT FRONT SEAT BELT BUCKLE BOP HERE	308
FOUND PASSENGER SEAT BELT BUCKLE WOULD NOT LATCH PERFORMED RECALL IN 021 ON DATE 7 20 01 CHECK SEAT BELTS AND THEY PASSED REPLACED SEAT BELT BUCKLE	A	Won't Latch	DRIVERS SEAT BELT BUCKLE WILL NOT HOLD	812
DIAG INSP VERIFIED CONCERN AND REPLACED PASS SIDE SEAT BELT INCP SEATBELT WILL NOT LATCH PROPERLY REPLACED LEFT FRONT SEATBELT ASSEMBLY, CHECKS GOOD (P)	X	Other	CUST STATES INSTALL BOP SEAT BELT ASBY SEE ZOOK PART BUYING BY HIS DECK	830
SEAT BELT BUCKLE SHEDING REPLACED BUCKLE	X	Other	PASS FRNT SEAT BELT WILL NOT SHAP	310
MT; TIME TO REPAIR SEAT BELT BUCKLES. NOF INSPECTED DRIVERS SEAT BELT DOES NOT SECURE PROPERLY. REPLACED SEATBELT AND VERIFIED REPAIRS.	C	Unlatches/Releases	OK SEAT BELT BUCKLE WILL LATCH BUT WHEN BELT IS PULLED ON BUCKLE UNLATCHES	317
PASS FRNT SEAT BELT DOESNT LATCH. REPLACED SEAT BELT BUCKLE ASBY. PSA 8388H (DRIVERS) REQUIRED SEAT BELT BUCKLES WITH TOOL CONCERN VERIFIED ON DRIVE BY JENNY. PASS SEAT FOR ACCESS TO SEATBELT, RFR SEATBELT BUCKLE WORKING TO SPEED REPLACED SEAT SEAT BELT BUCKLES	X	Other	CHECK DRIVER SEAT BELT	831
REPLACE SEAT BELTS REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSEMBLY REPLACE BOTH FRNT BUCKLE ASSEMBLIES, THEY RELEASED ON WHILE DRIVING AT TRIP	A	Won't Latch	PASSENGER FRONT SEAT BELT DOES NOT LATCH	337
INSPECT SEAT BELT WILL NOT WORK PROPERLY DISARM AIRBAG SYSTEM REMOVED AND REPLACED DRIVERS SIDE FRONT SEATBELT OK GOOD REPLACED BOTH SEAT BELT BUCKLES ON PASS FRONT SEATBELT NOT RELEASING PROPERLY	B	Won't Stay Latched Other	C 8 THE DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	882
CHISEL OUT TRIM LEFT SEAT BELT BUCKLE ON SHAP TO OPERATE PROPERLY IMPROPERLY INSTALLED	X	Other	BOP WHOM TECH 8877 FOR DRIVERS SIDE SEAT BULT DOES NOT WANT TO STAY LOCKED	818
R 8 DRIVERS FRNT SEAT BUCKLE INSTALL DRIVERS SEAT BELT BUCKLE MISSING WHEN DEALER TRANSFER HAS TENSIONER	A	Won't Latch/ Unlatches While Driving	OK CUST STATES DRIVERS SEATBELT WONT LATCH	303
102 SEAT BELT BUCKLE, CODE 48 REPLACED DRIVERS SEAT BELT BUCKLE DUE TO ERNATI Q OPERATION HED TO LOCKING SEAT CLIMBER TO THUMB SEAT BELT WARPING THRU FRAME	D	Driving	REPLACE DEFECTIVE SEATBELT OR BUCKLES BOP HERE	780
REPLACE PASS SEAT BELT BUCKLE WONT NOT STAY LATCH	A	Won't Latch	DRIVERS SEAT BELT BUCKLE WILL NOT LATCH INSTALL BOP	381
AIRBAG LIGHT IS ON AIR BAG RESTRAINT SYSTEM DIAGNOSIS	X	Other	PASS FRONT SEAT BELT DOES NOT RELEASE BOP	818
	X	Other	DRIVER SIDE SEAT BELT TURNED AROUND CUST STATES VEHICLE DEALER TRANSFERRED IN, DRIVERS SEAT BELT BUCKLE MISSING	817
	X	Other	DRIVERS SEAT BELT WILL NOT LATCH AT TRIP 888 CUST STATES PASS SIDE SEAT BELT WONT LATCH OK AND ADVISE SEE LEONARD.	838
	A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH AT TRIP 888	838
	A	Won't Latch	CUST STATES PASS SIDE SEAT BELT WONT LATCH OK AND ADVISE SEE LEONARD.	903
	X	Other	AIR BAG LIGHT ON	348

AIRBAG LIGHT FLASHES REPLACE LT SEAT BELT.	AIR BAG RESTRAINT SYSTEM DIAGNOSIS	X	Other	AIR BAG LIGHT FLASHING	040
		A	Won't Latch	CUSTOMER STATES THAT LEFT SEAT BELT WILL NOT LATCH	077
OBSERVE SEAT BELT INOP WILL NOT LATCH REPLACE SEAT BELT BUCKLE BUCKLE INOP WONT LATCH REPLACE DRIVERS SIDE SEAT BELT BUCKLE ASSY.		A	Won't Latch	CUSTOMER STATES PASSENGER SIDE SEAT BELT INOP	080
INTERVAL	REPLACED BUCKLE ASSEMBLY	A	Won't Latch	DRIVERS SEATBELT WILL NOT LATCH	088
PERFORMED RECALL FOR SEATBELTS		A	Won't Latch	DRIVER SEAT BELT WILL NOT LATCH	093
		R	Recall Performed	PERFORM RECALL 04281	333
FULLY WIRE AND BUCKLE INSTALLED NEW AND REASSEMBLED CHECK OK SEATBELTS CHECKED UNDER INOP IN ERROR BUT FOUND THAT PASSENGER SEATBELT FAILED. REPLACED BELT		A	Won't Latch	CHECK AND ADVISE ON PASSENGER SEAT BELT NOT BUCKLING CHECK OUT FOUND INOP FOLLOWS SEAT AND SEAT BELT ANCHOR	098
		X	Other		403
CHECK FOR FEMALE END OF DR SEAT BELT NOT HOLDING SEATBELT, YES. REMOVEREAT AND SEATBELT LATCH, REPLACE LATCH WITH UPDATED VERSION, REINSTALL SEAT,CHECK OPERATION, GOOD NOW.		A	Won't Latch	REPAIR FOR FEMALE END OF DR SEATBELT WONT HOLD SEATBELT	440
78 DRIVER SIDE PRETENSIONER LOW RESISTANCE AIR BAG DIAG AND REPLACED PRETENSIONER		X	Other	AIR BAG LIGHT FLASHED W AC 4 TIMES TWICE THEN 5 TIMES ONCE THEN SAVED ON	382
REPLACED THE FAULTY SEAT BELT.		A	Won't Latch	THE SEAT BELT DOES NOT LATCH	330
CCC 800 TESTED SYSTEM RAN PIN POINT TEST CC 48 REPLACED DRIVER SEAT BELT		X	Other	AIR BAG LIGHT ON IT FLASHES	070
REPLACED FRONT SIDE SEAT BELT		X	Other	CHECK SEAT BELTS	079
PERFORMED DIAGNOSIS AND REPLACED PASSENGER SIDE PRETENSIONER DIAGNOSE/REPLACE BELT AND BUCKLE		X	Other	PASSENGER SIDE SEAT BELT FEMALE END EXPLODED ON START UP (200)	078
BELT INOP SEATBELT DOESNT HOLD		A	Won't Latch	PASSENGER FRONT BELT WILL NOT BUCKLE	200
		O	Unlatched/Released	SEAT BELT DOES UNDOONE	070
REMOVE SEAT FOR ACCESS TO REPLACE PRETENSION BELT		X	Other	REPORT IN BUCKLE INOP REMOVE SEAT FOR ACCESS TO REPLACE PRETENSION BELT ON	070
REPLACED LEFT SEAT BELT BUCKLE		A	Won't Latch	LEFT SEAT BELT BUCKLE WILL NOT LATCH	717
REPL SEAT BELT ASSY		X	Other		006
TEST THE AIR BAG SYSTEM FOUND AND REPLACED THE FAULTY DRIVERS SEAT BELT BUCKLE ASSEMBLY		X	Other	AIR BAG LITE IS FLASHING	780
REPLACED PASSENGER SEATBELT.		X	Other	CUSTOMER STATES PASSENGER SEATBELT INOP (DOP IN)	708
		X	Other		343
REPLACE BOTH FRONT SEAT BELT BUCKLES		A	Won't Latch	SEATBELT BUCKLES WONT LATCH	019
CP780282 026 42 REPLACED RF SEATBELT		A	Won't Latch	RF SEAT BELT WONT BUCKLE	218
DRG 48 FLASH, M80 BODY TEST, DRG 81895 RMR DR SEAT DEACTIVATED AND REPLACED THE DR SEAT PRETENSIONER, CLEAR THE CODES AND RE TESTED SYSTEM PAS		X	Other	CHECK FOR AIRBAG LIGHT STAYING ON/FLASHING (200)	308
REPLACE TRILDATE LOCK ASSEMBLY.		X	Other	CHECK TAILGATE KEEPS LOCKING BY IT'S SELF.	218
REPLACE PASSENGER REAR CRADLE BELT RECEPTOR INOP		X	Other	CUSTOMER SAYS PASSENGER SEAT BELT LOCKS AND WILL NOT RELEASE	308
8127 IN RF SEAT AND REPLACED INOP SEAT BELT BUCKLE		X	Other	PASSENGER SEAT BELT WONT LOCK EARLY	308
REPLACE SEAT BELT BUCKLE, LEFT FRONT		X	Other	CHECK SEAT BELT BUCKLE LOCK	010
REPLACE SEAT BELT BUCKLE ASSY		X	Other	CHECK AIR BAG LIGHT SYSTEM NOT WORKING PROPERLY	010
TEST AND REPLACE BOTH SEAT BELT ASSEMBLIES		X	Other	CUSTOMER STATES SEAT BELTS DONT WORK PROPERLY	062
REPLACED BOTH SEAT BELTS		X	Other	SEAT BELTS DO NOT RETRACT	080
REPLACED BAD SEAT BELT TENSIONER		X	Other	CUSTOMER STATES AIR BAG LITE ON	540
1 REPLACED SEATBELT		A	Won't Latch	CUSTOMER REPORTS THAT SEAT BELT WILL NOT LATCH.	309
TESTED AIRBAG LIGHT ON, TEST CODE B3065, PIN POINT TESTED AND REPLACED PIT FRONT SEAT BELT RETRACTOR AND PRETENSIONER ...		X	Other	CUSTOMER SAYS AIR BAG LIGHT ON	296
DIAG INOP VERIFIED CONCERN IN TIME TO REPLACE SEAT BELT BUCKLE 148 RAN IN FRONT SEAT ASSEMBLY, REPLACE SEAT BELT LATCH ASSEMBLY CUSTOMER COULD GET SEAT BELT TO POP APART REPLACE SEAT BELT		X	Other	CUSTOMER STATES FRONT SEAT BELT PASSENGER SIDE WONT LATCH PROPERLY, PLEASE DOP . IN TRIM CODE IS	410
REPLACE LATCH IN SEAT TO ACCESS OK.		X	Other	SEAT BELT WONT HOLD PROPERLY	301
		X	Other	RF SEAT BELT LOCKS UP	406
DEFECTIVE SEAT BELT BUCKLE IN TIME TO REPLACE BUCKLE		X	Other	CUSTOMER STATES SEAT BELT LIGHT WILL NOT TURN OFF CHECK & ADVISE	714
TEST BUCKLE REMOVE AND REPAIR INSTALL.		A	Won't Latch	DRIVERS SEAT BELT BUCKLE WONT LATCH	076

REPLACED THE LEFT SIDE SEATBELT BUCKLE  
 REPLACED THE SEATBELT BUCKLES THAT DID NOT HOLD.  
 CHECK AND REPLACE SEATBELT ARMY, PRETEST, OK  
 REPLACE PASSENGER SIDE SEAT BELT HAD TO REMOVE SEAT TO GAIN  
 ACCESS TO BUCKLE  
 FOUND SEAT BELT NOT LATCHING REMOVED AND REPLACED RIGHT  
 PASSENGER FRONT BUCKLE  
 REPLACE SEATBELT  
 REPLACED THE LEFT SEATBELT BUCKLE THAT DOES NOT HOLD

BUCKLE WONT ACCEPT BELT REPLACED SEAT BELT BUCKLE MO LOPE  
 INSPECTED AND REPLACED BOTH BUCKLES  
 CAUSAL PART INSIDE PERFORMED AIR BAG DIAG, OKED AND REPLACED  
 SEAT BELT AND BUCKLE ARRY. CONDITION CODE 82

1988 HARNES OPEN AND BELT NOT HOLDING CHECKED AND FOUND  
 SEAT BELT WOULD NOT HOLD IN THE BUCKLE THE BUCKLE ASSEMBLY  
 AND LIGHT STILL STAYED ON AND CHECKING CHECKED OEM MODULE AND IT  
 PASSED CHECKING IN  
 RUN AIRBAG SYSTEM DIAG. REPLACE SEATBELT PRETENSIONER.

BAD BUCKLE TENSIONER MY TO R IN DRIVERS SEAT BELT BUCKLE  
 REPLACE DRIVERS SIDE SEAT BELT

CHEK AND FIND IF SEAT BUCKLE OPEN REPLACE BUCKLE AND RECHECK OK

RECALL 01821 REPLACE L AND R BUCKLES AS PER RECALL  
 REPLACED LEFT FRONT SEAT BELT BUCKLE

NOT LATCHING REPLACED PASSENGER SIDE BUCKLE  
 REPLACED DRIVERS SEAT BELT

REPLACED LEFT FRONT SEAT BELT BUCKLE ASSEMBLY.  
 RECALL 01821

INSTALL SEAT BELT BUCKLES  
 CHECK AND REPLACE LEFT FRONT SEAT BELT BUCKLE  
 REPLACE DRIVER SEAT BELT BUCKLE WILL NOT LATCH  
 CHECK OUT AND REPLACE LEFT FRONT PASSENGER SIDE SEAT BELT WOULD  
 NOT LATCH

REPLACED SEAT BELT BUCKLE  
 INSTALLED LEFT & RIGHT SIDE SEAT BUCKLE ASSEMBLIES, TESTED ALL  
 FUNCTIONS AFTER THE REPAIR ALL TO SPEC AT THIS TIME  
 THE L SEATBELT BUCKLE WOULD COME LOOSE REPLACE THE BUCKLE  
 TO CORRECT

FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE

SEAT BELT BUCKLE RELEASES ON ITS OWN AT TIMES  
 SO SEAT BELT AIR WARNER REMOVED AND REPLACED LEFT SIDE BUCKLE  
 ASS.

DIAG SEATBELT REPLACE RECEIVER  
 REPL LEFT SEAT BELT  
 REMOVED AND INSPECT DRIVERS SEAT AND BUCKLE INSTALLED NEW  
 BUCKLE NON SIR  
 REPLACE DRIVER SIDE SEAT BELT BUCKLE

WIRE FROM SEAT BELT TO  
 OEM AND FOUND OPEN IN BR  
 BL WIRE REACHED L IN SEAT  
 AND FUSE BOX ALONG WITH  
 TRIM PANELS ON L H SIDE AND  
 FOUND WIRE OPEN IN THE  
 GOK PANEL. RAN NEW WIRE  
 FROM OEM TO SEAT

A	Wont Latch	THE LEFT SIDE SEATBELT DOES NOT BUCKLE	608
A	Wont Latch	THE SEATBELT BUCKLES DO NOT HOLD.	620
X	Other	CHECK DR SEATBELT STICKY	664
A	Wont Latch	PASSENGER FRONT SEAT BELT BUCKLE WONT LATCH.	686
A	Wont Latch	PASSENGER SIDE SEAT BELT IS WOP	688
X	Other	SEAT BELT WILL NOT UNLATCH	440
A	Wont Latch	THE SEATBELT BUCKLE DOES NOT HOLD	322
A	Wont Latch	O O DRIVERS SEAT BELT WONT BUCKLE	316
X	Other	INSPECT BUCKLES	717
X	Other	SOB AIR BAG LIGHT ON	618
X	Other	CLUT STATER RECALL ON SEATBELTS	614
X	Other	AIRBAG LIGHTS ON	219
X	Other	CUSTOMER STATES THAT DRIVERS SIDE SEAT BELT BUCKLE DOES NOT WORK	610
A	Wont Latch	DRIVERS SEAT BELT WILL NOT LATCH	724
X	Other	CLUT SAYS BRK LIGHT ON	680
X	Other	LEFT AND RT SEAT BELT BUCKLE WONT PASS BUCKLE TEST FOR RECALL 01821	602
R	Recall Performed	WHILE INSPECTING STOCK VEH, FOUND SEAT BELT BAD	480
X	Other	DRIVERS SIDE SEAT BELT WILL NOT LATCH CORRECTLY	610
X	Other	RIGHT SEAT BELT WONT STAY LATCHED	
B	Wont Stay Latched	DRIVERS SEAT BELT WONT STAY LATCHED	600
B	Wont Stay Latched	BAD PASSENGER SIDE SEAT BELT WILL NOT LATCH	214
A	Wont Latch	CLUT REPORTS DRIVERS SEAT BELT BUCKLE WILL NOT LATCH	672
A	Wont Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH PROPERLY	618
R	Recall Performed	CHECK SEAT BELTS WILL NOT BUCKLE	388
A	Wont Latch	CHECK LEFT FRONT SEAT BELT BUCKLE KEEPS RELEASEING	600
C	Unlatches/Releasees	DRIVER SIDE SEAT BELT WILL NOT BUCKLE	601
A	Wont Latch		680
X	Other	PASSENGER SEATBELT DOES NOT WANT TO RELEASE	713
A	Wont Latch	SEAT BELT BUCKLES WILL NOT LOCK TOGETHER BOLD UNIT	664
D	Unlatches/Releasees	CUSTOMER REPORTS DRIVER S SEAT BELT BUCKLE POPE SEAT BELT LOOSE BY ITSELF AT TIMES	617
A	Wont Latch	C O CENTER SEAT BELT WONT LATCH	616
O	Unlatches/Releasees	CUSTOMER REPORTS DRIVERS SEAT BELT BUCKLE UNLATCHES ON ITSA OWN AT TIMES	626
X	Other	SEAT BELT ANCHER WILL NOT GO OFF AFTER FLOODING IN SEATBELT	416
X	Other	CUSTOMER STATES SEAT BELT WARNING LIGHT WILL COME ON WHILE DRIVING WHEN SEAT BELT IS LATCHED	279
B	Wont Stay Latched	LEFT SEAT BELT WILL NOT STAY ATTACHED	676
C	Unlatches/Releasees	CHECK DRIVER SIDE SEAT BELT BUCKLE KEEPS COMING UNDONE, UNABLE TO TEST WITH TESTER, BUT WILL REPLACE AS A PRECTION	615
X	Other	DRIVER SIDE SEAT BELT DOES NOT LATCH PROPERLY	608

TEST AND REPLACE DRIVERS SEAT BELT BUCKLE, WORKIN  
1 REPLACE SEATBELT BUCKLE

INOPERATIVE TRACK ASSEMBLY FRONT SEAT REPLACE  
IN REPLACED SEAT BELT SPECIAL ORDERED

RENEW DRIVERS SEAT BELT  
USED STOCK UNIT PART DUE TO HANDICAP CUSTOMER REPLACED  
SEATBELT BACK  
IN TIME TO REPLACE DRIVERS SEAT BELT BUCKLE DUE TO NOT LATCHING  
AT TIMES. 1  
CAME APART SEATBELT ASSEMBLY FRONT REPLACE

REPLACED RIGHT SEAT BELT BUCKLE PER RECALL  
SEAT BELT BUCKLE WOULD NOT LATCH REPLACED RIGHT FRONT SEAT  
BELT BUCKLE  
REPLACE LEFT SEAT BELT WOULD NOT RELEASE ONCE IT WAS BUCKLED  
WITHOUT EXTREME DIFFICULTY  
FAULTY SEAT BELT BUCKLE REPLACED PASSENGER SIDE SEAT BELT  
BUCKLE  
PERFORM TEST REPLACE BUCKLE AND SEAT BELT  
INSPECT AND REPLACE BOTH SEAT BELT BUCKLES  
REPLACED THE L F SEAT BELT BUCKLE

CHECKED SEATBELT PER RT SEAT AND REPLACED SEATBELT BUCKLE  
RPL SEAT BELT BUCKLE  
REPLACE PASS SEAT BELT BUCKLE ASB FOR WILL NOT LATCH

REPLACE BUCKLE

11486 INSTALL DRIVER SEAT BELT BUCKLE TEST VERIFY REPAIR  
C/O OF BPN 781228 IN PASSENGER SEAT BELT BUCKLE WOULD NOT STAY  
LATCH. REPLACED BUCKLE AND TEST PROVED OK  
CHECK FOR RECALLS, NO RECALLS, SAFETY BELT LATCH SWITCH NOT  
WORKING PROPERLY, REPLACE SEAT BELT  
CHECK AND REPLACE BUCKLE  
CENTER SEAT BELT ADDITIONAL MISC. REPAIRS  
SEAT BELT CHIME REPLACE DRIVER BELT ASBY  
SP17 PERFORMED SEAT BELT DAMBUCKLE BROKEN; PER SEAT BELT  
BUCKLE; ADJUSTED PASS REAR DOOR STRAP/PINTESTED DOOR AND  
BUCKLE OK  
VCC INSPECTED SEAT BELT FOUND THAT THE BUCKLE WAS JAMMED  
REMOVED FRONT SEAT AND REMOVED AND REPLACED LEFT FRONT SEAT  
BELT. CHECKED TO VERIFY REPAIR

REPLACE SEAT BUCKLE USED IN OUIY REPAIR  
DURING REPLACED SEAT BELT ON DRIVER SIDE

REPLACED THE SEAT BELT BUCKLE  
REPLACE SEAT BELT BUCKLE  
SEAT BELT CHIME ACCESS DRIVER SEAT  
REPLACED DRIVER SEAT BELT BUCKLE  
INSP PROBLEMS, PASS. SIDE DEFECTIVE, REPLACED BUCKLE, CHECKED  
OPERATION, MIDDLE LAP BELT HAD INCORRECT BELT REPLACE BELT AND  
RETEST BELT OPERATION

PER SEATBELT INOP  
J1 18 NOB TEST CK PID TEST NR ON SEAT AND REPLACE SEAT BELT  
BUCKLE WAS INOP

A	Wont Latch	SEAT BELT DRIVER SEAT BELT WONT LOCK (BUCKLE)	216
A	Wont Latch	ON DR SIDE SEATBELT PBU DOES NOT LATCH	636
A	Wont Latch	MIDDLE SEAT BELT BUCKLE AND PASS SEAT BELT BUCKLE WILL NOT SNAP	806
X	Other	INSTALL SGP SEAT BELT	834
D	Unlatches While Driving	C B DRIVERS SEAT BELT COMES UNLATCHED WHILE DRIVING	812
X	Other	REMOVE SEAT BELT TO INSTALL IN CUSTOMER VEHICLE WITH RECALL	708
D	Unlatches While Driving	01821 SEAT BELT BUCKLE FOUND BAD. REFERE	708
A	Wont Latch	SEATBELT DRIVERS SIDE COMES LOOSE WHILE DRIVING	608
A	Wont Latch	DRIVERS SEAT BELT DOES NOT LOCK	241
R	Recall Performed	PERFORM RECALL 01801 LEFT BUCKLE PASSED, RIGHT BUCKLE FAILED	208
A	Wont Latch	P B SEAT BELT DOES NOT LATCH PROPERLY	418
X	Other	LEFT SEAT BELT HOOKS (GOOD STAYS LATCHED GOOD BUT WHEN YOU TRY TO RELEASE IS VERY DIFFICULT TO RELEASE	918
A	Wont Latch	PASSENGER SIDE SEAT BELT WONT CONNECT	785
A	Wont Latch	DRIVERS SEAT BELT BUCKLE WILL NOT LATCH	784
X	Other	CHECK SEAT BELTS NOT WORKING PROPERLY	781
C	Unlatches/Release	940 PER CUST. DRIVERS SEAT BELT COMES UNLATCHED	812
C	Unlatches/Release	REPAIR RT SEATBELT COMES LOOSE	434
B	Wont Stay Latched	DRIVERS SEAT BELT WILL NOT STAY LATCHED	338
A	Wont Latch	PASS SIDE SEAT BELT WILL NOT LATCH SGP	748
X	Other		288
X	Other	C B SEAT BELT WARNING CHIME KEEPS GOING OFF AFTER SEATBELT LOCKED	284
D	Unlatches/Release	CUSTOMER STATES THE DRIVERS SEAT BELT KEEPS COMING UNLATCHED	829
D	Unlatches While Driving	SGP HERE	879
X	Other	840 DO THE PASSENGER FRONT SEAT BELT COMES UNDOING WHILE DRIVING	879
X	Other	SEAT BELT WARNING LIGHT STAYS ON AND BINGS UP TO 4 TIMES APT	830
X	Other	REAR PASSENGER SEAT BELT BUCKLE IS STICKING	707
X	Other	INSTALL SGP LEFT SEAT BELT BUCKLE	310
X	Other	CUSTOMER STATES DRIVER SIDE SEATBELT ALERT CHIME STAYS ON	881
C	Unlatches/Release	SEAT BELT DRIVER SEAT BELT COMES UNDOING AND PASS REAR DOOR STICKS AND HARD TO OPEN	891
X	Other	CUSTOMER STATES DRIVER SIDE SEAT BELT INOP	818
X	Other	INSTALL SGP SEATBELT BUCKLE TECH 171 SEE RD 300790	314
A	Wont Latch	DRIVER SIDE SEAT BELT BUCKLE WILL NOT LATCH	478
X	Other	CUSTOMER STATES SEAT BELT LIGHT COMES ON WHILE DRIVING, SGP	831
A	Wont Latch	CUSTOMER STATES THE PASS SIDE SEAT BELT WILL NOT LOCK	448
D	Unlatches While Driving	940 DRIVERS SEAT BELT COMES UNLATCHED WHILE DRIVING	713
R	Recall Performed	01821 SEAT BELTS PASS SEAT BELT WONT FASTEN	210
X	Other	SEAT BELT LIGHT IS ON AND STAYS ON WILL GO OFF AND ON AND WILL DING	602
X	Other	SEAT BELT LIGHT STAYS ON WONT GO OFF WHEN BELT IS BUCKLED	281



REPLACE DRIVER SIDE SEAT BELT AND LATCH ASSEMBLY  
 NA CHECK OPERATION REMOVE & REPLACE SEATBELT  
 BUCKLE  
 REPLACED JAMMED BUCKLE  
 R/R FRONT CAPTAIN'S CHAIR, REPLACED LEFT BUCKLE  
 8100B C/K FOR LT FT SEAT TO REPLACE SEAT BELT  
 RECALL, REPLACE FEMALE END OF SEATBELT  
 REPLACE FRT SEAT BELT BUCKLE  
 4818 R/R DRIVERS SEAT, INSTALLED NEW SEAT BELT  
 BUCKLE, TESTED, WORKS FINE AT THIS TIME

SEAT BELT BUCKLE LATCHED EVOKEN  
 BELT TWISTED R/R BUCKLE  
 BUCKLE WAS SHORTED OUT. ABNORMAL DIAG MSB TEST, PW POINT  
 TEST, TRACE THE WIRING FROM THE SEAT AREA TO THE GEN MODULE  
 ALL OF THE WIRING WAS  
 18118 AIR BAG LIGHT FLASHING W/ REPLACE ONE SIDE SEAT BELT LATCH  
 BOP PRECONDITION FOR DRG SIDE C1278 CODE PRETERMINATION  
 SHORTED TO BATTERY POWER

SEAT BELT BUCKLE RETENTION REPLACE ONE SEAT BELT BUCKLE

2278 (BAND) 781002 CONDITION 41 REPLACED THE INTERMITTENTLY  
 STICKING L F SEATBELT BUCKLE  
 INOPERATIVE SEAT BELT ASSEMBLY NEAR RIGHT OR LEFT  
 REPLACE  
 INSTALL NEAR SEATBELT.  
 1E RECALL 048210 0.4 HRS TECH 8170 BOP/NOT & REPLACE DRIVERS SEAT  
 BELT  
 317 FRONT SEAT BELT WONT LATCH SEATBELT ASSEMBLY FRONT  
 REPLACE  
 BOTH SEAT BELTS INOP REPLACE BOTH SEAT BELTS

1778 INSTALLED DRIVER SIDE FRONT SEAT BELT BUCKLE  
 1 CHECK DRIVERS SEATBELT BUCKLE IS INTERMITTENTLY INOP, REPLACE  
 DRIVERS SEAT BELT BUCKLE  
 1127 TRAN 1818 TO CHECK FOR CODE NO CODE. PAN ON DEMAND TEST  
 PASSED. PAN PWPOINT CHECK SEAT BELT BUCKLE SWITCH AND FOUND  
 ITS STUCK IN INTERMITTENTLY. REMOVE DRIVER SEAT. REPLACE DRIVER  
 SEAT BELT BUC  
 6898 WARR REMOVED AND INSTALLED DRIVERS FRONT SEAT BELT  
 ASSEMBLY RECALL 81871  
 M TIME TO TEST & REPLACE DRIVERS SEAT BELT BUCKLE FOR WILL NOT  
 LATCH CONCERN

CUST STATES THE RIGHT FRONT SEAT BELT WONT HOLD ON LOCK SEE  
 JC...CORREPLACED RIGHT FRONT SEAT BELT BUCKLE A ON 06 18 02  
 DRAB AND REPOSITION SEAT BELT BUCKLE LATCH  
 REPLACED SEATBELT BUCKLE  
 . D.S BUCKLE COMES UNLATCHED WHILE DRIVING. INSPECT & REPLACE  
 BUCKLE. WEAK LATCH SPRING

REPLACED SEAT BELT BUCKLE PASSENGER SIDE

PASS SEATBELT INOP SEATBELT ASSEMBLY FRONT REPLACE

18884 M TIME & M TIME NO OPS FOR SUPER CROWN TO REPLACE DRIVERS  
 SEAT BELT BUCKLE, BUCKLE IS INTERMITTENTLY JAMMED Q/C BY TECH  
 PLANNED REPLACED RIGHT REAR SEAT BELT BUCKLE

B	Wont Stay Latched	DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	803
	Unlatches While	CUSTOMER STATES DRIVER SEAT BELT COMES UNLATCHED WHILE	
D	Driving	DRIVING CHECK AND ADVISE	744
A	Wont Latch	DRIVERS SEAT BELT WILL NOT LATCH	880
X	Other	SEATBELT INOP	891
X	Other	DRIVING SEATBELT INOP/INSTALL BOP	770
X	Other	SEATBELT PART IN	
A	Wont Latch	FRT DR SEAT BELT BUCKLE DOESNT LATCH	887
	Unlatches While	848 CUST STATES DRIVERS SEAT BELT COMES UNDONE WHILE	
D	Driving	DRIVING, PART SHOULD BE HERE	881
X	Other	OWNER REPORTS THE CENTER SEAT BELT BUCKLE AND THE PASSENGER	
X	Other	BUCKLE ARE INOP	877
X	Other	LEFT FRONT SEAT BELT BUCKLE INSERTED.	883
X	Other	CUST STATES CHECK SEAT BELT LIGHT COMES ON EVEN WHEN BELTS	
X	Other	BUCKLED	817
X	Other	AIR BAG LIGHT ON BOP HERE 828	821
X	Other	C/S RECALL 048210 0.4 HRS TECH 8170 BOP/NOT & REPLACE DRIVERS SEAT BELT BUCKLE ORDERED NEW BELT	901
A	Wont Latch	CUSTOMER STATES DRIVER SEAT BELT BUCKLE JAMMED IN THE RELEASED	
A	Wont Latch	POSITION AND WOULD NOT ALLOW THE BELT TO BE LATCHED	408
X	Other	PASSENGER SEAT BELT WILL NOT ENGAGE	886
	Other	JAMMING SEATBELT IN REAR SEAT.	808
R	Recall Performed	RECALL 01821 SEAT BELT	889
A	Wont Latch	CUST STATES RIGHT FRONT SEAT BELT WONT LATCH BOP IS IN	881
X	Other	CUST STATES THE MIDDLE SEAT BELT WILL NOT LATCH BOP IS IN	884
X	Other	CUST STATES THE DRIVERS SIDE FRONT SEAT SEAT BUCKLE IS STUCK IN	
A	Wont Latch	INSTALL BOP	830
A	Wont Latch	CUSTOMER STATES DRIVER SEAT BELT WILL NOT LOCK AT THIS.	894
X	Other	C B WHEN SEAT BELT IS ON WHILE DRIVING SEAT BELT LIGHT FLASHED ON	
X	Other	AND OFF	818
X	Other	RECALL SEAT BELTS 01821...BOP IN PASS SIDE	815
A	Wont Latch	DRIVER SEATBELT WONT LATCH POPE OUT	780
A	Wont Latch	CUSTOMER STATES THE RIGHT FRONT SEAT BELT WONT HOLD ON LOCK	
X	Other	SEE JD 4	882
A	Wont Latch	REPOSITION DRIVERS SEAT BELT LATCH PER CUSTOMERS REQUEST	888
	Unlatches While	RIGHT FRONT SEAT BELT WONT LATCH	408
D	Driving	DRIVERS SEAT BELT KEEPS COMING UNLATCHED WHILE DRIVING	886
A	Wont Latch	828 PASS SIDE FRONT SEAT BELT BUCKLE WONT LATCH PART WAS	
A	Wont Latch	ORDERED AND IS HERE	818
A	Wont Latch	CHECK FOR PASSENGER FRONT SEAT BELT NOT LATCHING BOP IN	838
A	Wont Latch	CUST STATES THAT DRIVERS SEAT BELT WONT LATCH	809
X	Other	REAR PASSENGER SIDE SEAT BELT RECEPTACLE IS FLAWED	770

KLE. PWTEST, OK WPA

8280 DON'T RIGHT FRONT BUCKLE WILL NOT LATCH. REMOVE AND REPLACE BUCKLE.

RECALLED NEW SEAT BELT BUCKLE AND WE TEST. OK. AT 428 SEAT BELT NOT STAYING ATTACHED FOUND DRIVERS SEAT BELT NOT STAYING ATTACHED FOUND SEAT BELT BUCKLE NOT WORKING REMOVE SEAT TO ACCESS THE BUCKLE REMOVE OLD BUCKLE INSTALL NEW BUCKLE REINSTALL SEAT

7788 (2006 48) REMOVED D SIDE FRONT SEAT TO ACCESS. REMOVED AND REPLACED D SIDE FRONT SEATBELT RESTRACTOR AND REASSEMBLED. RESEATED. OK.

8290 TESTED BOTH FRT SEAT BELT BUCKLES, VERIFIED GOOD EM/ACCESS BOTH FRT SEAT B. REPLACED BOTH FRT SEAT BELT BUCKLES. SEAT BELTS WONT LATCH REPLACE SEAT BELTS

REPLACE SEAT BELT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE SEAT BELTS WILL NOT LATCH REPLACE SEAT BELTS

21 CHECK AND INSPECT PERFORMED RECALL 01821 REMOVE AND REPLACE PAB, BOTH FRONT SEAT BELT BUCKLE AND RELEASE ASBY 21 ADDITIONAL 148C REPAIRS DO NOT USE WITH ANY OTHER LATCH OPERATIO N

80 SEAT BELT RECALL. A SUSPECTED BOTH SEAT BELTS PASS FAILED REPLACED PASS SEAT BELT.

BUCKLE WILL NOT LATCH R/R FRONT RIGHT BUCKLE ASBY VERIFY CONCERN FOR SEAT BELT RELEASE BUTTON STICKS. REMOVED A REPLACED SEAT BELT BUCKLE. REPLACE SEAT BELT BUCKLE REPLACE SEATBELT SENSOR REPLACE SEATBELT SENSOR REPLACE BELT AND BUCKLE ASBY R & R BOTH FRONT SEAT BELT BUCKLES

VERIFIED SEAT BELT WARNING LIGHT & CHIME STAYS ON WITH SEAT BELTS BUCKLED. REMOVED DRIVERS SEAT TO INSPECT WIRING. OK. DISCONNECTED SEAT BELT SENSOR TO TEST. FOUND SENSOR HAS CLOSED SHORT CIRCUIT CAUSE FOUND DRIVERS SIDE SEAT BUCKLE WOULD NO LATCH REPLACE SEAT BELT BUCKLE LATCHES OK

7788 80 SECURED SEAT BELT TO FLOOR MOUNT

REPLACE BUCKLE R I SEAT TRACK TO REPLACE SEAT BELT BUCKLE JAMMED, WILL NOT ACCEPT BUCKLE TOMBIE. REPLACE BELT ASBY.

SEAT BELT BUCKLES WILL NOT LATCH OPEN CIRCUIT IN DRIVERS SEAT BELT ASSEMBLY NGS TEST PID MONITOR AND RECORD RECORDED DRIVER SEAT AND SEAT BELT ASSEMBLY RECALLED NEW/COM

REPL. FRONT FRT SEAT BELT BUCKLE VERIFIED CONCERN R R SEAT BELT BUCKLE TO FIX CONCERN . . .

REMOVED SEAT BELTS REINSTALLED SEAT BELTS CONFIRM DRIVERS SEATBELT DOESNT STAY LATCHED REPLACE DEFECTIVE LATCH WITH NO BELT SEATBELT BUCKLE INOP. WILL NOT LATCH. REPLACE WITH NEW. RECHECK OK.

3678 REPLACE RT SIDE SEAT BELT ANCHOR BOLT BRSL WAS MISSING

QUALITY TESTED OK

NO LIGHT TO STAY ON. REPLACED SEAT BELT BUCKLE & RETEST/REINSTALLED DRIVERS SEAT.

A	Wont Latch	RT FT SEATBELT WILL NOT BUCKLE. BOP IS HERE	781
A	Wont Latch	805 CLUT 078 DRIVERS SIDE SEAT BELT WILL NOT LATCH	127
B	Wont Stay Latched	CUSTOMER STATES: DRIVER SEAT BELT DOES NOT STAY ATTACHED. BOP IN	780
D	Unlatches While Driving	C B THAT WHILE DRIVING THE SEAT BELT BUCKLE WILL. RELEASE AND YOU HAVE TO REBUCKLE IT	834
B	Wont Stay Latched	INOP. BOTH FRONT SEAT BELTS WILL NOT STAY BUCKLED	817
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	845
X	Other	SEAT BELT BUCKLE INOP	408
X	Other	PASSIVE SEAT BELT INOP FRT	899
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
R	Recall Performed	RECALL 01821	658
A	Wont Latch	CUSTOMER STATES DRIVERSIDE SEATBELT WILL NOT LATCH GOOD CC 840 BOP IN PARTS	824
R	Recall Performed	SEAT BELT INSPECTION SEATBELT FRONT CENTER BUCKLE WILL NOT LATCH. BOP HERE SEE 81188	407
A	Wont Latch	USE BPO 8189888	840
X	Other	CHECK FOR SEAT BELT RELEASE BUTTON STICKS CHIME SOUNDING AT TIMES EVEN WHEN SEAT BELT IS LATCHED BOP HERE	888
X	Other	SEAT BELT BUCKLE INOP	428
X	Other	BOP LF SEATBELT SENSOR	801
A	Wont Latch	DRIVER SEAT BELT BUCKLE WONT LATCH	812
A	Wont Latch	DRIVERS SEAT BELT AT TIMES WILL NOT BUMP IN ADVISE OPER	806
X	Other	CUSTOMER STATES SEAT BELT CHIME & WARNING LIGHT BEEPS COMING ON DRIVING	358
A	Wont Latch	CUSTOMER STATES DRIVERS SEAT BELT DOES NOT HOLD	818
X	Other	DRIVE CHECK SEAT BELT MIDDLE FRONT SEAT NOT ATTACHED	778
X	Other	CUSTOMER STATES SEAT BELT ALERT WILL NOT STOP CHIMING WHEN BELT IS CONNECTED	888
X	Other	PASS SIDE INOP	381
A	Wont Latch	FRONT PASS SEATBELT BUCKLE INOP	885
A	Wont Latch	DRIVER SIDE SEAT BELT WILL NOT HOLD	881
X	Other	SEAT BELT LIGHT STAYS ON EVEN WHEN BELTS BUCKLED. BOP	828
X	Other	PASS FRONT SEAT BELT LOCKED WILL NOT RELEASE	802
X	Other	C B FRONT PRESENTER SEAT BELT BUCKLE INOP. . . .	438
X	Other	REMOVE SEAT BELTS TO INSTALL IN VEHICLE THAT FAILED 01841 RECALL. REPT. INOP SEAT	708
B	Wont Stay Latched		808
A	Wont Latch	CUSTOMER STATES DRIVER SIDE SEATBELT WONT LOCK	604
X	Other	Y88 CUSTOMER STATES COVER ON PASS SEAT BELT ANCHOR LOOSE BOP IN PARTS	381

0871 VERIFY CONCERN HAD TO REPLACE REMOVE SEAT TO REPLACE SEAT BELT BUCKLE. FOUND SEAT BUCKLE NOT WORKING SEAT BELT IS WORKING NORMAL.

REPLACE MISSING LAP BELT AND BUCKLE  
 INSTALLED SOP SEAT BELT BUCKLE  
 REP BUCKLE ASSEMBLY  
 DAMAGED WIRE ON SEAT BELT BUCKLE. REPLACED SEAT BELT BUCKLE ON DRIVER SIDE SEAT

SEAT BELTS WONT LATCH REPLACE SEAT BELTS  
 SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELT  
 REPLACED DRIVERS SEAT BELT BUCKLE  
 REPLACE ONE SEAT BELT  
 FOUND ROP SEAT BELT HAD TO REMOVE DRIVERS SEAT TO REPLACE BELT BUCKLE  
 WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE  
 SEAT BELT NOT OPERATING PROPERLY. VERIFIED AND R AND P SEAT BELT ANCHOR. RETESTED AND CHECKED OK AT THIS TIME  
 SEAT BELT BUCKLE OK. CP OF SEAT BELT INTERMITTENT BUCKLE.  
 REPLACE SEAT BELT ASSEMBLY.  
 REPLACED SEAT BELT BUCKLE  
 0181 Q SEAT BELT BUCKLE. REPLACE PASS SEAT BELT BUCKLE  
 1388 828 CHECK FOR CODES WITH WDM FOUND NO CODES PERFORMED ON DEMAND TEST FOR SEAT BELT FOR SENIOR. INTERMITTING IN SEAT BELT OPERING SEAT BELT PART. DID NOT HAVE PER MARK C 828 828 REMOVED SEAT AND

48 TEST SEAT BELT BUCKLE INTERMITTENTLY NOT LOCKING CHANGED SEAT BELT OUT  
 30 SPW REAR SEAT BELT BUCKLE

BROKEN CO IN REPLACED CENTER SEAT BELT

378 8428 BUCKLE, 42 DRIP CONFIRMED CONCERN OF PASSENGER SIDE SEAT BELT BUCKLE INOP ON 68 40 SPLIT SEAT. REPLACED PASSENGER SIDE BUCKLE ASY. DUST CONCERN NO LONGER PRESENT. DUB WHY FRONT SEAT BELT WONT UNLATCH BUCKLE IS BROKEN REPLACE RIGHT FRONT SEAT BELT ASSEMBLY

DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT REPLACE

REAR RIGHT FRONT BUCKLE ASSEMBLY  
 REPLACED SEAT BELT WITH NEW  
 SEAT BELTS WONT LATCH REPLACE SEAT BELTS  
 WONT HOLD SEATBELT ASSEMBLY FRONT REPLACE  
 11 INSPECT AND REPLACE 2 SEATBELT BUCKLES. 40 40 SPLIT BENCH WITH 40 POWER CHILD.

DAB AND REPAIRED OPEN CIRCUIT TO CONNECTOR AT SEAT BELT  
 REPLACED RIGHT SIDE SEAT BELT BUCKLE PER 01321.  
 NEC TO REPLACE BOTH TO CORRECT  
 SEAT BELTS WILL NOT LATCH PROPERLY REPLACE SEATBELT  
 FOUND DRIVERS SEATBELT BUCKLE INTERMITTENTLY OPEN AND REAR BUCKLE TO CORRECT, RETEST OK  
 RECEIVER JAMMED REPAIRED BUCKLE.  
 VERIFIED CONCERN TESTED SEAT BELT WIRING FOUND SEAT BELT BUCKLE INTERMITTENTLY OPEN REAR BUCKLE AND TESTED OPERATION NORMAL. MTRNG REQUESTED FOR ALL THE MENTIONED REPAIRS DONE DUE TO NO LABOR CIPPS FOUND

A	Won't Latch	CLUT. STATES DRIVERS SEATBELT WONT LATCH	512
X	Other	CENTER BUCKLE IS NOT WORKING	518
X	Other	CENTER BUCKLE IS NOT WORKING	518
X	Other	CENTER BUCKLE ON LEFT SIDE IS MISSING	518
X	Other	INSTALL SOP SEAT BELT LATCH	528
A	Won't Latch	TRPS CENTER SEAT BELT WILL NOT LATCH INSTALL SOP	538
X	Other	840 CS SEAT BELT BUZZER STAYS ON. SOP PART HERE	512
X	Other		528
A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	518
X	Other	PASSENGER SIDE SEAT BELT WILL NOT LATCH PROPERLY	518
X	Other	DRIVERS SEAT BELT IN CP REPORT	518
R	Recall Performed	RIGHT FRONT SEAT BELT FAILED OTHER	514
X	Other	DRIVERS SEAT BELT BUCKLE IN CP	548
A	Won't Latch	CK FOR SEAT BELT BUCKLE WONT HOLD	548
	Unlatches While Driving	DRIVERS SEAT BELT COMES UNLATCHED INTERMIT. WHILE DRIVING. SOP IN	512
D	Unlatches While Driving	848 DRIVER SIDE SEAT BELT BUCKLE KEEPS COMING UNLATCHED WHILE DRIVING	518
D	Other	OK SEATBELT CHIME WONT CHIME	591
R	Recall Performed	PERFORM SEATBELT RECALL PER OWNER	588
X	Other	THE SEAT BELT LIGHT AT TIMES WILL STAY ON EVEN WHEN THE SEAT BELT IS LATCHED, CORRECT FOR	518
A	Won't Latch	CUSTOMER CONCERN IS THAT PASSENGER FRONT SEAT BELT BUCKLE IS NOT WORKING PROPERLY AND SOMETIMES DOESNT LATCH AT ALL.	
X	Other	SPW PASSENGER FRONT SEAT BELT BUCKLE OCCAS	
A	Won't Latch	848 840 FRONT SEAT BELT WILL NOT BUCKLE TOGETHER SOP SEE ALERT	620
A	Won't Latch	PASS SEAT BELT RECEIVER WILL NOT LATCH (8090 N	417
X	Other	CUSTOMER STATES PASSENGER SEAT BELT IS LOOKING UP	588
A	Won't Latch	CLUT STATES THAT DRIVERS SEAT BELT WILL NOT LATCH.	387
A	Won't Latch	CLUT. ST. THE FRONT CENTER & PASS. SEATBELTS WILL NOT LATCH. CK. A ADVISE.	788
A	Won't Latch	SEAT BELT NOT LATCHING	817
A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	518
A	Won't Latch	CK FOR SEAT BELT BUCKLE WONT HOLD	548
R	Recall Performed	CENTRA 2001 MODEL YEAR CROWN VICTORIA EXCURSION 01/05/04	528
X	Other	TOPGUSH PASS/GRAND UNSECURE/NO GATOR/PLANS	603
R	Recall Performed	SEAT BELT WARNING INDICATOR FRONT SO OUT	628
X	Other	PERFORM RECALL 0181 RY ME 40 N P	638
X	Other	CLUT STATES SEAT BELTS INOP	618
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	618
X	Other	PER CUSTOMER SEAT BELT CHIME WILL NOT GO OFF AT TIMES UNLESS YOU HIT BUCKLE WITH YOUR HAND/DRIVER SIDE	428
X	Other	LF SEAT BELT INOP	
X	Other	OP SEAT BELT CHIME WILL NOT STOP WITH SEAT BELT ON	608



NEG OT REPLACE SEAT BELT	X	Other	CURT STATES SEAT BELT CHIME STAYS ON	359
LIGHT STAY ON	X	Other	OK SEAT BELT WARNING LIGHT STAYS ON	368
REPLACE SEAT BELT BUCKLE	A	Work Latch	PASS (SIDE FRNT SEAT BELT WILL NOT LATCH SW	372
SEAT BELT BUCKLE INOP	A	Work Latch	CHK DRIVER SIDE FRONT SEAT BELT WILL NOT LATCH	370
REPLACE DRIVERS SIDE BUCKLE	X	Other		
VEHICLE IN FRONT LH SEAT BELT IS INOP, FOUND FAULTY BUCKLE ASBY DUE TO INTERNAL MFLF, REPLACED	X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	378
SEAT BELTS WONT LATCH REPLACE SEAT BELTS	A	Work Latch		
OK AND REMOVED DRIVERS SEAT BELT BUCKLE ASBY AND REPLACED	X	Other	SEAT BELT CHIME STAYS ON	384
RECHECKS FIRE	X	Other		
VERIFY CONCERN CENTER BUCKLE WOULD NOT LATCH AND RT NEAR	X	Other	G S SEAT BELT NOT WORKING INOP PARTS HERE	383
REPLACED CENTER BUCKLE AND RIGHT REAR SEATBELT BUCKLES	X	Other	SEAT BELT BUCKLE INOP	389
REPLACED SEAT BELT	X	Other		
IS INSPECTED SEAT BELTS, FAULTY PERFORMED RECALL, REPLACED	R	Recall Performed	INSPECT PER 01321 RECALL INSTRUCTIONS	395
SEAT BELT	R	Recall Performed	RECALL 01321	399
RECALL 01321	A	Work Latch	CURT STATES DRIVERS SEAT BELT DOES NOT ENGAGE AND HOLD	370
SEAT BELT BUCKLE REPLACED DRIVERS SIDE SEAT BELT BUCKLE	X	Other	CUSTOMER STATES ALARM WAS GOING OFF WHEN SEAT BELT PLUGGED	375
SEAT BELT ALARM WAS GOING OFF WHEN SEAT BELT WAS PLUGGED IN				
REPLACED DRIVERS SIDE SEAT BELT LATCH				
DIAGNOSE SEAT BELT LIGHT ON OPEN IN SEAT BELT BUCKLE ASBY R & I				
SEAT ASBY TO ACCESS AND REPLACED SEAT BELT BUCKLE ASBY				
CODE IS	C	Unlatched/Plugged	CUSTOMER STATES DRIVERS SEAT BELT CHIME STAYS ON AND BUCKLE	388
WAS FINCHED & BROKEN	X	Other	RELEASED	389
REPL. ON SIDE SEAT BELT BUCKLE				
FAILED DRIVERS SEAT BELT BUCKLE TEST				
REPLACE DRIVER SIDE BELT				
BUCKLE NO RECALL OP CODE HAS WARRANTY	R	Recall Performed	SEAT BELT LIGHT WILL NOT TURN OFF	382
REPLACED SIDE BUCKLE WITH NEW	A	Work Latch	PERFORM RECALL 01321 NOTE NO OPEN RECALL CAMPAIGN PER OWNER	377
INSTALL SEAT BELT	B	Work Latch	BUT FAILED TEST	377
0111 WARN VERIFY CONCERN HAS DIAG TO MONITOR PER FOUND DRIVER			SEAT BELT WILL NOT LATCH	380
SEAT BELT NOT SHOWING SEAT BELT NOT BUCKLED. PERFORMED PPT.				
FOUND SEAT BELT BUCKLE INOP FOR BUCKLE WEAR AND QUALITY				
INSPECTED BY 3711				
VEVY AND TEST NECESSARY TO REPLACE BUCKLE				
				3911
	X	Other	CURT CHECKS CONCERN FOR DRIVER SIDE SEAT BELT CHIME AFTER	354
	X	Other	BUCKLING BELT.	354
	X	Other	CURT CONCERN FOR SEAT BELT LIGHT STAYING ON AFTER BUCKLED	
	X	Other	SEAT BELT BUCKLE INOP	377
	X	Other	FAILED	377
	X	Other	CURT STATES SEATBELTS INOP	389
	R	Recall Performed	04021 LFT FRNT SEAT BELT BUCKLE BAD	305
	X	Other		
	X	Other	CHECK PASSENGER SIDE SEAT BELT FOR ANY MALFUNCTIONS???	414
	X	Other	CUSTOMER STATES SEAT BELT WARNING CHIME WILL NOT GO OFF PART	408
	X	Other	IS HERE FOR DRIVER SIDE SEAT	
	X	Other	SEATBELT WARNING ALARMS WHEN SEAT BELT ARE LATCHED	408
	X	Other	INTERMITTENT	408
	X	Other	DOOR CHIME COMES ON WHEN CUSTOMER DRIVING (INTERMITTANT)	409
	R	Recall Performed	NAC 01321 SEAT BELT BUCKLE RECALL INSPECTED LEFT SIDE FAILED	414
	X	Other		
	R	Recall Performed	CERTAIN 1991 MODEL YEAR CROWN VICTORIA EXCURSION FT/BU/PRE	385
	X	Other	THROUGH PERFORM AND MARQUEL MANDACION JAMES	379
	A	Work Latch	SEATBELT IS INOP AT TIMES	379
	A	Work Latch	LEFT SEATBELT BUCKLE WONT LATCH	379
	R	Recall Performed		
	A	Work Latch	INSPECT PER 01321 RECALL INSTRUCTIONS	395
	A	Work Latch	PASSENGER FRONT SEATBELT WONT LATCH	370
	A	Work Latch	DIAG FRONT DRIVER SEAT BUCKLES INOP	329
	X	Other	SEAT BELT READER KEEP ON AFTER CONNECTED	329
	X	Other		
	X	Other	DRIVER SIDE SEATBELT BUCKLE INOP	439
	X	Other	CURT STATES SEAT BELT WILL NOT RETRACT CO ON	370

SEAT BELT BUCKLE FAILED REPLACE OK AND FOUND SEAT BELT BUCKLE BAD AND REPLACE SEAT BELT BUCKLE AND BUSHING REPLACED SEAT BELT INOP SEATBELT ASSEMBLY FRONT REPLACE 19187 P/B REPLACE PASS FRONT SEAT BELT BUCKLE ASSY WOULD NOT BUCKLE	A	Worn Latch	DRIVER SIDE FRNT SEATBELT WILL NOT LATCH	770
	X	Other	SEATBELT LIGHT ON AND CHIME RINGS	887
	X	Other	INSPECT FOR SEAT BELT CONCERN	890
	X	Other	CUSTOMER IS CONCERNED SEAT BELT CHIME NEVER SOUNDS	281
REMOVE AND REPLACE P/B, R/LF SEAT BELT BUCKLE END RELEASE ASSY. REPLACE SEAT BELT BUCKLE	B	Worn Stay Latched	RHD PASS FRONT SEAT BELT DOES NOT STAY LOCKED	601
	A	Worn Latch	RIGHT FRONT SEAT BELT FEASLE END DOES NOT HOLD	390
	A	Worn Latch	LEFT FRONT SEAT BELT BUCKLE WONT LATCH	619
INSPECT RIGHT FRONT SEAT BELT FOR WILL NOT BUCKLE. NEED BUCKLE OPENING BL. W/IN. REMOVE AND REPLACE SEAT BELT BUCKLE. DONE. VERIFIED CONCERN. REMOVED DRIVERS SEAT FOR ACCESS. UNEXPECTED BENDING FROM BUCKLE UNDER CARPET. F/W W/INS INSULATION CUT SHORTER CUT BUCKLE. ORDERED NEW BUCKLE. VEHICLE SAFE TO DRIVE. INSTALLED NEW BUC INSTEAD SEAT BELT BENDING BUCKLE. F/W BOTH FRONT SEATS TO REPL BOTH SEAT BELT BUCKLES. VLE ASSY RETESTED OK	A	Worn Latch	CUSTOMER STATES RIGHT FRONT SEAT BELT WILL NOT LOCK PROPERLY. CHECK OPERATION OF SEAT BELT.	818
	X	Other	INSPECT DRIVERS SEAT BELT. CUSTOMER STATES WHEN SEAT SECURED, BELL CHIME SOUNDS. INSPECT & REPORT	618
	X	Other	INSTALL SOP SEAT BELT ASSTY NEAR NEW GATE ORDERED	318
10188 BELL CHIME FROM SEAT BELT BUCKLE ON DRIVERS SEAT AS 4811 RHS 008 MT. S AS REPLACED L/F SEATBELT BUCKLE. RETEST OK 18496 MD IN BUCKLE. INJECT OK AND REPL. DRIVERS SEAT BELT BUCKLE AND PECK INOP SEAT BELT ASSEMBLY REAR FRONT ON LEFT REPLACE REPLACE RIGHT HAND SEAT BELT BUCKLE, 48 REPLACED BOTH SEAT BELT BUCKLES	A	Worn Latch	DRS LEFT SEAT BELT WILL NOT BUCKLE	812
	X	Other	BELL STILL CHIME WITH DR SEAT BELT LOCKED D&HE CAN TWIST BASE OF BELL AND BELL WILL STOP	818
	A	Worn Latch	RECEIVER TO SEAT BELT INOP WILL NOT CLICK OR HOLD	838
OPEN SEATBELT ASSEMBLY FRONT REPLACE FRONT REPLACE REPLACE PASSENGER FRONT SEAT BELT BUCKLE	X	Other	DRS INSTALL SOP PART FOR SEAT BELT LIGHT STAYING ON OK	727
	A	Worn Latch	DRIVERS SEAT BELT DOES NOT LATCH	381
	A	Worn Latch	RIGHT FRONT SEAT BELT WILL NOT CATCH AT TIMES	817
	X	Other	SEAT BELT BUCKLE BENDING	318
BACK SEAT BELT BUCKLE REASSEMBLY, PERFORMED ELECTRICAL TEST R&H BUCKLE, RETEST.	X	Other	NO PART IN FOR SEAT BELT CHIME WILL NOT SHUT OFF REPLACE R O P. SEAT BELT RECEIVER SETS TO HIGH AND SMACKS YOU IN THE REAR	458
	X	Other	REPLACE R O P. SEAT BELT RECEIVER SETS TO HIGH AND SMACKS YOU IN THE REAR	818
	X	Other	REPLACE R O P. SEAT BELT RECEIVER SETS TO HIGH AND SMACKS YOU IN THE REAR	714
REPLACED DRIVER SIDE SEATBELT W/ TO REINSTALL CLIP 14 VEHICLES FOUND PASS SEAT BELT INOP REPLACED 1 CHECK FRONT PASS SIDE SEAT BELT BUCKLE IS VERY HARD TO RELEASE REMOVE AND REPLACE FRONT FRONT SEATBELT BUCKLE 1 REMOVED AND REPLACED LEFT FRONT SEAT BELT BUCKLE. RECHROMED OK SEAT BELT BUCKLE SEATBELT ASSEMBLY FRONT REPLACE REPLACE SEAT BELT BUCKLE	X	Other	DOOR SEAT BELT CHIME STAYS ON WHILE DRIVING. SEAT BELT LIGHT STAYS ON CUST STATES DRIVERS SIDE SEATBELT WILL NOT STAY LATCHED WHEN FULLY ON	316
	C	Unlatched/Release	SEAT BELT CLIP FELL IN SLOT ON PASS SIDE	883
	X	Other	SEAT BELT CLIP FELL IN SLOT ON PASS SIDE	818
	X	Other	CUSTOMER STATE SEAT BELT INOP NEAR RECLINE ON	864
WOULD NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE REPLACE RIGHT FRONT SEATBELT BUCKLE ASSY. INOP RIGHT SEATBELT WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE 14888 R/F SEAT BELT BUCKLE BAD W/IN. VERIFIED CONCERN. FOUND R/F SEAT BELT WOULD NOT LATCH. TESTED AND FOUND SEAT BELT BUCKLE BAD. REPLACED R/F SEAT BELT BUCKLE ASSY. RETESTED ALL OK AT THIS TIME RECALL 01821 REPLACED LEFT SIDE SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE RECALL 01821 SEATBELT ASSEMBLY FRONT REPLACE	X	Other	PASS SIDE FRNT SEATBELT IS HARD TO RELEASE	284
	A	Worn Latch	LEFT FRONT SEAT BELT BUCKLE WAS NOT HOLDING	868
	X	Other	SEATBELT BUCKLE BROKEN	818
	X	Other	SEAT BELT BUCKLE INOP	458
	A	Worn Latch	SEAT BELT WILL NOT LATCH SOP HIGH SIDE 87917 TECH 348 PASS SIDE	820
	X	Other	LINE W/SEATBELT ORDER R/F SEAT BELT HARD TO LATCH	820
14888 R/F SEAT BELT BUCKLE BAD W/IN. VERIFIED CONCERN. FOUND R/F SEAT BELT WOULD NOT LATCH. TESTED AND FOUND SEAT BELT BUCKLE BAD. REPLACED R/F SEAT BELT BUCKLE ASSY. RETESTED ALL OK AT THIS TIME RECALL 01821 REPLACED LEFT SIDE SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE RECALL 01821 SEATBELT ASSEMBLY FRONT REPLACE	R	Recall Performed	FRONT PASSENGER SEAT BELT BUCKLE FAILED RECALL TEST	788
	A	Worn Latch	RIGHT SEAT BELT WILL NOT LATCH AT TIMES	817
	R	Recall Performed	RECALL 01821 RIGHT	820
	X	Other	CHECK SEAT BELTS	818
	X	Other	C O 3 FRONT PASS SIDE SEATBELT INOP AT TIMES	888
	X	Other	CUST STATES PASS SIDE SEATBELT INOP	405

SEATBELT INOP DEFECTIVE SEAT BELT BUCKLE AND BOLT	CENTER SEAT BELT ASSEMBLY VERIFY CONCERN. INSTALL SPECIAL ORDERED	X	Other	CUSTOMER SAYS THAT PASSENGER SIDE SEAT BELT BUCKLE	408
BELT	R IN BRACING PASSENGER FRONT BELT BUCKLE	X	Other	LEFT FRONT SEAT BELT BUCKLE INOPERATIVE	810
10988 VERIFY CUSTOMER COMPLAINT. INSPECT RT FT SEAT BELT BUCKLE. FOUND LATCH IN BUCKLE BAD. REMOVE AND REPLACE RT FT SEAT BELT BUCKLE. CC 48	REAR PASS SEAT BELT BUCKLE	X	Other	CUSTOMER STATES PASSENGER SIDE SEAT BELT BUCKLE INOP	810
10988 VERIFY CUSTOMER COMPLAINT. INSPECT RT FT SEAT BELT BUCKLE. FOUND LATCH IN BUCKLE BAD. REMOVE AND REPLACE RT FT SEAT BELT BUCKLE. CC 48	REAR PASS SEAT BELT BUCKLE	X	Other	NO RECALL BUT HAS BAD SEAT BELT ON PASS SIDE	886
0 CUSTOMER STATES SEAT BELT WILL NOT ENGAGE. CONFIRMED CUSTOMER'S COMPLAINT SEAT BELT WILL NOT ENGAGE DUE TO SEAT BELT RETAINER IS JAMMED. REPLACED RETAINER AND CHECKED OPERATION O.K. INSTALLED ORIDE	REAR PASS SEAT BELT BUCKLE	A	Won't Latch	CUSTOMER STATES RIGHT FRONT SEAT BELT INOP	883
BROKEN LATCH BT BUCKLE	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	PASS FRONT SEAT BELT WILL NOT ENGAGE	718
VERIFIED CUSTOMER'S COMPLAINT. FOUND RIGHT SIDE SEAT BELT BUCKLE NOT CATCHING. REPLACED SEAT BELT BUCKLE. VERIFIED REPAIR. FINISHED DAMAGED WIRE BODY CHASSIS ELECTRICAL (BCR) TEST REPLACE SEAT BELT KIT	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	REPLACE RT FRONT SEATBELT WONT LATCH	908
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	LEFT FRONT SEAT BELT WONT BUCKLE	204 818
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	CUSTOMER STATES: RIGHT FRONT SEAT BELT INOP	807
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	SEAT BELT CHIME AND LIGHT STAY ON	818
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	PASS SIDE FRONT SEAT BELT WONT BUCKLE	778
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	CUSTOMER STATES REPLACE SOP PROPERLY BUCKLE	873
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	CUSTOMER STATES CENTER FRONT SEAT BELT INOP. INSTALL SOP	878
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	CUSTOMER STATES SEAT BELT BUCKLE BROKEN DRIVER SIDE	818
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	SEAT BELT BUCKLE BROKEN DRIVER SIDE	886
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	CHECK DRIVER SIDE SEAT BELT WONT LAUNCH	818
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	CUSTOMER STATES PASSENGER FRONT SEAT BELT BUCKLE WONT STAY BUCKLED	841
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	B	Won't Stay Latched		
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	C	Unlabeled/Released	848 SEATBELT ON DRB SIDE LATCHES BUT CHIME UNDONE	881
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	SEATBELT ON THE DRIVERS SIDE DOESNT ALWAYS LATCH	818
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	CUSTOMER REPORTS RIGHT FRONT WONT BUCKLE IN	803
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	REPAIR TO MIDDLE SEAT BELT BUCKLE INOP	803
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	SEAT BELT PARTS WERE ORDERED ON MD AM 26 5 15 02	334
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	LT SEAT BELT BUCKLE NOT LATCHING CONCERN CODE 940	805
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	CUSTOMER STATES THAT SEAT BELT ALARM OFTEN GOES OFF WHEN SEAT BELT IS ON	845
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	SEAT BELT IS ON	847
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	BELTBINDER GOES OFF EVEN THOUGH IT HAS BEEN SHUT OFF	406
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other	PASS SIDE SEAT BELT INOP	
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	SEAT BELT LATCH IN PASS FRONT WIL NOT LATCH INTERMITTENTLY	817
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	X	Other		808
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	SEAT BELT WILL NOT LATCH	478
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	USE SPO 82074815 518
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	A	Won't Latch	CHECK FOR DRIVER SEAT BELT NOT LATCHING	408
0	SEATBELT ASSEMBLY FRONT REPLACE AS PER LAB REPORT WILL NOT GO INTO BUCKLE AND CLICK IN. REPLACE FRONT RIGHT SEAT BELT. REPLACE LP SEAT BELT BUCKLE	B	Won't Stay Latched	RIGHT FRONT SEATBELT WONT STAY CONNECTED	456

114 CHECK LEFT FRONT BELT BUCKLE HAS BRACKEN LATCH MECHANISM  
 REPLACE LATCH ASSEMBLY  
 SEAT BELT REPLACED SEAT BELT BUCKLE  
 REPLACE RIGHT FRONT SEAT BELT BUCKLE  
 REPLACE PASS SIDE SEAT BELT BUCKLE HAD TO SWITCH CIRCUITS BUOKLE  
 OVER TO WORK IN NEW BUCKLE ASSEMBLY CHECK OPERATION AFTER  
 REPAIR ALL O K

REMOVE SEAT AND REPLACE BUCKLE, REINSTALL SEAT AND REPEAT, OK  
 REPAIR OK REPLACE SEAT BELT

INTERNAL FAILURE IN BUCKLE REPLACED RT AND LT SEAT BELT BUCKLES  
 01821 O O 4 INSP AND ERPL P SIDE SEAT BELT  
 1 REPLACED RIGHT FRONT SEAT BELT

RECALL 01821 RECALL REPLACE SEAT BELT BUCKLE  
 OUT OF ADJUSTMENT ADDITIONAL MISC REPAIRS  
 WARNING SWITCH FAILING TEST SYSTEM AND REPLACE DRIVERS  
 SIDE SEATBELT BUCKLE  
 PAIR SEAT TO REPLACE SEAT BELT ASSY INTERNAL FM LINE  
 1 REPLACED RIGHT FRONT SEAT BELT BUCKLE  
 RT SEAT BELT PRETENSION NOT CONNECTING,CONNECT RT SEAT BELT  
 PRETENSION NOT CONNECTED,CONNECT & CLEAN  
 REMOVED DRIVERS SIDE SEAT BELT BUCKLE AND REPLACED WITH NEW  
 ONE, RECORDED OK

REPLACED BUCKLE ASSEMBLY  
 SEAT BELT WILL NOT FASTEN, REPLACE DRIVERS SEAT BELT BUCKLE  
 NEED TO REPLACE DRIVER SEAT BELT BUCKLE DUE TO IT BROKE  
 REPLACED LEFT FRONT DRIVERS SEAT BELT BUCKLE THAT KEEPS THE  
 BELT MINDER LIGHT ON  
 3288 REPLACED DRIVERS SEAT BELT BUCKLE QUALITY CHECKED  
 REVEALED  
 VERIFY CONCERN REPLACE PASSENGER SEAT BELT BUCKLE  
 VERIFY REPAIR  
 REMOVED LF SEAT AND REPLACED LF SEAT BELT BUCKLE, WOULD NOT  
 LATCH  
 CHECK OUT, CONFIRMED SEAT BELT INOP, REPLACE AND REPEAT  
 THE CHIMEING SEAT BELT WARN REPLACED SEAT BELT BUCKLE CHIMES  
 WHEN SEAT BELT NOT BUCKLED DOES NOT CHIME WHEN SEAT BELT IS  
 BUCKLED  
 REPLACED DRIVERS SEAT BELT

0184 INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT BUCKLE

01821 COMPLETED  
 REPLACE BELT BUCKLE ASSY ON DRIVERS SIDE

CON 048 CC 48 0184 INSP 0184 INSP 0184 INSP 0184 INSP  
 SEATBELT ASSEMBLY FRONT REPLACE (R11A32 R11A73)

SEAT BELT FAILED BODY CHASSIS ELECTRICAL (SCS) TEST

0184 INSP VERIFIED CONCERN M TIME TO REPLACE SEAT BELT BUCKLE

RR RIGHT SEAT AND REPLACE BUCKLE ASSY  
 CHECK AND REPLACE SEATBELT BUCKLE PER RECALL  
 REPLACED BOTH FRONT SEAT BELT BUCKLES PER RECALL  
 REPLACE DR SEATBELT

A	Worn Latch	DRIVER SEATBELT WONT BUCKLE	306
O	Unlatched/Released	CLUT STAYS DRIVER SEAT BELT BUCKLE COMES UNDONE	306
A	Worn Latch	PASSENGER FRONT SEAT BELT WILL NOT LATCH 3 30	306
A	Worn Latch	REPAIR PASS SIDE SEAT BELT DOES NOT LATCH INTO PLACEBUCKLEN OPENED AND IS IN PROCAL ORDER	380
A	Worn Latch	LEFT FRONT SEAT BELT WONT LATCH	417
A	Worn Latch	DRIVER SIDE SEATBELT WILL NOT HOOK FRONT DRIVERS SIDE AND FRONT PASSENGER SIDE SEATBELT WILL NOT LATCH	547
A	Worn Latch	01821 SEAT BELT RECALL	570
R	Recall Performed	CUSTOMER SEATED RIGHT FRONT SEAT BELT WILL NOT HOLD	595
A	Worn Latch	01821 SEAT BELT RECALL	617
X	Other	01821 SEAT BELT RECALL	630
R	Recall Performed	CLUT STAYS CENTER SEAT BELT WONT BOLTED DOWN	770
X	Other	SEAT BELT ALARM AND LIGHT WILL NOT GO OFF WHEN SEAT BELT IS BUCKLED	870
X	Other	DRIVERS SIDE SEATBELT IS DIFFICULT TO FASTEN	881
X	Other	INSTALL, INOP SEAT BELT (SEE PREV)	905
A	Worn Latch	AIR BAG WARNING LIGHT ON	975
A	Worn Latch	DRIVERS SIDE FRNT SEAT BELT WONT LATCH	918
B	Worn May Latched	CHECK DRIVERS SIDE SEATBELT BUCKLE WONT STAY LATCHED	918
A	Worn Latch	OK DRIVERS SEAT BELT INOP INSTALL SOP	770
A	Worn Latch	OK DRUMH SEAT BELT BUCKLE WILL NOT LOCK INTO PLACE	770
X	Other	SEAT BELT REMINDER LIGHT ON WITH BELT BUCKLED	618
A	Worn Latch	CHECK AND REPORT ON DRIVERS SEAT BELT WONT LOCK PASSENGER SIDE FRONT SEATBELT WILL NOT LATCH, ORANGE RELEASE BUTTON IS STUCK 338	403
A	Worn Latch	DRIVERS SIDE SEAT BELT INOP	880
X	Other	DRIVERS SEAT BELT INOP	880
X	Other	SEATBELT WARNING CHIME CONTINUES TO CHIME AFTER SEATBELT IS LATCHED	410
X	Other	NEEDS DRIVERS BELT	738
X	Other		830
X	Other		200
R	Recall Performed	RECALL 01821 LEFT SIDE OK, RIGHT SIDE REPLACE 1172 7861208 048	216
X	Other	SEAT BELT MINDER WILL NOT GO OFF	530
X	Other	CUSTOMER STAYS DRIVER S SEAT BELT BUCKLE HAS INTERMITTENT INOP	765
A	Worn Latch	CLUT STAY RT FRNT SEAT BELT WILL NOT LATCH CHECK SEATBELT BUCKLE SOLDS FOR 18 MIN AFTER STARTUP WITH ALL BELTS BUCKLED	314
X	Other		770
X	Other	RT FRONT SEATBELT BUCKLE NOT CLICKING PROPERLY INSTALL S O PART LINE 6FO 0180008	650
X	Other	RECALL 01821 SEATBELT INSPECT	306
R	Recall Performed	PERFORM RECALL 01821 LEFT AND RIGHT BUCKLE FAILED	606
R	Recall Performed	CHECK DR SEAT BELT WONT STAY LATCHED	206
B	Worn May Latched		318



REPLACED SEATBELT. 1

TEST W/ AIR REPLACED SEAT BELT BUCKLE  
1189 REPLACE PASS SIDE SEAT BELT BUCKLE  
8841 SEAT BELT BUCKLE BROKEN BY WRT PERFORMED VARIOUS  
CONCERN AND PERFORMED REMOVED AND REPLACE SEAT BELT BUCKLE  
ADMP PART ORDERED  
RESAMPLE CUSTOMER CONCERN REMOVE OLD BELT BUCKLE AND  
INSTALLED NEW ONE AND OK OPERATION GOOD  
2229 48 IN J J REPLACE CENTER BUCKLE ASY.  
1246 48 IN J J REPLACE BUCKLE  
CHECK AND REPLACE RF SEATBELT BUCKLE PER RECALL

REPLACED DRIVERS SIDE SEATBELT BUCKLE  
REPLACED L.F. SEAT BELT LATCH DE  
BY SEAT BELT RECALL. I INSPECTED BOTH SEAT BELTS DRIVER FAILED.  
REPLACED DRIVERS SIDE BELT  
REPLACED SEAT BELT BUCKLE  
SAFETY BELT CHIRPS INTERMITTENT REPLACED DRIVERS SIDE SAFETY  
BELT BUCKLE ASSEMBLY  
REPLACED DRIVERS SIDE SEATBELT BUCKLE  
COMPLETE RECALL.

48 REPL PASS SIDE SEATBELT BUCKLE  
11134 CHECK AND CONFIRM ORDER SEAT BELT ASY. INSTALLED NEW  
SEAT BELT BUCKLE. TESTED ALL OK.  
2244 REPLACE PASS SIDE SEAT BELT ASY. REMOVE SEAT TO ACCESS  
ANCHOR BOLT INSTALL AND TEST OK  
15269 REMOVED CENTER CONSOLE REMOVED DRIVER SIDE BUCKLE PART  
THAT ON ORDER WAS SW. INSTALLED RECALL BUCKLE WE HAD IN STOCK  
WAS ON RECALL. UPDATED BUCKLE WAS 1IN LONGER SHORTENED WIRE  
AND PARTS T

ED OK

UND RESISTANCE AIR. AS4  
ASS FOUND INTERNAL  
CONCERN PCM MODULE  
REPLACED MODULE AND  
RETEST SYSTEM REPLACED  
DRY SEAT BELT BUCKLE OPEN  
RESISTANCE. RETEST SYSTEM  
CHECK PASS. ON DEMAND

11876 48 W 142821, 1001289 VARIED AIR 8/8 18 FLAMING. NGA  
RETRIEVED BY 821, 81076, 81096 CHARGE ON DEMAND BELT TEST PCM  
MODULE 81081, 81126, 81088. PINPOINT TESTS AIR, ASS DEACTIVATE  
BRACKET QPC  
STICKING SEAT BELT BUCKLE REPLACE

REPLACE THE DRIVERS SIDE SEATBELT BUCKLE

RECALL INSPECT AND REPLACED TWO SEAT BELT BUCKLES.  
REPLACE SEATBELT BUCKLE BINDING  
44445 ORDERED SEAT BELT BUCKLE REMOVED OLD SEAT BELT AND  
INSTALLED NEW. TIMBER AND FOUND GOOD.  
SEAT BELTS WONT LATCH REPLACE SEAT BELTS  
REMOVED DRIVERS SIDE SEAT BELT LATCH FOR HARD TO  
UNLATCH  
REPLACE REAR BELT BUCKLE PASSENGER SIDE.  
COMPLETE RECALL

REPLACED DRIVERS SEAT BELT DUE TO BUCKLE COMING OUT AT TIMES  
COMPLETE RECALL

NOT WORKING PROPERLY SEATBELT ASSEMBLY FRONT REPLACE

X	Other	DRY SEAT BELT WARNING LIGHT KEEPS COMING ON AND FLASHING, EVEN WHEN SEAT BELT FASTENED	214
X	Other	SEAT BELT BUCKLE IS NOT LATCHING PROPERLY	802
K	Other	CUSTOMER STATES BELT CHIRPS WHEN POUND OFF HAS SEAT BELT BUCKLE ORDERED LEFT SIDE	302
A	Wont Latch	PASSENGER SEAT SIDE SEAT BELT WILL NOT CATCH IN BUCKLE	281
X	Other	(828) CUST. STATES PASS. SIDE SEAT BELT INOP.	559
X	Other	PASSENGER FRONT RIGHT SEAT BELT NOT WORKING (840)	403
X	Other	INSTALL BOP MIDDLE FRONT SEAT BELT BUCKLE	872
X	Other	PASSENGER SEAT BELT FEMALE PORTION ...FRASH DONE	572
R	Recall Performed	RECALL 01821 SEATBELT INSPECT SEATBELT SENSOR HAS BEEN DISCONNECTED. PLEASE OK TO SEE IF PART IS NOW IN	628
X	Other	DRIVERS SEAT BELT INOP	686
X	Other	DRIVERS SEAT BELT INOP	308
R	Recall Performed	SEAT BELT INSPECTION	427
X	Other	SEAT BELT BUCKLE INOP	428
X	Other	OK SEAT BELT LAMP, & CHIRPS GO ON INTERMITTENT CLOSED BY WPI	416
X	Other	SEATBELT CHIRPS GOING OFF	809
R	Recall Performed	RECALL 01821 ALL OK	318
A	Wont Latch	PASS SEAT BELT BUCKLE DOES NOT LATCH	913
X	Other	CUSTOMER STATES CENTER SEAT BELT DOESNT LATCH CUSTOMER STATES THAT THE PASSENGER SIDE FRONT SEAT BELT BUCKLE BUTTON IS HARD TO RELEASE	608
X	Other	BUCKLE BUTTON IS HARD TO RELEASE	308
A	Wont Latch	DRIVERS SEAT BELT WONT BUCKLE	612
X	Other	CUSTOMER STATES THAT THE AIRBAG LIGHT IS ON	322
X	Other	SEAT BELT LATCH STICKS	960
X	Other	DRIVERS SEATBELT BUCKLE WILL NOT STOP BUZZING EVEN WITH BELT ON/IN DRV SEATBE	780
R	Recall Performed	RECALL 01821 SAFETY RECALL SEAT BELT BUCKLES	390
X	Other	SEATBELT BUCKLE HARD TO UNLATCH	383
X	Other	SEE CUSTOMER STATES MIDDLE CENTER SEATBELT UNABLE TO LATCH	653
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
X	Other	LEFT SEAT BELT HARD TO RELEASE	417
X	Other	818 CUST STATES FRONT REAR SEAT BELT WONT LATCH INSTALL BOP	808
R	Recall Performed	RECALL 01821 ALL OK	216
O	Unlatch/Release	DR DRG SEAT BELT STICKY AND POPS OUT AT TIMES	713
R	Recall Performed	RECALL 01821 ALL OK	216
A	Wont Latch	DRIVERS FRONT SEAT BELT NOT HOLDING DIDNOT HAVE RECALL LISTED ON CASE	806

TYPE STICKING 61178AN A JN REPLACED R F SEATBELT BUCKLE  
PASSENGER SIDE SEAT BELT FAILED, REPLACED SEAT BELT  
DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT  
REPLACE  
1841 REMOVED PASSENGER SEAT AND INSTALLED INSURING SEAT BELT.  
REINSTALLED SEAT AND TESTED ALL OK CMO TECH SA  
FOUND L FRY SEAT BELT PRETENSIONER REPLACED BUCKLE  
FR BELT ASSEMBLY  
REPLACE SEAT BELT BUCKLE

REPLACED FRONT SEATBELT ASSY  
INSPECTED AND REPLACED FAILED RF SEAT BELT BUCKLE.  
SEAT BELTS WONT LATCH REPLACE SEAT BELTS  
BUCKLE WILL NOT LATCH REPLACED CENTER SEAT BELT BUCKLE  
DIE DIAG,FRONT,REPLACED BUCKLE ASSY AND INSTRT  
BT REPLACE BUCKLE  
8181B 08181B  
RAN TESTS ON SYSTEM AND FOUND THE BUCKLE BAD ORDERED A NEW  
BUCKLE WE WILL CALL WHEN THE PART COMES IN REPLACED  
THE SEAT BELT BUCKLE OK NOW  
CHECK AND R AND R THE LF SEAT BELT BUCKLE ASSY

CHECK AND DIAG CONCERN REPL F SEATBELT ASSY RECHECK OK NOW

INSPECT TEST AND MONITOR AND REPLACE BUCKLE ASSY AND RETEST  
10966 FRM AND RFP SEAT BELT BUCKLE  
SEAT BELT SEAT BELT ASSEMBLY REAR RIGHT OR LEFT  
REPLACE  
CHECK AND REPLACE BELT STICKERS

0248 DOES NOT OPERATE PROPERLY MILLS IN 1788 MILES OUT 1707 TEST  
FRONT CENTER SEATBELT BUCKLE OPERATION FOUND BUCKLE WOULD  
NOT EXCEPT THE SEATBELT INSPECT INSPECTED BUCKLE FOR  
REPLACED SEAT BELT BUCKLES  
COMPLETE RECALL

MT: TIME TO REPAIR SEAT BELT BUCKLES ON SEATL  
RECALL 61861  
1 REPLACED DRV BUCKLE  
INSPECTED AND DOES NOT LATCH, REPLACED PASSENGER SIDE SEAT  
BELT BUCKLE AND PRETESTED OK  
BUCKLE WILL NOT LATCH. REPLACED PASSENGER SIDE SEAT BELT  
BUCKLE  
COMPLETE RECALL  
OK OUT REPLACE BUCKLE  
OK OUT REPLACE BAD LATCH ASSY  
OK OUT REPLACE BAD SEAT BELT  
REPLACED DRIVER SIDE SEAT BELT BUCKLE

DIAG SEN MODULE FR FRONT SYSTEM FAME (212 0248) MON FOR BUCKLE  
FR IS NOT SEATBELT REPLACE L F SEAT BELT BUCKLE SHOP  
28 OPEN CIRCUIT. DIAGNOSIS TERMED WITH WDR ON SEAT BELTS AND  
CIRCUIT. SEPT TESTS. DTG ON DRIVER SIDE BELT CIRCUIT. OPEN AT  
TIMER

REPLACE SEAT BELT BODY CHASSIS ELECTRICAL (ECC) TEST  
18 REPLACED 60 SEAT BELT BUCKLE DO SMC

28 RPL DRIVERS SEATBELT BUCKLE FOR OPEN RETEST

X	Other	RIGHT FRONT SEAT BELT IS STICKING	606
X	Other	PASSENGER SIDE SEAT BELT FAILED (INSTALL 60P)	606
A	Wont Latch	RT FRT SEAT BELT WONT LATCH WF 846 CUSTOMER STATES THE SEAT BELT BUCKLE IS MISSING ON THE PASS SIDE INSTALL SPECIAL ORDER PART	606
X	Other	SEAT BELTS WILL NOT LATCH PROPERLY	408
X	Other	AIR BAG LIGHT ON	
X	Other	RF SEATBELT WOP BUCKLE JAMMED	
R	Recall Performed	SEAT BELT BUCKLE SHOP	409
R	Recall Performed	SEAT BELT PARTS ARE IN SEAT BELT RECALL OR WHEN B BELT IS BAD	303
R	Recall Performed	81821 RECALL CUSTOMER STATES PERFORM RECALL	310
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	310
X	Other	CENTER SEAT BELT WILL NOT BUCKLE	318
X	Other	SEATBELT CHIME KEEPS GOING OFF	718
A	Wont Latch	LEFT FRT SEAT BELT WONT LATCH	818
R	Recall Performed	CK FOR SEAT BELT WONT HOLD	648
X	Other	SEAT BELT BINDER GOES OFF EVEN WHEN BELT IS BUCKLED WILL GO OFF IF YOU BOUNCE ON THE SEAT	608
X	Other	LEFT SIDE SEAT BELT BUCKLE S O PART CUSTOMER STATES THAT THE SEAT BELT CHIMES WILL NOT SHUT OFF INTERIOR LIGHTS WILL NOT GO OFF	717
X	Other	CURT STATES SEAT BELT SIGNAL IN DASH WILL NOT GO OFF CHIME KEEPS SOUNDING	757
X	Other	QQQ CHECK FOR PASSENGERS FRY BUCKLE	287
C	Unlatched/Release	D S SEAT BELT DRENCHAGES	818
X	Other	CURT STATES DRIVERS SIDE SEATBELT BUCKLE JAMMED	814
X	Other		862
X	Other	CUST STATES FRONT MIDDLE SEAT BELT WILL NOT STAY LATCHED	881
X	Other	SEAT BELT BUCKLES NOT WORKING PROPERLY	281
R	Recall Performed	RECALL 01821 ALL O.K. CK SEAT BELT BUCKLE WILL LATCH BUT UNLATCHES WHEN BELT IS PULLED ON	816
C	Unlatched/Release	RECALL 01821	917
R	Recall Performed	SEAT BELT BUCKLE 60P IN	808
X	Other		882
X	Other	CUSTOMER STATES THE FRONT MIDDLE SEAT BELT DOES NOT CLASP	308
A	Wont Latch	CUSTOMER STATES THE PASS FRONT SEAT BELT WONT LATCH	308
R	Recall Performed	RECALL 01821 ALL OK	218
A	Wont Latch	CENTER SEAT BELT NOT LATCH	701
X	Other	REPAIR SEAT BELT NOT WORKING	701
X	Other	SEAT BELT CENTER WILL NOT WORK	701
B	Wont Stay Latched	DRIVERS SEATBELT BUCKLE DOESNT STAY LATCHED	813
X	Other	C B WITH BOTH SEAT BELTS ON THE CHIME AND LIGHT STAY ON INTERMITTENTLY	888
B	Wont Stay Latched	CUSTOMER STATES THAT DRIVERS SEAT BELT WONT STAY BUCKLED CHECK AND ADVISE	608
X	Other	SEAT BELT WARNING LIGHT STAYS ON	858
X	Other	L F SEATBELT LOOSE	818
X	Other	CUST STATES SEATBELT LITE NOT RESPONDING WHEN LATCHED	713

SEAT BELT CHIME STAYS ON ALL THE TIME WARN CODE TECH 188212  
MESSAGE OUT 11880 TEST WITH NISSA KODEN CODES MONITOR FIND  
FOUND DRIVERS SEAT BELT ON SHOWING LATCHED REPLACE DRIVERS  
SEAT BELT BUCKLE HERE

QT

X

Other

CUSTOMER STATES SEAT BELT CHIME HAPPENS ALL THE TIME WHILE DRIVING  
AFTER IN DRIVING SEE JAMES HE SPOKE TO CUSTOMER

770

8882 REMOVE REAR SEAT, REPLACE THE SEAT BELT BUCKLES REMOVE  
FRONT SEATS AND TURN TO THE SIDE, REPLACE BOTH FRONT SEAT BELT  
BUCKLES. FRONT REAR BUCKLE WAS BROKE AND THE REAR WERE STICKY

X

Other

CHECK REAR FEMALE SEATBELT ENDS. ALL HAVE BEEN MESSING UP, ONE  
IS JAMMED COMPLETELY.  
CUSTOMER STATES THE RIGHT FRONT SEAT BELT WILL NOT LATCH. OK AND  
ADVISE

701

USED M TIME TO REPLACE RH FMT BUCKLS. RETEST OK AFTER REPAIR

A

Wont Latch

REPOSITION SEAT BELT

802

FOUND SEATBELT TWISTED FROM FACTORY REINSTALLED CORRECTLY  
REPLACED SEAT BELT

X

Other

CUSTOMER STATES MIDDLE SEATBELT INOPERATIVE

301

X

Other

8888 REPLACED SEAT BELT BUCKLE DRIVERS FRONT ALL GOOD. 7861289

X

Other

CHECK DRIVERS SEATBELT INOPERATIVE NOT WORKING PROPERLY  
W/ BAY INSTALL SOP DRIVERS SEAT BELT BUCKLE COMES OPEN WHILE  
DRIVING

403

Unlocks While

8725 REPLACED DRIVERS SEATBELT PER PBA LABOR OF 008129 0 0 HRS  
INCP REPLACE ONE SEAT BELT

D

Chang

SEAT BELT BUCKLE DOES NOT WORK

408

SEAT BELT REPLACEABLE PASSENGER SEATBELT WONT STAY LATCHED CO 48  
REPLACED PASSENGER SEAT BELT

X

Other

PASSENGER SEAT BELT WONT STAY LATCHED CO 810  
SEAT BELT WARNING LIGHT STAYS ON AND ALARM SOUNDS EVEN  
WHEN BELT IS BUCKLED AT TIMES

702

CHECKED BUCKLES DID OK. TIGHT NISSAN DRIVERS FRONT SEAT  
BUCKLES REPLACED THE BUCKLE OK NOW

X

Other

RIGHT SIDE BUCKLE NOT LOCKING M TIME TO REPLACE RIGHT SIDE  
BUCKLE ASSEMBLY

A

Wont Latch

REPAIR FOR RIGHT SIDE BUCKLE FAILURE

TRM EM

880

PLN WDS, PID MONITOR, DRIVERS SEATBELT NOT CORRESPONDING WITH  
ACTION (W/BA. REASONE DRIVERS SEAT TO CHECK CONNECTIONS, GOOD.  
WDS TO CHECK SEATBELT MODULE ACTION, GOOD. COMPONENT TEST  
SEATBELT FAILED R

REPLACED DRIVERS SEATBELT  
BUCKLE, OK AT THE TIME.

X

Other

SEAT BELT LITE COMES ON AT TIMES

896

REPLACED SEAT BELT WITH NEW

A

Wont Latch

SEAT BELT WILL NOT LATCH

817

REPLACED R SIDE SEAT

BUCKLE

R

Recall Performed

01821 SEAT BELT BUCKLE

770

WDS TO REPLACE BOTH TO CORRECT

X

Other

CUSTOMER STATES SEAT BELTS INCP  
DRIVERS SEAT BELT NOT LATCHING

358

R & L LEFT FRONT SEAT & REPLACE BELT BUCKLE

A

Wont Latch

VERIFY CONCERN PASSENGER SIDE BUCKLE WONT LATCH REPLACED  
BUCKLE BUCKET SEAT TYPE WITH BR VERIFY REPAIR OK THIS TIME  
NOT OPERATING PROPERLY SEATBELT ASSEMBLY FRONT  
REPLACED FRONT

A

Wont Latch

RIGHT FRONT SEAT BELT BUCKLE DOES NOT LOCK

958

0081 REPLACE SEAT BELT BUCKLE WAS BROKEN WORKS OK  
REINSTALLED SEAT BELT WILL NOT STAY BUCKLED  
M TIME TO REPLACE BUCKLE ASSEMBLY  
REPLACE RIGHT SEAT BELT BUCKLE

A

Wont Latch

SEE CUSTOMER STATES THE DRIVERS SEATBELT BUCKLE WONT LATCHED.

883

SUSPECTED DRIVERS SEAT BELT, CONNECTION IS BROKEN. REPLACED  
SEAT BELT AND BUCKLE ASSEMBLY. RE TESTED, OK. WITHIN 2000 TIME  
TO REPLACE DRIVERS SEAT BELT AND BUCKLE ASSEMBLY, NO LABOR CHG  
APPL.

B

Wont Stay Latched

DRIVERS SEAT BELT WONT STAY BUCKLED

794

CHECKED AND REPLACED LEFT FRONT SEATBELT BUCKLE TO CORRECT  
CONCERN.

A

Wont Latch

CUSTOMER STATES DRIVERS SEAT BELT INCP. WILL NOT FIT INTO LATCH

781

REPLACE SUPER CREW BUCKET SEAT BUCKLE INCP

X

Other

DRIVERS SEATBELT IS BROKEN

786

REPLACE SEATBELT

X

Other

DRIVERS SEATBELT IS BROKEN

830

888A TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE  
PERFORMED RECALL 01821 REPLACED BOTH FRONT SEAT BELT BUCKLES  
OUT MESSAGE 8404

X

Other

CHECK LEFT FRONT SEATBELT BUCKLE

818

VERIFY CONCERN CHIME WENT ON WITH BUCKLE HOOKED CIRCULAR TEST  
SEAT BELT WARNING SYSTEM REPLACE DRIVER SEAT BELT BUCKLE OPEN  
CIRCUIT IN BUCKLE WARNING

B

Wont Stay Latched

SEAT BELT DRIVERS SIDE FAILED WONT STAY LATCHED

281

CHECK AND REPLACE LEFT FRONT SEATBELT

X

Other

REPLACE SOP SEAT BELT

816

888A TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE  
PERFORMED RECALL 01821 REPLACED BOTH FRONT SEAT BELT BUCKLES  
OUT MESSAGE 8404

A

Wont Latch

CUSTOMER STATES PASSENGER SEAT BELT WONT LATCH. OCLDR CODE  
KH MANUAL BUCKET SEAT.

719

888A TIME TO REPLACE RIGHT FRONT SEAT BELT BUCKLE  
PERFORMED RECALL 01821 REPLACED BOTH FRONT SEAT BELT BUCKLES  
OUT MESSAGE 8404

R

Recall Performed

RECALL 01821 SEAT BELT BUCKLE

884

VERIFY CONCERN CHIME WENT ON WITH BUCKLE HOOKED CIRCULAR TEST  
SEAT BELT WARNING SYSTEM REPLACE DRIVER SEAT BELT BUCKLE OPEN  
CIRCUIT IN BUCKLE WARNING

K

Other

WHEN USING SEATBELT THE SEATBELT WARNING CHIME WILL COME ON  
THEN SO OFF CHIM OUT

806

K

Other

LEFT FRONT SEATBELT DOES NOT LATCH PROPERLY

808

30000 VERIFIED PASS FRONT SEAT BELT RECEIVER IS INOP, REPLACED  
PASS SEAT BELT RECEIVER (80 00) ALL FUNCTIONS NORMAL. REPAIR  
SUBMISSION DELAYED DUE TO PARTS NOT AVAIL. REPAIR COMPLETED 4 13  
88 AT 20088 JB

REPLACED SEAT BELT WITH NEW  
NHS BSE TEST NO COORS MONITORING PICB FOUND DRIVERS BELT  
BUCKLE STRUCK OPEN AND NOT WORKING PROPERLY FAR BUCKLE  
TESTED OPERATION GOOD  
CHECKED COORS, NONE IN RESTRAINT SYSTEM LIGHT FLASHES WITH  
BELT BUOKLS.0. CHECKED PICB, ORDERED LEFT SEAT BELT LATCH ASSY  
REPLACED LATCH ASSY WHEN PARTS CAME IN.

SEAT BELT RELEASE SWINGING SEATBELT ASSEMBLY FRONT REPLACE

PRINT TEST PER MANUAL, FOUND BUCKLE BAD RHL BUCKLE AND REPLACE  
REPLACE SEAT BELT RELEASE ON RIGHT SIDE  
RIGHT FRONT SEAT BELT BUCKLE SWINGING. REPLACE, RETEST. OK  
JUNE 4488 PL 01178A J 120070 J 001 J 01 J 000 SYSTEM TESTS, KOEC  
51428, 01480, KOEC 04488 DCI. DISPLAY, RECORD & MONITOR PIDL  
PERFORM PINPOINT TESTS & ACTIVE COMMAND TESTS, REPLACED  
DRIVERS SID

REPLACED THE RIGHT SIDE SEATBELT BUCKLE THAT DOES NOT LATCH  
REMOVE SEAT BELTS FROM THE STOCK UNIT TO LINE TO REPAIR A  
CUSTOMERS VEHICLE AND REINSTALL BACK IN THIS UNIT  
REPLACED RIGHT SIDE SEATBELT BUCKLE

SEATBELT LOCKS UP WHEN TRAVELING, REPLACED SEATBELT  
SWINGING COMPLETED INSTALL OF SEAT BELT PASSENGER SIDE

1 REPLACED SEATBELT

RH SEAT BELT ASSY AND REPAIR  
018010 04070

LFT RHT SEATBELT SWINGING REPLACED SEATBELT ASSY.  
RECALL 01801 COMPLETED  
TRIM PIECE THAT IS AROUND BELT ON PASS SIDE IS NOT ON DRIVERS SIDE  
THAT IS NORMAL CHECKED OTHER VEHICLES  
10000 DR SEATBELT LOCK BROKEN DANG SEATBELT BUCKLE  
INOP, INPL DRIVEN SEATBELT LOCK ASSY, RETESTED OK  
INSPECTED AND TESTED SEAT BELT BUCKLES PER RECALL. REPLACED  
LEFT SEAT BELT BUCKLE PER RECALL.  
REPAIRED AND REPLACED SCREEN.  
REPLACE FRONT CENTER SEAT BELT.

SEAT BELT RECALL REPLACED LEFT SEAT BELT BUCKLE  
COMPLERE RECALL  
30000 WARR CHECK FOR LEFT SEAT BUCKLE WON T LOCK FAR AND  
REPLACE LEFT SEAT BELT BUCKLE REWORK OK  
REPLACE SEAT BELT BUCKLE AND LAP STRAP.  
HAD TO REPLACE BOTH RHT SEAT BELTS TO FIX 40  
0000 LOOK FULL TRUCK SEAT TO REPLACE DRIVERS SEAT BUCKLE TEST  
OK -QUALITY CONTROL BY TIM HUSCHMAN  
DIAGNOSED AND REWORKED FRONT FRONT SEAT BELT COVER AND  
UNWRISTED SEAT BELT, REWORKED AND VERIFIED SEAT BELT NOW  
RETRACTING  
PCM BODY CHASSIS ELECTRICAL (BOS) TEST

LEB	X	Other	O B PASS FRONT SEATBELT INOP, INSTALL SOP FROM ROMBERG	480
	A	Won't Latch	SEAT BELT WILL NOT LATCH	817
	X	Other	DR SEAT BELT CHIMES WILL NOT STOP WITH BELT ON	602
	X	Other	SEATBELT WARNING INDICATOR WILL COME ON WHILE DRIVING, DOES NOT SEEM TO COME ON WHEN BELT IS UNHOOK	618
	A	Won't Latch	SEAT BELT RELEASE NOT HOLDING ON CUSTOMER SEATED EVEN WITH SEAT BELT LOCKED THE CHIME STILL SOUNDS FOR SEVERAL MINUTES ON ADVISE 00 840	970
	X	Other	CHECK PASSENGER SIDE BELT WONT SHRAME	778
	A	Won't Latch	C S PASS PRT SEAT BELT BUCKLE INOP	706
	X	Other		805
E BUCKLE ASSY.	X	Other	WHILE DRIVING, WITH SEATBELT FASTEN, ROUNDER CHIME SUNDARY TUNE	300
	X	Other	REPLACE DEFECTIVE SEAT BELT	797
	A	Won't Latch	THE RIGHT SEATBELT DOES NOT LATCH REMOVE SEAT BELT FROM THIS UNIT TO LINE TO REPAIR CUSTOMERS VEHICLE, 0000 NO 01800	600
	X	Other	PASSENGERS SEATBELT BUCKLE WILL NOT STAY LATCHED	808
	B	Won't Stay Latched	CUSTOMER STATES WHEN TRAVELING DOWN THE STREET, PASSENGER SIDE FRONT SEATBELT LOCKS UP ON ITS OWN. SOP	397
	X	Other	CUSTOMER STATES PASSENGER SIDE SEAT BELT INOP	680
	X	Other	CUSTOMER STATES THE RIGHT FRONT SEAT BELT IS LOCKING UP. SOP IS IN	803
	X	Other		817
	X	Other		380
	X	Other	PASS SEAT BELT LATCH ON WRONG SIDE	878
	R	Recall Performed	OK FOR SEAT BELT WONT HOLD	645
	A	Won't Latch	CUSTOMER STATES THAT DR SIDE FRONT SEAT BELT WILL NOT BUCKLE.	210
	R	Recall Performed	RECALL 01801 ALL OK	216
	X	Other	CUSTOMER STATES THERE IS A TRIM PIECE MISSING OFF OF DRIVERS SIDE SEAT BELT	613
	A	Won't Latch	DIAG DR SEAT BELT NOT LOCKING INTO PLACE	306
	R	Recall Performed	PERFORM RECALL 01801 LFTY BUCKLE FAILED, RIGHT PASSED	208
	X	Other	RHT RHT SEAT BELT NOT SCREWED IN GOOD AT TOP	751
	X	Other	CUST STATES SEAT BELT ON FRONT SEAT IS FUSED IN MIDDLE	328
	R	Recall Performed	PERFORM RECALL 01801 LEFT BUCKLE FAILED, RIGHT BUCKLE PASSED	209
	R	Recall Performed	RECALL 01801 ALL OK	218
	A	Won't Latch	CUSTOMER STATES LT SEAT BELT BUCKLE WILL NOT HOLD	418
	A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH	751
	A	Won't Latch	SEAT BELT PASS SIDE NOT LOCKING IN 840	388
	D	Unlatches While Driving	SEAT BELT BUCKLE COMES UNSBUCKLED WHILE DRIVING AT TIMES	517
	X	Other	CUSTOMER COMPLAINS THAT THE PASSENGER SIDE FRONT SEATBELT WONT RETRACT.	217
	X	Other	SEAT BELT BUZZER WONT GO OFF	848

CHECKED OPERATION. REMOVED THE SEAT TO ACCESS & REPLACED A SPRING SEATBELT.

TRUCK 101 VERIFIED CONDITION. REPLACED RIGHT FRONT SEAT BELT BUCKLE AND RETESTED SEAT BELT OPERATION PROPERLY AT THIS TIME. INOP REPLACE BELT. PASS SIDE SEAT BELT DOESN'T HOLD. TESTED THE SEAT BELTS, REPLACED THE DRIVERS SIDE SEAT BELT BUCKLE SIDE.

1. REPLACED BOTH SEAT BELTS. WORKING GREAT. PROPERLY AND REPLACE DRIVERS SIDE SEATBELT BUCKLE ASSY. WILL NOT HOLD. BELT IN PLACE AT TIME NO LAB OP IN BELTS TO REPLACE BUCKLE ASSY. INSTALL SPO PART. INSTALLED SEATBELT BUCKLE.

NECESSARY TO REPLACE FRONT SIDE SEAT BELT BUCKLE NOT LATCHING PROPERLY. REPLACE BOTH FRONT BELT BUCKLES. AT TIME FOR REPAIR NO OPERATIONS AVAILABLE. STICKS BRASS OR BRASS. TESTED SEAT BELT BUCKLE AND FOUND THAT PASSENGER SIDE IS ENDING INTERNALLY R AND R. PASSENGER SIDE SEAT BELT.

REPLACE LEFT AND RIGHT SEAT BELT BUCKLES. DO NOT REPLACE RIGHT SEAT BELT BUCKLE. DIAG. FOR RIGHT FRONT SEAT BELT TO REPAIR. REPLACE DRIVERS SEAT BELT. INSTALLED DRIVER SIDE FRONT SEAT BELT, IT WAS MISSING.

VERIFIED THAT DRIVERS SEAT BELT BUCKLE WOULD NOT LATCH. REMOVED DRIVERS SEAT AND REPAIR AND REPLACED DRIVERS SEAT BELT BUCKLE. REINSTALLED DRIVERS SEAT AND CHECKED OPERATION OF NEW BUCKLE.

INSTALL DEFECTIVE SEAT BELT BUCKLE. TRUCK VERIFIED CONCERN. ACCESS DRIVERS SEAT, REMOVE AND REPLACE SEAT BELT. OK AT THIS TIME.

HAD TO INSTALL SEAT BELT ASSEMBLIES. AT TIME TO CHECK SEAT BELT OPERATION AND TO REPLACE BOTH BELTS. REPLACE LEFT SEAT BELT BUCKLE ASSEMBLY. REPLACE SEATBELT AND NOW OPERATION OK. REMOVED PASSENGER SIDE SEAT AND REPLACED BUCKLE, RECHECK OPERATION.

IS SEAT BELT REG. 1.1 INSPECTED BOTH SEAT BELTS. PASS FAILED. REPLACED PASS SEAT BELT.

RF SEATBELT BUCKLE STICKS FOUND DURING POSSIBLE BUR IN BUCKLE. REMOVE RF SEAT TO GAIN ACCESS TO RF SEAT BELT BUCKLE. REPLACE BUCKLE. RECHECK NORMAL LATCH OPERATION.

14797 LEFT FRONT SEAT BELT BUCKLE NOT LATCHING. CODE 42 CHECK SEAT BELT BUCKLES. FOUND LEFT FRONT NOT LATCHING. REMOVE LEFT FRONT SEAT. REMOVE RF SIDE SEAT TRACK. REMOVE BUCKLE. REINSTALL NEW BUCKLES. INSTALL TRACK AND REINSTALL SEAT AT TIME REQUIRED NO PUBLISHED OP FOR REPAIR.

REPLACED SEAT BELT BUCKLE...

REPLACED SEAT BELT FOR BRK HAZARD. 22000 REMOVE L F POWER SEAT TO GAIN ACCESS. REPLACE S D BUCKLE AS NEEDED. REINSTALL SEAT.

REPLACED DRIVERS SEATBELT ASSEMBLY. HAD TO REMOVE DRIVERS SEAT FOR ACCESS. REASSEMBLED AND RECHECKED OPERATION. OK. 1. VERIFY CONCERN. CHECK BUCKLE FOR OBSTRUCTIONS. NOW. REMOVE SEAT AND REPLACE BUCKLE AND REINSTALL SEAT. 10000 DRIVER SEAT BELT WILL NOT LATCH. REPLACE DRIVER SIDE SEAT BELT BUCKLE AND RETEST OK.

X	Other	CURT STATES SEATBELT MISSING.	833
X	Other	OK FOR RIGHT FRONT SEAT BELT LATCH INOP	724
A	Wor'n Latch	PASS SEAT BELT INOP	819
B	Wor'n Latch	SHL. THE DRIVERS SIDE SEAT BELT WILL NOT SATY BUCKLED	863
X	Other	SEAT BELT NOT WORKING CORRECTLY	828
A	Wor'n Latch	DRIVERS SEATBELT WON'T LATCH	780
X	Other	FACTORY WARRANTY SPO INSTALL. NO. 813488	806
X	Other	CHECK AND ADVISE ON PASS SIDE SEAT BELT INOP NECESSARY TO TEST SEAT BELT BUCKLES AND RESTRAINT SYSTEMS	808
X	Other	SEE BUCKLES NOT OPERATING PROPERLY	210
X	Other	BASE. CUSTOMER STATES PASSENGER SIDE SEAT BELT IS INOP 840	830
X	Other	CURT STATES SEATBELT INOP	828
X	Other	PASSENGER SIDE SEAT BUCKLE WILL NOT LATCH PROPERLY	818
X	Other	RIGHT FRONT SEAT BELT INOPERATIVE.	880
X	Other	CURT STATES THAT THE DRIVERS SEAT BELT IS MISSING CHECK AND CORRECT. SEE BOB IN PART 07	801
A	Wor'n Latch	DRIVER SEAT BELT IS INOP	408
X	Other	INSTALL SPECIAL ORDER SEAT BELT BUCKLE PARTS IN	862
A	Wor'n Latch	CURT STS THE DRIVERS SEAT BELT WILL NOT LATCH	828
X	Other	SEAT BELT NOT RETRACTING	788
X	Other	DRIVERS SEAT BELT INOP	803
A	Wor'n Latch	DRIVER SIDE SEATBELT WON'T LATCH.	808
A	Wor'n Latch	PASSENGER SIDE SEAT BELT BUCKLE WILL NOT HOLD	717
R	Repair Performed	SEAT BELT INSPECTION	807
X	Other	CUSTOMER CONCERN THAT THE PASS SIDE FRONT SEAT BELT STICKS IT WILL NOT RELEASE	807
A	Wor'n Latch	SHL REPAIR FRT SEAT BELTS WILL NOT LATCH CHECK. REARS PLEASE	780
D	Unlatched While Driving	REPAIRS SEAT BELT WILL COME UNLATCHED AS DRIVING	818
X	Other	CURT STATES SEAT BELT FAILED	828
X	Other	INSTALL SPO SEATBELT IT WAS BROKEN WE NOTICED ON THE LAST VISIT	788
A	Wor'n Latch	CUSTOMER REPORTS DRIVERS SEAT BELT WILL NOT LATCH.	380
A	Wor'n Latch	RIGHT FRONT SEAT BELT DOES NOT LATCH	
A	Wor'n Latch	DRIVERS SEAT SEAT BELT WILL NOT LATCH	881

FAILED BUCKLE ASBY PASS FRT REPLACED FAILED PASS FRT SEAT BELT BUCKLE ASSEMBLY, RETEST OK NOW

REPL PASS SIDE FRONT SEAT BELT BUCKLE NOT LATCHING AT TIMES  
 15YR PASSENGER SIDE SEAT BELT WILL NOT LATCH. REPLACED WORKS  
 NOW.  
 INSPECT FRONT SEAT BELT BUCKLES HARD TO CLIP & HOLD REPLACE  
 BOTH BUCKLES  
 VERIFIED CONCERN. FOUND BUCKLE INOP. REMOVED SEAT TO ACCESS  
 AND REPLACED ORDERED BELT BUCKLE VERIFIED REPAIR.  
 RECALL PERFORM RECALL

INOP REPLACED DRIVERS SEATBELT BUCKLE  
 REMOVE SEAT BELT AND REINSTALL NEW ONE  
 TRUCKLE END OF SEAT BELT BAD SEATBELT ASSEMBLY FRONT  
 REPLACE

X REPLACED BUCKLE ASBY WOULD NOT LATCH  
 C001 REPLACED FRONT FRONT SEAT BELT BUCKLE INT TRIM SE BUCKET  
 SEATS GRAY

TRIM ACCESS THE REAR SEAT AND REPLACED THE REAR C/P LLAR. R/R  
 FRONT PASS SIDE SEAT AND REPLACED THE OBSOLETE SEAT BELT  
 BUCKLE

REMOVE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH REINSTALL  
 NEW BUCKLE ASBY CHECK OPERATION OK ME NO PUBLISHED LABEL  
 OPERATION FOR THIS REPAIR  
 REPLACED SEATBELT ASBY  
 INSPECT AND REPLACED R BUCKLE FAILED L BUCKLE OK PASSED.

SE HAD TO ORDER LF SEAT BELT STOCK  
 REPLACE SEATBELT WILL NOT LATCH PROPERLY  
 TESTED BOTH FRONT SEAT BELTS DRIVERS SEAT RECEIVER FAILED R/R  
 SEAT BELT RECEIVER  
 TECH INSPECTED AND REPLACED DRIVER SIDE SEATBELT DUE TO DEFECT  
 WAS INOPERATIVE  
 REPLACE SEATBELT, FAILED CHECK DONE SAME AS FOR RECALL  
 STORMS DRIVERS SEATBELT BUCKLE REPLACED DRIVERS SEATBELT  
 BUCKLE TO REPAIR.

VERIFIED RR FRONT LR SEAT BELT BUCKLES, NOW OPS NORM  
 DISMANTLE ET REPLACER BUCKLE ALWAY DROPT NG BUCKLE  
 SEATBELT SURROUND FALL OFF SEATBELT ASSEMBLY FRONT  
 REPLACE

REPLACE BELT REMOVE SEAT FOR ACCESS  
 DRIVERS FRONT BUCKLE WAS NOT ACCEPTING THE BUCKLE REMOVED  
 HAD REPLACED THE BUCKLE

SEAT BELT INOP REPLACED SEAT BELT BUCKLE

NT REPLACED DRIVER SIDE SEAT BUCKLE

CONFIRM & REPLACED RIGHT SEATBELT ASSEMBLY

REPLACER CREATURE DEFECT

INSPECTED/REPLACED DRIVERS SIDE SEAT BELT & BUCKLE TEST &  
 RETEST

GROUND ON CNT THE 80 BK BL  
 WIRE BEATS LH REAR D PILLAR  
 TRIM PANEL AND CONTINUE  
 TRACING SHORT FOUND BLAKE  
 CLUSTER TO ACCESS WIRING

INSPECT BYS FOUND BLOWN FUSE ALSO FOUND INTERIOR LIGHTS INOP AS  
 WELL AS KEY CHIME WINDOW AND GAUGES FUSE NUMBERS R236 TO AMP  
 FUSE IN CENTRAL JUNCTION BOX ADDED HEADLAMP TO START  
 TRACING SHORT TO

TO CLUSTER MICRO  
 PROCESSOR CONTINUED  
 TRACING BK BL WIRE R/R/D  
 BEATS AND CRP

A	Wor'n Latch	CURT STATES PASS FRT SEAT BELT NOT BUCKLING	517
	Unlatches While		
D	Driving	CURT STATED PASS SEAT BELT BUCKLE OFF AT TIMES WHEN DRIVING CUST REPORTS PASS SIDE SEATBELT DOES NOT CLICK IN CHECK AND REPORT.	908
A	Wor'n Latch		388
X	Other	CHECK FRONT SEAT BELTS HARD TO CLIP IN	462
A	Wor'n Latch	CUSTOMER STATES PASSENGER SEAT BELT WILL NOT LATCH SOP.	
X	Other	RECALL 01882	328
X	Other	CUSTOMER STATES DRIVERS SEATBELT BUCKLE WILL NOT UNLATCH AT TIMES	388
A	Wor'n Latch	REPAIR LEFT SEAT BELT BUCKLE WILL NOT LATCH	799
A	Wor'n Latch	DRIVERS SEAT BELT WILL NOT LATCH, CUST NEEDS VEHICLE WILL TAKE SOP	527
A	Wor'n Latch	PASSENGER SEAT BELT DOES NOT WORK	527
C	Unlatches/Released	(ASKING) CUSTOMER STATES RR SEAT BELT BUCKLE COMES UNDONE INSTALL SOP	528
X	Other	TRD DRIVERS SIDE C PILLAR PANEL CRACKED PART HIRSELF FRONT SEAT BELT COMES UNDONE WHILE DRIVING PART HERE	528
A	Wor'n Latch	REPAIR LEFT FRT SEAT BELT WILL NOT BUCKLE	780
A	Wor'n Latch	CUST STATES SEAT BELT WILL NOT LATCH	712
X	Other	SEAT BELT INOP	928
A	Wor'n Latch	CUSTOMER STATES THAT THE DRIVER SIDE FRONT SEATBELT INOP, WILL NOT BUCKLE WF	889
X	Other		916
A	Wor'n Latch	DRIVERS SIDE SEAT BELT WON T LATCH	827
X	Other	CUSTOMER STATES NEED ONE SEATBELT REPLACED, RECALL NOT APPLY	787
R	Recall Performed	CHECKED SEATBELT SAME AS FOR RECALL 01882, BELT FAILED	487
A	Wor'n Latch	REPAIR DRIVERS SEAT BELT WILL NOT LATCH	388
X	Other	CR SEAT BELT INOPERATIVE	518
X	Other	VERIFIED CREATURE DE DEFECTIVE ALWAY DROPT NG FUNCTIONAL FAS PLASTIC SEAT BELT SURROUND ARE FALLING OFF SOP IM	418
X	Other	THIS IS THE PASSENGER FRONT SEATBELT. SEE PO 87182	948
A	Wor'n Latch	PASSENGER FRONT SEATBELT WONT HOOK	888
X	Other	CUSTOMER STATES THE DRIVERS SIDE BELT BUCKLE IS JAMMED	978
X	Other	O/S SEAT BELT BUCKLE INOP	907
A	Wor'n Latch	DRIVERS SEAT BELT CONCERN , WILL NOT LATCH. .	841
A	Wor'n Latch	R/R SEATBELT DOESN'T BUCKLE	528
X	Other		489
A	Wor'n Latch	SEAT BELT ON DRIVERS SIDE WONT BUCKLE	884
X	Other	REPAIR GAUGE OF GAUGES INOP NO KEY CHIME NO POWER WINDOW SIDE OTHER FUSE IS BLOWN	828

REMOVED SEAT AND SEAT TRACK AND REPLACED SEAT BELT BUCKLE

INOP ADDITIONAL MISC. REPAIRS

INOP SEATBELT ASSEMBLY FRONT REPLACE

REPLACE SEATBELT ASSY AS PER RECALL 01821  
18 INSTALL BELT LATCH TO FRONT AND REAR SEAT (C) DUE TO SEAT  
BUCKLE FAILURE OF THE SEAT BELT TEST USING THE TESTER REPLACE  
THE BUCKLES THE VEHICLE IS OK

NEED TO REPLACE BOTH

REPLACED PASS FRONT SEAT BELT BUCKLE FOUND WHEN INSPECTING  
BUCKLE UNIT FOR RECALL 01821, RECALL NOT OPEN ON THE NEW  
SEAT BELTS WILL COME UNLATCHED, REPLACED BOTH SEAT BELT  
BUCKLES

A REPLACED SEAT BELT BUCKLE  
42 SEATBELT ASSEMBLY FRONT REPLACE  
3.38 WARRANTY SEATBELT ASSEMBLY FRONT REPLACE  
REPLACED SEAT BELT DRIVER SIDE CAPTION CHAIR MISSING BELT  
COMPLETED

REPLACE RH SEAT BELT ASSY  
DRP BUCKLE REPLACED DRG SEAT BELT BUCKLE  
3.088 REPLACE PASS SIDE SEAT BELT BUCKLE

R & R LEFT FRONT SEAT & TRACK ASSEMBLY & REPAIR SEAT BELT  
ANCHOR REPLACE SEAT BELT BUCKLE ASSEMBLY  
CHECK AND REPLACE FRONT FRONT SEAT BELT BUCKLE  
INSPECT AND TEST SEATBELT BUCKLES DRIVER AND PASSENGER HAD TO  
REPLACE PASSENGER SIDE BUCKLE  
THIS DEFECTIVE PASS SIDE SEAT BELT LATCH ASSY. 180. ORDERED PASS  
SIDE SEAT BELT LATCH ASSEMBLY. R & R PASS SIDE SEAT LATCH  
ASSEMBLY. 180.

INSTALLED PASS SIDE SEAT BELT BUCKLE.  
4275 RIGHT SEAT BELT WILL NOT BUCKLE DAD HOME AND TESTED SEAT  
BELT BUCKLE FAILURE TO OPERATE REPLACE SEAT BELT BUCKLE PART 9  
REPLACE RIGHT SIDE SEATBELT BUCKLE AND LEFT SIDE PART TEST. C/C  
BY OEM

FAILED BELT CHECK, REPLACE SEAT BELT  
1 REPL. D R F SEAT BELT BUCKLE  
RECALL, INSTALLED PASS SIDE BELT AS PER RECALL 01821  
CHECK & REPLACED SEAT BELT BUCKLE

NY 10752

FROM SERVICE MANUAL  
FOUND PASSENGER  
PRETENSIONER BY ASSEMBLY  
FAULTY. RUN RIGHT FRONT  
SEAT, SAME PRETENSIONER  
ASSEMBLY CLEARED CODE  
FROM ECM, TESTED FOR  
PROPER OPERATION

SEMI PASSENGER PRETENSIONER ASSEMBLY VERIFIED CUSTOMER  
CONCERN, PERFORMED AIR BAG DIAGNOSTIC, HOOKED UP NEW TO PULL  
CODES FROM ECM, FOUND CODE 6188, PERFORMED PASSIVE RESTRAINT  
PRELIM TEST H

AIRBAG TESTS, REPLACED LEFT SEAT BELT BUCKLE  
TENSIONER CHIRP SHORTED DIAG BODY ELEC RAR DRIVER'S SEAT AND  
REPLACED SEAT BELT BUCKLE ASSY ON 40 23 49 SUPER CAS  
REPLACED PASS SIDE SEAT BELT BUCKLE WONT LATCH  
NEW TEST BY NEW CLERK CODE 61881 CHECK PRETENSIONER CONNECTOR  
BRACKET. SOUS BRACKET WERE REMOVE CONNECTOR REPLACE  
PRETENSIONER ALL OK  
PERFORM RECALL 01821

X	Other	DRIVER SEAT BELT INOP CUSTOMER STATES SEATBELT WARNING CHIRPS WHEN DRIVER'S BELT ATTACHED, SPD EXHIBITS	770
X	Other	CUSTOMER STATES SEATBELT WARNING INDICATOR ON WHEN DRIVER'S BELT ATTACHED	388
X	Other		363
X	Other		918
R	Recall Performed	RECALL 01821	215
R	Recall Performed	RECALL 01821	218
X	Other		288
X	Other	CUST STATES SEATBELT INOP	688
R	Recall Performed	PASS FRONT SEAT BELT WONT LATCH	423
C	Unlatched/Release	CUSTOMER STATES THAT SEAT BELT WILL NOT STAY LATCHED	893
A	Won't Latch	SEAT BELT BUCKLE NOT HOLDING BELT IN PLACE.	708
X	Other	INSTALL SEATBELTS	893
X	Other	SEAT BELT LATCH FOR PASS SEAT IS MISSING	308
X	Other	CUSTOMER STATES THAT THE DRIVER SIDE SEAT BELT IS MISSING (CONNECTOR ON THE FLOOR)	521
A	Won't Latch	CUSTOMER STATES FRONT PASSENGER SEAT BELT WONT LATCH.	881
A	Won't Latch	CHECK DRG SEATBELT NOT LATCHING	814
A	Won't Latch	DRG SEAT BELT PASS SIDE INOP BUCKLE DOES NOT HOLD	888
X	Other	LEFT FRONT SEAT BELT INOPERATIVE	704
X	Other	PASS SIDE FRONT SEAT BELT FEMALE BUCKLE INOP	880
A	Won't Latch	C & R P SEATBELT WILL NOT BUCKLE INTERMITTENTLY	915
X	Other	RIGHT FRONT SEAT BELT LOOKS UP AND WONT RELEASE	918
X	Other	PASS SIDE FRONT FEMALE END OF SEATBELT MISSING TRM CODE BH	703
A	Won't Latch	RIGHT SEAT BELT WILL NOT BUCKLE	817
X	Other	CHECK SEAT BELTS SAME AS FOR RECALL 01821, BELT FAILED	457
A	Won't Latch	CUSTOMER STATES R P SEAT BELT WONT BUCKLE	717
A	Won't Latch	CUST STATES THAT PASS SEATBELT BUCKLE DOES NOT HOLD	805
X	Other	CHECK DRIVER SIDE SEAT BELT	885
X	Other		800
X	Other	AIR BAG LIGHT COMES ON AND FLAMES THEN IT WILL STAY ON DOWNSTANT DE AND REPORT.	231
X	Other	CHECK AIRBAG LIGHT ON	915
X	Other	SEAT BELT CHIRPS GO ALL THE TIME EVEN WITH SEAT BELT FASTEN	890
A	Won't Latch	CUST STATES PASSENGER'S SEAT BELT BUCKLE INOP	815
X	Other	LUMBER OR AIR BAG TOWELDRIPS ALLU/MISS	919
R	Recall Performed	RECALL 01821 LEFT AND RIGHT	608

MINIMUM TIME TO REPLACE 1 SEAT BELT BUCKLE THAT DOES NOT FASTEN CORRECTLY, REPLACED BOTH FRONT SEAT BELTS

BUCKLE INOP M TIME TO RT BUCKLE  
RFR SEATBELT ON DRIVER SIDE

SEATBELT WONT LATCH TRACK ASSEMBLY FRONT SEAT REPLACE  
48 RFR PRETENSIONER  
42 DRIVERS SIDE SEAT BELT INOPERABLE FOUND AT TIME OF POI

X SEATBELT ASSEMBLY FRONT REPLACE  
TEST AND REPLACE SEAT BELT TWT O K.  
VERIFY CONCERN M TIME ID TO REPLACE DRIVER SEAT BELT BUCKLE  
REMOVE SEAT TO REPLACE REASSEMBLE AND VERIFY REPAIRS  
AIR BAG LIGHT ON DIAG CODE B222 LFC 23 SEAT BELT IMPLUG

ROAD TESTED TO VERIFY CONCERN, FOUND AIR BAG LIGHT,  
PERFORMED SIDE CLAMP, FOUND LOOSE GROUND TO AIR BAG AND SEAT  
BELT LIGHT, REMOVED AND REPLACED SEATBELT, RETESTED OK  
REPLD DEFECTIVE LF SEATBELT BUCKLE PRETENSIONER THAT WOULD  
NOT LATCH.

1 REMOVE REPLACE LEFT FRONT SEATBELT ASSEMBLY  
1 REMOVE REPLACE RIGHT SEATBELT BUCKLE ASSEMBLY LEFT SEATBELT  
REPLACED PREVIOUSLY

REPLACE LF SEAT BELT WITH RECALL BUCKLE  
CHECK AND REPLACE BOTH FRONT SEAT BELTS  
REMOVE AND INSTALL DRIVERS SEAT BELT ASSEMBLY  
CONFIRMED FOUND FEMALE REDUPTICAL NOT WORKING PROPERLY  
REMOVED AND REPLACED TO CORRECT

FAULTY SEAT BELT SEATBELT ASSEMBLY FRONT REPLACE

REPLACED DRIVERS SIDE PRE TENSIONER FOR SEATBELT  
OK FOR DODGE BODY CODE 1677 PP L83 TO DR BUCKLE POINT IT NOT  
LATCHED, RECONINERT  
INSPECT AND REPLACE PASS. SEAT BELT BUCKLE RECH ECK OK  
RETEST AND REPLACE DRIVERS SEAT BELT BUCKLE RECHECK OK  
RECALL 01821 SEATBELT PERFORMED 01301 SEATBELT RECALL  
01821 Q PERFORM RECALL SEAT BELTS AS PER RECALL  
TEST AIR BAG SYSTEM REPLACE LEFT PRETENSIONER

SEATBELT INOP REPLACED BUCKLE  
10M4 DIAGNOSED AND REPLACED DRIVERS SEAT BELT BUCKLE AND  
PRETENSIONER QUALITY CHECKED RETESTED  
REPLACE RT FRT SEATBELT BUCKLE WILL NOT STAY LATCHED AT TIMES  
PER CUSTOMER

INSPECT REPLACE SEAT BELT  
RECALL 01821 SEATBELT PERFORMED 01521 SEATBELT RECALL  
RECALL 01821 SEATBELT PERFORMED 01521 SEATBELT RECALL

R R L SEAT REPLACED L SEAT BELT BUCKLE TENSIONER INOP

SEAT BELT BUCKLE JAMMED SEATBELT ASSEMBLY FRONT REPLACE  
RESTRAINT DIAGNOSIS CODE B1891 FAULTY PASS PRE  
TENSIONER/REPLACE CLEAR CODES AND RETEST.  
REPLACED SEAT BELT BUCKLE

X	Other		304
X	Other	SEAT BELTS RETRACT SLOWLY REPAIR PASSENGER SEAT BELT BUCKLE WONT LATCH OR WILL UNBUCKLE ***SOLD UNIT***	306
Q	Unlatches/Retracts		314
A	Won't Latch	C S SEAT BELT NOT CLICKING TOGETHER	319
A	Won't Latch	CUSTOMER STATES DRIVERS SEATBELT WONT LATCH OR SEAT BELT BUCKLE WILL NOT LATCH	320
A	Won't Latch		323
X	Other	DRIVERS SIDE SEAT BELT INOPERABLE FOUND AT TIME OF POI CUSTOMER STATES SEAT BELT WARNING CONTINUES TO BEEP EVEN AFTER SEAT BELT IS BUCKLED.	327
X	Other	DRIVERS SEAT BELT WILL NOT STAY LATCHED DRIVERS SIDE SEATBELT WILL NOT LOCK INTO BUCKLE,	327
B	Won't Stay Latched		325
A	Won't Latch		326
X	Other		329
X	Other	CUSTOMER STATES AIR BAG LIGHT IS ON	312
A	Won't Latch	DRIVERS SIDE SEAT BELT WONT LATCH AT TIMES, INTERIOR TRIM REPAIR CUSTOMER STATES SEATBELT WILL NOT STAY LATCHED/REARND SOP	322
B	Won't Stay Latched	INTERIOR TRIM REPAIR CUSTOMER STATES PASS SEAT BELT WILL NOT STAY LATCHED	328
B	Won't Stay Latched		329
C	Unlatches/Retracts	DRIVERS SIDE SEAT BELT WILL NOT LATCH KEEPS COMING UNLATCHED INSPECT FOR SEAT BELT BUCKLE RECALL	321
R	Recall Performed	REPAIR DRIVERS SEAT BELT INOP	304
X	Other		320
X	Other	O S DRIVERS SEAT BELT DOES NOT WORK PROPERLY	321
X	Other	REPAIR FOR RIGHT SEATBELT FAILURE	TRM N T 320
X	Other	CUSTOMER STATES THE AIR BAG LIGHT KEEPS COMING ON AND STAYING ON	312
X	Other	AIR BAG LIGHT IS ON	308
A	Won't Latch	PASS SEAT BELT DOES NOT CLAMP	328
X	Other	REPLACE DRIVERS SIDE SEAT BELT BUCKLE	328
R	Recall Performed	PERFORM 01821 RECALL SEATBELT	318
R	Recall Performed	PERFORM 01821 RECALL SEATBELT	328
X	Other	CHEK AIR BAG LIGHT FLASHING CUSTOMER STATES PASSENGER SIDE SEATBELT DOES NOT STAY LATCHED	328
B	Won't Stay Latched	DRIVERS SEATBELT NOT LATCHING TO BUCKLE OR RETRACTING CHECK AND ADVISE	322
A	Won't Latch		328
B	Won't Stay Latched	CHECK PASSENGER SIDE SEATBELT WILL NOT LATCH CUSTOMER STATES SEAT BELT BROWN	321
X	Other		328
R	Recall Performed	PERFORM 01821 RECALL SEATBELT	318
R	Recall Performed	PERFORM 01821 RECALL SEATBELT CUSTOMER STATES THE DRIVERS SIDE SEAT BELT IS NOT LATCHING INTO PLACE. _340	318
A	Won't Latch		318
A	Won't Latch	CUSTOMER STATES PASS SIDE SEAT BELT WILL NOT LOCK	322
X	Other	AIR BAG LIGHT FLASHES	324
X	Other	SEAT BELT BUCKLE FAILED	328



LF SEAT BELT BUCKLE JAMMED	REPLACED LF SEAT BELT BUCKLE	X	Other	CUSTOMER STATED DRIVERS SEAT BELT BUCKLE WONT CHECK PASSENGER SEAT BELT. CUSTOMER STATED THAT IT DOES NOT STAY LOCKED	896
RR SEAT COVER TO REPL SEATBELT AND BUCKLE ASBY		B	Won't Latch		981
IN TIME TO REPLACE FRNT SEAT BELT BUCKLE		X	Other		982
REPLACED LF SEAT BELT BUCKLE		X	Other		999
REPLACED DRIVERS SIDE SEAT BELT		X	Other	REPLACE SEAT BELT	910
FOUND BAD SEAT BELT RECEPTAL. REMOVE AND REPLACE SEAT BELT RECEPTAL		A	Won't Latch	CUSTOMER STATED SEAT BELT WONT BUCKLE	917
BROKEN LATCH REPLACE SEAT BELT		X	Other	CUSTOMER STATES PASS. SIDE SEAT BELT STUCK	921
TEST DRIVE TO VERIFY AIR BAG LIGHT FLASH/LED TEST FROM PINPOINT TEST MONITOR REPLACE DRIVERS SIDE SEAT BELT PRETENSIONER CLEAR CODES TEST DRIVE		X	Other	AIR BAG LIGHT FLASHES.	922
CODES CHECKED OUT REMOVED DRIVERS SEAT AND REPLACED SEAT BELT BUCKLE		A	Won't Latch	BILL CHECKLT FRONT SEAT BELT BUCKLE DOES NOT LATCH	918
188 DMS AIR BAG SYS	PINPOINT TEST	A	Won't Latch	THE LEFT FRONT SEAT BELT WILL NOT LATCH.	918
RR LEFT SEAT TO REPLACE BELT PRETENSIONER		X	Other		929
DATE WAS ENTERED WRONG. CORRECT DATE NOW ENTERED.	CLEAR CODES & RETEST	R	Recall Performed	INSPECT DRIVERS FRONT AND PASSENGERS FRONT SEAT BELTS WITH SPECIAL TOOL	913
1 INSPECTED BOTH FRONT SEAT BELTS ONE FAILED REPLACED ONE		A	Won't Latch	BARE HANF C & DRIVERS SEAT BELT BUCKLE WONT LATCH SOB	929
STUCK INHIBIT OR STRAPS MECHANISM INSIDE OF BELT BUCKLE AS BROKEN		A	Won't Latch	DRIVERS AND PASSENGER SIDE SEAT BELTS WILL NOT LATCH PROPERLY	919
REPLACED SEAT BELT WORKS GOOD		R	Recall Performed	RECALL STRUT BELT	928
SEAT BELTS WONT LATCH PROPERLY REPLACE SEAT BELTS		A	Won't Latch	CHECK SEAT BELT BUCKLE	981
REPLACE SEAT BELT. RT SIDE		K	Other	FACTORY WARRANTY C & DRIVERS SEAT BELT WONT INTERMITT	982
SEAT BELT BUCKLE NOT DATCHING ALL THE TIME REC TO REPLACE FRONT BUCKLE		A	Won't Latch	C & DRIVER SAFETY BELT DOES NOT LATCH SOMETIMES	912
SEATBELT BUCKLE WONT REPLACED BUCKLE		X	Other	CHECK AIR BAG LIGHT ON	916
VERIFY CUSTOMER CONCERN REMOVE DRIVER SIDE SEAT AND REPLACE SEAT BELT BUCKLE		R	Recall Performed	SEAT BELT DAMAGED, PART ORDERED	925
REC TEST PINPOINT TEST WIGGLE TEST UNABLE TO DUPLICATE CONCERN		X	Other	DRIVERS SEAT BELT RECEPTACLE INOPERATIVE	909
RECALL	WE REPLACED THE RIGHT SEAT BELT	X	Other	REPLACED BELT AND TEST	979
REMOVES DRIVERS SEAT REPLACE BUCKLE PRETENSIONER ASSEMBLY		X	Other	AIR BAG LIGHT IS FLASHING	970
REPLACED SEAT BELT		R	Recall Performed	REPLACE RT FRNT SEAT BELT BUCKLE FAILED BUCKLE TEST	902
EXTENSIVE DIAG. BELT RETRACT,BAD AIR BAG RESTRAINT SYSTEM		R	Recall Performed	CHECK SEAT BELTS SAME CONDITION AS M881	981
DASHBORE		A	Won't Latch	DRIVERS SIDE AND PASSENGER SIDE SEAT BELTS WILL NOT LATCH PROPERLY	919
RECALL. REPLACED SEAT BELT TENSIONER BUCKLE AS PER RECALL		A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	938
SEAT BUCKLES NOT LATCHING CORRECTLY REC TO REPLACE BUCKLE AND BUSHINGS		A	Won't Latch	CUSTOMER STATED PASS SIDE SEATBELT, BROKEN WILL NOT LATCH	780
SEAT BELTS WONT LATCH REPLACE SEAT BELTS		A	Won't Latch	CUSTOMER STATED LEFT FRONT SEAT BELT WONT BUCKLE SOF HERE	989
SEAT BELTS WONT LATCH REPLACE SEAT BELTS		X	Other	SEAT BELT BUCKLE LOOSE	792
SEATBELT BUCKLE BROKEN SEATBELT ASSEMBLY FRONT REPLACE		A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH SOB	920
VERIFIED CUSTOMER CONCERN REPLACED LF SEAT BELT BUCKLE		A	Won't Latch	SOFT SEAT BELT WILL NOT LOCK (NO PHERS)	977
REINSPECTED ALL OK. 3.		K	Other	CUSTOMER STATED AIR BAG LIGHT ON	904
REPLACED DRIVERS SIDE SEAT BELT		R	Recall Performed	PERFORM OTHER RECALL SEATBELT	914
1 REPLACED FRONT SEAT BELT BUCKLE		X	Other	839 AIRBAG LIGHT STAYS ON	713
REPLACE TENSIONER		X	Other	CUSTOMER STATES PASS SIDE SEAT BELT DOESN T CLIP ALL THE WAY	915
RECALL OTHER SEATBELT PERFORMED SAME SEATBELT RECALL		X	Other	C & SEAT BELT ALARM GOES OFF WITH SEAT BELT BUCKLED	908
188 TEST PASSIVE RESTRAINTS SYSTEMS PWD DTC 1881. PINPOINT		X	Other	ADVISE ON SEAT BELT NOT LATCHING PROPERLY	758
PASSENGER SEAT BELT PRETENSIONER BAD. REPLACE RETEST OK CD 42		A	Won't Latch	CUSTOMER STATED SEAT BELT BUCKLE WILL NOT LOCK	915
REPLACED PASS SIDE SEAT BELT BUCKLE IN TIME TO REPLACE NO LABOR					
CD#					
989-42 IN RR LF SEAT, REPLACE LF SEAT BELT BUCKLE 2947					
PWD SEAT BELT BAD REPLCD OK					
REINSTALLED PS SEAT BUCKLE					

NEC TO REPLACED SEAT BELT BUCKLE FRONT LATCH

CLUE NOT LATCH  
CORRECTLY,CHECKED AND  
LUBED RAILS,REINSTALLED  
SEAT AND ASBY CHECKED  
SEAT ADJUSTING ALL  
FUNCTIONS WORKING  
CORRECTLY,NEW LATCH  
OPERATION OK.

B Won't Stay Latched DRIVERS SEAT BUCKLE WONT STAY LATCHED 881

INSPECTION OF DRIVERS SEAT BELT FOUND BUCKLE WOULD NOT  
LATCH,WORKED DASH FOR ACTIVE RECALL,FOUND NONE,REMOVED  
DRIVERS SEAT AND REPLACED DAMAGED BUCKLE UPON REINSTALLING  
SEAT FOUND SEAT RAIL ASBY'W

REPLACED SEATBELT ASSY  
REPLACE SEATBELTS WILL NOT LATCH PROPERLY  
VERIFY CONCERN LH SEAT BELT BUCKLES SHOWN PAR L F SEAT BELT  
BUCKLES VERIFY REPAIRS L F SEAT BELT BUCKLES NORMAL  
REPLACED 2 SEAT BELT BUCKLES  
PIN POINT TEST MONITOR PIDS CHMS ON LEFT PRETENSIONER BIOC  
SYSTEM LIGHT ONLY COMES ON AT TIMES REPLACED L SEAT BELT BUCKLE  
PRETENSIONER RESET OK  
REPLACE SEAT BELT  
MCP EEC (QUICK TEST) DIAGNOSIS

A Won't Latch

DRIVERS SEAT BELT WONT LATCH  
L F SEAT BELT WONT SNAP INTO BUCKLE

817  
887  
918

A Won't Latch

DRIVERS SEAT BELT WILL NOT BUCKLE IN SEAT  
SEATBELT TROUBLES

818  
824

K Other

AIR BAG LIGHT FLASHES AT TIMES AND NOT COMING ON AT OTHER TIMES  
SEAT BELT DOES NOT WORK PROPERLY  
CUST STATES THAT THE AIR BAG LIGHT IS ON

808  
708  
407

K Other

K Other

K Other

SEAT BELT LIGHT STAYS ON ALL THE TIME. TESTED,DRUCKLANT 8100AAA  
1 & 1.8 PERFORMED NGS TEST, PINPOINT TEST, REPEAT QUICK TEST, RM  
DRIVER SEAT. RM CAPDET TO CHECK WIRING, REPLACED SEAT BELT BUCK  
MCP AIR BAG RESTRAINT SYSTEM DIAGNOSIS REPLACE  
LEFT SIDE AIR BAG PRETENSIONER  
INSPECT AND REPLACE PASSENGER SEAT BELT

LE, RETEST OK CALIB PART  
188203 CONDITION CODE 12

K Other

SEAT BELT WARNING STAYS ON WHEN SEATBELT IS IN  
AIR BAG LIGHT WILL COME ON AT TIMES AND WILL STAY ON A COUPLE OF  
DAYS \*\*\* PARTS ARE IN FOR TECH BAG \*\*\*  
INSPECT FOR SEAT BELT BUCKLE RECALL

886  
770  
804

K Other

R Recall Performed

HIGH RESISTANCE AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
INSPECTED AND INSTALLED NGS TO CHECK FOR ANY CODES IN SYSTEM  
AND RETRIEVED CODE 1877,TESTED AND FOUND INTERMITTENT  
PRETENSIONER CODE FOR DRIVERS SIDE,REINSTALLED NEW DRIVERS SIDE  
PRETENS. CLEARED CODE

AND RECHECKED DONE

K Other

CUST STATES AIR BAG LITE FLASHES

407

3002 I PERFORMED A SRS SYSTEM TEST 1877 2. CHECKED QARS. 3  
PERFORMED A SRS SYSTEM PIN POINT TEST. 4 DEACTIVATE SRS SYSTEM  
5 REMOVED DRIVER SEAT, 6 TEST DRIVER SRS PRE TENSIONER. 7 FOUND  
PWS TENSE

DRIVER RESISTANCE HIGH  
18.501/888 8 REPLACED  
DRIVER SEAT BELT PRE  
TENSIONER. 9 REACTIVATE  
SRS SYSTEM. 10 REPEAT SRS  
SYSTEM 11 8.1UP QARS.

X Other

SRS CK SRS LIGHT STAYS ON WHILE DRIVING AT TIMES, CUSTOMER  
STATES

308

3017 I PERFORMED A SRS SYSTEM TEST 8881 1877 3. DEACTIVATE SRS  
SYSTEM 3 PERFORMED A SRS SYSTEM PIN POINT TEST. DRIVER 8 DRIVERS  
RESISTANCE. PASSENGER 7.8 CHMS RESISTANCE. 4 REMOVED DRIVER  
AND PASSE

NGER SEATS 8 REPLACED  
DRIVER AND PASSENGER SRS  
SEAT BELT PRETENSIONERS. 6  
REINSTALL DRIVER AND  
PASSENGER SEATS. 7  
REACTIVATE SRS SYSTEM.  
PROVE OUT SRS SYSTEM. 8  
RETEST SRS

X Other

SRS CK AIR BAG LIGHT FLASHES , CUSTOMER STATES

488

88138 W-F-LINE NGS-TO-RUN QUICK TEST SRS, RM. OCL TO CHECK  
SYSTEM. INTERMITTENT IN DRIVERS SIDE PRETENSIONER. REPLACE  
DRIVER SIDE PRETENSIONER. RETEST PASS  
DIAGNOSIS,TESTED SYSTEM,REMOVED AND REPLACED DRIVERS SIDE  
PRETENSIONER,RETESTED  
INSTALLED DRIVERS SIDE SEAT BELT BUCKLE  
8711 REPLACE DRIVERS SEAT BELT BUCKLE, WILL NOT LATCH. 8.40 SEAT,  
WITH PRETENSIONER

K Other

AIRBAG LIGHT FLASHES ON AND OFF  
AIR BAG LIGHT ON INTER, FLASHES INTER AND SOLID AT OTHER TIMES,  
ADVISE

813

X Other

A Won't Latch  
SEATBELT WILL NOT LATCH AT ALL, RECALL?  
DRIVERS SEAT BELT WONT LATCH, NOT ON RECALL, DOSE SAYS SHOULD  
HAVE PART IN STOCK

301  
418  
318

A Won't Latch

8731 81203 4E 14880 3 8 81178A 0.4 PERFORMED SRS DIAG REMOVED  
SEAT ON DRIVERS SIDE,REPLACED SEAT BELT PRETENSIONER RETEST OK

X Other

SRS,CUST SAYS AIR BAG LIGHT WOULD FLASH ON DASH,NOW LIGHT  
STAYS ON ALL THE TIME

308



PERFORM DIAG WDS DCL PPT FAILED SEAT BELT TENSIONER TO BE  
 INSTALLED AT S SHOP

OPEN PRETENSIONER AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
 SOP SEAT BELT

REPLACED RIGHT FRONT SEAT BELT WITH TENSIONER RETRACTOR.  
 1 TESTED AIR BAG SYS CODE B1877 WITH AIR BAG SYS PPT FOUND INT  
 WOP DRIVERS SEATBELT PRETENSIONER R R SEAT TO REPLACE  
 RUN AIR BAG DIAG, CODE B1877, PIN POINT TEST OPEN CIRCUIT  
 PRETENSIONER, REPLACE DRIVER AND PASS SEAT BELT ASBY  
 REPLACE LEFT FRONT SEAT BELT  
 PERFORMED AIRBAG DIAGNOSTIC REPLACED PASSENGER PRE  
 TENSIONER.  
 1877S DRIVERS PRE TENSIONER F C B9 AIR BAG DIAG, LFC 46, DTG B  
 1E77, PINPOINT TEST, FOUND DRIVERS PRE TENSIONER CRT OPEN, REPLACE  
 PRE TENSIONER, CLEAR DTC.  
 REPLACED SEATBELT ASBY AND USE M TIME TO REPLACE BUCKLE RETEST  
 OK AFTER REPAIR  
 RUN DIAG ON SEAT BELT, RUN RIGHT FRONT SEAT. REPLACED SEAT BELT  
 BUCKLE ASBY, TECH 8H  
 ELECTRIC TEST B1877 IN MEMORY ON DEMAND PASSED INTERMITTENT  
 PROBLEM PINPOINT TEST. B1 88 REMOVED DRIVERS SEAT AND REPLACED  
 PRETENSIONER AND RETEST OK  
 REPLACED SEAT BELT BUCKLE

SOP PRETENSIONER AIR BAG RESTRAINT SYSTEM ENGINEER  
 REPLACED ONE SEAT BELT BUCKLE

BROKEN M TIME TO REPLACE LEFT SEAT BELT BUCKLE  
 OPEN CIRCUIT REPL TENSIONER AIR BAG RESTRAINT SYSTEM  
 DIAGNOSIS  
 REPLACE PRETENS  
 GAUG TORQUE CCC A65 CC 42 VERIFY. PERFORM RCM SELF TEST.  
 RECEIVED CODE B187L. PERFORM PINPOINT TESTS B187L. DEACTIVATE  
 SYSTEM AND REPLACED

1 REPLACED DRIVERS PRETENSIONER HIGH RESISTANCE.

DRIVERS SEAT BELT BUCKLE SOP INSPECT BUCKLE WOULD NOT LATCH  
 IN R. DRIVER SEAT ASBY REPLACED DRIVERS SEAT BELT BUCKLE  
 LH FRONT BUCKLE JAMMED. DISABLE AIR BAG SYSTEM, REPLACED  
 BUCKLE. RE ACTIVATE AIR BAG SYSTEM.  
 INSTALL BUCKLE

SEAT BELT BUCKLE SOP REPLACE RIGHT PPT SEAT BELT BUCKLE  
 AIRBAG LIGHT DRIVERS SEAT BELT BUCKLE ASBY HAS HIGH RESISTANCE  
 REPLACED BUCKLE AS NEEDED  
 SEATBELT PRETENSIONER PERFORMED AIRBAG  
 DIAGNOSIS, INSTALLED SEATBELT PRETENSIONER  
 BURN PASSENGER SIDE SEAT BELT BUTTON SHOWS OPEN FOUND PASSENGER  
 SIDE BROKEN SHORT FOR SEAT AND REPLACED BELT/BUCKLE PROBLEM  
 COMPLETED  
 188188 26 M O 188188 AIR BAG LIGHT LFC 46 WAS START UP RCE BELT  
 TEST C1877 PID MONITOR RECORD HIGH DRIVER RETRACT CIRCUIT CHGS  
 HIGH 409886 P PINPOINT TEST  
 INSTALL SEAT BELT PRETENSIONER BOTH SIDES  
 REPLACE ONE SEAT BELT

X	Other	AIR BAG LITE ON	888
X	Other	AIRBAG LIGHT COMES ON AT TIMES , WORST COULD	818
A	Wont Latch	DRIVER SEAT BELT WILL NOT HOLD AT TIMES	218
A	Wont Latch	PASS SEAT BELT BUCKLE MALFUNCTION BUTTON STICKS AND WILL NOT ALLOW BELT TO LATCH IN UNLESS BUTTON IS PUSHED DOWN DIAG AND ADVISE CUST STATED AIR BAG LIGHT FLASHES WHILE DRIVING.....AS.....(888)	218 714
X	Other	WF 688 AIR BAG LIGHT ON	465
A	Wont Latch	THE DRIVERS SEATBELT WILL NOT LATCH INSTALL S O PART	890
X	Other	AIRBAG LIGHT IS ON	878
X	Other	SEE AIR BAG LIGHT IS ON, CUST SAYS SEAT BELT WONT STAY BUCKLED FOR WIFE BUT WILL FOR CHILD SEAT, COMES UNDONE AT OFF, TIMES	214 802
C	Unlatched/Released		
A	Wont Latch	PASS SEAT BELT WILL NOT LATCH	808
X	Other	CUSTOMER STATES AIR BAG LIGHT COMES ON INTERMITTENT	840
A	Wont Latch	DRIVERS SEAT BELT WONT LATCH CUST STATES AIRBAG LIGHT IS ON INSTALL SOP	718
X	Other	USE SPO 0E114004	806
X	Other	SEAT BELT BUCKLE NOT WORKING PROPERLY REPAIR DRIVERS SEAT BELT BUCKLE WONT BUCKLE UP OR WILL COME UNDONE --SOLD UNIT--	281 714
C	Unlatched/Released		
X	Other	OK AIR BAG LT IS ON & FLASHING	818
X	Other	O B SHE CAN SEE AIR BAG AND AIR BAG LIGHT IS GOING ON AND OFF	804
X	Other	CUST. STATES AIR BAGS AND BUNG A CODE OF 47 NO LIGHT IS ON RIGHT KNOW.....AS	330
X	Other	CUSTOMER STATES AIR BAG LIGHT CAME ON YESTERDAY. SOMETIMES IT WILL FLASH. SOMETIMES STAYS ON SOLID LIGHT WAS NOT	308
A	Wont Latch	SEE CUSTOMER STATES, SEAT BELT LATCH IS SOP ON DRIVER SIDE	872
A	Wont Latch	DRIVERS SEAT BELT WONT LATCH	306
X	Other	CHECK FOR DRIVER SIDE SEAT BELT LATCH STICKS	887
A	Wont Latch	CHECK FOR PASS SEAT BELT BUCKLE UNABLE TO BUCKLE THE SEAT BELT	708
X	Other	SEE AIR BAG LIGHT ON	388
X	Other	CUST STATED THE AIR LIGHT IS ON	310
X	Other	CUSTOMER STATES THAT THE AIR BAG LIGHT IS ON SOP ARE HERE	831
X	Other	CUSTOMER STATES AIRBAG LIGHT STAYING ON	841
X	Other	AIR BAG LIGHT ON SOP PARTS	806
X	Other	SEAT BELT BUCKLE SOP	788

POOR CONTACT G22 TESTED HO30 B1677, B1680, B1677  
 PINPOINT TESTED, REMOVED

REMOVED & REPLACED PRETENSIONER

WIP L F SEAT BELT BUCKLE STICKING MARKS INSPECTED L F SEAT BELT,  
 FOUND L F SEAT BELT BUCKLE WAS STICKING, DEACTIVATED AIR BAG  
 SYSTEM DUE TO PRETENSIONER, RFA L F SEAT BELT BUCKLE &  
 PRETENSIONER, RFA  
 DIAGNOSIS AIR BAG RESTRAINT SYSTEM TIME TO REPLACE DRIVER SEAT  
 BELT PRETENSION

G22B SHORTED OUT CIRCUIT. BASIC # 91688 WORKED CONCERN, NOTE  
 CLUT HAS RIGHT AIR BAG IN OFF MODE M28 DIAGNOSIS/SCHE TEST. AIR  
 BAG DIAGNOSIS, COMPLETED PIN POINT TEST. DTC B1677 CHECKED W/WRAP  
 DIRECTLY.  
 REPLACED THE LEFT FRONT SEATBELT THAT HAD FAILED CAUSING CHIME  
 TO STAY ON  
 B1694Z REMOVED THE PASSENGER SEAT TO REPLACE THE SEAT BELT  
 LATCH 6881

REPL. FRT SEAT BELT  
 R AND P SEAT REMOVE FROM FRAME REPLACE SEAT BELT TRACK AND AND  
 REINSTALL

VERIFY L FRONT BUCKLE SHOWS REPLACE NEEDED ON  
 REPLACE BROKEN DRIVER SIDE SEAT BELT BUCKLE  
 PERFORMED SIDE DIAGNOSIS, PINPOINT TEST AND AIRBAG DIAG CODE  
 B1677. REMOVED LF SEAT TO REPLACE LEFT FRONT SEAT BELT  
 PRETENSIONER. RETESTED OK.

DO NOT NEED TEST, PINPOINT TEST FOUND AND REPLACED INOP FRONT  
 FRONT SEAT BELT BUCKLE ASSEMBLY. NECESSARY TO REMOVE SEAT FOR  
 ACCESS. REASSEMBLED AND RETESTED OK.

3000 OPENED COIL INSPECTED DRIVERS SEAT BELT. FOUND BUCKLE  
 INOP. REMOVED AND REPLACED BUCKLE AND PRETENSIONER.  
 NECESSARY TO DISABLE SUPPLEMENTAL RESTRAINT SYSTEM TO REMOVE  
 PRETENSIONER. NECESSARY T

S43 AIR BAG DIAG CODE B1677. PERFORMED PIN POINT TEST REMOVED  
 DRIVERS SEAT TO REPLACE PRETENSIONER SEAT BELT BUCKLE PRETEST  
 ROADTEST OK CO IS

OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS WDS.  
 PINPOINT TEST, R & L DR  
 AIRBAG LIGHT ON WDS TESTS, CODES B1681, REPLACED PASS  
 BUCKLE, PRETEST

VERIFY CONCERN. REPLACED LEFT SEATBELT BUCKLE.

AIR BAG DIAG REPLACE PRE TENSIONER  
 4847 PERFORM AIR BAG SYSTEM DIAGNOSIS. DTC B1677 OPEN IN DRIVERS  
 SEAT BELT PRETENSIONER CIRCUIT. CHECK WIRING AND CONNECTIONS  
 TO PRETENSIONER, OKAY. REMOVE LEFT FRONT SEAT AND REPLACE  
 SEAT BELT BU

3000 G.C B1688 AIR RIGHT FRONT SEAT REPLACE FRONT SEAT BELT BU  
 CHIME FOR B1688 INOP  
 DRIVERS SEAT BELT BUCKLE. VERIFIED AIR BAG LITE ON. HOOK UP WDS  
 AND PERFORMED SIDE DIAG RETRIEVED CODE B1677 FROM PCM.  
 PERFORMED PPT TO DRIVERS SEAT

LATCHES INTERMITTENTLY SEATBELT ASSEMBLY FRONT REPLACE

L F SEAT FOR ACCESS,  
 RETESTED WITH NO  
 FURTHER PROBLEMS, NOW  
 SETUP & TEST, CHECKED &  
 CLEARED ANY AIR BAG  
 CODES

REMOVED LEFT FRONT SEAT  
 TO TRANCED OUT AND  
 REPLACED LEFT FRONT  
 PRETENSIONER ASSY.  
 CLEARED CODES AND  
 RETESTED.

D REMOVE DRIVERS SEAT TO  
 ACCESS BUCKLE.  
 RECHECKED OPERATION. OK

OKAY PRETENSIONER CLEAR  
 CODE AND RETEST, OKAY.  
 (R) PERFORM QUALITY  
 CHECK.

X	Other	AIR BAG LIGHT FLASHING CUSTOMER STATES AIR BAG (DR) WARNING LIGHT FLASHES 4 TIMES THEN 7 TIMES AND THEN WILL STAY ON	254
X	Other		714
X	Other	DRIVERS SIDE BUCKLE INOP	817
X	Other	AIR BAG LIGHT STAYS ON	337
X	Other	QUALITY CHECK INITIALS: OK AIR BAG LIGHT STAYS ON 888 THE SEAT BELT CHIME WILL SOUND AT ALL TIMES. EVEN IF THE SEATBELTS ARE FASTENED	810
X	Other		816
A	Wont Latch	CLUT STATES PASS SIDE SEAT BELT WILL NOT LATCH EVERY TIME. REPLACE PASSENGER FRONT SEAT BELT BUCKLE CAN PULL SEAT BELT OUT OF BUCKLE	740
C	Unlatched/Release	CUSTOMER STATES AIR BAG LIGHT FLASHING ON AND OFF CHECKED AIR BAG SYSTEM REPLACED PASS SIDE SEAT BELT BUCKLE	858
X	Other	DRIVERS SEAT BELT BUCKLE WONT LATCH INTER. ADVISE DRIVER BUCKLE WONT LATCH AT TIMES	810
A	Wont Latch		828
A	Wont Latch		828
X	Other	CUSTOMER STATES AIR BAG LIGHT STAYS ON AT TIMES WHILE DRIVING	870
X	Other	880 AIR BAG LIGHT FLASHES	818
X	Other	SEAT BELT COIL UNCOIL TROUBLE	348
X	Other	828 AIR BAG LIGHT IS FLASHING CODE 84 WHILE DRIVING OFF AND ON CUSTOMER STATES AIR BAG LIGHT FLASHING OFF AND ON WHILE DRIVING. AT TIMES LIGHT WILL STAY ON	304
X	Other		270
X	Other	OK AIRBAG LIGHT ON LEFT SEATBELT WONT STAY LATCHED	840
B	Wont Stay Latched		780
X	Other	AIR BAG LIGHT FLASHES ON AND OFF	888
X	Other	828 PASSENGER AIR BAG LIGHT SWITCH WAS AND AIR BAG LIGHT ON DASH WAS FLASHING, OWNER STATE	828
X	Other		-
X	Other	QCP 888 RT FT SEATBELT WONT BUCKLE	714
A	Wont Latch		714
X	Other		428
X	Other	PASSENGER SEATBELT NOT WORKING, INTERNAL CHECK AND ADVISE	818

NO	DESCRIPTION	DIAGNOSIS	SYMPTOM	REPAIR	REMARKS	TIME
1	DRIVER COORDINATING INTERLOCK PINPOINT DEACTIVATED AIR BAGS, REPLACE DRIVER'S PRETENSIONER ASSEMBLY, RFR MODULE AND RESETTED OK. AIR BAGS CLASSIFIED BY PINPOINT TEST CODE B1977 & DRILL & REMOVE SEDED SEAT PRETENSIONER BOLT. RFR DRIVE SEAT TO ACCESS & REPALE PRETENSIONER. CLEAR CODE & RETEST		CHIEF STATES AIR BAG LIGHT COMES ON WHEN HITTING A BUMP, GOES OUT WHEN SPEED IS CYCLED, AIR BAG LIGHT FLASHES AT TIMES	X	Other	041
1	DRIVER COORDINATING INTERLOCK PINPOINT DEACTIVATED AIR BAGS, REPLACE DRIVER'S PRETENSIONER ASSEMBLY, RFR MODULE AND RESETTED OK. AIR BAGS CLASSIFIED BY PINPOINT TEST CODE B1977 & DRILL & REMOVE SEDED SEAT PRETENSIONER BOLT. RFR DRIVE SEAT TO ACCESS & REPALE PRETENSIONER. CLEAR CODE & RETEST		AIR BAG LIGHT ON SOLID	X	Other	041
1	DRIVER COORDINATING INTERLOCK PINPOINT DEACTIVATED AIR BAGS, REPLACE DRIVER'S PRETENSIONER ASSEMBLY, RFR MODULE AND RESETTED OK. AIR BAGS CLASSIFIED BY PINPOINT TEST CODE B1977 & DRILL & REMOVE SEDED SEAT PRETENSIONER BOLT. RFR DRIVE SEAT TO ACCESS & REPALE PRETENSIONER. CLEAR CODE & RETEST		1 AIR BAG LIGHT ON	X	Other	041
1	ROAD TEST KODS FOUND CODE FOR PASS BUCKLE WDS PID MONITOR FOR ALL INPUT OUTPUT MONITOR ALL PASS RESET LIGHT RETEST AIR BAG DIAG DRIVER SEAT OPEN CRST IN PRETENSIONER REPLACED PRETENSIONER SEAT BELT BUCKLE CLEARED CODE NOW OPERATING PROPERLY		AIRBAG LIGHT COMES ON, AND STAYS ON AT TIMES	X	Other	014
1	REPLACE SEAT BELT		AIRBAG LIGHT FLASHES	X	Other	001
1	RECALL	REPAIRED AIR FEN RECALL	SEAT BELT BUCKLE INOP	X	Other	000
1	700 DRIVER SIDE SEAT BELT BUCKLE IN W CK AIR BAG LIGHT STARTS BLINKING AND THEN STAYS ON PERFORM QUICK TEST WITH HES FROM OPEN ON SEAT BELT BUCKLE RFR SEAT BELT BUCKLE RECHECK AND ROAD TESTED OK		FRONT PASS SEAT BELT WONT LATCH	A	Wont Latch	000
1	RFR LH SEAT BELT BUCKLE		000 CUSTOMER STATES AIR BAG LIGHT STARTS BLINKING AND THEN STAYS ON	X	Other	000
1	D REMOVED PASSENGER BUCKLE SEAT RFR SEATBELT ASSEMBLED TOGETHER, WORKS FINE NOW.		CUSTOMER STATES SEAT BELT BUCKLE WILL NOT STAY LATCHED	B	Wont Stay Latched	000
1	AIR BAG LIGHT CHROMA QUICK TEST TRACED TO INTERM OPEN IN RIGHT SEAT BELT BUCKLE		Q CHECK FOR PASSENGER SIDE SEATBELT NOT WORKING PROPERLY	X	Other	007
1	7 REPLACED DRIVER SEAT BELT BU OBLE WITH PRETENSIONER RECALL 01001 SEATBELT PERFORMED 01001 SEATBELT RECALL DC 01 HIGH SEATBELT BUCKLE INSTALLED	ER	AIR BAG LIGHT FLASHING REPL	X	Other	000
1	REPLACED DRIVER BUCKLE		CUSTOMER STATES SEAT BELT INOP	X	Other	004
1	REPLACED DRIVER BUCKLE		PERFORM 01001 RECALL SEATBELT	R	Recall Performed	010
1	TESTED & TRACED TO BND PRETENSIONER, REPLACED TO CORRECT DIAGNOSE AIR BAG LIGHT ON RFR SELF TEST B1977.PINPOINT TEST TL CHECK WIRING TO RETRACTOR OK REPLACE RETRACTOR HAS INTERMITTENT OPEN RECHECK OK		DRIVERS SEAT BELT LATCH IS BROKEN	X	Other	000
1	REPLACED SEATBELT AND NOW OK		FOR VEHICLE IS PART BULD DATE FOR RECALL, BUT DRIVERS BUCKLE FAILS	R	Recall Performed	014
1	REPLACE L SEAT BELT INOP		FOR VEHICLE IS PART DATE CODE FOR RECALL, BUT DRIVERS BUCKLE FAILS	R	Recall Performed	014
1	REPLACE SEAT BELT		CHECK AIRBAG LIGHT KEEPS COMING ON	X	Other	000
1	REPLACE DRIVER SIDE SEAT BELT ASBY		C-B AIR BAG LIGHT WAS FLASHING THEN ON SOLID ADVISE	X	Other	007
1	20 RECALL 01001. WFR PERFORM RECALL 01001 PERFORM INSPECTION ON SEAT BELT BUCKLES, TANK OK		DRIVER SIDE SEATBELT WONT LATCH	A	Wont Latch	000
1	TESTS IN PRETENSIONER UNBND J, CR1 -1, DR A, M1 .7 LS WDS TO BCE, PINPOINT B1977 RFR SEAT BELT BUCKLE CUSTOMER STATES IT WAS NOT WORKING, FAILED TESTER FOR 01001		AIRBAG LIGHT IS ON	X	Other	000
1	DOWN-HRY SEATBELT BUCKLES FAILED RECALL INSPECTION CARB. DOESNT SHOW VEHICLE INVOLVED IN RECALL. RFR BUCKLES DUE TO SAFETY LIABILITY ISSUES LISTED AS N TIME NO OPS FAIL.		SEAT BELT INOP	X	Other	000
1	IF R DRIVER FRONT SEAT AND REPLACED SEAT BELT BUCKLE WITH PRETENSIONER CAUSING AIRBAG LIGHT TO COME ON		OK FOR DRIVERS SEAT BELT WONT STAY LATCHED.	B	Wont Stay Latched	000
1	PERFORM PINPOINT TEST B1 SEAT REMOVE AND REPLACE OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM (DIAGNOSIS BY TO PINPOINT TEST B1 B3 37 REPL FRONT SEAT BELT		RECALL 01001	R	Recall Performed	000
1	1 SUPPLEMENTAL RESTRAINT SYSTEM DIAGNOSTIC CODE B1001 PINPOINT TEST REPLACE RIGHT SEATBELT PRETENSIONER RETEST INOPERATIVE BODY CHASSIS ELECTRICAL (BCE) TEST		RECALL 01001	X	Other	000
1	REPLACE ONE SEAT BELT		AIR BAG WARNING LIGHT TROUBLE	X	Other	070
1			REPLACED SEAT BELT BUCKLE	R	Recall Performed	000
1			PERFORM RECALL 01001 REPLACE SEAT BELTS PER INSTRUCTIONS CUSTOMER STATES THE AIRBAG LIGHT FLASHES THEN GOES SOLID. SOP HERE 001	R	Recall Performed	001
1			CHECK AIR BAG LIGHT ON	X	Other	001
1			THE AIR BAG LIGHT COMES ON AND OFF EST AND ADVISE	X	Other	000
1			SUPPLEMENTAL RESTRAINT SYSTEM LIGHT IS ON AIR BAG LIGHT ON INTER	X	Other	000
1			AIRBAG LIGHT ON	X	Other	000
1			SEAT BELT BUCKLE INOP	X	Other	000

LATCH STICKS, PULLED BUCKLE, REPLACED BUCKLE & REINSTALLED SEAT

REPLACED DRIVERS BUCKLE

DMS AIR BAG LIGHT ON AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
SEATBELTS WONT LATCH PROPERLY REPLACE SEATBELTS  
VERIFY CONCERN PERFORM DIAGNOSTIC CODES AS PRESENT PERFORM  
PINPOINT TESTS  
LEFT SEAT BELT REPLACED DEFECTIVE LEFT SIDE SEAT BELT  
BUCKLE

1 VERIFY CONCERN PERFORM AIR BAG SYSTEM TEST RETEST CODE FOR OR NE  
SEAT BELT HIGH RESISTOR PERF PINPOINT TEST PID MONITOR FOUR

AIRBAG LIGHT ON AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
AIRBAG LIGHT IS ON ESC (QUICK TEST) DIAGNOSIS

VERIFY CONCERN, HOOKED UP HES AND PERFORMED BODY CHASSIS  
ELECTRICAL TEST. PERFORMED PINPOINT TEST AND SOL DISPLAY,  
REPLACED OPEN DRIVER & SIDE PRETENSIONER, CLEARED CODES AND  
SEAT BELTS WONT LATCH REPLACE SEAT BELT  
AS SHOWN BY AIR BAG DIAG REMOVE DRVR SEAT REPLACE AIR BAG  
PRETENSIONER RETEST OK

1194L IN 1182222 HOOK UP M.U.B., RETRIEVE CONT. DTCS, D1181  
PRESENT, PASS SEATBELT PRETENSIONER OPEN CKT. PERFORMED DIAG.  
& PINPOINT TEST, RM PASS SEAT AND INSTP BY 46 SEATBELT  
PRETENSIONER BUCKLE

REPLACED DRIVERS BUCKLE

M08 TEST B1177 DRIVERS SIDE PRETENSIONER FULLY CLEAR CODES  
RETEST FAULTS INTERMITTEN M08 POS PINPOINT TEST REMOVE  
DRIVERS SEAT DISCONNECT HARNESS CHECK CIRCUITS 1180 AND  
1178 FOR SHORTS O  
SEAT BELT WOULD NOT LATCH, REPLACED WITH NEW SEAT BELT, WORKS  
PROPERLY

REPLACED SEAT BELT

488 VERIFY CUSTOMERS CONCERN CONNECTED M08 FOUND CODES  
B1171 DRIVER SIDE PRETENSIONER OPEN CIRCUIT AND B1181 DRIVER SIDE  
PRETENSIONER OPEN CIRCUIT. USED MULTIMETER TO PERFORM PINPOINT  
TEST M FOR B1171  
REPLACE RIGHT SEAT BELT, 48

DRIVERS SEATBELT BUCKLE FAILED BY 11821 INSPECTION. CAUSE NOT  
INCLUDED IN RECALL. RPL BUCKLE FOR SAFETY LABEL CONCERN. M  
TIME IS LOW TO REPLACE DRIVERS SEATBELT BUCKLE. NO OHS PUBL.  
AIR BAG DIAG REPLACE BUCKLE

IS ASBY., FOUND OPEN AT  
PRETENSIONER, REPAIR  
OPEN CKT NOW. CLEAR CONT  
DTCS. PERFORM FINAL  
CLICK TEST.

R OPEN CIRCUIT  
DEACTIVATE SYSTEM  
MONITOR PID WHILE  
WIGGLING HARNESS FROM  
MODULE TO PRETENSIONER  
FAULT DUPLICATED R AND R  
DRIVER PRETENSIONER  
REINSTALL SEAT VERIFY  
REPAIR

1 AND POINT TEST B1181 ALSO  
INSTALL THE SIMULATOR TO  
PERFORM PINPOINT FOUND  
BOTH CIRCUIT GOOD  
REPLACE BOTH  
PRETENSIONERS

PRETENSIONER HAS TO  
REMOVE BOTH FRONT SEAT  
TO GAIN ACCESS TO  
PRETENSIONERS.

A	Wont Latch	CUSTOMER STATES CANNOT LATCH DRIVERS SEAT BELT BUCKLE	718
R	Recall Performed	P16 VEHICLE IS PAST DATE CODE FOR RECALL BUT DRIVERS BUCKLE FAILS	314
X	Other	CUST SAYS A BAG LITE IS COMING ON & FLASHES 4 THEN 6 THEN STAYS ON	870
X	Other	DRIVER PASSES DRIVER SEAT BELTS WILL NOT LATCH PROPERLY	818
X	Other	AIR BAG LIGHT COMES ON INTERMITTENTLY	818
X	Other	DRIVERS SEAT BELT BUCKLE WOP	714
X	Other	AIR BAG LIGHT ON CUST STATES AIRBAG LIGHT FLASHES AND THEN STAYS ON (INTERMITTENT)	872
X	Other	AIR BAG LIGHT ON	738
X	Other	AIR BAG LIGHT ON	848
X	Other	AIRBAG LIGHT FLASHES AT TIMES. JIM	872
A	Wont Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
X	Other	HIS CUST STATES AIR BAG LIGHT COMES ON WHEN DRIVING	727
X	Other	AIR BAG LIGHT IS ON 828	878
R	Recall Performed	P16 VEHICLE IS PAST BUILD DATE FOR RECALL BUT DRIVERS SIDE FAILS	314
X	Other	AIR BAG LIGHT COMES ON INTERMITTENT SOMETIMES FLASHES SOMETIMES ON OTHERS NOT	841
A	Wont Latch	CUSTOMER STATES DRIVERS SIDE SEAT BELT WILL NOT LATCH SEAT BELT NOT WORKING PROPERLY L52	848
X	Other	1081822AAA	727
X	Other	PRETENSIONER HAS TO REMOVE BOTH FRONT SEAT TO GAIN ACCESS TO PRETENSIONERS.	818
A	Wont Latch	CUST. STATES AIR BAG LIGHT COMING ON RIGHT FRONT SEAT BELT WILL NOT CATCH AT TIMES	817
R	Recall Performed	PERFORM RECALL C11811 INSTALL DRIVERS SIDE SEAT BELT BUCKLE	801
X	Other	AIRBAG LIGHT STAYS ON	814

0029 OPEN PASS. SEATBELT PRETENSIONER LE  
 14888D (L)170A(L)PRETENSIONER 3 AIR BAG SYSTEM DIAGNOSIS FOUND  
 OPEN PRETENSIONER PASS PAGE SEAT TRACK TO BASH ACCESS.  
 REPLACED PASSENGER SIDE SEATBELT PRETENSIONER  
 01881 COMPLETED  
 6 RECALL W TECH SERPERFORMED RECALL 01881/PK PASS FRONT SEAT  
 BELT/PASSENGER ALL OK AT THIS TIME  
 REPLACED LF BUCKLE AIR

REPLACE LF SEAT BELT  
 DR BUCKLE AIR BAG RESTRAINT SYSTEM DIAGNOSIS  
 REPLACE BELTS  
 REPLACED BOTH DRIVERS AND PASSENGER BUCKLES  
 PK LEFT FRONT SEAT MARK A (BUZZLATOR FOR SEAT BELT BUCKLE IN CH)  
 REPLACE FRONT SEAT BELT BUCKLE AND PRETENSIONER  
 TEST SYSTEM REPLACED SEAT BELT ASSEMBLY  
 TEST PCM CODE B3077 PK FRONT TEST REPLACED LEFT FRONT SEAT BELT  
 BUCKLE AND RETEST PASS  
 INSTALLING AND TEST SYS REMOVE PASS SEAT AND REPLACE BUCKLE  
 ASBY AND INSTENT  
 INSPECTED SEATBELT BUCKLE, REPLACED PK SEATBELT BUCKLE  
 PERFORMED AIR SYSTEM DIAGNOSIS AND FAULT CODE RETRIEVAL, FAULT  
 LFC48,DRIVERS SIDE SEATBELT PRETENSIONER FAULT, REMOVED AND  
 REPLACED DRIVERS SIDE SEATBELT PRETENSIONER ASBY ROAD  
 TESTED,ALL SYSTEMS ARE  
 WORKING PROPERLY.  
 1 STEERING COLUMN DMS, AIR BAG DIAG, PINPOINT TEST, ESD, FOUND  
 BOTH PASSENGER AND DRIVER PRETENSIONERS TO BE BRK,  
 SEAT BELTS WONT LATCH, REPLACE SEATBELTS  
 RETRIEVE CODES IF PINPOINT TEST UNPOINTS TO HIGH PRETENSIONER  
 REPAIR LOOSE CONN, RETEST CODES WILL PRESS REPL, RIGHT FRONT  
 PRETENSIONER  
 VERIFY CONCERNS/DIAG CODE B1407, PINPOINT TEST HIGH  
 RESISTANCE, REPLACED DRIVERS SEATBELT BUCKLE  
 DOES NOT OPERATE FROM PK SEATBELT ASSEMBLY FRONT  
 REPLACE DR SIDE

8000 HIGH RESISTANCE CHECKED AIR BAG LIGHT INTERMITTENTLY  
 FLASHING, PERFORMED PCM SYSTEM SELF TESTS, RETRIEVED CODE  
 B1877, PERFORMED PINPOINT TESTS, MONITORED DRV BNS &  
 PASSENGERS SIDE PRETENSIONER  
 HQ8 TECH DTC B1877 PINPOINT TEST REPLACE SEAT BELT BUCKLE  
 PRETENSIONER INSTENT OK  
 148 DUPLICATE CUSTOMER CONCERN PROBLEM DETERMINED TO BE IN BUCKLE  
 ASBY ORDER REPLACEMENT REMOVE SEAT ASBY REMOVE AND REPLACE BNS PART OF BNS SYSTEM  
 SEAT BELT BUCKLE ASBY. REWORK ALL OKAY. WBS TEST SYSTEM DUE TO  
 BUCKLE IN  
 DRIVER SEAT BELT BUCKLE WONT LOCK DUE TO INTERNAL MECHANISM  
 FAILURE IN AND IN THE LF SEAT BELT BUCKLE ASBY  
 DIAGNOSIS FOR AIR BAGS HAD DPC B1877, REPLACE DRIVER SEAT BELT  
 PRETENSIONER THAT HAS AN OPEN CIRCUIT. 1  
 BOTH FRT SEATBELT BUCKLE ASBYS FAILED RECALL 01881 SEATBELT  
 INSPECTION, CASES DOESNT SHOW THIS VEHICLE AS BEING INVOLVED IN  
 RECALL ISSUE, REPLACED BOTH FRT SEATBELT BUCKLE ASBYS AS SAFETY  
 LIABILITY IS  
 REPLACE LEFT AND RIGHT SEAT BELT BUCKLES

MONITOR, RETEST PASSENGER,  
 ROADTESTED OK

WORKING PROPERLY.

BR CIRCUIT RES DISTANCE  
 DRIVERS SIDE AT 11.3 OHMS.  
 REMOVED DRIVERS SIDE  
 SEAT. REPLACED SEAT  
 BUCKLE FROM TENSIONER &  
 REASSEMBLED. CLEANED  
 CODES & ROAD TESTED OK  
 RETURN FROM SELF

SUB LISTED AS IN TIME. NO  
 OPEN PURLS SHED FOR BUCKLE  
 REPLACEMENT.

X	Other	CUSTOMER STATES AIRBAG LIGHT ON WAS FLASHING NOW ON ALL THE TIME	789
R	Recall Performed	RECALL 01881 PK SIDE BND 1LEZ 1081908 AAA	816
R	Recall Performed	JOB RECALL IN 821 SEAT BELT PASSENGER SIDE.	864
X	Other	LF DRIVERS BUCKLE CO BE ACTIVATE AIR BAG SYSTEM SPECIAL PARTS FOR SEAT BELT HAS ARRIVED PLEASE INSTALL DRIVER SIDE	418
X	Other	CUSTOMER STATES AIRBAG LIGHT IS FLASHING	590
X	Other	SEAT BELT BUCKLE	872
X	Other	SUSPECT SEAT BELT BUCKLE	804
X	Other	AIR BAG LIGHT ON	828
X	Other	AIR BAG LIGHT FLASHING	394
X	Other	CUST STATES THE AIR BAG LIGHT COMES ON AT TIMES	281
X	Other	AIRBAG LIGHT CAME ON, CHECK CAUSE	734
B	Won't Stay Latched	RIGHT SEAT BELT WILL NOT STAY BUCKLED	488
X	Other	AIR BAG LIGHT IS ON	882
X	Other	CUSTOMER SAYS AIR BAG LIGHT FLASHING ON AND OFF THEN AIR BAG LIGHT STAYS ON CONSTANTLY	872
A	Won't Latch	SEAT BELTS WILL NOT LATCH PROPERLY	818
X	Other	CUSTOMER STATES AIR BAG LIGHT STARTS FLASHING AND THEN STAYS ON STEADY	888
X	Other	CUSTOMER STATES AIRBAG WARNING LIGHT FLASHES WHILE DRIVING	308
X	Other	AIRBAG LIGHT IS FLASHING (1 THEN 4)	800
X	Other	AIR BAG LIGHT FLASHES	718
X	Other	AIRBAG LIGHT IS ON	304
C	Unlatches/Release	CUSTOMER STATES DRIVERS SIDE SEATBELT COMES UNLATCHED, DRIVES AND ADVISE	812
A	Won't Latch	SEAT BELT INCF	
X	Other	1 CUSTOMER STATES AIR BAG LIGHT FLASHING	714
R	Recall Performed	PERFORM RECALL 01881 REPLACE SEAT BELTS PER INSTRUCTIONS	801
R	Recall Performed	RECALL 01881	358



1188 SEAT BELT BUCKLE AS CHECK AIR BAG LIGHT FLASH OR PERFORMED NBS AND DIAGNOSTIC FROM MIDDLE MINORITY CODE 01877 SEAT BELT DRIVE PRETENSIONER OPEN DKT, CLEAN CODE AND PERFORMED ON DEMAND BELT TEST SA	ME CODE ON DRIVE SIDE, PERFORMED DIAGNOSTIC FROM FRONT TEST DRIVE SIDE BUCKLE CONNECTOR FOUND OPEN CIRCUIT REPLACED NEW DRIVE SIDE SEAT BELT BUCKLE AND CLEAN MEMORY CODE AND PERFORMED ON	X	Other	806 ...OWNER REPORTS INTERMITTENT AIR BAG LIGHT COMES ON INTERMITTENTLY	407
AIR BAG DIAG, INSPECT SEAT BELT, REPLACE DRIVERS SIDE SEAT BELT BUCKLE		X	Other	598 AIR BAG LIGHT ON INSTALL 80P SEAT BELT	727
TEST AIR BAG SYSTEM CODE 01881 RAN PIN POINT TESTS FOUND FAULTY RP PRETENSIONER RAS PRETENSIONER RESIST OK		X	Other	CUSTOMER SAYS AIR BAG LIGHT COMES ON SOMETIMES FLASHES SOMETIMES	541
VERIFY CONCERN AIR BAG DIAG SELF TEST 01877 PINPOINT TEST ELFO TEST T PRETENSIONER HIGH RESISTANCE DISCONNECT AIR		X	Other	AIR BAG LAMP IS ON	587
0801 CODE 42 840 DRIVERS SEAT BELT PRETENSIONER LIGHT WAS NOT ON INSTALLED NBS AND CHECKED FOR CONT. AND ON DEMAND CODES ONLY STORED (844 CONT., PERFORMED PINPOINT TESTS FOR CODE 1844 WITH NBS W	ENT INTO PID DATA AND CHECKED RESISTANCE OF BOTH DRIVERS AND PASS PRETENSIONER BUL BOTH READ 2.1 OHM WAGGLED DRIVERS WIRE AND DID NOT CHANGE RESISTANCE. REMOVED DRIVERS 80 BENCH SEAT	X	Other	C/S AIR BAG LIGHT WAS FLASHING UNTIL THIS MORNING.1 CUST STATES THE AIR BAG LIGHT WILL FLASH WHEN ENGINE STARTED AND STAY ON WHILE DRIVING INTERMITTANTLY	216
NOP SEATBELT ASSEMBLY FRONT REPLACE		X	Other		487
1 OPEN 20 TIME TO DIAGNOSE RUM CODES ON GEM MOD WITH WDS (NO CODES) TIME TO MONITOR PIDS WITH WDS WHILE OPERATING BELT LATCH TIME TO RUN PINPOINT ON BELT TIME T TO RUN CONTINUITY AND CHECK FOR 840	ITS TO POWER AND GROUND TIME TO TEST CIRCUIT IN PRETENSION LATCH (WHEN MOVED SHOULD OPEN IN LATCH EVEN WHEN LATCHED) TIME TO REPLACE PRETENSIONER LATCH TIME TO RA DRIVERS SEAT TO	X	Other	808 SEAT WARNING CHIMES STAY ON SEAT BELT CHIMES SEAT BELT LIGHT FLASHES EVEN WITH SEAT BELTS BUCKLED	872
INSTALL, NBS RFR LB SEAT OPEN 607 RFR SEAT SEAT BELT PRETENSIONER REINSTALL SEAT RETEST		X	Other	AIRBAG LIGHT ON	513
RESISTANCE HIGH PERFORMED TO ADJECTIVE RP BUCKLE ANY		X	Other	SEATBELT NOP ON DRIVER SIDE	778
NOP SEATBELT ASSEMBLY FRONT REPLACE		X	Other	AIR BAG LIGHT ON	
OPEN DKT. REPL					
80P DRIVERS SEAT BELT LATCH GOOD THE SEAT BELT SYSTEM AND R THE DRIVERS SEAT AND REPLACED THE SEAT BELT LATCH		A	Wont Latch	CUSTOMER STATES DRIVERS SIDE SEAT BELT LATCH WILL NOT LATCH	483
TEST AIR BAG SYSTEM WITH PINPOINT TEST ON PASS SIDE PRETENSIONERS CIRCUITS REPLACE TENSIONER AND AIRBAG MODULE					
REMOVE WIRE TO TEST HARNESS FOR SHORT TO GROUND FOUND ONE SPOT THAT MAY HAVE OVERLAY NET		X	Other	OK AIR BAG LITE ON	403
INTERNAL PROBLEMS REPL BUCKLE	80T REINSTALL CARPET	X	Other	AIRBAG LIGHT ON	
IS OK AND VERIFY NECESSARY TO REPLACE BUCKLE		X	Other	840 PASS 840 SEAT BELT NOP CUST STATE	684
AIRBAG SYSTEM DIAGNOSTICS PINPOINT TEST OK REPLACED DRIVERS SIDE SEATBELT PRE TENSIONER, TEST DRIVE RETEST, OK		X	Other	OK AIRBAG LIGHT IS FLASHING ON OFF	610
SEAT BELT BUCKLE NOT OPERATING PROPERLY IN TIME TO REPLACE INSTALLED NEW SEAT BELT BUCKLE, ENTERED AT WPI		X	Other	SEAT BELT NOP CAN T BUCKLE DRIVERS SEAT BELT	606
NOP SEATBELT ASSEMBLY FRONT REPLACE		A	Wont Latch	CUSTOMER STATES LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH	380
41 STICKING REPLACED SEAT BELT BUCKLE		A	Wont Latch	DRIVERS SEAT BELT WONT LATCH	410
DRIVE SEAT BELT WILL NOT STAY BUCKLED CC 48 REMOVE DRIVE SEAT AND REPLACE BUCKLE ASSEMBLY PARTS TURNED INTO T.L. QUALITY CHECKED BY BARRY H.		C	Unaddressed/Resolved	CUSTOMER STATES THE DRIVER SEAT BELT COMES UNBUCKLED INTERMITTENT. ADVISE	815

VERIFIED CUST CONCERN OF AIR BAG LIGHT BEING ON, FOUND PROBLEM IN THE BELT PRETENSIONER; SEAT BELT HAD OPEN CIRCUIT, REATTACHED WIRING IN PRETENSIONER, AIR BAG LIGHT OUT NOW.  
PERFORM DIAGNOSTIC TESTING CODE B1677 REPLACE DR SIDE PRETENSIONER AND RETEST

REPLACED SEAT BELT  
REPLACED DRIVERS SIDE LATCH

TRACED PROBLEM TO AN INTERMITTANT FAULT INSIDER PRETENSIONER  
REPLACE PRETENSIONER

FAULTY PAS PRETENSIONER REFL BUCKLE  
PERFORMED DIAGNOSIS AND REPLACED SEATBELT  
REPLACED RT FT BUCKLE WITH PRETENSIONER

AIRBAG LIGHT STAY ON SUSPECT PASSENGER SEAT BELT INTERNAL FAILURE  
REPLACED BELT

DRIVE INSTALL NEW SEATBELT TESTED NEW SEATBELT SOME BSM VERIFY CONCERN, REC TEST CODE FOR OPEN IN SEAT BELT TENSIONER.  
MONITORED PROBS FOUND RESISTANCE AT SENSOR. REMOVED DRIVERS SEAT BENCH REPLACED SEAT BELT PRETENSIONER. NO LABOR OPS TO R AND R DRIVE

INITIATED THE NEW SEAT BELT BUCKLE

PRETENSIONER VERIFIED CONCERN, DIAG & TEST, REC TO REPLACE SEATBELT PRETENSIONER, RETEST CUC

JOB SO WARR. VERIFIED CONCERN AIRBAG LIGHT ON/NOIS TEST AND RETURNED CODE B1677 PASSENGER SEATBELT PRETENSIONER OPEN/R  
RIGHT FRONT SEAT AND REPLACED SEATBELT BUCKLE CLEARED CODE/ALL OK

DOES NOT OPERATE PROPERLY SEATBELT ASSEMBLY FRONT  
REPLACE

RP SEAT BELT INOP, LATCH INOP, REPLACED BUCKLE  
SEAT BELT INTERNAL FAILURE, REPL

DRIVERS BUCKLE INOP BROKERN PERSONED DRIVERS SEAT REMOVED OLD BUCKLE INSTALL NEW BUCKLE AND BSA Y AND TEST  
INSPECTED DRIVERS SIDE SEAT IT WAS LOOSE AND THE SEAT BELT BUCKLE WAS MISSING. NEEDED TO INSTALL A SEAT BELT BUCKLE AND PUT THE SEAT BACK

CHECK OUT PROBLEM CODE B1677 PROBLEM IN DRIVER SEAT BUCKLE  
CHECK PIN POINT TEST REPLACE

100 PASS FRONT SEAT BELT INOP REPLACED PASS FRONT SEAT BELT BUCKLE DUE TO NOT WORKING PROPERLY @ 491288

RP SEAT BELT BUCKLE ASBY

NO AIRBAG LIGHT ON, TESTED AIRBAG SYSTEM WITH HSB, PULLED CODE B1677, CHECKED FAILURE CLEAR CODE, RETESTED ON DEMAND ALL PASS,  
MONITORED PID ALL WITHIN SPECS, ROAD TESTED AIRBAG LIGHT SAME ON, PULLED

2888 42 W PERFORMING AIR BAG DIAGNOSIS (EMANU) PID DATA MONITOR TESTS, NO CODES PERFORM PREPONT TESTS FOUND LT FRNT SEAT BELT WITH PRETENSIONER INOP REMOVE LT FRNT SEAT ASSEMBLY TO ACCESS AND REPLACE

BS DRIVERS PRE TENSIONER VERIFIED CUSTOMER CONCERN, HOOKED UP HSB TO FULL CODES FROM PCM FOUND CODE B1677, PERFORMED PASSIVE RESTRAINT PREPONT TEST T FROM SERVICE MANUAL, FOUND PASSENGER DE  
OK & FOUND SEATBELT BAD REPLACED & RECHECKED OK  
FOUND PART OF THE LATCHES MISSING PART FAILURE DUE TO PART BROKUE REPLA

1188 WBS BSW VEHICLE FOUND R H SEAT BELT INOP LATCHING, REMOVED SEAT REPLACED SEAT BELT LATCH  
REPLACE COMPLINE

R BENCH SEAT FOR ACCESS

X	Other	CUST STATES AIR BAG LIGHT ON	612
X	Other	RTS AIRBAG LIGHT WAS FLASHING 3 TIMES THEN 4 TIMES THEN STAYED ON	407
X	Other	DRIVER SEATBELT WILL NOT LOCK	919
A	Won't Latch	DRIVERS SEAT BELT WILL NOT LATCH	888
X	Other	AIR BAG LIGHT FLASHING	.
X	Other	AIR BAG LIGHT ON	.
X	Other	DRIVER SIDE SEATBELT INOP. BCP	508
X	Other	ADVISE ON RT FT SEATBELT BUCKLE INOP	513
X	Other		.
A	Won't Latch	RT FT SEAT BELT DOES NOT LATCH	794
X	Other	CUSTOMER STATED THAT THE AIRBAG LIGHT IS FLASHING	757
A	Won't Latch	R SEAT BELT BUCKLE WONT LATCH BUCKLE HAS AN INTERNAL FAILURE	.
X	Other	AIRBAG LIGHT FLASHES 4 6	352
X	Other	888 A	504
X	Other	DR SEAT BELT HARD TO LATCH	PARTS ORDERED 605
X	Other	AIR BAG LIGHT ON	.
X	Other		.
A	Won't Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH	714
X	Other	DRIVER SIDE FRONT SEAT LOOSE	619
X	Other	CUSTOMER STATES THAT AIR BAG LIGHT FLASHES 48 THEN STAYS ON SOLID	614
X	Other	PASS SEAT BELT BUCKLE INOP	282
X	Other	VEHICLE FRONT RH SEAT BELT BUCKLE INOP	.
X	Other	CHECK AIR BAG LITE STAYS ON	608
A	Won't Latch	CUSTOMER STATES THE DRIVERS SIDE SEATBELT BUCKLE WILL NOT LATCH IN HOLDER AT ALL, PLEASE INSPECT AND ADVISE BY TRIM CODE 6T	678
X	Other	AIR BAG LIGHT IS ON AND FLASHING	281
A	Won't Latch	SEATBELT WILL NOT LATCH	228
A	Won't Latch	SEAT BELT BUCKLE, DONT LATCH	.
A	Won't Latch	OK DRIVERS SEAT BELT WILL NOT LATCH	601
X	Other	SEATBELTS STICKING	628

VERIFIED CONCERN, FOUND ALL THREE SEAT BELT BUCKLES IN REGULAR  
 CAR FAILED SEAT BELT BUCKLE TESTS. REPLACED DRIVER SIDE,  
 PASSENGER, AND CENTER SEAT BELT BUCKLE ASSEMBLIES. INTERESTED  
 NORMAL AFTER REPAIRS  
 VERIFY CONCERN FOR DRIVERS SEAT, REPLACE BUCKLE.  
 VERIFY CONCERN REMOVE AND REPLACE INOP ASY

REPLACED SEAT BELT RETENTIONER

REPLACED RIGHT FRN SEAT BELT BUCKLE, BUCKLE WOULD NOT LATCH  
 VERIFIED CONCERN REPLACED BUCKLE CHECKED GOOD.  
 4434 41 81128A 8LY 8287 REPLACED RT. SEATBELT BUCKLE ASMY; QC  
 CHECK BY TECH  
 REPLACED SEAT BELT  
 REPLACE MIDDLE SEAT BELT BUCKLE  
 1 1 REPLACED BOTH FRONT SEATBELTS,  
 CENTER SEAT BELT NOT BOLTED TOP FLOOR 48 INSTALL CENTER SEAT  
 BELT 840  
 FOUND BUCKLE NOT CATCHING. R AND R PASS SIDE BUCKLE TO  
 CORRECT/READY.

COMPLETED INSTALLATION OF SPECIAL ORDERED PART AS REQUESTED  
 8888 REPLACED PASSENGER SEAT BELT LATCH + TEST. \*\*\* QUALITY  
 CONTROL BY JOHN MEDICIN \*\*\*  
 DRIVERS SIDE SEAT BELT DOES NOT RECORD, IT HAD TO BE REPLACED  
 INSTALL AND REPLACED DRIVER SIDE SEAT BELT

REMOVED DRIVER SIDE BELT FOR COMPLETION. INSTALL NEW  
 PASSENGER SIDE SEAT BELT. INSTALLED DRIVER SIDE SEAT BELT THAT  
 WAS BROKEN  
 REMOVED PASSENGER BELT ONTO VEHICLE STROD TO FINISH DRIVERS  
 FAILED INSTALLED DRIVER BELT INSTALLED BELT ON PASSENGER SIDE  
 THAT WAS ORDERED TECH 834 8811  
 R R PASSENGER FRONT SEAT BELT. LATCH WAS BAD.

REMOVED AND REPLACED DRIVERS SEAT BELT BUCKLE  
 REPLACE RIGHT FRONT SEAT BELT BUCKLE  
 87 TECH 88 REPLACED PASSENGER SIDE FRONT SEAT BELT

BUCKLE WILL NOT LATCH SEATBELT ASSEMBLY FRONT REPLACE  
 CHECK CONCERN AND FOUND DRIVERS SEAT BELT RECEPTACLE  
 BAD/ORDER PART INSTALL NEW SEATBELT RECEPTACLE AND VERIFY  
 OPERATION

TECH 146 VERIFIED AND REPLACED SEAT BELT RECHECKED OPERATION  
 REMOVED SEATS AND REPLACED SEAT BELT BUCKLES THAT WERE TAKEN  
 OUT OF STOCK UNIT REPLACED BUCKLES IN STOCK UNIT  
 84 REPLACE PASS SIDE BELT  
 1. REPLACED SEAT BELT AS PER RECALL. . . . .  
 1 REPLACED BOTH SEAT BELTS.  
 REPL. SEATBELTS  
 1 REPLACED PASS SEAT BELT.  
 1 REPLACED PASS SEAT BELT  
 17 PULLED THE PASSENGER SEAT OUT TURNED IT UP SIDE DOWN PULLED  
 THE SEAT COVER BACK TOOK OLD BELT BUCKLE, OUT REPLACE IT WITH A  
 NEW ONE  
 CONFIRMED CONCERN INSPECTED AND FOUND THE PRETENSIONER  
 SOUND UP-ORDERED PARTS. REMOVE DRIVER SEAT AND REPLACE SEAT  
 BELT BUCKLE.

	Unlatches While		
D	Driving	CUSTOMER STATES ALL SEAT BELTS WILL COME LIMOOOE WHILE DRIVING.	817
A	Won't Latch	CUST STATES THAT THE DR SEAT BELT WILL NOT BUCKLE	824
A	Won't Latch	CUST STATES PASS FRONT SEAT BELT BUCKLE WILL NOT LATCH INSPECT SEAT BELT BUCKLE FOR PROPER RETENTION DRIVERS SIDE NEEDS BUCKLE	782
X	Other		830
A	Won't Latch	PASSENGER SIDE FRN SEAT BELT BUCKLE WILL NOT LATCH	765
A	Won't Latch	PASSENGER SEAT BELT DOES NOT LATCH SOMETIMES.	800
X	Other	CUNT STATES RIGHT FRONT SEAT BELT BUCKLE INOP,	809
X	Other	CHECK SEAT BELT IS HARD TO BUCKLE	812
X	Other	BUCKLE SEAT BELT BUCKLE WORKS ERRACTIC	817
A	Won't Latch	SEAT BELTS NOT LOCKING.	820
X	Other	CUSTOMER STATES CENTER SEATBELT NOT CONNECTED	409
A	Won't Latch	CUSTOMER STATES THAT PASS SIDE SEATBELT BUCKLE DOES NOT LATCH. CUSTOMER REQUESTS INSTALLATION OF SOP PARTS. SEAT BELT BUCKLE	851
X	Other		884
A	Won't Latch	PASSENGER SEAT BELT WILL NOT CLIP	817
X	Other	INSTALL SEATBELT	840
X	Other	O B SEATBELT BUCKLE INOP PER CUSTOMER	824
A	Won't Latch	LJ SEATBELT WILL NOT HOLD	882
X	Other	CUSTOMER STATES SEAT BELT FAILED.	802
R	Recall Performed	DRIVER SIDE SEAT BELT FAILED INSPECTION .	806
A	Won't Latch	CUST STATES PASS SIDE SEAT BELT BUCKLE WILL NOT LATCH SOP IN	501
X	Other		820
X	Other	WP SEATBELT WILL NOT LATCH PROPERLY	880
X	Other	( ) PASSENGER SIDE SEAT BELT IS NOT WORKING	814
A	Won't Latch	C B PASSENGER SIDE FRONT SEAT BELT WILL NOT HOLD 840	818
	Unlatches While	CUNT STATES DRIVERS SEAT BELT HAS UNLATCHED 8 TIMES GOING DOWN HAY CR AND ADVISE WILL NOT LATCH AT THIS TIME	770
D	Driving		
X	Other	CUSTOMER STATES SEAT BELT LIGHT AND ALARM WILL GO OFF WITH SEATBELT FASTENED.	398
X	Other	OK FOR DRIVING SIDE SEAT WILL RETRACK BLOW SPECIAL ORDER PARTS	734
X	Other	STATES THAT THE FRN SEATBELTS WILL NOT FASTEN PROPERLY	488
R	Recall Performed	CAMPAIGN 01021	418
B	Recall Performed	CUSTOMER STATES THAT THE PASSENGER SIDE SEAT BELT FAILS	308
K	Other	CUSTOMER STATES THAT BOTH SEATBELTS FAIL	303
K	Other	BOTH SEATBELTS INOP.	302
K	Other	CUSTOMER STATES THAT PASSENGER SIDE SEATBELT FAILS	303
K	Other	CUSTOMER STATES THAT THE PASSENGER SIDE SEAT BELT FAILS	303
R	Recall Performed	RECALL 81801 SEATBELT INSPECTION	308
B	Won't Stay Latched	CUNT STATES THE DR SEAT BELT WILL NOT STAY LATCHED	851



ROAD TEST FLASH CODE 48888 TEST DTC B177, PMPONT TEST REPAIRS HIGH RESISTANCE IN CIRCUIT 1879 LD RD UNDER SEAT REPLACED DRIVER PRETENSIONER CLEARED CODES AND ROAD TEST AFTER REPAIRS OK. REPLACED PASSENGER SIDE SEAT BELT

8888 SEAT BUCKLE. 42 DNOP VERIFIED CONCERN OF PASS FRONT SEAT BELT NOT LATCHING PROPERLY. REMOVED PASS FRONT BUCKET SEAT AND REPLACED PRETENSIONED SEAT BELT BUCKLE REASSEMBLED VEHICLE AND VERIFIED

SEAT BELT BUCKLE REPLACE NOT WORKING CORRECTLY 5888 RAR LEFT FRONT SEAT ASBY, REPLACE PRETENSIONER SEAT BELT END. SEAT BELT WORKING NOW. CO 42 CP 108888 MY EQUALS TIME TO REPLACE SEATBELT BUCKLE DRIVERS SIDE

REPLACE SEAT BELT BUCKLE  
REPL YF SEAT PRETENSIONER

1124 DRIVERS SEATBELT BUCKEL HAS INTERNAL SHORT WARRANTY RM DRIVERS SEAT REPLACED SEAT BELT LATCH AIR BAG DIAGNOSIS CODE B1877 PMPONT TEST. REPAIR/DONE WIRE AT PRETENSIONER CONNECTION

8428 CUSTOMER STATES AIR BAG LIGHT COMES ON. PERFORM AIR BAG SYSTEM DIAGNOSIS, DTC B1877 DRIVERS SEATBELT PRETENSIONER CIRCUIT OPEN. CHECK WIRING AND CONNECTIONS TO PRETENSIONER. OKAY. REMOVE DRUG  
REPLACE LEFT FRONT SEAT BELT BUCKLE WILL NOT LATCH

REPLACED LEFT FRONT SEAT BELT BUCKLE. WILL NOT ALWAYS LATCH

1 FOUND DRIVERS SIDE SEATBELT BUCKLE JAMMED. REMOVED DRIVERS SIDE SEAT FROM VEHICLE AND REMOVED AND REPLACED SEATBELT REPLACE PRETENSIONER ASBY WPI

R88 RIGHT FRONT SEAT AND REPLACE BUCKLE, AND CLEAR CODE 1  
REPLACED SEAT BELT, FRONT LATCH

W P SOP 42 1881208 REPLACE DRIVERS FRONT SEAT BELT BUCKLE PRETENSIONER  
VERIFIED CONCERN/SEAT BUCKLE WONT STAY LATCHED ALL THE TIME REPLACED BUCKLE

B17 D AND L BEALERS REMOVE AND REPOSITION LEFT DOOR SEAL OPEN CIRCUIT CHECK OUT BY FOUND OPEN IN PRETENSIONER REPLACE DRIVER

1288 CODES REPLACED RIGHT FRONT PRETENSIONER SEAT BELT BUCKLE/OPERATED PROPERLY

8888 LF SEAT BELT WILL NOT LATCH, CHECKED, FOUND BAD BUCKLE, ORDERED NEW BUCKLE, DEACTIVATED AIR BAG SYSTEM, REMOVED LF SEAT, R R SEAT BELT BUCKLE-UP, REINSTALLED SEAT, REASSEMBLED AIRBAG SYSTEM, C

PROPER OPERATION AFTER REPAIR

RS SEAT AND REPLACE SEAT BELT BUCKLE PRETENSIONER ASSEMBLY. CLEAR CODES AND RETEST, OKAY (88) PERFORM QUALITY CHECK

CHECKED,

X	Other	AIR BAG LIGHT FLASHES WHEN DRIVING. RECHECK 112	414
X	Other	REPLACE BUCKLE SEAT BELT ASBY OR ET)	988
A	Won't Latch	O B PASS FRONT SEAT BELT WILL NOT LATCH SOMETIMES OK , ,	417
X	Other	SEAT BELT BUCKLE RETENTION	308
X	Other	DRIVERS SEAT BELT IN OP	348
A	Won't Latch	CUSTOMER STATES THAT SEATBELT DOESNT ALWAYS LATCH	414
A	Won't Latch	DRIVERS SIDE FRONT SEATBELT BUCKLE WONT CLASP OR HOLD	
A	Won't Latch	WARNING LIGHT AND CHIME WONT COME ON	818
A	Won't Latch	CUSTOMER STATES THAT THE R P SEATBELT WILL NOT LATCH	878
X	Other	G STATES THAT WHEN SEATBELT IS FASTENED AFTER A FEW BLOCKS OF	
X	Other	DRIVING THE SEATBELT CHIME WILL SOUND AND YOU MUST WIGGLE SEAT	452
X	Other	BELT TO STOP CHIME CHECK AND ADVISE.	
X	Other	CHECK AIR BAG LIGHT ON	328
X	Other	836 AIR BAG LIGHT ON, OWNER STATE	608
A	Won't Latch	REPAIR SEAT BELT	818
A	Won't Latch	SEAT BELT BUCKLE WILL NOT LATCH	318
A	Won't Latch	CUSTOMER STATES DRIVERS SIDE SEAT BELT WILL NOT LATCH	821
X	Other	SOP FOR SEAT BELT BUCKLE AIR BAG LIGHT WAS ON.	328
X	Other	CUSTOMER STATES SEATBELT INOP	418
X	Other	DRIVERS SIDE SEAT BELT IS INC. DCT30	248
B	Won't Stay Latched	CUSTOMER STATES THAT PASSENGER RT. PRT. SEAT BELT BUCKLE WONT	284
X	Other	STAY LATCHED	
X	Other	SURELY. CUSTOMER STATES HAS AN AIR NOISE DRIVING DOOR AND DOOR	814
X	Other	HARD TO CLOSE CHIME WILL SHOW	
A	Won't Latch	AIR BAG LIGHT ON	
A	Won't Latch	8 88 CUSTOMER STATES THE PASSENGER SIDE SEATBELT WILL NOT	218
A	Won't Latch	LATCH IN AND LOCK	
A	Won't Latch	848 L F SEAT BELT WONT LATCH	878



REPLACED LEFT SIDE LAP BELT WOOD NOT LATCH PART# NUMBER 812318 AND PERFORMED TESTING FOUND PRE TENSIONERS BAD REMOVED FROM AND HER STOCK UNIT AND INSTALLED NEW SEAT BELT BUCKLES OK NOW COMPLETE RECALL 8 PASS FRONT SEAT BELT BUCKLE WILL NOT LATCH AM SEAT TO REPLACE BUCKLE ASSEMBLY. REPL. FR SEAT BELT BUCKLE

REPLACED DRIVER SEAT THAT WOULD NOT LATCH. BUCKLE WONT SNAP THE SEAT BELT. REPL. NEW BUCKLE 1206 REPLACE DRIVERS SEAT BELT BUCKLE. INSPECT & REPLACE RT FRNT SEAT BELT BUCKELS WONT LATCH(BUCKEL BIND BELT BUCKLE INOP REACHED RT PASS SEAT TO GAIN ACCESS TO BUCKLE REPLACED BELT BUCKLE X REPLACED LEFT FRONT SEAT BELT BUCKLE

REPLACED DRIVER SEAT BELT BUCKLE WILL NOT LATCH BECC R R SEAT

2477 41 MI VSRUPED CONCPRA INSPECTION FOUND RT FRNT SEAT BELT BUCKLE INTERNALLY BINDING, REPL. AGED BUCKLE AND RETEST, OK REPLACED SEAT BELT BUCKLE

1163 PERFORM AIR BAG SYSTEM DIAG, CODE 51, TRACE AND REPAIR DAMAGED CONNECTOR AND RETEST, REPLACE ONE FUSE AND RETEST, R AND R DRIVERS SEAT AND REPLACE SEAT BELT BUCKLE AND RETEST OK BURNT OUT AIR BAG RESTRAINT SYSTEM DIAGNOSIS, REPLACE LEFT FRONT SEAT BELT BUCKLE PRE TENSIONER TECH INSTALLED DRIVERS FRONT SEATBELT BUCKLE DUE TO NOT LOCKING INTO PLACE PROPERLY

BELT BUCKLE WILL NOT LATCH WITH SEAT BELT, REMOVE OLD SEAT BELT BUCKLE, INSTALL REPLACEMENT SEAT BELT BUCKLE, TESTED, DRIVER FRONT SEAT BELT BELT BUCKLE WORKING PROPERLY AT THIS TIME.

3647 EXAMINE CONCPRA TESTED PASSENGER SEAT BELT FOR OPERATION, AT THIS TIME CAN NOT VERIFY ANY PROBLEM WITH PASSENGER FRONT SEAT BELT. TESTED DRIVER FRONT SEAT BELT BUCKLE FOUND THAT THE SEAT DRIVE SIDE SEAT BELT BUCKLE STUCK LOCK SPRING INSIDE. INTERNAL BUCKLE REPL. NEW BUCKLE R AND R SEAT BELT AND REPLACED TO CORRECT

CHECK FOR DOORS AIR BAG LIGHT ON WHEN PERFORM DIAGNOSIS CHECK AND DIAG REMOVED DRIVER SEAT AND REPLACED DRIVER SEAT BELT ASSEMBLY RECHECK AND REASSEMBLE RECHECK ALL PASS REPLACE RT SIDEBELT BUCKLE FOUND BUCKLE ON DRIVERS SIDE BROKEN. REPLACED DRIVERS SIDE SEAT BELT

HOOK UP NDS, RUN SELF TEST, RUN OIL DISPLAY, RUN PREPONE TEST ON PASSENGER SIDE SEAT BELT BUCKLE FOUND BUCKLE BAD, R AND R PASSENGER SIDE SEAT, REPLACE BUCKLE, CLEAR CODES, RETEST. PASS FRONT SEATBELT WONT LATCH, REPLACED PASS FRONT SEATBELT BUCKLE AND RETESTED. OK BDC TESTED FOUND CODE 51 SELF PERFORMED PREPONE TEST PER SHOP MANUAL RFR BOTH AIR BAGS TO INSTALL SHORTING BARS. PERFORMED SOP INSTALLED

A	Won't Latch	CR DR SEAT BELT JAMS AT TIMES WONT LATCH OR RELEASE SO PART IN HERE 340	318
X	Other	AIR BAG LIGHT ON	318
R	Recall Performed	RECALL 01521 ALL O.K.	215
A	Won't Latch	PASS SEAT BELT WILL NOT LOCK	559
X	Other	AIR BAG LIGHT IS ON	
X	Other	CUSTOMER STATES THE AIR BAG LIGHT STAYS ON WHILE DRIVING.	313
A	Won't Latch	CUSTOMER STATES DRIVERSIDE SEAT BELT WONT CLIP.	606
A	Won't Latch	PASS BUCKLE INOP	
X	Other	DRIVERS SEAT BELT BUCKLE INWIP	757
X	Other	CUST STATES FRONT FRONT SEAT BELT (PASSAGE) WILL NOT RELEASE SEAT BELT UNLESS YOU PULL ON BUCKEL.	612
X	Other	FT PASS SEAT BUCKLE INOP	
A	Won't Latch	CHECK FOR LEFT FRONT SEAT BELT DOES NOT BUCKLE	606
A	Won't Latch	STATES DRIVER SEAT BELT DOESNT LATCH	606
A	Won't Latch	325 RT FR SEATBELT WONT HOLD IN CATCH, PART IN STK.	318
X	Other	D-S SEAT BELT NOT WORKING	
X	Other	CUSTOMER STATES AIR BAG LIGHT FLASHES	285
X	Other	CUST STATES AIR BAG LIGHT IS ON	407
X	Other	CUSTOMER STATES PLEASE INSTALL SOP DRIVERS FRONT SEATBELT BUCKLE	318
X	Other	628 SEAT BELT PASSENGER FRONT INOP	313
X	Other	SEAT BELT INOP	
X	Other	OK PASSENGER FRONT SEAT BELT BUCKLE INOP. 545	778
X	Other	ADD ON REPAIR AIR BAG LIGHT IS ON	673
A	Won't Latch	340 RT SEAT BELT WONT LATCH	841
A	Won't Latch	CUST. STATES DRIVERS SIDE SEAT BELT BUCKLE WONT HOLD	264
X	Other	AIR BAG WARNING LIGHT TROUBLES	318
A	Won't Latch	CUST STATES THAT THE PASS SEAT BELT WILL NOT LATCH	704
X	Other		708

ESC TESTED AND FOUND CODE B868L. PERFORMED PINPOINT TEST. R AND R DRIVING SEAT TO TEST WIRE TO SAFETY BELT PRETENSIONER ALL OK. DEACTIVATED RESTRAINT SYSTEM TO R AND R AIR BAGS TO INSTALL DAG TOO	L. DCL DAG TO WATCH PIDS. FOUND PRETENS IONER AT B OTHER NECESSARY TO SPECIAL ORDER PRETENSIONER.	X	Other		100
1488 REPLACE RIGHT FRONT SEAT BELT COMP		A	Wont Latch	RIGHT FRONT SEAT BELT NOT BUCKLING	757
CAP ON BUCKLE BND LOOSE. RESECURED		X	Other	TRM CAP ON PASS SIDE SEAT BELT IS LOOSE	410
TRACK ASSEMBLY FRONT SEAT REPLACE		A	Wont Latch	PASS SIDE SEAT BELT WILL NOT LATCH	878
		X	Other		718
		X	Other		718
		A	Wont Latch	CUSTOMER STATES DRIVERS SEATBELT WILL NOT BUCKLE	504
		X	Other		
BUCKLE NOT LATCHING REPLACE DRIVER'S BUCKLE					
VERIFY CONCERNING REPLACE RIGHT FRONT SEAT BELT RECEPTACLE RECHECK OK		X	Other	DRIVER SEAT BELT BUCKLE IN OP.	815
PERFORM AIR BAG RESTRAINT SYSTEM DIAGNOSIS, PIN POINT TEST FOUND FAULTY DRIVER SIDE SEAT BELT BUCKLE ASSEMBLY OPEN REMOVE AND REPLACE DRIVER SEAT BELT BUCKLE IN TIME TO REPLACE. ROAD TEST, OKAY	REFUN FINAL QUICK TEST, PASS (OKAY)			CUSTOMER STATES AIR BAG LIGHT STAYS ON AT ALL TIMES WHILE DRIVING. VERIFIED FLASHING BEFORE STAYING ON AT ALL TIMES IN DRIVE (FLASHED CODE 81)	882
UP SEAT BELT DOESNT LOCK RE RE BELT AND REPL BUCKLE		X	Other		
REPLACED SEAT BELT ASBY		A	Wont Latch		
REPLACED RIGHT FRONT SEAT BELT BUCKLE.		X	Other	AIR BAG LIGHT ON	
PASS PRT SEAT SHOULDER BELT TRACK ASSEMBLY FRONT SEAT REPLACE		A	Wont Latch	CHECK RIGHT FRONT SEAT BELT WONT BUCKLE	706
OPEN CIRCUIT AIR BAG RESTRAINT SYSTEM DIAGNOSIS		X	Other	PASSENGER FRONT SEAT SHOULDER BELT DOES NOT BUCKLE INTO THE BUCKLE	714
REPLACED LEFT AND RIGHT SEAT BELT BUCKLES WERE SHOP		B	Wont Stay Latched	QUET STATES AIRBAG LIGHT ON LEFT AND RIGHT FRONT SEAT BELT BUCKLES DO NOT STAY LATCHED	904
	OR SEAT BELT BUCKLE HAVING INTERNAL SHORT REPLACED AND RETESTED FOUND NEW CODE B220 PASS SEAT AIR BAG MODULE LOW RESISTANCE REPLACED MODULE AND RETESTED CLEARED CODES AND RETESTED				
BAG REPAIRER ELED DAG FOUND AIR BAG LIGHT BLURSH 8 ON AND OFF TESTED RESTRAINT CONTROL. MODULE HAD CODE B886 RCM HAVING INTERNAL SHORT REPLACED MODULE AND RETESTED NEW CODE WAS FOUND B843A		X	Other	AIR BAG LIGHT STAYING ON	801
	RE CHECKED WIRING AT RCM WAS OK. HOT LINE BAG TO REPLACE PASS SIDE SEAT BELT BUCKLE WITH SWITCH AND TEST DRIVE 30 MILES HAD TO ACCESS CAPRET TO GET TO RCM NEED W TIME FOR SOME CP				
1888 42 HOOKED UP NBS AND GOT CODE B843B PIN POINT TEST R1 TO R6 BAG TO REPLACE RCM. CHECKED HISTORY RCM HAD BEEN REPLACED CALLED HOT LINE AND TALKED TO MINE JING TO CHECK WIRING AND CONNECTIO		X	Other	CUST STATES THAT AIR BAG LIGHT WAS FLASHING NOW IT STAYS ON ALL TIME RENTAL TO BE PAID FOR BY ESP	401
	B PRESENT IN ON DEMAND TEST, DEACTIVATE SYSTEM, ACCESS CAPRET TO ACCESS RCM (RESTRAINT CONTROL MODULE). RE CHECKED SHORT TO GROUND ON CIRCUIT IN R OK NO SHORT TO GROUND, RE CHECK				
2642 46 URGENCY CONCERN AIR BAG LIGHT COMER ON WHILE DRIVING, CHECK CODES B886 (PASSENGER SAFETY BELT BUCKLE SHORT TO GROUND), PERFORMED PIN POINT TEST R1: CHECK FOR A HARD OR INTERMITTENT BTC (CDD		X	Other	CUST STATES THAT AIR BAG LIGHT IS FLASHING RENTAL CAR TO BE PAID FOR BY ESP	486
VERIFY PINPOINT TEST; BUCKLE BROKEN. PAR SEAT TO ACCESS. REPLACE BUCKLE. RETEST; CLK		A	Wont Latch	DRIVER SEAT WONT BUCKLE	281
		X	Other	DRIVERS SIDE SEATBELT IS STILL STICKING WHEN RELEASING HAS TO PULL HARD TO RELEASE BUCKLE	352
5763		X	Other	CUSTOMER STATED THE SEATBELT IS NOT.	214
REPLACED SEAT BELT BUCKLE ON DRIVERS FRONT LEFT FRONT SEAT BELT WOULD NOT MOVE WAS BINDING REPLACED LEFT SEAT BELT		R	Other	RECALL #1481 REPLACE SEAT BELT BUCKLE	878
8842 REPLACE SEAT BELT.					





480 REPLACED SEAT BUCKLES AS PER RECALL 01821 VERIFY CONCERN REPLACED RIGHT FRONT SEATBELT WEAK AND NOT HOLDING TIED AND REPLACED BOTH SEAT BELTS AND BUCKLES DID W/ ROAD TEST PERFORMED AIR BAG DIAG NO CODES CALLED HOT LINE CONTACT 82222007 WAS TOLD POSS SEAT BELT SWITCH WAS INTERMITTENT OPEN TO REPLACED SEAT BELT BUCKLE AND SWITCH ASBY REMOVED D SEAT TO R REPLACED D SIDE SEAT BELT BUCKLE. M TIME FOR NO LABOR OPS REPLACE R SIDE SEAT BELT BUCKLE.	W	Went Day Labeled	CUSTOMER STATED THAT THE DRIVERS SEAT BELT WILL NOT STAY LATCHED	301
	A	Went Latch	RIGHT FRONT SEATBELT WILL NOT HOLD	301
	A	Went Latch	SEAT BELT BUCKLES WILL NOT HOLD	301
	X	Other	DRY CLIFT STATES AIR BAG LIGHT COMES AT TIMES HAVE TO TURN OFF SWITCH AND LIGHT GOES OFF	304
	X	Other	CUSTOMER STATED THAT D S SEATBELT DOES NOT WORK.	310
	X	Other	CUST SAYS PASS SIDE SEATBELT IS NOT WORKING	305
2108 42 W/ AIR BAG DIAGNOSTICS CODE B2409 DEMONSTRATE AIR BAG SYSTEM PROPOSED TEST #408 1 RESULT OPEN CIRCUIT TO SEAT SWITCH REPLACE SEATBUCKLE DEACTIVATE SYSTEM RETURN TEST #A LATCH LATCH ON SEAT BELT SWITCH INSIDE ASSEMBLY DRIVER FRONT SEAT REPLACE SEAT BELT LATCH FOUND SEAT BELT BUCKLE SWITCH DEFECTIVE. REPLACE DRIVER SEAT BELT BUCKLE AND RETEST #38 42	X	Other	AIR AIR BAG LIGHT GOES ON WHILE DRIVING THEN GOES OFF	305
	A	Went Latch	DRIVERS SIDE SEAT BELT WILL NOT LATCH AT TIMES	410
	X	Other	CUSTOMER STATED AIR BAG LIGHT IS ON	301
	X	Other		305
REPLACE LEFT FRONT SEAT BELT BUCKLE DEACTIVATE SW. REMOVE LEFT FRONT SEAT. REPLACE BUCKLE REACTIVATE SW. REMOVED BUCKLES FOR CUSTOMER CAR. REPLACED BOTH FRONT SEAT BUCKLES 1008 #1008, 41 #101000 0.8 REPLACE RIGHT FRONT SEATBELT BUCKLE, BANDS REPLACE LEFT FRONT SEAT BELT BUCKLE REPL BELT ASBY. REPLACE DRIVER SIDE SEAT BELT ASBY REPL LF SEAT BELT. #1000001 #0702 . REPLACED A FAULTY SEAT BELT BUCKLE ASSEMBLY TO CORRECT CONCERN REPLACED SEAT BELT LATCH XXXXXXXXXXXXXXXXXXXX FOUND SEATBELT BUCKLE IS BINDING. RR SEAT AND REPL RS SEATBELT BUCKLE. CLOSED AT WPL 13 CHARGE AIR BAG LIGHT FLASHING CONCERN VERIFIED CONCERN , NO DIAG CODES, CODES, CONT , BR428 HARD FAULT, PID DATA MONITOR, PPT P1 PL, REPLACED PASSENGER SEAT BUCKLE. CLEARED CODES. RETEST OK MPH 2	X	Other	REPLACE BOTH FRONT SEAT BELTS WHICH WERE REMOVED FOR GUEST VEHICLE #0 128413	318
	X	Other	DRY OK PRT PICKS SEAT BELT WONT BUCKLE	301
	A	Went Latch	DRIVERSIDE SEAT BELT WILL NOT BUMP IN ALSO OK ALL SEATBELTS	301
	A	Went Latch	CUST STATED DRIVERS SIDE FRONT SEAT BELT DOES NOT BUCKLE	301
	X	Other	INSTALL SCP FRONT SEAT BELT ASBY	718
	A	Went Latch	CUST STATED DRIVER SIDE FRONT SEAT BELT NOT BUCKLING	301
	X	Other		301
	X	Other	CUST STS DRIVERS SEATBELT BUCKLE IS NOT.	318
	X	Other		
	X	Other		
	X	Other		323
13 CHARGE AIR BAG LIGHT FLASHING CONCERN VERIFIED CONCERN , NO DIAG CODES, CODES, CONT , BR428 HARD FAULT, PID DATA MONITOR, PPT P1 PL, REPLACED PASSENGER SEAT BUCKLE. CLEARED CODES. RETEST OK MPH 2	X	Other	DRY AIR BAG WARNING LIGHT TROUBLE PERFORM RECALL 01821	425
	X	Other		214
REPLACE SEAT BELT BUCKLES TO INSURE OPEN CIRCUIT AIR BAG DIAG FOUND OPEN IN SEAT BELT BUCKLE REPLACED BUCKLE TEST OK FOUND DRIVER S BUCKLE SWITCH CIRCUIT OPEN TEST AND INSPECT AIR BAG TEST RETURNING DTC BR428 PROPORT TEST FOUND DRIVER S BUCKLE SWITCH CIRCUIT OPEN REMOVE SEAT FOR ACCESS REMOVE REPLACE BUCKLE RE METAL MANUFACTURER RECALL SEATBELT INSPECTION	X	Other	DRY AIR BAG FLASHING	713
	X	Other	BARE WARP O S AIR BAG LIGHT ON STEADY IN DASH SW CODE	320
	X	Other	SAFETY RECALL #1801 VERIFIER BUCKLE DE CEMTURE DE SECURITE COTE. DROIT AVANT NE PONS PAS	370
REPLACED RR SEAT BELT BUCKLE DOWN T CLIC ...	X	Other		460
TRIP TOOK OUT D S SEAT REPLACED BUCKLE ASSEMBLY INSPECT AND REPLACE SEAT BELT LATCH INOP INSPECTED DRIVERS SIDE SEAT BELT BUCKLE BANDS. REPLACED BUCKLE ASBY. RE TESTED, QUANTITATIVE TIME TO REPLACE DRIVER SEAT BELT BUCKLE ASBY. NO LABOR OPS.	X	Other	SEAT BELT DOESNT WORK ASAP	310
	A	Went Latch	CHECK SEATBELT WILL NOT LATCH	
	A	Went Latch	CUSTOMER STATED DRIVERS SIDE SEATBELT DOES NOT LATCH.	305

PERFORMED AIR BAG DIAGNOSTIC TEST, ACCESS FLOOR CARPET  
 AIR SEAT TO ACCESS AIR TEST CIRCUITS. REPAIRED FUSED  
 WIRING, REPAIRED HARNESS. RESET CODE STILL PRESENT, REPLACED SEAT  
 BELT BUCKLE AND MODULE  
 TEST SYSTEM FOUND TERMINAL PULLED OUT OF CONNECTOR, REPAIRED  
 HARNESS. RESETTED OK  
 PERFORM AIR BAG DIAGNOSTIC BELT TEST CODES B244 PINPOINT  
 TEST, REPLACED RIGHT FRONT SEAT BELT ASSEMBLY. AIR BAG LIGHT IS  
 OUT

FOUND FAULTY SEAT BELT WIRING. REPLACED DRIVER SEAT BELT BUCKLE  
 AND RESET. OK NOW. NO DP CODE USE IN TIME FOR BELT BUCKLE  
 MANUFACTURER RECALL. SEATBELT INSPECTION  
 SEAT BELT BUCKLE CIRCUIT OPEN. TECH CHECKED AND VERIFIED AIR BAG  
 LAMP OR CHECKED ALL FUSES OK. INSTALLED SEAT TOOL  
 REMOVE SEAT TO REPLACE SEAT BELT RECEPTACLE OLD BELT HARD TO  
 LATCH I  
 PERFORM DIAG FOUND CODES B244 PERFORM PINPOINT TEST REPLUG BUCKLE DUE  
 TO BAD SWITCH RECHECKED OPEN OK

REPLACE LA CENTURE  
 FRONT SEATBELTS DO NOT LATCH. REPLACED BOP L F SEAT BELT.  
 REMOVED THEATRE ON PROTECTIVE SIDE SHIELD AND CONSOLE MOUNT  
 PLATE IN ORDER TO ACCESS AND REPLACE THE DRIVERS FEMALE SEAT  
 BELT RECEPTACLE.  
 PERFORM AIR BAG DIAG. LOCATE AND INSPECT HARNESS. REPLACE  
 DRIVERS SEAT BELT BUCKLE

CHECKED REPLACED LEFT AND RIGHT FRONT SEAT BELT ASSEMBLIES  
 I REPLACED SEAT BELT

AIR BAG DIAG, REPLACE SEAT BELT ASSEMBLY  
 AIR BAG DIAGNOSTIC TEST PINPOINT TEST OK WIRING REPAIR OPEN  
 CIRCUIT AT DRIVERS SEAT LFC IN  
 REPLACED BOTH FRONT BUCKLES. RECALL 01821  
 FAULTY SEAT BELT. REPLACE SEAT BELT.  
 THE NEW TEST CODES IN DRIVERS SEAT BELT AND BUCKLE POSSIBLE AREA  
 SHORT TO GROUND WIRE BELT CHM TEST SHOWED NOTHING ON OLD  
 ONE LEFT IN BECAUSE OF DIFFERENCE R AND I SEATS FRONT R AND I  
 GOOD PART OF D  
 CHECK AIR BAG LAMP FLASHING CODE B1 TEST NOTE CAME TO THE SEAT  
 BELT BUCKLE NEED TO BE REPLACED REMOVED AND REPLACED SEAT  
 BELT BUCKLE  
 I REPLACED RIGHT FRONT SEAT BELT BUCKLE  
 REPAIRED WIRING CIRCUIT TO PASSENGER SEAT BELT BUCKLE  
 REPLACE SEAT BELT ASSEMBLY

INSTALL NEW TESTER CODE B222 B244 PINPOINT TEST DATA LOG ON  
 DISPLAY CHECK PROBLEMS FROM SEAT BELT TERMINALS OPEN

RECALL OR OWNER NOTIFICATION  
 PERFORM RESTRAINT SYSTEM DIAGNOSIS REPAIR OPEN CIRCUIT IN  
 DRIVERS SEAT BELT BUCKLE CIRCUIT  
 REPLACED BOTH FRONT BUCKLES.

BY INSTALL BUCKLE REPLACEMENTS PER RECALL 01821. LABOR 01821H  
 B244 BY 648182 WIF TESTED DRIVERS SIDE SEAT BELT BUCKLE LATCH  
 WOULD NOT HOLD PER DRIVERS SEAT TO REPLACE SEAT BUCKLE. NOTE  
 THIS VEHICLE IS A POLICE CAR AND HAD A PETITION B2584 DRIVERS  
 SEAT.

X	Other	CUSTOMER STATES BRS LIGHT IS ON	541
X	Other	CUSTOMER STATES AIR BAG LIGHT FLASHING REPORT	420
X	Other	SEAT BELT AIR BAG WARNING INDICATOR ON	918
X	Other	CLIENT STATES AIRBAG LIGHT STAYS ON.	408
X	Other	SAFETY RECALL 01821	570
X	Other	CUSTOMER REQUESTS DIAGNOSE AIR BAG SYSTEM DUE TO LAMP COMING ON	914
X	Other		910
X	Other	CLIENT SAYS THAT THE AIR BAG LIGHT ON	947
X	Other	CENTURE AWAIT GAUGES NE BUCKLE PASSENGER/DRIVER AWAIT	480
A	Won't Latch	SEAT BELTS NOT LATCHING PROPERLY	582
X	Other	INSTALL BOP L FRT SEAT BELT FEMALE END	308
X	Other	CLIENT STATES AIR BAG LT FLASHING CLIENT BELIEVES CLOCK SPRING	739
A	Won't Latch	CUSTOMER STATES BOTH FRONT SEAT BELT BUCKLES DO NOT HOLD BOP	713
X	Other	BY STOCK	706
X	Other	CUSTOMER STATES THAT SEAT BELT IS BOP NEW CAR YESTERDAY	810
X	Other	LUMBER AIR BAG ALIENE AIR TEST BY REPLACER SEAT BELT ASSEMBLY	810
X	Other	OK AIR BAG LT ON	791
X	Other	G & BOTH FRONT SEAT BELT BUCKLES WILL NOT HOLD RECALL 01821	201
X	Other	DRIVERS SIDE SEAT BELT WILL NOT STAY LATCHED	808
X	Other	SEE AIR BAG LIGHT ON	405
X	Other	CUSTOMER STATES THAT THE AIRBAG LIGHTS COME ON CODE 51	910
X	Other	INSTALL SP. ORDER SEAT BELT BUCKLE	769
X	Other	CHECK FOR AIR BAG LIGHT ON	540
X	Other	AIR BAG LIGHT IS ON.	408
X	Other	CUSTOMER STATES AIR BAG LIGHT IS FLASHING	827
X	Other		789
X	Other	SEAT BELT BUCKLE RECALL 01821	808
X	Other	CHECK AND ADVISE CLIENT STATES AIR BAG LIGHT STAYS ON	732
A	Won't Latch	BOTH FRONT SEATBELTS WILL NOT BUCKLE	291
X	Other	01821 RECALL SEAT BELTS (DRIVER SIDE DOES COME UNBUCKLED)	713
D	Unlatches/Pls	620/CUSTOMER STATES DR BELT KEEPS POPPING OFF	407